

Judicial Council of California · Administrative Office of the Courts

455 Golden Gate Avenue · San Francisco, California 94102-3688 www.courts.ca.gov

REPORT TO THE JUDICIAL COUNCIL

For business meeting on June 26, 2014

Title

Court Facilities: Trial Court Facility Modification Quarterly Activity Report, Quarter 3 of Fiscal Year 2013–2014

Submitted by

Trial Court Facility Modification Advisory
Committee
Hon. David Edwin Power, Chair

Agenda Item Type Information Only

Date of Report May 20, 2014

Contact

Patrick McGrath, 916-643-8051 patrick.mcgrath@jud.ca.gov

Executive Summary

The Trial Court Facility Modification Advisory Committee (TCFMAC) has completed its facility modification funding for the third quarter of fiscal year 2013–2014. In compliance with the *Trial Court Facility Modifications Policy*, adopted by the Judicial Council on July 27, 2012, the TCFMAC is submitting its *Trial Court Facility Modification Quarterly Activity Report: Quarter 3, Fiscal Year 2013–2014* as information for the council.

Previous Council Action

The Trial Court Facility Modification Working Group was established by Judicial Council policy in 2005. The working group first met in April 2006 and operated under the *Trial Court Facility Modifications Policy*, ¹ adopted by the Judicial Council in 2005 and revised on July 27, 2012. The working group's primary oversight responsibilities included reviewing statewide facility modification requests and approving facility modification funding.

The working group's charge was formalized by the Judicial Council on December 14, 2012, and the working group was assigned additional oversight responsibility for the operations and

¹ As adopted in 2005, the policy was known as the *Prioritization Methodology for Modifications to Court Facilities*. When it was revised in 2012, the name also changed. See www.courts.ca.gov/documents/jc-20120727-itemG.pdf.

maintenance of existing facilities, noncapital-related real estate transactions, energy management, and environmental management and sustainability. On April 25, 2013, the working group's status was elevated to that of advisory committee.

An alternative Court-Funded Facilities Request approval process was submitted and approved by the Judicial Council on August 23, 2013, requiring all Court-Funded Facilities Requests to be reviewed and approved by the TCFMAC. These submittals may include lease-related costs (e.g., lease payments and operating costs, repairs, or modifications required by a lease); allowable court operations expenditures under rule 10.810 of the California Rules of Court (e.g., equipment, furnishings, interior painting, flooring replacement or repair, furniture repair, or records storage); and other facility improvements that are not allowable court operations expenditures under rule 10.810 (e.g., facilities operations, maintenance, repairs, and modifications, but not capital projects), if they would improve a court's functioning or reduce ongoing court operating costs.

Reports previously approved by the Judicial Council are available at www.courts.ca.gov/2567.htm under Research and Reports: Conditions in Our Courts.

Methodology and Process

Funding decisions were based on the prioritization and ranking methodologies in accordance with the *Trial Court Facility Modifications Policy*. Facility modifications are assigned one of six priority categories: Priority 1–Immediate or Potentially Critical; Priority 2–Necessary, But Not Yet Critical; Priority 3–Needed; Priority 4–Does Not Meet Current Codes or Standards; Priority 5–Beyond Rated Life, But Serviceable; and Priority 6–Hazardous Materials, Managed But Not Abated. These categories are based on methods commonly used by private-sector facility management firms. Facility modifications that are determined to be Priority 1 are to be addressed immediately and regardless of whether the court occupies a shared-use facility. With current budget constraints, the TCFMAC primarily limits approvals of facility modification projects to Priority 1 and Priority 2 projects. Delaying TCFMAC approval of these projects would cause continued court closures, operational failures, and undue risk to continued court operations.

Policy and Cost Implications

During the third quarter of fiscal year 2013–2014, the TCFMAC reviewed and approved a total of 214 facility modifications for a total projected cost of \$11,326,879. The Facility Modification Program's share of these projects totals \$9,521,097. The projects are limited to Priority 1 emergency projects and Priority 2 critical needs projects. Please see Attachment A for a detailed list of approved projects.

During this quarter, six projects required additional funds in excess of \$50,000 from their original estimates, including projects in Fresno, Humboldt, Los Angeles, and Sierra. Projects that require excess costs of this magnitude are typically Priority 1 emergency projects that do not

have a full scope and cost estimate developed at the onset of the project and for which significantly more work or testing is discovered after commencement.

During this quarter, 19 Court-Funded Facilities Requests (CFRs) were reviewed and approved by the TCFMAC, including requests from El Dorado, Los Angeles, Nevada, San Bernardino, Stanislaus, and Tulare. As stated above, CFR submittals may include lease-related costs, allowable court operations expenditures under rule 10.810 of the California Rules of Court, and other facility improvement costs that are not allowable under rule 10.810. See Attachment B for a detailed list of CFRs approved by the TCFMAC during the third quarter of fiscal year 2013–2014.

The committee reviewed and approved seven projects designed to improve the overall energy efficiency of the electrical systems in our facilities, with a total potential cost of \$528,000. These projects will pay for themselves in decreased energy costs within the next five years.

Implementation Efforts

The TCFMAC met on January 17, 2014, and March 10, 2014, to discuss facility modification funding requests and to discuss the following topics:

- The committee had its regular review of facility modification projects lists: A (Emergency and Priority 1), B (\$15/5 Rule FMs—FMs less than \$15K), C (Increases Over \$50K), D (Eligible for Funding), E (Shared-Cost Approval Pending) and F (Court-Funded Facilities Requests).
- Administrative Office of the Courts (AOC) Real Estate staff presented an overview of leases, licenses, and dispositions of the judicial branch portfolio.
- AOC staff presented current issues related to electric vehicles charging at court facilities.
- The committee received an update related to historical changes to firm fixed pricing and cost plus tasking, as well as anticipated changes.
- AOC staff presented contract options for three regional maintenance service providers (ABM, Enovity, and Pride Industries) and asked the committee to specify their preferred level of involvement. The committee unanimously agreed that they would like to be briefed on contract options and to have input and approval on contract extension decisions.
- As requested by the committee, AOC staff summarized some workload issues that the Facility Modification Program is experiencing. The committee wants to make sure that appropriate staffing requests are approved to avoid the backlog of work.
- Presiding Judge Alan V. Pineschi, Judge Charles D. Wachob, and Court Executive Officer
 Jake Chatters, of the Superior Court of Placer County, attended the January meeting to
 provide an overview of a funding request for the arraignment/felony in-custody courtroom
 located at the South Placer Adult Correctional Facility. The committee understands the value
 of the requested project, sees it as a valid Priority 3 project, and would consider approval
 when funding for Priority 3 work becomes available.

 AOC staff provided an update on performance-based compensation for the three regional service providers and invited the committee members to participate in the next round of performance measurement meetings.

Next Steps

The *Trial Court Facility Modification Quarterly Activity Report: Quarter 4, Fiscal Year 2013–2014* will be submitted to the Judicial Council in August 2014.

Attachments

- 1. Attachment A: TCFMAC Funded Project List: Quarter 3, Fiscal Year 2013–2014
- 2. Attachment B: Court-Funded Facilities Requests (CFR): Quarter 3, Fiscal Year 2013–2014

	FM NUMBER	LOCATION	FACILITY NAME	BULDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
1	FM-0051562	Alameda	County Administration Bldg.	01-A2	2	Plumbing - Pipe Leak - Remove damaged drywall (approximately 6 SF) to access the leaking pipe and fitting to the wall hung lavatory, cut out the leaking pipe section and replace the pipe and new fitting. Work also requires adding a new access panel, tile base and painting of one wall.	\$	11,752	\$	2,480	21.10
2	FM-0043878	Alameda	Wiley W. Manuel Courthouse	01-B3	2	Elevators (5EA) - Completely install five new elevators with new controls - Includes design, mechanical and electrical upgrades to bring systems to current code. Fire alarm interface on existing Notifier 3030 fire alarm system for the 2010 Editions of CBC, CFC and NFPA-72. Note: Inmate Elevator down-time requires tunnel walkways to be operational between courts and adjacent County Jail or an alternate means of transport of inmates between these facilities, currently inmate stairs may not be used as primary means of transportation.	\$ 3	3,020,699	\$ 2	,531,346	83.80
3	FM-0049849	Alameda	Wiley W. Manuel Courthouse	01-B3	2	HVAC - Controls and Components - Remove and replace (16) Variable Air Volume boxes and controls with reheat coils including (64) valves - Replace as current coils are plugged and non operational - Install (1) Flow meter for installed Variable Air Volume boxes to monitor usage - Install (1) Paragon controller and Reconfigure paragon controls on SF-1 and SF-2 for proper operation - Install new hot and chilled water BTU meters - Provide and install a web based interface for the existing Schneider Electric Inet BAS - This new web base system will allow three concurrent users. Poor air velocity control capability creates negative pressure within courtrooms which impairs proper climate control - Project involves asbestos containing materials abatement	Ś	978,743		820,187	83.80
	1101-0043043	Alamcua	Whey W. Manuel Courthouse	01-03		Fire/Life/Safety - Door Hardware - Remove existing door hardware and replace with new fire rated panic exit devices,	Y	370,743	۲	020,107	05.00
4	FM-0051630	Alameda	Wiley W. Manuel Courthouse	01-B3	2	the existing court room back door does not allow for proper egress.	\$	3,251	\$	3,251	100.00
5	FM-0051686	Alameda	Wiley W. Manuel Courthouse	01-B3	2	Holding - Replace broken safety glass in interview cell - Remove and replace two damaged windows in the interview cell, one at approximately 12"x12" and one at approximately 18" x 36"; damage was caused by a person in custody Fire Protection - Correct fire system deficiencies that were found while performing the annual PM - Replace seven	\$	4,229	\$	4,229	100.00
_	FN4 00F1700	Alamada	Miles M. Manual Counthause	01 02	2	escutcheons, nine sprinklers, and four tamper switches throughout the facility. Properly label and reprogram the fire	\$	12.010	٠	10.743	92.90
6	FM-0051709	Alameda	Wiley W. Manuel Courthouse	01-B3	2	panel. Fire alarm system - Replace failed fire pump isolation valve tamper switch and fire panel backup batteries to eliminate	Ş	12,819	Ş	10,742	83.80
7	FM-0051799	Alameda	Wiley W. Manuel Courthouse	01-B3	2	trouble alarm condition	\$	3,298	\$	2,764	83.80
8	FM-0051632	Alameda	Juvenile Justice Center	01-C3	1	Holding Cell - P1 response - Remove and replace approximately 2,000 SF of water damaged carpet tiles, dry out approximately 400 SF of walls in offices and holding cell areas, sanitize holding cell walls and floor in and around Courtroom 1	\$	17,208	\$	17,208	100.00
9	FM-0051693	Alameda	Hayward Hall of Justice	01-D1	2	Electrical - Replace failed power pack and board for inmate interview phones - Effects multiple departments.	Ś	3,840	¢	3,840	100.00
	1101-0031093	Alaineua	Trayward Trail of Justice	01-01		Electrical - Electrical Panel - Replace two (2) circuit breakers, and two (2) feeder cable-set connections that failed	ڔ	3,840	٦	3,840	100.00
10	FM-0051737	Alameda	Hayward Hall of Justice	01-D1	2	thermo-graphic (IR) scan. Located in main and chiller switchboard panels	\$	8,504	\$	7,509	88.30
11	FM-0051594	Alameda	George E. McDonald Hall of Justice	01-F1	2	Emergency backup generator - Correct deficiencies discovered while performing a level IV preventative maintenance service - Replace failed temperature gauge - Replace 2 failed alarm indicator lights - Install crank case emissions recycling system - Work to be performed during off hours Roof - Replace failed sealant - Remove failed sealant along entire length of reglet, prepare and prime prior to installing	\$	8,043	\$	8,043	100.00
12	FM-0051583	Alameda	Fremont Hall of Justice	01-H1	2	new caulking.	\$	2,719	\$	2,159	79.40
		Contra				HVAC - Replace leaking boiler circulation pump - Leaking pump is causing water to puddle up on roof, creating slip			Ì.		
	FM-0051688	Contra	Bray Courts	07-A3	2	HVAC - Replace 13 Hot water valve actuators, four Air damper actuators, eight Variable Air Volume Controllers, and five Thermostats that have failed; Replace 32 Damaged ceiling tiles - There are numerous heating and cooling issues in the	\$	4,978		4,257	85.52
14	FM-0051689	Costa	Bray Courts	07-A3	2	building and water is leaking above the ceiling.	\$	12,498	\$	10,688	85.52

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
15	FM-0051504	Contra Costa	Danville District Courthouse	07-C1	2	Exterior - parking lot - Cold mill 223 Sqft of asphalt to a depth of 3 inches; Fill 1200 lineal feet of cracks with asphalt; Install 6600 SqFt of slurry seal asphalt; Restripe 6400 lineal feet; Add 6 directional arrows; Provide blue striping for 2 handicapped spaces; install 12 new signs and posts. Work to be done off hours This is a safety issue, there are numerous tripping hazards from cracks and tree roots. There has been at least one request for medical reimbursement.	\$	74,273	\$	74,273	100.00
16	FM-0051804	Contra Costa	Danville District Courthouse	07-C1	1	HVAC - Replace failed 5-ton AC Unit - Requires a crane and work has to be done off hours; provide and maintain temporary heaters for Commissioner's Courtroom and Chambers - AC-5 has failed and is beyond repair.	\$	70,000	\$	70,000	100.00
		Contra				HVAC - Boiler - Remove and replace pilot assembly and ignition electrode assembly; New electrode and flame rod assembly are also included. Verify operation of control circuitry, gas valves, and vents; Fine-tune and adjust boiler to its maximum efficiency; Verify burner operation based on a variable control signal; Check operation of the boiler isolation					
17	FM-0051756	Contra	Arnason Justice Center	07-E3	2	control valve and timing - Boiler no longer operates because of defective parts. Exterior Shell - Remove and dispose of asbestos containing roofing system; Install new roof (34,00 sq ft); New parapet coping (1800 Lin Ft); Remove and replace a 4 ton AC unit on roof; remove and replace leaking windows (32) on south side with aluminum frames and operable awnings; Install new 22 gauge galvanized metal wall panels on penthouse (3400 sq ft); New metal rain screen on south & east walls (13.300 sq ft); Reseal all windows; - Building is leaking through	Ş	11,003	Ş	11,003	100.00
18	FM-0051593	Costa	George D. Carroll Courthouse	07-F1	2	the roof, windows, and walls.	\$ 2	,052,000	\$ 1,	,538,795	74.99
19	FM-0051662	El Dorado	Main St. Courthouse	09-A1	2	Electrical - Install One 20AMP dedicated circuit - Install One 20AMP dedicated circuit including conduit and wiring at the front security screening area for the security system & computer. The current power supply is inadequate to support the recently upgraded security system. To be surface mounted conduit/fixture. HVAC - Replace five 3.5 ton failed split system heat / cool units - Facility temperature controlled by 5 split units	\$	2,174	\$	2,174	100.00
20	FM-0051648	El Dorado	Cameron Park	09-C1	2	combining to cause multiple failures. Current units cannot be accessed for maintenance and continued failure is impacting court operations. Strong recommendation to replace all five units simultaneously for project efficiency, consistent equipment options, ongoing operations and cost savings - all units are failing repeatedly. Significant utility savings will be realized as well.	ς.	62,387	s	62,387	100.00
	FM-0050463	Fresno	Fresno County Courthouse.	10-A1		Roof - Re-seal approximately 12,000 sq of roof leaks that have been identified along the perimeter of the roofing system and seams are at the point of curling and release. Re-sealing of roof to extend warranty for an additional 10 years and eliminate leaks. asbestos containing materials is a concern if roof leaks.	\$	178,659		171,352	95.91
22	FM-0051606	Fresno	Fresno County Courthouse.	10-A1	1	1 / 5 /	\$	5,402	\$	5,402	100.00
23	FM-0051671	Fresno	B.F. Sisk Federal Courthouse	10-01	2	Plumbing - Sump Pumps - Pull both sump pumps, disassemble, replace bearings and re-machine shafts, reassemble and install back in place. Sump pump system is failing.	\$	9,821	\$	9,821	100.00
24	FM-0047418	Humboldt	Humboldt County Courthouse (Eureka)	12-A1	2	Interior - Spline ceiling (11,000 SF) - Remove the damaged and falling spline ceiling and replace with a T-bar ceiling. Remove and reinstall ceiling lights and HVAC diffusers to facilitate work - Ceiling damaged. High reach equipment and barricading will be required. Ceiling is delaminating and falling to the ground below. HVAC - Replace rusted non functioning return air and outside air dampers - New stainless steel return air and outside air	\$	122,598	\$	122,598	100.00
25	FM-0051808	Humboldt	Humboldt County Courthouse (Eureka)	12-A1	2	dampers (2ea - AHU # 1 & #2- Court Exclusive) will be installed complete with all necessary stainless steel linkage, control arms and fasteners.	\$	32,127	\$	32,127	100.00

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Plumbing - Water Leak - Set up containment, removal/abatement of approx 25 sq ft of fireproofing (asbestos containing materials) above ceiling grid, Isolate the leaking pipe and replace the leaking section of piper, remove and replace				
26	FM-0051721	Kern	Bakersfield Superior Court	15-A1	1	affected ceiling in basement hallway of facility.	\$	13,948	\$ 13,948	100.00
			Bakersfield Superior Court			HVAC - HVAC Unit - Remove and replace the existing failing 2 ton HVAC unit, Currently the existing unit is beyond				
27	FM-0051641	Kern	Modular	15-A2	2	serviceable life expectancy with parts no longer available.	\$	5,087	\$ 5,087	100.00
28	FM-0051752	Kern	Bakersfield Juvenile Center	15-C1	1	Plumbing - Pipe Leak - Removed and replace rusted coupling leaking through ceiling tiles and replace 10 restroom ceiling tiles. Additional access to the pipe required removal and replacement of approximately 2 SF of wall tile and drywall. This work was completed as a P1 emergency due to water intrusion in a public hallway causing a safety and slip hazard.		3,705	\$ 3,705	100.00
29	FM-0051690	Kings	Probation Building	16-A4	2	Fire/Life/Safety - Horn/Strobe and Duct Detectors - Remove and replace six combination horn/strobes throughout the probation building, two devices failed the annual fire alarm panel test and these current horn/strobes are no longer manufactured. All six devices will need to be replaced as the new devices will not synchronize with current devices. Two duct detectors are currently not configured to report trouble when tampered with, the devices need to be wired into system to bring system into compliance with current regulations. Exterior Shell - Pest Control - Remove 256 square feet of termite and water damaged siding and batten boards from four separate areas of the building. Treat for dry wood termites as required. Remove and replace damaged Insulation and install new vapor barrier as required in these areas. Install new siding and batten boards and paint to best match	\$	2,363	\$ 275	11.65
30	FM-0051736	Kings	Probation Building	16-A4	2	existing.	Ś	13,536	\$ 1,577	11.65
	FM-0051620	Kings	Avenal Court	16-C1	2	HVAC - Remove programmable thermostats and wiring to all package units, and install 4 Honeywell Focus Pro TH6320WF Wi-Fi thermostats and new wiring - To enable remote monitoring and remote access for faster and more cost effective service provider response to facility temperature issues.	\$	3,907	\$ 2,266	58.01
32	FM-0051683	Lake	Lakeport Court Facility	17-A3	2	County Managed - Exterior - remove rust and seal - Remove rust on metal parts of stair case, prime, paint and install slip resistant surface to stair treads	\$	4,047	\$ 4,047	100.00
33	FM-0051539	Los Angeles	San Fernando Courthouse	19-AC1		Roof - Roof Overlay - Prepare approximately 12,800 Sqft to apply a new 3 ply cold process roofing system with emulsion, to include flood coat asphalt emulsion in between all 3 ply sheets over existing built up roof. Apply 3 coats of new title 24 white acrylic elastomeric coating to include primer, base and top/final coat.	\$	96,000	\$ 80,074	83.41
						Exterior - Replace door guides with stops, new safety edge, and new starter slat. Currently minor repairs and adjustments have been completed to door to make it temporarily operational. The main security roll-up door was hit				
34	FM-0051612	Los Angeles	Compton Courthouse	19-AG1	1	and damaged and must be repaired to secure the basement area of the courthouse.	\$	4,900	\$ 4,900	100.00
35	FM-0051631	Los Angeles	Compton Courthouse	19-AG1	2	Fire Protection - Sprinkler Pipe - Set-up containment and test for asbestos containing materials , open access in ceiling, and replace leaking section of fire sprinkler piping on the 5th floor elevator lobby.	\$	4,400	\$ 2,910	66.13
36	FM-0051772	Los Angeles	Compton Courthouse	19-AG1	2	Fire protection - Fire pump #1 - Remove and replace non-operational remote start solenoid for fire pump #1.	\$	5,706	\$ 3,773	66.13
37	FM-0051773	Los Angeles	Compton Courthouse	19-AG1	2	Fire Protection - Replace cracked sight glass and waste cone for fire pump test header.	\$	3,719	\$ 2,459	66.13
						Exterior Shell - Install a total of 7 handrails to the exterior of the North side of the building. Currently the exterior of the				
38	FM-0051774	Los Angeles	Compton Courthouse	19-AG1	2	building missing handrails which is needed to prevent slips and falls for the public. HVAC - Chillers - Remove and replace the failed make-up water valve and float assembly, the Chillers are going off-line due to no condenser water flow, which causes the courthouse to get warmer than normal causing unfavorable working	\$	5,706	\$ 3,773	66.13
39	FM-0051552	Los Angeles	Norwalk Courthouse	19-AK1	2	conditions.	\$	3,600	\$ 3,061	85.03

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
40	FM-0051616	Los Angeles	Norwalk Courthouse	19-AK1	2	Exterior Grounds and Parking - Planter Stone - Demo loose and chipping grout, removal of existing failing planter stone, clean and remove all loose mortar, apply new mortar, install existing stones to new planter, grout all gaps and spaces between stones, and prep and seal all newly applied grout lines. Currently, the exterior planters by Civic Center Drive have stone planels that are detaching due to failed caulking and motor.	\$	4,832	\$ 4,109	85.03
41	FM-0051753	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing - Abate asbestos, encapsulate fire proofing, remove wet building materials, and install new ceiling tiles damaged by failed water cooler.	\$	9,319	\$ 9,319	100.00
	FM-0051623		Bellflower Courthouse	19-AL1	2	Plumbing - Replace (2) non-functioning domestic water backflows to the courthouse. Currently the backflows are leaking and can not be repaired. This work is required for health and safety of the building occupants. Elevator - Replace blown fuse for non-functioning Judge's Elevator #5. This work was completed as a P1 emergency due	\$,	\$ 6,341	77.94
43	FM-0051727	Los Angeles	Downey Courthouse	19-AM1	2	to this being a Judge's elevator and is critical to court operation and the safety of Judge's. HVAC - Replace existing boiler tube bundles which have failed and left the boiler inoperable and the building without a	Ş	2,187		100.00
44	FM-0051578	Los Angeles	Santa Monica Courthouse	19-AP1	1	heating source.	\$	26,692	\$ 20,951	78.49
45	FM-0051643	Los Angeles	Santa Monica Courthouse	19-AP1	2	HVAC - Split System condenser not operating. Need to replace failed split air conditioning system.	\$	23,771	\$ 18,658	78.49
46	FM-0051589	Los Angeles	Beverly Hills Courthouse	19-AQ1	2	Electrical - Exterior Lighting - Replace vandalized flood lights at the exterior path of travel, work will require pulling new wire.	\$	4,171	\$ 3,317	79.52
	FM-0051600 FM-0051602	Los Angeles	Van Nuys Courthouse East Van Nuys Courthouse East	19-AX1	1 2	Interior Finishes – Water remediation from roof leak. Set up 2 containment area (768 sq. ft.) in the public lobby. Removed and replaced a total of 80 sq. ft. of ceiling tiles. Encapsulated 120 cubic sq. ft. of fire proofing (positive for asbestos containing materials) above ceiling. Placed 2 dehumidifiers in containment areas to dry ceiling over night. Vandalism - Remove graffiti on main entrance steps, replace broken window by main entrance admin department, replace two broken light ballasts by Jury Room, and replace 3 window panes with etched in graffiti. Currently, the broken window has been boarded up and the graffiti has been removed from the steps. This work must be completed due to safety issues for the courts employees and visitors.	\$	34,742 9,161		89.74 89.74
	FM-0051806		Van Nuys Courthouse East	19-AX1	2	Exterior shell - Storefront Glazing System - Replace the existing storefront glass system that was removed to complete the site stabilization and structural work at the entrance to the main lobby. This will also include the design and shop drawing and submittals for glass, glass frame and door system. The doors are to be sliding doors, electrically activated; photo sensor and contain a laser beam relay to act as a safety closure loop (so the door doesn't close while the beam is interfered). All glass to be tempered and tinted.	7	128,842		89.74
50	FM-0051618	Los Angeles	Van Nuys Courthouse West	19-AX2	1	Elevator - Rebuild Motor - Remove and rebuild and reinstall the motor armature, shaft coupling, and bearings. Currently the elevator is making a loud grinding noise and has been removed from service.	Ś	18,749	\$ 15,089	80.48
	FM-0051645		Van Nuys Courthouse West	19-AX2	2	Plumbing - Set up of containment and equipment to dry and clean area. Remove damaged ceiling tiles, test area, replace failed Sloan flush valve in Dept 101, placed ceiling tiles, and containment. This work was completed as a P1 emergency due to water dripping from the ceiling tiles above the 2nd floor cashier's office window #7 which was coming from Department 101 lock up area on the 3rd floor. HVAC - Replace access door to cooling towers 1 & 2 and re-seal seams on cooling towers 3 & 4. Work is needed to stop	\$	4,745		100.00
52	FM-0051719	Los Angeles	Van Nuys Courthouse West	19-AX2	2	tower leaks through cracks and seams and to prevent moss growth and corrosion on towers.	\$	22,123	\$ 17,805	80.48

Elevators, Escalators, & Holists Pemove and install new handfull chain drive. Escalators is making a thumping noise as it 5		FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
56 PM-0051898 Us Angeles Van Nays Courthouse West 19-AX 2 Severe the dost ropes for Judge's Elevator #3. Currently this elevator is not operable due to the safety S 9,853 9,853 0,000	53	FM-0051751	Ins Angeles	Van Nuys Courthouse West	19-ΔX2	2		¢	3 882	\$ 3.124	80.48
M-0051788 Os. Angeles Van Nuys Courthouse West 19-A02 1 See with the stretched out ropes. 19-A02 1 PAVI	33	1101-0031731	LO3 Aligeres	van Nays Courthouse West	13-7/12			7	3,002	y 3,124	00.40
HYAC - Refrigerant Leak - Remove and replaced an Oringo in the failed soleroid valve. Valve was leaking refrigerant, evaluated air from the package unit, charged the package unit with new refrigerant, and leak rhecked the package unit. I This work was completed as a P1 emergency due to the communication room severe soverheating. Final Point State Plumbing - Install access panel in the men's restroom where an opening in the wall was made to allow access to repair plumbing in the wall was made to allow access to repair allow a	54	FM-0051788	Los Angeles	Van Nuys Courthouse West	19-AX2	1	, , , , , , , , , , , , , , , , , , , ,	\$	9,853	\$ 9,853	100.00
Section Sect	55	FM-0051639			19-AY1	1	evacuated air from the package unit, charged the package unit with new refrigerant, and leak checked the package unit. This work was completed as a P1 emergency due to the communication room servers overheating.	\$	3,676	\$ 3,080	83.80
FM-0051574 Los Angeles Inglewood Courthouse 19-F1 2 completed. 19							l · · · · · · · · · · · · · · · · · · ·				
Section Sect	56	FM-0051685	Los Angeles	Torrance Courthouse	19-C1	2		\$	2,478	\$ 2,110	85.14
FM-005184 Los Angeles Inglewood Courthouse 19-F1 2 code. FM-0051735 Los Angeles Inglewood Courthouse 19-F1 2 doors would not open. FM-0051735 Los Angeles Inglewood Courthouse 19-F1 2 doors would not open. FM-0051736 Los Angeles Inglewood Courthouse 19-F1 2 doors would not open. FM-0051737 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051737 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051737 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051737 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051737 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051737 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051737 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051740 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051750 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051760 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051770 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051771 Los Angeles Burbank Courthouse 19-F1 2 doors would not open. FM-0051786 Los Angeles Alhambra Courthouse 19-F1 2 doors would not open. FM-0051786 Los Angeles Alhambra Courthouse 19-F1 2 doors would not		ENA 0051574	Las Angeles	Inclosed Countbours	10.51	,	,	۲.	4.040	¢ 2.000	74.56
5.8 FM-005184 (os Angeles Inglewood Courthouse 19-F1 2 code. 19-F1 2 cod	57	FIVI-0051574	Los Angeles	Inglewood Courthouse	19-F1		· ·	Ş	4,940	\$ 3,083	74.50
FM-0051735 Los Angeles Inglewood Courthouse 19-F1 2 will remain out of service until this work is completed. 5 FM-0051789 Los Angeles Inglewood Courthouse 19-F1 2 will remain out of service until this work is completed. 60 FM-0051789 Los Angeles Inglewood Courthouse 19-F1 2 doors would not open. 61 FM-0049503 Los Angeles Burbank Courthouse 19-G1 1 failure to replace these boilers will lead to heavy daily fines; HEATING HOT WATER BOILER 1,200,000 BTU EA. 5 75,892 \$ 68,880 90.76 62 FM-0051787 Los Angeles Burbank Courthouse 19-G1 2 excessive moisture in the landscaping along the front of the building. 63 FM-0051786 Los Angeles Alhambra Courthouse 19-G1 2 excessive moisture in the landscaping along the front of the building in case of earthquake. 64 FM-0051802 Los Angeles Alhambra Courthouse 19-G1 2 avoid bearings rapture which can cause an unbalanced rotation of the fan blades and damage the tower. 65 FM-0051624 Los Angeles Pasadena Courthouse 19-J1 2 sissue. 66 FM-0051625 Los Angeles Pasadena Courthouse 19-J1 2 issue. 75 FM-0051625 Los Angeles Pasadena Courthouse 19-J1 2 issue. 86 FM-0051626 Los Angeles Pasadena Courthouse 19-J1 2 issue. 87 FM-0051627 Los Angeles Pasadena Courthouse 19-J1 2 issue. 98 FM-0051627 Los Angeles Pasadena Courthouse 19-J1 2 issue. 99 FM-0051628 Los Angeles Pasadena Courthouse 19-J1 2 issue. 99 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 99 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 99 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 99 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 99 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 99 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 99 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 99 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 90 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 90 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 90 FM-0051629 Los Angeles Pasadena Courthouse 19-J1 2 issue. 90 FM-0051629	58	FM-0051684	Los Angeles	Inglewood Courthouse	19-F1	2		ς	6 160	\$ 4593	74 56
59 FM-0051735 Los Angeles Inglewood Courthouse 19-F1 2 will remain out of service until this work is completed. 5 25,916 5 19,323 74.56	50	1101 0031004	Los / lingeres	inglewood courthouse	15 11	-		7	0,100	7 4,555	74.50
60 FM-0051789 los Angeles Inglewood Courthouse 19-F1 2 doors would not open. \$ 3,541 \$ 2,640 74.56 FM-0049503 Los Angeles Burbank Courthouse 19-G1 1 failure to replace these boilers will lead to heavy daily fines; HEATING HOT WATER BOILER 1,200,000 BTU EA. \$ 75,892 \$ 68,880 90.76 FM-0051717 Los Angeles Burbank Courthouse 19-G1 2 excessive moisture in the landscaping along the front of the building. \$ 4,214 \$ 3,825 90.76 FM-00517186 Los Angeles Alhambra Courthouse 19-G1 2 needs to be installed after the gas meter to shut off gas supply to building in case of earthquake. \$ 4,863 \$ 4,182 86.00 HVAC - Replace cooling tower fan bearings including new fan shaft, fan sheave, upper hub to hold shaft in place and locking collar. Bearings have been properly lubricated and are still making grinding noise. They need to be replaced to the LEVEL IV PM - FIRE SYSTEMS, STAND PIPES, DELUGE, PREACT not passing the inspection which is a compliance and series from the fire panel to have the building. \$ 2,556 \$ 1,773 69.35 FM-0051625 Los Angeles Pasadena Courthouse 19-J1 2 ment of the fire protection - Replace two smoke detectors and perform a hard restart to clear the trouble alarms from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building. \$ 2,556 \$ 1,773 69.35 FM-0051625 Los Angeles Pasadena Courthouse 19-J1 2 ment of the fire protection - Replace two smoke detectors and perform a hard restart to clear the trouble alarms from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building. \$ 2,556 \$ 1,773 69.35 FM-0051625 Los Angeles Pasadena Courthouse Pasadena Court house Removed water in both affected areas. After clearance test results were negative. Removed dehumildifiers, air	59	FM-0051735	Los Angeles	Inglewood Courthouse	19-F1	2		\$	25,916	\$ 19,323	74.56
HVAC - Gas Fired Boiler - Remove and replace one 39 year old non-compliant boiler due to AQMD Notice of Violation, failure to replace these boilers will lead to heavy daily fines; HEATING HOT WATER BOILER 1,200,000 BTU EA. \$ 75,892 \$ 68,880 90.76 Plumbing - Failed Backflow Device - Remove and replace one, 1 1/4" irrigation backflow device and recertify. Also remove 3 plastic inline valves for irrigation and install new brass valves, currently 3 Irrigation valves are broken creating excessive moisture in the landscaping along the front of the building. \$ 4,214 \$ 3,825 90.76 Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve needs to be installed after the gas meter to shut off gas supply to building in case of earthquake. \$ 4,863 \$ 4,182 86.00 HVAC - Replace cooling tower fan bearings including new fan shaft, fan sheave, upper hub to hold shaft in place and locking collar. Bearings have been properly lubricated and are still making grinding noise. They need to be replaced to 4 FM-0051802 Los Angeles Alhambra Courthouse 19-11 2 avoid bearings rapture which can cause an unbalanced or totation of the fan blades and damage the tower. \$ 5,569 \$ 4,789 86.00 Fire Protection - Replace 6" OS&Y valve that is frozen in the open position. This work must be completed due to the LEVEL IV PM - FIRE SYSTEMS, STAND PIPES, DELUGE, PREACT not passing the inspection which is a compliance and safety for the fire panel to have the building from the fire panel to have the building from the fire panel to have the building from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building Plumbing - Flood mitigation - Responded to the Pasadena Court for water leak. Setup 2 containments in 1st floor restroom and basement file room. Removed water in both affected areas. After clearance test results were negative. Removed dehumidifiers, air			·				ELEVATOR - Elevator Doors - remove and replaced FM1 base contacts & door rollers. Work required because elevator		-		
FM-0051717 Los Angeles Burbank Courthouse 19-G1 1 failure to replace these boilers will lead to heavy daily fines; HEATING HOT WATER BOILER 1,200,000 BTU EA. \$ 75,892 \$ 68,880 90.76 Plumbing - Failed Backflow Device - Remove and replace one, 1 1/4" irrigation backflow device and recertify. Also remove 3 plastic inline valves for irrigation and install new brass valves, currently 3 Irrigation valves are broken creating common and install new brass valves, currently 3 Irrigation valves are broken creating plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve plumbing - Install a seismic shut-off valve at gas meter to shut off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off valve at gas meter to shut off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off valve at gas meter to shut off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off valve at gas meter to shut off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off valve at gas meter to shut off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off valve at gas meter to shut off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off valve at gas meter to shut off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off valve at gas meter to shut off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve	60	FM-0051789	Los Angeles	Inglewood Courthouse	19-F1	2	doors would not open.	\$	3,541	\$ 2,640	74.56
62 FM-0051717 Los Angeles Burbank Courthouse 19-61 2 excessive moisture in the landscaping along the front of the building. \$ 4,214 \$ 3,825 90.76 Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve Plumbing - Install a seismic shut-off valve at gas meter to shut off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off valve at gas meter to shut off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off gas supply to building in case of earthquake. Plumbing - Install a seismic shut-off gas supply to building in case of earthquake. Plumbing - Inst	61	FM-0049503	Los Angeles	Burbank Courthouse	19-G1	1	failure to replace these boilers will lead to heavy daily fines; HEATING HOT WATER BOILER 1,200,000 BTU EA.	\$	75,892	\$ 68,880	90.76
Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve needs to be installed after the gas meter to shut off gas supply to building in case of earthquake. \$ 4,863 \$ 4,182 86.00 HVAC - Replace cooling tower fan bearings including new fan shaft, fan sheave, upper hub to hold shaft in place and locking collar. Bearings have been properly lubricated and are still making grinding noise. They need to be replaced to avoid bearings rapture which can cause an unbalanced rotation of the fan blades and damage the tower. \$ 5,569 \$ 4,789 86.00 Fire Protection - Replace 6" OS&Y valve that is frozen in the open position. This work must be completed due to the LEVEL IV PM - FIRE SYSTEMS, STAND PIPES, DELUGE, PREACT not passing the inspection which is a compliance and safety \$ 6,120 \$ 4,244 69.35 Fire Protection - Smoke Detectors - Replace two smoke detectors and perform a hard restart to clear the trouble alarms from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building monitored safely. \$ 2,556 \$ 1,773 69.35 Plumbing - Install a seismic shut-off valve at gas meter. There is no automatic gas shut-off on the main gas pipe. Valve \$ 4,863 \$ 4,182 86.00 HVAC - Replace cooling tower fan bearings including new fan shaft, fan sheave, upper hub to hold shaft in place and looking collar. The protection of the fan blades and damage the tower. \$ 5,569 \$ 4,789 86.00 Fire Protection - Replace 6" OS&Y valve that is frozen in the open position. This work must be completed due to the LEVEL IV PM - FIRE SYSTEMS, STAND PIPES, DELUGE, PREACT not passing the inspection which is a compliance and safety \$ 6,120 \$ 4,244 69.35 Fire Protection - Smoke Detectors - Replace two smoke detectors and perform a hard restart to clear the trouble alarms from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building monitored safely. Plumbing - Flood mitigatio							remove 3 plastic inline valves for irrigation and install new brass valves, currently 3 Irrigation valves are broken creating				
63 FM-0051786 Los Angeles Alhambra Courthouse 19-11 2 needs to be installed after the gas meter to shut off gas supply to building in case of earthquake. \$4,863 \$4,182 86.00 HVAC - Replace cooling tower fan bearings including new fan shaft, fan sheave, upper hub to hold shaft in place and locking collar. Bearings have been properly lubricated and are still making grinding noise. They need to be replaced to 40 avoid bearings rapture which can cause an unbalanced rotation of the fan blades and damage the tower. 5 5,569 \$4,789 86.00 Fire Protection - Replace 6" OS&Y valve that is frozen in the open position. This work must be completed due to the LEVEL IV PM -FIRE SYSTEMS, STAND PIPES, DELUGE, PREACT not passing the inspection which is a compliance and safety. 5 6,120 \$4,244 69.35 Fire Protection - Smoke Detectors - Replace two smoke detectors and perform a hard restart to clear the trouble alarms from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building 8 2,556 \$1,773 69.35 Plumbing - Flood mitigation - Responded to the Pasadena Court for water leak. Setup 2 containments in 1st floor restroom and basement file room. Removed water in both affected areas. After clearance test results were negative. Removed dehumidifiers, air	62	FM-0051717	Los Angeles	Burbank Courthouse	19-G1	2	excessive moisture in the landscaping along the front of the building.	\$	4,214	\$ 3,825	90.76
63 FM-0051786 Los Angeles Alhambra Courthouse 19-11 2 needs to be installed after the gas meter to shut off gas supply to building in case of earthquake. \$4,863 \$4,182 86.00 HVAC - Replace cooling tower fan bearings including new fan shaft, fan sheave, upper hub to hold shaft in place and locking collar. Bearings have been properly lubricated and are still making grinding noise. They need to be replaced to 40 avoid bearings rapture which can cause an unbalanced rotation of the fan blades and damage the tower. 5 5,569 \$4,789 86.00 Fire Protection - Replace 6" OS&Y valve that is frozen in the open position. This work must be completed due to the LEVEL IV PM -FIRE SYSTEMS, STAND PIPES, DELUGE, PREACT not passing the inspection which is a compliance and safety. 5 6,120 \$4,244 69.35 Fire Protection - Smoke Detectors - Replace two smoke detectors and perform a hard restart to clear the trouble alarms from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building 8 2,556 \$1,773 69.35 Plumbing - Flood mitigation - Responded to the Pasadena Court for water leak. Setup 2 containments in 1st floor restroom and basement file room. Removed water in both affected areas. After clearance test results were negative. Removed dehumidifiers, air							Plumbing Install a saismis shut off value at sas mater. There is no automatic sas shut off on the main sas nine. Value				
HVAC - Replace cooling tower fan bearings including new fan shaft, fan sheave, upper hub to hold shaft in place and locking collar. Bearings have been properly lubricated and are still making grinding noise. They need to be replaced to 4,789 86.00 Fire Protection - Replace 6" OS&Y valve that is frozen in the open position. This work must be completed due to the LEVEL IV PM -FIRE SYSTEMS, STAND PIPES, DELUGE, PREACT not passing the inspection which is a compliance and safety 5,5,569 \$ 4,789 86.00 Fire Protection - Replace 6" OS&Y valve that is frozen in the open position. This work must be completed due to the LEVEL IV PM -FIRE SYSTEMS, STAND PIPES, DELUGE, PREACT not passing the inspection which is a compliance and safety 5,6,120 \$ 4,244 69.35 Fire Protection - Smoke Detectors - Replace two smoke detectors and perform a hard restart to clear the trouble alarms from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building 66 FM-0051625 Los Angeles Pasadena Courthouse 19-J1 2 monitored safely. Plumbing - Flood mitigation - Responded to the Pasadena Court for water leak. Setup 2 containments in 1st floor restroom and basement file room. Removed water in both affected areas. After clearance test results were negative. Removed dehumidifiers, air	63	EM-0051786	Ins Angeles	Alhamhra Courthouse	10-11			Ś	4 863	\$ 4187	86.00
LEVEL IV PM -FIRE SYSTEMS, STAND PIPES, DELUGE, PREACT not passing the inspection which is a compliance and safety Secondary			J				HVAC - Replace cooling tower fan bearings including new fan shaft, fan sheave, upper hub to hold shaft in place and locking collar. Bearings have been properly lubricated and are still making grinding noise. They need to be replaced to avoid bearings rapture which can cause an unbalanced rotation of the fan blades and damage the tower.	\$			
65 FM-0051624 Los Angeles Pasadena Courthouse 19-J1 2 issue. \$ 6,120 \$ 4,244 69.35 Fire Protection - Smoke Detectors - Replace two smoke detectors and perform a hard restart to clear the trouble alarms from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building \$ 2,556 \$ 1,773 69.35 Fire Protection - Smoke Detectors - Replace two smoke detectors and perform a hard restart to clear the trouble alarms from the fire panel to have the building \$ 2,556 \$ 1,773 69.35 Plumbing - Flood mitigation - Responded to the Pasadena Court for water leak. Setup 2 containments in 1st floor restroom and basement file room. Placed dehumidifiers and air scrubbers in the 1st floor and basement file room. Removed water in both affected areas. After clearance test results were negative. Removed dehumidifiers, air							· · · · · · · · · · · · · · · · · · ·				
from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building 56 FM-0051625 Los Angeles Pasadena Courthouse 19-J1 2 monitored safely. 5 2,556 \$ 1,773 69.35 Flumbing - Flood mitigation - Responded to the Pasadena Court for water leak. Setup 2 containments in 1st floor restroom and basement file room. Placed dehumidifiers and air scrubbers in the 1st floor and basement file room. Removed water in both affected areas. After clearance test results were negative. Removed dehumidifiers, air	65	FM-0051624	Los Angeles	Pasadena Courthouse	19-J1	2		\$	6,120	\$ 4,244	69.35
Plumbing - Flood mitigation - Responded to the Pasadena Court for water leak. Setup 2 containments in 1st floor restroom and basement file room. Placed dehumidifiers and air scrubbers in the 1st floor and basement file room. Removed water in both affected areas. After clearance test results were negative. Removed dehumidifiers, air							from the fire panel. This work was necessary to clear all of the trouble signals from the fire panel to have the building				
restroom and basement file room. Placed dehumidifiers and air scrubbers in the 1st floor and basement file room. Removed water in both affected areas. After clearance test results were negative. Removed dehumidifiers, air	66	FM-0051625	Los Angeles	Pasadena Courthouse	19-J1	2	'	\$	2,556	\$ 1,773	69.35
Removed water in both affected areas. After clearance test results were negative. Removed dehumidifiers, air											
	67	FM-0051672	Los Angeles	Pasadena Courthouse	19-J1	1	scrubbers, and containments areas.	\$	6,100	\$ 4.230	69.35

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - Chiller #1 - Replace failed piping to motors starter heat exchange. Chiller #2 - Replace failed piping to motor starter heat exchanger and failing motor bearings. This work was completed as a P1 emergency due to several				
68	FM-0051710	Los Angeles	Pasadena Courthouse	19-J1	1	refrigerant leaks being found after performing a leak check of the system.	\$	56,980	\$ 39,516	69.35
						Interior Finish - Install precut laminate counter on top of Judges Bench and remove failing laminate pieces. Surface is	_			
69	FM-0051579	Los Angeles	Stanley Mosk Courthouse	19-K1	2	delaminating and cutting staff.	\$	4,808	\$ 4,808	100.00
70	FM-0051599	Los Angeles	Stanley Mosk Courthouse	19-K1	2	Electrical - Lighting Control - Replace non-operational lighting contactor that controls the exterior lights at the Olive Street entrance. This work must be completed for the safety of court employees and the visitors to the courthouse Fire Protection - Replace defective parts and devices on 6 standpipe systems including fire sprinkler heads, gauges, valves and damaged hanger per Level IV inspection list. Work is needed to pass Level IV inspection to certify fire	\$	2,284	\$ 2,221	97.26
71	FM-0051604	Los Angeles	Stanley Mosk Courthouse	19-K1	2	sprinkler system and maintain building occupancy permit.	\$	14,400	\$ 14,005	97.26
72	FM-0051613	Los Angeles	Stanley Mosk Courthouse	19-K1	1	Plumbing - Flood Mitigation - Set up containment area (Approximately 150 SF), extracted 250 gallons of water from the carpet, set up multiple air movers, and de-humidifiers. Flood water from the 6th floor restroom traveled to the hallway and conference room. This work was performed as a P1 emergency due to the water leaking from the 6th floor employee restroom toilet overflowing and the water running down to some of the 5th floor.	\$	12,608	\$ 12,263	97.26
		·				Parking Lot - Demo existing damaged curb, epoxy dowel #3 rebar into existing concrete, form new curb and install rebar,				
73	FM-0051715	Los Angeles	Stanley Mosk Courthouse	19-K1	2	pour and finish curb with 5000 PSI concrete mix, and strip all from finished concrete. This work is necessary to due to this curb protects the marble wall from being struck by vehicles.	\$	4,727	\$ 4,597	97.26
						Plumbing - Remove failed ice machine and install new. Currently the existing ice machine is beyond repair and new one				
74	FM-0051757	Los Angeles	Stanley Mosk Courthouse	19-K1	2	must be purchased and installed.	\$	5,892	\$ 5,892	100.00
75	FM-0051770	Los Angeles	Stanley Mosk Courthouse	19-K1	2	Electrical - Renovate failed cooling system and replace fuel heaters system. The generator failed the Annual Level IV PM.	\$	7,118	\$ 6,923	97.26
76	FM-0051771	Los Angeles	Stanley Mosk Courthouse	19-K1	2	Security - Remove and replace key switches, upper rollers, guides and sensors on the exit door to Hill Street. Currently the doors do not operate properly and the parts are beyond repair creating a security concern for the building. Interior Finishes - Replace in-floor closers with complete case arms, service and adjust hardware and doors. Doors are	\$	3,114	\$ 3,029	97.26
77	FM-0051775	Los Angeles	Stanley Mosk Courthouse	19-K1	2	loose and do not operate properly, closers are beyond repair and must be replaced.	Ś	4,626	\$ 4,499	97.26
	FM-0051777		Stanley Mosk Courthouse	19-K1	2	Interior Finishes - Please provide battery containment sleeves for back up generators 1,2,3 Safety issue	Ś	2,400		
	****			1	_		T	_, . 30	,55 .	21.20
79	FM-0051780	Los Angeles	Stanley Mosk Courthouse	19-K1	2	Electrical - replace lights out in 5th floor high-ceiling stairwells near departments 45 and 96.	\$	3,035	\$ 2,952	97.26
80	FM-0051549		Clara Shortridge Foltz Criminal Justice Center	19-L1	2	Replace two 6" Hersey Model 1 back flow preventers (BFP) SN 3218 and 3219 with two new Wilkins Model 350AR BFP. This work will include replacement of four 6" isolation gate valves for these two BFPs since these gate valves are passing and one has a broken stem.	\$	20,270	\$ 13,944	68.79
			Clara Shortridge Foltz Criminal			Plumbing - Domestic Hot Water Motor & Pump Assembly #1 - Remove and replace the failed pump assembly and mounting brackets. Currently the supply water pressure as well as the suction pressure periodically drops due to the				
81	FM-0051644		Justice Center	19-L1	2	motor/pump being non-operational.	\$	5,313	\$ 3,655	68.79
63	FNA 0054574	J	Clara Shortridge Foltz Criminal			Plumbing - Isolate leaking water, replace cracked domestic water pipe from 10th floor holding cell, Abate and encapsulate fire proofing, water remediation, replace ceiling tiles, and clean up of 9th floor public hallway. This work was completed as a P1 emergency to remediate all effects of this flood and return the courthouse to it's original		·		
82	FM-0051674	Los Angeles	Justice Center	19-L1	1	condition.	\	12,105	\$ 12,105	100.00

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
83	FM-0051680		Clara Shortridge Foltz Criminal Justice Center	19-L1	2	HVAC - Leaking Coil - Drain water from coil and braze coil to stop leak into the mechanical room penetrating the concrete flooring and into the exhibit room storage space. Setup containment & dehumidification and run clearance testing for moisture in Exhibit room.	\$	4,650	\$ 3,19	9 68.79
84	FM-0051763		Clara Shortridge Foltz Criminal Justice Center	19-L1	2	Interior Finishes - Patch and replace two pieces of travertine, one piece by the elevators and one piece by the men's restroom. Walls have holes where the travertine is broken and missing. Work required to prevent further damage.	\$	2,715	\$ 2,01	.4 74.18
85	FM-0051765		Clara Shortridge Foltz Criminal Justice Center	19-L1	2	Grounds and Parking Lot - Replace sprinkler system, automatic irrigation valves, all lateral galvanized lines with new, plant new landscaping, add mulch and wood chips. Sprinkler system and landscaping has deteriorated over the years, multiple valves and sprinklers are non-functional. Replacing to restore image of court.	\$	4,443	\$ 3,29	74.18
86	FM-0051668	Los Angeles	El Monte Courthouse	19-01		Elevator/Replace motor bearing on the Judge's Elevator #5. This work was completed on a P1 emergency due to the elevator making grinding noises when in operation which caused a safety issue for those who rode in it.	\$	6,421	\$ 6,42	1 100.00
87	FM-0051723	Los Angeles	El Monte Courthouse	19-01		HVAC - 2ea. 200 Ton Cooling Towers - Replace defective motor assembly parts on Tower 1, replace defective drain valves & piping for Towers 1 & 2, replace inlet louvers, fill media and seal water leaks for Towers 1 & 2. Currently the tower are operable but less then optimum capacity. Repairs are need to ensure long term operation. HVAC - Run a new conduit and electrical wires overhead between the motor control panel and chilled water pump #1.	\$	56,028	\$ 32,56	53 58.12
88	FM-0051738	Los Angeles	El Monte Courthouse	19-01	2	Currently chilled water pump #1 is out of service due to shorted electrical wires inside an underground conduit that runs between the motor control panel and chilled water pump #1. The shorted electrical wires cause a circuit breaker to trip when chilled water pump #1 starts up.	\$	2,711	\$ 1,57	6 58.12
89	FM-0051744	Los Angeles	El Monte Courthouse	19-01		Interior Finishes - Roof Leak - Install 30' x 30' x 9' asbestos containing materials containment in the 3rd floor break room, kitchenette, and air handler room. Set-up five dehumidifiers and five air scrubbers during abatement and drying process, patch hole in roof, and install rain gutter to divert leaking water from the cooling towers. Replace 15 SF of damaged ceiling tiles and remove containment for clearance testing. Due to the deteriorated roof, rain water leaked through into the 3rd floor employee break room, kitchenette.	\$	26,337	\$ 26,33	37 100.00
90	FM-0051669	Los Angeles	Edmund D. Edelman Children's	19-Q1		Plumbing / Set-up containment, test areas for lead and asbestos containing materials , extract water, repair walls and ceiling. Water leaking from the exterior main entrance walkway into the ground floor conference room ceiling creating water damage to the ceiling and floors. Replace damaged ceiling tiles.	ć	2,693	\$ 1,88	5 69.99
		-	Edmund D. Edelman Children's			Plumbing / Set-up containment; test for lead and asbestos. Replace failed hot water piping section and install new add-a-valve and ball valve assembly. Water leaking from the ceiling causing water damage to the ceiling and floor causing a	ب	·		
	FM-0051670 FM-0051725	Los Angeles Los Angeles	Edmund D. Edelman Children's	19-Q1 19-Q1		safety hazard. Fire Protection - Replace (2) batteries, (1) charger, and (1) logic board for the fire panel. Currently the fire alarm panel is showing a trouble alarm and will not clear due to the batteries not charging properly. This work must be completed for the safety of the people in the courthouse.	\$	4,588 3,997		
	FM-0051743	9	Edmund D. Edelman Children's	19-Q1		Plumbing - Water Damage - set up approximately 4,000 SF of containment area, extract water from 1,800 SF area, remove and replace 84 Sqft of damaged ceiling tiles, re-insulate 15 LF of duct work, remove 1,750 for glue down carpet squares, scrape the compromised glue, and reinstall the carpet. Replace failed Variable Air Volume box with new hot water coil, all piping and duct work connections. Leaking coil in air handler leaked from ceiling into the ground floor County Council office/cubicle area.	\$	51,681		
94	FM-0051750	Los Angeles	Edmund D. Edelman Children's Court	19-Q1		Fire Protection - Replace two corroded and damaged butterfly valves for fire pump. Currently the pumps aren't working properly and if the valve fails completely, there will be a flood in the fire pump room and no water to the building sprinkler system.	\$	5,146	\$ 3,60	69.99

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
95	ENA 00E1EE0	Los Angeles	Matropoliton Counthouse	19-T1	,	HVAC - Replace defective and outdated 1.5 ton Split system. Work is necessary to maintain adequate temperatures in	\$	10.530	\$ 19.53	100.00
95	FM-0051550	Los Angeles	Metropolitan Courthouse	19-11		I.T. room. Roof - Roof Leak - Restore a 60 SF section of the roof over the 8th floor Assembly Room. This work was required due to	Ş	19,530	\$ 19,53	0 100.00
96	FM-0051580	I os Angeles	Metropolitan Courthouse	19-T1	2	water ponding on the roof and leaking into the building.	\$	5,253	\$ 4,96	6 94.54
30	1101 0031300	2037 tilgeres	Metropolitari courtilouse	13 11	_	Elevator - North Custody Elevator #10 and #8 - Replace badly worn/rusted elevator ropes (cables) on elevator #10 and	7	3,233	7 4,50	5 54.54
						replace the failed elevator generator set and rewind the motor on #8. this work is needed to maintain safe and un-				
97	FM-0051603	Los Angeles	Metropolitan Courthouse	19-T1	2	interrupted elevator operation.	\$	87,990	\$ 87,99	0 100.00
						Interior - Install 14 missing spit guards and replace damaged guards on cashier's windows. Currently the windows do not				
						have spit guards, leaving a hole in the window allowing the public to grab the employees or spit in their face. These				
98	FM-0051675	Los Angeles	Metropolitan Courthouse	19-T1	2	repairs must be completed due to the safety of the employees.	\$	2,800	\$ 2,80	100.00
						Elevator - Remove elevator #4 generator set and install into Elevator #8. Currently elevator #8 is not functioning and this				
99	FM-0051706	Los Angeles	Metropolitan Courthouse	19-T1	2	will bring elevator #8 back into operational status.	\$	6,562	\$ 6,20	94.54
						Grounds and Parking Lot - Repaint signage on public parking garage, two new clearance signs and one exit sign.				
100	FM-0051778	Los Angeles	Metropolitan Courthouse	19-T1	2	Currently it is confusing to the public when entering and exiting the garage with vehicles.	\$	4,903	\$ 4,63	5 94.54
						Elevator - Circuit Board - Replace malfunctioning circuit board and conduct a system check of the elevator operations.				
		l				Currently elevator #5 HC-PIO circuit board has malfunctioned making the elevator inoperable. The elevator has been				
101	FM-0051734	Los Angeles	Pomona Courthouse South	19-W1	2	place out of service for the safety of the courthouse.	Ş	3,996	\$ 3,64	2 91.14
						Interior Finishes - Floor tile and adhesive glue to be removed in an area of about 130 sq ft, asbestos containing materials removal, test for clearance, then install new floor tile. Tiles are starting to lift and are creating a trip hazard in employee				
102	FM-0051795	Los Angeles	West Covina Courthouse	19-X1	2	hallway near employee break room/law library.	Ś	5,364	\$ 4,98	9 93.01
102	1101-0031793	LO3 Aligeles	West covina courtilouse	13-71		nanway near employee break roomy law library.	۲	3,304	7 4,50	3 33.01
103	FM-0051577	Los Angeles	San Pedro Courthouse	19-Z1	1	PLUMBING - Drinking Fountain (Flood Remediation) - Remove and replace a leaking section of pipe from the water fountain, secure area, extract water at over 2,000 square feet, set up drying equipment, remove damaged drywall, and test for asbestos containing materials. Install new drywall where saturated and repaint walls.	\$	34,460	\$ 32,78	9 95.15
104	FM-0051692	Madera	Sierra Courthouse - Bass Lake	20-D1	2	Exterior Shell - Roof Gutter - Remove the small portion of gutter currently in place and install approximately 300 LF of new 6" gutter with leaf screens around the entire perimeter of the building - Currently there are not enough gutters in place and the rain water sheeting from the roof is causing erosion around the building perimeter and foundation.	\$	6,045	\$ 6,04	5 100.00
						HVAC - Install Control Boxes - Install to Johnson Controls boxes (2) to Boilers and Chillers, to allow programmed to	١.			
105	FM-0051556	Mendocino	County Courthouse	23-A1	2	operate based on AHU Demand	\$	6,082	\$ 4,11	3 67.62
100				22.44	_	HVAC - Replace Discharge Valve on Compressor #1, Brush Tubes, Install New Thermometer on chilled water lines, Re-	_			67.60
106	FM-0051557	Mendocino	County Courthouse	23-A1	2	seal angle valves (2), Correct Line leak, replace Chilled water flow switch HVAC - Chiller #1 - Remove refrigerant from compressors 1 and 2, replace suction valve on compressor 2, remove the	\$	9,344	\$ 6,31	8 67.62
						packed angle valves, reseal and reinstall, repair condenser water lines, brush the condenser tubes, install new condenser barrel gaskets, replace the thermometer on the chilled water line and recharge the units to factory				
107	FM-0051571	Mendocino	County Courthouse	23-A1	2	specifications.	Ş	9,157	\$ 6,19	2 67.62
108	FM-0051595	Mendocino	County Courthouse	23-A1	2	HVAC - Change air temp sensors (2) and reprogram reset temperatures in Air Supply based on demand response Event	\$	3,273	\$ 2,20	1 67.26
1							١.			
109	FM-0051597	Mendocino	County Courthouse	23-A1	2	HVAC - Return to Design Spec - Correct Operation of 2 outside air dampers, both currently in manual operation only.	\$	24,452	\$ 16,53	4 67.62
						HVAC - Boiler Switches - Replace failing high gas and low gas pressure switches on Boiler #1 - Replace Failing high and				
110	ENA 00E4600	Mand	Country Counth ave-	22.64	,	low gas pressure switches, Replace leaking pipe on Boiler #2 by welding 2" flange onto 16" pipe with a tee. Piping will be	ہ	10 200	ć co	
110	FM-0051609	ivienaocino	County Courthouse	23-A1	2	prefabricated.	\$	10,298	\$ 6,96	4 67.62

	FM NUMBER	LOCATION	FACUITY NAME	BUILDING ID	PRIORITY	SHORT TITLE HVAC - Pipe Insulation - Insulate approximately 600 LF of steam and chilled water pipes to reduce the heat loss through		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
111	FM-0051621	Mendocino	County Courthouse	23-A1	2	the pipe walls.	\$	12,486	\$ 8,44	3 67.62
112	FM-0051701		County Courthouse	23-A1		HVAC - Reconfigure Distribution lines - Install duct line extensions into courtroom #1, to allow for better air flow and cooling and reduce the number of Hot/Cold calls. commissioning to allow for corrected air flow, ventilation	\$	56,174	\$ 56,17	4 100.00
113	FM-0051702		County Courthouse	23-A1		HVAC - Replace 2 Failing Chillers - Remove and replace two 40 year old 35 - ton chillers that are failing and beyond repair. Install new controllers with BAC-net interface, includes electrical and piping, insulation as required. Replace four (4) Chilled Water Coils - The (4) custom sized Chilled Water Coils are failing and beyond repair and in need of replacement, asbestos containing materials abatement included. 3 coils in mechanical room and 1 coil on 3rd floor	\$	720,968	\$ 487,51	9 67.62
114	FM-0051650	Merced	New Downtown Merced Courthouse	24-A8	2	Security - Install a Proxy card reader for security purposes on the I.T. door - The court has requested the installation of the Proxy card reader due to equipment theft.	¢	4,591	\$ 4,59	1 100.00
	FM-0051798		New Downtown Merced Courthouse	24-A8		Grounds - Directional signage - Replace the damaged and dilapidated signage outside the courthouse. The signs have fallen apart causing directional confusion for the public.	\$	5,190		
116	FM-0051805	Modoc	Barclay Justice Center	25-A1	1	HVAC - Computer Server Closet AC - The 2.5 ton AC unit serving the computer closet has failed, is beyond repair, and needs to be replaced.	Ś	10,000	\$ 10,00	0 100.00
	FM-0051565		New Mammoth Lakes Courthouse		2	Grounds and Parking Lot - Remove temporary irrigation placed during construction for hydro seed. 3,966 ft of PVC pipe, 97 sprinkler heads, and 14 valve boxes System was placed for temporary use and scheduled for removal. The current irrigation is exposed above ground creating trip and safety hazards.	\$	4,476		
118	FM-0051667	Monterey	Salinas Courthouse- North Wing	27-A1	2	Holding Cell - Construct additional holding cell in existing space due to the King City Court Closure; compromising the safety of inmates and Juveniles currently held in Transport busses due to lack of holding cell capacity. Fire Protection - Failed Flow Switch - Removed and replaced failed water flow switch for fire system wet pipe(fire	\$	187,500	\$ 187,50	0 100.00
119	FM-0051694	Monterey	Salinas Courthouse- North Wing	27-A1	1	sprinkler). Isolated fire sprinkler system and drained at the basement level. Removed and replaced flow switch. Filled system and placed back on line. Performed operational testing. Performed fire watch while system was in test.	\$	5,249	\$ 5,24	9 100.00
	51.4.005:				_	Holding Cell - Holding Cell Door #4 - Replace (1) failed door carriage rollers kit and mounting hardware. Door is not		2 2 2 2		
120	FM-0051720	Monterey	Salinas Courthouse- North Wing	27-A1	2	Sliding shut. Exterior Siding Wall - Replace approx (100) missing wood siding shingles with treated cedar, to prevent water intrusion	Ş	3,060	\$ 3,06	100.00
121	FM-0051559	Monterey	Marina Courthouse	27-B1	2	and damage to the building structure.	Ś	7,247	\$ 7,24	7 100.00
	FM-0051712	,	Monterey Courthouse	27-C1		Stairwell Lighting- Replace (3) poorly lit wall mounted light fixtures causing unsafe conditions in the back stairwell, employees have reported cases of missing steps due to darkness.	\$	2,508		
123	FM-0051570	Napa	Criminal Court Building	28-A1	2	Plumbing - Replace Failed Domestic Water Backflow Device - Replace 1 Back Flow Device model LF880V and relief valve - replace check 1 and 2, replace relief valve, replace industrial side valve with new	\$	10,839	\$ 10,83	9 100.00
124	FM-0051807	Napa	Criminal Court Building	28-A1	2	Plumbing - Replace nonfunctioning institutional grade holding cell toilet - work needs to be performed afterhours	\$	5,183	\$ 5,18	3 100.00
125	FM-0051601	Orange	Central Justice Center	30-A1		Fire/Life/Safety - Fire Panel - To establish communications between the main EST3 fire alarm panel on the 1st floor and the subsequent panels as follows: 1) add EST CT1 modules and wiring from Cheetah fire suppression system on the1st floor CPU room to the EST3 main fire control panel. 2) Add EST CT1 modules and wiring from the fire lite miniscan 434A system in the AT&T room to the 1st floor EST3 main fire control panel. 3) Add EST CT1 modules to Fenwall model 2210 Halon system in basement walk in vault to the 1st floor	\$	11,776	\$ 10,73	6 91.17

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	NOTES CHICAN		FACILITY MODIFICATION PROGRAM SHARE % OF COST
						FM - HVAC - Hot Water Valves and Actuators - Install re-heat valves and actuators in 3rd floor West Wing and re- program to the BAS. County improperly removed valves and actuators resulting in no heat for courtrooms, chambers,					
126	FM-0051611	Orange	Central Justice Center	30-A1	2	and public hallways in this area.	Ś	7,913	\$	7,214	91.17
	FM-0051801	Orange	Central Justice Center	30-A1	2	Plumbing - Flood Mitigation - Drywall, carpeting, ceiling, and other interior finishes - Emergency remediation and cleanup, including but not limited to containment, disinfection, abatement, and dry out of areas impacted by the black water flood on 01/28/2014.	\$	4,400		4,011	91.17
						Plumbing - Flood Mitigation – Remove and replace 33,791 sq ft of drywall, 15,273 sq ft of flooring, 1,957 linear ft of ceiling perimeter, and 1,957 linear ft of floor perimeter and remove approx. 40 yards, 7-8 tons of debris. Emergency remediation and cleanup, including but not limited to containment, disinfection, abatement, and dry out of areas					
128	FM-0051818	Orange	Central Justice Center	30-A1	2	impacted by the black water flood on 01/28/2014.	\$	38,500	\$	35,100	91.17
129	FM-0051572	Orange	Betty Lou Lamoreaux Justice Center	30-B1	2	HVAC - Provide and install two T fittings, two butterfly valves, and insulate piping for temporary chiller connection. Building is currently being supported by Chiller #2 only. Work is necessary for a temporary chiller to restore cooling, minimize the impact to operations, avoid closing the facility until the repairs are complete. HVAC - The Building Automation System router - Remove and replace the failed BAS Router, the Building Automation	\$	6,834	\$	5,464	79.95
			Betty Lou Lamoreaux Justice			System router is not functioning properly. We are unable to make programming changes and see status of the building					
130	FM-0051665	Orange	Center	30-B1	2	equipment. A temporary router has been installed.	\$	3,290	\$	2,630	79.95
131	FM-0051722	Orange	Betty Lou Lamoreaux Justice Center	30-B1	2	Fire Protection - Standpipe - Remove and replace the corroded "T" Connection of fire sprinkler standpipe, and the flow switch in the Southwest stairwell on the 7th floor. It appears the pipe may have leaked at one point and now is rusted and brittle.	\$	3,425	\$	2,738	79.95
			Betty Lou Lamoreaux Justice			HVAC - Chiller #3 - Remove and replace failed 300 - ton Chiller #3 with energy efficient Multi-stack Chiller. Chiller #3 is non-operational. The building is being supported by Chiller #2 only with no redundancy. Failure of Chiller #2 would result					
132	FM-0051809	Orange	Center	30-B1	2	in zero cooling for the facility and possible closure.		595,242	\$	475,896	79.95
133	FM-0051732	Orange	Computer Systems Trailer	30-B2	2	COUNTY MANAGED. Please provide fumigation and soil treatment services to address the dry wood and subterranean termites. The project includes the County ISU trailers. The total cost is \$12,726.50.The Courts occupy approximately 5,084 SF. Probation occupies approximately 5,837 SF. The pro-rated cost would be \$5,930.50 for the Courts and \$6,796.00 for Probation.	\$	6,524	\$	6,524	100.00
						Grounds and Parking Lot - Grind and refinish approx. 43,500 sq ft of existing asphalt. There are several very large potholes in the driveway that runs through the parking lot of the facility creating substantial safety concerns. The project will smooth and resurface the damaged areas and apply a finish grade of new asphalt to match existing. Additionally, one heavy topcoat will be applied to entire driveway from one upper entrance to lower entrance with					
134	FM-0051587	Orange	North Justice Center	30-C1	2	speed bumps and crosswalks repainted.	\$	15,547	\$	14,040	90.31
135	FM-0051635	Orange	North Justice Center	30-C1	2	HVAC - Boiler - Remove and replace existing 3MBTU Ajax boiler, that has failed Nitrogen Oxide testing and is unable to be retrofitted to pass, with two (new) Lochinvar HVAC - BAS Tie In - Tie into the NOVA BAS four isolation valves and associated pumps for the HVAC system servicing	\$	161,172	\$	145,554	90.31
126	ENA 00E1640	Orango	North Justice Center	20.61	2	Phases I and II of the facility, the tie-in work will include installing a micro-regulator and programming the system.	ć	2 020	Ś	2 540	00.21
136	FM-0051649	Orange	North Justice Center	30-C1		Currently, all manipulation of the system is manual. HVAC - Phase I, 3rd Floor VFD (Variable Frequency Drive) - Remove and replace failed 40hp VFD for the Phase I, 3rd	Ş	3,920	Ş	3,540	90.31
137	FM-0051766	Orange	North Justice Center	30-C1	2	floor HVAC with new ABB VFD with Johnson N3, Siemens FLN, MODBUSRTU and BACNET embedded drive. Cost also included start up, two year warranty, couplings, connectors, fittings and anchors. Failure to replace will leave this phase of the building without sufficient HVAC.	\$	9,279	\$	8,380	90.31

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	2 7 1	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - Duct Work - Main Hard Duct in the lobby of room 350 is falling and has bent several T-bar supports for the light					
						fixtures and ceiling tiles causing them to also start to fall. Area is directly above queue for public payment windows.					
					_	Remove all affected ceiling tiles and T-bar. Add brackets mounted to ceiling to secure main hard duct. Replace T-bar and			_		
138	FM-0051767	Orange	North Justice Center	30-C1	2	ceiling tiles.	\$	1,786	Ş	1,613	90.31
						Grounds - Sidewalk Flooding - Install drains to direct flow of rain water into and through planter area to prevent flooding	5				
						of courthouse entrance during rainy season. This is a safety issue as water pools on sidewalk forcing public to walk through flooded area to get to courthouse entrance. Also, during morning rush, public entrance queuing forms into					
120	FM-0051543	Orange	West Justice Center	30-D1	2	flooded area causing trips, slips and falls.	خ	23,669	Ś	21,463	90.68
139	FIVI-0031343	Orange	West Justice Center	30-D1		Fire Protection - Fire/Life Safety Issue. When general alarm is activated, AHU1 & AHU2 supply fans does not shut off. In	Ş	23,009	Ş	21,403	90.06
						the event of a fire, both air handlers would feed the fire w/oxygen. Champion Fire Services to wire/program four (4)					
140	FM-0051681	Orange	West Justice Center	30-D1	2	duct detectors to fire panel (Notifier).	\$	6,088	Ś	5,521	90.68
							Ť	-,,,,,	7	-,	
						Plumbing - Install circulation pump and run approximately 150 ft. of 1/2" copper pipe from water heater on North side					
141	FM-0051682	Orange	West Justice Center	30-D1	2	of courthouse. Judges have complained that it takes over 8 minutes for hot water to reach chamber faucets.	\$	5,223	\$	4,736	90.68
						Grounds/Parking Lots - Resurface/Reseal-Lots A, B & C (per JOA) have deteriorated to the point where the neglected lots represent a major liability risk as spaces are no longer marked appropriately and pavement is uneven and graveling in many areas, degrading the surface. Contractor to grind and remove approximately 500 sq. ft. of pavement and replace with new asphalt; reseal using one (1) heavy coat of standard slurry over approximately 51,590 sq. ft. of parking lot. Restripe with handicap logo, arrows and lines and renumber as designated. Saw cut and replace 21 linear ft. of 18 curb					
142	FM-0051731	Orange	West Justice Center	30-D1	2	uprooted by tree, remove roots and haul away debris.	\$	14,728	\$	13,355	90.68
			Harbor Justice Center-Newport			Electrical - Replace main breaker. During ATS-IV PM main breaker failed. PM had not been performed in 14 years					
143	FM-0051628	Orange	Beach Facility	30-E1	1	according to tags and no history in CAFM.	\$	15,000	\$	12,648	84.32
144	FM-0051728	Orange	Harbor Justice Center-Newport Beach Facility	30-E1	2	Roof - Roof Leak - Remove and replace approximately 250 square feet of roofing material at the leaking and pooling areas of the roof. Scope will include the use of a white flood coat emulsion and to include resealing of 100 LF of coping and seams. This work is needed to maintain the roofs warranty and recommended by the product manufacturer and roof installer.	\$	6,716	¢	5,663	84.32
144	1101 0031720	Orange	Harbor Justice Center-Newport	30 L1	-	Interior Finishes - Stair Treads - Remove and replace brittle and loose vinyl flooring on the stairs; There has been a trip	۲	0,710	7	3,003	04.52
145	FM-0051729	Orange	Beach Facility	30-E1	2	and fall due to these stairs.	\$	12,742	\$	10,744	84.32
			Harbor Justice Center-Newport								
146	FM-0051768	Orange	Beach Facility	30-E1	2	HVAC - Replace failed 50HP 326T frame 1770RPM 460V AHU motor.	\$	5,674	\$	4,784	84.32
			Harbor Justice Center-Newport								
147	FM-0051800	Orange	Beach Facility	30-E1	2	Grounds and Parking Lot - Add asphalt to correct ADA Parking trip hazard caused by lifting concrete	\$	2,445	\$	2,062	84.32
148	FM-0051699	Riverside	Hall of Justice	33-A3	2	HVAC - Chiller #2 - The Carrier chiller has developed refrigerant leaks (motor cover o-ring, motor to compressor o-ring, compressor to volute o-ring, volute to inlet guide vane housing o-ring, and inlet guide vane actuator assembly) discovered during a leak check. The leaks are required to be repaired by EPA Rule 608 as well as to ensure the chiller is operating efficiently with design conditions. The project will replace the failed o-rings and actuator assembly. Chiller thrust will be tested	\$	11,768	\$	11,768	100.00
149	FM-0051792	Riverside	Larson Justice Center	33-C1	2	Grounds and Parking Lot - East Parking Lot - Replace approx 1200ft of 8 AWG and 600ft of 12 AWG of stolen wiring to recently vandalized parking lot lighting poles and feeds, currently leaving the lot with large sections unlit. 6 welded and locking covers will be added to prevent further theft. The project will restore functionality to the lighting and provide a safer and secure environment for Court patrons leaving in the evening.	\$	9,484	\$	7,664	80.81

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
150	FM-0051569	Sacramento	Gordon Schaber Sacramento Superior Court	34-A1	2	HVAC - Compressor Lines - Install a new solenoid valve into the main branch line and install a raceway and wire to the control cabinet. Provide and install a transformer and terminate all field devices. This also includes the programming, downloading, database synchronization between LON/Vista and the graphic updates. Final testing and verifying the system and amend the control drawings - The current pneumatic system is failing due to leaks requiring the air compressor to run all night.	\$ 3,656	\$	3,656	100.00
151	FM-0051598	Sacramento	Gordon Schaber Sacramento Superior Court	34-A1	2	Fire Protection - Remove and replace two failed check valves, work includes draining the fire system, pressurizing the system and verify the system is back in proper operating condition. The monitoring system is reporting trouble instead of fire because of the leaking valves.	\$ 10,425	\$	10,425	100.00
	FM-0051636		Gordon Schaber Sacramento Superior Court Gordon Schaber Sacramento	34-A1	2	HVAC - Provide (3) new addressable carbon monoxide sensors along the west wall of the garage area adjacent to the main north-south drive aisle as shown on the attached plan. Connect them through the BAS, so they will control the (2) existing exhaust fans - Currently, the (2) existing 48 diameter exhaust fans run continuously all day long, which is not necessary when the bulk of the vehicle traffic only occurs in the morning and evening. System required by Code Plumbing - Domestic Water System - Failed air compressor / pressure tank combination needs replacement, replace 50 year old pumps and tank with Variable Frequency Drive controlled pumps and bladder tank, eliminate air compressor. Reroute plumbing to new system as required, remove and discard existing equipment except pressure tank due to	\$ 28,432		28,432	100.00
153	FM-0051660	Sacramento	Superior Court	34-A1	2	removal cost.	\$ 109,500	\$	109,500	100.00
	FM-0051705 FM-0051610		Gordon Schaber Sacramento Superior Court Juvenile Courthouse	34-A1 34-C2	2	Electrical - One lighting contactor on the first floor and two lighting contactors on the sixth floor have failed in the closed positions. This means 1/4 of the first floor lighting and 1/2 of the sixth floor lighting are operating 24 hours a day every day - We are wasting electrical power, these lights should be off when the building is not occupied. HVAC - Control Room Heating - Cut in a 10" access through a fire rated wall, install a fire damper for the ductwork and Install an insulated flex duct and two supply registers in the Control Room. Work will also require relocating an existing thermostat.	\$ 3,940 4,300		3,940 4,300	100.00
156	FM-0051634	Sacramento	Juvenile Courthouse	34-C2	2	Electrical - remove and replace 54 batteries from two UPS units - Current batteries have failed	\$ 2,249	\$	2,249	100.00
157	FM-0050565	San Bernardino	San Bernardino Courthouse	36-A1		Parking Lot - Grind down approximately 23,150 Sqft., 3 inch depth, of asphalt and resurface with approximately 26,150 SqFt., 4 inch thick, asphalt in Judge's parking lot and driveway, extending to the in custody bus loading zone. Install 3 new removable bollards on Judge's parking lot driveway, slurry seal new asphalt and restripe. Currently the asphalt at the Judges driveway and parking lot has numerous cracks that have led to the substrate to fail leaving many uneven areas that pose a tripping hazard. The existing asphalt over the Central Plant must be ground down 3-4 inches as it has been built up substantially over the years and is causing excess load on the ceiling of the central plant. The Judges driveway must be ground down as well to maintain grading. Many areas will need to be completely removed with new underlayment installed prior to the resurfacing. Exterior Shell - Walk up Teller Windows Install 8LX4H walk-up window for 2 new teller window work stations into the exterior block wall. This work is to relieve congestion from the interior teller windows caused by the closing of area	\$ 233,516	\$	233,516	100.00
158	FM-0051585	San Bernardino	Fontana Courthouse	36-C1	2	courts. Scope of work to include saw-cut and demolition of the existing block wall, remove and replace 350 SF of existing sidewalk to make the windows ADA accessible, furnish and install a 35L X 8W stand alone canopy at new walkway.	\$ 130,000	\$	130,000	100.00

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Interior - 2nd Floor Work Space Renovation Demo 3 individual offices to create one open work area approx. 1200 SF of walls to accommodate additional court staff needed to sustain court operation due to the closure of the San Bernardino				
		San				Courthouse Annex, and recent reorganization of individual Court functions which will make this Court strictly operating traffic functions. Scope includes, rerouting electrical, relocate 43 lights, 2300 SF T-Bar/ceiling tile, 2100 SF carpet, patch				
159	FM-0051586	Bernardino	Fontana Courthouse	36-C1	2		\$	82,424	\$ 82,424	100.00
						Elevator - Replace old obsolete Imtra stepper switch with new solid state universal electronic stepper switch. Currently				
						the existing stepper switch is at end of life and is intermittently failing causing the holding elevator #6 to shut down which resulted in a recent entrapment. Each time the stepper switch intermittently fails it prevents the elevator from				
		San				being able to recognize what floor cart is on causing the elevator to automatically shut down possibly resulting in an				
160	FM-0051647	Bernardino	Rancho Cucamonga Courthouse	36-F1	1	entrapment.	\$	3,412	\$ 3,412	2 100.00
						COUNTY MANAGED - Plumbing- Replace the flue pipe on the newly installed boiler due to increased condensation created. Scope of work includes, but is not limited to, the install of a new stainless steel flue pipe inserted into an				
		San				existing vertical flue pipe. Due to offset of the piping shaft, the scope of work increased to accommodate the offset and				
161	FM-0051691	Bernardino	Rancho Cucamonga Courthouse	36-F1	2	installation.	\$	78,167	\$ 78,16	7 100.00
		San				Electrical - remove and replace all UPS Battery Back-Up batteries. Currently the UPS - Battery Back-Up unit contains batteries that are beyond useful service life, some of which have failed. All batteries must be replaced to ensure that				
162	FM-0051749	Bernardino	Juvenile Dependency Courthouse	36-P1	2	this UPS Battery Back-Up devices works when needed in emergency situations.	\$	3,237	\$ 1,765	5 54.53
						Elevators, Escalators & Hoists - Escalators (3EA) - Replace broken step threads and comb plates with broken teeth,				
163	ENA 00E1E00	Can Diago	County Counthouse	37-A1	٦	remove the excessive oil and grease and bring all escalators back to engineered specifications. These deficiencies were	\$	12 200	\$ 9,569	77.42
103	FM-0051590	San Diego	County Courthouse	37-A1	2	noted during the state inspection. Electrical - Lights and Ballast - Utilizing a lift, replace burnt out T-12 light bulbs with T-8 lights and any ballast that is not	Ş	12,360	\$ 9,569	77.42
						working in the 15 foot high lobby ceiling. Currently, more than 85% of the lighting is not working properly causing safety				
164	FM-0051605	San Diego	County Courthouse	37-A1	2	issues and tripping hazards.	\$	4,601	\$ 3,562	2 77.42
						HVAC - Boiler #2 Feed Pump - Remove and replace the complete end of Boiler #2 feed pump. Currently the pump has				
165	FM-0051646	San Diego	County Courthouse	37-A1	2		\$	3,400	\$ 2,632	77.42
						Escalator - Replace rollers on ten steps of escalator that runs from the 2nd floor down to the 1st floor. Currently the	_			
166	FM-0051745	San Diego	County Courthouse	37-A1	2	escalator has been tagged out and is not operating. HVAC - Heating Coil - Replace heating coil on AHU SBM-4. Currently the coil header is leaking at welded seem. This work	\$	3,812	\$ 2,953	1 77.42
167	FM-0051759	San Diego	County Courthouse	37-A1	2	must take place to prevent further damage to the system.	\$	5,379	\$ 4,164	77.42
	_									
169	FM-0051761	San Diego	County Courthouse	37-A1	1	HVAC - Replace failed chemical injection line. This work was completed as a P1 emergency due to the booster system tank failing causing loss of hot water to building and heating throughout the building causing a health and safety issue.	Ġ	6,806	\$ 5,269	77.42
100	1101-0051701	Jan Diego	County Courthouse	37-A1	_	HVAC - Remove and replace both condenser units on the roof. Currently Condenser 2 has a leak in the coil and is unable	7	0,000	7 3,20.	77.42
						to patch the coil and Condenser 1 has a bad compressor and is leaking. This repair must be completed due to no back up				
169	FM-0051762	San Diego	County Courthouse	37-A1	2		\$	5,880	\$ 5,880	100.00
170	FM-0051784	San Diego	County Courthouse	37-A1	1	HVAC - Repair chill water line and clean up the water and ceiling tiles that are wet. Chill water leak, leaking in judges chambers.	\$	4,707	\$ 4,707	7 100.00
			,			Electrical - Replace all 39 batteries in uninterruptible power supply system - Batteries strings failed annual performance		-		
171	FM-0051546	San Diego	Hall of Justice	37-A2	2	testing. Reliable power is needed to keep building power in case of a power outage.	\$	21,916	\$ 21,910	5 100.00
						HVAC - Butter Fly Valve - Remove and replace one (1) leaking 3" Lug Style Butterfly valve with new bolt kit, return water to the line and check new valve for any water leaks, and confirm Liebert units switch back to the Chilled water. Work				
						will require Isolating and draining the chilled water to the data center, confirm the Liebert units switch over and run on				
172	FM-0051596	San Diego	Hall of Justice	37-A2	2	the DX cooling.	\$	3,051	\$ 3,053	1 100.00

										COST
	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF CC
						COUNTY MANAGED - Shared Cost - Replacement of damaged in-ground exterior up lights at main entrance. Currently,				
173	FM-0051787	San Diego	Hall of Justice	37-A2	2	lights do not operate and fixtures need to be replaced. Requires saw cutting and removal of old in-ground light fixtures.	\$	11,781	\$ 11,7	31 100.00
17/	FM-0051564	San Diogo	Kearny Mesa Traffic Court	37-C1	,	Fire Protection - Replace exposed fire alarm wiring with covered wiring. Work is needed to comply with State Fire Marshal correction notice.	Ś	2,360	\$ 2,3	50 100.00
1/4	FIVI-0031304	San Diego	North County Regional Center -	37-C1		COUNTY MANAGED - Elevators - Hoist ropes on four (4) public elevators require immediate replacement due to safety	Ş	2,300	ξ 2,3	50 100.00
175	FM-0051540	San Diego	South	37-F1	2	concerns.	\$	24,518	\$ 24,5	18 100.00
			North County Regional Center -			Holding Cell - Intercom - Disconnect power and remove panic button from Women's cell and employee corridor. Install new intercom station in woman's cell, blank off employee corridor, and run new above ceiling grid cabling (50 ft) to the existing intercom at the Sheriff's guard station within Main Court Holding. Currently when the panic buttons are				
176	FM-0051560	San Diego	Vista Center	37-F2	2	activated, the Main Jail receiver's the signal disrupting proper communication and could lead to a safety situation.	\$	2,900	\$ 2,9	00 100.00
177	FM-0051563	San Diego	North County Regional Center - Vista Center	37-F2	2	HVAC - Failing Ball Valves - Remove and replace leaking ball valves and piping at reheats 8-3, 8-7 and 9-12. Also replace control valve for reheat 8-3. Work is needed to stop water leaks, potential slip and fall and damage to building materials.	\$	7,450	\$ 7,4	50 100.00
							_	,	,	
			North County Regional Center -			Plumbing - Install one (1) new "Acorn" air control valve assembly in place of the existing valve serving holding cell #7.				
178	FM-0051582	San Diego	Vista Center	37-F2	2	Currently there is not adequate water pressure to the sink and the toilet in holding cell #7.	\$	2,560	\$ 2,5	100.00
			North County Pagional Contar			Plumbing - Pipe Leak - Cut out leaking section of pipe and fitting, re-pipe and braze copper connections, re-insulate				
179	FM-0051698	San Diego	North County Regional Center - Vista Center	37-F2	2	repaired area, and check for leaks. Currently water is leaking from the ceiling causing a slip hazard to anyone walking in the hallway.	\$	5,531	\$ 5,5	31 100.00
							-	-,	7 0,0	
180	FM-0051607	San Diego	North County Regional Center - Traffic Annex	37-F3	1	Fire Protection - Replace leaking fire sprinkler, test water for contamination, use detection equipment to check for leaks, extract water, replace carpet, drywall, and cove base, and repaint where it is necessary. This work was completed as a P1 due to the .5 inch of water that was found due to the leaking fire sprinkler	\$	8,323	\$ 8,3	23 100.00
			North County Positional Contain			Fig. Darks time. Fig. Contain. Days and such as first all and the state of the stat				
101	FM-0051758	San Diego	North County Regional Center - Traffic Annex	37-F3	2	Fire Protection - Fire Curtain - Remove and replace fire release device (motherboard) on fire curtain #4. Currently the #4 fire curtain is non-operational because of a faulty fire release device creating a safety hazard.	ċ	2,824	\$ 2,8	100.00
101	. 11141-0031736	Jan Diego	Traine Aillex	3/-13		Fire Protection - Install load signage in courtrooms 32 and 33, install fire doors in D32 judge's chambers corridor, add	٧	2,024	2,0	100.00
			North County Regional Center -			drywall ceiling in electrical room and install exit signs in 'A' occupancy courtrooms. Work is required per fire inspection				
182	FM-0051797	San Diego	Traffic Annex	37-F3	2	deficiency list to pass fire test.	\$	18,258	\$ 18,2	100.00
						HVAC - Boiler - Remove and replace non-functioning blower motor with new and test for proper operation. Currently				
						the blower motor for Boiler #3 is not functioning. This work must be completed to keep the courthouse warm due to				
183	FM-0051551	San Diego	East County Regional Center	37-I1	2	colder weather.	\$	4,950	\$ 3,3	67.71
						Interior Finishes - Water Damage - Sanitize the Civil Business Office below AHU 14 and remove and replace the water				
19/	FM-0051581	San Diego	East County Regional Center	37-I1	2	damaged ceiling tiles. This work was due to the water overflowing from the clogged drainage piping from AHU 14 into the Civil Business Office.	\$	2,915	\$ 1,9	74 67.71
104		Juli Diego	East county regional center	5, 11	_	Interior Finish - Demo and disposal of existing quarry tile and base, ready concrete for installation, installation of	~	2,515	7 1,3	07.71
						expansion joint between old and new tile, grout, and seal. Currently 425 square feet of quarry tile has broken loose from				
185	FM-0051760	San Diego	East County Regional Center	37-I1	2	the concrete slab creating a trip and safety issue.	\$	7,142	\$ 4,8	67.71
						Security - Failing Multiplexers - Remove and replace three (3) existing Multiplexers with new like/kind/quality				
						Multiplexers; terminate, configure and test. Current units are defective and failing and need to be replaced to maintain				
		s 5:		27.16	_	required security. Each unit supports a total of 24 existing analog cameras for a total of seventy-two (72) cameras	,			
186	FM-0051779	San Diego	East County Regional Center	37-I1	2	throughout the building	\$	37,897	\$ 25,6	67.71

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Electrical - Replace existing light switch for holding cell, located in Custodial office, with Remote switch and install					
187	FM-0051575	San Mateo	Hall of Justice	41-A1	2	receiver/remote switch in the Holding area corridor.	\$	578	\$	578	100.00
188	FM-0051633	San Mateo	Hall of Justice	41-A1	2	HVAC - **COUNTY MANAGED**Replace existing 20+yr old Cooling towers (2) with new BAC towers (2) - Existing units are constantly leaking causing roof damage and at end of service life. Crane lifts will be required for removal and installation	\$	179,180	\$:	179,180	100.00
						Fire/Life/Safety - Panic Door Hardware - Remove the existing key cylinder and thumb turns from the doors and furnish and install two (2) new Von Duprin Panic bar assemblies and four (4) custom 6" x 24" push plates. The existing entry door hardware has failed for Courtroom 2B, is not code compliant and is critical for safe egress from the courtroom.					
189	FM-0051703	San Mateo	Hall of Justice	41-A1	2	Path of travel issue.	\$	9,175	\$	9,175	100.00
100	FM-0051637	Con Motos	Traffic/Small Claims Annex	41-A2	2	HVAC - Correct non-operational Economizers and replace failed duct detector - Economizers are rusted open allowing cold air into the facility/ Duct detector was disconnected due to failure.	Ś	4,775	\$	4 775	100.00
190	FIVI-0031037	San Mateo	Traffic/Sifiali Claims Affilex	41-AZ		Plumbing - Sewage Line - Excavate to access the root damaged waste line, replace the damaged section of pipe, cover	Ş	4,773	Ş	4,775	100.00
		Santa				and re-compact soil. Currently this sewage line serves the only ADA men's stall in the Santa Barbara Figueroa					
191	FM-0051673	Barbara	Santa Barbara Figueroa Division	42-B1	2	Courthouse.	\$	4,038	\$	4,038	100.00
192	FM-0051746	Santa Barbara	Santa Maria Courts Building C + D	42-F1	1	Plumbing - Replace leaking Hot and Cold Water lines - pinhole leak in Hot water line caused minor water intrusion in Melville Meeting room of Department 1 Chambers. Abate asbestos containing materials in impacted areas.	\$	13,491	\$	13,491	100.00
102	FM-0051232	Santa Clara	Hall of Justice East	43-A1	2	Fire Protection - Replace failed fire pump components; (13) PRV valves and close nipples, packing, pump bonnet, and gland hardware, (3) gauges and heat collectors. Found during 5 year testing. Required by the AHJ (Authority having jurisdiction) to achieve a fully functional fire suppression system to receive FM certification	Ś	25,612	\$	25,612	100.00
133	1101-0031232	Janta Ciara	Tian of Justice East	43.71		Plumbing - Regulatory Compliance - Received notice of violation to resolve leaks - Replace (2) check valves and assembly	7	23,012	Y	23,012	100.00
194	FM-0051695	Santa Clara	Hall of Justice (East)	43-A1	2	kit components that have failed for (2) Backflow Devices.	\$	3,216	\$	1,608	50.00
195	FM-0051654	Santa Clara	Old Courthouse	43-B2	1	Exterior Rain Gutter - Replace 200 sq ft of rotted gutters and seal on third level window area to resolve water intrusion into Judges Chambers. Water Remediation and environmental testing of chamber included.	Ś	7,346	¢	7,346	100.00
133	1101 0031034	Santa Ciara	ora courtificase	43 BZ	_	HVAC - Chiller - Replace failed Chiller parts to stop the current Freon and Oil Leaks. Scope of work includes, new O-rings,	Y	7,540	7	7,540	100.00
196	FM-0051666	Santa Clara	Old Courthouse	43-B2	2	condenser barrel gaskets, seals, valves, spacers and washers. Replace Freon and Oil, return Chiller to Factory operating levels.	Ś	8,344	Ś	8,344	100.00
							1	5,5	_		
197	FM-0051677	Santa Clara	Old Courthouse	43-B2	2	Roof Drain - Replace approx. 20 ft of rotted roof drain that is leaking into the judge's chamber. Sealing included.	\$	8,636	\$	8,636	100.00
198	FM-0051655	Santa Clara	Terraine Courthouse	43-C1	2	Plumbing - Replace wall hung toilets discharge gasket that is leaking. To get to the area of the leak, 2.5 ft of wall tile needs to be removed and replaced so it will no longer block the area of access for future replacement.	\$	4,267	\$	4,267	100.00
105	514 0054655				_		_ ا		_		100.55
199	FM-0051656	Santa Clara	Palo Alto Courthouse	43-D1	2	Elevator - Replace failed mechanical starter and contactor assembly to bring back to standard and safe operation. Plumbing - Basement - Extract pooling water on the floor and identify the cause of the encroaching water. Emergency	\$	4,574	\$	4,574	100.00
200	FM-0051658	Santa Clara	Palo Alto Courthouse	43-D1	1	clean out of lift station and verify that the pumps are operating with no problems.	\$	5,522	\$	3,647	66.04
201	FM-0051663	Santa Clara	Sunnyvale Courthouse	43-F1	2	Fire Life Safety - Notice of Violation Correction - Replace (1) riser gauge, (3) sprinkler heads, and (1) corroded pipe fitting Refill system, perform pressure and leak test. Return system to full service.	Ś	4,079	Ś	4,079	100.00
	5531003	-and clara	2, 1810 0001 1110000			Interior Finishes - Courtroom Flood - Replace 6ft of cracked black cast roof drain pipe causing flood in Dept 52 and 55 after heavy rain, Replace (48) ceiling tiles, Remediate 2964 sq ft of courtroom space and (18) chairs; includes water extraction, drying, cleaning and deodorizing, Moisture and Environmental testing performed 2x (first test was	7	.,073	Ψ	.,073	
202	FM-0051657	Santa Clara	Santa Clara Courthouse	43-G1	1	negative).	\$	25,000	\$	25,000	100.00

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE		FACILITY MODIFICATION PROGRAM SHARE % OF COST
202	FN4 00F1CC1	Conto Clava	Margan Hill Counth avec	42 NA	1	Holding cell - Flood Mitigation - Emergency unclog #1 toilet and extract grassy water, an inmate in custody stuffed toilet	۲.	4 511	ċ ,	4 511	100.00
203	FM-0051661	Santa Clara	Morgan Hill Courthouse	43-N1	1	paper, oranges, and underwear in toilet causing overflow in the cell space.	\$	4,511	\$ 4	4,511	100.00
204	FM-0051764	Santa Clara	Morgan Hill Courthouse	43-N1	2	Fire Protection - 5 Year Inspection Corrections: Replace painted sprinkler heads - 14 in the basement, Seven on the first floor, Six on the second floor. Replace five riser gauges that are out of date for calibration. HVAC-Replace hot water isolation valves (63) w/new ball valves - Currently multiple valves (35) are leaking or non-	\$	7,780	\$ 7	7,780	100.00
						operational due to end of service life; replacing all valves is the most cost effective correction for vendor access and	Ì				
205	FM-0051659	Santa Cruz	Main Courthouse	44-A1	2	'	\$	57,175	\$ 56	6,666	99.11
206	FM-0051785	Santa Cruz	Watsonville Courthouse	44-B2	2	COUNTY MANAGED - HVAC - Replace failed 12" Variable Air Volume box w/new - Variable Air Volume internal coil has become disconnected from the housing (seal), is causing major noise and possibility of leaks. Work area is above 16'.	\$	2,144	\$ 2	2,144	100.00
207	FM-0051608	Shasta	Main Courthouse	45-A1	1	Plumbing - Flood Mitigation - Extract water from two judges chambers, three jury deliberation rooms, two clerks areas and two courtrooms. Damage from flood required the replacement of multiple smoke detectors, two ceiling exhaust fans, light fixtures, ceiling tiles and one courtroom door that has been warped. HVAC - Reconfigure BAS - Modification to Variable Air Volume, Modification to BAS master level programming to return to correct function. BAS is not operating correctly and judges comfort level is severely affected. Tune BAS system for faster reaction and steady operation. Adjust heating valves for proper flow. Reprogram BAS at master level for tighter,	\$	17,300	·	7,300	100.00
208	FM-0051561	Solano	Hall of Justice	48-A1	2	reliable control.	\$	4,545	\$ 3	3,310	72.82
	FM-0051726 FM-0051687	Solano Solano	Hall of Justice Law And Justice Center	48-A1 48-A2		Plumbing - Sewer Ejector Pump - Replace failed float switches to include floats and relay controller so that sewage is ejected automatically, sump is being emptied manually several times a day until work is performed. HVAC - Air handler unit - Remove, replace and program one failed control board for the air handler unit.	\$	5,461 3,262		3,977 3,262	72.82 100.00
						Interior Finish - Replace failed electronic lock and door hardware - Install new Von Duprin Hardware - Lock is sheared	Ϊ.				
211	FM-0051678	Sonoma	Main Adult Detention Facility	49-A2	2	off. Parts are no longer available for the existing door hardware.	\$	4,197	\$ 4	4,197	100.00
212	FM-0051740	Stanislaus	Modesto Main Courthouse	50-A1	2	Grounds and Parking Lot - Remove the existing gate operator and install new wiring from pull box at gate to new sliding gate operator. Cut and re-install all new loops with new loop detectors. Install back up battery system. Ensure safe secure parking for court staff.	\$	8,255	\$ 8	8,255	100.00
	FM-0051782	Stanislaus	Modesto Main Courthouse	50-A1	1	Plumbing - Boiler - Provide all labor and materials to remove the inner-workings of the boiler, renovate them, re-install them re-fill the system, leak check the system, re-fire the boiler and re-establish all of the temperature and pressure settings - The existing boilers inner workings are failing, which would leave the Court without heat. Replacement of boilers this size (2.5 Million BTU) cost generally \$150K to \$200K each. HVAC - Building Automation Infrastructure - Provide 2 critical alarm points for control air, remote notification hardware, and programming for remote notification of critical equipment alarms. This added hardware and programming is to	\$	52,881	·	2,881	100.00
214	FM-0051803	Stanislaus	Modesto Main Courthouse	50-A1	2	address long-standing issues with frequent critical system/equipment failures that impact court operations.	\$	10,862	\$ 8	3,472	78.00
							\$ 1	1,326,879	\$ 9,521	1,097	

_											_		
***************************************	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	REQUEST TYPE	CFR DESCRIPTION	CFR TERM	FUND SOURCE	CURRENT YEAR COSTS (Includes existing costs prior to CFR term)	BUDGET YEAR COSTS	TOTAL CFR COMMITMENT (CFR Term)	REVIEW NOTES - OREFM, JBCPO, & FSO
	09-CFR002	El Dorado	09-B1	Building C	FM	Judges Bench Extension	Judges Bench Extension. This request is deemed urged because this project has been on hold since 2009. The work is requested in the criminal arraignment/pre-trial department with a calendar of over 100 cases per year. Two clerks are needed in the courtroom to effectively and efficiencly process the work.	N/A	CCF	\$ 21,350	\$ -	\$ 21,350	NO CONCERNS
	09-CFR003	El Dorado	09-C1	Cameron Park	FM	ADA Improvements	ADA Improvements to clerks counter, public restrooms, and entrance doors. This request is deemed urgent because this project has been on hold since 2009 and there are needed ADA accommodations. Currently staff must assist individuals with access limitations, such as use of a wheelchair.	N/A	CCF	\$ 58,332	\$ -	\$ 58,332	NO CONCERNS
	19-CFR006	Los Angeles	Multiple	Multiple	FM	Heath and Safety Facility Modifications	Health and Safety Facility Modifications for multiple locations. Ergonomic Adjustments to work stations, Security gate enhancements, Transaction Counter ADA; Courtroom ADA adjustments, Electrical circuitry upgrades. This request is deemed urgent due to health and safety concerns.	N/A	Fund Balance	\$ 55,955	\$ -	\$ 55,955	NO CONCERNS
	19-CFR009	Los Angeles	19-V1	East Los Angeles Courthouse	FM	ADA Improvements	Modify Judicial Assistant workstations in 7 departments. Workstations are not ergonomic friendly and have very little workspace. The electronics take up most of the space. Modifications would all be ergonomically correct. The Court deems this request urgent to address ADA accommodations.	N/A	Fund Balance	\$ 17,500	\$ -	\$ 17,500	NO CONCERNS
!	19-CFR012	Los Angeles	19-K1	Stanley Mosk Courthouse	FM	ADA Improvements	Convert one civil courtroom chambers/chamber's restroom to be wheelchair accessible. The Court deems this request urgent to address ADA accommodations.	N/A	Fund Balance	\$ 96,500	\$ -	\$ 96,500	NO CONCERNS
	19-CFR013	Los Angeles	19-H1	Glendale Courthouse	FM	Security	Add security arms/gates/spikes to the east and west sides of the lot. Parking lot is not secured and the public frequently uses the lot as an alley. This project is deemed urgent to address safety and security.	N/A	Fund Balance	\$ 175,000	\$ -	\$ 175,000	NO CONCERNS

ITEM#	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	REQUEST TYPE	CFR DESCRIPTION	CFR TERM	FUND SOURCE		CURREN I YEAR COSIS (includes existing costs prior to CFR term)	BUDGET YEAR COSTS	TOTAL CFR COMMITMENT (CFR Term)	REVIEW NOTES - OREFM, JBCPO, & FSO
7	19-CFR014	Los Angeles	19-AY1	Chatsworth Courthouse	FM	Security	Install plexiglas at front counter 16 windows long (2 ADA counters and 14 regular counters). Work is considered urgent because customers have jumped over the counter into the Clerk's Office. Customers often display anger over traffic fines and employees do not feel safe. This project will address safety and security concerns.	N/A	Fund Balance	\$ 2	100,000	\$ -	\$ 100,000	NO CONCERNS
8	19-CFR015	Los Angeles	19-T1	Metropolitan Courthouse	FM	Heath and Safety Facility Modifications	Proper electrical is needed to accommodate 60 new work stations and 2 supervisor offices in the First Floor Clerk's Office. Work is considered urgent becasue current work stations are old, falling apart, and replacement parts are no longer available. Wires are exposed and sharp jagged corners are visible and is a safety concern.	N/A	Fund Balance	\$	60,000	\$ -	\$ 60,000	NO CONCERNS
9	29-CFR001	Nevada	29-B1	Joseph Center	LEASE	Lease Renewal	Lease Renewal (7/1/14-6/30/19) This request is deemed urgent to avoid an interruption in traffic and family law case processing in the Truckee Branch Court.	5 years	Operating Budget	\$	36,619	\$ 40,518	\$ 215,116	NO CONCERNS
10	36-CEP010	San Bernardino	36-S2	Temporary Parking Lot	LEASE	Lease Extension	Month-to-month parking lease extension per contract terms for 5 months (12/1/13 - 4/30/14). This request is deemed urgent because continued temporary parking is needed until the new courthouse is complete and parking is available at the new location.	5 months	Operating Budget	œ .	143 370	\$ 60,321	\$ 60,321	NO CONCERNS
11		San Bernardino	36-F3	Rancho Training Center	LEASE	Lease Renewal	Renew lease on month-to-month basis until new training location can be established. This request is considered urgent because the AOC notice to exercise the lease renewal option is due 12/1/13, the lease will expire on 3/31/14 with no action.	1 year	Operating Budget				\$ 32,568	NO CONCERNS
12	36-CFR021	San Bernardino	36-N3	776 S. Gifford	LEASE	Lease Renewal	Renew first of three options for 5 year option (9/1/14 - 8/31/19). This request is deemed urgent because the AOC notice to exercise the renewal option is due on 2/28/14, the lease will expire on 8/31/14 without action.	5 years	Operating Budget	\$	36,294	\$ 35,008	\$ 187,968	NO CONCERNS

** ****	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	REQUEST TYPE	CFR DESCRIPTION	CFR TERM	FUND SOURCE	CURRENT YEAR COSTS		BUDGET YEAR COSTS	TOTAL CFR COMMITMENT (CFR Term)	REVIEW NOTES - OREFM, JBCPO, & FSO
				_	_	_	Renew first of three options for 5 year option (9/1/14 - 8/31/19). This request is deemed urgent because the AOC		_					
1	3 36-CFR022	San Bernardino	36-N5	780 S. Gifford	LEASE	Lease Renewal	notice to exercise the renewal option is due on 2/28/14, the lease will expire on 8/31/14 without action.	5 years	Operating Budget	\$ 68,	368	\$ 65.938	\$ 383,233	NO CONCERNS
1	4 36-CFR023	San Bernardino	36-N1	790 S. Gifford	LEASE	Lease Renewal	Renew first of two options for 3 year option (10/1/14 - 9/30/17). This request is deemed urgent because the AOC notice to exercise the reneal option is due on 3/31/14, the lease will expire on 9/30/14 with no action.	3 years	Operating Budget	\$ 104.	616	\$ 101.671	\$ 343,873	NO CONCERNS
1	5 48-CFR005	Solano	48-C1	Courage Drive Warehouse	LEASE	Lease Renewal	Lease Renewal (9/1/13-8/31/18). This request is deemed urgent becauset he existing lease expires 8/15/13. The new lease needs to be in place prior to lease expiration date to avoid a lease holdover.	5 years	Operating Budget	\$ 97	S14	\$ 96.131	\$ 508,403	NO CONCERNS
f	10 0111000	Columb	.0 01	Courage Division varieties	22,102	zease nemewar	Lease Renewal (7/2014 - 6/2016). This request is deemed	5 / 20.5	Operating			ψ σσ,τστ	ψ σσσ, ισσ	NO
1	50-CFR012	Stanislaus	50-B1	Modesto Juvenile Court	LEASE	Lease Renewal	urgent to support court operations.	2 years	Budget	\$ 2,	790	\$ 2,874	\$ 5,834	CONCERNS
1	7 50-CFR013	Stanislaus	50-F1	Modesto Traffic Court	LEASE	Lease Renewal (utility costs only)	Lease Renewal (1/1/2015 - 12/30/2019). Court deems the request urgent because no other space is available. CFR is only needed to cover the utility costs over the term of the lease.	5 years	Operating Budget	\$	591	\$ 712	\$ 3,838	NO CONCERNS
1	8 50-CFR014	Stanislaus	50-11	Bankruptcy Court Building	LEASE	New Lease of Existing Space	New lease and one-time moving costs (4/1/2014 to 3/31/2015). Court deems the request urgent because this building will be used to try multi-defendant high risk cases in Stanislaus County. These cases cannot be conducted at the Downtown Courthouse due to safety issues.	1 year	Operating Budget	\$ 63,	959	\$ 115,376	\$ 179,335	NO CONCERNS
1	9 54-CFR006	Tulare	54-J1	Visalia Convention Center	LEASE	Lease Renewal	Tulare Superior Court wishes to rent a conference room at the Visalia Convention Center to hold Small Claims Court on Mondays. The Court has been renting this space since 2009, which enables them to hold Small Claims proceedings to the benefit on the public. This day-use agreement is for all court operations on Mondays through the 2015 calendar year. This request is deemed urgent to support court operations.	2-Years	Operating Budget		955	\$ 8,124	\$ 16,079	NO CONCERNS