

Judicial Council of California

455 Golden Gate Avenue · San Francisco, California 94102-3688 www.courts.ca.gov

REPORT TO THE JUDICIAL COUNCIL

For business meeting on February 19, 2015

Title

Court Facilities: Trial Court Facility Modification Quarterly Activity Report; Quarter 1, Fiscal Year 2014–2015

Submitted by

Trial Court Facility Modification Advisory Committee Hon. David Edwin Power, Chair Agenda Item Type Information Only

Date of Report November 18, 2014

Contact

Patrick McGrath, 916-643-8051 patrick.mcgrath@jud.ca.gov

Executive Summary

The Trial Court Facility Modification Advisory Committee has completed its facility modification funding for the first quarter of fiscal year 2014–2015. In compliance with the *Trial Court Facility Modifications Policy*, adopted by the Judicial Council on July 27, 2012, the advisory body is submitting its *Trial Court Facility Modification Quarterly Activity Report: Quarter 1, Fiscal Year 2014–2015* as information for the council. This report summarizes the activities of the Trial Court Facility Modification Advisory Committee from July 1, 2014, to September 30, 2014.

Previous Council Action

The Trial Court Facility Modification Working Group was established by Judicial Council policy in 2005. The working group first met in April 2006 and operated under the *Trial Court Facility Modifications Policy*, ¹ adopted by the Judicial Council in 2005 and revised on July 27, 2012. The working group's primary oversight responsibilities included reviewing statewide facility modification requests and approving facility modification funding.

¹ As adopted in 2005, the policy was known as the *Prioritization Methodology for Modifications to Court Facilities*. When it was revised in 2012, the name also changed. See www.courts.ca.gov/documents/jc-20120727-itemG.pdf.

The working group's charge was formalized by the Judicial Council on December 14, 2012, and the working group was assigned additional oversight responsibility for the operations and maintenance of existing facilities, noncapital-related real estate transactions, energy management, and environmental management and sustainability. On April 25, 2013, the working group's status was elevated to that of advisory committee.

An updated Court-Funded Facilities Request approval process was submitted and approved by the Judicial Council on August 23, 2013, requiring all Court-Funded Facilities Requests to be reviewed and approved by the Trial Court Facility Modification Advisory Committee (TCFMAC). These submittals may include lease-related costs (e.g., lease payments and operating costs, repairs, or modifications required by a lease); allowable court operations expenditures under rule 10.810 of the California Rules of Court (e.g., equipment, furnishings, interior painting, flooring replacement or repair, furniture repair, or records storage); and other facility improvements that are not allowable court operations expenditures under rule 10.810 (e.g., facilities operations, maintenance, repairs, and modifications, but not capital projects), if they would improve a court's functioning or reduce ongoing court operating costs.

Reports previously approved by the Judicial Council are available at www.courts.ca.gov/2567.htm under Research and Reports: Conditions in Our Courts.

Methodology and Process

Funding decisions were based on the prioritization and ranking methodologies in accordance with the *Trial Court Facility Modifications Policy*. Facility modifications are assigned one of six priority categories: Priority 1–Immediate or Potentially Critical; Priority 2–Necessary, But Not Yet Critical; Priority 3–Needed; Priority 4–Does Not Meet Current Codes or Standards; Priority 5–Beyond Rated Life, But Serviceable; and Priority 6–Hazardous Materials, Managed But Not Abated. These categories are based on methods commonly used by private-sector facility management firms. Facility modifications that are determined to be Priority 1 are to be addressed immediately and regardless of whether the court occupies a shared-use facility. With current budget constraints, the TCFMAC primarily limits approvals of facility modification projects to Priority 1 and Priority 2 projects. Delaying TCFMAC approval of these projects would cause continued court closures, operational failures, and undue risk to continued court operations.

Policy and Cost Implications

During the first quarter of fiscal year 2014–2015, the TCFMAC reviewed and approved a total of 265 facility modifications for a total projected cost of \$8,418,471. The Facility Modification Program's share of these projects totals \$7,075,625. These approved projects are limited to Priority 1 emergency projects and Priority 2 critical needs projects. Please see Attachment A for a detailed list of all approved projects.

During this quarter, seven projects required additional funds in excess of \$50,000 over their original estimates. The Facility Modification Program's share of these cost increases totals

\$1,016,850. Projects that require excess costs of this magnitude are typically Priority 1 emergency projects that do not have a full scope and cost estimate developed at the onset of the project and for which significantly more work or testing is discovered after commencement.

During this quarter, 10 Court-Funded Facilities Requests (CFRs) were reviewed and approved by the TCFMAC, including requests from Fresno, Mariposa, San Bernardino, Santa Barbara, and Tulare courts. As stated above, CFR submittals may include lease-related costs, allowable court operations expenditures under rule 10.810 of the California Rules of Court, and other facility improvement costs that are not allowable under rule 10.810. See Attachment B for a detailed list of CFRs approved by the TCFMAC during the first quarter of fiscal year 2014–2015.

Implementation Efforts

The TCFMAC conducted an in person meeting on July 11, 2014 at the Sacramento field office, an out-of-cycle teleconference meeting on July 25, 2014, and a regularly scheduled teleconference on August 25, 2014, to review facility modification funding requests and to discuss the following topics:

- The committee conducted its regular review of facility modification projects lists: A (Emergency and Priority 1), B (FMs Less than \$50K), C (Cost Increases Over \$50K), D (FMs Greater than \$50K Eligible for Funding), and F (Court-Funded Facilities Requests).
- Judicial Council Real Estate staff presented an overview of leases, licenses, and dispositions of the judicial branch portfolio.
- The committee considered and unanimously approved a draft Trial Court Food Vendor
 Policy be released to the courts for comment and input. This document provides for
 standardized policies and practices for licensed vendor operations within Judicial Council—
 managed facilities.
- The committee implemented the requirements of California Rules of Court rule 10.75 (Meetings of advisory bodies), which became effective July 1, 2014.
- The committee considered and unanimously approved a six-month increase of the Judicial Council staff's preliminary approval authority for Priority 2 facility modifications from \$15,000 to \$50,000. The intent of this change is to improve responsiveness to the courts and eliminate administrative processing delays for Priority 2 projects under \$50,000, while maintaining appropriate TCFMAC oversight of the facility modification program. A permanent approval of this authority will be considered by the committee in January of 2015.
- The committee reviewed the FY 2014–2015 budget plan. The Judicial Council previously recommended approval of an augmentation to the Facility Modification Program budget of \$15 million for a 10-year period beginning in FY 2014–2015, which is now authorized in the Budget Act. This increased the budget from \$50 million in the prior fiscal year to \$65 million for the current fiscal year.
- The committee considered and unanimously approved a Judicial Council staff proposal to begin exploring participating in load-shedding programs with local utilities.
- The committee received a report on the damage that occurred at the Napa Historic Courthouse, which has been red tagged by the fire marshal and is currently fenced and

inaccessible. The three-courtroom civil and family courthouse sustained major structural damage, a water main break, fire system failure, a gas leak, elevator failure, partial roof collapse, and lighting and other fixture failures.

• The committee considered and unanimously approved a budget allocation of \$1 million for energy efficiency projects for fiscal year 2014–2015.

Next Steps

The *Trial Court Facility Modification Quarterly Activity Report, Quarter 2 of Fiscal Year 2014–2015* will be submitted to the Judicial Council in February 2015.

Attachments

- 1. Attachment A: TCFMAC Funded Project List: Quarter 1, Fiscal Year 2014–2015
- 2. Attachment B: Court-Funded Facilities Requests (CFRs): Quarter 1, Fiscal Year 2014–2015

1 0052104 Alameda Hayward Hall of Justice 01-D1 2 Phones: Heplace Interview phones: in holding cells damaged by unknown in-custodies 9 985 \$ FM. Wiley M. Manuel Courthouse 01-D3 2 Phones: Heplace approximately six hundred square feet of splined puzzle piece tile ceiling in two locations where removed for access. What the performed off courthouse 01-D3 2 In-custodly interview phones: Replace one destroyed handset on in-custodly side. Replace three phones on a strategy of the phones of the provide clear transmissions so that attorneys can hear in-custodly interview phones. Replace one destroyed handset on in-custodly side. Replace three phones on a strategy of the phones of the provide clear transmissions so that attorneys can hear in-custodly communications of the attorneys and the phones of the part of the provide clear transmissions so that attorneys can hear in-custodly interview phones. Replace one destroyed handset on in-custodly side. Replace three phones on a strategy of the phones of the provide clear transmissions so that attorneys can hear in-custodly interview phones. Replace one destroyed handset on in-custodly side. Replace three phones on a strategy of the phones of the part of the phone and the phone		FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
FM Wiley W. Manuel 2 0052138 Alameda Courthouse 01-83 2 where removed for access. Work to be performed affecthours FM- 3 0052145 Alameda Fremont Hall of Justice 01-H1 2 communications FM- 4 0052288 Alameda Hayward Hall of Justice 01-D1 2 custodies Work to be performed affecthours FM- 5 0052346 Alameda Hayward Hall of Justice 01-D1 1 performed on overtime Saturday May 31, 2014 FM- 7 0052384 Alameda Hayward Hall of Justice 01-D1 2 performed on overtime Saturday May 31, 2014 HVAC - Replace falled bearings on the 225 horsepower supply fan number one- Work to be performed offer hours FM- 8 0052384 Alameda Hayward Hall of Justice 01-D1 2 performed on overtime Saturday May 31, 2014 HVAC - Replace falled bearings on the 225 horsepower supply fan number one- Work to be performed offer hours Site - Includes a crane and reging for provide sold from the west rooftop mechanical room Site - Includes a crane and reging for provide sold from the minimum of the west rooftop mechanical room Site - Includes a crane and reging for provide sold from the minimum of the minimum		FM-			04 54	2		_ ا	005	_	005	400.00
FM Villey W. Manuel 2 0052193 Alameda	1	0052104	Alameda	Hayward Hall of Justice	01-D1			\$	985	\$	985	100.00
2 0052135 Alameda Fremont Hall of Justice 01-H1 2 communications of the performed after hours find a communication of the performed of the performed on overtime Saturday May 31, 2014 find a communication of the performed of the performed on overtime Saturday May 31, 2014 find a communication of the performed of the performed on overtime Saturday May 31, 2014 find a communication of the performed of the performed on overtime Saturday May 31, 2014 find a communication of the performed on overtime Saturday May 31, 2014 find a communication of the performed on overtime Saturday May 31, 2014 find a communication of the performed on overtime Saturday May 31, 2014 find a communication of the performed on overtime Saturday May 31, 2014 find a communication of the performed on overtime saturday find to the performed on overtime saturday find s		EN/I		Miloy M. Manuel								
FM. 3 052145 Alameda Fremont Hall of Justice 01-H1 2 communications in the service of the performed after hours of the performed on vertice the performed after hours of the performed on vertice the performed after hours of the performed on vertice the performed after hours of the performed on vertice the performed after hours of the performed on vertice the performed on vertice the performed after hours of the performe			Alameda		01_B2	2		ر	12 027	خ	12,037	100.00
attorneys side that have failed and do not provide clear transmission so that attorneys can hear in-custody 5 2,515 5 5 1 5 5 1 5 5 6 7 5 6 7 5 6 7 5 6 7 5 6 7 5 5 6 7 6 7 6 7 6 7 6 7 6 7 6 7 7		0032133	Alailleua	Courtilouse	01-03		·	ې	12,037	٦	12,037	100.00
3 0052145 Alameda Fremont Hall of Justice 01-B1 2 communications \$ 2,515 § FM- 4 0052268 Alameda Hayward Hall of Justice 01-D1 2 custodies - Work to be performed after hours \$ 2,135 § 1 telectrical - Rewire Tive light circuits which have shorted in a conduit wedding them in place so they cannot be removed to pull new wires - Install approximately 300 feet of new conduit above ceilings and pull five circuits with three wires each to re-feed existing light fixtures and associated temporary lighting - Work to be removed to pull new wires - Install approximately 300 feet of new conduit above ceilings and pull five circuits with three wires each to re-feed existing light fixtures and associated temporary lighting - Work to be removed to pull new wires - Install approximately 300 feet of new conduit above ceilings and pull five circuits with three wires each to re-feed existing light fixtures and associated temporary lighting - Work to be removed to pull new wires - Install approximately 300 feet of new conduit above ceilings and pull five circuits with three wires each to re-feed existing light fixtures and associated temporary lighting - Work to be removed to pull new wires - Install approximately 300 feet of new conduit above ceilings and pull five circuits with three wires each to re-feed existing light fixtures and associated temporary lighting - Work to be performed on overtime Saturday May 31, 2014 HVAC - Replace failed bearings on the 225 horsepower supply fan number one - Work to be performed of the remove and place fan which is in the west rooftop mechanical room \$ 47,063 \$ FM-		FM-										
Mayor Hayward Hall of Justice O1-D1 2 custodies - Work to be performed folloging cell door parts and weld securely in place - Door damaged by in-			Alameda	Fremont Hall of Justice	01-H1	2		5	2.515	Ś	2,515	100.00
4 0052268 Alameda					022			7		1		200.00
Electrical - Rewire five light circuits which have shorted in a conduit welding them in place so they cannot be removed to pull new wires - Install approximately 300 feet of new conduit above ceilings and pull five circuits with three wires each to re-feed existing light fixtures and associated temporary lighting - Work to be performed of 0052349 Alameda			Alameda	Hayward Hall of Justice	01-D1	2		\$	2,135	\$	2,135	100.00
FM- 5 0052326 Alameda Hayward Hall of Justice 01-D1 1 performed on overtime Saturday May 31, 2014 FM- 6 0052349 Alameda Courthouse 01-B3 2 site - Includes a crane and rigging to remove and place fan which is in the west moftop mechanical room 5 47,063 \$ FM- 7 0052384 Alameda Hayward Hall of Justice 01-D1 2 with ones with short cords for in-custody safety - Compliance issue 5 985 \$ FM- 8 0052398 Alameda Courthouse 01-B3 2 with ones with short cords for in-custody safety - Compliance issue 5 985 \$ FM- 8 0052398 Alameda Courthouse 01-B3 2 with ones with short cords for in-custody safety - Compliance issue 5 985 \$ FM- 9 0052399 Alameda Hall of Justice 01-B1 2 demand if weather becomes hot 10052713 Alameda Courthouse 01-B3 2 box Redwood tree with new irrigation 5 9 0052399 Alameda Hall of Justice 01-B1 2 box Redwood tree with new irrigation 5 1,835 \$ FM- 10 0052774 Alameda Courthouse 01-B3 2 box Redwood tree with new irrigation 5 1,835 \$ FM- 11 0052774 Alameda Hayward Hall of Justice 01-D1 2 box Redwood tree with new irrigation 5 1,835 \$ EM- FM- 12 0018296 Amador Courthouse 03-C1 2 courthouse 03-C1 2 courthouse 03-C1 2 box Redwood tree with new irrigation 5 1,835 \$ Exterior - Site stabilization - Install approximately 150 LF of rock retaining wall to the entire north side of building walkway and break area to eliminate the erosion and mud gathering on the sidewalk and break area to online walk and sterior said in subject to the parking as shown on the 5 244,073 \$ Parking Lots - Resurface several sections of the public and staff parking lots. Potholing and deterioration of the hearth parking as shown on the 5 244,073 \$,			·		<u> </u>		<u> </u>	
FM- Gos2349 Alameda Hayward Hall of Justice O1-D1 1 performed on overtime Saturday May 31, 2014 S 18,681 S							removed to pull new wires - Install approximately 300 feet of new conduit above ceilings and pull five circuits					
FM- 6 0052349 Alameda Courthouse 01-B3 2 site - Includes a crane and rigging to remove and place fan which is in the west rooftop mechanical room \$ 47,063 \$ FM- 7 0052384 Alameda Hayward Hall of Justice 01-D1 2 with ones with short cords for in-custody safety - Compliance issue Wiley W. Manuel 8 0052398 Alameda Courthouse 01-B3 2 Work to be performed after hours 0052398 Alameda Courthouse 01-B3 2 Work to be performed after hours 0052398 Alameda Courthouse 01-B3 2 Work to be performed after hours 0052398 Alameda Hall of Justice 01-F1 2 demand if weather becomes hot 0052399 Alameda Hall of Justice 01-B1 2 demand if weather becomes hot 00523713 Alameda Courthouse 01-B3 2 box Redwood tree with new wirrigation Vandalism - Replace falled power supply fan number one - Work to be performed off 9 0052399 Alameda Hall of Justice 01-B1 2 demand if weather becomes hot 00523713 Alameda Courthouse 01-B3 2 box Redwood tree with new irrigation Vandalism - Replace Dept. 519 holding cell interview phone handset destroyed by in-custody vandalism - Replace falled power supply wiring FM- 10 0052774 Alameda Hall of Justice 01-B1 2 box Redwood tree with new irrigation Vandalism - Replace falled power supply wiring Exterior - Site stabilization - Install approximately 150 LF of rock retaining wall to the entire north side of building walkway and break area to eliminate the erosion and mud gathering on the sidewalk and break area to concrete. Work includes histallation of 115 LF of wrought irron fence and three palses with hardware. FM- Butte County Courthouse 03-C1 2 facilities water barrier. Scaffolding required for 3-story facility. Parking Lots - Response several sections of the public and staff parking lots. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of asphalt and apply 105,000 square feet of slurry seal in several sections of the public and staff parking lots. Potholing as shown on the		FM-					with three wires each to re-feed existing light fixtures and associated temporary lighting - Work to be					
6 0052349 Alameda Courthouse 01-B3 2 site - Includes a crane and rigging to remove and place fan which is in the west rooftop mechanical room \$ 47,063 \$ FM- 7 0052384 Alameda Hayward Hall of Justice 01-D1 2 with ones with short cords for in-custody safety - Compliance issue \$ 985 \$ \$ PM- 8 0052398 Alameda Courthouse 01-B3 2 Work to be performed after hours \$ 66,030 \$ FM- 9 0052399 Alameda Hall of Justice 01-F1 2 demand if weather becomes hot \$ 42,309 \$ FM- 10 0052713 Alameda Courthouse 01-B3 2 box Redwood tree with new irrigation \$ 5 3,253 \$ PM- 10 0052774 Alameda Hayward Hall of Justice 01-D1 2 vandalism - Telephones - Replace Dept. 519 holding cell interview phone handset destroyed by in-custody vandalism - Replace failed power supply wiring \$ 1,835 \$ PM- 10 0052774 Alameda Hayward Hall of Justice 01-D1 2 vandalism - Telephones - Replace Dept. 519 holding cell interview phone handset destroyed by in-custody vandalism - Replace failed power supply wiring \$ 1,835 \$ PM- 10 0052774 Alameda Hayward Hall of Justice 01-D1 2 vandalism - Replace failed power supply wiring \$ 2,43,09 \$ PM- 13 001643 Butte County Butte County Alameda Courthouse 03-C1 2 concrete. Work includes the installation of 115 LF of force treatining wall to the entire north side of building walkway and break area to eliminate the erosion and mud gathering on the sidewalk and break area and stress cracks at main entry to facility. Restoring the reglet metal and rigid insulation will maintain the facilities water barrier. Scaffolding required for 3-story facility. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of salphl tand apply 105,000 square feet of slurry seal in several sections of the parking as shown on the	5	0052326	Alameda	Hayward Hall of Justice	01-D1	1	performed on overtime Saturday May 31, 2014	\$	18,681	\$	18,681	100.00
FM- O052398 Alameda Wiley W. Manuel O052398 Alameda Courthouse O1-B3 Viley W. Manuel O052398 Alameda Courthouse O1-B3 Viley W. Manuel O052398 Alameda Courthouse O1-B3 Viley W. Manuel O052398 Alameda O052398 Alameda Courthouse O1-B3 Viley W. Manuel O052398 Alameda O05239			Alameda		01-B3	2		\$	47,063	\$	39,439	83.80
FM- 0052398 Alameda Courthouse 01-B3 2 Work to be performed after hours FM- 0052399 Alameda Hall of Justice 01-F1 2 demand if weather becomes hot FM- 10 0052713 Alameda Courthouse 01-B3 2 FM- 11 0052774 Alameda Hayward Hall of Justice 01-B3 2 FM- 12 Vandalism - Telephones - Replace failed and leaking chiller condensing coil - Units cooling is at half capacity and will not meet 5 42,309 \$ FM- 10 0052713 Alameda Courthouse 01-B3 2 Grounds/Parking Lot - Replace dead 125' redwood tree - Remove tree and grind stump and plant (1) 24inch 5 box Redwood tree with new irrigation 5 Vandalism - Telephones - Replace Dept. 519 holding cell interview phone handset destroyed by in-custody 2 vandalism - Replace failed power supply wiring 5 1,835 \$ Exterior - Site stabilization - Install approximately 150 LF of rock retaining wall to the entire north side of building walkway and break area to eliminate the erosion and mud gathering on the sidewalk and break area 12 0018296 Amador Courthouse 03-C1 2 concrete. Work includes the installation of 115 LF of wrought iron fence and three gates with hardware. FM- 13 0010643 Butte Courthouse 04-A1 2 facilities water barrier. Scaffolding required for 3-story facility. Parking Lots - Resurface several sections of the public and staff parking lots. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of asphalt and apply 105,000 square feet of slurry seal in several sections of the parking as shown on the		FM-					Phones - In Holding Phone - Remove and replace the existing interview phone handsets in holding cell 3-C					
8 0052398 Alameda Courthouse 01-B3 2 Work to be performed after hours \$ 6,030 \$ FM-FM- 0052399 Alameda Hall of Justice 01-F1 2 demand if weather becomes hot 4052391 Alameda Courthouse 01-B3 2 box Redwood tree with new irrigation \$ 3,253 \$ FM- 0052713 Alameda Courthouse 01-B3 2 box Redwood tree with new irrigation \$ 3,253 \$ FM- 0052774 Alameda Hayward Hall of Justice 01-D1 2 vandalism - Telephones - Replace Dept. 519 holding cell interview phone handset destroyed by in-custody vandalism - Replace failed power supply wiring \$ 1,835 \$ FM- 0052774 Alameda Hayward Hall of Justice 01-D1 2 vandalism - Replace failed power supply wiring \$ 1,835 \$ FM- 0052774 Alameda Hayward Hall of Justice 01-D1 2 vandalism - Replace failed power supply wiring \$ 1,835 \$ FM- 0018296 Amador County \$ 03-C1 2 concrete. Work includes the installation of 115 LF of wrought iron fence and three gates with hardware. \$ 95,507 \$ FM- 0018296 Amador County \$ 04-A1 2 facilities water barrier. Scaffolding required for 3-story facility. Restoring the reglet metal and rigid insulation will maintain the Parking Lots - Resurface several sections of the public and staff parking lots. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of asphalt and apply 105,000 square feet of slurry seal in several sections of the parking as shown on the	7	0052384	Alameda	Hayward Hall of Justice	01-D1	2	with ones with short cords for in-custody safety - Compliance issue	\$	985	\$	985	100.00
9 0052399 Alameda Hall of Justice 01-F1 2 demand if weather becomes hot \$ 42,309 \$ FM- Wiley W. Manuel 0052713 Alameda Courthouse 01-B3 2 box Redwood tree with new irrigation 5 box Redwood tree with new irrigation 5 box Redwood tree with new irrigation 5 3,253 \$ FM- 11 0052774 Alameda Hayward Hall of Justice 01-D1 2 vandalism - Telephones - Replace Dept. 519 holding cell interview phone handset destroyed by in-custody 10052774 Alameda Hayward Hall of Justice 01-D1 2 vandalism - Replace failed power supply wiring \$ 1,835 \$ Exterior - Site stabilization - Install approximately 150 LF of rock retaining wall to the entire north side of building walkway and break area to eliminate the erosion and mud gathering on the sidewalk and break area concrete. Work includes the installation of 115 LF of wrought iron fence and three gates with hardware. \$ 95,507 \$ Exterior Renovation - Renovate - Remove, replace and repaint damaged EIFS and failing architectural metal and stress cracks at main entry to facility. Restoring the reglet metal and rigid insulation will maintain the 13 0010643 Butte Courthouse 04-A1 2 facilities water barrier. Scaffolding required for 3-story facility. Parking Lots - Resurface several sections of the public and staff parking lots. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of asphalt and apply 105,000 square feet of slurry seal in several sections of the parking as shown on the	8	0052398	Alameda	Courthouse	01-B3	2	Work to be performed after hours	\$	6,030	\$	6,030	100.00
FM- 10 0052713 Alameda Courthouse 01-B3 2 Grounds/Parking Lot - Replace dead 125' redwood tree - Remove tree and grind stump and plant (1) 24inch \$\frac{5}{3},253 \\$\$ FM- 11 0052774 Alameda Hayward Hall of Justice 01-D1 2 Vandalism - Replace Dept. 519 holding cell interview phone handset destroyed by in-custody vandalism - Replace failed power supply wiring \$\frac{5}{3},253 \\$\$ Exterior - Site stabilization - Install approximately 150 LF of rock retaining wall to the entire north side of building walkway and break area to eliminate the erosion and mud gathering on the sidewalk and break area 12 0018296 Amador Courthouse 03-C1 2 concrete. Work includes the installation of 115 LF of wrought iron fence and three gates with hardware. FM- Butte County Butte County Courthouse 04-A1 2 facilities water barrier. Scaffolding required for 3-story facility. Parking Lots - Resurface several sections of the public and staff parking lots. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of asphalt and apply 105,000 square feet of slurry seal in several sections of the parking as shown on the			Alameda		01-F1	2		ς	42 309	\$	42,309	100.00
10 0052713 Alameda Courthouse 01-B3 2 box Redwood tree with new irrigation \$ 3,253 \$	-		Marricaa		0111			7	42,303	7	+2,303	100.00
FM- 11 0052774 Alameda Hayward Hall of Justice 01-D1 2 Vandalism - Telephones - Replace Dept. 519 holding cell interview phone handset destroyed by in-custody vandalism - Replace failed power supply wiring \$ 1,835 \$ Exterior - Site stabilization - Install approximately 150 LF of rock retaining wall to the entire north side of building walkway and break area to eliminate the erosion and mud gathering on the sidewalk and break area concrete. Work includes the installation of 115 LF of wrought iron fence and three gates with hardware. \$ 95,507 \$ Exterior Renovation - Renovate - Remove, replace and repaint damaged EIFS and failing architectural metal and stress cracks at main entry to facility. Restoring the reglet metal and rigid insulation will maintain the facilities water barrier. Scaffolding required for 3-story facility. Parking Lots - Resurface several sections of the public and staff parking lots. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of asphalt and apply 105,000 square feet of slurry seal in several sections of the parking as shown on the			Alameda		01-B3	2		Ś	3.253	Ś	2,726	83.80
11 0052774 Alameda Hayward Hall of Justice 01-D1 2 vandalism - Replace failed power supply wiring \$ 1,835 \$ Exterior - Site stabilization - Install approximately 150 LF of rock retaining wall to the entire north side of building walkway and break area to eliminate the erosion and mud gathering on the sidewalk and break area concrete. Work includes the installation of 115 LF of wrought iron fence and three gates with hardware. \$ 95,507 \$ Exterior Renovation - Renovate - Remove, replace and repaint damaged EIFS and failing architectural metal and stress cracks at main entry to facility. Restoring the reglet metal and rigid insulation will maintain the Courthouse 04-A1 2 facilities water barrier. Scaffolding required for 3-story facility. \$ 244,073 \$ Parking Lots - Resurface several sections of the public and staff parking lots. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of asphalt and apply 105,000 square feet of slurry seal in several sections of the parking as shown on the					01 00			7	3,233	<u> </u>		33.33
Exterior - Site stabilization - Install approximately 150 LF of rock retaining wall to the entire north side of building walkway and break area to eliminate the erosion and mud gathering on the sidewalk and break area concrete. Work includes the installation of 115 LF of wrought iron fence and three gates with hardware. Solution Solut	11	0052774	Alameda	Hayward Hall of Justice	01-D1	2		\$	1,835	\$	1,835	100.00
13 0010643 Butte Courthouse 04-A1 2 facilities water barrier. Scaffolding required for 3-story facility. \$ 244,073 \$ Parking Lots - Resurface several sections of the public and staff parking lots. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of asphalt and apply 105,000 square feet of slurry seal in several sections of the parking as shown on the	12	FM- 0018296		New Amador County Courthouse		2	Exterior - Site stabilization - Install approximately 150 LF of rock retaining wall to the entire north side of building walkway and break area to eliminate the erosion and mud gathering on the sidewalk and break area concrete. Work includes the installation of 115 LF of wrought iron fence and three gates with hardware. Exterior Renovation - Renovate - Remove, replace and repaint damaged EIFS and failing architectural metal	\$			95,507	100.00
Parking Lots - Resurface several sections of the public and staff parking lots. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of asphalt and apply 105,000 square feet of slurry seal in several sections of the parking as shown on the			Butte	1	04-A1	2		Ś	244.073	\$	244,073	100.00
14 0052410 Butte Courthouse 04-A1 2 Loading zones, direction and control markings, and ADA parking stalls. \$ 146,000 \$		FM-		Butte County			Parking Lots - Resurface several sections of the public and staff parking lots. Potholing and deterioration of the asphalt have caused safety and erosion hazards. Remove and replace approximately 18,000 square feet of asphalt and apply 105,000 square feet of slurry seal in several sections of the parking as shown on the uploaded area map. Stripe with reflective road paint approximately 432 parking stalls, all No-Parking and	\$			146,000	100.00



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - IT Server Room - Install two new 2.5 ton AC split systems to replace temporary floor fans, project will					
	FM-		Wakefield Taylor			also require one 5 ton condensing unit and approximately 125 LF of new condenser line - Server room cannot					
15	0049202	Contra Costa	Courthouse	07-A2	2	maintain temperature and has insufficient airflow to reach critical equipment causing IT equipment failures.	\$	55,411	\$	55,411	100.00
						HVAC - Cooling tower basin and support structure - Recoat basin and replace tower support structure -					
	FM-		Wakefield Taylor			Rusted basin causing leaks - structure deterioration impacts capacity to support the cooling tower and					
16	0049210	Contra Costa	Courthouse	07-A2	2	maintain its operation - preventing impact to court.	\$	82,899	\$	82,899	100.00
	FM-		George D. Carroll			Plumbing - Main Water Line - Cut and remove an 18' long x 6' wide section of concrete; dig a trench 7' below ground; Remove and dispose of concrete and soil; Shore up trench with plywood, rails and hydraulic cylinders; Remove and replace 20 linear feet of 4 pipe; Pressure test and flush the water line pipe; Install new soil to fill trench; Replace concrete slab to match existing concrete. There is a substantial water leak in					
17	0052254	Contra Costa	Courthouse	07-F1	2	this section of pipe.	\$	54,848	\$	41,131	74.99
18	FM- 0052256	Contra Costa	Bray Courts	07-A3	2	HVAC - Boiler - Remove and replace the failing 1,800 MBH boiler. Fabricate and install a new skid for the outdoor heating hot water boiler, air separator with vent, 2 gallon chemical pot feeder, 2hp hot water circulation pump, and flue stack with in-line booster fan. Secure to existing rooftop platform. Work requires a crane and must be done off hours.	\$	45,169	\$	38,629	85.52
	FM-					Fire/Life/Safety - Alarm and Strobe - Install a notification Strobe/Audible Alarm in the break room, run 25 feet of cable and tie into the existing beam detector, Work to be done after hours. Employees continue to ignore the signage (about 3 times per week) and stand or leave items in front of the fire door sensor, this causes the fire panel to report a trouble call and requires attention from the service provider. This will provide a warning					
19	0052257	Contra Costa	Arnason Justice Center	07-E3	2	to notify employees that the sensor is being blocked	\$	3,940	\$	3,940	100.00
20	FM- 0052319	Contra Costa	Wakefield Taylor Courthouse	07-A2	2	Fire Protection - Remove sixteen (16) fire hoses; Install removable plugs on (16) existing fireman's hose valves (1.5"); Remove fire hose signage, where applicable; add (16) new 5 LB fire extinguishers. Hoses are due for replacement (every 5 yrs); This is an alternate and less expensive method of compliance.	\$	4,497	\$	4,497	100.00
	FM-		George D. Carroll			HVAC - Replace failed capacity control assembly and gasket; Replace bellows adjusting screw and gasket.					
21	0052327	Contra Costa	Courthouse	07-F1	2	Chiller has failed due to refrigerant leaks.	\$	8,465	\$	6,348	74.99
22	FM- 0052370	Contra Costa	George D. Carroll Courthouse	07-F1	2	HVAC - Recover/Weigh refrigerant to determine the amount lost due to the leak, replace failed seal; Laser align shaft on compressor and motor Replace 3 gallons oil; recharge system with R134a Refrigerant; Check systems operation - Oil seal is leaking refrigerant and the chiller will soon be non-functional	\$	7,871	\$	5,902	74.99
	FM-		George D. Carroll	J. 12	-	Electrical - At the lighting panels, Replace 3 ancillary breakers; Replace main breaker for the elevator -	T	- ,	7	2,332	155
23		Contra Costa	Courthouse	07-F1	1	Breakers failed during testing and need immediate replacement	\$	3,823	\$	2,867	74.99
	FM-		Concord-Mt. Diablo	-		Grounds and Parking Lot - Tripping hazard in the employee parking lot - Remove and replace 35 sqft of	·	, -	•	,	
24	0052397	Contra Costa	District	07-D1	2	crumbled and loose asphalt HVAC - Replace failed computer and outdated software and programming - Provide and install a new computer for the BAS system to replace the failed existing computer; Provide and install up to date BAS software (The old software ran on Windows XP); Provide remote access software; verify operation. The	\$	3,455	\$	3,455	100.00
	FM-		Wakefield Taylor			existing computer has failed. Data cannot be accessed, the system cannot receive alarms, and there is no					
25	0052751	Contra Costa	Courthouse	07-A2	2	remote access.	\$	14,526	\$	14,526	100.00

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE WAG Poplace failed computer and outdated software and programming. Provide and install a new	PRELIMINARY	AH II OVE	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - Replace failed computer and outdated software and programming - Provide and install a new computer for the BAS system to replace the failed existing computer; Provide and install up to date BAS				
						software (The old software ran on Windows XP); Provide remote access software; verify operation. The				
	FM-					existing computer has failed. Data cannot be accessed, the system cannot receive alarms, and there is no				
26	0052753	Contra Costa	Family Law Center	07-A14	2	remote access.	\$ 14,526	5 \$	14,526	100.00
	FM-		Danvilla District			Crounds and Darking Lat. Danlace 120' of wooden retaining wall that has broken down ever time. Dacks have				
27		Contra Costa	Danville District Courthouse	07-C1	2	Grounds and Parking Lot - Replace 120' of wooden retaining wall that has broken down over time- Rocks have begun to fall into the parking lot causing a tripping hazard and providing projectiles for unhappy people.	\$ 5,41 ⁴	1 6	5,414	100.00
27	FM-	Contra Costa	Del Norte County	07-01		Fire Protection - Remediation to SWO # 1347673 - Fire Panel and Device replaced - Due to Multiple false	7 3,414	+ \	3,414	100.00
28		Del Norte	Superior Court	08-A1	1	alarms and Panel Failure.	\$ 50,000) 5	30,635	61.27
	FM-		Del Norte County			Fire Protection - Provide labor and material to replace (10) 4-wire Photoelectric i3 smoke detector with	7 23/223	+		
29	0052417	Del Norte	Superior Court	08-A1	1	thermal sensor and Form C relay.	\$ 9,425	5 \$	5,775	61.27
						HVAC - New 2 Ton HVAC Split System - Server Room needs a secondary HVAC unit to keep temperatures				
						under 80 degrees. Building's HVAC is not adequate and temps have exceeded equipment tolerances				
	FM-					consistently during the summer months. Install a complete 2 ton HVAC split system. Includes all materials and				
30	0052422	El Dorado	Bldg. C	09-B1	2	labor.	\$ 13,000) \$	13,000	100.00
			D. F. Ciak Fordayal			HVAC - Replace failed refrigerant monitoring panel and program settings and RMS detectors back into the				
21	FM- 0052343	Erospo	B.F. Sisk Federal Courthouse	10-01	1	system - Refrigerant Monitoring Panel has failed and detection system is inoperable. Critical safety risk and potential to shut down chillers.	\$ 3,784	1 ¢	3,784	100.00
31	0032343	FIESHO	Courtilouse	10-01		County Managed -Exterior Shell - Doors - Replace doors - Replace one set of double glass doors (6'), install	3,704	+ \	3,764	100.00
	FM-		Humboldt County			new set of metal framed glass doors, including new panic hardware tied into alarm/lock down system. This is				
32	0052125	Humboldt	Courthouse (Eureka)	12-A1	2	a security issue as the current doors are not securing when locked down.	\$ 4,954	4 \$	4,954	100.00
			,			HVAC - Renovate - Modifications to AHU 9 controller, Modifications to controller programming to solve air	,		<u>, </u>	
	FM-		Humboldt County			temp set points, air flow amounts and schedules. Return to proper configurations for all VAV's and entire				
33	0052274	Humboldt	Courthouse (Eureka)	12-A1	2	system	\$ 4,672	1 \$	4,671	100.00
24	FM-		Humboldt County	42.44	2	HVAC - Provide and install five (5) new VFDs on exhaust and supply fans for AHUs 4, 5, 6, 7, & 8. Each VFD will	_		4.222	22.26
34	0052727	Humboldt	Courthouse (Eureka)	12-A1		be mounted on the ducting of the unit and will intercept the feed in between the disconnect and the motor. Exterior - Slip trips to be replaced at west and east exit, front main entrance and ADA access. South steps to	\$ 12,989) \$	4,333	33.36
						be painted with grit paint due to metal diamond plate surface. Anti slip tape is missing or old and not				
	FM-		Imperial County			functioning, creating a safety issue and has caused several people to fall. Concrete becomes very slippery				
35	0052320	 Imperial	Courthouse	13-A1	2	when wet	\$ 3,390) \$	3,390	100.00
		1				Fire Protection - Sprinkler Heads - Remove forty (40) Quick response heads and replace with forty (40)	, 2,23	+		
	FM-		Bakersfield Juvenile			standard response heads to match remainder of facility. Per National Fire Protection Association (NFPA)				
36	0052276	Kern	Center	15-C1	2	guidelines sprinkler heads cannot be mixed and matched in a given facility.	\$ 3,905	5 \$	2,607	66.76
						COUNTY MANAGED - Plumbing - Domestic Water Line Replacement - Remove and replace the domestic				
	FM-		Bakersfield Justice	4	_	water supply, return and distribution lines throughout the facility (each floor), the pipes have deteriorated			400 100	400.55
37	0052277	Kern	Bldg.	15-B1	2	over time and there have been many leaks occurring.	\$ 469,180) \$	469,180	100.00
	FM-		Bakersfield Juvenile			HVAC - HVAC Chiller compressor failed and subject to oil contamination from water. Removed and replaced the failed fittings, failed pressure gauge, two new driers and a new compressor. Chiller #2 offline rendering				
28	0052340	Kern	Center	15-C1	1	facility at 50 percent efficiency.	\$ 8,825	5 c	5,892	66.76
20	0002340	INCITI	CCITICI	12-01	Т	productly at 30 percent emoletics.	0,025	۲ ر	عر _ا ر د	00.70

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - Install two new 5 ton rooftop high efficiency gas electric package units: AC Units PKU #8 and PKU #9 including new Seismic Vibration Isolation Roof Curbs. A 90 ton crane will be used to remove the (2) package				
						units from the roof and lift the new units into place. Two rooftop HVAC units (5 ton each) no longer provide				
	FM-		Delano/North Kern	45.54		sufficient cooling to Judge's Chambers and the Deliberation room. Both units have had multiple parts	4 22 222		24.642	60.64
39	0052741	Kern	Court Dakensfield Constian	15-D1	2	replaced to no avail and units are operating at less than 60% capacity.	\$ 39,293	\$	24,613	62.64
40	FM-	Korn	Bakersfield Superior	15 42	2	HVAC - Replace compressor on AC-PKU to return unit to 100% functionality. HVAC BARD unit not providing	¢ 2,020	م ا	1 025	62.64
40	0052772	Kern	Court Modular	15-A2		cooling, unit has a failed compressor which must be replaced. Electrical - Remove and replace all parts involving the camshaft and governor assembly and perform	\$ 2,929	, 5 	1,835	02.04
	FM-					necessary adjustments and test operation - Failed assemblies are causing the generator to surge beyond 240-				
41	0052744	Kings	Corcoran Court	16-D1	2	250 volts during operation and threaten to damage the generator and attached load.	\$ 3,521	Ś	3,084	87.60
-	FM-		Edmund D. Edelman			Electrical - Remove and replace 4000 amp hub electrical assembly due to the existing one having a broken	7 3/3	7	3,00	
42	0051548	Los Angeles	Children's Court	19-Q1	1	handle and is a hazard if the power to the building has to be shut off.	\$ 38,082	\$	26,654	69.99
						Plumbing - Install a catch basin under the backflow check valve and trench it to the storm drain. City water				
						pressure fluctuating between a pound of pressure causing the backflow check value to purge water onto the				
	FM-		Edmund D. Edelman			ground. Catch valve is not working properly. Standing water on the floor is causing a slip hazard and the				
43	0052108	Los Angeles	Children's Court	19-Q1	2	standing water has algae growing in it.	\$ 6,925	\$	4,847	69.99
44	FM-		East Los Angeles	10.1/1	2	Fire Protection - Replace 17 concealed sprinkler heads & missing escutcheons. Missing escutcheons are no	¢ 2.705	.	2 402	77 72
44	0052109	Los Angeles	Courthouse	19-V1		Ionger manufactured therefore sprinkler heads and escutcheons must be replaced. Work is required by code. Grounds and Parking Lot - Install clearance bars at all entrance lanes and exit lanes. Remove damaged stucco	\$ 2,705)	2,102	77.72
	FM-					and replace backing then re-stucco. There are no clearance bars on the entrance and exit lanes, which has				
45		Los Angeles	Compton Courthouse	19-AG1	2	caused people with taller vehicles to hit the opening damaging the stucco.	\$ 13,025	Ś	8,613	66.13
.5	0032110	203711186163	Compton Courtnesse	13 / (01		Elevators, Escalators, & Hoists - Replace door rollers and door lock contacts on floors B, 1, 2, and 3. Check	7 13,023	+	0,010	00.13
	FM-					function of elevator and return to service. Elevator is stuck on 1st floor with doors closed. Intermittent issues				
46	0052126	Los Angeles	El Monte Courthouse	19-01	2	with doors cause elevator to go down.	\$ 8,213	\$ \$	4,773	58.12
						HVAC - Renovate the BAS - Convert the existing pneumatic controls to DDC, replace the front end control to				
						the system, install VFD's on all AHU supply fans, Isolate and eliminate all leaks throughout the system, replace				
	FM-		Clara Shortridge Foltz		_	the worn bearings on AH 19-1 AHU fan, replace the failed return air sensor on AHU 1-9 and insulate the				
		Los Angeles	Criminal Justice Center	19-L1	2	chilled and hot water piping at thirty-one (31) locations.	\$ 1,905,593	\$ \$	1,310,857	68.79
	FM-	l os Angolos	Nomically Countbours	10 41/1	1	HVAC - Replace faulty isolation valves on cooling tower pumps 1 and 2 and rebuild cooling tower pumps 1	6 20 411	ے	25 000	05.03
48	FM-	Los Angeles	Norwalk Courthouse	19-AK1	1	and 2. Electrical - Interior and Exterior Finishes - Install 5 interior lights and 2 receptacles with dedicated circuits for	\$ 29,411	<u>ې</u>	25,008	85.03
49		Los Angeles	Alhambra Courthouse	19-I1	2	the main entrance security screening. Court needs to relocate the court's main entrance.	\$ 2,741	ς	2,357	86.00
	FM-	200 / 11/80103	Beverly Hills	10 11		Plumbing - Sump Pump # 2 in basement 1 is deteriorated and not functioning properly. As of now only the	2,741	.	2,337	30.00
		Los Angeles	Courthouse	19-AQ1	2	backup pump is working in the system and this is not sufficient in the event of heavy rain.	\$ 4,847	, \$	3,854	79.52
	FM-			,		Plumbing - Install 2 new shut off valves and rebuild 4" watts backflow preventer. Currently shut off valves #1	,		,	
51	0052184	Los Angeles	Pasadena Courthouse	19-J1	2	& #2 are frozen and the backflow preventer must be rebuilt for certification.	\$ 4,938	\$ \$	3,425	69.35
			Michael D. Antonovich			Plumbing / Install a new OS&Y valve on a Febco 825YD 8" backflow device and test for certification. Currently				
	FM-		Antelope Valley			the backflow is leaking too much to test and must be replaced. Once backflow is replaced, the certification				
52	0052185	Los Angeles	Courthouse	19-AZ1	2	must be completed.	\$ 6,983	3 \$	5,133	73.51

FM NUMBER LOCATION BUILDING ID PRIORITY		MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMAT	MODIFICATION PROGRAM SHARE % OF
Michael D. Antonovich Plumbing / Depressurize system, drain building, rebuild dor			
FM- Antelope Valley every bathroom in building. Currently this device has failed			
53 0052186 Los Angeles Courthouse 19-AZ1 2 compliance.	\$ 2,620 \$	1,926	73.51
Interior Finishes / Install a galvanized gray steel hand railing approximately 4 feet long by 42 inches high to prevent people railing installed to help prevent the clerks from tripping and injurios to the personnel.	ple from tripping or falling. Currently there is not a //or falling on the floor which could cause serious	2 000	100.00
54 0052188 Los Angeles Alhambra Courthouse 19-I1 2 injuries to the personnel. FM- Grounds and Parking Lot - Install bumper post in front of bu	\$ 3,000 \$	3,000	100.00
	\$ 6,034 \$	5,457	90.43
55 0052196 Los Angeles Torrance Courthouse 19-C1 2 issue.		3,437	30.43
56 0052200 Los Angeles Airport Courthouse 19-AU1 2 from pipe onto floor, leak will get worse if not repaired projections.		4,520	77.17
FM- Exterior Finish / Replace rear entry door that is beyond repaired pro-		1,320	77.17
57 0052208 Los Angeles Burbank Courthouse 19-G1 2 rusted out and is no longer operational.	\$ 2,800 \$	2,541	90.76
Elevators, Escalators, & Hoists - Replace hoist ropes and sha		,-	
FM- way ropes are breaking/splintering and have bad spots in ro	opes, need to be replaced. Elevator is unsafe to		
58 0052212 Los Angeles Airport Courthouse 19-AU1 2 operate and is out of service.	\$ 9,533 \$	7,357	77.17
FM- Fire Protection - Replace 10" backflow and valves. Test devi	ce upon completion. 10" valve on fire main		
59 0052221 Los Angeles El Monte Courthouse 19-01 2 backflow device failed Level IV PM and requires replacement	nt. \$ 14,978 \$	8,705	58.12
Elevators, Escalators, & Hoists - Furnish, remove and install	new electronic door edge on elevator #3. Test car		
FM- Van Nuys Courthouse operations and return back to service. Doors edge sensor ha	as failed and will not close door car cannot be		
60 0052239 Los Angeles East 19-AX1 2 operated. Car at this time has been locked out on the 6th flo		3,854	89.74
Elevators, Escalators, & Hoists - Restore Elevator #3 and put			
FM- Van Nuys Courthouse motor on Elevator #3, clean all old carbon from fan before i			
61 0052241 Los Angeles East 19-AX1 2 needed new hoist fan motor. Car was in basement with doc		2,166	89.74
FM- Edmund D. Edelman Elevator emergency handheld phones do not work properly			
62 0052245 Los Angeles Children's Court 19-Q1 2 hard to hear. Replace with new ADA compliant phones.	\$ 10,174 \$	7,121	69.99
FM- Metropolitan Plumbing - Disable and remove (10) drinking fountains from		4.040	100.00
63 0052247 Los Angeles Courthouse 19-T1 2 request. FM- Electrical - Replace inoperative 42 year old. 1000 amp Auto	\$ 4,940 \$	4,940	100.00
		26.754	66.13
64 0052250 Los Angeles Compton Courthouse 19-AG1 1 to city power after and unplanned city power outage. Plumbing - Water leak from cracked plastic pipe in cafeteria	\$ 55,578 \$	36,754	66.13
FM- critical containment, disinfect 180 square feet of flooring. to			
65 0052258 Los Angeles Compton Courthouse 19-AG1 1 Dehumidifiers utilized to remove moisture form affected ar		9,012	66.13
HVAC - AHU #5 - Remove and replace a transformer and ma		3,012	00.13
FM- operation. AHU #5 had failed due to an electrical issue caus			
66 0052275 Los Angeles Alhambra Courthouse 19-I1 1 basement level.	\$ 4,494 \$	3,865	86.00
Plumbing - Water remediation, set up containment, contain		- /- 32	
walled. Removed and replaced 10ft of 2" cast drain line, 1 "			
Cleaned, bagged materials and wiped containment clean, so	et up dehumidifiers and fans to remove moisture		
FM- Van Nuys Courthouse in the leak affected area over weekend. Once area was dry	applied plaster on ceiling. ACM testing performed		
67 0052278 Los Angeles East 19-AX1 1 air clearance testing. Water leaking thru ceiling coming from	n 1st floor, safety \$ 9,192 \$	8,249	89.74

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	DREIMINARY	ESTIMATE	FACILITY	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Escalator - Coil and Brake - Remove and replace the coil and break to one escalator, work requires special					
	FM-		Stanley Mosk			rigging and the removal of the motor and gear box to access the break and coil. Currently the escalator has					
68	0052280	Los Angeles	Courthouse	19-K1	2	been taken out of service and work must be completed to bring it back to working conditions.	\$	17,010	\$	16,544	97.26
						Plumbing - Water remediation - Set up containments, demolish wall tiles around the mop sink and portion of			-	·	
						the wall. Remove and replace the leaking faucet and cracked mop sink. Replace the damaged drywall					
	FM-					(approximately 40sf) and install new wall tile. Leaky faucet, in a 2nd floor janitorial closet, dripped water					
69	0052281	Los Angeles	Norwalk Courthouse	19-AK1	1	through a cracked mop sink and into the 1st floor main lock up.	\$	8,555	\$	7,274	85.03
						Elevators, Escalators, & Hoists - Earthquake Reset - Remove and replace a selector cable, solenoid, and circuit					
						board to restore normal operation to public elevator #2. Elevator #1 and #2 stopped operating after an					
	FM-					earthquake. Earthquake safeties were reset to restore operation but public elevator #2 failed to start up due					
70	0052282	Los Angeles	Whittier Courthouse	19-AO1	1	to malfunctioning parts.	\$	4,546	\$	3,929	86.43
	FM-		San Fernando			HVAC - Install new Refrigerant Monitor System in Chiller Room. Refrigerant leak detector in not operating and					
71	0052285	Los Angeles	Courthouse	19-AC1	2	needs to be replaced.	\$	34,295	\$	28,605	83.41
						Fire Protection - Fire Panel - Remove and replace the air pressure and maintenance switches to the fire					
	FM-		Chatsworth			panel, the zone 2 for the lock up pre-action system was activated and the main fire panel would not clear it					
72	0052292	Los Angeles	Courthouse	19-AY1	1	back to normal.	\$	3,500	\$	2,933	83.80
						Grounds and Parking Lot - Remove, dispose and replace approx. 516 l/ft. of Polyurethane expansion joint and					
						backer rod filler at concrete slab in courthouse patio. Due to sprinklers that overrun, or occasional heavy rain,					
						pooled water sips through cement junctures and leaks into the ceiling and offices of the County Counsel.					
	FM-		Edmund D. Edelman			Need to treat/seal this junctures to prevent standing water from sipping through and causing damage to					
73	0052293	Los Angeles	Children's Court	19-Q1	2	underneath ceiling and offices.	\$	14,428	\$	10,098	69.99
74	FM- 0052294	Los Angeles	Pasadena Courthouse	19-J1		Plumbing - Removal of overflowing sewage from the pit and mechanical room floor. 1600 gallons of liquid waste and 1 barrel of solid waste was removed from the site to a licensed disposal site. Removed 4" to 5" of waste from the approximately 64 Sq. Ft. elevator pit. Cleaned and disinfected the area. Installed temporary pump system to remove waste from the pit, due to lead time on new grinder pumps and motors. Replace failed pumps and motors with a new Grinder Pump System. Basement sewage pumps we	\$	69,908	\$	48,481	69.35
	<u> </u>	<u> </u>	Parking Structure Lot			Grounds and Parking Lot - Parking Structure, remove, clean and fill 85 LF of rubber expansion material on		,	<u>-</u>	•	
	FM-		48 Van Nuys Court			parking roof. Rubber expansion filling will be sized cut and fit into place. Parking has broken and missing					
75	0052295	Los Angeles	Complex	19-AX6	2	rubber expansion materials on roof. Trip and fall hazards.	\$	8,928	\$	8,012	89.74
			Parking Structure Lot			•	·	·		<u>-</u>	
	FM-		48 Van Nuys Court			Plumbing - Remove existing failed 2.5" backflow and install new 2.5" double check backflow with new copper					
76	0052296	Los Angeles	Complex	19-AX6		pipe and fittings. Level 4 PM failed backflow test.	\$	8,151	\$	7,315	89.74
						Plumbing - Water remediation, set up containment in the employee lounge to prevent exposure to court					
	FM-		Santa Clarita			personnel, perform ACM testing of the affected area, containment and abatement. Water on employee					
77	0052298	Los Angeles	Courthouse	19-AD1	2	lounge floor next to wall and also on jury restroom floor next to employee lounge.	\$	3,379	\$	2,987	88.39
	FM-					Fire Protection - Perform overhaul of basement Fire Pump. Currently the fire pump is not working properly					
1	I	Los Angeles	Airport Courthouse	19-AU1		and did not pass the level IV PM.	1				

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
	FM-		Parking Structure Lot 48 Van Nuys Court			Fire Protection - Hydro test all 28 fire hoses and remove and replace 1 - 1 1/2" fire hose valve, 1- 2 1/2" fire hose valve and 1 - 2 1/2" X 1" nipple, all 3 are damaged and leaking. Level 2 PM failed - main fire system hose					
79		Los Angeles	Complex	19-AX6	2	valves and fire hoses SWO# 2425223. Once work is complete, retest hose valve.	\$	2,836	\$	2,545	89.74
	FM-	Los Angeles	Van Nuys Courthouse West	19-AX2		Fire Protection - Drain system on 10th and 8th floor. Remove and replace 3 failed pressure control valves, 2 on 10th and 1 on 8th floor, refill system and valves after work is complete. Level 2 PM failed, main fire system pressure control valves are damaged and leaking.	\$	7,964		6,409	80.48
81	FM- 0052310	Los Angeles	Norwalk Courthouse	19-AK1	1	Interior Finishes - Water remediation, set up containment, cleaned up wet ceiling tiles that dropped on the ground and setup containers to catch dripping water. Wipe and clean interior of containment, HEPA vacuumed work area inside of containment. Removed wet ceiling tiles and bagged debris for disposal. Dehumidifiers and fans were placed to expedite the drying process in the affected area. Replace affected ceiling tiles, and cleaned carpeting. Rain water penetrated thru the roof and into the Judges chambers	\$	8,013	\$	6,813	85.03
	FM-	-	Parking Structure Lot 59- Whittier Admin			Electrical - Replaced 2 door locks and 2 latches. Replaced missing circuit breakers and wiring to restore electrical power to the parking structure. Vandals broke into the electrical room and stole circuit breakers and					
82	0052312	Los Angeles	CTR	19-AO2	1	wires from multiple electrical panels. Due to this vandalism act the parking structure had no lighting.	\$	6,860	\$	5,929	86.43
	FM-		Metropolitan			Elevator - Replace failed bayonet on the elevator door. Currently public elevator #9 is out of service due to					
83	0052313	Los Angeles	Courthouse	19-T1	1	the door bayonet falling off, not allowing the doors to open or close.	\$	5,555	\$	5,252	94.54
						Fire Protection / Update fire panel and repair deficiencies found during level IV PM (Attached in the Notes &					
0.4	FM-		A: 10 11	40 4114	2	Documents section of SWO). Currently the fire panel is not compliant and this work must be completed	_	2 727	,	2.004	77.47
84		Los Angeles	Airport Courthouse	19-AU1		before the retest can be performed for the Level IV PM.	\$	3,737	\$	2,884	77.17
0.5	FM-		East Los Angeles	10.14	2	HVAC / Rebuild cooling tower pump #1 including the replacement of the shaft seal. Currently the cooling	۸ ا	C 245	<u> </u>	4.024	77 70
85	0052315	Los Angeles	Courthouse	19-V1	2	tower pump #1 is leaking from the shaft seal which could cause a flood if it fails completely.	>	6,345	>	4,931	77.72
	FM-					Fire Protection - Install one PCL460 Pyrochem kitchen hood system. Need to upgrade Fire					
		Los Angeles	Torrance Courthouse	19-C1	1	Suppression/Kitchen hood system up current code. Was out of compliance, impacting kitchen operation.	¢	4,738	¢	4,738	100.00
00	0032317	LOS Aligeres	Torrance Courtinouse	15 C1		COUNTY MANAGED - Replace failed 3/4" copper water line in ceiling. Demo and install new drywall in jury	7	4,730	Y	4,730	100.00
	FM-		Santa Clarita			room and employee lounge. Demo and install new floor tiles in jury room. Paint employee lounge and jury					
87		Los Angeles	Courthouse	19-AD1	1	room.	Ś	36,183	\$	36,183	100.00
						Plumbing - Replace Pressure Reducing Valve. Secured and Shut-off Main Water to the building, drained entire	+	00,200	τ	30,230	
						building of domestic water, once work was completed opened the shut-off valve and slowly refilled the entire					
						building, walked entire building and checked all domestic water fixtures (toilet and urinal flush valves, sinks,					
	FM-		Chatsworth			etc.) assured that all the air was let out of the system and that all fixtures worked properly, verified no water					
88	0052323	Los Angeles	Courthouse	19-AY1	2	leaks within the system. Main water pipe is shaking,	\$	4,856	\$	4,069	83.80
		_				HVAC - Chiller Compressor Has Seized - Remove and replace one failed 350 Ton OEM York compressor, piping					
						kit and 0-ring kit. Remove and replace two oil filters, oil seals and filter driers. Leak check chiller with nitrogen.					
						Install 10 new gallons of OEM oil. Evacuate system and prepare unit for new refrigerant charge. Install new R-					
	FM-					22 refrigerant, startup and test chiller operations. The compressor needs to be replaced; it is completely					
89	0052336	Los Angeles	Pasadena Courthouse	19-J1	2	locked up and not operational.	\$	162,538	\$	112,720	69.35



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
90	FM-	Los Angeles	Alhambra Courthouse	19-11	1	HVAC - Air Compressor - Remove and replace the failed 5HP/80Gal compressor #1 and restore building to normal operations. Air compressor is not operational and has caused temperature issues in all building levels	¢	11,433	¢	9,832	86.00
	FM-		Van Nuys Courthouse West	19-II	1	Interior Finishes - Water remediation - Set up containments and air movers at the 2nd, 3rd and 4th floor. Removed 12" x 80" of wet drywall on 4th fl and drilled holes in wall to help dry water between walls. Re-set 2 wall hung toilets that were leaking on 4th fl lock up, replaced bands and seals to both toilets. Containment areas were wiped clean and HEPA vacuumed. Replaced drywall, mud and sand wall. Replaced cove base on	<u>ې</u>	10,662		8,581	80.48
91		Los Angeles		19-AX2	Т.	4th and 3rd fl. Painted 4th fl hallway. Removed and replaced 85 ceiling tiles on 2nd fl and shampooed carpet.	Ş	10,002	Ş	8,381	80.48
92	FM- 0052342	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1		Plumbing - Replace failed piping on incoming steam supply from central plant to the building. Work required to maintain steam supply to building HVAC system.	\$	38,865	\$	28,830	74.18
	FM-		Van Nuys Courthouse			Fire Protection - Remove defective water level assembly and sensor probes in water storage tank. Install new sensor probes and adjust the new assembly to proper settings, test to insure proper operations when complete. High and low water sensors failed to operate during tank inspection on PM SWO 2422905.					
93	_	Los Angeles	West	19-AX2	2	Inspection found sensor probes corroded away and need to be replaced.	\$	2,809	\$	2,261	80.48
94	FM-	Los Angeles	Chatsworth Courthouse	19-AY1	2	Plumbing - Water Conditioning System - Remove and replace water treatment tanks. Water Conditioning System is leaking at upper neck connection by plastic top could cause a major leak.	¢	11,522	¢	9,655	83.80
34	FM-	LOS Aligeles	Metropolitan	13-A11		HVAC - Remove failed ABB drive, install new VFD drive and interview to existing bypass. The VFD was placed	٦	11,322	γ	9,033	83.80
95		Los Angeles	Courthouse	19-T1	2	on bypass and could not maintain the proper static air pressure throughout floor #6.	\$	4,000	\$	3,782	94.54
96	FM- 0052353	Los Angeles	Van Nuys Courthouse West	19-AX2	1	Grounds and Parking Lot - Removed damaged curtain and installed new curtain and miller edge, hauled away old damaged curtain, made all necessary adjustments. Sheriff inmate bus hit bottom rail of sally door. Door was open due to damaged door and could not be closed. Security issue.	\$	11,195	\$	9,010	80.48
97	FM-	Los Angeles	Van Nuys Courthouse West	19-AX2	1	Plumbing - Replace Leaking 2 1/2" Pipe - Shut off the water to the entire building and drain the system to perform the necessary work. Remove and replace one 10' section of 2 1/2" galvanized pipe with new 2 1/2" copper pipe, add one new 2 1/2" butter fly shut off valve.	¢	9,141	¢	7,357	80.48
37	FM-	LOS Aligeres	West	13 AA2		Elevators, Escalators, & Hoists - Elevator Door Edges - Remove and replace the elevator car door edges and place the elevator back into service. Public Elevator #2 was stuck and would not respond due to	7	3,141	7	7,337	00.40
98	0052355	Los Angeles	El Monte Courthouse	19-01	1	malfunctioning door edges on the car doors.	\$	4,789	\$	2,783	58.12
99	FM- 0052356	Los Angeles	Compton Courthouse	19-AG1	2	Plumbing - Need to bypass all 5 Cooling Units to be able to provide water to drinking fountains. All 5 cooling units will be abandon in place. Currently all 5 Cooling units for drinking fountains have failed and causing no drinking water to be available for public.	Ś	7,596	Ś	5,023	66.13
	FM-					Plumbing - Replace defective stainless steel water closet. Currently lock-up cell 10D has a defective stainless	T	7,000	7		00.20
100	0052358	Los Angeles	Compton Courthouse	19-AG1	1	steel water closet that is leaking onto the floor creating a slip hazard. HVAC - Failing Cooing Towers - Found low oil pressure in chiller and low water level in both cooling towers. Also found both 3" valves to be bad and not making up water. Added oil to chiller #1 and set up 4 hoses to help fill towers till parts came in. Removed and replaced both 3" valves and installed one new float. Removed	\$	3,535	\$	2,338	66.13
	FM-		Van Nuys Courthouse		_	and installed second float to east tower. Checked operations, calibrated and checked water levels on both					
101	_	Los Angeles	West Parking Pooth	19-AX2	1	towers. Fire Protection Peoples 10 correded sprinklers head replace 7 defective pressure gages replace banger and	\$	10,444	\$	8,405	80.48
102	FM- 2 0052361	Los Angeles	Parking Booth- Edelman Court	19-Q2	2	Fire Protection - Replace 10 corroded sprinklers head, replace 7 defective pressure gages, replace hanger and replace 10 escutcheons. Stand pipes is out of code.	Ś	3,628	\$	2,539	69.99
	1-32-20-	1		\- -			Г	-,		_,	

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
	FM-		Edmund D. Edelman			Fire Protection - Fire Pump - Re-pack the seals in the fire pump and restore the pump shafts sleeves, packing				
103	0052362	Los Angeles	Children's Court	19-Q1	2	glands, and packing bowls. Fire pump leaks every time it runs, need to re-pack seals.	\$ 2,926	\$	2,048	69.99
104	FM- 0052363	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	HVAC - Leaking Seals in Chilled Water Pumps #2 and #3 - Remove each water pump and send off to have them re-built; re-install pumps once returned and balance the system. Chilled water circulating pumps were leaking water from the shaft seal.	\$ 16,291	\$	11,207	68.79
105	FM- 0052364	Los Angeles	Long Beach Courthouse	19-Y1	2	Fire/Life/Safety - Main fire panel - Remove and replace the defective fire alarm bells at eight (8) locations throughout the building Identified in the State Fire Marshals findings during the annual inspection.	\$ 2,200	\$	1,663	75.59
106	FM- 0052365	Los Angeles	Torrance Courthouse	19-C1	2	Electrical - Insufficient Lighting - Demo existing track lights fixture and install six new 4ft light fixtures and conduit. Work requires concrete anchors into the floor deck above and seismic bracing. Lighting lumens are insufficient for work or egress.	\$ 3,413	\$	3,086	90.43
107	FM- 0052366	Los Angeles	Inglewood Courthouse	19-F1	2	Fire Protection - Replace non-functioning heat exchanger for Fire Pump #2. Currently the fire pump can not be run or the engine will overheat. This work must be completed due to the safety issue to the court. Plumbing - Water leak was found after hours. Water remediation, set up containment, dried leak affected	\$ 11,540	\$	8,604	74.56
108	FM- 0052367	Los Angeles	Van Nuys Courthouse East	19-AX1	1	area, approximately 250 SF, set up equipment to dry and clean air. Remove and replace damaged 144 SF of ceiling tiles. Water leak through acoustic ceiling tiles onto the floor on public side of 7th floor by Dept L. Slip hazard.	\$ 3,190	\$	2,863	89.74
109	FM- 0052368	Los Angeles	Burbank Courthouse	19-G1	1	Fire/Life/Safety - Exterior Shell - Remove and replace eroded concrete and re-secure the handrail to its foundation. Currently the railing at the rear exit of the building has weakened in spots and has separated from its foundation.	\$ 4,438	\$	4,028	90.76
110		Los Angeles	Mental Health Court	19-P1	2	HVAC - Failed 25 Ton Refrigerant Compressor - Remove and replace one failed 25 Ton Chiller Refrigerant Compressor, 3 pole Branch Circuit Breaker, in line Filter Drier and Three Phase Magnetic Starter. Work requires that the existing refrigerant be captured and stored until it used to re-charge the system when the work is complete.	\$ 16,020	\$	11,424	71.31
111	FM- 0052371	Los Angeles	San Fernando Courthouse	19-AC1	1	Elevators, Escalators, & Hoists - Rebuild Generator Elevator, #4, taken out of service, has a bad generator motor.	\$ 27,461	\$	22,905	83.41
112	FM- 0052374	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	Plumbing - Remove asphalt in employee parking lot, excavate a 4'x5' section to access the main, and install a new 2 way cleanout. After clean out is installed, hydro jet line, and camera to ensure line is cleaned out. 6" main sewer line keeps backing up creating a stoppage 2 times a month. Unable to fit hydro jet due to many turns in the line.	\$ 5,403	\$	3,972	73.51
113	FM- 0052375 FM-	Los Angeles	Van Nuys Courthouse East	19-AX1	1	Elevators, Escalators, & Hoists - Elevator Doors Closed and Not Responding - Removed advancing motor, replace failed contacts and re-installed the motor, tested operations and returned elevator back to service.	\$ 3,132	\$	3,132	100.00
114		Los Angeles	Parking Booth- Edelman Court	19-Q2	2	Elevators, Escalators, & Hoists - Replace the existing door operating equipment. Doors are not opening, due to broken parts and bad motor.	\$ 31,612	\$	22,125	69.99
115	FM- 0052385	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing - Setup containment area in the affected areas. Dehumidifiers and fans were placed to remove moisture in the affected area. Replaced elbow flush connection and couplings and returned toilet back to normal working conditions. A malfunctioning elbow flush connection and couplings were leaking, causing water to penetrate thru 6th floor pipe chase into the 5th floor, in room # 507. Safety and health hazards.	\$ 3,665	\$	3,665	100.00

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
	FM-					Plumbing - Opened wall to find source of leak, replace failed domestic hot water pipe inside wall. Contents of storage room as well as walls, floor, and ceiling were contaminated. Remediation/Restoration/Dispose of all					
116		Los Angeles	Torrance Courthouse	19-C1	1	contaminated items.	\$	24,866	\$	24,866	100.00
117	FM- 0052392	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	HVAC - Water remediation, set up containments. Restored coil to stop leak, replaced blower wheels, bearings, and shaft. Replaced damaged ceiling tiles. ACM sampling in affected area. Water leaking from ceiling, a blower wheel broke up and metal debris punctured the cooling coil. Water flooded the air handler room and leaked into the room below.	\$	32,662	\$	22,468	68.79
						Plumbing - 10th fl court room drinking fountain malfunctioned and leaked into 9th floor court room & jury					
112	FM-	Los Angeles	Compton Courthouse	19-AG1	1	bench room. Replace damaged ceiling tiles. Water remediation, set up containments, dehumidifiers and fans were placed to remove moisture in the leak affected area. ACM sampling.	ڔ	22,376	¢	22,376	100.00
119	FM- 0052394	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	HVAC - Replaced two defective 3 inch isolation valves, 40ft of 3 inch copper pipe and fittings. Removed ACM insulation. Insulated chilled water pipes. AHU #14-3 Air Handler leaked water from a deteriorated chilled water pipe. Chilled water isolation valves would not close properly and bypassed water. Plumbing - Remove damaged toilet and install new floor mount cell toilet, secure and assure it is working	\$	29,784	\$	20,488	68.79
	FM-		Clara Shortridge Foltz			properly. This work was completed as a P1 emergency due to the toilet leaking when flushed, which could					
120	0052408	Los Angeles	Criminal Justice Center	19-L1	1	have caused a flood to the lower floors. Plumbing - Extract water and sanitize 1st floor public lobby, 1st floor men's public restroom, level A parking,	\$	2,931	\$	2,931	100.00
121	FM- 0052409	Los Angeles	Metropolitan Courthouse	19-T1	1	and storage room. Turn off water to men's restroom and replace angle stop to urinal. Work required to remediate flooding into several rooms of the courthouse Plumbing - Removed the pumps from the facility one at a time to prevent impacting the domestic water service to the building. Pumps were rebuilt off site and returned to the building. Installed both rebuilt pumps.	\$	6,416	\$	6,066	94.54
	FM-		East Los Angeles			Domestic water booster pump #1 was seized up and would not operate. Domestic water booster pump #2					
122		Los Angeles	Courthouse	19-V1	1	was operating with noise coming from the bearings.	\$	3,877	\$	3,013	77.72
122	FM-	loc Angolos	Montal Haalth Caust	10.01	2	Electrical - Replace/install new lighting fixtures throughout building exterior. The building over night is very	۲	F 274	¢	2 020	71 21
	FM-	Los Angeles	Mental Health Court Santa Monica	19-P1	2	Interior Finishes - Demo a partition wall at Department S in support of Court Facilities reconfiguration of space. Due to the amount of cases being sent to Dept. S, the courtroom needs to be reconfigured in order to	\$	5,371		3,830	71.31
124	0052414	Los Angeles	Courthouse	19-AP1	2	maximized the usage of the space and facilitate the increasing number of courts customers.	\$	9,967	\$	9,967	100.00
125	FM- 0052427	Los Angeles	Bellflower Courthouse Parking Structure Lot	19-AL1	1	HVAC - Removed the VFD that malfunctioned and installed a new VFD. The supply fan motor VFD for AHU #5 malfunctioned and was not repairable. The Jury Assembly Room and the Public Defenders Office were affected and not getting supply air. This impacted court operations. Grounds and Parking Lot - Installed 2 new submersible pumps into the pit and re-piped the new pumps into the storm drain system for the structure; including new isolation valves and check valves. A third submersible pump was purchased for backup. New Duplex controls system was installed, water proof Hub panel installed	\$	3,991	\$	3,111	77.94
	FM-		48 Van Nuys Court			and rewired with new breakers. Flood in Judge's level parking caused by severe rain storms and sump pump					
126	0052708	Los Angeles	Complex	19-AX6	1	failure and damage to the electrical panel and control systems.	\$	36,553	\$	32,803	89.74



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
127	FM- 0052714	Los Angeles	Pasadena Courthouse	19-J1	1	HVAC - The burners in boiler #3 were replaced to restore operation and heating to the building. This is the most cost efficient option to restore heating since boilers #1, #2, & #3 will be replaced in the coming weeks. There was no heating in the building. Boiler #2 leaks water from a cracked heat exchanger and boiler #3 had deteriorated burners. Boiler #2 not repairable due to malfunctioning hot water isolation valves. The valves do not close completely. Water bypasses the valves.	\$ 3,407	\$	2,363	69.35
128	FM- 0052719	Los Angeles	Norwalk Courthouse	19-AK1	2	Interior Finishes - Marble Toilet Partition - Remove and replace a broken marble partition panel connecting two toilet stalls, work will require new mounting material and polish and seal all edges of the stone. A partition stone in the center stall has been vandalized and broken in-half, and is not able to be used by the public. The second stall door has less support due to the missing section. These represent a major safety hazard.	\$ 4,607	\$	3,917	85.03
129	FM- 0052723	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	2	Plumbing / Remove trash from sump pump pit confined space. Currently the sump pump pit is full of debris and must be removed to prevent pumps from getting damaged. Elevators - Install blank inserts in public elevators # 1-9 to prevent the passengers from pushing buttons on	\$ 3,510	\$	2,415	68.79
130	.	Los Angeles	Metropolitan Courthouse	19-T1	2	the floors that the elevator is not intended to stop. Currently the passengers are constantly pushing elevator floor buttons that are not intended to stop on, causing the elevator to time out. Also on various occasions, the elevator has got to floors where they were not intended, allowing the public to bypass weapons inspection screening.	\$ 5,425	\$	5,129	94.54
131	FM- 0052725 FM-	Los Angeles	Metropolitan Courthouse Metropolitan	19-T1	2	Elevator - Replace 1100 feet of ropes/cable for public elevator #3. Currently the elevator cable is badly rusted and rouged and is compromising the strength of the cable. Elevators - Replace failed hardware and components identified during annual Elevator Recall testing of (13)	\$ 14,999	\$	14,180	94.54
132	0052729 FM-	Los Angeles	Courthouse	19-T1	2	elevators as required by the Fire Marshall. Electrical - Replace Main 400 Amp Breaker in Emergency Electrical panel 2EHB. This work was completed as a P1 emergency due to the emergency electrical panel 2EHB main 400 amp breaker tripped and would not reset. The emergency electrical panel supplies the power to the fire panel and emergency lighting on the 1st	\$ 8,256	\$	7,805	94.54
133		Los Angeles	Airport Courthouse	19-AU1	1	and 2nd floors.	\$ 6,848	\$	5,285	77.17
134		Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	HVAC - Remove damaged shaft and parts, installed new bearing, shaft, blower wheels and tested return fan for proper operation. AHU 8-1 had broken shaft on return fan, this work is required for AHU to work properly. Holding Cell - Removed Chipped, damage and peeling paint from walls, benches and ceiling. Apply primer and re-paint holding cell allowing enough time for areas to dry. Remove floor tiles in lock up with full containment. Apply adhesive and new floor tiles. Men and women's holding cells have chipped. damaged,	14,868	\$	10,228	68.79
135	FM- 0052734 FM-	Los Angeles	Glendale Courthouse	19-H1	2	pilling paint on walls, benches and ceiling causing a health and safety issue. Main Area of Lock up have damage floor tiles causing a tripping hazard and health and safety issue. Interior Finishes - Patch holes in stone, insert wire mesh in voids, remove debris, and ensure no sharp edges in stone panels. Currently the stone panels in the panel hallways are cracked and have sharp edges which can	\$ 8,818	\$	8,818	100.00
	0052735 FM-	Los Angeles	Norwalk Courthouse	19-AK1		be a danger to the public. Fire Protection - Install two new batteries, one new power supply, and one duct detector. Currently the duct	\$ 8,260		7,023	85.03
13/	10052736	Los Angeles	Torrance Courthouse	19-C1		detector in the AHU room is defective and must be replaced.	\$ 3,590	γ	3,057	85.14

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
	E					Fire Protection - Install pendent sprinkler head in basement restroom, currently no coverage in restroom.					
12	FM-	Los Angeles	Glendale Courthouse	19-H1		Replace corroded 4" OS&Y valve on riser in basement. Lower sprinkler head in basement room for proper coverage, light fixture is blocking head. Hydro test hoses.	ر خ	5,471	Ċ	4,953	90.54
13	0 0032737	LOS Aligeles	Gleridale Courtilouse	19-П1		Coverage, light fixture is blocking head. Hydro test hoses.	Ş	5,471	Ş	4,900	90.54
13	FM- 9 0052738	Los Angeles	San Fernando Courthouse	19-AC1		Plumbing / isolate water supply to the facility, drain the hot water system, remove the damaged piping, install new piping, restore water to the facility, bleed the air from the water system, verify all fixtures in the facility are functioning, insolate the new piping, clean the area. This work was completed as a P1 emergency due to the hot water tank supply line leaking water, causing a safety hazard.	\$	3,600	\$	3,003	83.41
	FM-					Holding Cell - Furnish and Install 3 custom fences on existing gate. Align for proper operation; lubricate all moving points of friction. Check to insure proper operation. Fence on holding cells are loose and wires are cut					
14		Los Angeles	Glendale Courthouse	19-H1		causing a safety hazard	Ś	6,138	\$	6,138	100.00
-	0002733	203711186163	Grendare edurenteuse	13 111		Elevators, Escalators, & Hoists - Elevator phone system. Re-programmed phones to dial 24 hour number.	· ·	0,130	Υ	0,130	100.00
14	FM- 1 0052754	Los Angeles	Alhambra Courthouse	19-11		Checked for proper operation Elevator phone lines are not be directed to the Fujitec answering center but to another division within Fujitec. In an event of an entrapment the emergency answering center would be out of reach.	\$	3,637	\$	3,128	86.00
14	FM- 2 0052757	Los Angeles	Norwalk Courthouse	19-AK1		Plumbing - Water remediation, set up containments, disinfect affected areas. Dehumidifiers and fans were placed to remove moisture in the leak affected area. Ran plumbing snake through the affected drain and cleared the blockage. Standing water in the 2nd floor D.A.'s office and water leaking through the ceiling into the 1st fl corridor and room 104. Cause of flood was a urinal in the 2nd fl men's restroom affecting the 2nd fl D.A.'s offices, 1st fl Hallway, and rooms 104 A and 101.	\$	86,406	\$	73,471	85.03
14	FM- 3 0052758	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing - Two leaking sections in a 6 inch pipe replaced to prevent flooding and damage to court. Specifically, cut and remove, provide and install 20 feet of 6 inch copper piping, one 6 inch Victaulic copper isolation valve with gear operation, six 6 inch Victaulic copper couplings with EHP Gasket, two 6 inch adjustable band hangers with felt, one roto-hammer chain-wheel for new 6 inch valve, 30 feet of new chain with master link for new chain-wheel.	\$	10,338	\$	10,338	100.00
14	FM- 4 0052759	Los Angeles	Pomona Courthouse South	19-W1		Fire Protection - Isolate Fire Pump system, place building system in test mode, replace two (2) 4 inch Check Valves and put the system back into operation. Fire Pump System Loop Check Valves are leaking, causing the Fire Pump to send false signal to Fire Alarm Panel of General Alarm and Check Operations.	\$	4,556	\$	4,152	91.14
						Elevators, Escalators, & Hoists - Preliminary Order: 1. Shorten or adjust the hoist ropes. 2. Test operation					
	FM-		Pomona Courthouse		_	under seismic or emergency conditions. The state inspector issued a regulatory compliance to repair two					
14	5 0052764	Los Angeles	North	19-W2	2	deficiencies on elevator #1.	Ş 	4,578	\$	4,406	96.25
			Domona Courthouse			Elevators, Escalators, & Hoists - Preliminary Order: 1. Shorten or adjust the hoist ropes. 2. Test operation					
11	FM-	Los Angeles	Pomona Courthouse South	19-W1	ว	under seismic or emergency conditions. The state inspector issued a regulatory compliance to for two deficiencies on elevator #4.	ر	4,578	ċ	4,172	91.14
14	0 0032/03	ros Augeles	Michael D. Antonovich	T 2- A A T		uchicicues un cievatui #4.	٦	4,376	٦	4,1/∠	71.14
	FM-		Antelope Valley			 HVAC - Refurbish Chiller #. Chiller #1 has a bad shaft seal and it is leaking refrigerant. Additionally it is leaking					
14		Los Angeles	Courthouse	19-AZ1		refrigerant at the oil temp. control valve and oil cooler supply port.	\$	59,277	\$	43,575	73.51
- -	222.31	111165.00	Michael D. Antonovich		-	HVAC - Remove and replace (2) motor bearings, Remove and replace the seized purge pump, shaft seal		,	r	-,5.5	
	FM-		Antelope Valley			bearings, purge and return filters, oil seals and required O-Rings. Remove and replace restricted valves (two					
14	8 0052768	Los Angeles	Courthouse	19-AZ1	1	3/4" ball valves).	\$	52,069	\$	38,276	73.51



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
	FM-		Clara Shortridge Foltz			Interior Finishes - Removal and disposal of plaster from locker room ceiling (10x7 feet) due to water damage					
		Los Angeles	Criminal Justice Center	19-L1	2	and build back and paint. Currently the ceiling is exposed and the room is not in use.	\$	4,007	\$	2,756	68.79
	FM- 0052786	Los Angeles	Van Nuys Courthouse East	19-AX1	1	Elevator - Elevator Motor - Restore the existing exciter motor for Elevator #4 to manufactures specifications. This work was completed as a P1 emergency due to the elevator not responding and sitting on the 1st for with it's doors open.	Ś	2,531	\$	2,271	89.74
	FM-					Electrical - NTC-AQ 350 Kw Generator - Replace - Generator is too close to the school to run. Notice of	7		т		
151	0052837	Los Angeles	El Monte Courthouse	19-01	2	Violation received from SCAMQD.	\$	385,000	\$	223,762	58.12
152	FM- 0052181	Madera	Madera County Superior Court	20-A1		HVAC - The compressor has no oil pressure and needs to be replaced. The compressor refrigerant valves will be shut off and the compressor refrigerant recovered. A new Semi-Hermetic Compressor will be installed along with a new crank case heater. The system will be started up and the system topped off with customer supplied R-22 refrigerant - The chiller is only running on 3 compressors and with the summer heat approaching, the chiller will have a hard time keeping up with the cooling demand.	\$	10,793	\$	7,771	72.00
153	FM- 0052187	Madera	Madera County Superior Court	20-A1	2	HVAC - Replace failed copper refrigerant line between the TXV and the Evaporator. This will require recovering the entire refrigerant out of the system and replacing the copper line. The system will be pulled in a vacuum and leak checked. The refrigerant dryer will be replaced and old refrigerant reinstalled, any additional refrigerant needed will be supplied by Pride - To meet EPA regulation on leak repairs	Ś	3,524	\$	2,537	72.00
	FM-					Secretary of the secret	'	- / -	'	,	
154	0052135	Mendocino	County Courthouse	23-A1	2	HVAC - Replace - Remove and replace malfunctioning actuator	\$	2,634	\$	1,781	67.62
	FM-					HVAC - Emergency replacement -Remove and replace leaking steam pipes on make up water supply on					
	FM-	Mendocino	County Courthouse	23-A1		boilers 1 & 2. Fire Sprinklers - Correct Deficiencies - Install signage for the control vale at riser 1, 2 and 3.Replace broken standpipe 2-1/2 gate valve located at the roof top level. Provide labor and material to replace fifteen (15)	\$	7,228		4,888	67.62
	0052324 FM-	Mendocino	County Courthouse New Downtown	23-A1		loaded/painted/bent sprinkler heads Security - Cut hole into existing wall to install a 3' X 4' mirrored glass window - For added security the	\$	4,252	\$	2,875	67.62
	0052383	Merced	Merced Courthouse	24-A8	2	supervisor needs to see the counter area from	Ś	4,689	ς	4,689	100.00
158	FM- 0052386		New Downtown Merced Courthouse	24-A8	2	Security - Sound proofing judges conference room by install R-15 blow fill in 450sqft wall that has 3 1/2" cavities - Do to privacy issues in between the judges chamber and judges conference room you can hear conversations through the walls Utilities - Install approximately 150' of new underground poly gas line that will connect the existing regulator	\$	4,211		4,211	100.00
	FM-				_	to two connection points on the building - The existing gas service is leaking and has been shut off by PG&E.				_	
	0052747 FM- 0049233		Old Court Marina Courthouse	24-A1 27-B1		The Court currently does not have gas or a heat source. Roof - Replace built up portion of the roof north side (1600 SF), shingled portion of the roof, and missing shingles on the exterior walls - due to deterioration and blisters indicating possible water intrusion and damage.	\$	42,287		40,047 42,287	100.00

	FM NUMBER	LOCATION	SHORT TITLE Security - P1 - Removed old door hardware with burned out actuator- Installed new crash bar hardware with key card access to the door on the left- New electrical controller above T-Bar ceiling- New mechanical crash					PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						bar hardware on right hand door- Modified hardware mounting holes on doors due to the crash bars					
	FM-		Salinas Courthouse-			dimension- Powered doors electrical controller and tested secure card reader- Door is now secure and poses					
161		Monterey	North Wing	27-A1	1	no security threat.	Ś	4,384	\$	4,384	100.00
101	0032220	ivionicercy	Troitin Wing	2, , , ,		Electrical - Inadequate Lighting - Replace (5) recessed down lights with 2x2 reflective lighting fixtures to	-	1,301	Υ	1,301	100.00
	FM-		Salinas Courthouse-			produce more lighting in the closed area. Current lighting in public hallway is dark and is creating a safety					
162	0052252	Monterey	North Wing	27-A1	2	concern for the judges and staff when entering the secured area from the hallway lobby	\$	3,465	\$	3,465	100.00
	FM-	<u> </u>	Salinas Courthouse-			Elevator/Lifts/Hoists - Wheel Chair Lift - Remove and replace failed Vonduprin door latch safety and rewire as	<u> </u>	,	·	,	
163	0052253	Monterey	North Wing	27-A1	2	needed. Perform start up and full operational testing and return to service.	\$	4,237	\$	4,237	100.00
	FM-		Salinas Courthouse-			Fire Life Safety - Replace failed fire pump bearing packing - after hours work needed - This is allowing a loss of					
164	0052376	Monterey	North Wing	27-A1	2	sprinkler system water and effects the performance of the fire pump.	\$	4,009	\$	4,009	100.00
	FM-		Salinas Courthouse-			Elevator 1 and 4. Identified failed ram packing at time of service. There is a active hydraulic fluid leak in both					
165	0052407	Monterey	North Wing	27-A1	2	elevators.	\$	13,233	\$	13,233	100.00
						Interior Finishes - Install 1300 square feet of 1" thick Fabric wrapped acoustical panels inside existing wall					
	FM-					molding in courtroom. The echoing while speaking is effecting the judges concentration while making					
166	0052761	Monterey	Marina Courthouse	27-B1	2	decisions.	\$	10,759	\$	10,759	100.00
	FM-		Salinas Courthouse-								
167	0052771	Monterey	North Wing	27-A1	2	HVAC - Replace (1) failed evaporator coil for the electrical room. Room is hitting the 80s is temperature.	\$	2,362	\$	2,362	100.00
	FM-										
168	0052710	Napa	Criminal Court Building	28-A1	2	HVAV - Replace failed compressor #1 lockout control module	\$	3,397	\$	3,397	100.00
						HVAC - VFD for AH16 remove existing defective starter and replace with 25hp ABB VFD and transducer for					
	FM-			22.44		control of AH16. Presently AH16 is in the on position and cannot be shut off due to defective starter.					24.4
169	0052105	Orange	Central Justice Center	30-A1	2	Courtrooms C-48 thru C-54 affected.	\$	8,446	\$	7,700	91.17
4.70	FM-			22.44		Plumbing - Install a new steam valve with new nut and bold and gasket kit, presently valve is leaking and is		0.070			04.47
1/0	0052106	Orange	Central Justice Center	30-A1	2	causing a safety issue for staff having to work next to the unit.	\$	8,278	\$	7,547	91.17
						HVAC - Chiller 1 and associated cooling tower for Phases I and II are not tied in to the Building Automation System (BAS). This work will include installation of new Schneider Flostric programmable MR controllers, new					
						System (BAS). This work will include installation of new Schneider-Electric programmable MR controllers, new					
	FM-					current sensors with control relays for monitoring system status and providing stop/start via the BAS rather					
171		Orango	North Justice Center	20 C1	ว	than manually. New BAPI temperature sensors will also be installed as part of this project. Once installed,	ځ	4 002	خ	2 605	00.21
1/1	0052107	Orange	North Justice Center	30-C1		everything will be tested and programmed into the BAS. Install bypass valve and circulation pump to Ajax Boiler to maintain supply/return water temperature to	٦	4,092	٦	3,695	90.31
	FM-					prevent further damage to firebox & door flange due to condensation, per manufacturer's recommendation.					
172	0052143	Orange	West Justice Center	30-D1	2	See SWO 1314081 for details.	\$	5,793	\$	5,253	90.68
1/2	0002170	Orange	West sustice certici	30 01		JCC JITO 131 1001 101 GCGHIS.	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	3,733	<u> </u>	3,233	50.00
	FM-		Harbor Justice Center-			Electrical - Add GFI to main breaker for code compliance - Remove the exisiting failed Shunnt Trip breaker					
173	0052177	Orange	Newport Beach Facility	30-E1	2	from the 2000amp service and replace with a refurbished ground fault relay, includes test and certification.	Ś	9,848	\$	8,304	84.32
		<u> </u>	[<u> </u>	-,		- /	3 1.04
	FM-		Harbor Justice Center-			Grounds and Parking Lot - Lifting concrete has caused a 1.5" level change in the ADA parking path of travel.					
174	0052178	Orange	Newport Beach Facility	30-E1	2	This lifting concrete is also a trip hazard for the public.	\$	24,002	Ś	20,238	84.32



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Secure motor of exit gate by installing a lockable stainless steel arm cover to top of operator. Install magnetic lock to swing gate to prevent gate from opening if motor is inoperable. This request is due to a security					
	FM-					breach in which an individual removed the swing arm and accessed the secure parking during overtime					
175	0052182	Orange	West Justice Center	30-D1	2	business hours. See Sheriff Incident Report and SWO 1338403 for details.	\$	3,612	\$	3,612	100.00
	FM-					Roof - Degraded Roofing - Remove approximately 550 SF of degraded and wrinkled roof system down to the					
176	0052192	Orange	West Justice Center	30-D1	2	substrate. Fill in area with fiber board to match existing roof, install 2ply composite sheets set in with cold adhesive and retrofit drain. Broadcasted new granules to match existing roof.	Ś	10,875	Ś	9,861	90.68
170	0032132	Orange	West sustice certici	30 51		dantesive and retroite aram. Broadcasted new granales to materi existing root.	7	10,073	Υ	3,001	30.00
						Exterior - Concrete Renovation - Demo broken and loose concrete spalls at expansion joints, fill voids with					
						Emaco Polymer Concrete Grout. Fill large cracks in facade and spaulding by injecting epoxy. Demo large					
477	FM-	0.10.10.70	North Listing Conton	20.64	2	3'x3'x1" patch in SE wall, fill with Emaco Polymer Concrete Grout flush with surface of concrete. Paint all	,	22.254	~	20.000	00.24
1//	0052209	Orange	North Justice Center	30-C1		damaged areas to match. This is a safety issue - areas of spalling appear ready to drop.	\	22,254	\$	20,098	90.31
178	FM- 0052227	Orange	Central Justice Center	30-A1	2	Plumbing - Remediation and abatement related to P1 Flood SWO 1338385 — ACM testing and associated abatement of the VCT tile and the ceiling and wall drywall per the testing report, replace the existing carpet that has been severely damaged from the flood water, remove and replace the failed couplings on both the supply and return lines for the hot and cold coils. The flood damage occurred in the 2nd and 3rd floor secure hallway and courtroom space as well as the 2nd floor Victim Witness space; the Victim Witness space is currently closed and has impacted the operations of the court.	Ś	96,411	Ś	87,898	91.17
		U				Hazardous Material - Asbestos Abatement - Signs of delaminating of sprayed on acoustic ceiling is occurring		,	•	,	
179	FM- 0052229	Orange	West Justice Center	30-D1	2	in Department W12 Courtroom (approx. 2425 sq. ft.). Samples of acoustic ceiling material contained from 8% to 12% Chrysotile asbestos. SWO 1335104 & 1335241 was issued after particles of acoustic ceiling fell during a lamp change. Grounds - Sidewalk Flooding - Install an overflow drain to divert excess collected rain water from gravel laden	\$	30,155	\$	27,345	90.68
						planter to northeast planters. Although modifications to the planter were made under FM 1314023, planter					
	FM-					became waterlogged after heavy rain. Drainage problem is due to the difficult soil conditions (heavy					
180	0052231	Orange	West Justice Center	30-D1	2	compacted clay) that make drainage slow or fails to drain at all.	\$	6,965	\$	6,316	90.68
	FM-		Betty Lou Lamoreaux			Plumbing - Replace two 2 1/2" three piece ball valves on 3rd and 4th floors and one 1" ball valve and one 3/4" ball valves on the 2nd floor. Valves are stuck and non operational. Install two 3/4" shut off valves and replace Simmons cartridge for the shower. Functioning valves are necessary to isolate leaks, complete repairs					
181	0052271	Orange	Justice Center	30-B1	2	and avoid turning the building water off which will affect operations.	\$	6,107	\$	4,883	79.95
182	FM- 0052289	Orange	Central Justice Center	30-A1	2	Doors - Emergency Exit Roll Up Gate - Remove and replace one (1) damaged, non repairable 20' x 10' roll up gate in the basement. In case of an emergency there is no way to evacuate the vehicles in the basement. Interior Finishes - Reconfigure the existing space to create three offices, one storage room, ADA compliant public counter with glass, minor electrical, HVAC, Fire Sprinkler, carpet and paint work. Work is needed to	\$	10,336	\$	9,423	91.17
	FM-		Betty Lou Lamoreaux			relocate the Domestic Violence Assistance Program staff from the 6th floor space to proceed with the					
183	0052330	Orange	Justice Center	30-B1	2	Courtroom project under SWO 1283239	\$	85,000	\$	85,000	100.00

FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMAT	FACILITY MODIFICATION PROGRAM SHARE % OF
					Electrical - Remove and replace antiquated duplex pump system controls for ground/storm water pumping					
 FM-					stations that have far exceeded its lifespan and parts are no longer available to make the necessary repairs.					
	Orango	Most lustice Center	30 D1	2	The new duplex pump control panel will provide a reliable alternating operation of two pumps with	۲	10.254	۲	0.200	00.68
184 00523	34 Orange	West Justice Center	30-D1		automatic override control.	Ş	10,354	Ş	9,389	90.68
 FM-					Remove eroded soil from drainage field (approx. 325 sq. ft.) along east side of courthouse and replace with 1"					
185 005239	Orange	West Justice Center	30-D1	2	gravel, 2 inches thick to prevent ground and surface water from penetrating or damaging building.	ς .	3,120	¢	2,829	90.68
FM-	Orange	West Justice Certer	30 D1		Plumbing - Pipe and Flange Leak - Replace a 2' section of 4" hot water line and replace one leaking flange, at	7	3,120	7	2,023	30.00
186 00524	Onange	Central Justice Center	30-A1	2	this time the hot water line is leaking and is corroded around flange.	5	7,491	ς	6,830	91.17
100 0032 10	or Grange	Central Justice Center	30 711		Interior Finishes - Asbestos Abatement - Signs of delaminating of sprayed on acoustic ceiling has occurred in	-	7,131	7	0,030	31.17
					Department W12 Courtroom (approx. 2425 sq. ft.). FM request: SWO 1341102 was issued to abate ceiling					
					after samples of acoustic ceiling material tested positive for asbestos (samples contained from 8% to 12%					
FM-					Chrysotile asbestos). As recommended, acoustical ceiling spray of the same type throughout the facility					
187 005240)5 Orange	West Justice Center	30-D1	2	should be considered for removal before delimitation occurs.	Ś	334,444	Ś	303,274	90.68
107 0002 1	os Grange	Trest sustrice Service.	30 21		Plumbing -REGULATORY COMPLIANCE FAILURE. Replace Domestic Water Backflow #2 4305, piping Tee (1)	+	33 1, 1 1 1	<u> </u>	303,271	33.33
					and piping 90's (2) with new Wilkins 375AR. Backflow #2 failed the Backflow Prevention Device test under PM					
FM-		Betty Lou Lamoreaux			SWO 2397152. Replacement of the device is necessary due to the age of the device (23 years old), prior					
188 005240	06 Orange	Justice Center	30-B1	2	failure in 2013, to avoid repair costs and ensure the device functions properly.	Ś	6,700	Ś	5,357	79.95
					Plumbing - REGULATORY COMPLIANCE FAILURE. Replace Domestic Water Backflow #1 3881, piping Tee (1)	T		Т		10.00
					and piping 90's (2) with new Wilkins 375AR. Backflow #1 failed the Backflow Prevention Device test under PM					
FM-		Betty Lou Lamoreaux			SWO 2397150. Replacement of the device is necessary due to the age of the device (23 years old), prior					
189 00524	L5 Orange	Justice Center	30-B1	2	failure in 2013, to avoid repair costs and ensure the device functions properly.	\$	6,700	\$	5,357	79.95
					Plumbing - Remove and replace 12" of 4" domestic cold water line. Cut out the old line and install the new					
FM-					section of pipe and associated fittings. The cold water line is leaking and has damaged the ceiling in					
190 00524	L8 Orange	Central Justice Center	30-A1	2	basement.	\$	4,190	\$	3,820	91.17
					HVAC - Phase II Cooling Tower - Remove existing deteriorated distribution hot water basin from Cooling					
					Tower 2 and replace with new galvanized basin. During PM 2369098, hot water basin was found to be rusted					
FM-					and corroded through. Attached pictures show extreme rust and corrosion, as well as the placement of the					
191 00527	21 Orange	West Justice Center	30-D1	2	areas completely deteriorated through. A temporary patch was fitted under work order 1334393.	Ś	12,883	Ś	11,682	90.68
					Remove and replace leaking clay valve located in basement mechanical room. The valve regulates pressure	*	,555	7		30.00
FM-					for the domestic water to the tower at the Central Justice Center. If the valve fails domestic water will not be					
192 00527	26 Orange	Central Justice Center	30-A1	2	able to be pumped into the tower for domestic use.	\$	2,300	\$	2,097	91.17
	<u> </u>	1111111111111			Fire Protection - Remove and replace 35 existing outdated, painted sprinkler heads located in sub-basement	†	,	•	,	
					holding areas, they are old and on the verge of failing. Champion Fire will replace the fire sprinkler heads with					
FM-					new chrome 401 type pendant 155 degree fire sprinkler heads and escutcheons. All work will be done after-					
193 005273	30 Orange	Central Justice Center	30-A1	2	hours.	\$	3,850	\$	3,510	91.17

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
	FM-					Hazardous Material - Remove Abandoned Halon Suppression System - Remove all equipment and devices associated with the Halon system once used to support emergency communication equipment using C-16 certified contractor. Hard wire smoke and heat detector directly to the main fire panel and install 3 sprinkler heads to existing sprinkler system. The Halon system failed LEVEL III PM in January, re: SWO 1324561.					
194	0052742	Orange	West Justice Center	30-D1	2	Supporting documentation was obtained from Orange County Fire Authority.	\$	4,000	\$	3,627	90.68
105	FM-			22.44		Grounds and Parking Lot - Replace broken tension barrel to exit gate to judges basement parking area.				- 40-	04.47
195	0052748 FM-	Orange	Central Justice Center	30-A1		Currently the gate has to be manually raised and lowered affecting court operations HVAC - Fall Protection - Design, build, and install custom service platforms w/catwalks and fall protection to access the tops of the Cooling Towers during routine and preventative maintenance. Current conditions require two techs instead of one performing any work utilizing a temporary plywood bridge and tie offs. Working conditions are extremely dangerous. Access ladder with safety cage to elevated catwalk and	\$	5,599	<u>\$</u>	5,105	91.17
196	0052752	Orange	North Justice Center	30-C1		platform on each tower will be installed as required by OSHA.	\$	171,186	\$	154,598	90.31
197	FM- 0052769	Orange	West Justice Center	30-D1	2	Exterior - Fire Escape - Replace and treat against rust, damaged fire escape components to prevent deterioration and failure. The fire escape was replaced in 2006 but was not properly treated to prevent rapid deterioration from weather. It consists of open steel frame and deck with concrete treads and landings. Evidence of invasive rust is present throughout.	\$	5,204	\$	4,719	90.68
198	FM- 0052267	Riverside	Family Law Court	33-A1	1	HVAC - Chiller - Remove and replace failed rooftop building chiller with a new 185 ton unit. A crane will be required to remove and replace the chiller. Both compressors of the existing chiller failed within a week of each other. Additional work includes installation of additional chilled water storage to eliminate short-cycling. Fire Protection - Freight Elevator WON Fire Door - Remove and replace failed door motor and batteries of the		250,000	\$	250,000	100.00
199	FM- 0052426	Riverside	Larson Justice Center	33-C1		third floor freight elevator WON door. Work will restore door to original function as mandated by the State Fire Marshall.	\$	5,635	\$	4,554	80.81
	FM-						,	,	•	,	
200	0052838	Riverside	Family Law Court	33-A1		HVAC - Replace the 1.5 Million BTU Boiler, which has failed the recent Source testing.	\$	103,350	\$	103,350	100.00
201	FM- 0052333	Sacramento	Juvenile Courthouse	34-C2	2	HVAC - Chiller - Restore chiller tubes in Chillers 1 and 2 to factory condition - Chemical treatment and descaling required at the condenser section of chiller - no cooling for building HVAC - Replace failed 7 Ton elevator room dual HVAC unit with 7.5 ton dual unit. System maintains temps for	\$	3,519	\$	3,519	100.00
			Gordon Schaber			the elevator equipment/computers & insulate penthouse ceiling and 2 walls not insulated already. Air lift					
	FM-		Sacramento Superior			old/new units in place, remove abandoned cooling unit. Existing unit is 20 yrs old and repair is not					
202	0052783	Sacramento	Court	34-A1	1	economically feasible.	\$	49,000	\$	49,000	100.00
	FM-		Victorville Courthouse-			Elevators, Escalators, & Hoists - Rebuild limit bar, replace failed limit switches, and locate short in down					
203		San Bernardino		36-L1		circuit. Currently the wheel chair lift V-4 is non-operational creating a possible ADA compliance issue.	Ś	4,967	\$	3,191	64.25
	FM-	20.1.20.110.0110	San Bernardino		_	Elevator/Lifts/Hoists - Breaker - Electrical contractor to replace failed breaker with burnt terminal. Elevator		.,507	7	<u> </u>	323
204	0052255	San Bernardino	Courthouse - Annex	36-A2	1	contractor to test for proper operation and return car to service when complete.	\$	3,664	\$	3,502	95.58
207	FM-	C D	Earten C. II	26.61		Interior Finishes - Install containment curbs across the door thresholds and epoxy coat the floors of both hydraulic elevator mechanical rooms in order to contain a possible future hydraulic oil spill to the mechanical		2.22	<u> </u>	7.00-	02.47
205	0052266	San Bernardino	Fontana Courthouse	36-C1	2	rooms and prevent it from seeping into or through the concrete floors. Code required.	 \$	8,927	\$	7,335	82.17



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
	FM-					Interior Finishes - Install containment curbs across the door threshold and epoxy coat the floor of the hydraulic elevator mechanical room in order to contain a possible future hydraulic oil spill to the mechanical					
206		San Bernardino	Barstow Courthouse	36-J1	2	room and prevent it from seeping into or through the concrete floor. Code required.	\$	6,640	\$	5,175	77.93
207	FM- 0052270	San Bernardino	San Bernardino Courthouse	36-A1	2	Electrical - Install (2) wall mount LED fixtures to provide additional lighting for the Judges parking lot and (3) LED pole mount fixtures (including pole) to provide additional lighting for the pedestrian walkway leading to the Judges parking lot. The current lighting level in some spots associated with these areas is as low as .08fc (foot-candles) and must be increased to assure the safety of Judges accessing the lot from the new Courthouse.	\$	13,360	\$	13,360	100.00
						COUNTY MANAGED - HVAC- Chiller#1 & 2. Replacement of both chillers and control panels due to failures. One chiller has completely failed and is offline. Other chiller will not meet cooling demands in the summer on					
	FM-		Rancho Cucamonga			its own. Chillers are 30 years old. Project scope includes but is not limited to the replacement of (2) Trane					
208	0052272	San Bernardino	Courthouse	36-F1	2	centrifugal chillers, Controls and mechanical components as per the SOW.	\$	696,360	\$	696,360	100.00
209	FM- 0052404	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	COUNTY MANAGED - Fire Sprinklers - Replace approximately 200 fire sprinklers throughout the facility. The existing fire sprinklers were found to be non compliant in a recent 5 year inspection by local authorities.	\$	31,754	\$	31,754	100.00
210	FM- 0052728	San Bernardino	New San Bernardino Courthouse	36-R1	1	Grounds and Parking Lot - Sheriff's vehicle struck the South bus bay roll-up door requiring immediate service in order to secure it. The following components are damaged and need to be replaced: (8) door slats, (1) bottom door bar, (1) weather stripping, and (1) stainless guide grill. The sally port bus bay roll-up door was hit by a sheriff's vehicle and is out of operation, safety and security issue. Will pursue reimbursement from the County	\$	6,244	\$	6,244	100.00
	E.N. 4					Roof - Replace 10X30 ft. section of roof per 2014 survey including damaged counter flashing and glue					
211	FM- 0052749	San Bernardino	Juvenile Dependency Courthouse	36-P1	2	membrane spills which are pulling granules from the roof system. Work is needed to prevent roof leaks, causing damage to building structure and interior	Ś	7,865	Ś	4,289	54.53
	FM-		Barstow Courthouse	36-J1	1	Plumbing - Replace 100 gallon domestic hot water heater that is leaking from the tank. The existing hot water heater is over 20 years old and is at end of life.	\$	6,922		5,394	77.93
213	FM- 0052778	San Bernardino	Fontana Courthouse	36-C1	2	Exterior Shell - Roof - Exterior wall has cracked masonry joints in multiple locations, apply acrylic urethane sealer, and replace several deteriorated sections of roof totaling approximately 300SF. This work is necessary to prevent future leaks that were observed during the last rains.	\$	5,393	\$	4,483	83.13
	FM-		Fontana Jury Assembly			Exterior shell - Exterior walls have cracked masonry joints in multiple locations. Apply acrylic urethane sealer to masonry. This work is necessary to prevent future leaks that were observed during the last rain.	\$	5,056		5,056	100.00
215	FM-	San Diogo	Juvonilo Court	27 [1	a	Plumbing - Remove and dispose of existing water heater. Replace with 100 gallon, 275 MBH, Natural Gas	۲	7 100	ć	E 2E0	74.62
	FM-	San Diego San Diego	Juvenile Court County Courthouse	37-E1 37-A1	1	Vertical water heater and connections. Pinhole leak in existing water heater. Elevators, Escalators, & Hoists - Replaced blown fuse and bad amplifier PCB. Judge's Elevators seven and eight were not operating.	\$	7,180 2,292		5,358 2,292	100.00
217	FM- 0052339	San Diego	North County Regional Center - Vista Center	37-F2	1	Plumbing - Remediate Foul Odor - Replace the leaking joints in the 3" vent pipe. Staff in business offices, Family Law Services, Interpreters Offices, Juvenile Services and Family Court Services all reported a foul odor. Access through ceiling sections of the restrooms and Child Care Center.	\$	4,025	\$	4,025	100.00

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY	ESTIIVIATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Elevators, Escalators, & Hoists - Refurbish Court Elevator Brake Pad Lining - Remove brake shoes from machine, refurbish the pads in order to remove any, and all foreign substance from the pad surface. Re-install					
						the brake shoes and adjust for proper operation. This phase of the work includes the work to install the rated					
	FM-		South County Regional			load in the elevator plus 125% and test for accurate braking. There is a lubricant on the brake shoe lining that					
218	0052360	San Diego	Center	37-H1	2	has caused slippage of the brakes.		3,414	\$	3,414	100.00
						Elevators, Escalators, & Hoists - Remove the Generator from the mounting of elevator #8 and replace with a					
						refurbished generator. Make required modifications to the floor mounting brackets and wiring to					
	FM-		East County Regional			accommodate the new generator. Make required operational adjustments to the new generator to allow for					
219	0052715	San Diego	Center	37-I1	1	proper operation. Judge's elevator #8 was stuck.	\$ 21	,519	\$	21,519	100.00
						Furniture and Equipment - Re-spring the seat mechanism to 35 chairs to prevent a trip hazard. There are 35					
			Manual Mana Tunffia			chairs in which the spring mechanism is broken and the chair will not return to a folded position on its own.					
	FM-	Can Diago	Kearny Mesa Traffic	27.61	2	The broken chairs need to be fixed due to a recent accident in which a defendant tripped over one of the	- م	7 456	۲	7.456	100.00
220	0052/1/	San Diego	Court	37-C1		unfolded chairs and hit her face on a wooden armrest.	Ş <i>i</i>	7,456	Þ	7,456	100.00
	FM-					HVAC - Open heat exchanger one, hydro tube bundle, plug tube passes that are leaking. Replace all gaskets, hydro and check for leaks. If unit holds hydro align heat exchanger to HHW loop. Heat exchanger one, sprung a leak, losing chemicals and contaminating condensate return system. Number 2 is barely keeping up with the					
-		San Diego	County Courthouse	37-A1	2	demands of the heating loop. It is presently taking all night to come back up to set temperature.	+	5,400	\$	4,181	77.42
	FM-	S 5:		27.42	4	COUNTY MANAGED - Fire Life Safety - Emergency work required to Fire Damper and Fire Damper Motors as a	_	060	4	40.060	400.00
	FM-	San Diego	Hall of Justice	37-A2		result of the City of San Diego fire inspection deficiency notice.		,068	>	18,068	100.00
		San Diego	Juvenile Court	37-E1	2	Plumbing - Replace two backflow preventer assemblies and re-secure to piping. Backflow devices are severely corroded and leaking.	_	3,635	ċ	6,443	74.62
		Jan Diego		37-L1		HVAC - Replace non operational Chillgard monitoring system with new Chilltech LE Series Refrigeration Monitoring Device. The Chillgard monitoring system which operates with a gas sensor that determines the refrigerant concentration for the system and outputs electrical analog signal proportionate to the	, ,	5,033	<u>٧</u>	0,443	74.02
	FM-		East County Regional			concentration is not operating. This is a safety hazard, the chiller units will not shut down if there was a					
224	0052776	San Diego	Center	37-I1	2	refrigerant leak.	•	7,358	\$	4,982	67.71
						Interior Finishes - Restore existing concrete ceiling, shoring of spalling areas in sub-basement as noted in SFM					
	FM-	San Diogo	County Courthouse	27 11	2	2012 report. Deteriorated/inadequate lathe and plaster on ceiling and absorber pier support beams in north	¢ 10	706	Ļ	0.251	77.42
223	0052787	San Diego	County Courthouse	37-A1		sub-basement. Area needs to be shored to prevent falling plaster and/or risk of falling.	\$ 10	,786	٠ ا	8,351	77.42
	FM- 0052136	San Francisco	Civic Center Courthouse	38-A1	2	Interior Finishes - Correct damage in Dept 302, 303 and 206 affected by a fire sprinkler piping leak; vacuum water; expose affected drywall/insulation for drying; operate blowers, dehumidifiers; clean affected carpet; replace ceiling tiles (Dept 206); patch/paint drywall (closets) in 302, 303 and 206 (ceiling).	\$ 13	,755	\$	13,755	100.00
			Municipal Court								
	FM-		Building - Northern		_	Plumbing - Pipe leak - Evacuate water, dry effected areas, replace several damaged ceiling tiles and remove			٨	2 22-	100.00
227	0052103	San Mateo	Branch	41-C1	2	and replace 80 sf of damaged drywall.	Ş 2	2,805	\$	2,805	100.00
						Plumbing - Remediate water leak from sink - Remove loose paint from walls and remove swollen drywall,					
	FM- 0052205	San Mateo	Hall of Justice	41-A1	2	approximately 40SF, set de-humidifiers and air movers to dry the walls and ceilings, remove and replace 12 LF of rubber cove base and 40 SF of drywall and paint the damaged area.		,133	\$	6,394	52.70

	NUMBER	ATION	ILITY NAME	BUILDING ID	RIORITY			STIMATE	SILITY	DIFICATION GRAM SHARE OF LIMINARY ESTIMATE	DIFICATION GRAM SHARE % OF T
	Σ	0.0	.AC	II N	N N	SHORT TITLE		PRE STI	FAC	MOI PROI	MOI WOI PRO
	FM-		<u> </u>	ш		Electrical - Replace existing non positional exterior light fixtures (6) with motion sensor LED lights - reduced		ш		2 4 4	2 11 0
229	0052237	San Mateo	Central Branch	41-B1	2	usage facility has become a social gathering location w/trash and vandalism	\$	5,136	\$	5,136	100.00
						Grounds and Parking Lot - Install new bollards and security cable across both driveways - padlocks to be used	'	,	•	,	
						at either end: one side keyed to court Primus the other side keyed alike for SMPD and SMFD - metal parts to					
						be stainless steel - bollards to be painted safety yellow - reduced usage facility has become a social gathering					
	FM-					location w/trash and vandalism - locals are using the parking lot to park their cars creating a liability issue.					
230	0052238	San Mateo	Central Branch	41-B1	2	AOC to install appropriate signage at each driveway.	\$	5,503	\$	5,503	100.00
						Water damage remediation - Extract standing water from affected areas (55 Gal) - dry out all moisture - move	•	,	•	,	
						furniture (Desk and 7 file cabinets) to access affected areas - remove / replace damaged: ceiling tiles (300),					
	FM-					base board (30 Ft), and duct insulation (above the ceiling) (40 ft, 24" duct. –Relief valve on the floor above					
231	0052325	San Mateo	Hall of Justice	41-A1	2	failed, allowing water to flood the area below.	\$	22,601	\$	11,911	52.70
						HVAC - Forced Air Heating Units - Remove and replace 2 each failing FAU's. Failing FAU's causing Condenser	•	,	<u> </u>	,	
	FM-		Santa Maria Courts			to freeze up and system not providing adequate Cooling and Heating to Department 5 Courtroom and Judge's					
232	0052264	Santa Barbara	Building A + B	42-F3	2	Chambers.	\$	8,697	\$	2,003	23.03
	FM-		Santa Barbara Figueroa			HVAC - Replace inoperable compressor - Remove and replace the failed HVAC compressor in the IT Server		,	•	,	
233	0052279	Santa Barbara	Division	42-B1	1	room.	\$	4,020	\$	4,020	100.00
						HVAC - HVAC Unit #7 - Remove and replace a faulty inducer fan motor, igniter and front burner plate. HVAC		,		•	
	FM-		Santa Maria Juvenile			unit #7 has faulty inducer fan motor, igniter and front burner plate. Unit malfunction not providing heating					
234	0052283	Santa Barbara	Court (New)	42-H1	2	and cooling to the lobby of the Santa Maria Juvenile Center.	\$	2,726	\$	1,807	66.30
	FM-		Santa Maria Courts			HVAC - restore leaks found in Chiller #1 - Leaks found during routine PM of Chiller #1, Circuit #1 on the					
235	0052328	Santa Barbara	Building G	42-F5	1	unloaders of each compressor (2.) Chiller operating at 50% capacity causing excess strain on Chiller #2.	\$	7,069	\$	6,821	96.49
						Fire/Life/Safety - Elevator - Auto Dial Telephone - Install a new autodial telephone for Elevator recall safety					
	FM-		Santa Barbara Figueroa			requirement. The existing phone does not allow for proper communication with Elevator monitoring vendor					
236	0052423	Santa Barbara	Division	42-B1	2	due to age of system installed. Unit is not code compliant.	\$	3,622	\$	3,622	100.00
						Fire/Life/Safety - Elevator - Auto Dial Telephone - Install a new autodial telephone for Elevator recall safety					
	FM-		Santa Maria Courts			requirement. The existing phone does not allow for proper communication with Elevator monitoring vendor					
237	0052424	Santa Barbara	Building C + D	42-F1	2	due to age of system installed. Unit is not code compliant.	\$	3,622	\$	1,981	54.70
	FM-					HVAC - Chiller Compressor - Remove and replace one (1) failed 80 ton chiller compressor in the 7th floor penthouse. Work will require the use of a crane. Replace the electronic expansion and discharge check valves. Electrical, wiring, and startup of the new compressor and existing chiller is included. Refrigerant recovery of					
238		Santa Clara	Hall of Justice East	43-A1	2	approximately 50lbs. Perform acid contamination test on the refrigerant prior to recharging.	Ś	78,680	Ś	78,680	100.00
230	FM-	Janua Ciara	a or sastice East	13 /11		Plumbing - Clear (20feet) of clogged main sewer line. Install new (1) two way clean out in patio area. Jury		. 5,555	~	, 5,555	100.00
239		Santa Clara	Sunnyvale Courthouse	43-F1	2	Assembly Restroom is currently closed for use	Ś	3,940	\$	3,940	100.00
233	0002100	Janua Ciara	Jamiy vale coultilouse	13 1 1		A SECTION OF THE SECTION OF SECTION ASSET		3,340	~	3,340	100.00
	FM-		Morgan Hill			Fire protection regulatory compliance failure - Remove, replace and re-certify BF03 OM00019234 and BF04					
240		Santa Clara	Courthouse	43-N1	1	OM00020617. Work to include, replacing (1) 8" gate valve, rebuilding (1) 8" back flow and (1) 3/4" back flow.	\$	5,645	\$	5,645	100.00
3	FM-		Downtown Superior		-	Electrical - Replace (3) failed breaker's - During the planned Electrical Preventive Maintenance Service, the	T	-,	r	-,	
241		Santa Clara	Court	43-B1	1	breakers failed during the load testing due to age and worn contact points	\$	15,420	\$	15,420	100.00
	<u> </u>	1	1	=			1 .	, -	•	, -	

UMBER	LOCATION	ITY NAME	ING ID	ORITY		PRELIMINARY STIMATE	ITY FICATION RAM SHARE OF MINARY ESTIMATE	ITY FICATION RAM SHARE % OF
N N D	CA	ACILI	BUILDING	PRIOR		RELI	FACILITY MODIFICA PROGRAN	FACIL MODI PROG
FM-	<u> </u>	Santa Clara	<u> </u>		SHORT TITLE W/AC Chiller replace failed head pressure controller (1) valve and (1) actuator. Pun and test enerations	9 N		
242 0052175	Santa Clara	Courthouse	43-G1	2	HVAC Chiller - replace failed head pressure controller (1) valve and (1) actuator. Run and test operations. Chiller has failed and there is not AC in the building. Work completed after hours.	\$ 9,293	\$ 9,293	100.00
FM-	Santa Ciara	Courtilouse	45-01		Electrical - Replace (2) lights and (2) ballast. Boom truck required to complete this work, these light poles	Ş 9,295	۶ 9,295	100.00
243 0052203	 Santa Clara	Old Courthouse	43-B2	2	shine on the front of the building. Perimeter safety and security is impaired	\$ 2,799	\$ 2,79 9	100.00
FM-	Santa Ciara	Morgan Hill	73 02		Shine on the none of the banding. I chineter safety and security is impaired	2,733	2,733	100.00
	Santa Clara	Courthouse	43-N1	2	Fire Protection - Replace (1) failed FM200 storage tank, with (1) new initiator and cylinder valve assembly	\$ 11,653	\$ 11,653	100.00
211 0032202		Courtinouse	13 111		The Frotestion Replace (1) funea 11/1200 storage tarm, with (1) flew initiator and symbol valve assembly	7 11,033	Ψ 11,033	100.00
FM-					Irrigation - Leaking Shut Off Valve - Remove and replace the 2" shut off valve and assembly, once complete,			
245 0052263	Santa Clara	Old Courthouse	43-B2		test & certify the backflow prevention assembly and submit the results to the appropriate agency	\$ 2,540	\$ 2,540	100.00
					Fire/Life/Safety - Fire Roll Up Doors - Replace five (5) 3' x 8' failed Rolling Steel Fire Doors, work also requires			
FM-					the removal and replacement of five (5) Fire Releasing Devices with Battery Backup into the existing door and			
246 0052265	Santa Clara	Hall of Justice (East)	43-A1	2	restring four (4) existing doors	\$ 112,420	\$ 112,420	100.00
FM-					Exterior Shell - Sally Port Door - Remove and replace (1) failed gear head motor operator for the south sally			
247 0052344	Santa Clara	Palo Alto Courthouse	43-D1	2	port vehicle roll door.	\$ 4,178	\$ 4,178	100.00
					HVAC - Chiller #1 Electronic Expansion Valve and Compressor Control Board - Remove and replace the failed			
					EXV and I/O board to bring chiller #1 to a fully operational state to provide required cooling to building. The			
FM-			42.42	4	physical location of the EXV requires that the refrigerant be captured and the coil removed to access EXV,	44202	4420	10000
248 0052348	Santa Clara	Hall of Justice (West)	43-A2	1	once replaced, the coil will be re-installed and the refrigerant lines re-charged.	\$ 14,203	\$ 14,203	100.00
FM-	Santa Clara	Old Courthouse	42.02	2	Electrical - Emergency Generator - Remove and replace the leaking radiator, (2) radiator coolant hoses, (1) air		¢ 9.1E0	100.00
FM-	Santa Clara	Old Courthouse	43-B2		filter, (1) fan belt, fill with 50/50 mix of coolant. Run/test and return unit to full service Fire Protection - Leaking Alarm Valve - Remove and replace (1) 4" failed Alarm valve, trim piping, and retard	\$ 8,150	\$ 8,150	100.00
250 0052352	 Santa Clara	Sunnyvale Courthouse	43-F1	2	chamber. Currently valve is leaking causing potential for flooding.	\$ 7,676	\$ 7,676	100.00
230 0032332	. Santa Ciara	Samiy vaic Coartiloase	4511		Plumbing - Water Softener has failed - Cut into pieces and remove the existing water softener from the	7,070	7,070	100.00
					Penthouse, cap existing connections on water softener system and bypass the piping for domestic water. The			
					existing softener has been decommissioned for some time and has corroded. Work will require the use of a			
FM-					crane and off hours schedule.			
251 0052357	Santa Clara	Hall of Justice (East)	43-A1	2		\$ 9,578	\$ 9,578	100.00
FM-					HVAC - Replace failed ACU #4 split system Compressor Failed - Unit is specific cooling for the PBX equipment -			
252 0052396	Santa Clara	Hall of Justice (West)	43-A2	2	Replacement required to provide required equipment cooling.	\$ 3,473	\$ 3,473	100.00
FM-		Morgan Hill			Plumbing - Replace (3) feet of 1 1/2 copper pipe found in Domestic Water - Leak found during routine Rounds			
253 0052401	Santa Clara	Courthouse	43-N1	2	above the T-Bar.	\$ 2,812	\$ 2,812	100.00
					Plumbing - Replace failed & corroded galvanized suction piping with Schedule 80 PVC for the sump pump.			
FM-				_	Pump is suctioning air an shutting pump down. Water level rises causing sewage flood. Cycle system for			
254 0052709	Santa Clara	Hall of Justice (West)	43-A2	2	normal operation.	\$ 11,739	\$ 11,739	100.00
FM-	Comba Cl	Dala Alia C	42.54	2	Elevator, Escalators & Hoists - Wheel chair lift failing and unsafe. Replace (1) failed power inverter and (1)		6 22-	66.04
255 0052740	Santa Clara	Palo Alto Courthouse	43-D1		hand held controller for wheelchair lift. Work is required by code. Elevator - Elevator #7 - Replace (1) failed mechanical starter contactor assembly. Provide and install a new	\$ 3,141	\$ 2,074	66.04
 FM-					Solid-State Starter to control motor starting and limit the inflow of current. The new starter shall be wired,			
256 0052746	Santa Clara	Hall of Justice (East)	43-A1	2	adjusted, and tested for smooth operation	\$ 5,979	\$ 5,979	100.00
FM-	Janta Clara	Trail Or Justice (East)	42-41		aujusteu, anu testeu foi sintoutii operation	7 کرور کی	9/5,5	100.00
257 0052716	Shasta	Main Courthouse	45-A1	1	HVAC - Restore BAS in building - BAS offline due to system failure	\$ 160,000	\$ 111,536	69.71
23, 3032, 10	Johnson	iviani coaranoase	13 /11		1.17.10 Mestere Bris in Sanama Bris offinie due to system fandre	7 100,000	Y 111,000	03.71

Interior finishes - Replace three failed high security locksets and two failed door closers complete with keys 5		FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
FM- FM- FM- Modesto Main FM- Courthouse 50-A1 2 Elevators, Escalators, & Hoists - Replace failed emergency phone in public elevator #1 \$1,095 \$797 72.82												
259 0052142 Solano Hall of Justice 48-A1 2 Elevators, Escalators, & Hoists - Replace failed emergency phone in public elevator #1 \$ 1,095 \$.797 72.82 FM-	258	+	Solano	Hall of Justice	48-A1	2	for doors into secure areas - Work to be performed afterhours	\$	6,389	\$	6,389	100.00
260 0052378 Solano Law And Justice Center 48-A2 2 Valve, work requires replacement of several damaged ceiling tiles as well. \$ 5,290 \$ 5,290 100.00 Plumbing - Black Water Remediation - Isolate the cause of the black water spill, remove debris from the sump pump and hydro-jet the sewer main to the building. Remove and replace approximately 32.5F of drywall and 8 ceiling tiles, extract water, clean and sanitize flooring and pressure wash the gutter in front of the court. All restrooms, drinking foundariss, sinks etc. overflowing black water and all restrooms are out of order. \$ 5,000 \$ 4,990 99.80 FM- Modesto Main Courthouse 50-A1 1 HVAC - Labor and Programming to replace 4 failed control modules for damper operation of AHU serving Hall PMC - Courthouse 50-A1 2 of Records. HVAC - Oil Equalizer Pipe - The 1" oil equalizer pipe has spilt apart between the two circuit 1B compressors causing the loss of all charged R-22 refrigerant and a portion of its refrigerant oil. The P1 is required to re-gain causing the loss of all charged R-22 refrigerant and a portion of its refrigerant oil. The P1 is required to re-gain causing the loss of all charged R-22 refrigerant and a portion of its refrigerant oil. The P1 is required to re-gain causing the loss of all charged R-22 refrigerant and four damaged slats and double angle bottom bar on the Sallyport roilup gate - The Tulare County Sheriff's Office bus hit the Sallyport rollup gate before the gate had been completely raised damaging the gate longer and rendering the gate inoperable. The Tulare Center 54-11 2 County Sheriff's Office is submitting a claim with Tulare County Risk Management for reimbursement to AOC 5 6,319 5 6,319 100.00 COUNTY MANAGED - Abate tile and replace carpet: Abate VAT (vinyl asbestos floor tile). The approx. 11,700 Sq Ft of tile flooring under carpet is lifting, broken and pulverized which poses a health risk. Remove and reinstall court seating. Move furniture in the affected areas. Install carpet & baseboard coving in the affected 5 125,	259	0052142	Solano	Hall of Justice	48-A1	2		\$	1,095	\$	797	72.82
FM- 261 0052183 Stanislaus Courthouse 50-A1 1 restrooms, drinking foundation, solidate the cause of the black water spill, remove debris from the sump pump and hydro-jet the sewer main to the building. Remove and replace approximately 32 SF of drywall and a celling tiles, extract water, clean and sanitize flooring and pressure wash the gutter in front of the court. All restrooms, drinking foundations, sinks etc. overflowing black water and all restrooms are out of order. FM- 262 0052305 Stanislaus Courthouse 50-A1 2 of Records. FM- Modesto Main 263 0052750 Stanislaus Courthouse 50-A1 1 cooling of the courthouse and not interfere with Court operation of its refrigerant oil. The P1 is required to re-gain cooling of the courthouse and not interfere with Court operations. FM- South County Justice FM- 17 Tulare Center 54-11 2 County Sheriff's Office bus hit the Sallyport rollup gate before the gate had been completely raised, damaging the gate beyond repair and rendering the gate inoperable. The Tulare Center 54-11 2 County Sheriff's Office is submitting a claim with Tulare County Risk Management for reimbursement to AOC. \$ 6,319 \$ 6,319 \$ 100.00 COUNTY MANAGED - Abate tile and replace carpet: Abate VAT (vinyl asbestos floor tile). The approx. 11,700 \$ 6,512,000 \$ 100.00 COUNTY MANAGED - Abate tile and replace carpet: Abate VAT (vinyl asbestos floor tile). The approx. 11,700 \$ 125,000 \$ 100.00 COUNTY MANAGED - Abate tile and replace carpet: Abate VAT (vinyl asbestos floor tile). The approx. 11,700 \$ 125,000 \$ 100.00 COUNTY MANAGED - Abate tile and replace carpet: Abate VAT (vinyl asbestos floor tile). The approx. 11,700 \$ 125,000 \$ 125,000 \$ 100.00	260		Solano	Law And Justice Center	19.12	2		ر	5 200	ر	5 200	100.00
262 0052305 Stanislaus Courthouse 50-A1 2 of Records. \$ 7,100 \$ 5,525 77.82 FM-	261		Stanislaus		50-A1	1	pump and hydro-jet the sewer main to the building. Remove and replace approximately 32 SF of drywall and 8 ceiling tiles, extract water, clean and sanitize flooring and pressure wash the gutter in front of the court. All	\$	5,000	\$	4,990	99.80
HVAC - Oil Equalizer Pipe - The 1" oil equalizer pipe has spilt apart between the two circuit 1B compressors causing the loss of all charged R-22 refrigerant and a portion of its refrigerant oil. The P1 is required to re-gain cooling of the courthouse and not interfere with Court operations. Security - Replace existing damaged motor operator and four damaged slats and double angle bottom bar on the Sallyport rollup gate - The Tulare County Sheriff's Office bus hit the Sallyport rollup gate before the gate had been completely raised, damaging the gate beyond repair and rendering the gate inoperable. The Tulare County Sheriff's Office is submitting a claim with Tulare County Risk Management for reimbursement to AOC. COUNTY MANAGED - Abate tile and replace carpet: Abate VAT (vinyl asbestos floor tile). The approx. 11,700 Sq Ft of tile flooring under carpet is lifting, broken and pulverized which poses a health risk. Remove and reinstall court seating. Move furniture in the affected areas. Install carpet & baseboard coving in the affected 265 0052380 Yuba Courthouse 58-A1 2 Courtrooms and Chambers. Conduct pre/post-construction air quality tests as required. SOURTY MANAGED - Abate tile and replace carpet: Abate VAT (vinyl asbestos floor tile). The approx. 11,700 Sq Ft of tile flooring under carpet is lifting, broken and pulverized which poses a health risk. Remove and reinstall court seating. Move furniture in the affected areas. Install carpet & baseboard coving in the affected \$125,000 \$125,000 \$100.		FM-		Modesto Main			HVAC - Labor and Programming to replace 4 failed control modules for damper operation of AHU serving Hall					
FM- Modesto Main Courthouse 50-A1 1 causing the loss of all charged R-22 refrigerant and a portion of its refrigerant oil. The P1 is required to re-gain cooling of the courthouse and not interfere with Court operations. \$ 4,022 \$ 3,130 77.82 \$ 50-A1 7.82 \$ 50-A1 7.	262	0052305	Stanislaus	Courthouse	50-A1	2		\$	7,100	\$	5,525	77.82
the Sallyport rollup gate - The Tulare County Sheriff's Office bus hit the Sallyport rollup gate before the gate had been completely raised, damaging the gate beyond repair and rendering the gate inoperable. The Tulare Center Center Center Center County Sheriff's Office is submitting a claim with Tulare County Risk Management for reimbursement to AOC. COUNTY MANAGED - Abate tile and replace carpet: Abate VAT (vinyl asbestos floor tile). The approx. 11,700 Sq Ft of tile flooring under carpet is lifting, broken and pulverized which poses a health risk. Remove and reinstall court seating. Move furniture in the affected areas. Install carpet & baseboard coving in the affected Courthouse Se-A1 2 Courtrooms and Chambers. Conduct pre/post-construction air quality tests as required. \$125,000 \$ 125,000 \$ 100.00	263		Stanislaus		50-A1	1	causing the loss of all charged R-22 refrigerant and a portion of its refrigerant oil. The P1 is required to re-gain	l .	4,022	\$	3,130	77.82
FM- Yuba County Sq Ft of tile flooring under carpet is lifting, broken and pulverized which poses a health risk. Remove and re-install court seating. Move furniture in the affected areas. Install carpet & baseboard coving in the affected Courthouse 58-A1 2 Courtrooms and Chambers. Conduct pre/post-construction air quality tests as required. \$ 125,000 \$ 125,000 \$ 100.00	264		Tulare	-	54-11	2	the Sallyport rollup gate - The Tulare County Sheriff's Office bus hit the Sallyport rollup gate before the gate had been completely raised, damaging the gate beyond repair and rendering the gate inoperable. The Tulare		6,319	\$	6,319	100.00
\$ 8 418 471 \$ 7 075 625	265		Yuba	,	58-A1	2	Sq Ft of tile flooring under carpet is lifting, broken and pulverized which poses a health risk. Remove and reinstall court seating. Move furniture in the affected areas. Install carpet & baseboard coving in the affected	\$	125,000	\$	125,000	100.00
								¢Ω	<u>//12 //71</u>	 ¢ -	7 075 625	



ITEM #	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	REQUEST TYPE	CFR DESCRIPTION	CFR TERM	FUND SOURCE	CURRENT YEAR COSTS (Includes existing costs prior to CFR term)	BUDGET YEAR COSTS	TOTAL CFR COMMITMENT (CFR Term)	REVIEW NOTES - OREFM, JBCPO, & FSO
1	10-CFR009	Fresno	All	All	Establish Annual Budget		Establish an annual budget for Rule 10.810 projects and non-allowable projects less than \$15k each. The costs that the court's proposed funding contribution would cover is described as miscellaneous crafts and trades work as needed throughout the fiscal year.	NA	Operating Budget	\$ 119,000	\$ 119,000	\$ 119,000	No Concerns
2	22-CFR012	Mariposa	22-B2	Vault Number 5	Lease Extension		7/1/14 - 6/30/16 - Lease extension due to space constraints at the 1854 Historic Courthouse, all closed case files have been stored in this offside records storage facility since 2004. The court is seeking new leases for its current storage vaults. This will enable the Court to assign one vault for criminal and traffic, one vault for civil, family and juvenile, and one vault for confidential and collections records. This request is deemed urgent because without the storage vaults, there would be no space for record storage that is fire-safe and secured.	2 years	Operating Funds	\$ 2,340	\$ 2,340	\$ 4,680	No Concerns
3	22-CFR013	Mariposa	22-B1	Vault Number 9	Lease Extension		7/1/14 - 6/30/16 - Lease Extension due to space constraints at the 1854 Historic Courthouse, all closed case files have been stored in this offside records storage facility since 2004. The court is seeking new leases for its current storage vaults. This will enable the Court to assign one vault for criminal and traffic, one vault for civil, family and juvenile, and one vault for confidential and collections records. This request is deemed urgent because without the storage vaults, there would be no space for record storage that is fire-safe and secured.		Operating Funds/AB 1058 Grant	\$ 2,340	\$ 2,340	\$ 4,680	No Concerns
4	22-CFR014	Mariposa	22-TBD	Vault Number 10	New Lease	Ongoing	7/1/14 - 6/30/16 - Due to space constraints at the 1854 Historic Courthouse, all closed case files have been stored in this offside records storage facility since 2004. The court is seeking new leases for its current storage vaults. This will enable the Court to assign one vault for criminal and traffic, one vault for civil, family and juvenile, and one vault for confidential and collections records. This request is deemed urgent because without the storage vaults, there would be no space for record storage that is fire-safe and secured.	2 years	Operating Funds	\$ 2,340	\$ 2,340	\$ 4,680	No Concerns
5	36-CFR025	San Bernardino	36-N1	790 S. Gifford	New Lease		9/1/14-8/31/19 New Lease for initial term of five years with one three year option to extend the term of the lease. The request is deemed urgent because the AOC Office of Real Estate and Facilities Management is negotiating the new lease to include the required seismic retrofit certification from lessor.	5 years	Operating Budget	\$ 120,252	\$ 82,643	\$ 558,220	No Concerns



	ITEM #	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	REQUEST TYPE	CFR DESCRIPTION	CFR TERM	FUND SOURCE	CURRENT YEAR COSTS (Includes existing costs prior to CFR term)	BUDGET YEAR COSTS	TOTAL CFR COMMITMENT (CFR Term)	REVIEW NOTES - OREFM, JBCPO, & FSO
								9/1/14-8/31/19 New Lease for initial term of five years with one three year option to extend the term of the lease. The request is deemed						
			Cara		Records			urgent because the AOC Office of Real Estate and Facilities	_	0				NI -
	6 3		San Bernardino	N4, N5, N6	Storage	New Lease		Management is negotiating the new lease to include the required seismic retrofit certification from lessor.	5 years	Operating Budget	\$ 323,56	 \$ 216 108	\$ 1,631,655	No Concerns
	0 .	30 CI 1(020	Dernaramo	140	Storage	New Lease	Ongoing	Scisific retront certification from lessor.	ycars	Dauget	7 323,30	210,100	7 1,031,033	Concerns
								9/1/14-8/31/19 New Lease for initial term of five years with two five						
								year options to renew. The request is deemed urgent because the						
					Rancho			current facility lease expired on 3/31/14 and is now on a month-to-						
	_		San	26 TDD	Training	No. 1		month basis to allow AOC and Court to find a new location better	5	Operating	ć 22.5C	20.520	ć 400.200	No
-	/ :	36-CFR027	Bernardino	36-TBD	Center	New Lease	Ongoing	suited to the technology, logistic, and hospitality needs of the Court.	years	Budget	\$ 32,56	3 \$ 28,529	\$ 180,298	Concerns
	8 4		Santa Barbara		Garden Street Parking Lot	New Lease		7/1/2014-6/30/2019 - New Lease for five years with 3 one-year options to renew. This request is deemed urgent because without this parking space there would be no space available for jury parking. This lease has been in place since 2007, an audit finding recognized that only the JCC can enter into a lease with the County for these services and the Court was directed to submit a CFR.		Operating Budget	\$ 36,00	0 \$ 36,000	\$ 180,000	No Concerns
			Santa		Santa Maria Juvenile	Facility		There is a need for a jury box, so jurors can observe the trial. A multiple defendant gang related high security trial is scheduled to commence in November 2014. There are 6 defendants. The court has explored other available spaces in the community in which to try the case, the cost of tenante improvements and security has proven to be prohibitive. This		Fund				No
	9 4		Barbara	42-H1	Court (new)	Modification		request is deemed urgent due to the scheduled trial date.	NA	Balance	\$ 20,00	0 \$ -00	\$ 20,000	Concerns
			Tulare		Family Law Facilitator	Lease Extension		8/1/14-7/31/17 - Lease Extension for self help resource center. 3 year lease with a two year option to extend. This request is deemed urgent due to no other space available for self help center.		Operating Budget and Grant Funds	\$ 39,74			No Concerns