



TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

#### TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

#### OPEN MEETING WITH CLOSED SESSION AGENDA

Open to the Public Unless Indicated as Closed (Cal. Rules of Court, rule 10.75(c)(1))

OPEN PORTION OF THIS MEETING IS BEING RECORDED

Date:	March 6, 2015
Time:	12:05 PM - 1:05 PM
Location:	Teleconference
Public Call-in Number:	1-877-820-7831 Listen Only Code: 4502468

Meeting materials for open portions of the meeting will be posted on the advisory body web page on the California Courts website at least three business days before the meeting. Agenda items are numbered for identification purposes only and will not necessarily be considered in the indicated order.

#### I. OPEN MEETING (CAL. RULES OF COURT, RULE 10.75(C)(1))

#### Call to Order and Roll Call 12:05 PM

#### Approval of Minutes

Approve minutes of the January 16, 2015 Trial Court Facility Modification Advisory Committee meeting.

#### II. ACTION ITEMS (ITEMS 1-7)

# Action Item 1 – (Action Required) – List A – Emergency Facility Modification Funding (Priority 1)

Summary: Ratify emergency facility modifications from List A.

**Action Requested:** Staff recommends 70 projects for a total of \$1,266,206 to be paid from funds previously encumbered for emergency funding.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### Action Item 2 – (Action Required) – Priority 1 Funding – Reallocation of Funding

Summary: Review and discuss Priority 1 funding

Action Requested: Staff recommends reallocation of \$2.8M in funding to support Priority 1 projects.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

# Action Item 3 – (Action Required) – List B – Facility Modifications Less than \$50k (Priority 2)

Summary: Ratify facility modifications less than \$50k from List B.
Action Requested: Staff recommends 107 projects for a total of \$946,617 to be paid from funds previously encumbered for facility modifications less than \$50k.
Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### Action Item 4 – (Action Required) – List C – Cost Increases Over \$50k

**Summary:** Ratify facility modifications requiring cost increases over \$50k from List C. **Action Requested:** Staff recommends one project for a total cost increase to the Facility Modification Program Budget of \$257,716.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### Action Item 5 – (Action Required) – List D – Facility Modifications Over \$50k

Summary: Review recommended facility modifications over \$50K List D.

Action Requested: Staff recommends six projects for a total cost to the Facility Modification Program Budget of \$2,470,997.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

# Action Item 6 – (Action Required) – List F – Court-Funded Facilities Requests (Facility Modifications)

Summary: Review Court-Funded Facilities Requests (Facility Modifications) from List F.

Action Requested: Staff recommends two Court-Funded Facilities Requests for review and approval.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### Action Item 7 – (Action Required) – Quarterly Activity Report, Quarter 2 of Fiscal Year 2014-2015

**Summary:** Review and discuss the *Trial Court Facility Modification Advisory Committee Quarterly Activity Report, Quarter 2 of Fiscal Year 2014-2015* 

Action Requested: Provide input and additions to draft document and approve release to E&P upon revision.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### III. DISCUSSION ITEMS (ITEMS 1-3)

2 | Page

#### **Discussion Item 1 – Larson Justice Center Parking Project**

**Summary:** Priority 3 project request: Larson Justice Center East Parking Lot **Presenter:** Mr. Patrick McGrath, Facilities Operations Manager

#### **Discussion Item 2 – Year End Process for Court Funded Requests**

Summary: For encumbrance and execution in FY 14-15, Court Funded Requests must be submitted by Monday, March 23, 2015.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### Discussion Item 3 – May TCFMAC Two-Day Meeting in Los Angeles

Summary: Discuss courthouse tours (Van Nuys, Mosk, and Foltz) and determine meeting place Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### Ι٧. ADJOURNMENT

**Adjourn to Closed Session** 

Rev. 2 03.03.2015





TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

#### TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

#### MINUTES OF OPEN MEETING WITH CLOSED SESSION

January 16, 2015 10:00 a.m. – 4:00 p.m. In Person Meeting

Advisory Body Members Present:	Hon. David Edwin Power, Chair, Hon. William F. Highberger, Vice-Chair, Hon. Donald Cole Byrd, Hon. James L. Stoelker, Hon. Vanessa W. Vallarta, Ms. Linda Romero-Soles, Ms. Christina M. Volkers, Mr. Michael M. Roddy, Ms. Jeanine D. Tucker
Advisory Body Members Absent:	
Others Present:	Mr. Curt Soderlund, Mr. Gerald Pfab, Ms. M.R. Gafill, Mr. Nick Turner, Mr. Kenneth Kachold, Ms. Gisele Corrie, Mr. Price Eres, Ms. Christa Jennings, Ms. Peggy Symons, and Mr. Jake Chatters
OPEN MEETING	

#### Call to Order and Roll Call

The chair called the meeting to order at 10:00 a.m., and took roll call.

#### **Approval of Minutes**

The advisory body reviewed and approved the minutes of the December 15, 2014, Trial Court Facility Modification Advisory Committee meetings.

#### PUBLIC WRITTEN COMMENT

No public comments were received.

#### ACTION ITEMS (ITEMS 1-11)

# Action Item 1 – (Action Required) – Minutes of the November 3, 2014, Trial Court Facility Modification Advisory Committee meeting.

**Summary:** Review changes to the approved minutes of the November 3, 2014, Trial Court Facility Modification Advisory Committee meeting.

Action: Reviewed and approved modifications made to Item 2 of the November 3, 2014, minutes.

# Action Item 2 – (Action Required) - List A – Emergency Facility Modification Funding (Priority 1)

Summary: Ratify emergency facility modifications from List A.

Action: Reviewed and ratified 51 projects for a total of \$841,252 to be paid from funds previously encumbered for emergency funding.

# Action Item 3 – (Action Required) - List B – Facility Modifications Less than \$50k (Priority 2)

Summary: Ratify facility modifications less than \$50k from List B.

Action: Reviewed and ratified 64 projects for a total of \$619,677 to be paid from funds previously encumbered for facility modifications less than \$50k. The committee expressed concern regarding FM-0054243 at the New Susanville Courthouse. The committee is requesting a report from the Capital Projects Team to summarize the historical use (last 24 months) of Facility Modification Program funding for new construction projects. Information is requested on why the funds are being used this way and what is being done to mitigate this issue.

#### Action Item 4 – (Action Required) - List C – Cost Increases Over \$50k

**Summary:** Ratify facility modifications requiring cost increases over \$50k from List C. *Action: Reviewed and ratified three projects for a total cost increase to the Facility Modification Program Budget of \$286,383.* 

#### Action Item 5 - (Action Required) - Priority 3 Project Requests

Summary: Priority 3 project requests from multiple courts:

• Item 5A – Placer Superior Court

Action: The committee reviewed the project and approved funding pending successful completion of the funding negotiations and transfer process with the County.

• Item 5B – Merced Superior Court

Action: The committee is requesting this project be deferred indefinitely due to budget constraints. Several courts have similar security screening issues and will need to be evaluated before any funds can be allocated for this type of project. Facilities Management Unit staff will work with the Security staff to evaluate all security related projects and report back to the committee October 2015, with prioritized funding recommendations.

• Item 5C – Nevada Superior Court

Action: The committee is requesting this project be deferred indefinitely due to budget constraints.

• Item 5D – Santa Barbara Superior Court

Action: The committee is requesting this project be deferred indefinitely due to budget constraints. The committee is also recommending this project is completed as a Court-Funded Facilities Request.

• Item 5E – Solano Superior Court

Action: The committee is requesting this project be deferred indefinitely due to budget constraints.

• Item 5F – Tulare Superior Court

Action: The committee is requesting this project be deferred to the April 2015 meeting once more information is presented to the committee.

# Action Item 6 – (Action Required) - List D – Facility Modifications Over \$50k and Energy Efficiency Projects

**Summary:** Review recommended facility modifications over \$50K and energy efficiency projects from List D.

Action: Reviewed 13 projects for a total cost to the Facility Modification Program Budget of \$4,227,505. Upon committee review, it was determined FM-00051253 should be removed from the list and not funded with Facility Modification Program funds.

# Action Item 7 – (Action Required) - List F – Court-Funded Facilities Requests (Facility Modifications)

Summary: Review Court-Funded Facilities Requests (Facility Modifications) from List F.

Action: Reviewed and approved two Court-Funded Facilities Requests from Alameda and El Dorado Superior Courts.

# Action Item 8 – (Action Required) - Preliminary Approval Authority for Judicial Council Staff of \$50K for Priority 2 Projects

**Summary:** Review preliminary approval authority for Judicial Council Staff of \$50K for Priority 2 projects and determine if approval authority should continue.

Action: The committee unanimously approved continuing the approval authority for Judicial Council staff of \$50K for Priority 2 projects.

#### Action Item 9 – (Action Required) – *Trial Court Facility Modification Quarterly* Activity Report, Quarter 1 of Fiscal Year 2014-2015

**Summary:** Review draft report *Trial Court Facility Modification Quarterly Activity Report, Quarter 1 of Fiscal Year 2014-2015.* 

Action: The committee provided input and approved to move to Judicial Council as an information only item at the February 20, 2015, Judicial Council meeting.

#### Action Item 10 – (Action Required) - TCFMAC 2015 Annual Agenda

Summary: Review draft TCFMAC 2015 Annual Agenda.

Action: The committee provided input and approved to move to E&P pending additional edits members of the committee have. Members are encouraged to work with staff to provide additional input after the meeting.

#### DISCUSSION ITEMS (ITEMS 1-7)

#### **Discussion Item 1**

**Summary:** Reviewed changes to updated Prioritization Methodology. Staff will continue to update based on committee feedback and then present this document as an action item at a future meeting once the committee has had sufficient time to review.

#### **Discussion Item 2**

**Summary:** Judicial Council staff provided an update to FMU staffing, FM workload, and Delayed FM Projects.

#### **Discussion Item 3**

**Summary:** Judicial Council staff provided an update on Service Delivery Methods; Service Provider (SP) contracts, Job Order Contracting (JOC), and Delegation.

#### **Discussion Item 4**

**Summary:** Judicial Council staff provided an update on the finalization requirements for the delegation pilot program based on the program guidelines.

#### **Discussion Item 5**

**Summary:** Judicial Council staff provided an update on the Operations and Maintenance budget projections for fiscal year 2015-2016.

#### **Discussion Item 6**

**Summary:** Judicial Council staff provided a report on FM system analysis and the historic spend by system & projections for fiscal year 2015-2016.

#### **Discussion Item 7**

**Summary:** Judicial Council staff provided an overview of the projected Court-Funded Facilities Requests process for fiscal year closeout, identifying key deadlines that may need to be communicated to the courts.

#### INFORMATION ONLY ITEMS (ITEMS 1-2)

#### Information Item 1 – Updated Trial Court Facility Modification Policy

**Summary:** The updated Trial Court Facility Modification Policy was included in the meeting materials. Changes to the policy were made in alignment to newly established Cal. Rule of Court 10.65, *Trial Court Facility Modification Advisory Committee*.

# Information Item 2 – Cal. Rule of Court 10.65, *Trial Court Facility Modification Advisory Committee*

**Summary:** The newly established Cal. Rule of Court 10.65, *Trial Court Facility Modification Advisory Committee* was included in the meeting materials.

#### ADJOURNMENT

There being no further open meeting business, the meeting was adjourned at 3:50 p.m.

Approved by the advisory body on enter date.





TRIAL COURT FACILITY MODIFICATION Advisory committee

### Action Item 1 – (Action Required) - List A – Emergency Facility Modification Funding (Priority 1)

#### **Summary:**

List A – Emergency Facility Modification Funding (Priority 1)

Total Project Count:	70
Total Potential FM Budget Share of Cost:	\$1,266,206

#### **Supporting Documentation:**

• List A - Emergency Facility Modifications (Priority 1)

#### **Action Requested:**

Ratify Judicial Council Staff preliminary decision for execution approval of List A – Emergency Facility Modifications (Priority 1).

# Action Item 1 List A – Emergency Facility Modification Funding (Priority 1)

There were 70 new Priority 1 FMs this period
Total estimated FM Program budget share is \$1,266,206
P1 Budget is projected to be significantly over budget.



JUDICIAL COUNCIL OF CALIFORNIA



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF	JOB STATUS	FACILITY MODIFICATION PROGRAM
						Electrical - Replace failed engine starter on emergency						
						generator. Temporary generator brought to facility and						
	FM-		Torrance			connected for back up, due to emergency generator out of						
1	0054322	Los Angeles	Courthouse	19-C1		service.	\$	12,367	\$	10,529	Complete	85.14
			Van Nuys			Fire Protection - Replace coupling connector/flange on						
	FM-		Courthouse			Standpipe supply line, restore supply line. Standpipe supply			Ι.			
2	0054324	Los Angeles	East	19-AX1		line has leak at coupling connector.	Ş	6,650	\$	5,968	Complete	89.74
						HVAC - Electronic replacement parts need to be ordered to						
						exchange failed boards for the Building Automation System						
						(BAS). Boards failed due to water infiltration from a broken						
						supply line and are required to properly control the air						
			New			handling system and boiler. Air handler is currently not						
			Mammoth			operational and is impacting courthouse temperature.						
	FM-		Lakes			Replacement parts need to be ordered from Sweden ASAP.			Ι.			
3	0054325	Mono	Courthouse	26-B2		SMW Interior Finishes - Water remediation, set up containment	Ş	24,000	Ş	24,000	In Work	100
			Edmund D.			(468 sq ft), dried leak affected areas, and extracted water						
			Edelman			from 120 sq ft of carpet; disinfected and HEPA vacuumed.						
	FM-		Children's			ACM and LBP testing. Replaced deteriorating expansion						
		Los Angolos		10.01		joints with new Latex materials, removal of old materials	ć	40,824	¢	28,573	Complete	69.99
4	0054550	Los Angeles	Court	19-Q1		HVAC - Replace mag starter contactor on refrigeration	Ş	40,824	Ş	20,575	Complete	09.99
			Monrovia			compressor. This work was completed as a P1 emergency						
	FM-					due to the compressor not allowing A/C to flow through						
		Los Angolos	Training	10 N1			\$	2 007	¢	2 007	Complete	100
5	0054552	Los Angeles	Center	19-N1	T	the courthouse after a power outage.	Ş	3,007	\$	5,007	Complete	100
						Plumbing - Replace cracked 2" cast iron p-trap, contain						
						leaking, set-up containment 7' x7' x 15', environmental						
	FM-		Metropolitan			testing, and replace damaged ceiling tiles 20 sq ft. 2' cast						
6			·			iron P-trap in ceiling of 1st flr is cracked and leaking.	ç	10 500	ć	10 500	Complete	100
0	0034398	ros Augeles	Courthouse	19-T1			Ş	10,500	Ş	10,500	Complete	100



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST		GRA	BUDGET SHARE OF	JOB STATUS	FACILITY MODIFICATION PROGRAM
						Plumbing - Collapsed Cast Iron Pipe - Replace 4' section of cast iron pipe. Pipe has collapsed and there is a large piece							
						of the pipe blocking the flow of sewage and causing							
						multiple black water floods. Will require jackhammer to get							
	FM-		West Justice			through concrete floor and slab and replacement of							
7	0054399	Orange	Center	30-D1		removed flooring.	\$	11,668	\$	11,	668	In Work	100
						Interior Finishes - Encapsulate friable ACM fireproofing in							
						3rd flr Mechanical room (Rm 309) 120'X30'X16' and (Rm							
						304) 40'X20'X16'. Set up containment 4th flr Mechanical room (Rm 404) 16'X13'X16'. Remediate 9,680 sq. ft of							
	FM-		Pasadena			material, remediate 1550 sq. ft. of contaminated							
8			Courthouse	19-J1		equipment surfaces.	Ś	251,777	\$	174.	607	Complete	69.35
	FM-		Clara Shortridge Foltz Criminal Justice			Plumbing – remediate internal water intrusion due to leaking water hammer device. Remediation includes demo the west side wall in the Judges Conference room 6-801, included: 4' x 4' area was build back with drywall. 2' x 2' access hatch was installed on the wall. 3' x 9' wooden panels reinstalled. Plumbing work includes replacement of ¾" and 1" water supply piping was reinsulated, approximately 12' of ¾" and 13' of 1". (3) ¾" 90 Elbows and (1) ¾" Tee was reinsulated. Replacement of numerous acoustic ceiling tiles Full containment on 5th and 6th floor							
9		Los Angeles		19-L1		and environmental testing conducted.	¢	52,855	¢	36	250	In Work	68.79
	FM-	-	Airport Courthouse	19-AU1		Exterior Shell - Replaced defective barrier arm units motor and operator entrance to the underground parking structure - not operating and will not close or open	\$	10,302				Complete	77.17



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE	JOB STATUS	FACILITY MODIFICATION PROGRAM
	FM-		Pasadena			Plumbing - Water remediation, disinfect and dried leak affected areas. Environmental testing. Work performed: 4th flr Holding Cell Court B & C Containment 8ftx15ftx9ft, extract gray water 120 sqft; 4th flr Vestibule Holding Area Containment 5ftx28ftx9ft extract gray water 140 sqft; 4th flr Secured Hallway Containment 5ftx69ftx9ft, extract gray water 325 sqft; 4th flr Judges Chambers 401C Containment 2ftx10ftx9ft extract gray water 20 sqft; 4th flr Court C						
1	1 0054425	Los Angeles	Courthouse	19-J1	1	Containment 15ftx24ftx12ft extract gray	\$	47,766	\$	47,766	Complete	100
1	FM-	San Diago	County	27 41		Interior Finishes - Water remediation, set up 2 ACM containments 8 x 8, contain leaking, dry leak affected areas, removed & replace water damaged ceiling tiles. ACM testing and renovated leaking portions of roof. Rain Water	ć	0 702	ć	0 702	Complete	100
	2 0054426	Sali Diego	Courthouse	37-A1	1	leaking through South Tower roof into offices.	Ş	8,782	Ş	0,/02	Complete	100
1	FM- 3 0054427		Metropolitan Courthouse	19-T1	1	HVAC - Water remediation, contain leaking. area affected 6' x 6' (32 sq ft), replace 32 - 1'x1' ceiling tiles. ACM testing. Water leak is coming from 9th Flr Chiller Room, down onto 8th Flr . Drain line for Chiller Room is leaking.	\$	8,387	\$	8,387	In Work	100
1	FM- 4 0054429		Mental Health Court	19-P1		Plumbing - Dig-up approximately 3 x 3 x 3 hole, Replaced cracked 3" copper pipe and 3 galvanized flange connection - water was leaking from the main supply line.	\$	4,695	\$	3,348	In Work	71.31



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	OCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC -UNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE	JOB STATUS	FACILITY MODIFICATION PROGRAM
_	<b>L</b>		-			Elevators, Escalators, & Hoists - Circuit and selector brushes			- 2			
			Bakersfield			replaced after hours and generator adjusted. Elevator car						
	FM-		Superior			(s) 001 and 002 inoperable, P1 condition required circuit						
15	0054436	Kern	Court	15-A1		and selector brush replacement.	\$	8,469	\$	8.469	Complete	100
		_				County Managed - HVAC - Replace (6) failed mixer boxes.	'	-,		-,		
			Sylmar			Dismantle various areas of ceiling and metal hatches to						
	FM-		Juvenile			access mixer boxes. Re-install ceiling and metal hatches to						
16	0054439	Los Angeles	Court	19-AF1	1	normal operation. P1 Condition	\$	11,323	\$	3,885	In Work	34.31
17	FM- 0054440 FM-	Los Angeles	Van Nuys Courthouse West Juvenile	19-AX2	1	Plumbing - Weld temporary patch on corroded and leaking Domestic Hot Water. Domestic Hot Water Storage Tank sprung a leak. Fabrication and installation of a new tank will be completed under a separate Priority 2 FM project. Interior Finishes - Replace affected ceiling tiles, drywall, and a thermostat that were damaged due to roof leaks from recent rains. Set up containment 8x10 feet. Remediate mold that was identified within a section of wall and install new wall board. Seal deficient sections of roof to	\$	4,050	\$	3,259	In Work	80.48
18		San Diego	Court	37-E1		prevent future leaks	\$	13,766	Ś	13 766	Complete	100
	FM-		West Covina			COUNTY MANAGED- HVAC - Replacement of controls such as valve actuators, sensors, and pumps associated to two heating boilers and two cooling towers. The proposed work				· · · ·		
19	FM-	LOS ANGEIES	Courthouse San Fernando	19-X1		will also include an updated BAS server. Elevators, Escalators, & Hoists - Replace failed generator motor and motor controls for elevator. Custody Elevator #1 had smoke within the machine room, generator motor	\$	72,000	Ş	<u>, 22,707</u>	In Work	83.01
20	0054447	Los Angeles	Courthouse	19-AC1	1	and motor controls panel has black soot.	\$	37,790	\$	37,790	In Work	100



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST		PROGRAM BUDGET SHARE	JOB STATUS	FACILITY MODIFICATION PROGRAM
			Van Nuys			Interior Finishes - Water remediation, set up containment,						
	FM-		Courthouse			and dried leak affected rooms. Ceiling leak in Sheriff's office						
21		Los Angeles		19-AX2	1	storage room coming from 4th flr employee shower.	\$	7,250	\$	5,835	In Work	80.48
		0				Electrical - Main Electrical Breaker Replacement; Electrical						
						utility (Southern California Edison) to shutdown electrical						
						service to the building and will re-energize the building						
			Pomona			after work is complete. One of two main building circuit						
	FM-		Courthouse			breakers malfunctioned, faulty circuit breaker must be	_					
22	0054457	Los Angeles	South	19-W1	1	replaced.	\$	76,389	\$	69,621	In Work	91.14
			Clara			Plumbing - Water remediation, set up containment 4' x 10'						
			Shortridge			x 10', dried leak affected areas, and environmental testing.						
			Foltz Criminal			Replace trolling valve, check valve, section of pipe, and						
	FM-		Justice			pipe fittings. Ceiling leak on the 18th floor, source of leak is						
23	0054459	Los Angeles	Center	19-L1	1	a domestic 3/4" copper hot water return pipe.	\$	9,870	\$	6,790	In Work	68.79
		0				Elevators, Escalators, & Hoists - Replace rectifiers and brake	-					
	FM-		Stanley Mosk			coils n Escalator 1 to 2. Escalator 1 to 2 is not working						
24	0054465	Los Angeles	Courthouse	19-K1	1	properly, has burnt out rectifier and brake coil.	\$	11,870	\$	11,545	In Work	97.26
						Plumbing - Replace faulty flush valve for wall urinal for						
	FM-		Delano/Nort			men's restroom and water intrusion cleanup. Water leaking						
25	0054467	Kern	h Kern Court	15-D1	1	from wall from broken valve.	\$	6,314	\$	6,314	In Work	100
			Van Nuys									
	FM-		Courthouse			Elevators, Escalators, & Hoists - Replace elevator encoder.	~	F 000		F 000		100
26	0054470	Los Angeles	west	19-AX2	1	Elevator is not running properly, causing entrapments.	Ş	5,998	Ş	5,998	In Work	100



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF	JOB STATUS	FACILITY MODIFICATION PROGRAM
						Interior Finishes - Replaced 200sf. of 1x1 ceiling tiles, ACM testing, and areas was cleaned to mitigate ACM					
27	FM- 0054472	Los Angeles	Torrance	19-C1		contamination including carpet and restored back to normal operations. Ceiling tile adhesive failed causing tile to collapse overnight. inside chambers.	\$ 3,414	4	2 907	Complete	85.14
27	003472				-			7	2,507	complete	05.14
			Parking Structure Lot			Elevator - Replace auto dialer and restore phone line inside					
	FM-		94 Airport			Elevator #11. Emergency Phone inside elevator not					
28	0054477	Los Angeles	Courthouse	19-AU2	1	working, phone is code required.	\$ 2,231	\$	1,722	Complete	77.17
						containment double layer, install silicone around window					
						seal, and set up air mover and dehumidifiers. Remove and					
	FM-		Airport			replace approximately 4 sf of drywall, texture and paint. This work was completed as a P1 emergency due to rain					
29		Los Angeles	•	19-AU1	1	water coming through window onto the 7th floor public	\$ 6,736	\$	5,198	Complete	77.17
		0				HVAC - Failed Exhaust Fan - Remove and replace motor	,		,		
			Van Nuys			controls contactor and exhaust fan motor that have failed.					
	FM-		Courthouse			Currently the exhaust fan is not functioning which has					
30	0054479	Los Angeles	East	19-AX1	1	stopped production in the kitchen.	\$ 4,956	\$	4,448	In Work	89.74
						Plumbing - Pipe Leak - Remove and replace 30 If of 3/4"					
						copper line, two each 3/4" ball valves and one 1 1/4" ball					
						valve. The copper pipe leaked onto the hard lid Ceiling in					
						room #803 and the old kitchen. this work required					
	FM-		Metropolitan			environmental testing, a 20x15x9.5 containment size and					
31	0054480	Los Angeles	Courthouse	19-T1	1	32sq. ft. of drywall, patch and paint.	\$ 12,763	\$	12,066	In Work	94.54



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF	JOB STATUS	FACILITY MODIFICATION PROGRAM
						HVAC - Failing Fan Motor - VFD to supply fan motor on Air						
						Handler #3 keeps tripping affecting cooling/heating to the 1st & 2nd flr W Wing. Removed and replaced burned out						
						15hp supply fan motor to Air Handler #3. Wired new supply						
			Santa			fan motor and checked motor for proper rotation.						
	FM-		Monica			Replaced belts, pulleys, (3)30amp fuses and collaborated						
32	0054481	Los Angeles	Courthouse	19-AP1	1	VFD.	\$	10,613	\$	8,330	Complete	78.49
	FM-	Los Angeles	Pasadena Courthouse Michael D. Antonovich Antelope Valley	19-J1	1	HVAC - Contaminated Duct Work - Abate ACM from return air plenum, set up containment in the basement and mechanical room, environmental testing, air monitoring for clearance. Loose fire proofing inside return plenum. Plumbing - Water remediation - extract water from 1st Flr Chiller Room (2,250 Sq. Ft.), 1st Flr Fan Room (600 Sq. Ft.) 1st Flr Judge's Dining Rm (600 Sq. Ft.) remove water from loading dock area (900 Sq. Ft.) Replace condenser pump, diffuser, 6 isolation valves and check valve. Condenser Water Pump #2 leaking in chiller room defective pump and	\$	43,479			In Work	69.35
34	0054491	Los Angeles	Courthouse	19-AZ1	1	valves.	\$	76,484	Ş	56,223	In Work	73.51
	FM-		Parking Structure-Lot 53 Pasadena			Elevators, Escalators, & Hoists - Install a hydraulic valve assembly. Elevator is not responding and has a faulty						
35	0054494	Los Angeles		19-J3		hydraulic valve that needs to be replaced.	\$	8,040	\$	8,040	In Work	100
			East Los			Electrical - Replace failed Battery Charger - Emergency						
	FM-		Angeles	10.1/1		Generator Battery Charger not functioning and must be	ے ا	7 207			Comulate	
36	0054495	Los Angeles	Courthouse	19-V1	1	replaced.	\$	7,297	\$	5,6/1	Complete	77.72



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF	JOB STATUS	FACILITY MODIFICATION PROGRAM
						Elevators, Escalators, & Hoists - Replace the catch release						
	FM-		Downey			switch - Catch release switch broke causing the elevator to						
37	0054497	Los Angeles	Courthouse	19-AM1	1	stop.	Ş	8,988	Ş	8,988	In Work	100
	FM-		Reedley			Grounds - Water is leaking from under the walkway in front of the courthouse. Locate water leak. Replace cracked galvanized irrigation pipe with 20' of 1" PVC in front of the building and 30' under concrete walkway. Remove 10 sf of concrete and install new concrete patch. Install one ball						
20	0054499	Erospo	Court	10-F1	1	valve Water is leaking onto grounds and front walkway and sidewalk creating safety hazard.	¢	5,281	\$	1 1 2 6	In Work	78.13
30	0034499	FIESH0	Court	10-11	1	HVAC - Replace domestic water booster pump #1 and	ې	3,201	ې ا	4,120		70.13
	FM-		Norwalk			motor contactor. Domestic Water Booster Pump #1 tripped off of overload causing the building to have no domestic						
39	0054501	Los Angeles	Courthouse	19-AK1	1	water pressure.	\$	10,461	\$	8,895	In Work	85.03
40	FM- 0054504	Los Angeles	Airport Courthouse	19-AU1	1	Elevators, Escalators, & Hoists - Replaced defective output board, latch board, and two logic relays. Freight elevator #7 on basement level not responding, multiple boards were found to be defective. Interior Finishes - Set up containment, environmental	\$	7,763	\$	5,991	In Work	77.17
11	FM-	Los Angeles	Norwalk	19-AK1		testing, and restore pipe to stop leak. Domestic water leak in a 6th flr pipe chase, water seeped through floor of the pipe chase and leaked into the 5th flr office #507. Court employee in office #507 relocated until drying process is completed.	\$	10,176	¢	8 652	In Work	85.03
	0054505	2037 (ingenes	Courthouse		-		ት	10,170	7	0,000		05.05



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY	PROGRAM BUDGET SHARE OF	JOB STATUS	FACILITY MODIFICATION PROGRAM
						Interior Finishes - A section of the ceiling (30 sq. ft.)						
						collapsed in a storage room on the 1st floor of the west						
						wing. The damage was caused from a water leak that						
						occurred at an unknown date. There was no moisture						
						present only plaster and ceiling tile debris. Remediation technicians contained the entire storage room (15ft x 15ft x						
						8ft). They also abated ACM containing debris, HEPA						
						vacuumed and wiped (700 sq. ft.) of wall and floor						
	FM-		Pasadena			surfaces, installed (30 sq. ft.) of drywall, and placed (qty.						
42			Courthouse	19-J1		30) ceiling tiles.	Ś	15,565	Ś	10 794	In Work	69.35
	0001010	2007 (1)50100	Courtinouse	13 31		HVAC - Replace failed fan motor. Cooling Tower #2 is non-	<b>Y</b>	13,303	Υ 	10,751		03.33
			Van Nuys			operational; chillers are not keeping chilled water						
	FM-		Courthouse			temperature and have to be reset every 15 mins. Building is						
43	0054511	Los Angeles	West	19-AX2		warming up.	\$	8,650	\$	6,962	In Work	80.48
	FM-		Van Nuys Courthouse			HVAC - Failed Pressure Relief Valve - Water remediation, environmental testing, removed pipe insulation, replaced Pressure Relief Valve, 6" Flanged Gate Valve and 2" Ball Valve. Boilers (for comfort heating) supply piping was hammering vigorously and pressure relief valve to the boilers continuously relieving causing the area around the						
44	0054513	Los Angeles	East	19-AX1		boiler to flood, the pressure relief valve failed.	\$	9,975	\$	9,975	In Work	100



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF	JOB STATUS	FACILITY MODIFICATION PROGRAM
						Electrical - Replace Failed Electrical Circuits - Electrical						
						circuits (2ea.) have a direct short affecting approximately						
						ten exterior 400 Watt Metal Halide light fixtures. Tall						
						ceilings will require Ariel Lift. Removed and replaced three						
						out of ten shorted out ballasts. Replaced time clocks and						
	FM-		Compton			ballasts. When the ballast shorted out it also shorted out						
45	0054515	Los Angeles	Courthouse	19-AG1	1	the time clocks that were controlling the lights.	\$	7,503	\$	7,503	In Work	100
						Interior Finishes - Failed C.O. Sensors - Removed and						
						replaced twelve defective C.O. sensors. All new C.O.						
						sensors have been calibrated to manufactures						
						specifications and lower level parking structure exhaust						
	FM-		Airport			fans have properly turn off. The lower level basement parking structures C.O. sensors are currently in alarm and						
16		Los Angeles	Airport	19-AU1	1	have activated the exhaust fans.	\$	11,975	ć	0 2/1	Complete	77.17
40	0034310	LUS Aligeles	Courtilouse	13-A01		HVAC - Replace the VFD for AHU #4. The supply motor	ې ا	11,973	ې ا	9,241	complete	//.1/
						variable frequency drive (VFD) for AHU #4 is						
						nonoperational. At this time the supply motor is operating						
	FM-		Norwalk			only at full speed. In this condition the air ducts can over						
47	0054517	Los Angeles	Courthouse	19-AK1		pressurize and burst apart.	\$	7,565	\$	6,433	In Work	85.03
		0				Fire Protection - Replace Alarm Switch device. Alarm flow		,				
						switch device has failed on the pre-action system on the						
	FM-		Chatsworth			1st floor Northside; and a communication trouble signal on						
48	0054518	Los Angeles	Courthouse	19-AY1	1	the 2nd floor enunciator panel.	\$	4,142	\$	4,142	In Work	100
						HVAC - Pipe Leak - Set-up Containment, conduct						
						Environmental Testing, and replace copper piping to the						
	FM-		Burbank			chilled water supply line. Currently water is dripping from						
49	0054519	Los Angeles	Courthouse	19-G1	1	the ceiling into the judge's chamber.	\$	12,445	\$	11,295	In Work	90.76



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY	PROGRAM BUDGET SHARE OF	JOB STATUS	FACILITY MODIFICATION PROGRAM
	ш		<b>LL</b>			SHOKT IIILE			ш 2			
	FM-		Airport			Plumbing - Replace defective floats (2) to the sewage						
50	0054525	Los Angeles	Courthouse	19-AU1		ejector pump. Sewage ejector does not operate properly	\$	13,320	\$	10,279	In Work	77.17
			Dasadona			Interior Finishes - Drain Leak - Containment set-up, environmental testing, clean up, restore lighting circuit breaker panel and replace drain pipe. Water leaked into the 3rd floor electrical room and affected a lighting circuit breaker panel. The source of the leak was a cracked drain pipe in the 4th floor. The electrical room and adjacent						
51	FM- 0054526	I os Δngeles	Pasadena Courthouse	19-J1	1	room #308 are under containment to expedite the drying process of the plaster ceilings.	¢	16,158	¢	16 158	In Work	100
	FM-		Pasadena	10.11		Interior Finishes - Failed Flush Valve - Containment set up, clean up, environmental testing, and build back. Water leaked into the 2nd flr office #222 and adjacent office. The source of the leak was a faulty urinal in the 3th floor Public Defenders. Containment will stay up until the drying and	ć	15 222	č			100
52	0054527	Los Angeles	Courthouse	19-J1	T	build back processes are completed.	\$	15,223	\$ 	15,223	In Work	100
53	FM- 0054530	Los Angeles	Torrance Courthouse	19-C1	1	HVAC - Failing Chiller - Rebuild Chiller #1, work to include compressor rebuild, chemical etch tubes and PRV actuator replacement. Chiller not working due low oil pressure. HVAC - Gas Leaks - Replace induced draft assembly in AHU- 4. evaporator motor in AHU-6. faulty igniter in AHU-11 and	\$	110,646	\$	94,204	In Work	85.14
54	FM- 0054531	San Diego	Kearny Mesa Traffic Court	37-C1		4, evaporator motor in AHU-6, faulty igniter in AHU-11 and return units to proper operation. Perform a leak check with the assistance of SDGE throughout the building and at each HVAC unit. Lock out gas supply to AHU's 4, 12, 13, and 14 as they were determined to have leaks in the induced draft assemblies.		6,536	\$	6.536	In Work	100
<u> </u>						TCEMAC WORK PRODUCT Last Underted 2/27/2015 at 1:19 PM	Ŧ	2,200	1 7	2,200		11 of

Trial Court Facility Modification *Emergency and Priority 1 (List A)* 12/27/2014 to 2/13/2015 Meeting Date 3/6/2015

11 of 14



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF	JOB STATUS	FACILITY MODIFICATION PROGRAM
						Elevators, Escalators, & Hoists - Rebuild and reinstall					
	FM-		Stanley Mosk			Elevator #6 generator. Generator failed and caused the car					
55	0054539	Los Angeles		19-K1		to not level properly to the floors.	\$ 58,668	Ş	57,060	In Work	97.26
			Edmund D.			Plumbing - Failed Water Pump - Remove and replace					
			Edelman			Domestic Skid Mounted Water Booster System, Controls					
	FM-		Children's			and Control Panel. One of three water pumps has failed,					
56	0054540	Los Angeles	Court	19-Q1	1	controls and control panel not working.	\$ 81,356	\$	56,941	In Work	69.99
						Interior Finishes - Water remediation, set up containments,					
						dried leak affected areas, and environmental testing. 2nd					
						floor Probation Men's Staff Restroom flooded. Water					
	FM-		Pasadena			leaked into the 1st Floor Lobby adjacent to the District					
57	0054544	Los Angeles	Courthouse	19-J1		Attorneys.	\$ 14,963	\$	10,377	In Work	69.35
						Plumbing - Pump water out of sewage pit and rebuild					
						sewage pump #2. Sewage pump #2 is not currently					
	FM-		Downey			operating and water needs to be removed from the sewage					
58	0054545	Los Angeles	Courthouse	19-AM1	1	pit.	\$ 5,273	\$	4,414	In Work	83.7
	FM-		Alhambra			Interior Finishes - Water remediation, set up containments, clean up, dried leak affected rooms and environmental testing. An in-custody clogged a toilet in 2nd Flr Holding Cell and flooded holding cell A. Water leaked into the 1st					
59	0054546	Los Angeles	Courthouse	19-11	1	floor Courtroom 2, Chambers 2, and the public lobby.	\$ 12,273	\$	10,555	In Work	86
						Interior Finishes - Replace the compressor for A/C buildup					
						split system in the basement. The compressor for the A/C					
			Monrovia			buildup split system has failed internally. The system					
	FM-		Training			supplies cooling to the 1st floor classroom 100,					
60	0054547	Los Angeles	Center	19-N1	1	administration offices, and the rear nurses offices.	\$ 14,273	\$	10,032	In Work	70.29



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

Image: Second		FM NUMBER	LOCATION	FACILITY	BUILDING	PRIORITY	SHORT TITLE		TCFMAC FUNDED CC	FACILITY MODIFICATION	PROGRAM BUDGET SH	JOB STATUS	FACILITY MODIFICATION PROGRAM
FM-Van Nuys CourthouseChambers, boom lift required for window replacement. Window cracked due to expanding and contracting glassS8,575\$7,695In Work8610054548Los AngelesEast19-AX11 due to temperature changes.\$8,575\$7,695In Work8610054548Los AngelesEast19-AX11 due to temperature changes.\$8,575\$7,695In Work8610054549Los AngelesMichael D. Antonovich AntelopeElectrical - Replace battery charger. Emergency Generator not working; battery not charging need to replace battery battery not charging need to replace battery\$6,298\$4,630In Work7620054549Los AngelesCourthouse19-A211 charger.\$6,298\$4,630In Work7630054553Los AngelesCourthouse19-K11 needs rectifier and brake coil replaced.\$10,410\$10,125In Work5630054553Los AngelesCourthouse19-K11 needs rectifier and brake coil replaced.\$10,410\$10,125In Work5640054560Los AngelesCourthouse19-K11 pleubing - Dig up sewer line at (2) locations, sally port and planter area and replace failed pipe (separation) - black water is currently leaking. Use camera footage to determine exat location approx 26ft from clean out and 189 ft from clean out. Depth of 5'e' to 6' deep. when complete backfill holes with compacted soi													
FM-CourthouseWindow cracked due to expanding and contracting glassS8,575\$7,695In Work8610054548Los AngelesEast19-AX11due to temperature changes.\$8,575\$7,695In Work861Michael D.AntonovichAntonovichElectrical - Replace battery charger. Emergency Generator\$\$\$8,675\$7,695In Work8620054549Los AngelesCourthouse19-AZ11charger.\$6,298\$4,630In Work7620054549Los AngelesCourthouse19-AZ11charger.\$6,298\$4,630In Work7630054553Los AngelesCourthouse19-K11needs rectifier and brake coil replaced.\$10,410\$10,125In Work5630054553Los AngelesCourthouse19-K11needs rectifier and brake coil replaced.\$10,410\$10,125In Work5640054560LakeCenter17-811planter area and replace failed pipe (separation) - black water is currently leaking. Use camera footage to determine exact location approx 26ft from clean out and 189 ft from clean out. Depth of 5'6" to 6' deep. when complete backfill holes with compacted soil/fill, at Sally port cap hole with 3" layer of concrete with a height 2'\$22,000\$22,000In Work													
610054548Los AngelesEast19-AX11due to temperature changes.\$8,575\$7,695In Work8Image: Michael D. Antonovich AntelopeMichael D. AntelopeAntonovich AntelopeImage: Michael D. AntelopeImage: Michael D. Image: Michael D. AntelopeImage: Michael D. Image: Michael D. Image: Michael D.Image: Michael D. Image: Michael D. Image: Michael D.Image: Michael D. Image: Michael D. Image: Michael D.Image: Michael D. <td></td>													
Michael D. Antonovich Antelope ValleyMichael D. Antonovich Antelope ValleyMichael D. Antonovich Antelope ValleyElectrical - Replace battery charger. Emergency Generator not working; battery not charging need to replace battery\$ 6,298\$ 4,630In Work7620054549Los AngelesCourthouse19-A211charger.\$ 6,298\$ 4,630In Work7FM- 63Stanley Mosk FM- 63Stanley Mosk Courthouse19-K11needs rectifier and brake coil replaced.\$ 10,410\$ 10,125In Work9630054553Los AngelesCourthouse19-K11needs rectifier and brake coil replaced.\$ 10,410\$ 10,125In Work9640054560LakeSouth Civic CenterPlumbing - Dig up sewer line at (2) locations, sally port and planter area and replace failed pipe (separation) - black water is currently leaking. Use camera footage to determine exact location approx 26ft from clean out and 189 ft from clean out. Depth of 5'6" to 6' deep. when complete backfill holes with compacted soil/fill, at Sally port cap hole with 3" layer of concrete with a height 2'\$ 22,000\$ 22,000In Work								<b>_</b>		4			
FM-Antonovich AntelopeIElectrical - Replace battery charger. Emergency Generator not working; battery not charging need to replace batteryIII <t< td=""><td>61</td><td>0054548 Los</td><td>•</td><td></td><td>19-AX1</td><td>1</td><td>due to temperature changes.</td><td>Ş</td><td>8,575</td><td>Ş</td><td>7,695</td><td>In Work</td><td>89.74</td></t<>	61	0054548 Los	•		19-AX1	1	due to temperature changes.	Ş	8,575	Ş	7,695	In Work	89.74
FM-Antelope ValleyAntelope ValleyElectrical - Replace battery charger. Emergency Generator not working; battery not charging need to replace batteryAntelope valleyNoNo620054549Los AngelesCourthouse19-A211charger.\$6,298\$4,630In Work7630054553Los AngelesCourthouse19-K11charger.\$10,410\$10,125In Work9630054553Los AngelesCourthouse19-K11needs rectifier and brake coil replaced.\$10,410\$10,125In Work9640054560LakeCourthouse19-K11needs rectifier and brake coil replaced.\$10,410\$10,125In Work9640054560LakeCourthouse19-K11needs rectifier and brake coil replaced for elaced nout and planter area and replace failed pipe (separation) - black water is currently leaking. Use camera footage to determine exact location approx 26ft from clean out and 189 ft from clean out. Depth of 5'6'' to 6' deep. when complete backfill holes with compacted soil/fill, at Sally port cap hole with 3'' layer of concrete with a height 2'\$22,000\$22,000\$22,000In Work													
FM-Valleynot working; battery not charging need to replace batteryss<							Flastrical Daplace bettery charger Emergency Concreter						
620054549Los AngelesCourthouse19-AZ11charger.\$6,298\$4,630In Work7FM-Stanley MoskBrake Coil. Grand side Escalators, & Hoists - Replaced Rectifier and Brake Coil. Grand side Escalator 1 - 2 non-operational and 0054553\$10,410\$10,125In Work5630054553Los AngelesCourthouse19-K11needs rectifier and brake coil replaced.\$10,410\$10,125In Work5640054560LakeCenter17-B11below the asphalt finish height\$22,000\$22,000In Work5													
FM-       Stanley Mosk       Elevators, Escalators, & Hoists - Replaced Rectifier and Brake Coil. Grand side Escalator 1 - 2 non-operational and 0054553 Los Angeles       \$ 10,410 \$ 10,125 In Work       In work       S         63       0054553 Los Angeles       Courthouse       19-K1       1 needs rectifier and brake coil replaced.       \$ 10,410 \$ 10,125 In Work       S       In work       S         63       0054553 Los Angeles       Courthouse       19-K1       1 needs rectifier and brake coil replaced.       \$ 10,410 \$ 10,125 In Work       S         64       0054560 Lake       South Civic       Plumbing - Dig up sewer line at (2) locations, sally port and planter area and replace failed pipe (separation) - black water is currently leaking. Use camera footage to determine exact location approx 26ft from clean out and 189 ft from clean out. Depth of 5'6" to 6' deep. when complete backfill holes with compacted soil/fill, at Sally port cap hole with 3" layer of concrete with a height 2'         64       0054560 Lake       Center       17-B1       1 below the asphalt finish height       \$ 22,000 \$ 22,000       In Work				,	10 471			ç	C 200	4	4 ( 20		72 51
FM- 63Stanley Mosk 0054553ID-SAngelesStanley Mosk CourthouseID-K1ID-R1Brake Coil. Grand side Escalator 1 - 2 non-operational and needs rectifier and brake coil replaced.\$ 10,410\$ 10,125In WorkSID-SA	62	0054549 LOS	Angeles Col	burthouse	19-AZ1		3	Ş	6,298	Ş	4,630		73.51
630054553Los AngelesCourthouse19-K11needs rectifier and brake coil replaced.\$10,410\$10,125In Work94444999			Sta	anlov Mock									
FM-South CivicSouth CivicPlumbing - Dig up sewer line at (2) locations, sally port and planter area and replace failed pipe (separation) - black water is currently leaking. Use camera footage to determine exact location approx 26ft from clean out and 189 ft from clean out. Depth of 5'6" to 6' deep. when complete backfill holes with compacted soil/fill, at Sally port cap hole with 3" layer of concrete with a height 2'South CivicImage: Concrete with a height 2'640054560LakeCenter17-B11below the asphalt finish height\$ 22,000\$ 22,000Image: Nork	62				10 K1		·	ć	10/10	ć	10 125	In Work	97.26
FM-South CivicSouth Civicport cap hole with 3" layer of concrete with a height 2'\$ 22,000\$ 22,000In Work	03		Aligeles Col	Juitilluse	19-К1			ې	10,410	ې ا	10,125		97.20
FM-South Civic640054560LakeCenter17-B11below the asphalt finish height\$ 22,000<													
FM-South CivicSouth Civicfrom clean out. Depth of 5'6" to 6' deep. when complete backfill holes with compacted soil/fill, at Sally port cap hole with 3" layer of concrete with a height 2'\$ 22,000\$ 22,000In Work													
FM-South Civic189 ft from clean out. Depth of 5'6" to 6' deep. when complete backfill holes with compacted soil/fill, at Sally port cap hole with 3" layer of concrete with a height 2'Image: Conter in the second													
FM-South Civiccomplete backfill holes with compacted soil/fill, at Sally640054560LakeCenter17-B11below the asphalt finish height\$ 22,000\$ 22,000In Work													
FM-South Civicport cap hole with 3" layer of concrete with a height 2'640054560LakeCenter17-B11below the asphalt finish height\$ 22,000\$ 22,000In Work													
64         0054560         Lake         Center         17-B1         1         below the asphalt finish height         \$ 22,000         \$ 22,000         In Work		FM-	Sou	outh Civic									
	64	0054560 Lake	e Cer	enter	17-B1			\$	22,000	\$	22,000	In Work	100
								•	,	· ·	,		
There is currently a short in an electrical component of the						ŀ	There is currently a short in an electrical component of the						
FM-     Airport     East sally port gate operator which is not operating		FM-	Air	rport			East sally port gate operator which is not operating						
65 0054562 Los Angeles Courthouse 19-AU1 1 properly, causing a security issue. \$ 8,768 \$ 8,768 Complete	65	0054562 Los	Angeles Co	ourthouse	19-AU1			\$	8,768	\$	8,768	Complete	100
COUNTY MANAGED - Roof Damage - Remove and replace							COUNTY MANAGED - Roof Damage - Remove and replace			1			
approximately 1,600 sf of torch down roof, high winds have							approximately 1,600 sf of torch down roof, high winds have						
FM-       Chester Civic       blown off a signification portion of the roof ad it will need		FM-	Che	nester Civic			blown off a signification portion of the roof ad it will need						
66         0054564         Plumas         Complex         32-C1         1         to be replaced.         \$ 17,200         \$ 17,200         \$ 17,200         In Work													

Trial Court Facility Modification *Emergency and Priority 1 (List A)* 12/27/2014 to 2/13/2015 Meeting Date 3/6/2015

13 of 14



DRAFT

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF	JOB STATUS	FACILITY MODIFICATION PROGRAM
	FM-		Pasadena			Interior Finishes - Water remediation, set up containment, contain leaking, and dry leak affected areas. A floor drain overflowed in the 3rd AHU #3 mechanical room. Water leaked into the 2nd floor Probation Dept. The affected area						
67	0054565	Los Angeles	Courthouse	19-J1	1	in the Probation Dept is cubicle D inside of room #214.	\$	13,735	\$	13,735	In Work	100
68	FM- 0054577		New Downtown Merced Courthouse	24-A8		HVAC - Failed Pump Bearings - Remove and replace bearings, the boiler Hot water circulating pump bearings have failed	\$	5,897	\$	5,897	In Work	100
	FM-		Santa Monica			Plumbing - Replaced Leaking Pipe - Set-up containment and drying equipment, conduct environmental testing, replaced 2 ft of 1 1/2" piping and fitting, replaced one 90 and coupling, reset hangers and supports, and installed new ceiling tiles. This work was completed as a P1 emergency						
69	0053541	Los Angeles	Courthouse	19-AP1		due to water leaking into Room 202B, file storage room.	\$	16,375	\$	12,853	Complete	78.49
70	FM- 0054554	Los Angeles	Torrance Courthouse	19-C1		Elevators, Escalators, & Hoists - Install newly fabricated Selector Tape Deflector Sheaves. Elevator #5 Selector Tape Bearing worn out and requires replacement.	\$	22,653	\$	19,287	Unfunded	85.14
						TOTAL:	\$1	,535,771	\$1	,266,206		





TRIAL COURT FACILITY MODIFICATION Advisory committee

Meeting Date: 3/6/2015

### Action Item 2 – (Action Required) – Priority 1 Funding – Reallocation of Funding

#### **Summary:**

Review and discuss Emergency Facility Modification Funding (Priority 1) funding

#### **Supporting Documentation:**

• None

#### **Action Requested:**


Staff recommends the reallocation of \$2.8M in funding to support Priority 1 projects.

# Action Item 2 List A – Emergency Facility Modification Funding (Priority 1)

Original P1 Budget \$7M P1 Budget Increase to \$8M approved Current projection is that P1 requirements will reach \$11.5M **Re-allocation Recommendations** Reallocate \$986k from Funding Hold Projects 2. Adjust Planned Spend from April/May



# Action Item 2 List A – Emergency Facility Modification Funding (Priority 1)







TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

Meeting Date: 3/6/2015

### Action Item 3 – (Action Required) - List B – Facility Modifications Less than \$50k (Priority 2)

#### **Summary:**

List B – Facility Modifications Less than \$50k (Priority 2)

Total Project Count:	107
Total Potential FM Budget Share of Cost:	\$946,617

#### **Supporting Documentation:**

• List B – Facility Modifications Less than \$50k (Priority 2)

#### **Action Requested:**

Ratify Judicial Council Staff preliminary decision for execution approval of List B – Facility Modifications Less than \$50k (Priority 2).

# Action Item 3 List B – Facility Modifications Less than \$50k (Priority 2)

- There were 107 new FMs Less than \$50k this period
  - Total estimated FM Program budget share is \$946,617
  - Maintaining current rules that restricts funding to \$50K for Priority 2 FMs only
  - Funding is tracking at a potential of \$400k below approved budget





	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGE I SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
			Clara			Grounds and Parking - Damaged Sallyport Roll-Up - Replace aluminum bottom rail						
			Shortridge			and install new safety edge. Straighten rods, reinstall curtain back onto guides and						
			Foltz Criminal			set limits/test for proper operation. Bus hit bay #2 when coming down causing						
1	FM-0054327	Los Angeles	Justice Center	19-L1	2	damage to bottom rail and safety edge.	\$	3,415	\$	2,349	Complete	68.79
			Morgan Hill			Electrical - Replace 3 failed non-keyed switches to ATS system. Generator does not						
2	FM-0054328	Santa Clara	Courthouse	43-N1	2	switch for back-up power	\$	4,351	\$	4,351	In Work	100
						Security - Replace failing motor and controller on oversize Sheriff's Vehicle Bus Gate -						
						install one new 1 horse power, 230 volt Gear Head Motor Operator with heavy duty						
			East County			brackets, wire and electrical connection. Sheriff's large bus gate equipment motor						
			Regional			and control panel is starting to fail, causing a safety issue with unloading and loading						
3	FM-0054331	San Diego	Center	37-11	2	of inmates.	\$	4,768	\$	4,768	In Work	100
						Plumbing - Replace leaking gate valve and spool on the domestic water booster						
			Metropolitan			system pump. Currently the gate valve and spool is leaking and can go off-line						
4	FM-0054333	Los Angeles	Courthouse	19-T1	2	causing the building to not have any water.	Ş	3,663	\$	3,463	In Work	94.54
5	FM-0054334	Los Angeles	Metropolitan Courthouse	19-T1		HVAC - Rebuild circuit pump #1 on boiler #1. Currently the circuit pump #1 failed to operate properly during the level III PM (PM 2491405). The portable analyzer test (SCAQMD) will not be able to be performed until this replacement is completed.	\$	3,684	\$	3,483	In Work	94.54
						Plumbing - Replace 22 bathroom sinks that are severely chipped and rusted; Risk Management recognizes this as a hazard. The uneven surfaces are hard to clean and						
						harbor infectious bacteria, fecal bacteria, and tetanus. The edges are cut hazards and						
6	FM-0054335	Contra Costa	Bray Courts	07-A3		could aid in infection spread.	¢	14,534	¢ 1	2 129	In Work	85.52
	1101 0054555			07 43		Roof - Install guardian roof railing system including (4) ground plates, (1) 10 safety	<b>,</b>	17,337		2,723		05.52
			Mental Health			rails, (2) 6 safety rails & painted safety striping to comply with Cal-OSHA fall						
7	FM-0054338	Los Angeles		19-P1		protection / Current roof is missing guard rails for fall protection.	Ś	7,179	\$	5,119	In Work	71.31
		2007.180100				Fire Protection - Replace the clogged cooling lines on diesel fire pump - Install new	Υ 	,,_,,	Ψ	0)220		/
						pressure switch, strainers, pressure regulator, gate valves & 20-feet galvanized pipe,						
						union elbows and tee's. Replace leaking 4-bolt flange on other side of fire pump.						
			East County			Diesel fire pump has a bad gasket around flange and is leaking water. Needs new						
			Regional			piping, gate valves, a pressure switch and a pressure regulator due to they have out						
8	FM-0054393	San Diego	Center	37-11		lived their life span and failure is imminent.	\$	4,908	\$	3 <u>,</u> 323	In Work	67.71



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY FSTIMATF	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
			George E.			HVAC Baplace failed reaften exhaust fan whase wern out drive components are						
9	FM-0054395	Alameda	McDonald Hall of Justice	01-F1		HVAC - Replace failed rooftop exhaust fan whose worn-out drive components are creating excessive and unacceptable noise and vibration	Ś	12,231	\$	12 231	In Work	100
	1101 003 4333	Alameaa				HVAC - Replace failed and worn-out supply fan shaft bearings and sheaves on air	<b>,</b>	12,231	Υ ·	12,231		100
10	FM-0054396	Solano	Hall of Justice	48-A1		handler AHU-S2 to eliminate excessive vibration	\$	12,911	\$	9,402	In Work	72.82
			Old	_		Grounds and Parking Lot - No power to 12 exterior light posts - Replace 300 feet of		<b>,</b> -		- / -		
11	FM-0054397	Santa Clara	Courthouse	43-B2		failed #12 wire - Safety and Security Risk	\$	5,569	\$	5,569	In Work	100
12	FM-0054400	Santa Clara	Palo Alto Courthouse	43-D1	2	Fire Protection - Per Fire Marshall Notice -Install metal signage for (4) FDC's and (1) PIV - Install (3) missing exit signs - Install (25) triangular fire extinguisher wall mount signs - Remove and dispose of abandoned (1) Ansul system in holding cell kitchen.	\$	5,982	\$	3,951	In Work	66.04
13	FM-0054402	Orange	North Justice Center	30-C1		defective and need to be replaced. Existing defective burners, hot surface igniters and flame sensors to be removed and 14 new burners, 1 new hot surface igniter and 1 new flames sensor to be installed in each RayPak Boiler. Work to include start up and testing.	\$	2,832	\$	2,558	In Work	90.31
14	FM-0054404	Orange		30-A1	2	HVAC - Failing VFD - Remove and replace the top portion of the VFD due to the present VFD shorting out. System is on bypass and if the bypass were to fail there would be no air flow to the 5th floor.	\$	4,517	\$	4,118	In Work	91.17
10		Orango	Central Justice			HVAC - Air Handler Bearings - Remove and replace the worn bearings on Air Handler	ć		ć	0 661	In Mork	01 17
13	FM-0054405	Orange	Center Central Justice	30-A1		15, the bearings are worn which is causing the air handler to work harder with the Grounds and Parking - Automatic controls on Dock roll up doors have failed. Doors do not shut when using remote or automatic closer on the dock. Staff have to manually engage door before they can work properly. If doors cannot be closed by remote then this creates a safety issue due to staff having to leave the door open	\$	9,500	Ş	0,001	In Work	91.17
16	FM-0054406	Orange	Center	30-A1	2	until someone can manually close it.	\$	6,735	\$	6,140	In Work	91.17
17	FM-0054407	Orange		30-D1	2	FM - Flooring - Replace 24 square yards of high endurance carpet tile and 92 LF of black 4" cove base to match what was abated. Flooring was abated due to a black water flood on 12/19/14 and was severely contaminated requiring removal.	\$	7,945	\$	7,945	In Work	100
			Inglewood			Elevator - Replace 2-defective selector switches on Elevator #1 - Elevator is stuck on				<b>o i</b> = -		
18	FM-0054408	Los Angeles	Courthouse	19-F1	2	the 4th floor, doors open not responding.	\$	4,629	Ş	3,451	In Work	74.56



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
			New San			Grounds and Parking Lot - Replace approx. 30 SF of damaged concrete. Sand, repaint,						
		San	Bernardino			and reutilize two existing bollards near a light pole in the secure bus area. Existing						
19	FM-0054409	Bernardino	Courthouse	36-R1	2	concrete was destroyed by Sheriff's bus impact to one of the two bollards.	Ş	4,607	\$	4,607	Complete	100
			Salinas			UVAC Cooling Tower Bonlace failed (2) Fan Shaft Bearings DVC Drift Eliminators						
20	FM-0054413	Monterey	Courthouse- North Wing	27-A1		HVAC - Cooling Tower - Replace failed (2) Fan Shaft Bearings, PVC Drift Eliminators and spray nozzle. Found during level 8 PM	¢	13,316	¢	12 216	In Work	100
20	1101-0054415	wonterey		27-AI	2	and spray nozzie. I odna daring level o Fivi	ې ا	13,310	ې ا	13,310		100
			Downtown			Plumbing - Replace Approx 10 feet of failed 4 inch sewer pipe, add a dual cleanout in						
			Superior			the planter area, hydro jet to remove tree roots. Camera scope included . Tree roots						
21	FM-0054414	Santa Clara	-	43-B1		have created breaks in the pipe causing sewage leaks into the building	\$	10,060	\$	10,060	In Work	100
			Gale -					,		,		
			Schenone Hall			Security - Door Locking Hardware - Replace three failed solenoid door locking devices						
22	FM-0054415	Alameda	of Justice	01-E1	2	and one door control switch	\$	2,244	\$	2,244	In Work	100
						Interior Finishes - Setup full containment with negative air machine, HEPA vacuum						
						and wipe down the complete work area in the basement 2nd floor Air Handler						
			Metropolitan			rooms. Loose particles have been found on the floor and must be removed for						
23	FM-0054419	Los Angeles	Courthouse	19-T1	2	safety.	\$	10,679	\$	10,096	In Work	94.54
			Van Nuys			Elevators, Escalators, & Hoists - Replace Timed Relay Contact, Reset door lock faults,						
			Courthouse			tested and return elevator to service. Elevator #2 not responding to calls, tripped	4					
24	FM-0054420	Los Angeles	West	19-AX2	2	loop overload due to timed relay contact failure.	Ş	2,535	Ş	2,040	In Work	80.48
						HVAC - Install new tube bundle in heat exchanger #3 - Refurbish end cap before						
			Ctoploy Moole			installing along with installing new gaskets, piping material, bolt kits and hardware. If						
25			Stanley Mosk	10 K1		the online heat exchanger goes down for any reason there will be no heating in the	ć	14 562	ć	14 160	In Mort	07.26
25	FM-0054421	LOS AUREIES	Courthouse	19-K1	2	court.	ې ا	14,562	Ş	14,103	In Work	97.26
			Stanley Mosk			HVAC - Rebuild seals and bearings for Chill Water Pump #21. Currently the seals are						
26	FM-0054422	Los Angeles	Courthouse	19-K1		blown and water is leaking onto the electrical equipment creating a safety situation.	Ś	11,200	Ś	10.893	In Work	97.26
								,200	<u>т</u>	_0,000		57.20
			Central Justice			Plumbing - Replace failed heat exchanger with leaking internal tubes. The exchanger						
27	FM-0054423	Orange	Center	30-A1		provides heat to all public hallways.	\$	24,255	\$	22,113	In Work	91.17



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
			Salinas			HVAC - Replace failed 12x10 hot water reheat coil, (1) VAV box Coil Kit, (2) FDI						
		• •	Courthouse-			flexible hoses for coil connection, Re-pipe utilizing flex connectors to protect from	4		4			
28	FM-0054428	Monterey	North Wing	27-A1	2	vibration, Replace water damaged baseboard for effected area.	Ş	14,137	\$	14,137	In Work	100
29	FM-0054431	Los Angeles	Edmund D. Edelman Children's Court	19-Q1		Exterior Shell - Restore 2 ea Metal "A" Frame structures, sand all steel, application of 1 coat primer and 2 oil base. Metal frames are deteriorating and losing its structural integrity	\$	4,832	\$	3,382	In Work	69.99
			Parking			Grounds and Parking Lot - Vandalism - Replace 20 each 10" x 24" "Gate Drain						
			Structure Lot			Covers". The drain covers at the Upper Levels of the parking area are missing and						
30	FM-0054434	Los Angeles	59- Whittier	19-AO2	2	believed to have been stolen for scrap recyclables. Failure to replace these covers	\$	4,745	\$	4,745	In Work	100
31	FM-0054435	Los Angeles	Chatsworth Courthouse	19-AY1	2	Plumbing - Install new booster pump and re-pipe connections. Currently the booster pump motor is not functioning and must be replace or it will start to effect the water supply to the building.	\$	7,825	\$	6,557	In Work	83.8
32	FM-0054437	El Dorado	Main St. Courthouse	09-A1		HVAC - Replace 5 Window AC units, Install 1 Window unit and 1 Split System and install a sub panel with 2 circuits - AC units are old and failing. Some zones need AC units added with necessary electrical circuits	\$	20,733	\$	20,733	In Work	100
33	FM-0054438	San Diego	Juvenile Court	37-E1		Interior Finishes - Unsafe Carpet - Remove and replace 78 square yards of the existing damaged carpet on the 2nd floor public corridor due to a trip hazard. Scope also includes prepping floor after the removal and disposal of the existing damaged carpet. All attempts to stretch, repair and patch the existing carpet have been exhausted.	\$	4,660	\$	4,660	In Work	100
			Arnason			Interior Finish - Replace failed in-floor door closer with a surface mounted door closer. The surface mounted unit is 1/3 the cost of installing another in-floor unit -						
34	FM-0054443	Contra Costa	Justice Center	07-E3	2	Existing closer does not properly close the exit door.	\$	15,605	\$	15,605	In Work	100
			Wiley W. Manuel	04.52		HVAC - Replace failed and leaking supply fan 01 cooling coil piping, ACM present in		4 475		0.05		
35	FM-0054448	Alameda		01-B3		the facility so testing and abatement if confirmed within piping insulation.	<u>ې</u>	1,175	Ş	985	In Work	83.8
			Downtown			Exterior Shell - Replace failed main door operator (motor) and closure, (2) exit						
		Conto Class	Superior	42.04		devices (panic bar) and continuous door hinges to doors, threshold plate 6 inches X		4 4 7 6 9		1 4 7 6 9	1	
36	FM-0054449	Santa Clara	Court	43-B1		72. Door is not latching shut and is a safety security risk HVAC - Remove, replace, and dispose of damaged 30' section of 2" cast iron pipe and	Ş	14,763	Ş	14,763	In Work	100
37	FM-0054451	San Diego	Juvenile Court	37-E1		fittings. Waste lines are corroded and at risk of leaking, needs to be replaced due to	\$	3,586	\$	2,676	In Work	74.62



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY	MOUIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY FSTIMATF	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Plumbing - Failed Backflow Device (Vault Location) - The Fire System backflow device						
20		Pivorsido	Larson Justice	22 C1		has been tested and failed, the new backflow device will be replaced above ground	ć	12 050	ć	11 102	In Work	00.01
38	FM-0054453	Riverside	Center Tulare	33-C1	2	to meet the current California plumbing code. Plumbing - Remove and replace defective sewage sump pump that has failed -	Ş	13,850	Ş	11,192	In Work	80.81
20	FM-0054454	Tulara		54-B1	2	Sewage pump trips on voltage overload and is inoperable.	ć	2,709	\$	1 906	In Work	70
59	FIVI-0054454	Tulare	DIVISION	54-Б1		Fire Protection - Replace (1) smoke head and correct ground fault. Ground fault	Ş	2,709	Ş	1,090		/0
			Morgan Hill			trouble caused smoke head to fail. Fire Watch will be conducted while fire panel is						
10	FM-0054455	Santa Clara	•	43-N1		offline. Work to be performed off hours.	¢	4,445	\$	1 1 1 5	In Work	100
40	1101-0054455		Van Nuys	43-111		Fire Protection - Failed Booster Pump Valve - Remove and replace a broken valve on	ې ا	4,445	ې ا	4,445		100
			Courthouse			fire booster pump for roof hoses, and add 3 code required signs. The valve is broken						
/1	FM-0054458	Los Angeles		19-AX1		and stuck in the open position.	¢	5,227	\$	1 691	In Work	89.74
41	1101-0054458	LUS Aligeles	Gordon	13-471	2		Ş	5,227	ې ا	4,091		05.74
			Schaber Sacramento Superior			Roof - Repair leaks at the 3rd, 4th, & 5th floor roofs - Remove roof ballast to expose the areas of the leaking roof, prep the roof areas where the single ply roof has separated and apply new roofing to these areas (Approximately 150 LF), Continued						
42	FM-0054463	Sacramento	•	34-A1		leaking will cause damage to building structure	\$	8,562	\$	8,562	In Work	100
	FM-0054464		El Monte Courthouse	19-01		Vandalism - Buff out 70 windows and replace 4 windows and 1 door of the courthouse. Graffiti has been etched into the windows on the 1st, 2nd, and 3rd floors, along with the guard shack and juror room windows.	\$	15,000			In Work	58.12
44	FM-0054468	Los Angeles	Metropolitan Courthouse	19-T1		Plumbing - Install wye strainer to reduce the debris in the backflow, currently there is debris from the domestic water supply becoming lodged between the check valve seat and the sealing disc, preventing the check valve from closing all the way.	\$	9,221	\$	8,718	In Work	94.54
45	FM-0054469	Los Angeles	Metropolitan Courthouse	19-T1		Electrical - Replace gaskets and valve cover gaskets to the emergency generator. The emergency generator is leaking oil which could cause the generator to fail during an emergency creating a safety situation.	\$	7,775	\$	7,350	In Work	94.54
46	FM-0054471	Los Angeles	Compton Courthouse	19-AG1		Plumbing - Failed Backflow Device - Remove and replace one failed 6" backflow assembly for the domestic water to the courthouse. The backflow was tested and failed, this assembly was beyond repair and had to be replaced.	\$	10,459	\$	6,917	In Work	66.13
47	FM-0054473	San Diego		37-H1		on the 3rd floor of holding block Effort is required to maintain integrity of the holding cell block, work to be completed after hours.	\$	24,295	\$	24,295	In Work	100
48	FM-0054474	Los Angeles	Airport Courthouse	19-AU1	2	Elevators, Escalators, & Hoists - Replace boards, power supply, speed sensor & door detector. Drive erased all parameters on boards, Elevator will not move with no	\$	2,158	\$	1,665	Complete	77.17



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Plumbing - Non Functioning Combination Toilet/Sink Unit - Remove and replace						
		Conto	Santa Maria			inoperable combination toilet and sink in Holding Cell 11, combo unit no longer						
40	FM-0054475	Santa	Courts	42-F5		functions rendering the cell offline. Replace with similar unit as existing model is no longer available.	ć	5,367	\$	E 170	In Work	96.49
49	FIVI-0054475	Dalvala	Building G	42-63	2	Interior Door Hardware - Replace failed non-mullioned double door ADA compliant	Ş	5,507	Ş	5,179		90.49
			Juvenile			panic hardware complete with top and bottom latches and linkage bars for						
50	FM-0054476	Alameda	Justice Center	01-C3		courtroom side of entry vestibule - Work to be performed after hours	Ś	13,540	Ś	13.540	In Work	100
			Sunnyvale			HVAC - Failed Chiller 2 - Remove and replace two each failed chilled water pump	Ψ		Υ 			
51	FM-0054482	Santa Clara	-	43-F1		motor bearings, one seal and two failed pressure gauges on Chiller Circuit 2.	\$	2,177	\$	2,177	In Work	100
52	FM-0054483	San Bernardino	New San Bernardino Courthouse	36-R1		Grounds and Parking Lot - Install rigging points onto 6 existing bollards located in front of Edison equipment cabinets. Utilize a forklift to remove the bollards and later reinstall them. This work is necessary for code required clearance for the equipment cabinets.	\$	4,141	\$	4,141	In Work	100
- 0		<b>.</b>	Larson Justice			HVAC - Replace failed 15HP cooling tower fan motor. Currently only one chiller can	4		4	c o <b>-</b> 4		
53	FM-0054484	Riverside	Center	33-C1	-	operate, presenting court operational disruption threat	Ş	8,627	\$	6,971	In Work	80.81
54	FM-0054485	Orange	West Justice Center	30-D1		Structural - Large cracks have been identified on and around expansion joints in detention tunnels. Inject Sonnaborn MPII Poly Urethane sealant and carry out other related labor to prevent structural damage. Work must be completed during non-working hours.	\$	5,500	\$	5,500	In Work	100
			Metropolitan			HVAC - Rebuild the condenser water pump #2. The pump is currently leaking water						
55	FM-0054486	Los Angeles	Courthouse	19-T1		and if it fails, it will affect the chiller to the building.	\$	6,723	\$	6,356	In Work	94.54
56	FM-0054489	San Diego	County Courthouse	37-A1		full containment 30x30 in order to access the ballasts which are located on the back of the light fixtures. Depart 19 was recently reutilized and current lighting levels are insufficient.	\$	6,426	\$	6,426	In Work	100
57	FM-0054492	Orange	Betty Lou Lamoreaux Justice Center	30-B1		HVAC - Replace failed 30 HP motor for chilled water pump #5. The facility is running on one pump only; loss of the 2nd pump would result in complete loss of cooling.	\$	6,643	\$	5,311	In Work	79.95
58	FM-0054493	Alameda	Wiley W. Manuel Courthouse	01-B3		Fire Suppression System - Correct deficiencies discovered during quarterly inspection to include replacing one missing sprinkler escutcheon, one missing 2.5 inch standpipe cap, five painted sprinkler heads, and one corroded sprinkler head		2,502	\$	2,097	In Work	83.8



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	PROGRAM BUDGET SHARE OF PRELIMINARY FSTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
			Pasadena			Electrical - Underground Storage Tank - Replace non operational annular veeder root				
59	FM-0054496 L	os Angeles	Courthouse	19-J1		sensor in compliance with fire code and EPA regulations.	\$ 3,887	\$ 2,696	In Work	69.35
60	FM-0054500 L	os Angeles	Norwalk Courthouse	19-AK1	2	Elevators, Escalators, & Hoists - Enlarged the hole in the wall to prevent wires from chaffing and prevent short. Restored elevators 1-4 back to normal working conditions. Wires chaffing on call station housing which caused a short. Plumbing - Set-up containment, perform environmental testing, replace 10 feet of 8	\$ 2,239	\$ 1,904	Complete	85.03
61	FM-0054502 L	os Angeles	Metropolitan Courthouse	19-T1		inch pipe and fittings that are leaking. Currently water is leaking from the drain into the parking garage mechanical room. A heavy duty man lift will be utilized during this replacement.	\$ 13,581	\$ 12,839	In Work	94.54
62	FM-0054503 S	San Diego	Regional Center - Vista	37-F2		Fire/Life/Safety - Replace 40 failed strobes and horns. Fire alarm strobes and horns are not operating when an alarm is in progress.	\$ 4,705	\$ 4,705	In Work	100
63	FM-0054505 L	os Angeles	Metropolitan Courthouse Santa Clara	19-T1		Electrical - Install dedicated circuits for appliances to prevent over loading of circuit breakers. Currently the circuits are over loaded with the break room appliances, which is creating a safety hazard due to the circuits could catch on fire. Exterior Light Poles - Replace 12 failed parking lot lamps. Will require a lift truck for	\$ 13,040	\$ 12,328	In Work	94.54
64	FM-0054508 S	Santa Clara	Courthouse	43-G1	2	to access lights.	\$ 9,545	\$ 9,545	In Work	100
65	S FM-0054512	San Bernardino	Rancho Cucamonga Courthouse	36-F1		HVAC - Replace chiller condenser fan motor. Motor is making excessive noise at low speed and the bearings are showing signs of wear. Chiller provides cooling to critical Court IT equipment.	\$ 2,659	\$ 2,659	In Work	100
66	FM-0054520 N	Modoc	Barclay Justice Center	25-A1		Interior Finishes- Remove and replace small area of carpet to correct a reported and noted safety hazard in the primary cross office thoroughfare and break area.	\$ 2,000	\$ 2,000	In Work	100
67	FM-0054521 L	os Angeles	Mental Health Court	19-P1	2	Parking Lot - Demo existing 18 ft. x 5 ft. x 6 in. failing CMU block wall and replace with new 18 ft. x 5 ft. x 6 in. galvanized chain link fence. Currently CMU Block wall is cracked and ready to fall creating and safety hazard for public or pedestrians.	\$ 4,944	\$ 3,526	In Work	71.31
68	FM-0054522 L	os Angeles	Compton Courthouse	19-AG1	2	HVAC - Failing VFD Motor - Remove and replace one (1) 15 HP VFD, motor, pulleys and belts. Return Fan unit has defective VFD motor. Currently the VFD is in bypass causing the motor to run full speed wasting energy, adding stress on ducting, and shortening life expectancy on equipment.	\$ 5,796	\$ 3,833	In Work	66.13
69	FM-0054523 L	os Angeles	Airport Courthouse	19-AU1		Electrical - Replace 10 defective lights and 10 ballasts in the basement parking - Poor lighting conditions have created an egress issue in the parking structure.	\$ 4,038	\$ 3,116	In Work	77.17



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Elevators, Escalators, & Hoists - Install new closed-loop door operator - Remove and						
			Santa Monica			replace the failed closed-loop door operator, the elevator is unable to maintain						
70	FM-0054524	Los Angeles	Courthouse	19-AP1	2	proper operation as the hoist way door operator is malfunctioning.	\$	19,720	\$	15,478	In Work	78.49
						Garland CPR seam sealer and GarMesh product to cover 2 penetrations at each wall						
						brace, vent pipes and vent base flashings, ridge cap laps seams and exposed screws,						
			Superior			flashings at perimeter roof edging. Fabricate and install 18 gaugesheet metal cap and						
			Court at			cricket at AC unit 1, and install and seal sleeper flashings on the 2 remaining AC units.						
71	FM-0054528	Tehama	Corning	52-B1	2		\$	11,200	\$	11,200	In Work	100
						Doors and Hardware - Replace electric lock parts no longer available after hardware						
			South Placer			company consolidation. Install monitor, card reader and expansion panel for card						
72	FM-0054529	Placer	Justice Center	31-H1	2	reader system. Include 4 card reader panels for possible use by court if additional	Ş	9,900	Ş	9,900	In Work	100
			Matropolitan			Vandalism - Paint and remediate graffiti around the public sidewalk, planters, fixtures and sidewalk right outside courthouse. Graffiti must be removed for the safety of the						
72		Los Angolos	Metropolitan	19-T1		courthouse visitors and employees.	ć	1 1 7 7	\$	2 007	In Work	04 54
/3	FM-0054532	LOS Angeles	Courthouse	19-11	2	COUNTY - INTERIOR FINISHES - Remove and replace minor carpet areas in Court	Ş	4,122	Ş	5,697	In Work	94.54
74	FM-0054533	Shacta	Justice Center	15 42	2	Rooms 1 and 2 that totaling 600 sq. ft. Carpet can no longer be repaired.	ć	2 166	ć	2 166	In Work	100
/4	FIVI-0034355	5118518	Justice Center	43-AZ	2	HVAC - Replace faulty condenser flow proving switch on chiller #2 with IMF type flow	Ş	3,466	\$	5,400		100
			Fresno County			switch - Existing flow switch is not working properly which locks out the chiller when						
75		Fracha	Courthouse.				ć	2 526	ć	2 122	In Work	05.01
/5	FM-0054534	FIESHO	Courthouse.	10-A1	2	start is requested.	Ş	2,536	Ş	2,432	In Work	95.91
76	FM-0054535	San Bernardino	San Bernardino Courthouse	36-A1		Plumbing - Replace chilled water pump's failed bearings and seals. Install insulation on chilled water pump #'s 1 and 2. Chilled water pump is frozen in place and currently inoperable. Chilled water pump is critical in ensuring adequate chilled water flow to the air handlers to provide necessary cooling for the building.	\$	9,430	\$	<u>9,4</u> 30	In Work	100
77	FM-0054536	Los Angeles	Pasadena Courthouse	19-J1		Interior Finishes - Removal and replacement of 4x4 ceiling tiles with 2x4 ceiling tiles. Due to the change of tiles, need to install new T-bars - total of 30 pcs. Ceiling tiles need to be replaced in the 2nd floor West Wing Div. 7. They are very old, worn and severely damaged due to water damage.	\$				In Work	69.35
78	FM-0054537	Fresno	Fresno County Courthouse.	10-A1		HVAC - Remove leaking chilled water valve on AHU #6 and replace with new 3" pneumatic 3-way mixing valve with new actuator and pilot positioner. Re-insulate new valve - The existing valve is leaking treated system water from the closed loop.	\$	5,462	\$	5,239	In Work	95.91



TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET	SHARE OF PRELIMINARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Security - Replace existing roof top PTZ camera with a new IP PTZ camera and tie it						
						into the new upgraded NVR CCTV system MCM. Exterior color camera has fuzzy						
			Airport			unclear feed on monitor; plaza control camera is not showing color on the monitor.						
79	FM-0054538	Los Angeles	Courthouse	19-AU1		Images cannot be seen clearly when reviewed and camera needs to be replaced.	\$	3,808	\$ 2	,939	In Work	77.17
			Wiley W.			Plumbing - Replace leaking reheat coil and provide new reconnection of piping, new						
			Manuel			dielectric unions, two isolation ball valves and new pneumatic control valve located in						
80	FM-0054541	Alameda	Courthouse	01-B3	2	the 1st floor Clerk's Office.	\$	9 <i>,</i> 625	\$ 9	,625	In Work	100
			Shafter/Wasc			Fire Protection - Replace Failing Fire Roll- up Door and Auto Crank. Roll-up door is						
81	FM-0054543	Kern	o Courts Bldg.	15-E1	2	extremely hard to open and close, court staff are manually lifting and closing.	Ş	3,923	Ş 3	,529	In Work	89.95
						Dlumbing Deplace 15' of failed cower line in the bacement parking garage. Droject						
			Central Justice			Plumbing - Replace 15' of failed sewer line in the basement parking garage. Project will include fittings, hangers, and scoping of the line, removal of 12'X16' area of ACM						
82	FM-0054550	Orange		30-A1		fire proofing with containment, and active monitoring of the ACM containment area.	¢	5,139	د <i>ر</i>	685	In Work	91.17
02	1101-0054550	Orange		JU-AI	2	Grounds - Large cracks on the main walkway to the Courthouse are creating a trip	ې ا	5,135	<u>ې د</u>	,005		51.17
						hazard - Remove and replace approximately 738 SF of concrete sidewalk. Complaints						
			West Justice			of people tripping and women's heels getting caught on these cracks have been						
83	FM-0054551	Orange		30-D1		communicated to Facilities.	\$	6,283	\$ 5	.697	In Work	90.68
		0	JIC			Security - Replaced failed power supply, motherboard and three 1 TB hard drives in		,		/		
84	FM-0054552	Fresno	Delinquency	10-P1	2	Multiplexer #4 - Multiplexer has failed and the sixteen connected cameras are not	\$	6,150	\$ 6	,150	In Work	100
						Grounds - Remove and replace approximately 2,300SF of concrete sidewalks in front						
			San			of the Courthouse. Concrete is cracked, chipped, and uneven in many areas, creating						
		San	Bernardino			a trip hazard for court staff and the public. Court has reported public and staff						
85	FM-0054557	Bernardino	Courthouse	36-A1	2	tripping.	\$	21,909	\$ 20	,954	In Work	95.64
						exchanger supplying upper floor courtrooms, chambers,, and public restrooms						
			Central Justice			currently without hot water. Project will include installation of a 3" backflow and						
86	FM-0054558	Orange	Center	30-A1		piping with 4 new flanged strainers to prevent sediment build up.	\$	25,055	\$ 22	,843	In Work	91.17
						Exterior Shell - Waterproof Membrane - Remove and replace approximately 750						
0-			Hayward Hall	01 51		square feet of aged and failed deck membrane to eliminate storm water intrusion		40.000		<b>-</b> 4 4		
87	FM-0054559	Alameda	of Justice	01-D1	2	into the building	\$	13,300	\$   11	,/44	In Work	88.3

DRAFT



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	ILITY DIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
			Criminal Court			Security - Modify and adjust Filing Counter Lobby entrance doors (2 ea) - Double						
88	FM-0054561 Nag			28-A1		glass doors are not closing causing a security issue (doors are rubbing at header)	Ś	6,738	Ś	6.738	In Work	100
			Kearny Mesa			HVAC - Replace failed heat exchanger, induced blower assembly, wiring harness, and	T		T			
89	FM-0054563 San	n Diego	Traffic Court	37-C1	2	igniter on AHU-14	\$	8,754	\$	8,754	In Work	100
90	FM-0054566 San		Hall of Justice (East)	43-A1		Grounds and Parking Lot - Judges Parking Lot Gate - Remove and replace (1) failed vehicle exit gate operator module required for proper operation to maintain security in the area.	¢	5,036	¢	5 036	In Work	100
50			B.F. Sisk	-5 //1		Elevators - Worn Elevator Sheave and Suspension Ropes - Remove and replace	Υ 	5,050	Ŷ	3,030		100
			Federal			damaged drive sheave and suspension ropes on Elevator #1. Work is needed to						
91	FM-0054567 Fre			10-01		comply with code.	\$	25,000	\$	25,000	In Work	100
92	FM-0054568 Los		Parking Structure Lot 59- Whittier Admin CTR	19-AO2		Electrical - Replace 7 poles with (2) 175watt metal halide lamps per pole. There is a total of (14) light fixtures s, boom lift required. Exterior light poles on the top level are nonoperational due to blown lamps and ballasts.	\$	3,112	\$	3,112	In Work	100
93	FM-0054569 Los		Airport Courthouse	19-AU1		Electrical - Replace emergency lighting battery packs. Stairway 4 and 5 have a total of 36 T-8 lighting fixtures with battery packs, these serve as emergency lighting. The battery packs have a date code of 9802 and are 16 years old. Battery packs are showing signs of damage and are beyond their life expectancy and require replacement. This is a fire/life safety issue.	¢	4,156	¢	3 207	In Work	77.17
			West Justice	13-701		Grounds - Remove Planter - Remove all plants and excess dirt, cap sprinkler lines and make all necessary preparations for the installation of gravel to this planter. The existing planter is an incline planter in the Secure Judges Parking lot which is creating constant problems and expenses. Located next to the bus bay and air Conditioning equipment, debris from dead plants flies into the a/c equipment. Irrigation and rain		4,130	Υ 	3,207		//.1/
94	FM-0054570 Ora			30-D1		causes dirt to erode onto the Judges parking lot creating a slip hazard.	\$	4,700	\$	4,700	In Work	100
	FM-0054571 Ora		Central Justice			Exterior Shell - Replace failed inner spring of dock bay door to accommodate motor replacement. Project will include a 16X11 Cookson rolling steel service door with surface mount, heavy duty guides, slide locks on each side, 22 gauge slats (flat#5)	\$	6,243	\$		In Work	91.17
٩٢	FM-0054573 Los		Antonovich Antelope Valley	19-AZ1		Fire Protection - Replace the pressure switch for the compressor on the Pre-Action system. The Pre-Action system is losing air and the compressor is not starting.	\$	2,948	\$	2 167	In Work	73.51



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY FSTIMATE	JOB STATUS	Facility Modification Program Budget % of Cost
						Safety - Prep and patch any areas of spalled concrete, prime and finish paint the entire area under the soffits and the fascia/front face of the roof overhangs - The						
						underside of the existing eaves have several areas that are showing signs of the						
97	FM-0051815	Merced	Old Court	24-A1		concrete spalling that could fall onto passers-by below	\$	42,611	\$	42,611	Unfunded	100
			Torrance			Grounds - Replace broken curb (35 lf) and concrete (350 sf) causing trip hazard in						
98	FM-0047040	Los Angeles	Courthouse	19-C1	2	parking lot, caused by tree roots which need to be addressed during construction.	\$	18,285	\$	18,285	Unfunded	100
						Electrical - Replace 2500 amp breaker - Currently a 2500 amp breaker at the main						
			Edmund D.			panel is not resetting properly, this breaker controls the power to the penthouse on						
			Edelman			the roof where the chiller plant and boiler plants are located. If the breaker trips						
			Children's			there is high probability that it will not reset and the court will lose the cooling and			4			
99	FM-0053445	Los Angeles	Court	19-Q1		heating to the building.	Ş	39,293	Ş	27,501	Unfunded	69.99
						HVAC - Install two new 5 ton rooftop high efficiency gas electric package units: AC						
			Delano/North			Units PKU #8 and PKU #9 including new Seismic Vibration Isolation Roof Curbs. A 90						
100	FM-0052741	Korn		15-D1		ton crane will be used to remove the (2) package units from the roof and lift the new units into place. Two rooftop HVAC units (5 ton each) no longer provide sufficient	\$	19,010	ć	15,330	Unfunded	80.64
100	FIVI-0032741	KEIII	Kern Court	12-01			Ş	19,010	Ş	13,330	Unnunueu	00.04
						Roof - Perform roof rehabilitation to several areas of the roof, to areas that are in						
						failing condition. The Following work will be done. Main Deck- Roof Membrane, Roof						
						Blister & Roof Drains restored to a better state. Remediate leaks to roof						
			Glendale			penetrations, remove and replace material for roof blisters and renovate leaking drain and pitch pockets. Insert roof Membrane Blanket. Approx. 2,850 SQ/FT of						
101	FM-0053946	Los Angeles		19-H1		rehabilitation	ć	24,539	\$	22 218	Unfunded	90.54
101	1101-0055540	LOS Aligeles	Monrovia	19-111		Roof - Install guardian roof railing system including 30-ground plates, 15-10 feet	ې ا	24,335	ې ا	22,210	Uniunueu	30.34
			Training			safety rails, 11- 6 feet safety rails & painted safety striping to comply with Cal-OSHA						
102	FM-0054183	Los Angeles	•	19-N1		fall protection / Current roof is missing guard rails for fall protection	Ś	18,356	Ś	12.902	Unfunded	70.29
							T		T			
			Clara			Fire Protection - Failing Alarm Components - Remove and replace thirty - five (35)						
			Shortridge			pull stations that failed to activate during annual test and one (1) fire bell that						
			Foltz Criminal			sounded poorly. This work must be completed before the annual fire alarm test can						
103	FM-0053491	Los Angeles	Justice Center	19-L1		be completed. locations are uploaded in the Notes & Documents section of this SWO	\$	24,032	\$	16,532	Unfunded	68.79
			Shortridge			replace duel backflow preventers and isolation valves, restore water service to the						
			Foltz Criminal			building and restart buster pumps. The duel domestic water backflow preventers did						
104	FM-0053481	Los Angeles	Justice Center	19-L1		not pass annual inspection and the isolation valves are bypassing water when in the	\$	33,623	\$	23,129	Unfunded	68.79



FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
					Vandalism - Remove and replace existing window tint form all exterior windows						
		Pasadena			located on Walnut street and side elevation of building. Currently window tint is						
105 FM-0054326	Los Angeles	Courthouse	19-J1	2	damaged due to the age, weather, and the public scrapping off the original tinting.	\$	7,400	\$	5,132	Unfunded	69.35
					Elevators - Install over speed rupture valves to all 9 hydraulic elevators. The elevators						
					currently do not have these valves and run the risk of dropping with no safety						
		Central Justice			mechanism and consequently will not pass the 5 year inspection. The new over						
106 FM-0054340	Orange	Center	30-A1	2	speed rupture valve comply with ASME A17.1-2007 safety code.	\$	35,559	\$	32,419	Unfunded	91.17
					Elevators, Escalators, & Hoists - Elevator #3 Failing Generator - Dismantle generator,						
		Downey			remove, rebuild, and reassemble. Elevator #3, generator #2 failed and needs to be						
107 FM-0054180	Los Angeles	Courthouse	19-AM1	2	rebuilt.	\$	31,711	\$	26,542	Unfunded	83.7
					TOTAL:	<b>\$ 1,</b>	,064,581	\$	946,617		



TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

### Action Item 4 – (Action Required) - List C – Cost Increases Over \$50k

#### **Summary:**

List C – Cost Increases Over \$50k

Total Project Count:	1
Total Potential FM Budget Share of Cost:	\$257,716

#### **Supporting Documentation:**

• List C – Cost Increases Over \$50k

#### **Action Requested:**

Approve Judicial Council Staff recommendation to execute projects on List C – Cost Increases Over \$50k.

## Action Item 4 List C – Cost Increases Over \$50k

JCIL .

There was one cost increases in excess of \$50,000, with a total cost increase of \$257,716 to the FM Program Budget.

## Action Item 4 List C – Cost Increases Over \$50k

County	Building	Building ID	FM ID	Original Funded Cost	Current Cost Estimate	Amount of Increase
Lake	South Civic Center	17-B1	FM- 0049123	\$ 188,207	\$ 445,923	\$ 257,716

#### **Reason for Increase :**

This 41 year old roofing system is not to current code. Additional work required to address structural, drainage, mechanical curbs, and additional sq. ft. of roofing materials.


#### Notes:

FM Program Budget share is 100%, therefore cost increase to FM Program Budget is \$257,716.





	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	10DIFICA	PROGRAM BUDGET SHARE OF TCFMAC FUNDED COST	CURRENT COST ESITMATE	MODIFICA	PROGRAM BUDGET SHARE OF CURRENT COST ESTIMATE	NOTES	FACILITY MODIFICATION PROGRAM COST INCREASE	JOB STATUS
1	FM-0049123		South Civic Center	17-B1	2	Roof - Drains and downspouts (10 ea) - Replace roof (9700 SF),drains, down spouts, roof edge cap and roof hatch - Water penetration impacting court operations.	\$ 188,207	\$	188,207	\$ 445,923	\$		This 41 year old roofing system, except for periodic repair, is the same as originally constructed. The original approved scope of work was more in alignment with partial replacement than a complete overview of the roofing system but given the age, newly identified code and structural deficiencies we recommend implementing a project which will achieve a 25 year renovation as opposed to a 5 - 10 year solution. Code requirements are driving changes to the original installation. As time passed, in the facility portions of the original drainage system were sealed to prevent leaks from failed drain piping. This must be corrected and brought up to code. Some structural work is required due to age of the facility to address the failed drainage system that was not anticipated in the original, less comprehensive scope of work.	\$ 257,716	In Work
							\$ 188,207	\$	188,207	\$ 445,923	\$	445,923		\$ 257,716	



	E	FACILITY MODIFICATION
	PF	PROGRAM BUDGET % OF
100	CC	COST



TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

Meeting Date: 3/6/2015

### Action Item 5 – (Action Required) - List D – Facility Modifications Over \$50k

#### **Summary:**

List D – Facility Modifications Over \$50k

Total Project Count:	6
Total Potential FM Budget Share of Cost:	\$2,470,997

#### **Supporting Documentation:**

• List D – Facility Modifications Over \$50k

### **Action Requested:**

Approve Judicial Council Staff recommendation to execute projects on List D – Facility Modifications Over \$50k.

## Action Item 5 List D – Facility Modifications Over \$50k

Items 1-6 are recommended for funding Total estimated amount of FM Program budget share is \$2,470,997



JUDICIAL COUNCIL OF CALIFORNIA



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
			Wiley W. Manuel			HVAC - Replace six failed, corroded and severely leaking cooling coil condensate drain pans in air handlers one and two located in the rooftop								
1	FM-0054507	Alameda	Courthouse	01-B3		mechanical penthouses.	\$	123,669	\$	103,635	\$	103,635	47	83.8
2	2 FM-0054617	Kern	Bakersfield Superior Court	15-A1		Elevators, Escalators, & Hoists - Rebuild Elevator #1 & #2 Generator, Sheave Deflector and Bearing Replacement. Elevator #1 & #2 Generators failed having reached the end of their useful life and need to be dismantled and rebuilt. Deflector Sheaves having reached the end of their useful life and need to be replaced.	\$	257,000	\$	160,985	\$	264,620	45	62.64
	FM-0054043	Calara	Hall of Justice	48-A1	2	HVAC - Replace three (3) failing chilled water coils and three (3) failing heating hot water coils located in AHU S1.	ć	107,865	ć	78,547	ć	343,167	85	72.82
	FM-0053008		Compton Courthouse	19-AG1		Roof - Remove and replace the upper roof, main roof deck and stand alone restroom roofs (approximately 34,000 SF) with a 3 ply roofing system, roofing system is failing. Work includes new flashings, and reglet metal where needed.	\$	747,216	\$	494,134	\$	837,301	60	
5	FM-0052982	Los Angeles	Metropolitan Courthouse	19-T1		Roof - Remove and replace existing main deck, penthouse & stairwell deck roofs (27,000 SF) with new 3 ply roof systems. Roofing system is failing. Work includes new flashings and reglet metal where needed, metal etching and repainting of the deteriorating standing seam metal roof (2,535 SF) and cleaning and resetting roof drains and caps.	\$	634,160	\$	599,535	\$	1,436,836	50	94.54
e	5 FM-0052980	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1		Roof - Remove and replace existing roof (62,550 SF) with new PVC roof system at the Main Deck, Penthouse decks (4) and lower eyebrow deck. Roofing system condition reports recommends replacement to mitigate leaks and imminent failure in a large percentage of the overall roofing system. New roof drains required for change in roofing systems.	\$	1,503,360	\$	1,034,161	\$	2,470,997	65	68.79
7	7 FM-0053004	Los Angeles	Van Nuys Courthouse West	19-AX2	3	Roof - Remove and replace existing roof with new roof system - Due to roof currently being in poor condition at best, recommended removal and replacement of existing roof will bring building roof to good condition. Roof - Remove and replace existing roof with new roof system - Due to roof currently being in poor condition at best, recommended removal and	\$	554,400	\$	446,181	\$	2,917,178	80	80.48
8	FM-0053003	Los Angeles	Alhambra Courthouse	19-11		replacement of existing roof system will bring building roof to good condition.	\$	945,840	\$	813,422	\$	3,730,601	70	86



DRAFT

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
						Roof - Remove and replace existing roof with new PVC roof system - Due								
9	FM-0053006	l os Angeles	Bellflower Courthouse	19-AL1		to roof currently being in poor condition, recommended removal and replacement of existing roof will bring entire system to good condition.	Ś	646,800	s	504,116	Ś	4,234,717	60	77.94
		Los Angeles			5	Roof - Remove and replace existing roof with new PVC roof system at		040,000	<u> </u>	504,110	<u> </u>	7,237,717	00	77.54
						main deck (23,220 sq. ft.) & lower north deck (2,838 sq. ft.). Overlay								
						existing roof with new PVC roof system at lower south deck (2,838 sq. ft.).								
						/ Due to roofs currently being in poor to fair condition at best,								
			Pomona			recommended removal and replacement of main deck and lower north								
			Courthouse			deck and overlay of existing roof at south deck will bring all roof decks on								
10	FM-0053554	Los Angeles	South	19-W1	3	the building to good condition.	Ş	652,680	Ş	594,853	Ş	4,829,569	70	91.14
			Santa Monica			Roof - Remove and replace existing roof with new PVC roof system / Due to roof currently being in poor to fair condition at best, recommended								
11	FM-0054101	Los Angeles	Courthouse	19-AP1		removal and replacement of existing roof will bring it to good condition.	\$	1,128,960	\$	886,121	Ş	5,715,690	35	78.49
12	FM-0052988	Los Angeles	San Fernando Courthouse	19-AC1		deck, 2nd and 3rd floor Northeast decks / Due to these three sections of roof currently being in poor to fair condition, recommended removal and replacement of existing areas will bring entire roof system to good condition.	\$	561,120	\$	468,030	\$	6,183,720	35	83.41
						Roof - Remove and replace existing roof with new PVC roof system / Due								
			East Los Angeles			to roof currently being in poor to fair condition at best, recommended	4		4				<b>.</b> -	
13	FM-0052981	Los Angeles	Courthouse	19-V1		removal and replacement of existing roof will bring it to good condition.	Ş	596,400	Ş	463,522	Ş	6,647,242	85	77.72
						Roof - Remove and replace existing main deck, lower east deck and lower west deck - Due to main and lower decks currently being in poor condition								
			Downey			at best, recommended removal and replacement of existing systems will								
14	FM-0053549	Los Angeles	Courthouse	19-AM1		bring building roof to good condition.	Ś	806,400	\$	674,957	\$	7,322,199	80	83.7
						Roof - Remove and replace existing roof system at areas eleven different	† '	,		,		, ,		
						areas 20,000 amount of SF / Due to the poor condition of these areas,								
			Monrovia			recommended removal and replacement of existing systems will bring								
15	FM-0053002	Los Angeles	Training Center	19-N1		entire building roof to good condition.	\$	278,040	\$	195,434	\$	7,517,633	70	70.29
						Roof - Overlay existing roof with new PVC roof system - Due to roof								
			Airport	10 4114		currently being in poor to fair condition, recommended overlay of existing		252.000			~		70	
16	FM-0053398	Los Angeles	Courthouse	19-AU1	3	roof will bring it to good condition. 25,500 square feet.	Ş	352,800	Ş	272,256	\$	7,789,889	70	77.17



DRAFT

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
	FM-0053394		Torrance Courthouse Glendale	19-C1	3	Roof - Overlay existing main deck and lower deck sections with new PVC roof system / Due to roof decks currently being in poor to fair condition, remaining service life is less than 5 years. The recommended overlay of existing decks will bring building to good condition. 40,000 square feet. Roof - Overlay 38,000 sq. ft. of existing roof system with new PVC membrane overlay / Due to roof decks currently being in poor to fair condition, remaining service life is less than 5 years. The recommended overlay of all existing roofs will bring the building to good condition. The multi-level, multi-sectioned roof area totals approximately 34,000 square foot	\$	554,400	\$	472,016	\$	8,261,905		
		Los Angeles Los Angeles	Courthouse Chatsworth Courthouse	19-H1 19-AY1		feet. Roof - Overlay existing main roof and penthouse roof sections with new PVC roof system / Due to roof sections currently being in poor to fair condition, remaining service life is than 5 years. The recommended overlay of existing roofs will bring building to good condition.	> \$	453,600 984,480	\$ \$	410,689 889,379	\$ \$	8,672,595 9,561,974		
20	FM-0053460	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	3	Roof - Overlay existing roof with new PVC roof system / Due to roof currently being in poor to fair condition, recommended overlay of existing roof will bring it to good condition. The Square Footage for this roof overlay is approx. 43,000	\$	577,920	\$	404,486	\$	9,966,460	55	69.99
21	FM-0052979	Los Angeles	Burbank Courthouse	19-G1		Roof - Overlay existing gravel roof section with new PVC roof system. Remove & replace existing shingled roof section with new shingled roof system / Due to roof currently being in poor to fair condition, recommended overlay of existing gravel roof and replacement of existing shingle roof will bring entire roof of building to good condition.	\$	369,600	\$	335,449	\$	10,301,909	55	90.76
22	FM-0052970	Los Angeles	Whittier Courthouse	19-AO1		Roof / Remove and replace existing one story section of roof with new and overlay 5 story section of roof with torch applied system / Due to both sections of roof currently being in poor to fair condition, recommended overlay of 5 story section and replacement of 1 story section of existing roof will bring entire roof system to good condition.	\$	458,640	) \$	396,403	\$	10,698,312	42	86.43



FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
23 FM-0053561	Los Angeles	Metropolitan Courthouse	19-T1	3	Electrical - Replace a total of 98 exterior Mercury Vapor, High Pressure Sodium, and Fluorescent Light fixtures with high efficient LED fixtures. Building exterior lighting fixtures/poles have broken lenses, sockets, bulbs making the area dark at night, safety issue. Parts are no longer available due to fixtures being outdated.	\$ 166,259	\$	157,181	\$ 10,855,493	35	94.54
24 FM-0054462	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	3	Elevator - Elevator Renovation - Complete renovation of fourteen (14) geared traction elevators. Work will include but not be limited to, car frames and platforms, buffers and safeties, hoistway entrance frames, doors and pit equipment, new AC gearless machines, micro-processor control systems, regenerative VVVF AC drives, fly ball governors, current code required wiring, interior and lobby control panels, car and hall door panels with new doors, counterweights and (see additional description)	\$ 4,594,739	\$	3,215,858	\$ 14,071,351	90	69.99
25 FM-0053022	Riverside	Larson Justice Center	33-C1	3	Grounds and Parking Lot - East Parking Lot - Create and install 80 parking stalls out of perimeter landscape around the current lot. The recent closure of the County lot behind the courthouse, closure of the Court Annex/County building next door and its parking lot, and the building of a County Law building next door have created a serious parking issue in the immediate area of the Larson Justice Center resulting in a 200+ parking stall loss. Customers are currently parking on the landscape.	\$ 470,000	) \$	379,807	\$ 14,451,158	70	80.81
26 FM-0054137	Tulare	Visalia Superior Court	54-A1	3	Furniture and Equipment - Security - Reconfigure Judge's bench in Dept 11 to provide greater security for judge and the two court clerks. Extend bench by building new walls to fill in open areas to judge and clerk with new laminate countertop and additional power to accommodate both clerks, moving one clerk from floor desk. Remove steps at open area to judge's seat and replace with new deck. Install new floor covering at steps and behind bench, new bookcase, set of cubbies, and paper tray bet	\$24,670.44	ı Ş	24,670	\$ 14,475,828	55	100



## TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
	EN4 0051 400		Butte County	04.44		Energy Efficiency Project - Lighting Upgrade - Retrofit all 52 exterior light fixtures with high efficiency lighting components. 14 parking lot pole light fixtures will receive induction style bulbs and ballasts. 38 wall mounted exterior fixtures will receive LED systems. The completed project will return \$1,870 in energy rebates and reduce electrical consumption by an estimated 18,230 kilowatt hours annually.		27 500	ć	27 500	ć 14 502 220		100
	FM-0051490 FM-0050722		Courthouse Airport Courthouse	04-A1 19-AU1		Interior Finish - Grind chipped and irregular floor and apply elastomeric filler to recessed areas to bring floor to flush condition (Approximately 80 SF)Work is needed to prevent possible tripping hazard and maintain clean floor surface.	\$ \$	27,500		27,500 21,251	\$ 14,503,328 \$ 14,524,579		
			Alhambra Courthouse	19-11		Plumbing - Remove and replace 7 recessed wall drinking fountains and 1 surface mount ADA drinking fountain. Eight drinking fountains in the public areas of the courthouse are deteriorated and are not operational.	\$	30,915		26,587	\$ 14,551,166		
			Butte County			Holding Area - The single in-custody holding cell located in the older section of the courthouse is substandard for current criminal cases. The project goal is to accommodate larger number of simultaneous in-custody classifications and increase overall holding capacity. This project addresses							
	FM-0052382 FM-0047407	Butte Alameda	Courthouse George E. McDonald Hall of Justice	04-A1 01-F1		the deficiency by remodeling to add 3 holding cells. HVAC - Hot water reheat coils leaking causing extensive water damage - remove and replace reheat coils- scaffolding required for removal and installation	\$ \$	280,000 14,266	\$	280,000	\$ 14,831,166 \$ 14,845,432		
32	FM-0054053	Santa Barbara	Santa Barbara Jury Assembly Bldg.	42-G1	3	Interior Finishes - Construct 3 Attorney/Client Mtg Rms - Required to Facilitate Move of Juvenile Proceedings to this location	\$	67,154	\$	67,154	\$ 14,912,586	45	100
33	FM-0052331		Kearny Mesa Traffic Court Santa Maria Courts Building	37-C1	3	Grounds and Parking Lot - Slurry coat, re-stripe the parking lot and paint the curbs as required. The striping is fading to where directional arrows and lane markings are, making it difficult for people to see. Roof Access - Replace Roof Access Window with Door/Landing/Hand	\$	18,189	\$	18,189	\$ 14,930,775	60	100
34	FM-0052763	Santa Barbara	•	42-F5		railing - Safety Hazard	\$	27,017	\$	26,069	\$ 14,956,844	60	96.49

DRAFT



DRAFT

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
			George D.			Energy Efficiency Project - Electrical - Install new lighting control system;							
			Carroll			Install 66 new occupancy sensors; Retrofit 36 four lamp light fixtures to 2							
35	FM-0051519	Contra Costa	Courthouse	07-F1	3	lamp fixtures; Engineering and design - Energy savings \$14,000.00 per year	\$	215,794	\$	161,824	\$ 15,118,668	70	74.99
						Energy Efficiency Retrofit Project - Install occupancy sensors for lighting							
36	FM-0050684	Santa Clara	Old Courthouse	43-B2	3	control in core restrooms on floors 1-3 - EEM 5	\$	16,208	\$	16,208	\$ 15,134,876	65	100
						County Managed - Grounds and Parking Lot - Patch and repair, slurry seal							
2-				24 52		and re-strip parking lot - deteriorated beyond useful and acceptable	~	27 202	~	27 202	¢ 45 462 470		100
3/	' FM-0049698	Placer	Juvenile Hall	31-B3	3	condition	\$	27,303	Ş	27,303	\$ 15,162,179	65	100
						Elevator (Wheelchair lift) - Units 1 - 3, Replace defective parts, make adjustments, service and return to safe operation. Currently units operate							
			West Covina			with the door open which is unsafe to the public. This work is also needed							
20	FM-0051535	Los Angeles	Courthouse	19-X1		to comply with ADA access requirements.	¢	22,670	¢	18,818	\$ 15,180,997	68	83.01
- 50		LUS Angeles		19-71		Energy Efficiency Retrofit Project - Chilled water system temperature	ې ا	22,070	<u>ې</u>	10,010	\$ 13,180,337	00	05.01
						system - reset - system not running at full efficiency - HVAC duct static							
						pressure set points - Reset - System not running at optimum efficiency							
						Occupancy sensors - Install - lights are on even when spaces are							
			Fremont Hall of			unoccupied - Courtroom - lighting - Retrofit - lights are high reach and							
39	FM-0050597	Alameda	Justice	01-H1	3	utilize energy inefficiently	\$	106,724	\$	84,739	\$ 15,265,736	69	79.40
						EARTHQUAKE - Repair cracks and aesthetic damage created by		,		,	. , ,		
						earthquake throughout building in secured hallways, courtrooms 101-104,							
						and jury courtyard scaffolding is required. Epoxy injection at concrete							
			Solano Justice			wall, 35 lin ft. and approx 650 sq ft of drywall and stucco repairs. Paint and							
40	FM-0053551	Solano	Building	48-B1	3	patch cracks to match existing.	\$	19,476	\$	19,476	\$ 15,285,212	69	100
			Morgan Hill			Energy Efficiency Project - Retrofit Exterior Parking Lot Lighting from250w							
41	. FM-0050766	Santa Clara	Courthouse	43-N1	3	Metal Halide to 150w LED lamps	\$	61,539	\$	61,539	\$ 15,346,751	95	100
						Exterior Shell - Remove, replace, or restore approximately 80 If of 2 1/2" x 11" bottom ledger, 48 If of 2" x 6" fascia and trim, and 96 If of 1" x 12" fascia; remove small section of existing white gutter and install 25 If gutter and 1 down spout to match as close to exterior brown color; caulk and patch trim areas as required to receive paint; paint all exterior brown color only - Existing wood fascia and trim is cracking, splitting, and							
42	FM-0052829	Kings	Avenal Court	16-C1	3	deteriorating due to fungus and weather damage.	\$	12,461	\$	7,228	\$ 15,353,979	70	58.01



DRAFT

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	NT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
		San Luis	Courthouse		Interior Finishes - Replace existing warn and defective seating with new auditorium style fixed seating - 16 standard seats and 2 ADA seats. Work is							
43	FM-0051527	Obispo	Annex	40-A1	3 needed to maintain acceptable courtroom seating.	\$	22,230	\$	22,230	\$ 15,376,209	70	100
44	FM-0049235	Santa Clara	Hall of Justice (East)	43-A1	Plumbing - Floor drains (8 ea) - Roof mechanical room - Remove existing roof mechanical room drains - Install new drains and reseal flooring - 3 Drains are plugged and not draining creating potential flooding	\$	24,070	\$	24,070	\$ 15,400,279	70	100
45	FM-0034097	San Bernardino	Barstow Courthouse	36-J1	Parking Lot - Saw cut and demo approximately 28,000 SF, 4 inch depth, of asphalt at lower level employee parking lot that is JCC managed and resurface with approximately 28,000 SF, 4 inch thick asphalt w/ 6 inch base, install 59 parking bumpers and re-stripe. Slurry seal new asphalt. Currently the asphalt in the parking lot has numerous cracks, pot holes, 3 and uneven areas that pose a tripping hazard.	\$	230,000	\$	230,000	\$ 15,630,279	60	100
			Civic Center		Exterior Walls - Prepare and apply anti-graffiti coating to all exterior walls from grade to 10ft high (approx. 6700sqft) - janitorial efforts are having	, ,		Ţ				
	FM-0052775 FM-0036208	San Francisco Santa Cruz	Courthouse Main Courthouse	38-A1 44-A1	<ul> <li>3 minimal results, time consuming and causing public hazard at sidewalks</li> <li>HVAC - Install HVAC system for lobby and circulation areas - The area does not receive HVAC and becomes very hot in summer and very cold in winter, HVAC is required for comfort of the public awaiting access to court</li> <li>3 rooms</li> </ul>		60,318 246,526		60,318 244,332	\$ 15,690,597 \$ 15,934,929		
		San Joaquin	Manteca Courthouse	39-C1	Energy Efficiency- HVAC; Replace 15 year old 3-ton package unit with	ې د	9,564	ې د	9,564	\$ 15,944,493		
	FM-0052978		Parking Structure Lot 59- Whittier Admin CTR		<ul> <li>3 energy efficient model.</li> <li>Grounds and Parking Lot - To provide and install new safety enclosures throughout the garages existing openings. Such opening as: the side facing walls, the decorative open spaces, the areas between each support columns and each opening for the first 2 floors. This project will also include the installation of a new rolling safety gate (with card reader), electrical installation to the panel and low voltage (for new gate motor)</li> <li>3 and approx. 550 LF of new welded iron fencing and mesh.</li> </ul>	\$	9,304	\$	9,504	\$ 16,073,179		
50	FM-0050686	Santa Clara	Santa Clara Courthouse	43-G1	Energy Efficiency Retrofit Project -Install VFD on cooling tower fan and 3 implement CWT reset - EEM 4	\$	32,760	\$	32,760	\$ 16,105,939	75	100



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
			Wiley W. Manuel										
51	FM-0051373	Alameda	Courthouse	01-B3	З	Energy Efficiency project - HVAC - Install VFD's - install (2) VFD for EF 1&2,	Ś	170,903	Ś	143,217	\$ 16,249,156	120	83.8
91	110 0031373	/ latitedu		01 03	5	Interior Finishes - Earthquake Restoration of cracks and aesthetic damages	Ŷ	170,000	Ŷ	143,217	Ŷ 10,243,130	120	05.0
52	FM-0053444	Contra Costa	Bray Courts	07-A3	3	to approx 7100 sq ft of the interior building	\$	38,792	\$	33,175	\$ 16,282,331	75	85.52
			,					,			. , ,		
			Downtown			Energy Efficiency Project - Redesign and program BAS system and install							
53	FM-0051115	Santa Clara	Superior Court	43-B1	3	necessary hardware to implement Variable Flow Chilled Water Pumping	\$	57 <i>,</i> 070	\$	57,070	\$ 16,339,401	70	100
						Plumbing - Remove and replace 8 high-low recessed drinking fountains							
			Chatsworth			and 3 ADA wall hung drinking fountains. Drinking fountains in the public							
54	FM-0052950	Los Angeles	Courthouse	19-AY1	3	areas of the courthouse are not operational.	\$	58,201	\$	52,579	\$ 16,391,979	55	90.34
						Elevators, Escalators, & Hoists - Judge's Elevator #5 Modernization.							
			Torrance			Judge's Elevator #5 runs too slow and keeps getting stuck, replacement							
55	FM-0054555	Los Angeles	Courthouse	19-C1		parts are no longer available.	\$	335,315	\$	285,487	\$ 16,677,466	80	85.14
						Exterior - Safety-Security - Members of the public are exposed to the							
						elements while standing in long lines prior to entering the facility through							
						weapons screening. This project will provide an awning to reduce							
						exposure. The lines are very long which causes discomfort for the public							
			Betty Lou			during inclement and hot weather. The court architect developed a							
			Lamoreaux		_	proposal consisting of free standing steel tube columns, metal bracing-							
56	FM-0044066	Orange	Justice Center	30-B1	3	ribbing, and a canvas barrel-shaped cover.	Ş	60,657	Ş	48,495	\$ 16,725,962	95	79.95
						Energy Efficiency Project - Electrical Lighting - Change Light bulbs, install							
	-		County	22.44	2	photocell and sensors - Swap 234 T12 Bulb and ballast to T8 install 3	~	64.625	4	40 700		100	
57	FM-0051344	Mendocino	Courthouse	23-A1	3	occupancy sensors, install 3 photo cells	Ş	64,635	Ş	43,706	\$ 16,769,668	100	67.62
<b>F</b> 0					ſ	HVAC - BAS, Installation for integration with BAS at New Merced - Needed	4		4		ć 10 040 3F7	105	100
58	FM-0025086	Merced	Old Court	24-A1	3	for proper system operation	Ş	79,589	Ş	79,589	\$ 16,849,257	105	100
БО		Orango	Central Justice	20 41	C	HVAC - Replace Air Handling units for improved control-efficiency - The air	4	1 002 004	4	1 902 004	¢ 19 653 351	105	100
59	FM-0040539	Orange	Center New Amador	30-A1	5	handlers are beyond their replacement life cycle	Ş	1,803,094	Ş	1,803,094	\$ 18,652,351	105	100
			County			Electrical - LED Lighting - Convert 14 parking lot and 34 building exterior							
60	FM-0043866	Amador	Courthouse	03-C1		and public walkway lamps to energy saving LED fixtures - Energy Savings	¢	71,476	¢	71,476	\$ 18,723,827	110	100
	101 00+3000				5	Grounds - Parking lot renovation - Lot in poor condition, project includes	<u>ب</u>	, 1,470	<u>ب</u>	/ 1,4/0	Υ 10,723,027	110	100
			Butte County			slurry seal parking lot, (166,000 square feet) to include curb prep, and							
61	FM-0025793	Butte	Courthouse	04-A1	ຊ	restriping parking lot to include handicap parking area	Ś	105,164	Ś	105,164	\$ 18,828,991	110	100
		54110		S . /\1			Ŷ	100,104	Ŷ	100,104	÷ 10,020,001	110	100



DRAFT

FM NUMBER	LOCATION	FACILITY NAME	Building ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
		Family Law			Exterior Windows - Weather protection gasket deteriorated - Needed for							
62 FM-0000163	Riverside	Court	33-A1	_	energy efficiency, prevention of water damage	\$	114,552	\$	114,552	\$ 18,943,543	3 110	0 100
63 FM-0051473	Alameda	George E. McDonald Hall of Justice	01-F1	3	Energy Efficiency Project - HVAC - Restore Economizer Dampers and Actuators, install VFD (4) - Restore Damper and Actuators (5), install 2 VFD to Supply and Return Fan on unit #1, install 2 VFD to Primary Chilled Water Pumps COUNTY MANAGED - Interior Finishes - Replace All Interior Door Hardware Failing - Low Quality/Failing - County Managed Recommended	\$	83,847	\$	83,847	\$ 19,027,390	) 12(	0 100
		Juvenile			by County/MP - Bldg was built in 2005. Per County, "Hardware is of low							
64 FM-0052844	Ventura		56-F1		quality, failing and is no longer being made.	\$	70,934	\$	70,934	\$ 19,098,324	80	100
		East County		-	ENERGY EFFICENCY - COUNTY MANAGED - Electrical - Interior Lighting							
65 FM-0052843	Ventura	Courthouse	56-B1	3	Retrofit	\$	125,502	\$	125,502	\$ 19,223,826	5 8!	5 100
66 FM-0051791	Sacramento	•	34-A1		Plumbing - To abate and remove two (2) abandoned boilers and associated plumbing and equipment - Boilers have been decommissioned and abandoned in place and are occupying valuable space.	\$	97,000	\$	97,000	\$ 19,320,826	5 9(	0 100
		Stanley Mosk	10 1/1	2	Cleans all LIV/AC durat would through out fooility	~	100 177	4	100 177	ć 10 427 002		100
67 FM-0001928   68 FM-0053476 5		Manteca Branch	19-К1 39-С1		Clean all HVAC duct work through out facility Energy Efficiency - Lighting - Replace a total of 305 light fixtures throughout the facility. Remove: (19) T12 light fixtures, (73) Compact Fluorescents, (201) T8 Light Fixtures, (2) Incandescent Light Fixtures and (10) Metal Halide Light Fixtures. All fixture will be replaced with LED fixture	\$ \$	106,177 66,972		106,177 66,972	\$ 19,427,003 \$ 19,493,975		
69 FM-0050449 I	Los Angeles	Compton Courthouse	19-AG1		Interior finishes - Holding Cell Walls - Renovate the damaged/Peeling paint throughout (Approximately 2,663 sf of walls). Proposed work to be done in three (3) phases with a Petra coating system, which is a long term solution rather than another coat of standard commercial paint. The paint in the holding cells has been etched and is peeling from the walls. Walls were identified in an Environmental Health Evaluation.		89,689	\$	89,689	\$ 19,583,664	- 9(	0 100
70 FM-0022145	Santa Clara	Santa Clara Courthouse	43-G1		Elevator - Refurbish elevator and controls and install Vista Monitoring System to enhance reportability - This is the only elevator in the building	\$	122,615	\$	21,519	\$ 19,605,183	8 10	6 17.55



	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
71	FM-0052830	Ventura	Hall of Justice	56-A1	2	COUNTY MANAGED - Electrical - 4160 Volt Breaker Upgrade. Replace 36yr old Breakers to improve reliability of e-system	¢	88,249	4	88,249	\$ 19,693,432	110	100
		Madera	Sierra	20-D1		Security - Install fencing for sheriff and staff secured parking - reduce potential custody escapes or attacks - provide safety for court staff and patrons	\$	162,397	\$	110,430	\$ 19,803,862		
73	FM-0052781	Solano	Hall of Justice	48-A1	3	Security - Interior Finishes - Secure transaction counter - Install approximately 100 lineal feet of barrier wall and public transaction counter with twelve (12) 4 wide forced entry resistant laminated glass transaction windows, to ensure the safety of the family law clerks. There have been numerous security incidents involving disgruntled public customers including punching, spitting and verbal altercations.	\$	252,078	\$	252,078	\$ 20,055,940	50	100
74	FM-0052782	Merced	New Downtown Merced Courthouse	24-A8	3	Security - Expand the vestibule and add a covered staging area - Remove the existing store front and provide a separate storefront in the new location, level the existing alcove concrete to expand the new interior security vestibule, construct a new 1,800 SF covered walkway and staging area, this will require a single 400 SF tilt concrete panel, sixteen (16) column footings, two (2) new 3'6" power activated storefront doors, transparent roof panels at the covered walkway and staging areas, two new cameras at the staging area and approximately 800 SF of flooring and t-bar ceiling at the lobby and vestibule. This work is required to alleviate security issues at the main entry due to inadequate circulation.	\$	683,000	\$	683,000	\$ 20,738,940	70	100
75	5 FM-0051097	San Diego	East County Regional Center	37-11	3	Security - Surveillance Camera Installation - Install twenty-five (25) tamper resistant dome cameras and two (2) 4.0 tear byte 16 channel DVR with two (2) fused power supplies. Work includes installing BNC connectors, 2C/18 AWG plenum rated cable and RG-6 plenum rated cable. Currently, only a few cameras provide coverage of attorney/prisoner visit area and access gate. Holding cells lack sufficient security camera coverage.	\$	68,200	\$	68,200	\$ 20,807,140	80	100



DRAFT

FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	F	MUDIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
					Security - Surveillance Camera Installation - Install forty-two (42) tamper resistant dome cameras in Departments 1 through 19, three (3) 4.0 tear byte Multiplexer's, three (3) 16 channel fused power supplies. Work							
		North County Regional Center			includes installing BNC connectors, 2C/18 AWG plenum rated cable and RG-6 plenum rated cable. Currently nineteen (19) courtrooms and							
76 FM-005110	2 San Diego	Vista Center	37-F2	3	Custody break room are not equipped with cameras	\$	111,825	\$	111,825	\$ 20,918,965	80	100
77 FM-002837	2 Solano	Hall of Justice	48-A1	3	Fencing - 30K sf, Install secured fencing with card reader access for judges parking lot for security from the public - Contingency Only	\$	142,200	\$	142,200	\$ 21,061,165	120	100
78 FM-003442	Kern	Arvin/ Lamont Branch	15-H1		Security - Repair-modify exterior grounds-parking to accommodate judicial officer safety - Branch suffers from lack of secured parking and access to building	ć	121 220	Ś	79,926	\$ 21,141,091	55	60.91
70[710]-0034420			12-01	3		ې ا	131,220	Ş	19,920	ş 21,141,091	55	00.91
		Shafter/Wasco			Security - Enhance parking by adding Judges Secure Parking and Access to		72.000	¢.	70.000	6 24 24 4 25 7	05	400
79 FM-005034	8 Kern	Courts Bldg.	15-E1	3	the Courthouse - Branch suffers from lack of secure parking.	Ş	73,866	Ş	73,866	\$ 21,214,957	95	100



TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

Meeting Date: 3/6/2015

### Action Item 6 – (Action Required) - List F – Court-Funded Facilities Requests (Facility Modifications)

#### **Summary:**

Review Court-Funded Facilities Requests (Facility Modifications) from List F.

#### **Supporting Documentation:**

• List F – Court-Funded Facilities Requests (Facility Modifications)

#### **Action Requested:**

Staff recommends two Court-Funded Facilities Requests for review and approval.

Action Item 6 List F – Court-Funded Facilities Requests (CFRs) Facility Modifications

San Francisco – Hall of Justice
 Jury Seating Reconfiguration \$179k
 Los Angeles – Multiple Facilities
 Electronic Calendar Installations - \$529k



JUDICIAL COUNCIL OF CALIFORNIA Action Item 6 List F – Court-Funded Facilities Requests (CFRs) Facility Modifications

Placer – 4075 Cincinnati Ave 3-year Storage Lease Extension - \$254k Stanislaus – 1130 12<sup>th</sup> St. • 1-year Bankruptcy Lease Extension - \$141k Tulare – City Council Chambers 3-year Traffic Lease Extension - \$10.5k





ITEM #	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	REQUEST TYPE	CFR DESCRIPTION	CFR TERM	FUND SOURCE	ESTIMATED CURRENT YEAR	COSTS FY 14-15 (Includes existing costs prior to CFR term)	ESTIMATED BUDGET YEAR COSTS	ESTIMATED TOTAL CFR COMMITMENT (CFR Term)	REVIEW NOTES - Real Estate and Facilities Management, Capital Program, and Finance
							Reconfigure and expand the Jury Assembly Room to accommodate the growing number of double jury panels. The							
							room has not been updated since the 1980s. The large crowds							
		San					in close quarters have become a security and staff safety							
1 3	8-CFR004	Francisco	38-B1	Hall of Justice	FM	One Time	issue, therefore this request is deemed urgent.	NA	TCTF	\$	179,117 \$	179,117 9	\$ 179,117	Pending
							Install digital sign boards to communicate up-to-the-minute							
							information to the public. This project allows cost savings by							
							eliminating recurring costs associated with printing,							
							installation and disposal of currently used notification means.							
							Work includes electrical, abatement and containment. 24							
2 1	9-CFR025	Los Angeles	Multiple	Multiple		One Time	buildings.	NA	TCTF	\$	548,968 \$	548,968	\$ 548,968	Pending
					Lease									
				4075 Cincinnati	Extensi		Extend lease for three more years (8/1/2015-7/31/2018) to							
4 3	1-CFR003	Placer	31-K1	Avenue	on	Ongoing	continue storage of archived records.	Three Years	TCTF	Ş	-00 \$	82,465	\$ 253,632	No Concerns
							Extend Bankruptcy Court lease and utilities for one year. The							
					Lease Extensi		building will be used to try multi-defendant high risk cases in Stanislaus County. These cases cannot be safely tried in the							
5 5		Stanislaus	50-11	1130 12th Street		One-Time	current Downtown courthouse.	One Year	TCTF	¢	-00 \$	141,044	\$ 141 044	No Concerns
			50 11				Continue use of space for Traffic Court at the Visalia City Hall					141,044	, 1+1,0++	
					Lease		on a weekly basis on Thursdays. The Court has been using this							
				City Council	Extensi		space for awhile, free of charge, but now the City wants to							
6 5	4-CFR008	Tulare	54-TBD	, Chambers	on	Ongoing	charge for continued use at \$100/per use.	Two Years	TCTF	\$	1,700 \$	5,200	\$ 10,500	No Concerns
										\$	729,785 \$	956,794	\$ 1,133,261	





TRIAL COURT FACILITY MODIFICATION Advisory committee

Meeting Date: 3/6/2015

### Action Item 7 – (Action Required) – *Trial Court Facility Modification Quarterly Activity Report, Quarter 2 of Fiscal Year 2014-2015*

#### **Summary:**

Review draft report *Trial Court Facility Modification Quarterly Activity Report, Quarter 2 of Fiscal Year 2014-2015.* 

#### **Supporting Documentation:**

• Trial Court Facility Modification Quarterly Activity Report, Quarter 2 of Fiscal Year 2014-2015

#### **Action Requested:**

Staff is requesting committee input and approval to move to Judicial Council.

# Action Item 7 TCFMAC Q2 Report

Comment and Input
Recommendation:

Approve for release to E&P based on adjustments from committee input



зCІ

JUDICIAL COUNCIL OF CALIFORNIA



#### Judicial Council of California

455 Golden Gate Avenue · San Francisco, California 94102-3688

www.courts.ca.gov

### REPORT TO THE JUDICIAL COUNCIL

For business meeting on April 16-17, 2015

Submitted by Trial Court Facility Modification Advisory Committee Hon. David Edwin Power, Chair Agenda Item Type Information Only

Date of Report March 4, 2015

Contact Patrick McGrath, 916-643-8051 patrick.mcgrath@jud.ca.gov

#### **Executive Summary**

The Trial Court Facility Modification Advisory Committee has completed its facility modification funding for the second quarter of fiscal year 2014–2015. In compliance with the *Trial Court Facility Modifications Policy*, adopted by the Judicial Council on July 27, 2012, the advisory body is submitting its *Trial Court Facility Modification Quarterly Activity Report: Quarter 2, Fiscal Year 2014–2015* as information for the council. This report summarizes the activities of the Trial Court Facility Modification Advisory Committee from October 1, 2014 to December 31, 2014.

#### **Previous Council Action**

The Trial Court Facility Modification Working Group was established by Judicial Council policy in 2005. The working group first met in April 2006 and operated under the *Trial Court Facility Modifications Policy*,<sup>1</sup> adopted by the Judicial Council in 2005 and revised on December 12, 2014. The working group's primary oversight responsibilities included reviewing statewide facility modification requests and approving facility modification funding.

<sup>&</sup>lt;sup>1</sup> As adopted in 2005, the policy was known as the *Prioritization Methodology for Modifications to Court Facilities*. When it was revised in 2012, the name also changed. See <u>www.courts.ca.gov/documents/jc-20120727-itemG.pdf</u>.

The working group's charge was formalized by the Judicial Council on December 14, 2012, and the working group was assigned additional oversight responsibility for the operations and maintenance of existing facilities, noncapital-related real estate transactions, energy management, and environmental management and sustainability. On April 25, 2013, the working group's status was elevated to that of advisory committee.

An updated Court-Funded Facilities Request approval process was submitted and approved by the Judicial Council on August 23, 2013, requiring all Court-Funded Facilities Requests to be reviewed and approved by the Trial Court Facility Modification Advisory Committee (TCFMAC). These submittals may include lease-related costs (e.g., lease payments and operating costs, repairs, or modifications required by a lease); allowable court operations expenditures under rule 10.810 of the California Rules of Court (e.g., equipment, furnishings, interior painting, flooring replacement or repair, furniture repair, or records storage); and other facility improvements that are not allowable court operations expenditures under rule 10.810 (e.g., facilities operations, maintenance, repairs, and modifications, but not capital projects), if they would improve a court's functioning or reduce ongoing court operating costs.

Reports previously approved by the Judicial Council are available at <u>www.courts.ca.gov/2567.htm</u> under Research and Reports: Conditions in Our Courts.

#### **Methodology and Process**

Funding decisions were based on the prioritization and ranking methodologies in accordance with the *Trial Court Facility Modifications Policy*. Facility modifications are assigned one of six priority categories: Priority 1–Immediate or Potentially Critical; Priority 2–Necessary, But Not Yet Critical; Priority 3–Needed; Priority 4–Does Not Meet Current Codes or Standards; Priority 5–Beyond Rated Life, But Serviceable; and Priority 6–Hazardous Materials, Managed But Not Abated. These categories are based on methods commonly used by private-sector facility management firms. Facility modifications that are determined to be Priority 1 are to be addressed immediately and regardless of whether the court occupies a shared-use facility. With current budget constraints, the TCFMAC primarily limits approvals of facility modification projects to Priority 1 and Priority 2 projects. Delaying TCFMAC approval of these projects would cause continued court closures, operational failures, and undue risk to continued court operations.

#### **Policy and Cost Implications**

During the second quarter of fiscal year 2014–2015, the TCFMAC reviewed and approved a total of 386 facility modifications for a total projected cost of \$27,066,997. The Facility Modification Program's share of these projects totals \$23,396,856. These approved projects are limited to Priority 1 emergency projects and Priority 2 critical needs projects. Please see Attachment A for a detailed list of all approved projects.

During this quarter, eight projects required additional funds in excess of \$50,000 over their original estimates. The Facility Modification Program's share of these cost increases totals

\$1,128,963. Projects that require excess costs of this magnitude are typically Priority 1 emergency projects that do not have a full scope and cost estimate developed at the onset of the project and for which significantly more work or testing is discovered after commencement.

During this quarter, three Court-Funded Facilities Requests (CFRs) were reviewed and approved by the TCFMAC, including requests from Glenn, Los Angeles, and San Joaquin courts. As stated above, CFR submittals may include lease-related costs, allowable court operations expenditures under rule 10.810 of the California Rules of Court, and other facility improvement costs that are not allowable under rule 10.810. See Attachment B for a detailed list of CFRs approved by the TCFMAC during the second quarter of fiscal year 2014–2015.

#### **Implementation Efforts**

The TCFMAC conducted an in person meeting on November 3, 2014, at the Sacramento office, and a teleconference on December 15, 2014, to review facility modification funding requests and to discuss the following topics:

- Regular review of facility modification projects lists: A (Emergency and Priority 1), B (FMs Less than \$50K), C (Cost Increases Over \$50K), D (FMs Greater than \$50K Eligible for Funding), and F (Court-Funded Facilities Requests).
- Discussion and review of facility modification requests for Priority 3 projects received from Courts.
- Status updates on the Department of Finance denial response to the FY 15-16 Budget Change Proposals.
- Informational presentation from Judicial Council staff to review expenditures from FY 13-14 relative to the operational budget.
- Reviewed and approved a utility cost outreach letter that was sent to all presiding judges.
- Informational presentation from Judicial Council staff to review the process involved in obtaining a solar power purchase agreement.
- Discussion and review of the Department of Finance deferred maintenance report.
- Informational presentation from Judicial Council staff to review current staffing status and constraints.
- Discussed comments received from Merced, Nevada, Placer, Santa Barbara, Solano, and Tulare Superior Courts.
- Discussion and review of the proposed California Rule of Court 10.65 (Trial Court Facility Modification Advisory Committee).
- Discussion and review of the Annual Report of the Trial Court Facility Modification Advisory Committee for Fiscal Year 2013-2014.
- Judge David Edwin Power visited the Napa County Historic Courthouse and Napa County Criminal Courthouse to examine the earthquake damage and the ongoing repairs at both facilities.
- Ms. Christina Volkers, court executive officer of the San Bernardino Superior Court, conducted a site visit at both the Placer Superior Court Auburn jail arraignment courtroom and the shelled facility at the new Placer jail.

#### **Next Steps**

The *Trial Court Facility Modification Quarterly Activity Report, Quarter 3 of Fiscal Year 2014–2015* will be submitted to the Judicial Council in June 2015.

#### Attachments

- 1. Attachment A: TCFMAC Funded Project List: Quarter 2, Fiscal Year 2014–2015
- 2. Attachment B: Court-Funded Facilities Requests (CFRs): Quarter 2, Fiscal Year 2014–2015



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	ATION	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Exterior Grounds - Flood prevention - Storm Drains (20) - Restore the storm drains to the original engineered design capacity, remove mud, vegetation and debris within the basins and					
			Fremont Hall of			pipes, pressure flush drain pipes and install carbon filters - Storm water drains are clogged and					
1	FM-0023333	Alameda	Justice	01-H1		prone to flooding.	\$	26,530	\$ 2	21,065	79.40
						Fire Protection - Fire Alarm System - Correct deficiencies found while performing a level IV PM -					
			Wiley W. Manuel			Replace failed water flow device located on the 3rd floor stairway #1 and Fireman's phone jack			4		
2	FM-0052860	Alameda	Courthouse	01-B3	2	on the 1st floor	Ş	2,114	Ş	1,772	83.80
3		Alamada	Fremont Hall of		2	HVAC - Replace the failed slide valve piston and lip seal bypass kit on compressor #1 on Chiller	ć	6 746	¢		70.40
5	FM-0052881	Alameda	Justice Berkeley	01-H1		#1. Exterior window flashing - Replace two missing window head flashings on the front and rear	Ş	6,746	Ş	5,356	79.40
4	FM-0052952	Alameda	Courthouse	01-G1		second floor windows for wet weather proofing to match existing	Ś	3,225	Ś	3,225	100.00
						Fire Sprinkler - Replace leaking fire sprinkler system weld-o-let on the second floor, welding	<b>Υ</b>	0)220	7	0)220	
						required. Isolate fire sprinkler system riser on the south stairwell to allow all sprinklers to be					
			Wiley W. Manuel			feed from the north side riser. (Full building coverage overnight) Drain and fill system checking					
5	FM-0053024	Alameda	Courthouse	01-B3	2	all floors and floor isolation valves for leaks.	\$	8,569	\$	7,181	83.80
			Wakefield Taylor			HVAC - Remove and dispose of existing cooling tower; Re-slope and re-roof 800 sq ft of roofing; Install one (1) new 227 ton cooling tower. Provide and install 40 LF of 8 steel piping and 20 LF of 1 copper piping including fittings, valves and supports; Provide a new VFD; Connect cooling tower to the existing BAS. Work requires a crane and is to be done off hours - Existing Cooling					
6	FM-0053469	Alameda	Courthouse	07-A2	2	tower is rotting and leaking. The water pools on the roof due to slope problems.	\$	429,416	\$ 42	29,416	100.00
_			Fremont Hall of			Remove and replace failed twenty five horsepower motor for the pneumatic tube transport			1		
7	FM-0054040	Alameda	Justice	01-H1	2	system blower - Work to be performed after hours.	Ş	14,845	Ş 2	1,787	79.40
			Howward Hall of			Exterior Shell - Replace the failed outdoor steel staircase, guardrails, and hand rails, with an					
8	FM-0054046	Alameda	Hayward Hall of Justice	01-D1	2	industrial aluminum staircase, guardrails, and hand rails, located outside of the basement mechanical room - Rusted to a point of being unsafe	ć	52,822	¢ /	16,642	88.30
0	1101-0034040	Alameua	Justice		2	HVAC - Replace 2 Condenser Fan Motors, Fan Blades and Motor Speed Controls - The 2 motors	Ş	JZ,022	ې <u>د</u>	10,042	88.30
			Butte County			have quit working and the Chiller runs high pressures on warm days. Putting heavy load on					
9	FM-0052948	Butte	Courthouse	04-A1		compressors.	\$	6,521	\$	6,521	100.00
			New San Andreas					,			
10	FM-0054066	Calaveras	Courthouse	05-C1	2	Elevator - Elevator #4 stuck in basement with entrapment, replace failed vane behind rotor.	\$	2,812	\$	2,812	100.00
						COUNTY MANAGED - HVAC - Replace 22 year old, 60 ton HVAC unit that has completely failed.					
11	FM-0053025	Colusa	Courthouse Annex	06-A2	1	Repair is not economically prudent. Crane will be utilized to replace the unit.	\$	80,000	\$ 8	30,000	100.00
		Contra	George D. Carroll			HVAC - Restore AHU-11 to manufacturers specifications, work includes the installation of one new high efficiency motor with a VFD. This unit serves public areas that are presently not getting					
12	FM-0052942	Costa	Courthouse	07-F1		air. The VFD is required to lower air flow because the unit originally served a much a larger area.		14,841	\$ 2	1,129	74.99
L	I	1	1		1				-	-	



						Vandalism - Graffiti removal in six restrooms - Replace 2 - 5 x 3 etched restroom mirrors;	<u> </u>			
		Contra	George D. Carroll			Remove multiple instances of graffiti in clerks area and public spaces; Replace 24 defaced ceiling				
13	FM-0052943	Costa	Courthouse	07-F1	2	tiles.	Ś	9,073 \$	6,804	74.99
						Fire Protection - Install 80 ft 1-1/2 steel pipe; Install 7 new sprinkler heads with escutcheon; Re-	<u>† '</u>	, ,	,	
						plaster 36 sq ft ceiling plaster; Install straps (8), fittings (20), Replace 3 pre-action gauges; Drain				
		Contra				and recharge 3 floors 3 times; Perform fire watch; off hours work - Deficiencies found during				
14	FM-0052992	Costa	Bray Courts	07-A3	2	annual Fire Inspections by the SFM.	\$	57,155 \$	48,879	85.52
						HVAC - Remove and dispose of (4) failing rooftop AHUs; Install (4) new units, (1) 7.5 ton, and (3)				
						12.5 ton; Install 4 new roof curbs; Install (4) economizers and (4) smoke detectors; Install and				
		Contra	Danville District			wire (4) new thermostats (200 ft of wire); Modify 240 sq ft of ductwork to fit new units; Requires	5			
15	FM-0053468	Costa	Courthouse	07-C1	2	a crane and off hours installation.	\$	294,518 \$	294,518	100.00
						Fire Protection - Provide and install one (1) upgraded fire beam detector in the atrium; Provide				
						Start-up, testing, and verification of operation; Work to be performed by a specialty fire alarm				
						company; Work to be done off hour and requires a lift to access the detector location - Present				
		Contra	Arnason Justice			beam detector creates false alarm conditions. System adjustments completed since construction	1			
16	FM-0053473	Costa	Center	07-E3	2	have not resolved initial design deficiency.	\$	14,238 \$	14,238	100.00
						HVAC - Remove and replace one (1) 40 Ton roof top condenser, (1) 40 Ton indoor condenser,				
						and (4) 10 ton scrolls and heat exchanger; removal and replacement of (16) seismic spring				
						isolators, (2) water pumps, (2) 3 triple duty valves and suction diffusers and (6) 3 flex				
						connections, (2) thermometers and pressure gauge valve kits, (2) 1 1/4 and 1 3/8 flex				
		Contra	George D. Carroll	07.54		connections, (1) Pot Feeder, (100) LF of 3 chilled water piping and (100) LF of refrigerant piping;	4			74.00
1/	FM-0053477	Costa	Courthouse	07-F1	2	New refrigerant Leak detection system	<u>Ş</u>	567,603 \$	425,645	74.99
10		Contra	George D. Carroll	07 51		UNAC Develope Oty 1 failing hypring on bailer #2. The hypromia a seferty issue			2 4 6 2	74.00
18	FM-0054085	Costa	Courthouse	07-F1	2	HVAC - Replace Qty 1 failing burning on boiler #2 - The burner is a safety issue	<u> </u>	4,616 \$	3,462	74.99
						HVAC - Install new stainless steel outside air and return air dampers, linkages, and actuators for				
						nine (9) economizers (AH-1, AH-2, AH-3, AH-4, AH-5, AH-6, AH-8, AH-9, AH-11). Remove existing				
			Del Norte County			ductwork and install new dampers, insulation, and sheet metal. Reinstall existing ductwork and	*			
19	FM-0053412	Del Norte	Superior Court	08-A1	2	seal new dampers. Remove and dispose of existing dampers, linkages, and actuators.	Ś	75,881 \$	66,775	88.00
					+ -		+	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
						Exterior Shell - Replace 5 single glazed window & 2 door panes with opaque dual glazed units				
						and install 2 dual glazed doors/fame. Current conditions leave room too cold even after				
20	FM-0053450	El Dorado	Johnson Bldg.	09-E1	2	repeated HVAC adjustments that cannot overcome thermal loss from the exterior conditions.	\$	11,000 \$	11,000	100.00
			B.F. Sisk Federal			Grounds and Parking Lot - Replace slat, bottom rail and adjust - Judges' parking lot gate was hit				
21	FM-0052876	Fresno	Courthouse	10-01	2	with a vehicle and damaged, requiring parts replacement to operate properly.	\$	4,070 \$	4,070	100.00
						Fire Protection - Replace 2 stolen post indicator valve heads and secure as necessary them to				
						prevent them from being removed in the future. Order 4 new Knox covers and install them on				
						the 4 fire department connections. Paint the new valves fire red and secure them with new				
			Fresno County			padlocks - Fire Protection equipment must be maintained properly to insure it is ready when				
22	FM-0053039	Fresno	Courthouse.	10-A1	1	required for life safety.	\$	4,758 \$	4,563	95.91
						Security - (1) Install Windows 8.1 software on the two existing security camera system				
						workstations, replacing Windows XP; (2) Upgrade existing ViconNet software to v. 6.7SP1;				
						update software, drivers or firmware as necessary for existing Nucleus, 167 cameras, NVRs,				
						storage; (3) Replace one failed encoder Windows XP is no longer a supported operating				
			B.F. Sisk Federal			system, and is a security risk on the Courts network. The ViconNet software needs to be	L			
23	FM-0053461	Fresno	Courthouse	10-01	2	upgraded to support Windows 8.1.	\$	8,253 \$	8,253	100.00



			B.F. Sisk Federal			Energy Efficiency - HVAC - Install 30 smart room sensors, add building pressure controls to AHU- 6 along with transfer duct in Jury Assembly Room; reconfigure BAS software to maximize					
24	FM-0053522	Fresno	Courthouse	10-01	3	operational and program efficiencies relative to set points, temperature dead bands, fan control functions and temperature dead bands.	ć	61,604	ć	61,604	100.00
	110-0055522		Courtilouse	10-01	5		Ş	01,004	ې ا	01,004	100.00
						Interior Finishes - Remove approximately 270 sq. ft. of lead-based and non-lead-based paint at					
						areas of efflorescence and wall damage in Library and DCSS office. Perform clearance test of					
						abated areas to ensure no lead paint left behind. Patch and paint approximately 350 sq. ft. of					
						wall space - Moisture intrusion through outside wall from sprinkler system has caused					
25	FM-0054064	Fresno	Firebaugh Court	10-K1	2	efflorescence and wall damage. Environmental tests have been conducted and are attached.	\$	6,575	Ś	3,815	58.02
			JJC Delinquency	_		Security - Replace power supply and one hard drive in Multiplexer #1 - Multiplexer #1 has failed	-	- /			
26	FM-0054073	Fresno	Court	10-P1	2	and is inoperable.	\$	2,675	\$	1,565	58.50
						HVAC - Remove pump and pump motor for heating water system. Install new viton pump seal,		,		,	
			Fresno County			sleeve the seal race and remove grease from the motor. Reinstall pump and pump motor -					
27	FM-0054093	Fresno	Courthouse.	10-A1	2	Pump had failed and was badly leaking.	\$	2,895	\$	2,777	95.91
			Historic					,		,	
28	FM-0052947	Glenn	Courthouse	11-A1	1	HVAC - Replace condensing unit - Unit has dumped all refrigerant and will need to be replaced	Ś	3,500	Ś	1,715	49.00
								,		,	
			Humboldt County			Interior - Remediate Sound Issue - Supply and install forty-eight (48) sound emitters to mask the					
1			Courthouse			noise transfer issues in family law mediators office, safety issues when family members can hear					
29	FM-0052859	Humboldt	(Eureka)	12-A1	2	conversations with mediators outside in waiting rooms. Set up and training included.	\$	13,105	\$	13,105	100.00
						HVAC - Install Mini Split Unit - Install 1 recessed ceiling mounted Mini Split heat pump in Court		,		,	
						IT, the house system cannot control air temperature in this room due to heat load from					
						Computers, it is connected to Court Finance so we either keep one group hot or the other group					
			Humboldt County			cold. Including core drilling and roof penetrations, roofing patching at roof top compressor					
			Courthouse			location, modification to T-bar ceiling in IT room to allow recess unit to be installed, all electrical					
30	FM-0052861	Humboldt	(Eureka)	12-A1	2	connection and wireless	\$	52,322	\$	52,322	100.00
						HVAC - Install two new 5 ton rooftop high efficiency gas electric package units: AC Units PKU #8		,		,	
						and PKU #9 including new Seismic Vibration Isolation Roof Curbs. A 90 ton crane will be used to					
1						remove the (2) package units from the roof and lift the new units into place. Two rooftop HVAC					
						units (5 ton each) no longer provide sufficient cooling to Judge's Chambers and the Deliberation					
			Delano/North			room. Both units have had multiple parts replaced to no avail and units are operating at less					
31	FM-0052741	Kern	Kern Court	15-D1	2	than 60% capacity.	\$	39,293	\$	39,293	100.00
						HVAC - Compressors were replaced returning cooling to Court exclusive (critical) areas. Replace					
			Delano/North			faulty compressors (2) that are both grounded and not providing cooling to Courtroom - failed					
32	FM-0052831	Kern	Kern Court	15-D1	1	compressors have rendered unit servicing Courtroom inoperable.	\$	8,656	\$	8,656	100.00
						COUNTY MANAGED - Electrical - P2/PHASE 2 of P1 Electrical Work - Replace 50yr old					
			Bakersfield			cabling/conductors/breakers/disconnects. The existing electrical panel has been in service for					
33	FM-0052841	Kern	Superior Court	15-A1	2	fifty years and parts can no longer be replaced, this is a 12000 volt system.	\$	485,210	\$	485,210	100.00
			Bakersfield			HVAC - Replace failed Compressor #2 on Chiller #1. Chiller working below capacity due to failed					
34	FM-0052904	Kern	Juvenile Center	15-C1	1	Compressor #2 on Chiller #1.	\$	42,791	\$	28,567	66.76
			Bakersfield			Plumbing - Replace approximately 5' of leaking 3" chilled water pipe and multiple fittings.					
35	FM-0052907	Kern	Juvenile Center	15-C1	2	Chilled water line has small leak and must be replaced.	\$	3,304	\$	2,206	66.76
						Plumbing - Restore leaking pipe in Men's public restroom: Area scrubbed and dried out, drywall					
			Shafter/Wasco			removed and replaced in lobby and men's public restroom. Patch and paint to match existing.					
36	FM-0052985	Kern	Courts Bldg.	15-E1	1	Court staff reported wet wall and floor tile in restroom.	\$	31,918	\$	28,710	89.95



			Bakersfield							
37	FM-0053037	Korn	Superior Court Modular	15-A2	2	HVAC - HVAC Bard unit compressor has failed. Installation of replacement (Energy Efficient) HVAC unit to service Superior Court Modular.	ć	5,328 \$	3,337	62.64
57	FIVI-0055057	Kern		15-AZ	Ζ		ې ا	5,526 Ş	5,557	62.64
						Plumbing - Water line restored, judge's chambers and clerk's offices scrubbed/dried out over 48				
			Bakersfield			hour period. Small paint touch up to Clerk's office wall. In custody in Holding Cell #2 damaged				
38	FM-0053453	Kern	Superior Court	15-A1	1	water line to toilet (clean water) causing water intrusion to judge's chambers and clerk's offices.	Ś	3,047 \$	1,909	62.64
			Bakersfield			HVAC - Replace burnt out supply fan motor, pulley w/hub and 2 new belts. Reconnect wiring to	τ 			
39	FM-0053487	Kern	Superior Court	15-A1	2	new motor. Burnt out supply fan motor not providing cooling to AHU 04.	Ś	2,699 \$	1,691	62.64
			Arvin/ Lamont		_	Fire Protection - Fire curtain door at window 5 tension wheel assembly replaced and installed	Ŷ	<b></b> )000		02101
40	FM-0053951	Kern	Branch	15-H1	2	onto shutter. Fire curtain at window # 5 in clerk's office will not open.	Ś	2,731 \$	1,663	60.91
				101	_		Ŷ			
						Exterior Grounds - Asphalt - Remove and replace approximately 13 Cubic Yards of damaged				
						asphalt, fill 800 LF of cracks and seal the parking lot (approx 38000 SF ). Work includes the				
41	FM-0047471	Lake	South Civic Center	17-B1	2	installation of 20 lf concrete curb, 16 sf truncated domes, 1 bollard and striping	Ś	55,421 \$	55,421	100.00
							1	,	/	
						Safety - Bullet Resistant Glazing - Remove and replace one (1) 4' x 2' Cracked Bullet Resistant				
			New Susanville			Glass window in Judges Conference Room - A Bullet Resistant glass window is cracked and has				
42	FM-0052963	Lassen	Courthouse	18-C1	2	lost its structural integrity, therefore can no longer perform its design function.	Ś	3,873 \$	3,873	100.00
						HVAC - Boiler 1 & 2 will not stay online, control boards have failed and the building cannot be	T			
			New Susanville			heated. Replace control boards and add heat tape and windshield to unit housing to protect and				
43	FM-0054087		Courthouse	18-C1	1	help prevent reoccurrence.	\$	2,000 \$	2,000	100
						Grounds and Parking Lot - Potential Hazardous Material Leak- contain and mitigate		, ,	,	
						environmental hazard. Saw cut and hand demo 8'x8' area of concrete where the Glycol is				
						seeping through concrete fissures and determine the source of the leak. Replace the leaking PVC				
			New Susanville			couplers with Shark Bite brass couplers. Retrieve and properly dispose of ponded Glycol. Restore				
44	FM-0054111	Lassen	Courthouse	18-C1	1	concrete to existing conditions	\$	10,000 \$	10,000	100
								, ,		
						Elevator - Elevator Renovation - Complete renovation of five (5) traction and two (2) hydraulic				
						elevators. Work will include but not be limited to, car frames and platforms, buffers and				
						safeties, hoist way entrance frames, doors and pit equipt., new AC gearless machines, micro-				
						processor control systems, regenerative VVVF AC drives, fly ball governors, closed loop heavy				
						duty high speed operators, current code required wiring, interior and lobby control panels,				
						counterweights and roller guides, hoist and governor ropes, cab ceilings with LED down lights,				
			Pasadena Superior			rope compensation, new submersible pump units and underground cylinders encased in PVC for				
45	FM-0035537	Los Angeles	•	19-J1	2	hydraulic elevators, and seismic provisions. Provide new air conditioning to the machine rooms.	\$	3,893,560 \$	3,163,518	81.25
		_				Plumbing - Replace Leaking 250 Gallon Water Heater in Rm. B27 - Needed to maintain the				
			El Monte			buildings potable hot water supply to all restrooms and entire facility for the comfort and				
46	FM-0036206	Los Angeles	Courthouse	19-01	2	cleanliness of the court	\$	40,828 \$	23,729	58.12
			Torrance			Grounds-Replace broken curb (35 lf) and concrete (350 sf) causing trip hazard in parking lot,				
47	FM-0047040	Los Angeles	Courthouse	19-C1	2	caused by tree roots which need to be addressed during construction.	Ś	9,264 \$	7,887	85.14



						Elevator - Elevator Renovation - Complete renovation of eight (8) gearless traction elevators, six					
						3,000 lb capacity and two 8,000 lb capacity. Work will include but not be limited to, car frames					
						and platforms, buffers and safeties, hoist way entrance frames, doors and pit equipt., new AC					
						gearless machines, micro-processor control systems, regenerative VVVF AC drives, fly ball					
						governors, closed loop heavy duty high speed operators, current code required wiring, interior					
			Stanley Mosk			and lobby control panels, counterweights and roller guides, hoist and governor ropes, cab					
10	FM-0049106	Los Angeles		19-K1	2	ceilings with LED down lights, rope compensation and seismic provisions.	Ś	3,851,000	ć	3,745,483	97.26
40	1101-0049100	LUS Angeles	Courthouse	13-11	2	Interior Finish - Grind chipped and irregular floor and apply elastomeric filler to recessed areas	Ş	3,831,000	ې ا	5,745,485	57.20
			Airport			to bring floor to flush condition (Approximately 80 SF)Work is needed to prevent possible					
10	FM-0050722	Los Angeles		19-AU1	2	tripping hazard and maintain clean floor surface.	ć	8,810	ć	6,799	77.17
49	1101-0030722	LUS Angeles	Courthouse	13-401	2	Fire Protection - Replace 1,811 sprinkler heads throughout the 736,000 SF. facility that are	ې ا	0,010	ې ا	0,799	//.1/
			Stanley Mosk			painted over, some are more than 50 yrs old and found deficient during latest Fire Marshals					
50	FM-0052807		-	10 11	2	inspection. The sprinkler heads have failed U/L testing.	ć	215 621	4	209,713	97.26
50	FIVI-0032807	Los Angeles	Chatsworth	19-K1	2	Electrical - Replace 120 UPS Batteries for Alarm System. Batteries failed and put system into	ې ا	215,621	Ş	209,713	97.20
51	FM-0052811	Los Angeles		19-AY1	1	alarm status.	ć	66,495	ć	55,723	83.80
51	FIVI-0052811	LOS Aligeles	Courthouse	19-AT1	1	Interior Finishes - Frame and install a secured door to the back hallway to Judge's chambers	ې ا	00,495	ې ا	55,725	05.00
			Staploy Mock			#421. Currently the hallway is not secured to the public and the public waits by the chamber					
<b>_ _ _ _ _ _ _ _ _ _</b>			Stanley Mosk	10 1/1	2		ć		4	2 5 6 1	100.00
52	FM-0052813	Los Angeles		19-K1	2	doors while in line for the restroom, creating a safety situation.	Ş	3,561	Ş	3,561	100.00
			Clara Shortridge Foltz Criminal			Plumbing - Clear out main line to stop overflow onto cells, remove all debris from floor and disinfect entire area due to sowage water. 8th Elect main line back up causing sowage water to					
<b>Г</b> 2				10.11	1	disinfect entire area due to sewage water. 8th Floor main line back up causing sewage water to	ć	2 740	4	1 005	69.70
53	FM-0052817	LOS Angeles	Justice Center	19-L1	1	come out floor drains on 4-cells. Plumbing - Replace cracked porcelain sink with stainless steel sink that complies with public and	Ş	2,740	<u>ې</u>	1,885	68.79
			Alhambra								
EA				10.11	2	safety standards. The porcelain sink in the holding cell is cracked presenting safety hazard for	ć	4 705	4	4 705	100.00
54	FM-0052818	Los Angeles	Courthouse	19-11	Z	the inmates and sheriff deputies if it breaks. Grounds - Cut and remove concrete that is causing the uneven surface. Pour new concrete and	Ş	4,795	Ş	4,795	100.00
			Compton								
EE			Compton	10 101	2	smooth out walkway area. Currently the concrete walkway and expansion joint is uneven	د د	E 201	4	2 402	66 12
55	FM-0052819	Los Angeles	Courthouse	19-AG1	2	causing a safety and trip hazard.	Ş	5,281	Ş	3,492	66.13
			Clara Shortridge			Plumbing - Replace failed and angle stop to cell. Leaking down to 3rd floor public hallway.					
			Foltz Criminal								
EG		Los Angolos		10.11	1	Secure water supply, contain area. Installed Add-a-valve to secure water supply and changed	ć	6 900	4	1 691	69.70
50	FM-0052823	LUS Aligeles	Justice Center	19-L1	1	out damage angle stop, seal pipe chase floor to prevent future leaks to lower floor. Elevators, Escalators, & Hoists - Obstruction in Comteeth - Isolate the cause of the loud grinding	ې ا	6,809	ې ا	4,684	68.79
						sound at the 1st to 2nd floor escalator, found and removed a metal object wedged in the					
57	FM-0052825		Van Nuys	10 4 2 2	2		ć	2024	4	2 1 5 9	00.40
57	FIVI-0052825	LOS Aligeles	Courthouse West	19-AX2	2	comteeth, put the escalator back into operation.	Ş	3,924	Ş	3,158	80.48
						Elevators, Escalators, & Hoists - Found F11 and F12 fuses open, elevator trips loop overloaded					
			Van Nuys			due to brake pick failure. Renovate 2TR relay, adjusted 2TR timer, tested operation and returned					
EO	FM-0052827			10.472	1	elevators to normal service. Public Elevator 1 & 2 not responding, sitting on main ground floor.	'  ċ	2 107	¢	2 561	80.48
30	1 101-0032627	LOS AIIREIES	Courthouse West Hall of Records-	19-AX2		COUNTY MANAGED - ELEVATOR - Replace Hydraulic elevator pump motor and starters Y and	ې ا	3,182	ې ا	2,561	00.40
EO			County Records		1	Delta at Archives 222 N. Hill St., Los Angeles 90012. This is the Freight Elevator (1of 1). Non-	4		4		100.00
59	FM-0052828	Los Angeles		19-AV3		operating elevator is impacting Archive operations. Interior Finishes - Frame and install a secured door to the back hallway to Judge's chambers	<u> </u>	6,500	ې ۲	6,500	100.00
			Staplay Made								
60			Stanley Mosk	10 1/1	2	#321. Currently the hallway is not secured to the public and the public waits by the chamber	4	F 400	4	г лээ	100.00
60	FM-0052834	LOS Angeles	courthouse	19-K1	2	doors while in line for the restroom, creating a safety situation.	\$	5,433	Ş	5,433	100.00



						Elevator - Furnish and install new fire rated door with laminate wood grain to match existing					
			Compton			doors and test for proper operation. Currently the elevator lobby is damaged and needs to be					
61	FM-0052836	Los Angeles		19-AG1	2	replaced due to the current condition does not present any fire rating.	¢	2,886	¢	1,909	66.13
01			Courtilouse		2	Interior Finishes - Install safety straps tight around columns to prevent from falling. Columns will	ې ا	2,000	ې ا	1,505	00.15
			Van Nuys			be strapped every 5-8 feet. 50 ft columns have panels falling and some ready to fall causing a					
62	FM-0052839	Los Angeles	Courthouse West	19-AX2	1	huge safety issue.	¢	12,762	¢	10,271	80.48
02					-	Elevators, Escalators, & Hoists - Restore default memory, reset microprocessor and re-sync	ې ا	12,702	ې ا	10,271	00.40
			Beverly Hills			position system by driving elevator to its lowest level to regain its default memory. Elevator #2					
63	FM-0052852	Los Angeles	•	19-AQ1	2	has lost its memory and the hoist way door keeps on cycling at the 4th floor.	¢	3,197	¢	2,542	79.52
05			Parking Lot-San		2	Parking Lot / Resurface Jury parking lot. Currently the pavement/concrete throughout the	ې ا	5,157	ې ا	2,542	75.52
			Fernando			parking lot is damaged, with numerous cracks and potholes scattered throughout the parking					
64	FM-0052854	Los Angeles	Courthouse Jury-	19-AC6	2	lot, creating tripping hazards along with tire damage to the cars.	¢	5,225	¢	4,358	83.41
04					2	Elevators, Escalators, & Hoists - Clean contacts on selector, overload and dashpot oil low.	ې ا	5,225	ې ا	4,550	05.41
			Van Nuys			Refilled oil and tested car and returned to service. Judges elevator #6 is stuck on 2nd floor not					
65	FM-0052855	l os Angeles	Courthouse East	19-AX1	1	responding, no entrapment.	¢	2,634	¢	2,634	100.00
05			Courthouse Last		-	Elevators, Escalators, & Hoists - Shorten the hoist ropes and test operation under seismic or	ې ا	2,034	ې ا	2,034	100.00
			Pomona			emergency conditions. The elevator did not pass the annual inspection and a preliminary order					
66	FM-0052856	Los Angeles	Courthouse South	10_\//1	2	was written.	¢	4,578	¢	4,172	91.14
00				19-001	2		ې ا	4,378	ې ا	4,172	91.14
						Plumbing - Drained and isolated water pipe system, removed a 2" and 1-1/2" water valve that					
						were rusted/corroded. Installed new valves and re-filled system, checked for any leaks. Two					
			Bellflower			water valves were leaking water constantly in lock up pipe chases, water was penetrating to the					
67					1		ć	2 705	ć	2 059	77.94
07	FM-0052864	Los Angeles	Courthouse	19-AL1		floor below. Water was accumulating in pipe chases creating slipping and safety hazard. Electrical - Remove existing batteries and install lead acid batteries 8D. Install 24v charger in the	Ş	3,795	Ş	2,958	77.94
			Metropolitan			generator and replace existing cable. Currently the batteries and cable are originals and need to					
68	FM-0052865	Los Angeles		19-T1	2	be replaced.	ć	4,938	ć	4,668	94.54
00	FIVI-0032803	LOS Angeles	Burbank	19-11	2	Fire Protection - Replace fire-fly IV (dropping device) on the fire door. Currently the fire door has	Ş	4,930	Ş	4,008	94.94
60	FM-0052866	Los Angeles		19-G1	2	failed to drop when the fire alarm is on, creating a safety situation.	¢	4,834	¢	4,387	90.76
09	1 101-0032800	LUS Angeles	Clara Shortridge	19-01	2		Ş	4,034	Ş	4,387	90.70
			Foltz Criminal			Exterior Finishes - Remove and replace one (1) 4'x4' damaged piece of glass. High reach					
70	FM-0052868	Los Angeles		19-L1	2	equipment will be required to complete this work.	ć	2,360	ć	1,623	68.79
70	1 101-0032808	LUS Angeles	Metropolitan	19-L1	2	Elevators - Relays - Isolate the failures identified during the Reg 4 test on elevators 1-9, found	Ş	2,300	ې ا	1,023	08.79
71	FM-0052875	Los Angeles		19-T1	2	that multiple relays were failing and were replaced .	ć	3,724	ć	3,521	94.54
/1		LUS Angeles	Courtilouse	19-11	2	HVAC - Failing Return Fan Motor - Remove and replace return blower motor and bearings, AHU	ې ا	3,724	ې ا	3,321	94.94
			Pasadena			#6 is not operating due to the faulty return fan motor affecting the air flow on the 5th and 6th					
72	FM-0052880	Los Angeles		19-J1	2	floors.	¢	4,345	¢	3,013	69.35
12	110-0052880		Metropolitan	T7-1T	2	HVAC - Bypass water on the chilled water system for the drinking fountains and recover	ې ا	4,343	ې ا	3,013	05.55
73	FM-0052882	Los Angeles		19-T1	2	refrigerant. Floor#2, 3, 5, and 7. Currently there is no way to by-pass the failed chillers.	¢	5,616	¢	5,309	94.54
/3	1 101-0052882	LUS Angeles	Courtilouse	19-11	2	Electrical - Replace the single wall day tank with a double wall tank and anchor it down to the	ې ا	5,010	ې ا	5,505	94.94
1						roof, install a monitoring device to insure no over flow or loss of fuel, replace all piping with new					
						stainless steel flex lines to bring the system up to code. Currently the day tank is a single wall					
			Metropolitan			tank with no alarm for high or low fuel and no leak detector. If the tank cracks it will leak fuel on					
71	FM-0052891	Los Angeles		19-T1	2	the roof creating a safety situation.	ć	10,585	ć	10,007	94.54
/4	1 101-0032091	LOS AIIgeles	Torrance		<u> </u>	Vandalism - Strip doors and frames, sand and remove graffiti off doors, stain to match existing	ې ا	10,000	ې ا	10,007	54.54
75	FM-0052893	Los Angeles		19-C1	2	and apply clear finish coat. Total of 25 doors and 5 frames.	ć	7 750	ć	6 601	
72	1111-0052893	LOS AUREIES	Courtilouse	13-01	Z	and apply clear ministr coat. Total of 25 doors and 5 frames.	\$	7,753	၃	6,601	85.14



						Fire Protection - Fire Alarm Wiring - Isolate and remove multiple shorts and ground faults in the					
			Long Beach			wiring for the fire alarm panel. Currently there is intermittent trouble alarms due to the faulty					
76	FM-0052894	Los Angeles	Courthouse	19-Y1	2	wiring.	\$	4,944	\$	3,737	75.59
			Education of D			Interior Finishes - Water remediation, set up containments, installed new waterproof panel in					
			Edmund D.			the janitorial mop sink area, install new drywall and repaint area. Water leaking through the 5th					
			Edelman	10.01	1	floor ceiling in the secure hallway between the restrooms, water coming from the 6th floor	4		د د	4 1 0 0	<u> </u>
77	FM-0052896	Los Angeles	Children's Court	19-Q1		janitorial mop sink. Plumbing - Replace faulty water valve under the women's jury restroom sink. Water	<u>ې</u>	5,858	Ş	4,100	69.99
			Torrance			remediation, set up ACM containment. Water impacted 2nd floor and down to Dept. H and					
78	FM-0052897	Los Angeles		19-C1	1	judges chamber.	\$	6,616	¢	6,616	100.00
/0	1101 0032037				<u> </u>	Electrical - Drain coolant from Generator, re-core radiator, replace, all hoses and connectors to	<u> </u>	0,010	Υ 	0,010	100.00
						generator, and refill with new coolant. Currently the generator radiator is leaking coolant which					
			Metropolitan			is causing a safety situation when the generator were to be used in an emergency and it over					
79	FM-0052899	Los Angeles	Courthouse	19-T1	2	heats due to the coolant being low.	\$	31,711	\$	29,980	94.54
						Elevator - Remove and replace defective solid state starter. Currently the broken solid state					
			Santa Monica			starter is disabling the elevator, leaving the court with no working elevators for the public					
80	FM-0052900	Los Angeles	Court Annex	19-AP3	1	causing a ADA compliance issue.	\$	2,565	\$	2,013	78.49
						Plumbing - Replace failed piping and remediate ACM contamination. Replace 5 ft of 3 inch cast					
						iron waste pipe and coupling and 2 ft of 2 inch waste pipe, comby and coupling. Water					
						remediation, set up containments, HEPA vacuum, disinfect. Dehumidifiers and fans were placed					
			Pasadena			to remove moisture in the leak affected areas. 3rd floor men's restroom drain line leaked into		46 700	4		co o <b>-</b>
81	FM-0052906	Los Angeles	Courthouse	19-J1	1	2nd floor.	Ş	46,782	Ş	32,443	69.35
			Chatsworth			Plumbing - Replace punctured backflow to Cooling Tower #1. Currently the backflow has a hole					
82	FM-0052908	Los Angeles		19-AY1	2	in the body and could leak at anytime, which would affect the water flow to the cooling tower effecting major operation of cooling.	ć	4,944	ć	4,143	83.80
02	1101-0032908	LUS Aligeles		13-AT1	Z	HVAC - Remove and replace (2) leaking 4" gate valves in the AHU room. This work was	Ş	4,944	ې ا	4,143	83.80
			Bellflower			completed as a P1 emergency due to the floor being constantly wet with pool water, creating a					
83	FM-0052917	Los Angeles		19-AL1	1	slipping and safety hazard.	Ś	3,371	Ś	2,627	77.94
							T	-,	T		
						HVAC - Replace leaking pipes and valves on Cooling Towers #1 and #2. Return and supply lines					
			Downey			have rust spots on the pipes which could spring a leak at any moment. Valves need to be					
84	FM-0052918	Los Angeles	Courthouse	19-AM1	2	replaced, they are almost frozen, very hard to turn, safety concern, possible flooding.	\$	21,598	\$	18,078	83.70
			Parking Structure-								
			Lot 53 Pasadena			Grounds and Parking Lot - Replace leaking 3" dry control valve. Dry standpipe control valve is					
85	FM-0052920	Los Angeles	Court-	19-J3	2	leaking, not holding pressure.	\$	5,146	\$	3,569	69.35
			Edmund D.								
00			Edelman	10.01	ſ	Parking Lot / Replace broken cables and straighten bent panels on the Sheriff's sally port gate.	4	2 0 2 2	<u>ج</u>	2 752	<u> </u>
80	FM-0052924	Los Angeles	Children's Court	19-Q1	Ζ	One of the cables broke causing one side of the door to fall, damaging the panels. HVAC - Remove and replace damages parts (bearings, blower wheels, shaft, & B85 belts) from	Ş	3,933	Ş	2,753	69.99
						Air Handler Unit. Currently the basement exhaust fan has a broken drive shaft and is non-					
			Norwalk			operational. Air in the basement is not being exhausted properly and this is a safety and health					
87	FM-0052926	Los Angeles		19-AK1	2	hazard.	Ś	9,399	Ś	7,992	85.03
			Parking Structure-		_	Plumbing - Replace malfunctioning floats and remove the debris from the sewage injector	+ +	2,233	Ŧ	.,	
			El Monte			pumps. The sewage injector pumps were operating continuously due to malfunctioning floats					
88	FM-0052937		Courthouse-	19-02	2	and high amount of debris in the sewage pit.	\$	4,579	\$	2,661	58.12
			Chatsworth			HVAC - Replace Worn Gear Reducing Transmission. Gear Reducing Transmission causing					
00	FM-0052940	Los Angeles	Courthouse	19-AY1	2	vibration, might break down and fail, effecting cooling system.	\$	43,174	Ś	36,180	83.80



			Pasadena			Elevators, Escalators, & Hoists - Remove worn out bearings and install new bearings sheave.				
90	FM-0052953	Los Angeles	Courthouse	19-J1	1	Judge's elevator #5 was out of service, bearing sheave worn out need to be replace/repair	\$	14,960 \$	14,960	100.00
			Burbank			Plumbing - Install water heater. Currently there is no hot water in over 50 percent of the				
91	FM-0052954	Los Angeles	Courthouse	19-G1	1	courthouse which is a safety and health concern.	\$	6,181 \$	5,610	90.76
						Electrical - Door detector edge on elevator #1 - Remove and replace the failed door detector				
						edge, damaged cable and transformer in the control monitor mother board. Currently the				
			Inglewood			elevator is not working due to the cable for the door edge snapped causing the door edge to fail				
92	FM-0052955	Los Angeles	Courthouse	19-F1	1	and the mother board to short out.	\$	5,618 \$	4,189	74.56
			Van Nuys			Plumbing - Set up containment, repair 2' cast-iron drain line that is cracked and leaking into the				
93	FM-0052956	Los Angeles	Courthouse West	19-AX2	1	10th floor D.A.'s secure hallway (southeast corner), which is creating a slip hazard.	\$	8,000 \$	6,438	80.48
			Parking Structure							
			Lot 94 Airport			Elevators, Escalators, & Hoists - Replace failed seal and pressure test the system. Elevator has a				
94	FM-0052958	Los Angeles		19-AU2	1	bad packing seal to piston.	\$	6,904 \$	5,328	77.17
			Clara Shortridge							
			Foltz Criminal			Plumbing - Set up containment, test, and secure water supply with add-a-valve and replace				
95	FM-0052960	Los Angeles	Justice Center	19-L1	1	damaged plumbing. Water leaking through the Dept 33 ceiling.	Ş	7,978 \$	5,488	68.79
0.0			Metropolitan	10 74	2	HVAC - Replace two existing pneumatic valves and associated piping on the 3rd and 8th floor.	~		6 720	0454
96	FM-0052961	Los Angeles	Courthouse	19-T1	2	Currently the existing valves are leaking water in the AHU rooms, creating a slip hazard.	Ş	7,119 \$	6,730	94.54
			A incont			Elevator - Remove and replace with new elevator entry doors. Currently the stainless steel door				
07			Airport	10 4111	2	skin is failing and its delaminating causes the doors to get hung up on the hoist way and will	4	0.221	C 252	77 17
97	FM-0052964	Los Angeles		19-AU1	2	cause entrapments.	Ş	8,231 \$	6,352	77.17
00	FM-0052987	Los Angeles	Torrance	10 C1	1	HVAC - Replace exhaust fan motor on kitchen hood. Currently the kitchen is very hot due to the	ć		4 257	OF 14
90	FIVI-0052967	LOS Aligeles	Courtilouse	19-C1	1	kitchen exhaust is not functioning properly. HVAC - Replaced failed VAV controls in Dept K. Currently the supply air is a 77 degrees for the	Ş	5,000 \$	4,257	85.14
			Pasadena			4th floor and not dropping to a cooler temperature which is creating a uncomfortable work				
۵۵	FM-0052989	Los Angeles		19-J1	1	environment for the court employees.	¢	5,000 \$	5,000	100.00
55	110-0052585	LUS Angeles	Clara Shortridge	17-11	-	Plumbing - Replace failed hardware for hot water supply to Air Handing Unit 14-3. Currently	ې ا	5,000 \$	5,000	100.00
			Foltz Criminal			there is water dripping from the pneumatic actuator valve. Set up containment, abatement of				
100	FM-0052990	Los Angeles	Justice Center	19-L1	1	ACM insulation and wrapping.	Ś	20,000 \$	13,758	68.79
100		20071180100			-	Plumbing - Replace failed drain line. Contain ACM area and repair water damaged areas	Ŷ	20,000 9		00175
			Van Nuys			required for court access. Currently water is dripping into the 10th floor District Attorney				
101	FM-0052991	Los Angeles	Courthouse West	19-AX2	1	hallway.	Ś	10,000 \$	8,048	80.48
		<u> </u>	Airport			Elevators - Replace bad S1O Board and Bad Power Supply. Elevator #1 is not function without a		, ,	,	
102	FM-0052993	Los Angeles	Courthouse	19-AU1	2	new S10 board and power supply.	\$	7,467 \$	5,762	77.17
			Van Nuys			HVAC - Replace fan motor on Cooling Tower #1. Currently cooling tower is not functioning which	1		-	
103	FM-0052997	Los Angeles	Courthouse West	19-AX2	1	is making the courthouse temperatures rise.	\$	10,000 \$	8,048	80.48
						HVAC - Replace Variable Frequency Drive (VFD) for Air Handler Unit #1. Currently the circuit				
			Bellflower			board for the supply VFD is faulty and the drive will not ramp up or down causing high air flow				
104	FM-0052998	Los Angeles	Courthouse	19-AL1	1	from the air duct.	\$	10,000 \$	7,794	77.94
			Stanley Mosk			HVAC - Replace a failing seam on the ductwork insulation. Contain and abate ACM				
105	FM-0052999	Los Angeles	Courthouse	19-K1	1	contaminants. Condensation was leaking above the ceiling tile on the 4th floor in room 425C.	\$	10,000 \$	9,726	97.26



						HVAC - Replace condenser pump for the split system in the communication room. Currently the					
			Norwalk			split system is not functioning causing the server room to become hot which could affect the					
106	FM-0053000	Los Angeles	Courthouse	19-AK1	1	computer equipment for the courthouse.	Ś	5,000	Ś	5,000	100.00
						HVAC - Replace the motor and motor starter on Air Compressor #1. Currently the motor	Υ 	0,000	Υ 		
			Inglewood			contactor and motor grounded out on the pneumatic air compressor. The dampers on all AHUs					
107	FM-0053001	Los Angeles	Courthouse	19-F1	1	are closed and no cooling can be provided to the courthouse.	\$	10,000	Ś	7,456	74.56
107		20071180100			-	Plumbing - Replace 7 feet of 4" cracked drain pipe inside pipe chase of Department O lock-up on	Ŷ	10,000	Υ	7,100	/ 110 0
			Compton			the 12th floor, ACM and bacterial clean up of floors 7-12, and build back affected areas. Water					
108	FM-0053014	Los Angeles	-	19-AG1	1	dripping from the 12 floor all the way down to the 7th floor.	\$	17,723	Ś	11,720	66.13
100		20374162103			-		Ŷ	17,723	Υ 	11,720	00.13
						Plumbing - Replace 2 failed toilets, replace damaged ceiling tiles, set up and maintain ACM					
			Compton			containment on the 9th - 12th floors. System failure on the 12th floor caused leaking all the way					
109	FM-0053015	Los Angeles		19-AG1	1	down to the 9th floor causing a health and safety hazard throughout the courthouse.	\$	19,091	¢	12,625	66.13
105	110-0055015	LUS Angeles	courtilouse	17-401	-		ې ا	15,051	ې ا	12,023	00.15
						Electrical - Remove head assembly, replace gasket seals, fuel filters, Rocker Arms and Rocker					
			Stanley Mosk			stand. Rebuild fuel injectors and governor, perform load test. Emergency diesel generator #2					
110	FM-0053016	Los Angeles		19-K1	1	has coolant leaking into head assembly and in oil sump, governor not regulating speed.	¢	42,226	¢	41,069	97.26
110		LUS Angeles	Pasadena		-	Exterior Finishes / Replace sally port entrance gate. The sally port gate was struck by a police	ې ا	42,220	Ŷ	41,005	57.20
111	FM-0053023	Los Angeles		19-J1	1	vehicle and is badly damaged. The gate will not secure which a security issue.	¢	10,000	¢	10,000	100.00
	1101-0055025	LUS Aligeles	Courtilouse	19-11		Interior Finishes - Renovate court clerk stations in departments 101 and 102. Court IT changes	ې ا	10,000	ې ا	10,000	100.00
						require work station renovation to facilitate additional hardware for court clerk. Work will also					
			Van Nuys			eliminate existing ergonomic issues related to document transfer between the judges and					
112	FM-0053027	Los Angolos	Courthouse West	10 4 2 2	2		ć	4,719	ć	3,798	80.48
112	FIVI-0055027	LOS Aligeles	Courthouse west	19-AX2	2	clerks. HVAC - Chiller #1 is shutting down on high head pressure - Descaled all corroded chiller tubes,	Ş	4,719	Ş	5,790	00.40
			Compton								
112		Los Angolos	Compton	10 101	1	replaced the head gaskets and returned chiller into service. The non operating chiller has caused temperatures in the courthouse rise.	e e	6 000	ć	2 0 6 9	66 12
115	FM-0053028	Los Angeles	Courthouse	19-AG1	1	HVAC / Replace failed and leaking pressure relief valves to comfort heating boilers. ACM	Ş	6,000	Ş	3,968	66.13
			East Los Angolos			containment and disposal. Currently water is dripping from the 5th floor mechanical room down					
111		Los Angolos	East Los Angeles	10.1/1	1		4	10 000	ć		
114	FM-0053029	Los Angeles	Courthouse	19-V1	1	to the 4th floor Judge's chamber 418C and Deputies Gym room 417.	Ş	10,000	Ş	7,772	77.72
			Clara Shortridge			Rhumbing (replace cracked 2" waste line utilizing lift, includes ACM containment and					
115			Foltz Criminal	10.11	1	Plumbing / replace cracked 2" waste line utilizing lift, includes ACM containment and	4	20.000	ج ح	12 750	C 9 70
115	FM-0053423	Los Angeles	Justice Center	19-L1	1	environmental testing.	Ş	20,000	Ş	13,758	68.79
			Compton			Electrical - Emergency Generator Fuel Leak - Replaced a defective gaskets and tightened all fuel					
110			Compton	10 101	1	lines. Diesel fuel was discovered inside the generator engine block and oil pan during the	4	10.000	ج ح	C C12	CC 12
110	FM-0053424	Los Angeles	Courthouse	19-AG1	T	emergency generator PM.	ې ا	10,000	\$	6,613	66.13
			Michael D.								
			Antonovich			Dlumbing / Snake and clean out main line due to blockage. Currently sources is coming we from					
447			Antelope Valley	10 471	1	Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from	~	10.000	~	7 254	
	FM-0053426	Los Angeles	Courthouse	19-AZ1		the floor drains and causing slip hazard to the kitchen workers.	> 	10,000	Ş	7,351	73.51
			Clandala			UVAC Poplace Shaft Scale Head Caskets and O Pings on compressor. Demove and realess					
110			Glendale	10.111	1	HVAC - Replace Shaft Seals, Head Gaskets and O-Rings on compressor. Remove and replace	4	70 200	ć	71 700	
118	FM-0053432	Los Angeles		19-H1		Motor Control Center (MCC). AHU #3 has refrigerant leak, no signal from MCC, not cooling.	>	79,300	Ş	71,798	90.54
110		Loc Angeles	Stanley Mosk	10 1/1	<b>_</b> _	Elevators, escalators, & hoist - Public elevator #3 - Remove and replace bad bearings on the	4		ć		
113	FM-0053436	LOS Angeles	Courthouse	19-K1	Z	generator set, the elevator is out of service due to leveling issues.	Ş	35,651	Ş	34,674	97.26



						Electrical - Replace 2500 amp breaker - Currently a 2500 amp breaker at the main panel is not				
			Edmund D.			resetting properly, this breaker controls the power to the penthouse on the roof where the				
			Edelman			chiller plant and boiler plants are located. If the breaker trips there is high probability that it will				
120	FM-0053445	Los Angeles	Children's Court	19-Q1	2	not reset and the court will lose the cooling and heating to the building.	\$	18,285 \$	12,798	69.99
			Edmund D.			Fire Protection - Replace one set of fire doors with new 45 min rated fire doors to meet code.				
			Edelman			Currently the fire doors have a crack on the side of the doors and they do not meet the fire				
121	FM-0053446	Los Angeles	Children's Court	19-Q1	2	code.	Ş	5,301 \$	3,710	69.99
			Davia and			UNAC Disconstructed Chiller #1 and realized acade, realizets, and O views. Chiller #1 leads that				
122			Pomona	10 \\/1	2	HVAC - Disassemble Chiller #1 and replace seals, gaskets, and O-rings. Chiller #1 leaks thru			22.012	01 14
122	FM-0053454	Los Angeles	Courthouse South	19-W1	2	deteriorated seals, gaskets, and O-rings. Chiller #1 is not operational due to the refrigerant leaks.		25,031 \$	22,813	91.14
						HVAC - Replacement of the (2) existing chillers at the Pasadena Court. Includes: new VFD drives,				
			Decedere			design/engineering, plan check, permits, inspections, new Refrigerant Monitoring System,				
122			Pasadena	10.11	2	exhaust fans, ACM abatement, interim P1 chiller maintenance, and engineering is being			(22,002	CO 25
123	FM-0053465	Los Angeles	Courthouse	19-J1	2	completed.	\$	899,772 \$	623,992	69.35
			Devener			Plumbing - Repair leaking hot water domestic pipe (3/4" Copper Pipe) includes ACM				
124			Downey	10 4 44	4	containment and environmental testing. Currently there is water leaking from the ceiling into		10.000	0.270	0.2.7
124	FM-0053466	Los Angeles	Courthouse	19-AM1	T	the 1st floor clerk's area.	\$	10,000 \$	8,370	83.7
			Edmund D.			Dlumbing (Creaked water pipe, Currently water is dripping from the solling into the 2nd floor				
125			Edelman	10.01	1	Plumbing / Cracked water pipe. Currently water is dripping from the ceiling into the 2nd floor	L C	10,000 6	6 000	60.00
125	FM-0053467	Los Angeles	Children's Court	19-Q1	1	secured hallway causing a hazard the employees.	Ş	10,000 \$	6,999	69.99
			Inglewood			HVAC - Replace return shaft and front and back bearings on AHU #2 and balance return fan.				
126	FM-0053471	Los Angolos	-	19-F1	1	Currently the 3rd floor has no return air and it is affecting the temperature on the entire floor.	¢	10.000 \$	7,456	74 56
120	FIVI-0055471	Los Angeles	Courthouse	19-г1	1	Currently the Std hoor has no return an and it is anecting the temperature on the entire hoor.	Ş	10,000 \$	7,450	74.56
			West Covina			County Managed - HVAC - Install four ductless air-conditioning systems in hallway to ensure the				
127	FM-0053472	Los Angeles		19-X1	2	court with adequate cooling in a consistent warm part of the building throughout the year.	4		84,255	100.00
127	FIVI-0033472	LUS Aligeles	Courtilouse	19-71	۷.	court with adequate cooling in a consistent warm part of the building throughout the year.	ې ا	84,255 \$	64,233	100.00
			Compton			HVAC - Replace defective VFDs to the return fans on the 10th and 12th floors. Currently both of				
128	FM-0053478	Los Angeles	-	19-AG1	2	the return fans are running at 100% causing air flow to be unbalanced and wasting energy.	¢	5,883 \$	3,890	66.13
120					2	HVAC - Remove and Replace (1) 15 HP VFD. Currently the VFD drive is tripping on common lose	ې ا	<u> </u>	5,650	00.15
			Chatsworth							
129	FM-0053479	l os Angeles		19-AY1	2		Ś	5 460 \$	4 5 7 5	83.80
123							Ŷ	<u> </u>	1,373	
						Plumbing - Failing Sewage Pump - Replace discharge piping on Pump #1 & #2 and replace floats.				
130	FM-0053480	Los Angeles		19-AZ1	1		Ś	14.392 \$	10.580	73.51
							+			
			Clara Shortridge							
			Foltz Criminal							
131	FM-0053481	Los Angeles	Justice Center	19-L1	2		\$	24,032 \$	16,532	68.79
							†	, - T	,	
						Plumbing - Demo and build back of wall after replacing cracked pipe, includes ACM containment				
			Van Nuys			and environmental testing. Currently water is dripping from the angle-stop in the wall of the				
132	FM-0053483	Los Angeles		19-AX1	1	woman's restroom onto the floor under the sink in the restroom creating a slip hazard.	\$	12,000 \$	10,769	89.74
130	FM-0053481	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse Clara Shortridge Foltz Criminal Justice Center Van Nuys	19-AY1 19-AZ1 19-L1 19-AX1	2 1 2 1	and environmental testing. Currently water is dripping from the angle-stop in the wall of the	\$	5,460 \$ 14,392 \$ 24,032 \$ 12,000 \$	4,575	73.5 68.7



						HVAC - Replace failed piping on condensate for the AHU includes ACM containment, leak					
			Pasadena			remediation equipment and environmental testing. Currently there is condensate water leaking					
133	FM-0053484	Los Angeles	Courthouse	19-J1	1	through the roof into room 209.	\$	10,000	\$	6,935	69.35
			Compton			Exterior Shell - Repair concrete and sure railing. Currently the exterior ledge railing located on					
134	FM-0053486	Los Angeles	Courthouse	19-AG1	2	the Westside of the building has broken concrete causing a safety hazard.	\$	4,944	\$	3,269	66.13
						Plumbing - Remove and replace all defective wye strainer and pressure reducer valves.					
			Chatsworth			Currently the water pressure is not regulated throughout the building and could cause the main					
135	FM-0053488	Los Angeles	Courthouse	19-AY1	2	pipes to break down, causing a flood.	\$	7,763	\$	6,505	83.80
						Interior Finishes - Replace defective vinyl floor tiles approx. 60 sq ft. Currently the vinyl tile					
			Compton			flooring is breaking and coming up off the floor. It is causing a trip and safety hazard on					
136	FM-0053489	Los Angeles		19-AG1	2	occupants.	\$	3,017	\$	1,995	66.13
			Edmund D.			Exterior Shell - Replace (2) 9' 11" x 9'7" heavy duty steel rolling doors with double angle foot					
			Edelman		-	piece and new motor operators with eclectic miller safety edges. Currently the rolling doors			4		
137	FM-0053490	Los Angeles	Children's Court	19-Q1	2	have broken spring and are not working properly.	Ş	13,239	Ş	9,266	69.99
			Clara Shortridge			Fire Protection - Repair (35) pull stations that failed to activate alarm during annual test and (1)					
120		Los Angolos	Foltz Criminal	10.11	2	fire bell that sounded poorly. This repairs must be completed before the annual fire alarm test	ć	16 275	¢	11 264	69 70
130	FM-0053491	Los Angeles	Justice Center	19-L1	Z	can be completed due to it being a safety issue. Plumbing - Replace defective sump pump and test for proper operation. Currently one of the	Ş	16,375	Ş	11,264	68.79
			Compton			sump pumps for storm water has failed and must be replaced. Heavy rain or any other form of					
139	FM-0053498	Los Angeles	•	19-AG1	2	heavy water going into basement area could cause flooding in Basement.	\$	14,634	Ś	9,677	66.13
135			Clara Shortridge	15 //01	2	Elevator - Install generator start up controls to all 23 elevators. This installation must be	Υ 	14,004	Υ 	5,077	00.15
			Foltz Criminal			completed to make sure the generator transfers power to the elevators in case of an emergency					
140	FM-0053499	Los Angeles	Justice Center	19-L1	2	as per the State Inspector and Fire Marshall. (Compliance Issue)	\$	6,573	\$	4,522	68.79
			Compton			Parking Lot - Install up to 50 feet of new 6" no hub piping. Currently the storm drain is cracked		,		,	
141	FM-0053500	Los Angeles	Courthouse	19-AG1	2	and the water drips on the cars parked in the parking garage.	\$	5,570	\$	3,683	66.13
						HVAC - Replace shaft and bearing on Air Handler Unit #9. Currently the Air Handler is being					
			Metropolitan			controlled manually and the motor had to be ramped down so no further damage would take					
142	FM-0053501	Los Angeles	Courthouse	19-T1	2	place. This repair is necessary due to this air handler provides air to the entire 8th floor.	\$	11,845	\$	11,198	94.54
						Elevators - Replace chicken legs for elevator #2 at the 2nd & 3rd floors and elevator #3 at the					
			Santa Monica		_	3rd floor. This repair must be completed to ensure the doors close as intended per DIR		_			
143	FM-0053504	Los Angeles	Courthouse	19-AP1	2	preliminary orders.	Ş	4,581	Ş	3,596	78.49
						HVAC - Install new bearings and sleeve on the blower shaft, remove deteriorated piping and					
			Clara Shortridgo			replace with new copper piping. Remove frozen isolation valves and replace with new butterfly					
			Clara Shortridge Foltz Criminal			valves. Replace Chilled Water line and insulation on the Chilled Water line. AHU 14-2 Vibrating					
111	FM-0053506	Los Angeles	Justice Center	19-L1	1	due to worn shaft and bearings on the blower, vibration caused water leak on Chilled Water piping, 2 isolation valves found seized and replaced.	ć	35,500	ć	24,420	68.79
144	1 101-0055500	LUS Aligeles		19-61		Plumbing - Replace failed and corroded flush valve assembly & pipe from above ceiling area.	ې ا	33,300	ې ا	24,420	00.79
						Water remediation, set up containments, disinfect area. Dehumidifiers and fans were placed to					
			Clara Shortridge			remove moisture in the leak affected area. Install new 1-1/2" Pneumatic Flush Valve Assembly,					
			Foltz Criminal			new pipe with fittings. Remove damage ceiling and build back. Water Leak/Flood on 3rd fl Dept.					
145	FM-0053507	Los Angeles		19-L1	1	41.	Ś	21,987	Ś	15,125	68.79
			Clara Shortridge			Plumbing - Install (3) VFDs, Pump Repairs, Pressure Sensors. Hot water pumps are leaking,	'	,- • ·	·		
			Foltz Criminal			pumps run 100% due to no VFD's. If pumps not repaired there will be no hot water to entire					
146	FM-0053508	Los Angeles		19-L1	1	building.	\$	47,144	\$	32,430	68.79
			Compton			HVAC - Clean tubes on Chiller #2, repair leaks, install new purge pump. Chiller is not working,					
147	FM-0053509	Los Angeles	Courthouse	19-AG1	1	building is hot.	\$	58,602	\$	38,754	66.13



						HVAC - Replace leaking valve on reheat coil above ceiling includes ACM containment and				
			Bellflower			environmental testing. Demo and rebuild failing ceiling areas . Water was dripping through the				
1/18	FM-0053510	Los Angeles		19-AL1	1	ceiling into the Woman's public restroom creating a slip hazard.	¢	10,000 \$	7,794	77.94
140		LOS Angeles					ې ا	10,000 \$	7,754	11.54
						HVAC / Rebuild leaking chilled water pump #23 includes ACM containment and environmental				
			Stanley Mosk			testing and abatement. Currently water is leaking through the seals and this is the second of the				
149	FM-0053511	Los Angeles		19-K1	1	three pumps available to circulate chilled water through the cooling loop for the HVAC.	Ś	10,000 \$	9,726	97.26
						HVAC - Replace leaking valve on reheat coil above ceiling includes ACM containment and	Ŧ			07.20
			Bellflower			environmental testing and abatement. Water was dripping through the ceiling into the court				
150	FM-0053512	Los Angeles		19-AL1	1	reporters office creating a safety hazard.	\$	10,000 \$	10,000	100
		0		_		Plumbing / Set-up containment, drying equipment, and conduct environmental testing.				
			Van Nuys			Currently water is dripping from the ceiling into the secure hallway on the 10 floor creating a				
151	FM-0053513	Los Angeles	, Courthouse West	19-AX2	1	safety hazard	\$	10,000 \$	8,048	80.48
		0				Plumbing / Replace failed 90 degree elbow behind the wall of the sink includes ACM		, ,	,	
			Stanley Mosk			containment and environmental testing. Currently water is dripping down from the 7th floor to				
152	FM-0053514	Los Angeles	Courthouse	19-K1	1	the 5th floor, room 546 court counsel room, damaging the ceiling tiles.	\$	10,000 \$	10,000	100
						Plumbing - Replace failed seal on janitors sink area on the second floor and replace		, ,		
						damaged/fallen ceiling tiles includes ACM containment and environmental testing. Water				
			Inglewood			spilled from Janitor's sink and the water leaked through to the 1st floor ceiling causing ceiling				
153	FM-0053515	Los Angeles	Courthouse	19-F1	1	tiles to fall on the lobby floor.	\$	10,000 \$	7,456	74.56
						Plumbing - Replace cracked drain pipe includes ACM containment and environmental testing.				
			Norwalk			Janitor closet on the 4th floor has cracked drain pipe, leaking water into 3rd floor secured				
154	FM-0053516	Los Angeles	Courthouse	19-AK1	1	hallway.	\$	10,000 \$	8,503	85.03
			Clara Shortridge			Plumbing - Set up sump pumps in tunnel to drain water, set up containment in lower gym, test				
			Foltz Criminal			for ACM, repairs were completed by County ISD. Steam leak (Flex line) in tunnel causing leak in				
155	FM-0053524	Los Angeles	Justice Center	19-L1	1	lower gym room B-302	\$	4,836 \$	3,327	68.79
						Plumbing / Set-up containment & drying equipment, conduct environmental testing, and				
			Stanley Mosk			insulate vent duct that is sweating causing a leak in the ceiling. This work was completed as a P1				
156	FM-0053526	Los Angeles	Courthouse	19-K1	1	emergency due to water leaking through the ceiling tiles above the entrance of room 258.	\$	8,937 \$	8,692	97.26
						Plumbing / Replace failed Sloan valve assembly includes ACM containment and environmental				
			Clara Shortridge			testing, vacuum all water in Dept.121 and sanitize carpet dry. Toilet continuously flushing				
			Foltz Criminal			causing water to flood the jury room, courtroom, and water to leak down to the 12 floor				
157	FM-0053527	Los Angeles	Justice Center	19-L1	1	hallway.	\$	10,087 \$	6,939	68.79
						Fire Protection - Replace fire pump motor, batteries, wiring, battery cables, and auto relays 3D5				
						& 4D2. This work was completed as a P1 emergency due to the motor starter failing (burning				
			Compton			up) causing the batteries and battery cables to fail as well as other wiring inside fire pump				
158	FM-0053530	Los Angeles	Courthouse	19-AG1	1	control cabinet.	\$	14,994 \$	9,916	66.13
						Holding Cell - Set-up containment and drying equipment, conduct environmental testing, secure				
			Clara Shortridge			water to cell #8, and auger/clear clogged toilet to stop water from overflowing. This work was				
			Foltz Criminal			completed as a P1 due to an inmate clogging his cell toilet causing water to overflow and leak				
159	FM-0053531	Los Angeles	Justice Center	19-L1	1	down to the 13th floor public hallway.	\$	10,225 \$	7,034	68.79
						Grounds and Parking Lot - Isolated control valve and replaced valve, pumped area to prevent				
			Stanley Mosk			water from entering the building. Landscaping control valve stuck open over the weekend				_
160	FM-0053532	Los Angeles	Courthouse	19-K1	1	flooding area, causing water to enter the building rm-119	\$	3,900 \$	3,793	97.26



		Compton			Plumbing - Flood Remediation - Set-up containment and drying equipment, conduct environmental testing, and replaced 40' of 4" cast iron sewer drain pipe, no-hub couplings, and					
161 FM-0053533	Los Angeles	-	19-AG1	1	miscellaneous fittings. Water is leaking into the basement from the cracked pipe.	\$	16,765	\$	11,087	66.13
		Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Interior Finishes / Set-up containment and drying equipment, perform environmental testing, remove ceiling tiles, and check for leak above cubicle. This work was completed as a P1 emergency due to an employee stating a leak was coming from the ceiling above her.	\$	5,406		3,719	68.79
163 FM-0053535		Clara Shortridge Foltz Criminal	19-L1	1	HVAC - 3 HP Exhaust Fan - Remove and replace the failing kitchen exhaust fan, the new fan will include a timer, for more efficient operation. The kitchen exhaust fan has a high vibration causing the exhaust fan to not work properly.	ć	14,998	ć	10,317	68.79
103 FIVI-0055555	LOS Aligeles	Justice Center	19-L1	T	causing the exhaust fan to not work properly.	Ş	14,998	Ş	10,517	08.79
		Clara Shortridge Foltz Criminal			Plumbing - Drain building cold water to 5th floor to stop leak, once secure Cut out section 2-1/2 copper that was leaking, installed ball valve with new 2-1/2 copper line and pro press secure Re-fill entire building and check all toilets, urinals for proper operation and repair as needed. Checked new plumbing for leaks, once cold water was filled. 5th Floor Women's public restroom					
164 FM-0053536	Los Angeles	Justice Center	19-L1	1	had leak in ceiling, located source leaking coming from 2-1/2 copper pipe cold water supply.	\$	19,350	\$	13,311	68.79
		Inglewood			Interior Finishes - Water remediation, set up containments, dry areas with proper drying equipment. Build back, replace ceiling tiles, floor tiles, drywall ceiling. Remove all debris associated within scope of work. Water leak from roof to 2nd flr court room # 241, 2nd flr men's					
165 FM-0053537	Los Angeles	Juvenile Court	19-E1	1	public restroom and the 1st flr court room # 240. Interior Finishes - Water remediation, set up containments, disinfect areas. Dehumidifiers/fans	\$	29,051	\$	23,467	80.78
100 5052520		Van Nuys	10.472	1	were placed to remove moisture in the leak affected areas. Remove drywall for access to drain pipe, remove and replace damaged drain pipe. Install drywall after pipe installation and complete finish work (painting and cove base). Tear out wet ceiling tile and replace ceiling tile (108 pcs). Cracked 2" black steel pipe leaking through walls on 10th floor down to the 9th floor	č	20.011	ć	20.025	90.49
166 FM-0053539	LOS Aligeles	Courthouse West	19-AX2	T	ceiling.	Ş	36,811	Ş	29,625	80.48
167 FM-0053541	Los Angeles	Santa Monica Courthouse	19-AP1	2	Interior Finishes - Set-up containment and drying equipment due to water leaking into Room 202B file storage room, conduct environmental testing, replaced 2 ft of 1 1/2" piping and fitting, replaced one 90 and coupling, repaired hangers and supports, and installed new ceiling tiles. Interior Finishes - Removal and disposal of loose and flaky paint and plaster from the 12th floor	\$	18,356	\$	14,408	78.49
168 FM-0053543	Los Angeles	Compton Courthouse	19-AG1	2	N/E stairwell, replaster approximately 30 sq ft. and color match paint. This is a slip hazard at the stairway	\$	2,889	\$	1,910	66.13
		Compton	10 4 6 4	2	Interior Finishes - Build containment 11X6 feet and removed and replace VCT floor tiles 12x12. Repair a piece of concrete on the 9th floor 4x4 feet. Currently there are floor tiles missing and some that are ready to break causing a trip hazard. Also, a small piece of concrete has broken off		0 774	ć	1.024	
169 FM-0053544	Los Angeles	Courthouse	19-AG1	2	causing a trip hazard. Plumbing / Set-up containment, conducted environmental testing, create larger access panel in	<u>ې</u>	2,774	<u>ې</u>	1,834	66.13
170 FM-0053553	Los Angeles	Compton Courthouse	19-AG1	1	restroom wall, and replaced the hot & cold isolation valve. This work was completed as a P1 emergency due to the valves breaking in the off position and the restroom having no access to water.	\$	9,249	\$	6,116	66.13
171 FM-0053556	Los Angeles	Bellflower Courthouse	19-AL1	1	HVAC - Removed the old, faulty External Float Switch and installed a New External Float Switch. Checked the Cooling Towers, Chillers, and Condenser Water Pumps to ensure the system is in normal working conditions. Building was very hot due to a faulty External Float Switch on the Cooling Towers. Chillers #1 and #2 were tripped due to restricted condenser water flow. This was a health and safety issue.	\$	2,348	\$	1,830	77.94



		East Los Angeles			HVAC - Replace Chilled Water Valve and piping, new insulation was wrapped on the new sections of piping. The chilled water valve for AHU # 4 seized up and would stroke properly. This caused the AHU to not cool properly. The chilled water piping adjacent to the unit was					
172 FM-0053557	Los Angeles	Courthouse	19-V1	1	deteriorated and leaked water.	\$	10,961	\$	8,519	77.72
		Van Nuwr			Plumbing - Drain building cold water to 5th floor to stop leak, once secure Cut out a 3' section of 2-1/2" copper line that was leaking, installed ball valve with new 2-1/2" copper line and pro press secure. Re-fill entire building and check all toilets, urinals for proper operation and repair as needed. Checked new plumbing for leaks, once cold water was filled. 5th Floor Women's public restroom had leak at the ceiling, isolated the leak coming from a 2-1/2" copper cold water supply pipe.					
		Van Nuys		1	water supply pipe. Extract water from bathroom floor, remove and replace approximately 16SF	Ċ	10 500			00.40
173 FM-0053560	Los Angeles	Courthouse West	19-AX2	1	of damaged drywall and seal and paint approximately 80 SF of the ceiling	Ş	19,588	Ş	15,764	80.48
		Pomona			Plumbing - Water remediation, set up containments, abated insulation from the pipes. Replaced deteriorated sections of pipe. New fiberglass insulation was wrapped on the new sections of pipes. Water supply and return water lines from buildings boiler system have multiple leaks, leaking is from deterioration of lines. This caused safety issues with electrical panels and slippery					
174 FM-0053562	Los Angeles	Courthouse South	19-W1	1	floor surfaces.	\$	66,361	\$	60,481	91.14
		Clara Shortridge			Plumbing - Set-up Containment, drying equipment, and conduct environmental testing.					
		Foltz Criminal			Currently water is dripping from the ceiling into the public hallway in front of the entrance Dept					
175 FM-0053565	Los Angeles	Justice Center	19-L1	1	32 courtroom causing a slip hazard.	\$	10,000	\$	6,879	68.79
		Whittier			Parking Structure - Replacement and installation of 20 gate drains in the upper parking structure. The homeless have stolen the floor drain covers for the upper levels of the parking area. This leaves a 10 inch by 24 inch gap for each one that is missing on the floor. This is a					
176 FM-0053566	Los Angeles	Courthouse	19-AO1	2	safety hazard.	\$	4,745	\$	4,101	86.43
177 FM-0053573	Los Angeles	Norwalk Courthouse	19-AK1	1	HVAC - Failing AHU #7 - Replace supply fan motor, variable frequency drive, pulleys, and fan belts. AHU #7 had a faulty bearing and the variable frequency drive is tripping on the ground fault protection. If the unit had failed completely, there would have been no air conditioning to the entire seventh floor, impacting the courts operations.	\$	14,071	\$	11,965	85.03
178 FM-0053577	Los Angeles	Stanley Mosk Courthouse	19-K1	2	<ul> <li>HVAC / Replace Pneumatic Air Compressor #3. Currently the air compressor has a seized which supplies air to the HVAC system and the building will not be able to control the air to the air handlers used to maintain comfort throughout the building.</li> <li>Grounds and parking lot - Restored operation to (1) Hy-Security HRG swing riser gate operators.</li> </ul>	\$	18,870	\$	18,353	97.26
179 FM-0053578	Los Angeles	Downey Courthouse	19-AM1	1	Removed and installed new hydraulic hoses, bled the system, removed and installed the new flow control valves, furnished and installed (2) new Reno AX-3 safety loop detectors, adjusted & checked for proper operation. The Sally port gates would not swing open and the custody bus could not leave the sally port.	\$	7,595	\$	7,595	100
		Norwalk			Plumbing - Ran fiber optic camera through the drain line in order to locate the stoppage and clear the drain line. Removed all debris and pumped water from sump pits to prevent water from backing up and causing a flood in the basement. The floor drain line in the basement got clogged not allowing water to drain properly. Water is pooling in the basement presenting a					
180 FM-0053579	Los Angeles	Courthouse	19-AK1	1	safety hazard to damage our electrical panels and a slipping hazard to ABM personnel.	\$	6,162	\$	5,240	85.03
		Norwalk			Elevators, Escalators, & Hoists - Control Panel - Replaced bad circuit that had a short and restored elevators 1-4 back to normal working conditions. Call Stations for Elevators 1-4 were not responding. The public as well as court employees were overcrowding and congesting public					
181 FM-0053580	Los Angeles	Courthouse	19-AK1	1	elevator lobbies on all floors. This was a safety and security hazard.	\$	2,239	\$	1,904	85.03



					HVAC - Remove, rebuild, then re-install fuel injector pump and reseal oil return line. The					
		El Monte			generator has leaks at both the oil return line and the fuel injector pump while under load.					
182 FM-0053581	Los Angeles	Courthouse	19-01	1	Hazards include possible fire due to the fuel igniting.	\$	11,801	\$	6,859	58.12
		Van Nuys			HVAC / Repair supply trunk lines and install new VFDs to AHU #21. Currently there is no A/C to					
183 FM-0053945	Los Angeles	Courthouse West	19-AX2	1	the 2nd floor Clerk's area creating uncomfortable work conditions for the employees.	\$	15,000	\$	12,072	80.48
					Roof - Perform a minor renovation to the buildings roof which will include repairing the					
					following components. Membrane, Blister & Drain Repairs - Main Deck. Blister & Penetration					
					Repairs -Penthouse. Pitch Pocket & Drain Repairs -Lower Decks. Membrane Repair, Condensate					
		Glendale			Drain -Rear Lower Deck. Clear Leaves -Lower Canopy. Insert Membrane Blanket -					
184 FM-0053946	Los Angeles	Courthouse	19-H1	2	Penthouse/Rear Lower Deck. Approx. 2,850 SQ/FT of repairs	\$	19,010	\$	17,212	90.54
					Roof - A minor roof renovation will be done to the following areas (Main Deck & Lower Deck).					
					Main Deck-Coated Area of Repair, Caulk Metal Laps, Caulk Stucco, Three-Course Ceramic Roof					
		Torrance			Drain, Reset Ladders. Lower Decks- Three-Course Hole in Membrane, Re-Caulk Perimeter Edge					
185 FM-0053947	Los Angeles	Courthouse	19-C1	2	Metal, Re-Caulk Counter-Flashing. Approx. 2,300 SQ/FT of repairs.	\$	15,145	\$	12,894	85.14
					Elevators, Escalators, & Hoists - Remove and replace worn out packing. Install new hydraulic					
					packing on the jack and make sure that all leaks are addressed properly. Replace and properly					
					disposed off old oil/fill system with fresh hydraulic oil. Elevator #3 has a worn out/leaking					
		Santa Monica			hydraulic jack packing. Oil is leaking on the floor and will burn out the motor if leak is not					
186 FM-0053949	Los Angeles	Courthouse	19-AP1	2	corrected.	\$	6,921	\$	5,432	78.49
					HVAC - Rebuild failed CW Pump #22, replace CW Pump motor, remediate ACM pipe insulation	-	-	-		
		Stanley Mosk			and replace. #22 Chilled water pump motor has bad bearings and pump does not provide					
187 FM-0054037	Los Angeles	Courthouse	19-К1	1	proper discharge pressure.	\$	27,382	\$	26,632	97.26
	<u> </u>									
					Grounds and Parking Lot - Motor Failure - Remove and replace damaged Sally Port Door with					
		Clara Shortridge			new Custom Built Door (The door is not of typical size). Install new tubing, hardware and re-wire					
		Foltz Criminal			controls/push button/card reader and assured door work for proper operation. Sally Port door					
188 FM-0054038	Los Angeles	Justice Center	19-L1	1	motor failed and the door dropped and was damaged beyond repair.	\$	106,109	Ś	72,992	68.79
		Inglewood			Elevator / Replace selector tape and sheave on elevator #1. Currently Elevator #1 is stuck on the	T		T		
189 FM-0054039	Los Angeles	Courthouse	19-F1	1	3rd floor with the doors closed and is not functioning.	Ś	10,000	Ś	7,456	74.56
				-	Roof - A minor roof renovation will be done to the following areas Pitch Pan Repairs, Roof Drain	<b>•</b>		Ŧ	.,	,
		Chatsworth			Repairs & Remove Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof is in fair condition at					
190 FM-0054042	l os Angeles	Courthouse	19-AY1	2	best.	Ś	23,482	Ś	19,678	83.80
150 110 005 +0 +2			15 //11	2		<u> </u>	23,402	<b>Y</b>	19,070	05.00
		Clara Shortridge			Exterior - Install and secure metal grills so the homeless will not enter areas beneath the facility.					
		Foltz Criminal			The homeless have accessed an area under the building leaving hazardous materials and trash,					
191 FM-0054047	Los Angeles	Justice Center	19-L1	1	under and around the building, creating contamination risks on the east side of the building.	¢	23,794	¢	16,368	68.79
191 110-0034047	LUS Angeles		19-61		Electrical - Water remediation, dehumidifiers and fans were placed to remove moisture in the	ې ا	23,734	ې ا	10,308	00.79
					affected area. HVAC -Restore Chiller operations; Plumbing - Restore pumps to full operations;					
					Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical					
		Domono			transformer short circuited causing power failure to the injector pumps to the building drainage					
		Pomona	10 \4/4	1	system that the current cooling tower drains into. As a result of loss of power the injector pumps	רא א	10 004	<u>ج</u>	AD 770	01 1 1
192 FM-0054048	LOS Angeles	Courthouse South	19-001		were not online.	<b>&gt;</b>	46,931	<u>ې</u>	42,773	91.14
		Roverly Hills			Dlumbing / Sot up containment Conduct Environmental Tecting, and realized fittings for the 2					
		Beverly Hills	10 001	1	Plumbing / Set-up containment, Conduct Environmental Testing, and replace fittings for the 2	4	10 000	ć		
193 FM-0054051	LOS AUgeles	Courthouse	19-AQ1		1/2" domestic cold water supply line that is leaking. Water leak has been isolated and contained	·   구	10,000	Ş	7,952	79.52



						Plumbing / Set-up Containment, drying equipment, shampoo carpet, clean upholstery, &					
			Alhambra			replace ceiling tiles. Currently there is water dripping from the snack bar into the basement call					
104	FM-0054054	Los Angeles		19-11	1		ć	10,000	ć	8,600	86
194	1101-0034034	LUS Aligeles	Courthouse	19-11		center. Plumbing / Set-up containment, conduct environmental testing, and replace cracked 4" main	ې ا	10,000	ې ا	8,000	
			Indowood								
105			Inglewood	10 51	1	cast iron drain pipe in ceiling. Water dripping from the ceiling into the self help center on the 1st	4		4	0.220	
192	FM-0054055	Los Angeles	Courthouse	19-F1	1	floor. Currently the leak from the ceiling has been contained.	\$	12,500	Ş	9,320	74.56
						Electrical - Trace electrical wires to assure there are not shorts in system. Currently the lights in					
100			Van Nuys	10 11/2		Rooms 233, 237, & 238 will not function even though there is electrical power going to the	~	7 500		7 500	100
196	FM-0054057	Los Angeles	Courthouse West	19-AX2	1	space.	Ş	7,500	Ş	7,500	100
			Clara Shortridge			Plumbing / Set-up Containment, disinfect area, set-up Drying equipment, and conduct					
			Foltz Criminal			environmental testing. Currently water is dripping into the 15th floor, public hallway from the	.				
197	FM-0054058	Los Angeles	Justice Center	19-L1	1	employee's Men's restroom on the 16th floor.	\$	10,000	\$	6,879	68.79
						Plumbing - Water remediation, set up containments, contain leaking, and dried leak affected					
			Pasadena			areas. Water leaking from 4th floor through to the ceiling on 3rd floor, Room 319 Public					
198	FM-0054059	Los Angeles	Courthouse	19-J1	1	Defender's Office.	\$	10,000	\$	10,000	100
			Clara Shortridge			Grounds / Replace burnt out motor, bottom guide rail, and bent/broken rods. The gate came					
			Foltz Criminal			down on top of the bus transporting the in-custodies creating a safety situation since the gate					
199	FM-0054060	Los Angeles	Justice Center	19-L1	1	no longer opens correctly.	\$	10,000	\$	10,000	100
						Plumbing / Replace broken toilet, replace telephone, and repair holes in wall. Currently an	1				
			Torrance			inmate has torn out the phone for the holding cell, broken the toilet, and punched holes in the					
200	FM-0054061	Los Angeles	Courthouse	19-C1	1	wall creating a safety situation for all deputies.	Ś	10,000	Ś	10,000	100
						Roof - Replace Missing Vent Caps. Approx. 200 SQ/FT of repairs. / Roof is in poor condition.	T	/	T		
			Alhambra			Immediate removal & replacement is recommended. IF removal & replacement is not done,					
201	FM-0054068	Los Angeles		19-11	2	immediate maintenance is strongly recommended.	¢	2,247	Ś	1,932	86.00
201	110-0034008	LUS Aligeles	Courthouse	1.7-11	2	Roof - Perform a minor renovation to the buildings roof which will include repairing the	ې ا	2,247	ې ا	1,552	80.00
						following components. Re-Caulk Lead Flashings, Clear Loose Granules From Roof Surface, Repair					
			Airport								
202			Airport	10 111	2	Expansion-Joint Hole & Re-Tighten Roof Drains. Approx. 1,500 SQ/FT of repairs / Roof system is		10.011		7 7 7 5 6	77 47
202	FM-0054069	Los Angeles		19-AU1	2	in poor to fair condition at best.	\$	10,011	\$	7,725	77.17
			Michael D.								
			Antonovich			HVAC - Replaced vane actuator shaft control pre-rotation device, vane actuator and associated					
			Antelope Valley			linkages. Installed (3) new gaskets and (3) new 0-ring seals, and recharged Chiller. Compressor					
203	FM-0054076	Los Angeles	Courthouse	19-AZ1	1	on the chiller not functioning due to a failed vane actuator to the vane linkage arm.	\$	36,461	\$	26,802	73.51
						Elevators, Escalators, & Hoists - Replace bearings, motor shaft and Exciter Armature, restore					
			Metropolitan			elevator to normal operations. Judge's elevator #12 bearings over heated. Elevator was on the					
204	FM-0054077	Los Angeles	Courthouse	19-T1	1	8th floor and out of service.	\$	40,730	\$	40,730	100
						Plumbing - Excavate concrete around meter vaults and planter in front of the courthouse to					
						expose water line. Sidewalk removed. Installed new copper piping, valves, and regulators. New					
						sidewalk poured, dirt removed is replaced. Water Main Leak under sidewalk and into planter,					
			Burbank			vault containing the water meters was flooded. Additional leak located in the planter area					
205	FM-0054078	Los Angeles	Courthouse	19-G1	1	coming from a clay-valve and gate valve.	\$	43,324	\$	39,321	90.76
							1				
						Interior Finishes - Water remediation, set up containments, dehumidifiers and fans were placed					
						to remove moisture in the leak affected areas. ACM & Bacterial testing & clearance. Install new			1		
			Clara Shortridge			Cast iron pipe with fittings and install support hangers for pipes to meet current building codes.			1		
			Foltz Criminal			Major drain line water leak on the 7th floor; areas affected due to this water leak include			1		
206	FM-0054079	l os Angeles	Justice Center	19-L1	1	secured hallways, court rooms, judge's chambers, restrooms, and clerk's areas.	\$	46,803	Ś	32,196	68.79
200					1		<u>۲</u>	-0,003	<u>ب</u>	52,130	00.75



	l l l l l l l l l l l l l l l l l l l	T		1		Interior Finishes Water remediation, set up containments, restroom wall enaned up to make			<u> </u>		
						Interior Finishes - Water remediation, set up containments, restroom wall opened up to make					
						repairs, wall repaired to match existing. Replaced failed valve with copper pipe and fittings.					
			Metropolitan			Replace damaged ceiling tiles and install access panel. Water leak in Judges rest room on the 6th					
207	FM-0054080	Los Angeles	Courthouse	19-T1	1	floor, water leak also affected Dept. #66 on the 5th floor.	Ş	29,852	Ş	28,222	94.54
						HVAC - Water remediation, set up containment, contain leaking, and dried leak affected area.					
						Replace floor drain and pipe in ceiling. Replace 2 custom Chilled Water Coils including copper					
						piping. Build back of Snack Bar area including drywall and paint to match existing paint. 2nd					
						floor Mechanical Room floor drain is cracked and leaking into the ceiling below. Also the coils on					
			Norwalk			AHU-2 have deteriorated and are leaking on the floor of the Mechanical Room and seeping					
208	FM-0054081	Los Angeles	Courthouse	19-AK1	1	through to the ceiling below.	\$	75,210	\$	63,951	85.03
						Plumbing - Set-up containment, conduct environmental testing, and replace leaking portion of					
			Glendale			domestic hot water pipe. Currently water is dripping from the ceiling of the traffic clerk's area					
209	FM-0054084	Los Angeles	Courthouse	19-H1	1	creating a safety hazard.	\$	12,500	\$	11,318	90.54
						Plumbing - Set-up containment, conduct environmental testing, and replace cracked drain pipe.					
			Metropolitan			Currently water is dripping from the ceiling into the 8th floor Jury office room causing a safety					
210	FM-0054088	Los Angeles	Courthouse	19-T1	1	hazard.	\$	10,000	\$	9,454	94.54
						Parking Lot - Restore bent grill and rods on main roll-up gate. The gate was hit by a car and is not				-	
			Compton			operational which is a safety hazard for the employees and staff of the courthouse. The vehicle					
211	FM-0054089	Los Angeles	•	19-AG1	1	has not been identified at this time.	Ś	10,000	\$	6,613	66.13
						HVAC - Repair (3) non-functioning domestic hot water boilers. Currently there is no hot water	T		T	-,	
			Van Nuys			supply throughout the entire building. This includes showers and faucets, not allowing judges					
212	FM-0054091	l os Angeles	Courthouse West	19-AX2	2	and employees to shower.	\$	4,999	\$	4,023	80.48
			Torrance	10 7 0 12		Elevator / Replace malfunctioning door edge sensor. Door edge sensor not sensing when	Υ 	1,000	Υ 	.,020	
213	FM-0054094	Los Angeles		19-C1	1	someone was in the door way and closing which was causing a safety situation.	Ś	2,474	Ś	2,106	85.14
			Van Nuys			Electrical - Replaced failed generator 3/8" fuel line and placed generator back into service. Fuel		_,			
214	FM-0054095	l os Angeles	Courthouse East	19-AX1	1	line broke while generator was running (outage due to DWP power issues).	\$	2,606	\$	2,339	89.74
			Bellflower	10 / 0/1	-	Elevator - Replace buffer circuit boards on top of the elevator car. Currently the elevator is not	Υ 	2,000	Ŷ	_,	00171
215	FM-0054096	Los Angeles		19-AL1	1	stopping on the designated floors which is causing a safety situation.	Ś	10,000	Ś	7,794	77.94
213	1101 003 4030				-	Plumbing - Water Leak - Set-up containment, conduct environmental testing, and located the	<b>→</b>	10,000	<b>→</b>	7,754	11.54
						source of leak, removed and replaced a 15' section of 4" cast iron that had cracked. Removed					
			Metropolitan			and replaced approximately 10 wet ceiling in storage room 3 and where water dripped through					
216	FM-0054097	Los Angeles	-	19-T1	1	the ceiling tiles in storage room 4.	¢	10,000	¢	9,454	94.54
210	1101-0034037		Airport	1.7-1.1	-	Exterior Finishes / Replace panic hardware on ADA front entrance doors. Currently the doors are	ې ا	10,000	ې ا	5,454	54.54
217	FM-0054098	Los Angeles		19-AU1	1	not securing at night making the courthouse unsafe.	ć	5,000	ć	3,859	77.17
217	1101-0034038	LUS Angeles	Courthouse	13-A01			ې ا	5,000	ې ا	3,833	//.1/
			Torrance			Plumbing / Replace malfunctioning toilet in 5th floor lock up area. Inmate clogged the toilet and					
210		Los Angolos		10 C1	2			2 2 2 5	ć	2 2 2 5	100.00
210	FM-0054099	Los Angeles	Courthouse	19-C1	2	flooded the lock up area on the 5th floor and water ran down to the 4th floor Dept P courtroom.	Ş	2,325	Ş	2,325	100.00
						HVAC - Replace (3) Variable Frequency Drives to the cold deck, hot deck and return fan. This					
240			Van Nuys	10 41/2		work was completed as a P1 emergency due to the 9th floor not having any heating which made		0.040	~	7 7 6 2	00.40
213	FM-0054100	LOS Angeles	Courthouse West	19-AX2		it uncomfortable for the visitors and employees.	>	9,646	>	7,763	80.48
						Plumbing - Set-up containment, conduct environmental testing and drying equipment, replace					
						angle stops from the 5th floor Jury restroom. This work was completed as a P1 emergency due					
						to water leaking from the 5th floor Depart 420, Jury Restroom into the 4th floor lawyer's					
			Van Nuys		_	interview room, the audience seating adjacent to the lawyer's interview room, and the jury			4		_
220	FM-0054102	Los Angeles	Courthouse East	19-AX1	1	room.	\$	15,851	Ş	15,851	100



221FM-0054104Los AngelesAirport Courthouse19-AU11Plumbing - Replace leaking cap for the 4" domestic cold water supply pipe. Water leaking into the pump room which could become a flood if the work is not completed immediately.\$2,466\$221FM-0054104Los AngelesCourthouse19-AU11the pump room which could become a flood if the work is not completed immediately.\$2,466\$241FM-0054104Los AngelesFPlumbing / Set-up containment, conduct environmental testing, replace 3" cracked pipe leaking from ceiling into the secure hallway adjacent from the DA's office, replace damaged drywall, and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and ceiling tiles. This work was completed as a P1 emergency due t	1,903 77.17 0,301 80.48 2,320 100
Van NuysPlumbing / Set-up containment, conduct environmental testing, replace 3" cracked pipe leaking from ceiling into the secure hallway adjacent from the DA's office, replace damaged drywall, and ceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and leaking water into the secure hallway creating a slip and safety hazard.\$ 12,800 \$222 FM-0054105Los AngelesCourthouse West19-AX21leaking water into the secure hallway creating a slip and safety hazard.\$ 12,800 \$223 FM-0054107Los AngelesCourthouse19-AD11the base of the toilet and sink creating a slip hazard.\$ 2,320 \$223 FM-0054107Los AngelesCourthouse19-AD11the base of the toilet and sink creating a slip hazard.\$ 2,320 \$	0,301 80.48 2,320 100
Image: state of the state of	2,320 100
Image: state of the state of	2,320 100
A logVan Nuysceiling tiles. This work was completed as a P1 emergency due to a sewage pipe cracking and Los AngelesSanta ClaritaSanta ClaritaSanta ClaritaPlumbing - Replace faulty control valve to toilet in the men's lock-up area. Water leaking from the base of the toilet and sink creating a slip hazard.Santa ClaritaSanta ClaritaSant	2,320 100
222FM-0054105Los AngelesCourthouse West19-AX21leaking water into the secure hallway creating a slip and safety hazard.\$12,800\$23FM-0054107Los AngelesSanta ClaritaPlumbing - Replace faulty control valve to toilet in the men's lock-up area. Water leaking from\$2,320\$23FM-0054107Los AngelesCourthouse19-AD11the base of the toilet and sink creating a slip hazard.\$2,320\$1Interior Finishes / Replace broken and loose floor tiles in the 1st floor snack bar. Currently theImage: Courter of the court of the secure hallway creating a slip hazard.\$1Image: Court of the court of the secure hallway creating a slip hazard.\$2,320\$	2,320 100
223FM-0054107Los AngelesSanta Clarita CourthousePlumbing - Replace faulty control valve to toilet in the men's lock-up area. Water leaking from the base of the toilet and sink creating a slip hazard.\$ 2,320\$20FM-0054107Los AngelesCourthouse19-AD11the base of the toilet and sink creating a slip hazard.\$ 2,320\$1Interior Finishes / Replace broken and loose floor tiles in the 1st floor snack bar. Currently the1111	2,320 100
223       FM-0054107       Los Angeles       Courthouse       19-AD1       1       the base of the toilet and sink creating a slip hazard.       \$ 2,320       \$         4	
223       FM-0054107       Los Angeles       Courthouse       19-AD1       1       the base of the toilet and sink creating a slip hazard.       \$ 2,320       \$         4	
Compton floor tiles are beginning to break and loosen up from the floor creating a trip hazard to the staff	
224 FM-0054112 Los Angeles Courthouse 19-AG1 2 and the public. \$4,844 \$	3,203 66.13
HVAC - Water remediation, set up containments, contain leaking, disinfect and dried leak	· · · · · · · · · · · · · · · · · · ·
affected area. ACM testing. 8 sq. ft. of ceiling tiles were removed and replaced. Installed new	
custom manufactured hot water and chilled water coils along with new piping, and a new	
custom manufactured stainless steel drain pan and pipe. Replace 4 gate valves and replace	
Pomona insulation from piping. Water leak from 2nd floor air handler room, is going into 1st floor lobby	
	6,249 91.14
HVAC - Replace Pneumatic control valves and actuators AHU-1 & AHU-2. Control valves are	
broken and non-operational. There is no way of controlling the cooling at these units because of	
Compton this issue. Also the chilled water isolation valves and bypass valves are non-operational at this	
	9,304 66.13
Exterior Shell - Replace sally port door. The gate was struck by a vehicle and found on the	
Pasadena ground off of the track which causes a security concern due it being where they drop off the in	
227 FM-0054118 Los Angeles Courthouse 19-J1 1 custody visitors.	6,935 69.35
	· · · · · · · · · · · · · · · · · · ·
Plumbing - Water Leak - Set-up containment, drying equipment, and conduct environmental	
testing. Removed and replaced one broken hose bib, remove and replace approximately 35 sf of	
San Fernando damaged plaster ceiling and 100sf of plaster walls. Water from the janitorial sink ran down from	
228 FM-0054119 Los Angeles Courthouse 19-AC1 1 the 4th floor to the 2nd floor effecting rooms 4046, 4045, 3096, 3095, 2102, & 2104. \$ 10,000 \$	8,341 83.41
Plumbing / Construct containment, set-up drying equipment, conduct environmental testing,	· · · · · · · · · · · · · · · · · · ·
and replace fallen ceiling tiles. Initial work will be conducted under hot conditions until testing	
Compton results are received. Water leaked from the janitorial hose from the 11th floor down to the 8th	
229 FM-0054120 Los Angeles Courthouse 19-AG1 1 floor. \$ 12,500 \$	8,266 66.13
Norwalk Exterior Shell / Replace closing mechanism on exit doors. Currently the doors are not retracting	
230 FM-0054121 Los Angeles Courthouse 19-AK1 1 and locking automatically which is causing a security concern. \$ 5,000 \$	4,252 85.03
Plumbing - Flood Water Mitigation - Construct containment, conduct environmental testing, and	
replaced a 5 foot section of 2 inch cracked drain line and replaced one 2x2 ceiling tile in room	
Stanley Mosk 106 which has a 14 foot ceiling.	
231 FM-0054122 Los Angeles Courthouse 19-K1 1 \$ 10,000 \$	9,726 97.26
Plumbing / Set-up containment, drying equipment, conduct environmental testing, and replace	
Norwalk ceiling tiles. Water leaked from an overflowing toilet in the 3rd floor men's public restroom	
232 FM-0054123 Los Angeles Courthouse 19-AK1 1 through the ceiling into the 2nd floor room 206R which created a safety situation. \$ 10,000 \$	8,503 85.03



		Deve deve			HVAC - Set Up Containment, heppa Vacuum, change out filters, and abate loose fire proofing.					
		Pasadena	10.14		Loose fire proofing was found in the air filters of AHU #2 which could have caused a health and	~	10.000	~	6.005	CO 25
233 FM-0054124	Los Angeles	Courthouse	19-J1	1	safety issue. Elevator - Install (1) emergency battery back-up power supply unit for the 110 volt elevator cab	\$	10,000	\$	6,935	69.35
					lighting circuit on each elevator. The installation will entail the mounting of the power supply					
					unit on the elevator car top, piping and wiring between the power supply unit and the					
					emergency light fixture mounted in the ceiling area of the elevator cab, and piping and wiring to					
		Alhambra			the car top alarm bell. This unit will activate during loss of supply power to the emergency light					
234 FM-0054128	Los Angeles	Courthouse	19-11	2	and emergency alarm bell	Ş	15,819	Ş	13,604	86.00
					Plumbing - Water remediation, set up containments, secure water supply and disassemble Sloan					
		Clara Shortridge			assembly, re-build removed all calcium, installed new 3.5 master re-build kit with master					
		Foltz Criminal			vacuum break re-build kit. 4th floor Cell #1 Sloan assembly has calcium build up causing leak					
225 514 005 4120			10.11	1		ć	11 400	ć	7017	69 70
235 FM-0054130	LOS Angeles	Justice Center	19-L1	1	when flushed in pipe chase. causing flood to 3rd floor in front Dept.32.	Ş	11,400	Ş	7,842	68.79
					Elevators, Escalators, & Hoists - Build containment and enclose basement elevator door area,					
		Pasadena			wiped clean and set up negative air machine. Replace brake coil Judge's elevator #5. Brake coil					
236 FM-0054131	Los Angeles	Courthouse	19-J1	1	in Judge's elevator has failed. Elevator was shut down for safety reasons and locked out.	\$	7,679	\$	5,325	69.35
					HVAC - Water remediation, set up containments, vacuumed carpets to remove water and dried		,		- ,	
					leak affected rooms. Replace ceiling tiles. Water leaked on the floor of the central plant from					
		East Los Angeles			chiller. The water seeped thru the concrete floor and leaked into the 3rd floor offices 301S and					
237 FM-0054132	Los Angeles	_	19-V1	1	301T. The water damaged ceiling tiles in both offices.	Ś	5,635	Ś	4,380	77.72
		Inglewood			HVAC - Remove defective 15HP motor. Installed new 15HP motor, drive pulley, bushing and 3	Ŧ	-,	Ŧ	.,	
238 FM-0054133	Los Angeles	Courthouse	19-F1	1	new B79 belts. Cooling tower fan motor not operational.	\$	3,493	\$	2,604	74.56
					Plumbing - Water remediation, set up containment, and remove existing failed copper water				,	
		Van Nuys			supply line and replace it. Water leaking from pipe within space between floors above women's					
239 FM-0054134	Los Angeles	Courthouse East	19-AX1	1	restroom.	\$	12,186	\$	10,936	89.74
					HVAC - Replace compressors, condenser fan motor, and evaporator coil. Repair leak in the 1st					
					stage and charge with refrigerant. This work was completed as a P1 emergency due to Package					
					Unit #1 had a grounded compressor, the other had bad valves, and a faulty condenser fan					
		Norwalk			motor. The first stage refrigerant was also flat. The evaporator coil had an internal restriction					
240 FM-0054135	Los Angeles	Courthouse	19-AK1	1	inside the metering devise. The unit was not supplying cooling to the elevator mechanical room.	\$	15,610	\$	13,273	85.03
		Tarranaa			Durphing Deplete analysed 2 holt toilet with 4 holt toilet. The toilet was analysed and was about					
		Torrance	10.01	2	Plumbing - Replace cracked 3 bolt toilet with 4 bolt toilet. The toilet was cracked and was about	<u>ج</u>	4 0 2 1	<u>ج</u>	4 405	05 14
241 FM-0054138	Los Angeles		19-C1	2	to break off the wall and needed to be replaced for the safety of the visitors to the restroom.	<u>ې</u>	4,821	\$	4,105	85.14
242 ENA 0054170	Los Angolos	Inglewood	19-F1	1	Plumbing - Replace failed domestic hot water heater, no hot water to all public restrooms. Need to restore hot water.	ć	1 200	ć	2 5 7 0	74 56
242 FM-0054179	LOS Angeles	Courthouse Downey	19-г1		Elevators, Escalators, & Hoists - Dismantle generator, remove, rebuild, and reassemble. Elevator	Ş	4,800	Ş	3,579	74.56
243 FM-0054180	l os Angeles	Courthouse	19-AM1	2	#3, generator #2 failed and needs to be rebuilt.	Ś	37,042	Ś	31,004	83.70
	2007.1180103				HVAC / Replace motor for cooling tower #2 and diagnose VFDs for Cooling Towers 1 & 2.	· ✓	57,072	<u>۲</u>	51,007	03.70
		East Los Angeles			Currently the motor has failed and could affect the cooling for the courthouse. The VFDs have					
244 FM-0054181	Los Angeles	Courthouse	19-V1	1	been placed out of auto due to the trouble that must be diagnosed.	\$	10,000	\$	7,772	77.72
					Roof - Install guardian roof railing system including (30) ground plates, (15) 10 safety rails, (11) 6	· 	,	-	,	
		Monrovia Training			safety rails & painted safety striping to comply with Cal-OSHA fall protection / Current roof is					
1 1	1		19-N1		missing guard rails for fall protection.	\$		1		



						HVAC - Abate ACM Fireproofing and restore valve to allow water flow into the cooling towers.					
			Pasadena			Chiller #2 when off line due to high head pressure. The cause of the high head pressure was low					
246	FM-0054188	Los Angeles		19-J1	1	water level in the cooling towers.	\$	9,263	\$	6,424	69.35
	SWO-		Edmund D. Edelman Children's Court -			Elevator - Elevator Renovation - Complete renovation of two (2) traction and one (1) hydraulic elevators. Work will include but not be limited to, car frames and platforms, buffers and safeties, hoist way entrance frames, doors and pit equipt., new AC gearless machines, micro-processor control systems, regenerative VVVF AC drives, fly ball governors, current code required wiring, interior and lobby control panels, car and hall door panels with new doors, counterweights and roller guides, hoist and governor ropes, cab ceilings with LED down lights, rope compensation, new submersible pump units and underground cylinders encased in PVC for					
247	1368822	Los Angeles	Parking Structure	19-Q2	2	hydraulic elevators, and seismic provisions. Install new machine room air conditioning.	Ş	934,670	Ş	747,736	80.00
248	FM-0054129		Madera County Superior Court	20-A1	1	HVAC - Remove the two defective fire tubes and install two new tubes in their place. Once the new tubes are in place they will be rolled to create the seal. After the tubes have been rolled and the seal created; a Hydro-static test will be performed to insure that the new tubes and the remaining tubes will hold pressure and the boiler has no further leaks. The price will include the ASME documentation and the installation of a new fire gasket on the main access panel.		4,075	\$	2,934	72
			County			HVAC - Replace failed blower motor on boiler #2 and replace pump #2 on the vacuum					
249	FM-0053032	Mendocino	Courthouse	23-A1	2	condensate return.	\$	7,078	\$	4,786	67.62
250	FM-0053570	Mendocino	County Courthouse	23-A1	2	Electrical - Change Lighting - change 6 recessed 8"x8" lights to new single tube 4' florescent fixture in ground floor Hallways, fixture to be security type as this hallway is used for transportation of in-custody individuals. Current lighting not compliant with holding standards. Safety - Prep and patch any areas of spalled concrete under building eves, prime and finish paint the entire area under the soffits and the fascia/front face of the roof overhangs - The underside of the existing eaves have several areas that are showing signs of the concrete spalling that	\$	5,365	\$	3,628	67.62
251	FM-0051815	Merced	Old Court	24-A1	2	could fall onto passers-by below.	\$	42,611	\$	42,611	100.00
252	FM-0052867		New Downtown Merced Courthouse	24-A8	2	Security - Replace the Hirsch Velocity computer, update software, provide new PC server, flash memory to all control panels - The control access computer Hirsch velocity is outdated, damaged and needs to be replaced. Computer has been damaged throughout the years and software is not working correctly.	\$	16,193	\$	16,193	100.00
253	FM-0052916	Merced	New Downtown Merced Courthouse	24-A8	1	Exterior Shell - Saw cut and jack hammer concrete, replace failed pipe and fittings There is a very large water leak on the system Exterior Shell - Remove existing entryway storefront doors size 9-51/2 w x 9-2 H with a single	\$	2,405	\$	2,405	100.00
254	FM-0053019	Merced	Old Court	24-A1	2	emergency exit storefront door size 76 W x 86 H. The New door will be equipped with emergency exit hardware. The existing door has a long history of sticking open when exiting and causing a security breach to the courthouse. Work would include build side and top area with CMU block to replace the existing glass size 9-51/2 w X 9-2 T. SMW	\$	21,437	\$	21,437	100.00
			Salinas			Electrical - Install (3) 2 X 4, T-8 3-LAMP 18CELL FIXTURES in judges chamber. Judge is					
255	FM-0053429		Courthouse- North Wing	27-A1	2	experiencing headaches from eye strain - doctors note and light readings indicate inadequate lighting in room.	Ś	3,191	Ś	3,191	100.00
			Marina Courthouse	27-B1	2	Roof - Replace failed built up roof (8500 sq ft), steep slope shingled roof (7500 sq ft), and rotted gutters (600 sq ft) - due to deterioration and blisters, there is evidence of water intrusion into the building.	\$	533,940		533,940	100.00



			Salinas								
			Courthouse-			Fire Protection - Replace failed NAC 4 unit on Fire Annunciator Panel. Program and perform					
257	FM-0053944	Monterey	North Wing	27-A1	2	operational testing of new NAC.	\$	3,565	\$	3,565	100.00
			Criminal Court			HVAC - AC Unit/Compressor #1 - Remove and replace the failed discharge gasket and O-ring on					
258	FM-0052913	Napa	Building	28-A1	2	Compressor #1	\$	4,074	\$	4,074	100.00
						Earthquake Remediation - Work includes; Lead and mold remediation, restoring operating					
						systems to their original condition, document restoration, perimeter fencing, fire watch, fire					
						alarm and fire sprinkler assessments, domestic water restoration and isolation valves installed					
						between buildings 28-B1 and 28-A1, replace failed fire alarm panel and sentry-one (71) devices,					
						utilities restoration; install isolation valve on the natural gas line to separate buildings 28-A1 and					
						28-B1, restoration of the buildings plumbing infrastructure, re-secure the existing water heater,					
						verify the operating systems of the mechanical units, replace or provide new damaged light					
			Napa Historic			fixtures, damaged switch gear and replace the hydraulic jack packing on the hydraulic					
259	FM-0053463	Napa	Courthouse	28-B1	1	passenger elevator.	\$	1,000,000	\$	939,900	93.99
						Earthquake Remediation - Work includes; Isolate and remediate three water leaks within the					
						building, replace multiple damaged light fixtures, secure loose wiring, relocate court equipment,					
			Criminal Court			fixtures and materials to new location for Court Operations and restore elevators to proper					
260	FM-0053464	Napa	Building	28-A1	1	operation.	\$	500,000	\$	500,000	100.00
						Earthquake Restoration - Interior Finishes - Replace damaged fire sprinkler heads, carpet and					
						ceiling tile. Patch, paint and seal cracked wall, ceiling and baseboard surfaces throughout					
261	FM-0054065	Napa	Juvenile Court	28-C1	1	building.	\$	50,000	\$	50,000	100
						Fire Protection - Annual PM of stand pipe and sprinklers did not pass due to failed equipment					
						elements. The project requires replacement of 19 missing escutcheons, inspector butterfly					
			Central Justice			valve with chain lock (space 80), 90 fire hoses, and tamper switch at inspector butterfly valve					
262	FM-0052810	Orange	Center	30-A1	2	(space 62/63).	\$	9,097	\$	8,294	91.17
			North Justice			HVAC - Remove and replace failed AHU-2 motor with new 40 HP 1730 RPM 324 Frame 460V					
263	FM-0052845	Orange	Center	30-C1	2	Motor.	Ş	7,434	Ş	6,714	90.31
			North Justice			HVAC - Remove and replace failed AHU-1 motor with new 40 HP 1730 RPM 324 Frame 460V	-		4		
264	FM-0052846	Orange	Center	30-C1	2	Motor.	Ş	7,434	Ş	6,714	90.31
						HVAC - Cooling Tower on roof does not have a Variable Frequency Drive (VFD). It has a manual					
						Mag Starter. Replace the Mag Starter with a 20 HP ABB 3R VFD. New VFD to be installed in a					
205		0	North Justice	20.01	2	weather-tight enclosure. The VFD will be more efficient and will save energy as it can be		10 1 11	~	0.450	00.24
265	FM-0052847	Orange	Center	30-C1	2	programmed to the BAS system.	\$	10,141	\$	9,158	90.31
			North Instigo			Electrical - Replace 5 failed high-pressure sodium wall-pak lighting fixtures in the secured judicial					
200		0.000	North Justice	20.01	2	parking lots with 64W LED Wall-Pak lighting fixtures. The LED lighting will give more hours of	4		~	4 2 2 2	00.21
266	FM-0052848	Orange	Center	30-C1	2	light than the standard bulb currently used.	Ş	4,787	\$	4,323	90.31
207		0.000	North Justice	20 C1	2	HVAC - Remove and replace failed AHU-6 motor with a new 25 HP 1775 RPM 284 T Frame	4	F 01F	ć	4 5 2 0	00.21
267	FM-0052849	Orange	Center Harbor Justice	30-C1	2	motor.	Ş	5,015	Ş	4,529	90.31
						Fire Protection Fire Alarm Panel Replace newer supply resulting from over 20 recorded					
260		Orango	Center-Newport	20 51	2	Fire Protection - Fire Alarm Panel - Replace power supply resulting from over 20 recorded	ć	10 700	ć	0 106	01 27
208	FM-0052853	Orange	Beach Facility	30-E1	<u> </u>	trouble instances, perform follow-up system inspection, and return to service. Remove eroded soil from drainage field along the South side of the building (approximately	Ş	10,799	ې ا	9,106	84.32
			West Justice			1009 sq. ft.) and replace with 1" gravel, Two inches thick, to prevent ground and surface water					
260		Orango		20 01	2		ć	6 1 2 0	ć	5 5 5 0	00.68
209	FM-0052879	Orange	Center Betty Lou	30-D1		from penetrating and damaging the building. HVAC - Air Handler #8 - Remove and replace failed 60hp supply fan motor that services all floors	ې ا	6,120	ې ا	5,550	90.68
			Lamoreaux Justice			of the South West section of the building. There was loss of cooling in this area that required					
270	FM-0052929	Orange	Center	30-B1	2	immediate replacement.	Ċ	4,920	¢	3,934	79.95
270		Unange		10-01	2		Ş	4,320	ې ر	5,554	19.93



						Fire Protection - Fire Hoses - Replace 10 each of 11/2" by 75' fire hoses, during annual			
			Central Justice			inspection fire hoses failed hydro test and need to be replaced before annual and 5 year			
271	FM-0052930	Orange	Center	30-A1	2	certification can be completed.	\$ 4,100	\$ 3,738	91.17
						Conveyances - Remove and replace non-functioning detention chairlift; replacement parts are			
						no longer available for the current lift. The project will include a new inclined wheelchair lift to			
			West Justice			be installed in place of the existing lift along with a new battery backup and hydraulic drive. This			
272	FM-0052944	Orange	Center	30-D1	2	is a noted safety and ADA deficiency; specifications and proposals are attached.	\$ 43,155	\$ 43,155	100.00
						Conveyances - Elevator #1 hydraulic feed line is leaking. Work will include shutting off oil line			
			North Justice			and replacing damaged sections of pipe and pipe joint, reopen oil line, and testing operation of			
273	FM-0052994	Orange	Center	30-C1	2	elevator before placing back in service.	\$ 6,323	\$ 5,710	90.31
			North Justice			Fire/Life/Safety - "Knox" Key - Install code required "Knox" key override into gate system for			
274	FM-0053009	Orange	Center	30-C1	2	secured parking areas per State Fire Marshals inspection.	\$ 3,900	\$ 3,522	90.31
						HVAC - replace two near failure roof mounted economizer fans with new Domex belt driven			
			West Justice			centrifugal units. Both are prone to frequent failure requiring excessive maintenance to retain			
275	FM-0053419	Orange	Center	30-D1	2	operational condition.	\$ 9,384	\$ 8,509	90.68
						Grounds & Parking Lot - Remediate and treat the metal gates to the Secure Parking Lot to			
			West Justice			prevent further deterioration and failure due to rust. Evidence of invasive rust is present			
276	FM-0053420	Orange	Center	30-D1	2	throughout	\$ 8,429	\$ 8,429	100.00
						Grounds - Raised Concrete - Saw cut and remove approximately 105 sq. ft. of concrete sidewalk			
						that became uneven as a result of tree roots. Remove tree roots as necessary, construct new			
			West Justice			sidewalk and apply broom finish. Trip hazard/safety risk to employees and court tenants who			
277	FM-0053449	Orange	Center	30-D1	2	use sidewalk to gain access to courthouse.	\$ 3,007	\$ 2,727	90.68
						HVAC - Variable Frequency Drive (VFD) - Replace the existing 20 HP Return Fan VFD with a new			
						ABB 20 HP VFD. The existing VFD has three blown fuses and has ceased to function properly in			
			Betty Lou			automatic mode. The VFD is currently in bypass mode to run at 100% capacity all the time. The			
			Lamoreaux Justice			VFD controls the Return Fan for AHU #8 and needs to be replaced to avoid disruption to			
278	FM-0053517	Orange	Center	30-B1	2	operations and prolong the life of the equipment. Related JO 1361775.	\$ 6,933	\$ 5,543	79.95
			North Justice			HVAC - Replace failing cooling tower manual Mag Starter with 40 HP ABB 3R VFD in a weather-			
279	FM-0053545	Orange	Center	30-C1	2	proof enclose.	\$ 13,946	\$ 12,595	90.31
						Vandalism - Remove existing window film where necessary, clean interior glass surface, and			
						install high performance window film to 433 panels of glass on south, east, and west facing			
						exterior windows. The window tinting throughout the building is faded, torn in places, has			
			North Justice			etched graffiti in places, and is in generally poor shape. Installation of new window tint is an			
280	FM-0053546	Orange	Center	30-C1	2	energy-cost saving project.	\$ 52,563	\$ 47,470	90.31
						HVAC - Replace the failing A/C Package Unit that serves the Sheriffs locker room and basement			
			West Justice			areas. Deterioration of the coils and indoor fan motor/compressor makes system unable to			
281	FM-0053564	Orange	Center	30-D1	2	maintain space temperature.	\$ 6,628	\$ 6,010	90.68
						HVAC- Replace the failed Variable Frequency Drive (VFD) for Air Handler Unit #5 with a new 20			
			North Justice			HP ABB VFD with Johnson NE, Siemens FLN, MODBUS RTU, and BACNET Controls embedded in			
282	FM-0054067	Orange	Center	30-C1	2	drive.	\$ 6,222	\$ 5,619	90.31
				1		Holding Cells - Rehabilitate a large section of wall in the detention hallway that exhibits large			
			West Justice			cracks. There are approximately 32LF of large random cracks that need to be filled with Slka 31			
283	FM-0054127	Orange	Center	30-D1	2	Epoxy Grout. This work is to be completed during non-working	\$ 3,500	\$ 3,500	100.00



						Grounds and Parking Lot - Remove approximately 1,620 SF of existing 6 inch concrete, re-grade					
						for bus clearance and water flow, pour new 6 inch thick concrete with No. 4 rebar at 18 inch on					
						center in both directions at 4,000 PSI. Existing Driveway is steep and uneven. The Sheriff bus					
			North Justice			scrapes along the driveway every day as it drives into/out of the bus bay. Water run-off from the					
284	FM-0054185	Orange	Center	30-C1	2	street pools along the bottom of the driveway contributing to the deficiency.	\$	33,818	Ś	30,541	90.31
						Exterior Shell - Replace 54 wood windows - 80% of the windows in the historic courthouse have	· ·	00,010	Ŧ	00,012	
						failed due to dry rot and wear, and are beyond repair. The balance of the windows are showing					
						signs of wear and will soon be in disrepair. Window replacement will prevent further damage to					
			Historic			the interior finishes and the courthouse structure related to water and pest intrusion.					
285	FM-0002953	Placer	Courthouse	31-A1	2	Replacement windows will reduce impact to courts operations.	Ś	1,025,200	Ś	789,404	77.00
			South Placer		-	HVAC - Install new 3 ton Split HVAC system for Electrical room E0034 - Reduce run time on 27	· ·	_,==;===;===	Ŧ	,,	,,,,,,,
286	FM-0053448	Placer	Justice Center	31-H1	2	ton chiller by 108 hours per week	\$	11,708	\$	11,708	100.00
				01111	-	Fire Protection - Correct deficiencies identified during 5 year system inspection and Fire Marshal	· ·	11),00	Ŷ	11,700	100.00
						inspection - Remove and replace three (3) 300psi gauges, five (5) non compliant sprinkler heads,					
			South Placer			five escutcheons, fire caulk two (2) areas of wall penetration and install a hydraulic placard at					
287	FM-0053470	Placer	Justice Center	31-H1	2	the fire riser. Current installation does not meet code requirements	\$	14,451	Ś	14,451	100.00
207					-	HVAC - Burnt Compressor - Remove and replace Air Handler #1 compressor, the existing		1,131	Ŷ	1,131	100.00
			South Placer			compressor grounded out and was smoking causing the system to go into alarm and shutting					
288	FM-0054063	Placer	Justice Center	31-H1	1	down.	\$	28,932	Ś	28,932	100
200	1101 003 1003		Portola/Loyalton	51 111		Grounds and Parking lot- Irrigation system is leaking and flooding grounds in several areas.		20,552		20,552	100
289	FM-0052983	Plumas	Court	32-B2	2	Replace failed valves and piping. Add valves if required.	Ś	8,147	¢	8,147	100.00
205	1101 0052505				2	HVAC - Cooling Tower - Remove and replace drift eliminators of the building's cooling tower in		0,147	7	0,147	100.00
						cells 1 & 2. The existing eliminators are beyond their lifecycle and if not replaced will result in					
						failure of the HVAC system. Due to the failed eliminators water coming from the condensers is					
						getting to the chillers at a higher temperature than needed, resulting in the chillers working					
						harder and tripping off on high condenser temperature. Install new CTPC150 Counter Flow					
200	FM-0052822	Riverside	Hall of Justice	33-A3	1	Eliminators, 20 new NK-23	ć	27,473	¢	27,473	100.00
290	1101-0052822			33-A3		Lighting - Main Lobby - Arch Ceiling - Remove and retrofit 18 canned 400w mercury vapor bulbs	ې ا	27,475	ې ا	27,475	100.00
						and ballasts with new 100w LED, 5500k cluster. Currently nearly half of the bulbs are dead and					
						in need of replacement. The lights are housed in the second floor arched ceiling and require a lift	-				
						to replace the mercury vapor bulbs. LED replacement would allow change out from above lights					
						via a catwalk. Mercury bulbs and ballasts last approx. 20k hours, while LED will increase the life					
201	FM-0053421	Pivorsido	Hall of Justice	33-A3	2		ć	7,369	ć	7 260	100.00
291	FIVI-0055421	Riverside	Carol Miller	55-A5	2	to 50k HVAC - Replace pillow block bearings for cooling tower fan - Chillers cannot run without cooling	Ş	7,509	Ş	7,369	100.00
202	FM-0054044	Sacramonto		24 D1	2		ć	2 5 0 2	¢	2 502	07 75
292	FIVI-0054044	Sacramento	Justice Center	34-D1	2	tower fan, chillers trip out on high head	Ş	3,583	Ş	3,502	97.75
						HVAC - Removed damaged Variable Frequency drive for cooling tower #1 50 HP fan motor.					
			Juvenile		1	Replace with new Drive ABB Model # ACH550-UH-072A-4 - Variable Frequency drive controls					
202		Sacramonto		24 (2)	2		ć	0 711	¢	0 211	100.00
293	FM-0054090	Sacramento	Courthouse	34-C2	2	fan speed which regulates the water temperature required for chillers to function correctly.	>	8,211	Ş	8,211	100.00
			Needles			COUNTY MANAGED- Parking Lot - Demo approximately 56,265 SF of existing asphalt paving that					
		San	Courthouse-Dept.			is beyond repair, re-grade demo area, and resurface with new asphalt paving. The parking lot is					
201	EN4_0052402				2		Ċ	100 /21	ć	100,431	100.00
294	FM-0052402	Bernardino	N-1	36-K2		severely cracked and with several pot holes creating a trip hazard to the public.	Ş	100,431	Ş	100,431	100.00



					Electrical - Install power receptacles in 14 locations with additional empty data receptacles next	Τ				
					to each power receptacle. Power and data receptacles are needed to accommodate new kiosks					
		Victorville			and monitors that are due to be installed by the Court. New self help kiosks and monitors will					
	San	Courthouse-Dept.			help improve check-in processes caused by increased traffic due to nearby court closures and					
295 FM-0052883	Bernardino	•	36-L1	2	reduced staff.	Ś	3,868	Ś	3,868	100.00
					Elevators, Escalators, & Hoists - Replace the failed selector switch in public elevator #1 as well as	<u> </u>	0,000	Υ 	5,000	100.00
					the selector switch in public elevator #2 which is problematic and near failure. This work is					
	San	San Bernardino			necessary to return public elevator #1 to service and to increase both elevators reliability to					
296 FM-0052890	Bernardino		36-A1	2	prevent possible future entrapments.	¢	8,863	\$	8,477	95.64
				<u> </u>	Roof - Remove and Replace Roof - Remove and replace approximately 26,000 SF of existing ACM		0,005		0,477	55.04
					roof material. Scope includes a 3rd party Hygienist to monitor the abatement, removing					
	San	Barstow			damaged seal around building, replacing counter flashing and pipe / vent flashing at various					
297 FM-0052909	Bernardino		36-J1	2	locations.	ć	580,000	ć	451,994	77.93
297 FIVI-0032909	Demarumo		20-11		Electrical - Install power receptacles in 14 locations with additional empty data receptacles.	- <del></del>	380,000	Ş	431,994	77.93
		Rancho			Power and data are needed to accommodate self-help kiosks and monitors. Equipment will					
	San									
	San	Cucamonga		2	alleviate significant check-in processes backlog caused by increased traffic stemming from court		0.040	~	0.040	100.00
298 FM-0052945	Bernardino	Courthouse	36-F1	2	closures and staff reductions.	>	9,940	\$	9,940	100.00
					Interior Finishes - Replace failed lights. Remediate lead dust containing debris from the back of a					
	San	San Bernardino			horizontally suspended stained glass window. The grand stairwell is dimly lit creating a safety					
299 FM-0052946	Bernardino	Courthouse	36-A1	2	hazard. Scaffolding required.	Ş	5,669	Ş	5,422	95.64
					COUNTY MANAGED- Parking Lot- Saw cut, demo and replace approximately 30,000 SF, 4 inch					
					depth, of asphalt, slurry seal and re-stripe. Construct concrete sidewalks, curbs and drainage for					
	San	Joshua Tree			proper egress and rain run-off. Currently the asphalt in the parking lot has numerous cracks, pot					
300 FM-0053005	Bernardino	Courthouse	36-E1	2	holes, and uneven areas that pose a tripping hazard.	\$	120,000	\$	120,000	100.00
					COUNTY MANAGED- Exterior Shell- Reseal & repaint the exterior of the building approx-					
		Needles			15,400SF. Existing paint is dull, cracking and exposing the block. Work is necessary to prevent					
	San	Courthouse-Dept.			water intrusion in the rainy season. Scope includes clean & pressure wash walls, seal & repair					
301 FM-0053007	Bernardino	N-1	36-K2	2	cracks, and paint.	\$	12,100	\$	12,100	100.00
					Exterior Shell - Replace and seal failed roofing material which occurred during recent rains					
	San	San Bernardino			affecting Department 50. Replace damaged ceiling tiles and extract water from carpets in					
302 FM-0053011	Bernardino	Courthouse	36-A1	1	affected areas.	\$	4,682	\$	4,478	95.64
					Roof - Seal under interior counter flashing of (3) existing roof drain sumps, seal the outside of					
					the scuppers, install new down spouts, and install 5 roof vent caps and tighten 5 existing. 3					
	San	San Bernardino			existing roof drains are leaking, work is needed to prevent additional roof leaks which where					
303 FM-0053418	Bernardino	Courthouse	36-A1	2	observed during recent torrential rains	\$	5,169	\$	4,944	95.64
					Interior Finishes - Restore damaged concrete sub floor - Perform initial ACM testing, remove a 6'	<u> </u>	,		,	
					X 9' section of carpet over the affected area. Remove the failing concrete section of sub floor in					
		Rancho			the 6' X 9' area. Level concrete sub floor and install approximately 54SF of new carpet. All work					
	San	Cucamonga			to be performed after-hours. The damaged floor patch beneath the carpet is near the attorney's					
304 FM-0053422	Bernardino	•	36-F1	2	table and is a trip hazard.	Ś	5,817	Ś	5,817	100.00
		San Bernardino	5011		Roof - Cut and reseal roof blisters. Seal multiple roof penetrations, fabricate and install (3) drain		5,017		3,017	100.00
	San	Courthouse -			baskets, and install vent covers on 11 roof vents. This work is necessary in order to prevent					
305 FM-0053447	Bernardino	Annex	36-A2	2	future roof leaks.	ć	3,558	ć	3,401	95.58
505 1110-0055447			JU-AZ	<u>ک</u>		<u>ې</u>	2,000	ې ا	5,401	53.38
	San	Fontana			HVAC - Install a new 1.5 ton split system that serves the 2nd floor A/V room. The current split					
206 ENA 0052452			26 01	<b>_</b> _		¢	7 7 / 1	ć	7 7/1	100.00
306 FM-0053452	Bernardino	Courthouse	36-C1	2	system has failed, has a bad compressor as well as an un-repairable leak on the evaporator coil.	<u>ې</u>	7,241	Ş	7,241	100.00



					COUNTY MANAGED - Grounds- Remove dead grass, trees, plants, and old landscape materials,					
					level mounds & holes in dirt area, and replace with gravel / dryscape to meet current city water					
		San Bernardino			restrictions. Existing area is currently a trip hazard due to the unevenness of the dirt & debris					
	San	Courthouse -			and also a fire hazard due to the dead landscape and dryness of the area as a result of missing					
307 FM-0053482	Bernardino		36-A2	2	irrigation.	Ś	16,375	\$	16,375	100.00
					Roof - Leak remediation. Replace pipe seals, fabricate and install 12 drain screens, seal and coat	Ŷ	10,070	Ŷ	10,070	100100
					white (2) splits, install 360LF of walk pads around mechanical equipment, vents, and drains.					
	San	Fontana			Replace old asphalt repairs/coat with white coating at N&S wall tie-in, 80' tie-in, (3) vent					
308 FM-0053518	Bernardino		36-C1	2	flashings, and 3 pipe flashings.	Ś	11,934	Ś	9,921	83.13
					HVAC - Correct inadequate airflow resulting from additional heat load (staff and IT equipment)	Ŧ		Ŧ	-,	
					following court reductions and realignment of resources. Tie into ductwork after existing VAV.					
					Install 35' of rigid 12" ductwork, 80' of flexible 12" ductwork, 25' of 10" flexible duct work, (1)					
					balancing damper, (1) new VAV box with Belimo actuator, and (1) thermostat. Provide and					
	San	San Bernardino			install power from existing 120V junction box and connect to transformer. Insulate all ductwork					
309 FM-0053558	Bernardino		36-A1	2	and support all rigid duct	Ś	16,634	Ś	15,909	95.64
				_		Ŷ	10,001	<b>•</b>	10,000	55101
					Grounds and Parking Lot - Relocate (3) irrigation controllers (currently without power). Install (1)					
					new 24 zone controller to serve all zones and tie to JCC controlled electrical circuit. The existing					
					controllers are located in County managed areas and are powered by County circuits. Power has					
	San	Fontana			been disrupted for almost 4 weeks as a result of County work. The landscaping is currently dying					
310 FM-0054056	Bernardino		36-C1	2	and will result in significant replacement costs if the irrigation system is not restored soon.	Ś	4,475	Ś	3,720	83.13
						Ŧ	.,	<b>•</b>	0)/ 20	00120
					Elevator - Elevator Renovation - Complete renovation of Nine (9) gearless traction elevators.					
					Work will include but not be limited to, car frames and platforms, buffers and safeties, hoist way					
					entrance frames, doors and pit equip., new AC gearless machines, micro-processor control					
					systems, regenerative VVVF AC drives, governors (elevators 1,2&3 only), closed loop heavy duty					
					high speed operators, current code required wiring, interior and lobby control panels,					
		East County			counterweights and roller guides (Elevators 7&9 only), hoist and governor ropes, cab ceilings					
311 FM-0011923	San Diego	Courthouse	37-11	2	with LED down lights, rope compensation and seismic provisions.	Ś	3,494,260	Ś	2,817,422	80.63
						Ŷ	0)101)200	<b>•</b>	_,;;_,;=_	00.00
		County			Elevators, Escalators, & Hoists - Check encoder, Hoist motor brushes, tighten all I/O, Drive 23					
312 FM-0052821	San Diego	Courthouse	37-A1	1	faults. Change out card rack. Operational problems with elevator responding to service calls	\$	4,963	\$	3,842	77.42
	U	North County					,		,	
		Regional Center -			HVAC - Replace chilled water valve, and back flush evaporator coil. AHU S-11 is not producing					
313 FM-0052840	San Diego	Vista Center	37-F2	2	cool air. Court staff feels uncomfortable at times.	\$	3,977	\$	2,674	67.24
	<u> </u>				Elevators, Escalators, & Hoists - Elevator technician to adjust controller, drive and door				,	
		County			operating equipment. This work will enhance the overall operation of both elevators. On going					
314 FM-0052850	San Diego	Courthouse	37-A1	2	issues with the operation of number seven and eight Judge's elevators.	\$	5,178	\$	5,178	100.00
		County			Elevators, Escalators, & Hoists - Refurbish escalators 1-2 and 2-1 to bring back into service by		,		,	
315 FM-0052858	San Diego	Courthouse	37-A1	2	replacing the worn step rollers.	\$	7,766	\$	6,012	77.42
		East County			Elevators, Escalators, & Hoists - Remove and replace the existing elevator hoist, the hoist is	1				
316 FM-0052872	San Diego	<b>Regional Center</b>	37-11	2	worn and the elevator could become disabled due to current condition.	\$	14,791	\$	10,015	67.71
		South County			Interior Finishes - Repair and replace various area of carpet. Carpets are worn, torn, have snags					
317 FM-0052878	San Diego	<b>Regional Center</b>	37-H1	2	and is separating from concrete flooring. This is a trip hazard. (Jury Lounge, Public waiting)	\$	4,937	\$	1,769	35.84



						HVAC - Replace number one and two condensate return pumps. Waste make up water and					
			County			chemicals, cause excessive make up water for the boiler feed system. Condensate leaking all					
318	FM-0052951	San Diego	Courthouse	37-A1	1	over the floor, Safety hazard.	Ś	5,350	Ś	4,142	77.42
							Ŧ	-,	Ŧ	.,	
						COUNTY MANAGED - Grounds - A condition assessment has shown that the underground					
319	FM-0052957	San Diego	Hall of Justice	37-A2	2	parking garage is in need of restriping. There are approximately 478 parking spaces to restripe.	Ś	4,520	Ś	1,819	40.24
						COUNTY MANAGED - Fire Protection - The existing fire suppression system's post indicator valve	т	.,	T		
			South County			(PIV) is badly deteriorated and needs to be replaced along with the addition of a tamper switch					
320	FM-0052959	San Diego	, Regional Center	37-H1	2	and replacement of fire main shut off valve and check valve.	\$	26,377	\$	26,377	100.00
			County			HVAC - Replace complete pump end. Boiler two feed pump is leaking from both ends, wasting	,	,		,	
321	FM-0052965	San Diego	Courthouse	37-A1	2	chemicals. Number two boiler is the main boiler. and no back up feed pump.	\$	4,944	\$	3,828	77.42
						Fire Protection - Fire Alarm System-system has code required upgrades based on State Fire		-			
						Marshal Correction Notice. Install four (4) pull station installations; tie-in two (2) existing tamper					
						switches to Notifier panel; install two (2) enunciators (1 each) for Sheriff and Engineering office;					
			County			install two (2) new smoke detectors in lobby of North tower and two (2) horns / strobes in					
322	FM-0052995	San Diego	Courthouse	37-A1	2	holding areas.	\$	29,049	\$	22,490	77.42
			North County								
			Regional Center -			COUNTY MANAGED - Grounds - Gate Failure - Restore the failing motorized gate back to normal					
323	FM-0052996	San Diego	South	37-F1	2	operating standards.	\$	3,599	\$	3,599	100.00
			East County			HVAC - Replace Chiller #1 600 amp main breaker. Breaker supporting Chiller #1 is worn out and					
324	FM-0053012	San Diego	Regional Center	37-I1	1	not operational.	\$	13,735	\$	9,300	67.71
			East County			Elevators, Escalators, & Hoists - Removed worn out sheave bearings and installed new sheave					
325	FM-0053021	San Diego	<b>Regional Center</b>	37-l1	1	bearings in place. Elevator is making too much noise and disrupting court.	\$	14,748	\$	9,986	67.71
						HVAC - Removed and replaced 15 HP Variable Frequency Drive and Variable Frequency Drive					
326	FM-0053033	San Diego	Juvenile Court	37-E1	1	enclosure fan. AHU #1 not working and affecting depts. 6, 7 and 8.	\$	5 <i>,</i> 428	\$	4,050	74.62
						Plumbing - Replace failed Sloan Flushometer. Water remediation, set up containments, Extract					
						water from carpets throughout affected area. Disinfect/deodorize area. Set multiple					
						dehumidifiers throughout chambers until dry. Test carpet/walls before final clean up and					
			County			returned furniture back in place. Flooding occurred throughout Judges' chambers 51 and 50 and					
327	FM-0053425	San Diego	Courthouse	37-A1	2	entering chambers' 38 restroom ceiling.	\$	12,164	\$	12,164	100.00
			East County			Elevators, Escalators, & Hoists - Remove existing generator, rewire and rebuild, install back into					
328	FM-0053438	San Diego	Regional Center	37-l1	2	place. Elevator #3 generator needs to be rebuilt, stopped working.	\$	13,131	\$	8,891	67.71
						Elevators, Escalators, & Hoists - Failing Motor Starter - Install new Solid State Starter, reducing					
329	FM-0053441	San Diego	Juvenile Court	37-E1	2	potential damaging high inrush current and starting torque. Motor starter is worn and failing.	\$	4,337	\$	3,236	74.62
			North County								
			Regional Center -								
			Department 34			Roof - Install fall protection/guardrail system in areas of fall risk. The rooftop air conditioners are					
330	FM-0053455	San Diego	Trailer	37-F4	2	too close to the edge of the roof. Roof requires fall protection rails.	\$	4,489	\$	4,489	100.00
			North County								
			Regional Center -								
			Department 35			Roof - Install fall protection/guardrail system in areas of fall risk. The rooftop air conditioners are					
331	FM-0053457	San Diego	Trailer	37-F5	2	too close to the edge of the roof. Roof requires fall protection rails.	\$	4,489	\$	4,489	100.00
			County		_	Plumbing - Replace 20 section of failed cast iron pipe and a 10 section of copper pipe, fittings		_	4		
332	FM-0053497	San Diego	Courthouse	37-A1	2	and bands.	\$	4,173	Ş	3,231	77.42
			County		_	HVAC - Replace Power Modular Equipment Controller (MEC). Units will not operate in	_ ۱	<b>-</b>	<u>ــــــــــــــــــــــــــــــــــــ</u>	•	
333	FM-0053503	San Diego	Courthouse	37-A1	1	automatic. Departments 4 and 5 temperature was too warm.	\$	8,753	Ş	6,777	77.42



					Electrical - Lights and Ballast - Remove and properly dispose of 15 burnt out lights and failed				
		County			ballast, and replace with new T-8 lights and ballast. Various lights are burned out in Department				
334 FM-0053525	San Diego	Courthouse	37-A1	2	28, Safety and trip hazard.	¢	6,232 \$	6,232	100.00
554 110-0055525		North County	37-AT	2	Holding Cell - Replace touch screen "in custody" door control monitor - The touch screen	ې ا	0,232 9	0,232	100.00
		Regional Center -			operation of the door monitoring system is not functioning/freezes. This prevents automatic				
	San Diago		27 52	2		ć	10.240 6	10.240	100.00
335 FM-0053528	San Diego	Vista Center	37-F2	2	opening and closing of certain holding cell doors.	Ş	10,349 \$	10,349	100.00
		East County			HVAC - Remove and replace evaporator and condenser with new. Split unit in Civil Business				
336 FM-0053529	San Diego	Regional Center	37-11	2	Office IT room non-functional. IT equipment could be damaged due to excessive heat in room.	Ś	5,612 \$	3,800	67.71
	Sun Diego				Exterior Shell - Repair the exterior damaged grout of 4 existing carrot wood brick planters.	<u> </u>	<u> </u>	3,000	07.71
					Damaged or loose bricks on planters need to be repaired to prevent bodily injury, this is an				
337 FM-0053540	San Diego	Juvenile Court	37-E1	2	immediate safety risk.	Ś	2,262 \$	1,688	74.62
557 110 0055540	Sun Diego	North County			Fire Protection - Refurbish 5 Fire Doors, re-wire and re-string, tighten all loose mountings and		2,202 9	1,000	74.02
		Regional Center -			fasteners, lube all points of friction, balance and align doors. The fire curtains are not operating.				
338 FM-0053568	San Diego	Traffic Annex	37-F3	2	Curtains will not drop in a fire alarm event.	¢	4,699 \$	4,699	100.00
			5715	2	HVAC - Secure HVAC vent with additional ceiling hangers and replace broken ceiling tiles in grid.	<u>ې</u>	<del>ب</del> (250, <del>+</del>	+,055	100.00
					The ceiling air vent outside of D-5 in public corridor are loose and at risk of falling, this is a safety				
339 FM-0054049	San Diago	luvonilo Court	37-E1	2		د د		2 001	7460
559 FIVI-0054049	San Diego	Juvenile Court	57-ET	2	concern. Exterior Shell - Elevator 4B replaced Power Supply Board, ran car and verified, tested okay.	Ş	2,682 \$	2,001	74.62
		County		1		ć		2 206	77 40
340 FM-0054050	San Diego	Courthouse	37-A1		Elevator not responding to call, stuck on 2nd floor, getting stuck on random floors.	Ş	2,965 \$	2,296	77.42
		County		2	HVAC - Replace failing blower motor and place system back in service. Motor is failing and need			2 424	400.00
341 FM-0054071	San Diego	Courthouse	37-A1	2	to be replaced before it fails. This units supplies D-24 and D-25.	Ş	3,434 \$	3,434	100.00
					Interior Finishes - Set up containment, ACM testing/clearance, replace drywall, and remount the	2			
					light fixture. Suspended ceiling light fixture fell in northwest end of basement. A portion of the				
		Kearny Mesa			plaster from ceiling's hard lid broke loose, due to potential ACM disturbance a containment was				
342 FM-0054092	San Diego	Traffic Court	37-C1	1	set-up and environmental testing performed.	\$	4,498 \$	4,498	100
					Elevators, Escalators, & Hoists - Replaced step roller wheels and tightened up guide plates.				
		County			Escalator 2-3 is thumping in operation, step roller wheels need replacement. Loose guide plates				
343 FM-0054117	San Diego	Courthouse	37-A1	2	are tearing up step rollers.	\$	2,252 \$	1,743	77.42
					HVAC - Replace condenser fan motors and blades, also installed new wires to motors for AHU				
		Kearny Mesa			#2. Tested and placed unit back in operation. HVAC #2 not providing cool air. Two condenser				
344 FM-0054198	San Diego	Traffic Court	37-C1	1	fans went out at the same time, need to replace.	\$	3,413 \$	3,413	100
					HVAC - Replace the upper section of the heating hot water (HHW) and chilled water (CHW) coils				
	San	Civic Center			on AHU #4, balance the supply fan (SF) on air handler (AHU) #3, increase the max CFM from 759	0			
345 FM-0053948	Francisco	Courthouse	38-A1	2	to 100%, achieve duct static pressure from 1.13" to 1.5", and provide vibration analysis report.	\$	57,707 \$	57,707	100.00
					Safety- Install handrails along main entry handicap ramp. Court customers are currently				
		Manteca Branch			stepping off high points at middle and end of upper ramp into flower beds. (this is a safety				
346 FM-0052936	San Joaquin	Court	39-C1	2	issue). Drop at mid-point is >24", Drop at end of upper ramp into flower bed is >12"	\$	4,242 \$	4,242	100.00
		Manteca Branch			Plumbing - Cut out all old solder fittings and failed fittings and replace with pro press fittings -				
347 FM-0053462	San Joaquin	Court	39-C1	2	Old fittings are failed and causing leaks throughout older section of courthouse.	\$	10,706 \$	10,706	100.00
					COUNTY MANAGED - Roofing - Remove existing multilayer roofing, including ACM substrate,				
					under Cooling Tower and Pumps; install 3 layer, urethane/glass mat fabric roofing system,				
					approx 900 Sq/Ft and apply masonry damp-proofing to existing stucco walls - Continuing roofing	S			
348 FM-0052815	San Mateo	Hall of Justice	41-A1	2	patches have failed to correct multiple location leaks resulting in Court operation disruptions.	\$	65,875 \$	65,875	100.00



			Municipal Court			HVAC - Replace Ten (10) failed hot water reheat coils, associated valves and piping at New Wing					
			Building -			side - Active and temporarily remediated leaks at (7) coils; (3) additional coils clogged and					
349	FM-0054074	San Mateo	Northern Branch	41-C1	2	inactive	Ś	88,703	Ś	73,810	83.21
						Roof - Installation of roof rail system for lower section (North) of Building G - safety concern for	Ŧ		Ŧ		
		Santa	Santa Maria			roof access to skylight and exhaust fans (1, 15 & 16). Parapet walls do not comply with OSHA					
350	FM-0052824	Barbara		42-F5	2	requirements for safe access to the work space.	Ś	9,775	Ś	9,432	96.49
					_	Exterior Shell - Reapply Water Sealant is required to maintain non-slip texture of footpath:	+	0)//0	Ŧ		
						Clean, pressure wash, and tape off stain concrete areas. Re-stain and coat exterior stained					
		Santa	Santa Maria Clerks			concrete. Outside new construction warranty period. Heavy foot traffic causes concrete's water					
351	FM-0052832	Barbara	Building	42-F7	2	sealant to wear and create slipping hazard.	\$	8,326	\$	8,326	100.00
								-,			
l						Plumbing - Water Intrusion and Microbial Remediation of Secured stairwell, men's and women's					
						public restroom and water membrane correction of North exterior wall - 3000 square feet of					
		Santa	Santa Maria			drywall replacement in secured stairwell, men's and women's public rest room damaged as a					
352	FM-0052984	Barbara		42-F5	2	result of Water Intrusion caused by faulty water membrane on exterior of facility.	\$	16,171	\$	15,603	96.49
			Santa Maria								
l		Santa	Courts Building C			Plumbing - Replace ceiling in lobby of Building C due to Water Intrusion - SB County condenser					
353	FM-0053017	Barbara	+ D	42-F1	1	leak caused damage to 925 sq. ft. of ceiling in lobby adjacent to Dept. 4 entrance.	\$	14,128	\$	7,728	54.70
						Plumbing - Replace failed main water line, pinhole leak capped, wall tile removed and replaced;				,	
l		Santa	Lompoc Municipal			Restroom restored to pre-water intrusion conditions. Water leaking in wall between Men's and					
354	FM-0053036	Barbara	Court	42-D1	1	Women's public restroom	\$	6,110	\$	2,155	35.27
						Roof - Installation of copper angle to existing gutter, current system allows water to run off from	-		-		
		Santa	Santa Barbara			roof (open skylight design) onto the screening area. Gutters are unable to contain all run-off					
355	FM-0053038	Barbara	Figueroa Division	42-B1	2	causing water to leak onto Security Screening equipment.	\$	12,792	\$	12,792	100.00
		Santa	Santa Maria			HVAC - Replace failing 8.5 Ton HVAC unit (PKU 11) - PKU servicing Department 7 Courtroom is					
356	FM-0053519	Barbara	Courts Building G	42-F5	2	failing and no longer functioning as designed.	\$	16,207	\$	16,207	100.00
						Elevator - Restore elevator, replace seal and install to hydraulic system casing for elevator to					
		Santa	Santa Barbara Jury	,		function properly. Elevator has a seal that broke and detached from the casing of the hydraulic					
357	FM-0053523	Barbara	Assembly Bldg.	42-G1	2	system.	\$	2,636	\$	2,636	100.00
						Plumbing - Remove material surrounding elbow joint in contained environment and area to be					
l			Santa Maria			cleared per JCC/ABM protocol. Once cleared, replace leaking section of hot water pipe and					
		Santa	Courts Building C			restore area to pre-leak conditions. Leaking pipe in Depart. 2 Courtroom above jurors box to be					
358	FM-0053567	Barbara	+ D	42-F1	2	replaced. Questionable material wrapping elbow joint.	\$	10,946	\$	10,946	100.00
			New Santa								
		Santa	Barbara Criminal			Grounds and Parking Lot - Parking Lots A, B & C - Install Safety Lighting - Safety/Security for					
359	FM-0054125	Barbara	Courthouse	42-M1	2	Court Staff in JCC-managed Parking Lots	\$	4,000	\$	4,000	100.00
						Exterior Shell - Replace 87 wood windows - Remove and replace 87 wood windows in the					
						historic courthouse. 50% of the windows have failed due to wear, termite damage and dry rot.					
						The remaining balance of the windows are starting to fail. The cost delta between 100%					
			Historic			replacement and 50% replacement is \$200k. Recommend 100% replacement as most cost					
360	FM-0020267	Santa Clara	Courthouse	43-B2	2	effective - long term solution.	\$	1,634,710	\$	1,634,710	100.00
						Exterior Shell - Exterior windows at stairwells (120 ea) - Remove and replace the existing					
						interior and exterior failing window gasket seals. The existing vinyl seals will be replaced with a					
			Palo Alto			silicone based liquid sealant. Water is leaking into the building under heavy rains, Work will					
361	FM-0049249	Santa Clara	Courthouse	43-D1	2	require the use of high reach equipment, aerial lift and scaffolding.	\$	84,427	\$	55,756	66.04



						HVAC - Restore Air Handler Unit 4 and nine (9) coils to manufacturers specifications - The					
						cooling to the building has not been sufficient and is affecting operations. Cutting through					
			Sunnyvale			existing ductwork is needed to gain access to the coils. Replace and Patch ductwork sheet metal.					
362	FM-0052835	Santa Clara	Courthouse	43-F1	2	HVAC will be shut down during the work over the weekend.	Ś	14,239	Ś	14,239	100.00
			Morgan Hill			Holding Cell - Replace (1) door window 25 1/4 x 7 1/2 x 1/2 Tempered laminate. Repair lock	Ŧ		Ŧ	,	
363	FM-0052869	Santa Clara	Courthouse	43-N1	2	operation to avoid lock outs.	Ś	4,411	Ś	4,411	100.00
505	111 0032003		Morgan Hill		-	HVAC - Replace failed pump seal and bearing assembly to the leaking heating hot water pump	Υ 	.,	Ŷ	,,,,	100.00
364	FM-0052870	Santa Clara	Courthouse	43-N1	2	#1	Ś	3,136	Ś	3,136	100.00
501	111 0032070		Hall of Justice			Elevators, Escalators, & Hoists - Rebuild failed generator motor for elevator #2 - This is the only	Ŷ	5,150	Ŷ	5,150	100.00
365	FM-0052938	Santa Clara	(West)	43-A2	1	public elevator in building and is not operational at this time.	¢	28,599	\$	28,599	100.00
505	11010032330		Downtown	+5 //2	-	Plumbing - Replace (1) Failed check valve and (1) failed cleanout in 4 inch sewer line in	<b>·</b>	20,333	Ŷ	20,333	100.00
366	FM-0052966	Santa Clara	Superior Court	43-B1	2	basement file room to eliminate leak	¢	7,713	¢	7,713	100.00
500	110-0052500			43-01	2	Fire Protection - Code Compliance Issue - Replace failed internal parts (bolts and gaskets to (2)	ې ا	7,713	Ļ	7,715	100.00
						FDC 8" check valve - check valve deficiencies were found during the 5 year inspection located in					
			Hall of Justice			the valve box - removal of the internal check parts are required to bring the fire system to code					
267	FM-0052975	Santa Clara		43-A1	2		ć	1 100	ć	1 1 2 2	100.00
507	FIVI-0052975		(East)	45-A1	2	compliance. Fire Protection - Replace failed 6" Fire main grooved coupling - Shutdown fire system and drain -	Ş	4,423	Ş	4,423	100.00
						remove steel ceiling panels in in-custody transfer tunnel to access failed fire main coupling -					
						disassemble and remove failed coupling and piping - install approx. 8' of new 6" piping with 2					
200		Canta Clara	Hall of Justice	42 44	2	new 6" Victaulic couplings - re-charge fire system and leak test - re-install steel ceiling panels -	~		~	0.050	100.00
368	FM-0053026	Santa Clara	(East)	43-A1	2	clean and remove debris from site	\$	8,659	\$	8,659	100.00
2.52			Downtown				4		4		
369	FM-0053428	Santa Clara	Superior Court	43-B1	2	Vandalism - Replace 7x 3 shattered safety laminated glass at public entry.	Ş	1,571	Ş	1,571	100.00
			Downtown			Plumbing - Replace (1) failed ejector pump motor and check valves. Pump is overflowing and	4		L		
370	FM-0053440	Santa Clara	Superior Court	43-B1	2	flooding the basement area.	Ş	8,106	Ş	8,106	100.00
						Roof - Replace 22,000 sq. ft of deteriorated roof, coping metal (1000 sq ft), Gravel stops (250 sq					
			Palo Alto			ft), Surface mount (450 sq ft) and deteriorated over flow drains. The roof is showing signs of					
371	FM-0053442	Santa Clara	Courthouse	43-D1	2	cracking and ponding. Roof leaks are evident in the building.	Ş	824,415	Ş	544,444	66.04
						HVAC - Replace failed re-heat coils (13), valve train from isolation valve to VAV's including pipe,					
						strainers, belimo valve, temp sensors and thermostats - Re-heat coils failing due to corrosion					
						from service without dialectic pipe connections; issue discovered during isolation valve					
372	FM-0052863	Santa Cruz	Main Courthouse	44-A1	2	replacement modification.	\$	60,503	\$	59,965	99.11
			Jury Assembly			Pest Control - Full building termite fumigation, tenting required - termites found in several					
373	FM-0053417	Santa Cruz	Room	44-A3	2	locations causing structural damage.	\$	7,105	\$	7,105	100.00
						Electrical - Storm water and sewage discharge pumps - Replace four (4) 480 volt 7.5 horsepower					
						pumps with four (4) 200 volt 7.5 pumps and two (2) 480 volt 5 horsepower pumps with two (2)					
						200 volt 5 horsepower pumps, so their motor voltage matches the emergency generator output					
						voltage - connect the new pumps to the emergency power panel so they function during a					
374	FM-0051922	Solano	Hall of Justice	48-A1	2	power outage.	\$	258,000	\$	187,876	72.82
			Solano Justice			Interior finishes - Replace failed fire shutter at transaction window number seven in the criminal					
375	FM-0052814	Solano	Building	48-B1	2	division. Code Required.	\$	13,505	\$	13,505	100.00
						Fire Alarm System - Correct deficiencies found while performing a level IV PM - Replace failed					
376	FM-0052862	Solano	Hall of Justice	48-A1	2	duct detector, LED enunciator, and horn strobe	\$	3,054	\$	2,224	72.82
						Electrical - Sump pump - Install electrical feed from emergency panel so the pump functions					
377	FM-0052873	Solano	Hall of Justice	48-A1	2	during a power outage	\$	4,123	\$	3,002	72.82
			Solano Justice			HVAC - Replace failed two ton split air-conditioning unit that cools Court IT (MDF) room 118 -					
378	FM-0053439	Solano	Building	48-B1	2	Work to be performed afterhours	\$	14,950	\$	14,950	100.00



						Electrical - Replace failed secure door lock control relay - Remove and replace control panel for			
						the secure door lock entering the secured stairwell, the relay has failed and cannot be replaced			
						without replacing the control panel all together. The door is currently in the "Fail Open"			
379	FM-0053950	Solano	Hall of Justice	48-A1	2	position. Work to be performed after hours with escort.	\$ 6,729	\$ 6,729	100.00
						COUNTY MANAGED - Elevators Renovation - Renovate South Common Area - Single elevator in			
380	FM-0046916	Sonoma	Hall of Justice	49-A1	2	south lobby is beyond useful life	\$ 156,741	\$ 156,741	100.00
			Modesto Main						
381	FM-0053435	Stanislaus	Courthouse	50-A1	1	HVAC - Replace supply and return fan VFD and Chiller #1 upgrades to Circuit A	\$ 50,000	\$ 38,910	77.82
						HVAC - Replace Failed Mini-split unit for Tech Print Room. Existing condenser unit has failed			
						beyond repair. Replacement parts not feasible and replacement condensing unit not available			
382	FM-0053456	Stanislaus	Hall of Records	50-A2	2	with R-22 refrigerant (replacement is required).	\$ 8,154	\$ 8,154	100.00
			Modesto Main			Plumbing - Replace failed hot water heater for main courthouse. Main tank is cracked and			
383	FM-0053458	Stanislaus	Courthouse	50-A1	2	unable to be repaired.	\$ 5,310	\$ 4,132	77.82
						Safety - Carpet: Remove knock down strips - re-stretch carpeting in courtrooms 1 and 2 and			
			Modesto Main			replace knockdown with rubber molding - The carpet is bunching up causing a potential trip			
384	FM-0054075	Stanislaus	Courthouse	50-A1	2	hazard	\$ 3,276	\$ 3,276	100.00
						Fire Protection - Replace four fire sprinkler heads (two corroded fire sprinkler heads, two			
						painted fire sprinkler heads), replace the drain valve with an approved valve, and relocation of			
385	FM-0053548	Tehama	Annex No. 2	52-A3	2	the gauges on the riser to an approved location - Annual FMS PM failed	\$ 3,152	\$ 3,152	100.00
						Fire Protection - Remove and replace fire alarm panel with failing communicator. The failing			
386	FM-0053013	Yolo	Traffic Court	57-A3	2	communicator is causing a loss of communication with fire alarm monitoring company.	\$ 3,055	\$ 3,055	100.00

\$ 27,066,997 \$ 23,396,856

Attachment B



## JUDICIAL COUNCIL OF CALIFORNIA

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

ITEM #	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	REQUEST TYPE	CFR DESCRIPTION	CFR TERM	FUND SOURCE	ESTIMATED CURRENT YEAR COSTS (Includes existing costs prior to CFR term)	ESTIMATED BUDGET YEAR COSTS	TOTAL ESTIMATED CFR COMMITMENT (CFR Term)	REVIEW NOTES - OREFM, JBCPO, & FSO
1	11-CFR003	Glenn	11-C1	Resource Center	Lease	One- Time	(Utility costs are court funded) Lease extension from 5/1/2015-12/31/2016. The leased space houses the Family Court Facilitator, FCS Mediator, Self Help Center and court records storage. This request is considered urgent because this space is needed until the new courthouse is completed, estimated completion date is 10/31/16.		CCF for Lease Costs, Operating Budget for Utility Costs	\$ 74,666	\$ 77,105	\$ 129,533	No Concerns
2	19-CFR024	Los Angeles	Multiple	Multiple	FM	One- Time	Electrical upgrades at El Monte Courthouse and Stanley Mosk Courthouse. These upgrades are deemed urgent because they are needed to support the new case management system. The existing T1 & DSL line is not sufficient for the new Court's	NA	Operating Budget	\$ 225,000	\$-	\$ 225,000	No Concerns
3	39-CFR002	San Joaquin	39-C1	Manteca Branch Court	FM	One- Time	case management system that is currently in the implementation stage. This project will increase bandwidth capactiy from 1.5 MBS to 20 MBS, significantly improving computing capacity and faster computing response times. This request is deemed urgent because the new case management system requires this additional bandwidth. This project will also reduce the Court's monthly services cost	NA	Operating Budget	\$ 9,156	\$ -	\$ 9,156	No Concerns



TRIAL COURT FACILITY MODIFICATION Advisory committee

Meeting Date: 3/6/2015

### **Discussion Item 1**

#### **Summary:**

Priority 3 project request: Larson Justice Center parking project

#### **Supporting Documentation:**

• Summary, diagram and photograph packet

#### **Action Requested:**

Review and discuss project for potential funding

# Discussion Item 1 Priority 3 Project Request

# Larson Justice Center FM-0053022 – Create 80 parking stalls out of perimeter landscape – Potential Project ROM \$470,000



**Larson Justice Center Parking**  Project Merits Creates additional parking in an area where many cannot afford paid parking Eases delays from late court users and jurors Prevents further damage to court property and potential claims Current Status Prioritized as Priority 3 Project ROM is \$470,000, JCC share \$379,807 IUDICIAL COUNCIL



CALIFORNIA



TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

## **Riverside Request**

#### 1. Executive Summary

Riverside Superior Court is requesting a facility modification for the Larson Justice Center (33-C1) to develop a free paved parking lot adjacent to existing paid parking where there is currently only landscaping. Court users are currently parking illegally on the landscape, creating damage to the irrigation system and creating a possibility for safety or injury claims.

#### a. FM # and description

FM-0053022 - Grounds and Parking Lot - East Parking Lot - Create and install 80 parking stalls out of perimeter landscape around the current lot. The recent closure of the County lot behind the courthouse, closure of the Court Annex/County building next door and its parking lot, and the building of a County Law building next door have created a serious parking issue in the immediate area of the Larson Justice Center resulting in a 200+ parking stall loss. Customers are currently parking on the landscape damaging irrigation lines and boxes.

#### b. Project overview paragraph

The improper use of the landscaping as a parking lot has resulted in damage and continued improper use could result in major damage and waste of water from damaged pipes. The project includes the demolition and removal of landscape/grass adjacent to current lot; excavate, grade and compact area; install 6 base and compact; install approx. 30,000sf of new asphalt; install 80 parking bumpers; slurry seal approx. 77,000sf of existing parking lot to match new and restripe stalls; install 6 new lighting poles in new lot with wiring; remove approximately 6 trees.

#### c. Project cost factors including shared cost if applicable

JCC Percentage Share is 80.81. The total cost of the project is anticipated to total \$470,000.

- **d.** Implementation hurdles if any: Standard permitting and design required. County permitting may be required.
- 2. Court justification document package

#### 3. Site plan/drawing or similar document if available

- a. Map of proposed parking lot location
- b. County Law Building Offsite Logistics Plan
- 4. Supporting documentation from Security or other entity None at this time
- 5. Pictures of current conditions if available



Chambers of HAROLD W. HOPP Presiding Judge

Superior Court of California County of Riverside

February 3, 2015

Honorable David E. Power, Chair Trial Court Facility Modification Advisory Committee Solano Superior Court 580 Texas Street Fairfield, CA 94533

Dear Judge Power:

The Trial Court Facility Modification Advisory Committee (TCFMAC) has recently received a request from the Riverside Superior Court to expand one of the State/Court-owned parking lots at our Larson Justice Center in Indio. This courthouse is the largest in our court's Eastern Division (essentially everything east of the Banning Pass) and has the highest volume of public visitors, jurors and court staff in that region. Until last August, Riverside County had permitted court staff and visitors to use a paved open lot adjacent to the courthouse without an MOU or cost to the court. This additional county-owned parking lot of approximately 350 spaces was critical parking for our jurors, court users, and court staff. The county has now built a new parking structure on this site, which has severely limited the availability of free parking in an area where many cannot afford the additional cost of paid parking.

Since access to the county parking lot was lost in August, we have observed many parking issues. Lack of free public parking has led to parking on the State/Court owned unpaved, turf area adjacent to our east parking lot. Our efforts to post no parking signs and install chain barricades to protect the turf and irrigation system have not been successful. Court staff have found cars and trucks parked in the turf after someone had removed or broken through the chains and signs that were placed. Court staff has also observed vehicles becoming stuck in the

4050 Main Street Riverside, CA 92501 (951) 777-3162 February 3, 2015 Page 2

turf after it had become muddy during recent rains. The court has not received any damage claims yet from this unauthorized parking, but we expect that litigation will occur. Damage to irrigation equipment and water leaks have also become an ongoing issue in this dry climate.


The request that the court has submitted to the TCFMAC calls for the addition of approximately 80 parking spaces to be constructed as an expansion of the existing east parking lot. The Court would like as many parking spaces on this lot as will fit per building code. The construction of the new spaces will require removal of the existing turf area that has currently become a problem. The project was originally entered as a Priority 3 with an estimated cost of \$470,000.00 per the JCC. The court believes the priority level should be increased to a P2 due to multiple factors. If the parking lot is not enlarged to compensate for the loss of the County overflow parking, deterioration of the land surrounding the lot will continue. Court users and jurors who cannot find available free parking will continue to damage court property, be late to court hearings or jury service and the probability of a claims being filed against the Court will remain high.


Please let us know what can be done to prioritize this critical project higher so that funding can be obtained. Of course, should you have any questions or need any further information, do not hesitate to contact me.

Thank you for your consideration.

Sincerely,

HAROLD W. HOPP Presiding Judge






#### County Law Building

offsite logistics plan

#### LEGEND


















TRIAL COURT FACILITY MODIFICATION Advisory committee

Meeting Date: 3/6/2015

### **Discussion Item 2**

#### **Summary:**

Year end process for Court Funded Requests utilizing FY 14-15 funds. Submittal cutoff is March 23, 2015.

#### **Supporting Documentation:**

• None

Action Requested:

None

# Discussion Item 2 Year End Process for Court Funded Requests

- Official Notice Feb 2, 2015
- Final Requests March 23, 2015
- Final Approval Meeting March 30, 2015
- Anticipate additional CFR requests from LA and several other courts.



TRIAL COURT FACILITY MODIFICATION Advisory committee

Meeting Date: 3/6/2015

### **Discussion Item 3**

#### **Summary:**

May TCFMAC two-day meeting to be held in Los Angeles

#### **Supporting Documentation:**

• None

#### **Action Requested:**

Discuss courthouse tours and determine meeting place

Discussion Item 3 May 21-22 Meeting

- Day 1
  - Land in Burbank
  - Meet in Foltz/Mosk
  - Tour of Foltz/Mosk
- Day 2
  - Meet in Van Nuys
  - Tour Van Nuys East & West

Discussion Item 3 May 21-22 Meeting

- Topics
  - Meeting Lists
  - 15-16 Budget plans O&M & FM
  - Potential Planned Work List
  - Construction Related FM projects
  - Security Projects Overview