

Meeting Documents

Meeting Date April 10, 2023



Request for ADA accommodations should be made at least three business days before the meeting and directed to: JCCAccessCoordinator@jud.ca.gov

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

NOTICE AND AGENDA OF OPEN IN-PERSON MEETING WITH CLOSED SESSION

Open to the Public Unless Indicated as Closed (Cal. Rules of Court, rule 10.75(c)(1), (d), and (e)(1))

OPEN PORTION OF THIS MEETING IS BEING RECORDED

Date: April 10, 2023 **Time:** 10:00 - 3:00

 Location:
 Sacramento / Videocast for Public Access

 Public Videocast:
 https://jcc.granicus.com/player/event/2188

Meeting materials for open portions of the meeting will be posted on the advisory body web page on the California Courts website at least three business days before the meeting.

Members of the public seeking to make an audio recording of the open meeting portion of the meeting must submit a written request at least two business days before the meeting. Requests can be e-mailed to tcfmac@jud.ca.gov.

Agenda items are numbered for identification purposes only and will not necessarily be considered in the indicated order.

OPEN MEETING (CAL. RULES OF COURT, RULE 10.75(C)(1))

Call to Order and Roll Call

Approval of Minutes

Approve minutes of the March 10, 2023, Trial Court Facility Modification Advisory Committee meeting.

II. PUBLIC COMMENT (CAL. RULES OF COURT, RULE 10.75(K)(1)-(2))

Written Comment

In accordance with California Rules of Court, rule 10.75(k)(1), written comments pertaining to any agenda item of a regularly noticed open meeting can be submitted up to one complete business day before the meeting. For this specific meeting, comments should be e-mailed to tcfmac@jud.ca.gov. Only written comments received by 12:00 Noon on April 7, 2023 will be provided to advisory body members prior to the start of the meeting.

III. DIRECTOR'S REPORT

Director's Report

- Fiscal Year 2023–24 Budget
- Utility Costs
- Storm Damage
- Supply Chain Concerns
- Staff Workload for CFR and IT Facility Modifications

IV. ACTION ITEMS (ITEMS 1-7)

Item 1

List A – Emergency Facility Modification Funding (Priority 1) (Action Required)

Approve 56 projects for a total of \$1,259,157 to be paid from Facility Modification program funds previously encumbered for Priority 1 projects.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

Item 2

List B – Facility Modifications Under \$100K (Priority 2) (Action Required)

Approve 90 projects for a total of \$1,005,938 to be paid from Facility Modification program funds previously encumbered for Priority 2 projects under \$100K.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

Item 3

List C – Facility Modification Cost Increases Over \$50K (Action Required)

Approve cost increases over \$50K for four (4) facility modification projects, totaling a cost increase to the Facility Modification program budget of \$4,094,506.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

Item 4

List D – Facility Modifications Over \$100K (Priority 2) (Action Required)

Approve 12 Priority 2 FMs over \$100K for a total cost to the Facility Modification Program budget of \$5,126,197.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

Item 5

October Meeting Travel Plans (Action Required)

Approve one of the following options for October off-site courthouse tours and committee meeting on October 26th and 27th:

Option 1 (Los Angeles)

- Day 1 Tour Compton, Stanley Mosk, and Clara Shortridge Foltz courthouses
- Day 2 Committee meeting and tour of the Van Nuys courthouse

Option 2 (Los Angeles/Orange)

- Day 1 Tour Central Justice Center and North Justice Center courthouses
- Day 2 Committee meeting and tour of the Long Beach courthouse

Presenters: Ms. Pella McCormick, Director, Facilities Services

Mr. Jagan Singh, Principal Manager, Facilities Services

Item 6

Trial Court Facility Modifications Report for Quarter 3 of Fiscal Year 2022–23 (Action Required)

Approve draft *Trial Court Facility Modifications Report for Quarter 3 of Fiscal Year* 2022–23, for submission to the Judicial Council as an Information-Only item.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

Item 7

List E – Court-Funded Requests (CFRs) (Action Required)

- 1) Review CFR projects approved by the Facilities Services Director since the last meeting and CFR projects cancelled.
- 2) Approve ongoing O&M costs associated with CFR No. 36-CFR081 for installation of electric vehicle charging stations at the San Bernardino Justice Center.

Presenter: Ms. Pella McCormick, Director, Facilities Services, Facilities Services

V. DISCUSSION ITEMS (NO ACTION REQUIRED)

Discussion Item 1

List F - Funded Facility Modifications on Hold

Standard list of previously funded facility modification projects on hold.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

Discussion Item 2

Sustainability Update

Update on stainability initiatives.

Presenter: Mr. Harry O'Hagin, Principal Manager, Facilities Services

Meeting Notice and Agenda April 10, 2023

Discussion Item 3

Facilities Maintenance Performance Report

Report on facilities maintenance performance.

Presenter: Mr. Mike Sablich, Principal Manager, Facilities Services

Discussion Item 4

Stanley Mosk Courthouse Sewer Power Washing and Replacement Project

Update on the sewer power washing and replacement project at the Stanley Mosk Courthouse.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

VI. INFORMATION ONLY ITEMS (NO ACTION REQUIRED)

Information Item 1

Deferred Maintenance Funding - DMF-2 Projects Update

Update on the status of DMF-2 projects. DMF-2 projects are funded by a one-time general fund budget allocation in July 2018 of \$50 million. \$5 million was earmarked specifically for facility assessments and \$45 million for roof, BAS, elevator, and HVAC projects.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

Information Item 2

Deferred Maintenance Funding - DMF-3 Projects Update

Update on the status of DMF-3 projects. DMF-3 projects are funded by a one-time general fund budget allocation in July 2019 of \$15 million which is earmarked for fire alarm system projects.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

Information Item 3

Deferred Maintenance Funding - DMF-4 Projects Update

Update on the status of DMF-4 projects. DMF-4 projects are funded by a one-time general fund budget allocation in July 2021 of \$180 million (reduced to \$132.6) for trial court facilities. Funding is earmarked primarily for HVAC, roof, elevator, electrical, and fire protection projects.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

Information Item 4

Architectural Revolving Fund Projects Update

Update on the status of facility modification projects in the Architectural Revolving Fund.

Presenter: Mr. Jagan Singh, Principal Manager, Facilities Services

Meeting Notice and Agenda April 10, 2023

VII. ADJOURNMENT

Adjourn to Closed Session

VIII. CLOSED SESSION (CAL. RULES OF COURT, RULE 10.75(D))

Call to Order and Roll Call

Approval of Minutes (Action Required)

Approve closed session minutes of the March 10, 2023 Trial Court Facility Modification Advisory Committee meeting.

Item 1

Closed pursuant to California Rules of Court, Rule 10.75(d)(5)

Security plans or procedures or other matters that if discussed in public would compromise the safety of the public or of judicial branch officers or personnel or the security of judicial branch facilities or equipment, including electronic data.

Security-Related – Facility Modifications Under \$100K – Priority 2 (Closed List B) (Action Required)

Approve one (1) security-related project for a total of \$6,436 to be paid from the Facility Modification Program budget.

Presenters: Mr. Jagan Singh, Principal Manager, Facilities Services
Mr. Ed Ellestad, Security Operations Supervisor, Facilities Services

Item 2

Closed pursuant to California Rules of Court, 10.75(d)(10)

Topics that judicial officers may not discuss in public without risking a violation of the California Code of Judicial Ethics, necessitating recusal, or encouraging disqualification motions or peremptory challenges against them, including proposed legislation, rules, forms, standards of judicial administration, or jury instructions.

Legislative Update on Facilities Related Bills - AB 61 and AB 959

Information and request for discussion around Assembly Bill 61 (Bryan): Criminal procedure: arraignment and an update to Judicial Council sponsored legislation Assembly Bill 959 (McCarty): Courts.

Presenter: Ms. Morgan Lardizabal, Legislative Advocate, Governmental Affairs

Adjourn Closed Session



TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

MINUTES OF OPEN SESSION OF MEETING

March 10, 2023

12:00 PM - 1:14 PM

Judicial Council of California - Videocast for Public Access

Advisory Body

Hon. Donald Cole Byrd, Chair

Members Present:

Hon. William F. Highberger, Vice-Chair

Hon. John B. Ellis

Hon. Jennifer K. Rockwell Hon, Vanessa W. Vallarta

Mr. Jarrod Orr Mr. Darrel E. Parker Ms. Nocona Soboleski

Advisory Body

Hon. Brad R. Hill

Members Absent:

Hon, Patricia M. Lucas

Staff Present:

The following Judicial Council staff were present:

Mr. John Wordlaw, Chief Administrative Officer, Executive Office

Ms. Pella McCormick, Director, Facilities Services Mr. Tamer Ahmed, Deputy Director, Facilities Services Mr. Harry O'Hagin, Principal Manager, Facilities Services Mr. Michael Sablich, Principal Manager, Facilities Services Mr. Jagan Singh, Principal Manager, Facilities Services

Ms. Maria Atayde-Scholz, Manager, Facilities Services Ms. Mimi Chung, Manager, Facilities Services

Mr. Jack Collins, Manager, Facilities Services

Ms. Nanci Connelly, Manager, Facilities Services

Mr. Andre Navarro, Manager, Facilities Services

Mr. Ed Ellestad, Supervisor, Facilities Services

Ms. Donna Jorgensen, Supervisor, Facilities Services Mr. Yassen Roussev, Supervisor, Facilities Services

Mr. Steve Shelley, Supervisor, Facilities Services

Mr. Randy Swan, Supervisor, Facilities Services

Mr. Paul Terry, Supervisor, Facilities Services

Mr. Patrick Treanor, Supervisor, Facilities Services

Mr. Guillermo Urena, Supervisor, Facilities Services

Mr. Doug Walthour, Supervisor, Facilities Services Ms. Kate Albertus, Facilities Analyst, Facilities Services

Ms. Sadie Varela, Facilities Analyst, Facilities Services

Ms. Mary Li, Associate Analyst, Facilities Services

Ms. Akilah Robinson, Associate Analyst, Facilities Services

Ms. Kristin Kerr, Supervising Attorney, Legal Services Ms. Erin Stagg, Attorney, Legal Services

Ms. Morgan Lardizabal, Legislative Advocate, Governmental Affairs

OPEN SESSION OF MEETING

Call to Order, Opening Remarks, and Roll Call

The chair called the open session of the meeting to order at 12:02 PM, roll was taken, and opening remarks were made.

Approval of Minutes

The advisory committee voted to approve the open session minutes of its meeting held on February 3, 2023. (*Motion: Rockwell; Second: Ellis*)

PUBLIC WRITTEN COMMENTS

No public comments were received.

DIRECTOR'S REPORT

The committee received the following updates:

- 1. Intra-Branch Agreements (IBAs) for Delegated Superior Courts:
 - To ensure consistent operations and maintenance (O&M) practices across the Judicial Council real estate portfolio, Facilities Services is taking steps to align the O&M delegation program with the Judicial Council's service provider contract model standards.
 - San Bernardino, Riverside, and Orange superior courts have opted to remain in the delegation program. San Luis Obispo is opting out of the program in 2023–24.
 - Facilities Services will meet with the courts' leadership on March 28, 2023, to review updated IBAs, and the courts will have 30 days to provide written comments.
 - The goal is to finalize the IBAs by July 1, 2023.
- 2. 2024–25 Budget Change Concepts (BCCs):
 - The Judicial Branch Budget Committee (JBBC) is scheduled to meet on March 14, 2023, to review branch-wide BCCs for 2024–25.
 - Facilities Services has submitted BCCs for trial court maintenance and utilities, facilities modifications, deferred maintenance, electrical system safety and reliability, energy retrofits, water conservation, trial court security related to physical security assessments, capital program support, and capital program projects.
 - Facilities Services is hopeful the JBBC will support the proposals, as the program is close to turning the corner on the run-to-failure model of O&M performance and has gained ground on the deferred maintenance backlog.
- 3. Budget Hearings:
 - At the February 27, 2023, Senate Budget Subcommittee hearing on Public Safety, the Legislative Analyst's Office provided an educational overview of trial court construction and facility maintenance.

- There were no questions from the subcommittee regarding the \$5.9 million proposal for O&M funding for the nine new courthouses.
- 4. San Diego Central Courthouse Canopy Removal:
 - At the San Diego Central Courthouse, most of the pedestrian canopy has been removed. The remaining work, which includes the plaza level ADA ramp, curbside loading, and final clean-up of the sidewalk and debris, will be completed on March 13, 2023.

OPEN SESSION - ACTION ITEMS (ITEMS 1-5)

Action Item 1 - Fiscal Year 2022-23 Facility Modification Program Budget Actions

The committee approved the following 2022–23 FM Program Budget actions:

- 1. Reallocation of \$4 million from the FMs over \$100k budget to the Priority 1 Emergency FMs budget.
- 2. Cancellation of FM-2002641, a Priority 3 sewer line power wash project at the Clara Shortridge Foltz Criminal Justice Center, with a total FM Program budget share of \$3,034,327. Cancellation was owing to county refusal to sign the shared-cost letter.

(Motion: Vallarta; Second: Highberger)

Action Item 2 - List A - Emergency Facility Modification Funding (Priority 1)

The committee approved 72 projects for a total of \$2,025,097 to be paid from facility modification (FM) program funds previously encumbered for Priority 1 projects.

(Motion: Ellis; Second: Orr)

Action Item 3 – List B – Facility Modifications Under \$100K (Priority 2)

The committee approved 78 projects for a total of \$788,105 to be paid from FM program funds previously encumbered for Priority 2 projects under \$100K.

(Motion: Highberger; Second: Vallarta)

Action Item 4 – List C – Facility Modification Cost Increases Over \$50K

The committee approved cost increases over \$50K for one project for a total of \$1,019,956 to be paid from FM program funds. (Motion: Highberger; Second: Ellis)

Action Item 5 – List D – Facility Modifications Over \$100K (Priority 2)

The committee approved 8 of 10 Priority 2 FMs over \$100K for a total cost to the FM program budget of \$5,210,589. The committee asked staff to provide further information about the two remaining projects at the San Diego North County Regional Center (FM-2003952 and FM-2004119) for consideration at a future meeting. (Motion: Highberger; Second: Rockwell)

OPEN SESSION - DISCUSSION ITEMS (ITEMS 1-2) (NO ACTION REQUIRED)

Discussion Item 1 – List E – Court-Funded Requests (CFRs)

The committee reviewed five CFRs (all FMs) that were approved by the Facilities Services Director since the last committee meeting. Two CFRs were cancelled during this reporting period.

Discussion Item 2 – List F – Funded Facility Modifications on Hold

The committee reviewed the list of previously funded FMs on hold.

ADJOURNMENT TO CLOSED SESSION AND ADJOURNMENT

There being no further open session business, the open session of the meeting was adjourned at 1:14 PM, and the advisory committee moved to the closed session of the meeting—which was closed to the public for discussion of security-related items (per Cal. Rules of Court, Rule 10.75(d))—was adjourned at 1:30 PM.

| Αı | DI | proved | by | the | advisor | y 1 | body | on | |
|----|----|--------|----|-----|---------|-----|------|----|--|
| | | | | | | | | | |



Meeting Date: 4/10/2023

Director's Report

Summary:

Updates on the following:

- Fiscal Year 2023–24 Budget
- Utility Costs
- Supply Chain Concerns
- Staff Workload for CFR and IT Facility Modifications
- Storm Damage

Supporting Documentation:

• See presentation

Director's Report

- Fiscal Year 2023–24 Budget
- Utility Costs
- Supply Chain Concerns
- Staff Workload for CFR and IT Mods
- Storm Damage

Director's Report Mono- Mammoth Lakes







Meeting Date: 4/10/2023

Action Item 1 – (Action Required) - List A – Emergency Facility Modifications (Priority 1)

Action Requested:

Approve 56 projects for a total of \$1,259,157 to be paid from Facility Modification program funds previously encumbered for Priority 1.

Supporting Documentation:

• List A – Emergency Facility Modification Funding Report (Priority 1)

Priority 1 = Immediately or Potentially Critical.

Condition requires immediate action to return a facility to normal operations, or a condition that will become immediately critical if not corrected expeditiously. Such conditions necessitate the need to stop accelerated deterioration or damage, to correct a safety hazard that imminently threatens loss of life or serious injury to the public or court employees, or to remediate intermittent function and service interruptions as well as potential safety hazards. Such conditions may include, but are not limited to, the following: major flooding; substantial damage to roofs or other structural building components; or hazardous material exposure. Depending on scope and impact, a severe deterioration in life safety protection may also be considered a priority 1 condition requiring a facility modification.

Owing to their critical nature, priority 1 requests will be addressed immediately by JCC staff using internal procedures that ensure timely and effective responses to unplanned emergency or potentially critical conditions, including a method and a process for setting aside funds to address priority 1 conditions.

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|---|------------|-------------|--|-------------|----------|---|--------------------|---|------------|--|
| 1 | FM-2002388 | | North County Regional Center - North | 37-F2 | | HVAC - Condensation Leak - Replace (2) 5 x 7 foot sections of corroded sheet metal, drain pans, and sections of transition ductwork for AHU #07. Replaced (3) SF of saturated ceiling tiles, (8) SF of drywall, and (4) LF of thermal shield duct insulation. The condensation pan failed due to corrosion and age that resulted in cat 2 water intrusion in public corridor. Environmental and remediation work required to complete work. Work included 10×10 SF containment, cleaning and sanitizing of 20 SF of hard surfaces due to known ACM in roof-top mastic. | \$ 107,086 | \$ 107,086 | Complete | 100 |
| 2 | FM-2002659 | | Hall of Justice (East) | 43-A1 | | Fire Protection - Repair leaking standpipe, isolate, drain, replace 10 FT of 4 inch standpipe, pressurize, and leak test. 35 year old fire sprinkler standpipe leaking due to age, is causing minimal flooding in the stairwell. | \$ 8,841 | \$ 8,841 | Complete | 100 |
| 3 | FM-2003758 | _ | North County Regional Center - North | 37-F2 | | HVAC - Replace (4) 1/2-inch chilled water line valves, (1) 1/2-inch heating hot water valve, (2) 24 x 24 inch return air grills in courtroom and 13 thermostats located in criminal business office. The failed components have resulted in numerous cold calls in the impacted areas. Repairs are needed to maintain building temperatures. | \$ 22,446 | \$ 22,446 | Complete | 100 |
| 4 | FM-2003790 | Los Angeles | Pasadena Courthouse | 19-J1 | | Plumbing - Sewer Line Leak - Replace (32) 6 x 6 inch ceiling tiles, mechanically clear 40 LF of main drain line, sanitize 4,400 SF of surfaces and (1) 1/2-inch copper cap. Drinking water fountain drain line on 4th floor public hall backed up due to a clogged line causing water to leak into the 3rd floor public hallway and 2nd floor probation office. During water intrusion inspections of 2nd floor Probation office, it was discovered that the main water supply line to a different drinking fountain was also leaking which penetrated down to the 1st floor public main entrance and basement file room. Both leaks penetrated through fire proofing. Set up (6) containments and extracted over 1,700 gallons of water. Environmental oversight and remediation protocols were required due to known ACM and category 2 grey water. Remediation effort extended over a period of 15 days. Leak occurred over a holiday weekend. | \$ 132,501 | \$ 91,889 | Complete | 69.35 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|---|------------|-------------|--|-------------|----------|--|--------------------|---|------------|--|
| 5 | FM-2003818 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | | HVAC - Isolate and shut down Air Handling Units (AHUs) to conduct environmental sampling of particles, and visual inspection of AHUs in multiple areas throughout courthouse to identify the type of material falling from HVAC registers. There are several complaints throughout the building reporting debris and soot falling from the HVAC vents. A positive test for mold was found in AHU #12. A separate FM has been issued to address mold. | \$ 10,000 | \$ 10,000 | In Work | 100 |
| 6 | FM-2003834 | Los Angeles | Pasadena Courthouse | 19-J1 | | HVAC - Replace (1) 3inch 3-way chilled water valve, (3) ft of 3 inch copper pipe, (2) 3 inch flange and associated fittings. Valve failed due to age in the closed position and is unable to control temperatures throughout the West Wing 1st floor. | \$ 18,491 | \$ 12,824 | Complete | 69.35 |
| 7 | FM-2003939 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | | Elevators, Escalators, & Hoists - Replace (1) drive chain and adjust (1) carriage switch on Escalator #1. Drive chain is worn due to normal use rendering escalator inoperable. First floor west side of building has limited vertical transportation making this escalator a priority repair. | \$ 12,643 | \$ 12,297 | In Work | 97.26 |
| 8 | FM-2003951 | Los Angeles | Inglewood Juvenile Court | 19-E1 | | Plumbing - Replace (1) failed domestic water heater, mount on stand, install (1) unistrut, and (2) straps to affix the unit to wall. Install (1) sediment trap to gas line and expansion tank to cold-water inlet to bring up to code. During rounds and readings, it was found that the domestic water heater was leaking. Upon further inspection rust was discovered under the unit which required replacement. | \$ 5,199 | \$ 4,200 | Complete | 80.78 |
| 9 | FM-2003954 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | | Elevators, Escalators, & Hoists - Replace (1) Door lock pulley and assembly for Public Elevator #1. Elevator was non-operational with an entrapment. Parts failed due to age. | \$ 5,935 | \$ 4,363 | In Work | 73.51 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|-------------------------------|-------------|----------|---|--------------------|--|------------|--|
| 10 | FM-2003958 | Los Angeles | Pasadena Courthouse | 19-J1 | | HVAC – Replace (1) 4 in. 3-way chilled water valve and (6) LF of pipe insulation. Air handler #11 chilled water valve failed in the closed position due to age affecting temperatures throughout the 2nd floor of the annex building (west wing). | \$ 7,856 | \$ 5,448 | In Work | 69.35 |
| 11 | FM-2003965 | Los Angeles | Torrance Courthouse | 19-C1 | | HVAC - Replace (2) 1-11/16 inch mounting blocks, (2) bolt flanges, (2) grease kits, (4) brass compression couplings, (20) 1/4 inch tube straps, (2) belts, (1) pulley, (1) bushing, and (2) 50 ft grease line sets. Repair AHU fan shaft, and balance fan and bearings located at the 4th floor Mechanical Room. Fan bearing seized causing excessive vibration to fan, shaft, and full mounting. This bearing was original construction and likely failed due to age. | \$ 25,323 | \$ 21,560 | Complete | 85.14 |
| 12 | FM-2003966 | Los Angeles | Alhambra Courthouse | 19-I1 | | Elevators, Escalators, & Hoists - Replace (1) escape hatch switch on Public Elevator #1. Switch failed due to age preventing the elevator from responding. | \$ 2,816 | \$ 2,422 | Complete | 86.00 |
| 13 | FM-2003967 | | Downtown Superior Court | 43-B1 | | Elevators - Remove, repair, and reinstall elevator #2 break arm. Unit is offline, break arm is outdated and experiencing failures. | \$ 13,992 | \$ 13,992 | Complete | 100 |
| 14 | FM-2003970 | | Downtown Superior Court | 43-B1 | | HVAC - Replace (1) 7.5 hp heating hot water pump - Pump motor failed due to age causing loss of heating. | \$ 3,792 | \$ 3,792 | In Work | 100 |
| 15 | FM-2003971 | Los Angeles | Airport Courthouse | 19-AU1 | | Plumbing - Domestic Water Pipe Leak - Replace 5 ft of 4 inch copper pipe, 10 ft of 1/2 inch copper pipe, (2) 1 1/2 inch copper adapter, (1) 1 1/2 inch ball valve, (4) 1 1/2 x 90 inch pipe elbows, (1) 4 x 2 inch copper reducer, (1) 2 x 1 1/2 inch copper reducer, (2) 4 inch tees, (3) 4 inch coupling, and (3) pressure gauges. Replace the leaking pipe above eyewash station at 10th floor chiller room. During the rounds and readings in 10th floor chiller room, a pipe leak was identified for repair. | \$ 10,336 | \$ 7,976 | Complete | 77.17 |

| 16 | FM-2003981 | NO TIEGO | Facility NAME | BUILDING ID 37-11 | PRIORITY 1 | Interior Finishes - Replace (10) 2 x 4 ft ceiling tiles impacted by janitorial cleaning | \$ | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | In Work | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|--------------|-------------|----------------------------------|----------------------|------------|---|----|--------------------|--|----------|--|
| 10 | FIVI-2003981 | Sali Diego | Regional Center | 37-11 | | supplies and 5-gallons of cat-2 water that stored on the 7th floor. Clean and dry 80 SF of ceiling tile grid on the 6th floor, and 100 SF of affected concrete on the 7th floor. The spill affected restricted corridor near juvenile reception counter and public defenders office. Claim is being filed by risk management with the county for county employed janitorial contractor. | Ş | 7,702 | \$ 7,702 | III WOIK | 100 |
| 17 | FM-2003985 | Los Angeles | Compton Courthouse | 19-AG1 | | Vandalism - Replaced 20 SF of carpet and mechanically cleared 75 LF of main drain line in the 4th floor. Clog was caused by clothing flushed by an in-custody which clogged the entire 4th floor riser. Sanitized 220 SF of flooring due to category 3 water spillage. Remediation and environmental oversight required to complete work. | \$ | 20,868 | \$ 20,868 | In Work | 100 |
| 18 | FM-2003986 | Los Angeles | Santa Clarita Courthouse | 19-AD1 | | County Managed - Plumbing - Replace domestic hot water recirculation pump located in the mechanical room. Pump failed due to age, is inoperable, and does not pump domestic hot water into the building. | \$ | 2,210 | \$ 2,210 | In Work | 100 |
| 19 | FM-2003996 | Kern | Bakersfield Superior Court | 15-A1 | | Plumbing - Replaced (1) pump float switch in 1st floor restroom and 10 SF of plaster ceiling in the basement. Replaced 850 SF of carpet in (2) chambers and court reporters office and will be HEPA vacuumed. Cleaned, dried and sanitized 780 SF of hard surfaces in 14 restrooms due to category 3 water and ACM environment. Sewer ejector pump float failed due to age resulting in sewer system back-ups. The remediation process included 14 containments. Remediation and environmental oversight required to complete work. | \$ | 87,968 | \$ 54,980 | In Work | 62.50 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|---|-------------|----------|---|--------------------|--|------------|--|
| 20 | FM-2003997 | | Riverside Hall of Justice | 33-A3 | | Plumbing - Domestic Water Pipe Leak - Remediate damage caused by water leak from the drain line connection between the wall hung toilet and the wall of chambers restroom. A leak had been occurring for an undetermined amount of time and caused growth on the inside of the wall and between the ceramic tiles and plaster. Work includes replacement of 15 LF of drywall, 64 SF of cement board, 60 SF of tile, and reinstallation of plumbing and restroom fixtures. Required setting up 265 SF of containment, and use of air scrubber and dehumidifier. Remediation and environmental oversight required to complete work. | \$ 38,072 | \$ 38,072 | Complete | 100 |
| 21 | FM-2004001 | Los Angeles | Hollywood Courthouse | 19-51 | | Exterior Shell - Replace 10 SF of carpet on stairwell steps, 150 SF of basement carpet, and 20 SF of wall base. Due to heavy rain, water is coming through exterior wall, affecting the 1st floor East stairwell down to basement. Remediation and Environmental oversight required to complete work. Remediation process included installation/removal of (2) 40 x 90 inch critical barriers, (1) dehumidifier, (2) axial fans, for a total of 19 days due to continuous rains. A follow up project will be done to find the source of water entry and to provide remediation. | \$ 25,000 | \$ 22,773 | In Work | 91.09 |
| 22 | FM-2004002 | | Edmund D. Edelman Children's Court | 19-Q1 | | Exterior Shell- Replace (2) 2 x 2 FT ceiling tile. Patched/Repaired (40) LF of roof. Cleaned, dried, and sanitized 10 SF of drywall. Due to heavy rains, water penetrated through exterior plaza affecting 1st floor, county office. The remediation process included the installation of (1) temporary diverter wall. | \$ 18,000 | \$ 12,598 | In Work | 69.99 |
| 23 | FM-2004004 | | Morgan Hill Courthouse | 43-N1 | | Electrical - Replace (1) battery charger and (2) batteries on generator. During preventive maintenance, the battery charger was determined to have failed due to age, causing both batteries to fail. | \$ 5,825 | \$ 5,825 | In Work | 100 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|--------------------------------|-------------|----------|---|--------------------|--|------------|--|
| 24 | FM-2004006 | Los Angeles | Alhambra Courthouse | 19-I1 | | Interior Finishes - Replace (1) 7×3 foot fire rated emergency exit door at 2nd floor stairs. Door has split and exposed fire proofing causing a safety hazard. Door has failed due to age and requires remediation and environmental oversight. | \$ 25,837 | \$ 22,220 | In Work | 86.00 |
| 25 | FM-2004012 | Riverside | Hemet | 33-F1 | | Vandalism - Replace vandalized 55 x 46 in graffiti film on the mens public restroom mirror above the sinks. | \$ 1,199 | \$ 1,199 | In Work | 100 |
| 26 | FM-2004016 | _ | Compton Courthouse | 19-AG1 | | Elevators, Escalators, & Hoists - Removed elevator cables to replace bearings to the cable pulley on custody elevator #9. Elevator was shaking while in use. Parts failed due to age. | \$ 19,351 | \$ 19,351 | Complete | 100 |
| 27 | FM-2004017 | Los Angeles | Monrovia Training Center | 19-N1 | | Exterior Shell - Replace 30 SF of 2 x 4 FT ceiling tiles, 10 SF of drywall, 5 SF of VCT tile, 15 SF of carpet, reseal 50 LF of windows, reseal 50 LF exterior HVAC ducting and sanitize 200 SF of surfaces. Rainwater entered through the failed windows seals and additionally leaked into the building from HVAC ducting affecting the health and Nurses Supervisor's office. Remediation and environmental required. Three separate containments had to be set up. | \$ 23,000 | \$ 16,167 | In Work | 70.29 |
| 28 | FM-2004031 | Los Angeles | Airport Courthouse | 19-AU1 | | Plumbing - Domestic Water Pipe Leak - Installed 1 1/2 inch repair coupling on 1 1/2 inch copper pipe. Cut and repaired 12 x 12 inch access hole in drywall, containments and drying equipment installed in 4 restrooms. Environmental testing and oversight required to complete work. Leak identified above 8th floor leaked to the 8th and 7th floors. | \$ 15,890 | \$ 12,262 | In Work | 77.17 |
| 29 | FM-2004032 | Los Angeles | Airport Courthouse | 19-AU1 | | Exterior Shell - Resealed 5 \times 5 foot area of water proofing on concrete at exterior plaza level. Rainwater penetrated cracked concrete and leaked into the basement lock up. Installed 48 \times 48 \times 10 inch water diverter, cleaned, dried, and sanitized 50 SF of flooring. Environmental testing and oversight required. | \$ 29,830 | \$ 23,020 | In Work | 77.17 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|--------------------------------|-------------|----------|--|--------------------|--|------------|--|
| 30 | FM-2004033 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | Plumbing - Sewer Line Leak - Replaced (3) feet of cast iron drainpipe, installed 24 in x 24 in x 15 ft water diverter, cleaned, dried, and disinfected 500 SF of concrete flooring. Water leaked from the ceiling at the sally port bus ceiling onto the concrete floor. Environmental testing was required. | 14,748 | \$ 12,556 | Complete | 85.14 |
| 31 | FM-2004034 | Los Angeles | San Fernando Courthouse | 19-AC1 | 1 | Plumbing - Domestic Water Pipe Leak - Replaced 5 FT of 2 inch copper piping, along with associated fittings, and couplings. Replaced (1) 2 inch 90-elbow of hot water boiler supply piping and 10 FT of pipe insulation. There were multiple leaks along the copper supply pipe to the domestic hot water boiler. Drained the entire domestic hot water down to the basement to complete the repairs. Once repairs were completed restored service to courthouse and walked the entire building to purge all air from the system and plumbing fixtures. Remediation and Environmental oversight required to complete work. | 20,003 | \$ 16,685 | Complete | 83.41 |
| 32 | FM-2004038 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 1 | HVAC - Replace boiler fireside gaskets and remove burner assembly to clean and clear buildup on Boiler #4. Replace advanced pressure controller on Boiler #5. Boilers were both offline, short cycling due to clogged tubes and were nonresponsive due to a failed controller, causing cold temperatures throughout various sections of the courthouse. Boiler gaskets failed due to age. | \$ 20,000 | \$ 17,948 | In Work | 89.74 |
| 33 | FM-2004043 | Los Angeles | Airport Courthouse | 19-AU1 | 1 | Plumbing - Sewer Line Leak - Replaced 60 feet of 4 inch cast iron, 20 feet of 3 inch cast iron, 20 feet of 2 inch cast iron, (9) various 4 inch fittings, (5) various 3 inch fittings, (3) various 2 inch fittings, and 80 various sized couplings. Installed 520 SF of moisture barrier, cleaned, dried, and sanitized 60 SF, and removed and replaced 14 mounted jury box chairs. Placed (2) 520 SF floor covers to protect the floor from plumbing repairs. Scaffolding and high reach ladders were required to make repairs. Ceiling leak reported in 9th floor courtroom. Three (3) cast iron drain lines were identified to be cracked above 10th floor mechanical room. Environmental testing and oversight required. | \$ 51,914 | \$ 40,062 | In Work | 77.17 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|-----------------------------------|-------------|----------|--|--------------------|--|------------|--|
| 34 | FM-2004048 | Yolo | Yolo Superior Court | 57-A10 | | Vandalism - Replaced 11 glass panes of the front exterior windows, sealed all panes, and restored access to front of courthouse. Unidentified person broke the glass panes. A boom lift was required to access the windows. | \$ 73,683 | \$ 73,683 | In Work | 100 |
| 35 | FM-2004066 | Los Angeles | Santa Monica Courthouse | 19-AP1 | 1 | Plumbing - Replace failed 1-1/2 inch isolation valve, (2) 1-1/2 inch couplings, install (2) 1.28 gallon floor mount toilets, (2) 1.28 GPM flush valve kits, and 1-inch brass pipe and wax ring. Install 7 \times 7 \times 8 foot containment and cut out 18 \times 18 inch access panel in wall. Two (2) toilets on 2nd floor restroom failed to regulate pressure causing regular overspray onto floor. During replacement the isolation valve failed, requiring replacement. Environmental testing and oversight required. | \$ 14,767 | \$ 14,767 | Complete | 100 |
| 36 | FM-2004069 | Los Angeles | Torrance Annex | 19-C2 | | Plumbing - Domestic Water Pipe Leak - Replaced 40 LF of 1 inch copper pipe and 3/4-inch L-copper piping with hangers. Insulated 70 feet of copper pipe. Extracted 810 SF of water from carpet, erected 24 x 24 x 15 water diverters, covered 520 SF of flooring, and disinfected 1,530 SF hard surfaces. Copper pipes in the basement, cracked due to age and corrosion. Environmental containment and testing was required. | \$ 30,852 | \$ 26,267 | In Work | 85.14 |
| 37 | FM-2004072 | Los Angeles | Santa Monica Courthouse | 19-AP1 | 1 | Roof - Replace (2) ceiling tiles and patch (4) SF of roof material. Water leak was due to rainwater that penetrated the 2nd and 1st floors and impacted court operations. Environmental containment and remediation work performed. | \$ 23,593 | \$ 18,518 | In Work | 78.49 |
| 38 | FM-2004074 | Kern | Ridgecrest- Main Facility | 15-J1 | 1 | HVAC - Replace (1) fan belt, and (4) filters in the package unit. Perform leak check and refill refrigerant. Package unit failed due to age affecting courtroom temperatures. | \$ 2,478 | \$ 2,478 | Complete | 100 |
| 39 | FM-2004075 | San Diego | East County Regional Center | 37-I1 | 1 | HVAC - Replace (1) failed 20HP supply fan motor and VAV Box #10-3 on AHU #10 and replace (1) 30HP failed return fan motor with belts and (1) leaking heating hot water-strainer on AHU #24. Failed components was due to age resulting in both air handler units causing an unbalanced air circulation throughout the floors and resulting in multiple hot calls. | \$ 19,448 | \$ 13,168 | In Work | 67.71 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILI' PROGR | SHARE OF ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|--|-------------|----------|---|--------------------|------------------|----------------------|------------|--|
| 40 | FM-2004076 | San Diego | North County Regional Center - North | 37-F2 | | Plumbing - Sewer Line Leak - Replace 30 LF of 3 inch cast iron pipe, (4) 3 inch couplings, (6) support hangers, (2) SF of plaster ceiling, and (1) SF of fire-rated drywall. Sewer drain line in ceiling cracked due to corrosion and age causing Category 3 water intrusion affecting flooring and plaster ceiling inside in-custody tunnel. Remediation work required to complete work, including setting up (2) containments, cleaning, drying, and sanitizing (4) SF of concrete. | \$ 42,569 | \$ 4 | 2,569 | Complete | 100 |
| 41 | FM-2004081 | Los Angeles | Alhambra Courthouse | 19-I1 | | HVAC - Replace (1) 30 HP motor and (2) pulleys, and associated parts. Air handler #4 supply fan motor failed due to age affecting the temperature throughout the 4th floor. | \$ 20,000 | \$ 1 | 7,200 | In Work | 86.00 |
| 42 | FM-2004090 | Los Angeles | Inglewood Courthouse | 19-F1 | | HVAC - Replace (3) 250-amp fuses inside motor control center (MCC). MCC failure caused Chiller #1 to go offline and caused high temperatures throughout the building. MCC failed due to blown fuses and burnt electrical wiring. One of the fuses failed/overheated causing the burning and failure and chiller shut down. | \$ 5,826 | \$ | 4,344 | Complete | 74.56 |
| 43 | FM-2004099 | Los Angeles | Compton Courthouse | 19-AG1 | | HVAC - Replace (1) 40 HP motor, (3) belts, and associated parts. Air handler #12 supply fan motor failed due to age affecting the HVAC throughout the 12th floor. | 9,344 | \$ | 6,179 | In Work | 66.13 |
| 44 | FM-2004103 | Los Angeles | County Records Center | 19-AV3 | | County Managed - Plumbing - Remove ejector pumps, pump out debris, unclog pumps, re-install, and install catch basket for debris. The sewer ejector pumps are clogged due to public flushing debris and trash items. | \$ 18,600 | \$ 1 | 8,600 | In Work | 100 |
| 45 | FM-2004104 | San Diego | East County Regional Center | 37-I1 | | Plumbing - Replace (1) 2 inch domestic cold-water valve, (1) 1-1/4 inch domestic hot water valve, (1) 1/2 inch recirculation water valve. The kitchen shut off valve are stuck in the open position and can be isolated for general plumbing maintenance, due to the age and corrosion the valve is frozen open and cannot be closed. | \$ 8,707 | \$ | 5,896 | In Work | 67.71 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|---|-------------|----------|---|-----------|--------------------|--|------------|--|
| 46 | FM-2004108 | Los Angeles | Alfred J. McCourtney Juvenile Justice Center | 19-AE1 | 1 | County Managed - Fire Protection - Replace (6) sprinkler heads, (1) riser 3-way valve, (1) gauge, (1) sprinkler head box wrench, (1) FDC (Fire Department Connection) cap. Install FDC, name plate, chain & lock, and repaint piping. Deficiencies found during the 5-year fire sprinkler system test. Repairs are needed in order to pass the 5 year certification. | \$ | 2,012 | \$ 2,012 | In Work | 100 |
| 47 | FM-2004114 | Butte | Butte County Courthouse | 04-A1 | 1 | Exterior Shell - Replaced, textured, and painted 20 SF of leak damaged sheetrock in courtroom and judges chambers. Remediated/sanitized 30 SF of carpet and 10 SF of dry wall in the jury room. Microbial and ACM testing was performed prior and after remediation to all areas affected (approx. 50 sf). Debris from the gutters were removed for proper drainage; a boom lift was needed for access. Rain and leaf debris from the wind and rain event caused the roof gutters to clog and leaked into the walls. The current design of gutter and roof contributes to the leak into the building. A P2 will be opened to assess for corrosion and the leak points of the gutters. | | 74,175 | \$ 74,175 | In Work | 100 |
| 48 | FM-2004121 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | Plumbing - Domestic Water Pipe Leak - Replace 70 LF of copper pipe in different sizes. Erect 12 x 12 x 11 containment with 36 x 76 decontamination chamber. Remove (2) 24 x 24 ceiling tiles and set up (1) 24 x 24 x 11 water divert in basement. Remove and replace 16 LF of insulation. Sanitize 1,140 SF of hard surface and 80 LF of T-bar system. Replace (8) 24 x 24 damaged ceiling tiles. Hot water pipe leak in the ceiling in the basement caused by internal corrosion of copper pipe due to hard water and aging of pipe. Environmental containment and remediation work required. | \$ | 29,433 | \$ 25,059 | In Work | 85.14 |
| 49 | FM-2004122 | Fresno | Fresno County Courthouse | 10-A1 | 1 | HVAC - Replace failed purge system pump, solenoid valve, and sensors for air purge system for Chiller #1. Chiller will not operate reliably without purge system. Purge system pump failed due to age. | \$ | 8,619 | \$ 8,619 | In Work | 100 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|-----------------------|-------------|----------|--|--------------------|---|------------|--|
| 50 | FM-2004125 | San Diego | Hall of Justice | 37-A2 | | Plumbing - Fixture Leak - Replaced 120 SF of drywall, 100 SF of carpet, and 24 LF cove base. Cleaned, dried, and sanitized 160 SF of hard surfaces. A jury deliberation restroom toilet overflowed on the 5th floor affecting the adjacent staff restroom and 4th-floor restroom below which caused a category 3 water intrusion. The jury restroom on the 5th floor was clogged and required 4 feet to be mechanically removed. Remediation and environmental oversight were required to complete the work. | \$ 44,559 | \$ 44,559 | In Work | 100 |
| 51 | FM-2004126 | San Diego | Kearny Mesa Court | 37-C1 | | Roof - Replace (2) 3-inch roof drain pipe couplings, 75 SF carpet tiles and (6) 2 x 4 ft ceiling tiles. Roof drain line leaked Category 2 water intrusion caused by rain affecting the East public corridor and judge's 1st floor entrance to chambers. Remediation work required to complete work including setting up containment, cleaning, drying, and sanitization of 60 SF of concrete and 32 LF of ceiling grid. | \$ 26,859 | \$ 26,859 | Complete | 100 |
| 52 | FM-2004139 | Los Angeles | Burbank Courthouse | 19-G1 | | Exterior shell - Rainwater penetrated through the exterior shell of building through multiple cracks in the concrete affecting basement elevator lobby, hallway to attorney conference rooms, and employee beak room. Environmental and remediation protocols used due to category 2 grey water (1,000 gallons extracted). Repair will be completed under water proofing project. A separate Priority 2 project is in design for basement waterproofing. | \$ 25,000 | \$ 22,690 | In Work | 90.76 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|---|-------------|----------|--|----------------------------|--|------------|--|
| 53 | FM-2004146 | Los Angeles | Santa Clarita Courthouse | 19-AD1 | | County Managed - Plumbing - Retrofit and install new electric water heater, supply and return piping, isolation valves, electrical subpanel, recirculation pump, and expansion tank. The existing domestic hot water is supplied by the County Central Plant located off-site. The current hot water supply and return lines from the central plant have been nonoperational. The source of the issue is underground, but currently undetermined. The new retrofit install will disconnect the domestic hot water from the central plant and supply hot water locally from the basement of the building. | \$ 62,668 | \$ 62,668 | In Work | 100 |
| 54 | FM-2004148 | Los Angeles | Inglewood Courthouse | 19-F1 | | Fire Protection - Repair airlock on diesel jockey pump, replace (2) 6 inch pipes, (1) fuel gauge, and (1) coolant hose on heat exchanger for fire pump. Includes removal, cleanup, and proper disposal of 300 gallons of mixed diesel fuel, engine coolant, and water. Fuel/coolant leak was caused by failed seals on heat exchanger for Fire Pump A. Environmental testing and oversight required. | \$ 23,919 | \$ 17,834 | In Work | 74.56 |
| 55 | FM-2004158 | Los Angeles | County Records Center | 19-AV3 | | County Managed - Vandalism - Remove graffiti, primer, spot primer, repaint stairwells and ceiling in building entrance. Main entrance and entrance stairwells have heavy graffiti and profanity on walls and ceilings. | \$ 31,620 | \$ 31,620 | In Work | 100 |
| 56 | FM-2004199 | | Edmund D. Edelman Children's Court | 19-Q1 | | Roof - Replace sheet metal housing to prevent rainwater from entering 50 SF of ducted screened rooftop economizers vents. Sealed cracks in mechanical and filter rooms where rainwater penetrated to the 6th floor courtroom below. Set up $4 \times 8 \times 10$ ft water diverter, (1) water extractor & carpet cleaner, and (1) water collection barrel. | 33,861 1,447,326 | \$ 23,699 \$ 1,259,157 | In Work | 69.99 |

Meeting Date: 4/10/2023

Action Item 2 – List B – Facility Modifications Under \$100K (Priority 2)

Action Requested:

Approve 90 projects for a total of \$1,005,938 to be paid from Facility Modification program funds previously encumbered for Priority 2 Under \$100,000.

Supporting Documentation:

• List B – Facility Modifications Under \$100K (Priority 2)

Priority 2—Necessary, but Not Yet Critical. Condition requires correction to preclude deterioration, potential loss of function or service, or associated damage or higher costs if correction is further deferred.

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|---|------------|---------------|----------------------------|-------------|----------|--|--------------------|---|------------|--|
| 1 | FM-2002365 | Los Angeles | Inglewood Courthouse | 19-F1 | | HVAC - Rebuild Condenser Water Pump #2. Rewind motor windings, replace seals, gaskets, o-rings, and bearings. Sandblast and paint exterior. Isolate water flow, drain pump section. Setup rigging, remove pump and rebuild. The motor and pump were seized and inoperable due to age. | \$ 8,797 | \$ 6,559 | Complete | 74.56 |
| 2 | FM-2003030 | Los Angeles | Torrance Courthouse | 19-C1 | | Interior Finishes - Replace (1) offset in-floor door closer. The existing door closer for Mens restroom in public hallway on 2nd Floor (South) failed and the door slams shut, disrupting nearby court operations. | \$2,301 | \$ 1,959 | In Work | 85.14 |
| 3 | FM-2003289 | Riverside | Corona | 33-J1 | 2 | COUNTY MANAGED - HVAC - Replace failed boiler. The current boiler is over 20 years old and at the end of its lifecycle. | \$ 6,519 | \$ 6,519 | In Work | 100 |
| 4 | FM-2003886 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | | Elevators, Escalators, & Hoists - Elevator - Replace car rollers on Public Elevator #5. Elevator #5 is making loud noises while elevator is in motion. Existing roller failure is due to part failure. No longer under warranty. | \$ 6,679 | \$ 6,496 | Complete | 97.26 |
| 5 | FM-2003916 | San Francisco | Civic Center Courthouse | 38-A1 | 2 | HVAC - Replace (1) failed reheat pump and supporting VFD. 20 yr old pump motor and VFD failed due to age causing loss of heating. | \$ 14,438 | \$ 14,438 | In Work | 100 |
| 6 | FM-2003930 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | | Elevators, Escalators, & Hoists - Replace 12 coils and contactors, and test to insure proper operation on Escalator #5 located on west side (Grand Street) between 3rd and 4th floors. Existing coils and contactors have shorted due to normal usage and caused escalator to shut down. | \$ 22,515 | \$ 21,898 | In Work | 97.26 |
| 7 | FM-2003950 | Los Angeles | Inglewood Courthouse | 19-F1 | 2 | Elevators, Escalators, & Hoists/ Other - Replace (1) brake module on public elevator 2. Elevator 2 is having continued issues and it was found that the brake module needed to be replaced due to wear and tear. Impacting court operations | \$ 5,658 | \$ 4,219 | Complete | 74.56 |
| 8 | FM-2003955 | San Francisco | Civic Center Courthouse | 38-A1 | | HVAC - Rebuild failed heating hot water pump (HHWP), replace (4) seals, and (2) gaskets. HHWP is leaking and has failed, causing loss of heating hot water capacity. | \$ 8,129 | \$ 8,129 | In Work | 100 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BLIDGET | SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|---------------|-----------------------------------|-------------|----------|---|--------------------|---------------------------------------|-------------------------------|------------|--|
| 9 | FM-2003959 | | Santa Monica Courthouse | 19-AP1 | 2 | HVAC - Replace (1) pneumatic actuator above the ceiling in courtroom. Pneumatic actuator seized due to age and no longer responds to thermostat adjustment. Environmental testing and oversight required. | \$ 4,385 | \$ | 4,385 | Complete | 100 |
| 10 | FM-2003964 | Yolo | Yolo Superior Court | 57-A10 | | Plumbing - Replace (3) domestic water pump mechanical seals. During preventative maintenance, the seals on the water pump were found to be leaking due to age. | \$ 4,293 | \$ | 4,293 | In Work | 100 |
| 11 | FM-2003969 | San Francisco | Polk St. Annex | 38-A2 | 2 | Vandalism - Replace (1) 4 x 12 ft. broken windowpane w/new powder-coated aluminum panel. Unidentified person broke window. | \$ 12,105 | \$ | 12,105 | In Work | 100 |
| 12 | FM-2003984 | | Wakefield Taylor Courthouse | 07-A2 | 2 | Grounds and Parking Lot - Replace an 8×8 foot section of the sidewalk. Sidewalk is lifting caused by adjacent tree roots creating at trip hazard. | \$ 13,811 | \$ | 13,811 | In Work | 100 |
| 13 | FM-2003988 | • | Stockton Courthouse | 39-F1 | 2 | HVAC - Replace solenoid valve for CRAC unit #0101, and recharge refrigerant. Data Room CRAC unit produced low pressure alert and the solenoid valve was found leaking. | \$ 7,134 | \$ | 7,134 | Complete | 100 |
| 14 | FM-2003989 | | Concord Courthouse | 07-D1 | 2 | Vandalism - Reinstall a 2 x 6 foot 1st floor windowpane. Windowpane was damaged by an unidentified person. | \$ 3,507 | \$ | 3,507 | In Work | 100 |
| 15 | FM-2003992 | Contra Costa | Wakefield Taylor Courthouse | 07-A2 | 2 | Grounds and Parking Lot - Excavate a 4 x 4 foot hole next to sidewalk and replace (4) LF of 3-inch storm drain line. Storm drain line collapsed due to age causing the drain to back up. Drain line repairs are required to restore proper drainage from the courthouse. | \$ 22,306 | \$ | 22,306 | In Work | 100 |
| 16 | FM-2003993 | _ | Burbank Courthouse | 19-G1 | 2 | HVAC - Replace (1) hot water heating coil, 15 LF of pipe insulation, and associated fittings. Air handler #4 heating hot water coil has deteriorated due to age, affecting the HVAC throughout the south side of the building. Hot water heating coil has to be fabricated for the custom sized unit. | \$ 37,537 | \$ | 34,069 | In Work | 90.76 |
| 17 | FM-2003994 | Shasta | Main Courthouse | 45-A1 | 2 | Elevator - Replace door sensor controller on Elevator #1 which has failed due to age. | \$ 3,371 | \$ | 2,350 | Complete | 69.71 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-----------|--|-------------|----------|---|--------------------|--|------------|--|
| 18 | FM-2003998 | _ | Civil Complex Center ("CXC") | 30-A3 | | Plumbing - Replace failed 30-gallon commercial water heater. The current water heater is deteriorated and leaking. Work includes lock out, tag out for electrical and work will be completed after hours. | \$ 6,539 | \$ 6,539 | In Work | 100 |
| 19 | FM-2003999 | Riverside | Larson Justice Center | 33-C1 | | Pest control - Install a bird exclusion net on the front of the building as well as the beams between the pillars and ledges by the windows to the left and right of the front entrance. Birds roosting on light fixtures, ledges and beams between the pillars in the front entrance drop feces in a high traffic area causing a health concern to staff and public waiting in the area to access the building. Net is required to prevent access to areas where birds can settle. Because of the closure of Indio Juvenile courthouse, resulting in increased traffic to the courthouse, and public having to wait outside in this area, exclusion netting is required. | \$ 8,079 | \$ 7,868 | In Work | 97.39 |
| 20 | FM-2004000 | | Van Nuys Courthouse West | 19-AX2 | | Vandalism - Replace (1) 120 x 35 inch mirror with safety backing in an existing frame with new sealants and fasteners. The mirror in the mens public restroom on the 5th floor was cracked by unidentified person. | \$ 3,293 | \$ 2,650 | In Work | 80.48 |
| 21 | FM-2004003 | J | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 2 | Interior Finishes - Replace (1) swing gate in 2nd floor courtroom. Swing gate was cracked and failed due to wear and tear. | \$ 2,456 | \$ 2,456 | In Work | 100 |
| 22 | FM-2004013 | Riverside | Banning Justice Center | 33-G4 | 2 | Plumbing - Replace failed 2-inch domestic water backflow. Backflow failed City inspection. Work includes new fittings and couplers, and testing after replacement. | \$ 4,730 | \$ 4,730 | In Work | 100 |
| 23 | FM-2004014 | | Civic Center Courthouse | 38-A1 | 2 | HVAC - Replace 30 feet of 8 inch steel condenser pipe, (4) 8 inch isolation valves/gaskets, 16 feet of 1 inch copper make-up water pipe and (4) 12 inch steel isolation bushings/brackets. 25 year-old cooling tower pipes are corroded due to age and exposure, and need to be replaced to avoid complete failure. | \$ 48,307 | \$ 48,307 | In Work | 100 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BLIDGET | SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|---|-------------|----------|--|--------------------|---------------------------------------|-------------------------------|------------|--|
| 24 | FM-2004024 | Merced | New Merced Courthouse/N Street Building | 24-A8 | 2 | HVAC - Replace failed ignition transformer on hot water boiler. Boiler is not starting. Ignition transformer failed due to age. | \$ 2,639 | \$ | 2,639 | In Work | 100 |
| 25 | FM-2004025 | San Joaquin | Stockton Courthouse | 39-F1 | 2 | HVAC - Replace purge unit solenoid valve on Chiller #1. Valve failed causing air to be induced into the refrigerant system. | \$ 5,460 | \$ | 5,460 | In Work | 100 |
| 26 | FM-2004028 | Kern | Delano/North Kern Court | 15-D1 | 2 | Exterior Shell - Replace (1) 6 x 6 ft dome skylight in the exterior entrance of the courthouse. The acrylic skylight material became brittle, and cracked due to age and exposure to the elements. | \$ 7,265 | \$ | 5,858 | In Work | 80.64 |
| 27 | FM-2004030 | San Diego | North County Regional Center - North | 37-F2 | 2 | Exterior Shell - Replace (1) 85 x 70 inch exterior tempered glass window in criminal business office, 1st floor. Window broke due to falling branch from County landscaping contractor trimming trees at exterior. Claim filed with County of San Diego for reimbursement. | \$ 6,370 | \$ | 6,370 | In Work | 100 |
| 28 | FM-2004035 | San Diego | North County Regional Center - North | 37-F2 | 2 | Exterior Shell - Replace (1) 83 x 81 inch insulated exterior tempered glass window in chambers on 1st floor. The hermetically sealed air space between the double-pane glass window failed, resulting in condensation inside the glass affecting thermal capabilities and potential issues with mold growth. | \$ 8,822 | \$ | 8,822 | In Work | 100 |
| 29 | FM-2004039 | Santa Clara | Morgan Hill Courthouse | 43-N1 | | Vandalism - Replace (1) 7 x 5 ft. cracked insulated glass window panel at 2nd floor clerks office. Requires scissor lift. Court reported cracked window. | \$ 7,075 | \$ | 7,075 | Complete | 100 |
| 30 | FM-2004042 | Los Angeles | Chatsworth Courthouse | 19-AY1 | 2 | Electrical - Replace (120) 12-volt 44 AH batteries for the emergency lighting Inverters. The batteries failed a load test on the annual preventive maintenance due to age. | \$ 32,304 | \$ | 27,071 | In Work | 83.80 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION | PROGRAM BUDGE! SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-----------|--|-------------|----------|---|--------------------|-----------------------|--|------------|--|
| 31 | FM-2004046 | _ | Inglewood Courthouse | 19-F1 | | Electrical - Replace (1) Automatic Transfer Switch (ATS) #4. Existing switch transfers power intermittently and is unreliable. Original equipment is no longer supported by manufacturer requiring replacement. Replacement will ensure that the transfer of power will be reliable when the building is under emergency generation power. Issue found while performing preventative maintenance. | \$ 14,200 | \$ | 10,588 | In Work | 74.56 |
| 32 | FM-2004047 | _ | Inglewood Courthouse | 19-F1 | | Electrical - Replace (1) Automatic Transfer Switch (ATS) #3. Existing switch transfers power intermittently and is unreliable. Original equipment is no longer supported by manufacturer requiring replacement. Replacement will ensure that the transfer of power will be reliable when the building is under emergency generation power. Issue found while performing preventative maintenance. | \$ 14,200 | \$ | 10,588 | In Work | 74.56 |
| 33 | FM-2004049 | | New Merced Courthouse/N Street Building | 24-A8 | | Utilities - Replace leaking fuel pump on emergency generator. Internal case is cracked and cannot be repaired. The fuel pump failed due to age. | \$ 7,086 | \$ | 7,086 | In Work | 100 |
| 34 | FM-2004051 | | New Merced Courthouse/ N Street Building | 24-A8 | | Exterior Shell - Repair water leak at main public stairwell windows. Requires lift and complete removal and resealing of glass panels. Seals on windows have failed and water leaks into building when raining | \$ 23,752 | \$ | 23,752 | In Work | 100 |
| 35 | FM-2004052 | El Dorado | Johnson Bldg. | 09-E1 | | Elevator – Replace (1) set of hydraulic elevator packing seals. Elevator was shuttering and upon further inspection it was determined that the packing seals and gaskets were leaking and failed due to age. | \$ 10,226 | \$ | 10,226 | In Work | 100 |
| 36 | FM-2004053 | | Carol Miller Justice Center Court Facility | 34-D1 | | HVAC - Replace (2) cooling tower bearings and (2) motor drive shafts and sheaves which have failed due to age. During the annual preventative maintenance, bearings, shaft, and drive sheaves were found to be severely degraded and could not be repurposed. | \$ 7,036 | \$ | 7,036 | In Work | 100 |

| 27 | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|---|-------------|----------|--|-----------|--------------------|--|------------|--|
| 37 | FM-2004054 | San Mateo | Northern Branch Courthouse | 41-C1 | | Plumbing - Replace 10 feet of cracked 4 inch roof drain piping, (1) wye joint, and (3) no-hub connections at basement file storage room, remediate water and test all affected areas. Drain pipe failed due to age during rain event, causing flooding. | \$ | 11,527 | \$ 9,592 | In Work | 83.21 |
| 38 | FM-2004055 | Merced | Los Banos Division - The Robert M. Falasco Justice Center | 24-G1 | 2 | Exterior Shell - Install concrete and cages for (3) backflow preventers along public street. Backflows for water main, fire-water, and landscaping have been opened and winter protective covers removed by unidentified persons. | \$ | 22,365 | \$ 22,365 | In Work | 100 |
| 39 | FM-2004057 | Santa Clara | Hall of Justice (East) | 43-A1 | 2 | HVAC - Replace (1) failed dryer on controls air compressor and (2) failed pneumatic thermostats in courtroom. Failed air dryer allowed moisture into airlines which caused thermostats to fail affecting temperatures. | \$ | 3,465 | \$ 3,465 | Complete | 100 |
| 40 | FM-2004059 | San Diego | North County Regional Center - South | 37-F1 | 2 | Grounds and Parking Lot - Replace (2) failing 120V/230VAC control systems for sliding gate operators of judges vehicle gate. The current controls are past useful life and resulting in gate being stuck open or closed creating entrance and egress issues. Work includes disconnect/reconnect of power and signal to existing control system, adjustment of all keypads, and sensor loops. | \$ | 67,104 | \$ 67,104 | In Work | 100 |
| 41 | FM-2004061 | Santa Clara | Morgan Hill Courthouse | 43-N1 | 2 | Plumbing - Replace (2) check valves and (2) float switches at sewage lift station, and pump out pit with vacuum truck. Work requires 3-person team for confined space protocol safety. Lift station check valves have failed due to wear, causing pump to continuously run. | \$ | 11,015 | \$ 11,015 | In Work | 100 |
| 42 | FM-2004062 | San Diego | South County Regional Center | 37-H1 | 2 | COUNTY MANAGED - HVAC - Replace (2) 40 HP chilled water pumps and motors that serves the entire building. Severe corrosion was found due to age and requires replacement of the pump. The pump is at end of life and failure to replace will leave the building with insufficient cooling. | \$ | 55,035 | \$ 55,035 | In Work | 100 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION | PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|-------------------------------|-------------|----------|---|--------------------|-----------------------|--|------------|--|
| 43 | FM-2004065 | Los Angeles | Pasadena Courthouse | 19-J1 | | Fire Protection - Replace (1) 3-gallon fire suppression tank, (1) CO2 cartridge, (1) extinguishing hose, and (3) fusible links for kitchen hood fire suppression system. Deficiencies were found during annual kitchen hood inspection. | \$ 3,334 | \$ | 2,312 | In Work | 69.35 |
| 44 | FM-2004070 | Kern | Bakersfield Superior Court | 15-A1 | 2 | Elevators, Escalators, & Hoists - Replace (1) emergency stop switch on Down escalator. Emergency stop switch failed due to age Discovered during annual inspection. | \$ 6,453 | \$ | 4,033 | In Work | 62.50 |
| 45 | FM-2004071 | Kern | Bakersfield Superior Court | 15-A1 | 2 | Elevators, Escalators, & Hoists - Replace (1) emergency stop switch on Up Escalator. Emergency stop switch failed due to age. Discovered during annual inspection | \$ 6,453 | \$ | 4,033 | In Work | 62.50 |
| 46 | FM-2004087 | Stanislaus | Turlock Superior Court | 50-D1 | 2 | Security - Replace ballast and lamps in (3) parking lot lights. Ballasts have failed due to age (lift required). | \$ 3,441 | \$ | 3,441 | In Work | 100 |
| 47 | FM-2004091 | Ventura | Juvenile Courthouse | 56-F1 | 2 | Grounds and Parking Lot - Replace (4) 20 foot poles and light fixtures in the parking lot. Two light poles fell during high winds and the bases on all (4) were found to be rusted out. | \$ 28,789 | \$ | 28,789 | In Work | 100 |
| 48 | FM-2004092 | Santa Clara | Palo Alto Courthouse | 43-D1 | 2 | Vandalism - Unclog toilet and floor drain, snake line, and clean/disinfect cat 3 water flooded areas. In-custody threw lunch bag and lunch in toilet causing sewer backup at holding cell. | \$ 7,178 | \$ | 7,178 | In Work | 100 |
| 49 | FM-2004095 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 2 | Plumbing - Sewer Pipe Leak - Replace 30 LF of 3-inch cast iron pipe and associated fittings. Replace (3) 3-inch heavy duty couplings. Build 15 x 15-foot containment and perform demolition and build-back of 12 x 3 ft, and plaster. Remove and build back 3 x 2 ft of plaster ceiling. Sanitize area. Environmental testing and oversight required. | \$ 42,666 | \$ | 33,928 | In Work | 79.52 |
| 50 | FM-2004097 | Santa Clara | Downtown Superior Court | 43-B1 | 2 | HVAC - Replace (1) control transformer, repair (1) leaking flair fitting, and top off refrigerant on cooling unit #1. Control failed due to age causing loss of cooling. Small leak was found during repair. | \$ 2,840 | \$ | 2,840 | In Work | 100 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|----------------------------|-------------|----------|---|--------------------|--|------------|--|
| 51 | FM-2004105 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | Fire Protection - Replace (2) failed fan motors located in stairwells #4 and #6. Replace (1) mag lock/relay in stairwell at G level that failed to de-energize at time of inspection. (6) doors inspected failed to close when stairwell is pressurized. Discovered during rounds and readings. Subsequent inspection identified stairwell fans were not maintaining sufficient pressure to keep fire rating. | \$ 12,925 | \$ 9,974 | In Work | 77.17 |
| 52 | FM-2004106 | Alameda | Hayward Hall of Justice | 01-D1 | 2 | HVAC - Replace (1) 5-ton compressor for AC-2. Compressor locked up due to age causing loss of cooling to court IT room. | \$ 16,554 | \$ 16,554 | In Work | 100 |
| 53 | FM-2004107 | Alameda | Hayward Hall of Justice | 01-D1 | 2 | Fire protection - Replace 35 non-compliant fire hoses. During state inspection, existing fire hoses were non compliant due to expiration date. | \$ 24,222 | \$ 21,388 | In Work | 88.30 |
| 54 | FM-2004110 | Santa Clara | Hall of Justice (West) | 43-A2 | 2 | Plumbing - Vacuum/clear out sewage pit, and pull pump. Replace (2) check valves and (2) floats. Work requires 3-person team for confined space protocol safety. Check valves failed due to age, causing sewage pump station to backup. | \$ 11,015 | \$ 11,015 | In Work | 100 |
| 55 | FM-2004112 | Los Angeles | Santa Monica Courthouse | 19-AP1 | 2 | Plumbing - Replace (1) domestic hot water pump, motor, gaskets, bolts, flange and 10 LF of electrical flexible conduit and electrical conductors. Pump has failed and is leaking. | \$ 6,969 | \$ 5,470 | In Work | 78.49 |
| 56 | FM-2004116 | Santa Clara | Downtown Superior Court | 43-B1 | 2 | HVAC - Replace (1) 5 hp, 3ph, VFD ready fan motor, reinstall blower wheel, and set clearances. AHU-37 fan motor failed due to age causing loss of comfort air. | \$ 9,052 | \$ 9,052 | In Work | 100 |
| 57 | FM-2004117 | Santa Clara | Santa Clara Courthouse | 43-G1 | 2 | HVAC - Repair building automation system control, replace and/or confirm status of (4) sensors at boiler and zone 1. Sensors failed due to age. Found during scheduled preventative maintenance. | \$ 5,464 | \$ 5,464 | In Work | 100 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BLIDGET | SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|---|-------------|----------|--|--------------------|---------------------------------------|-------------------------------|------------|--|
| 58 | FM-2004120 | Santa Clara | Santa Clara Courthouse | 43-G1 | 2 | Plumbing – Remediate domestic water leak from 1st floor drinking fountain, test area, extract water, dehumidify, patch basement ceiling and 1st floor/basement walls, retest for occupancy, decommission drinking fountain. Water supply line to fountain leaked due to age, causing damage to 1st floor and basement. | \$ 8,552 | \$ | | In Work | 100 |
| 59 | FM-2004123 | Solano | Hall of Justice | 48-A1 | 2 | HVAC - Replace (1) VAV heating hot water coil (VAV 3-13), located on 3rd floor. Heating coil has failed due to age and replacement is required to restore proper temperature control. | \$ 9,066 | \$ | 9,066 | In Work | 100 |
| 60 | FM-2004124 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 2 | Fire Protection - Replace the seals and gaskets, and hardware accessories on fire pump discovered to have failed during an annual Preventive Maintenance. | \$ 9,661 | \$ | 7,509 | In Work | 77.72 |
| 61 | FM-2004127 | Sacramento | Gordon Schaber Sacramento Superior Court | 34-A1 | 2 | Elevator - Replace circuit board for Elevator #1. Elevator has stalled because of failed circuit board due to age. | \$ 2,546 | \$ | 2,546 | In Work | 100 |
| 62 | FM-2004129 | San Joaquin | Stockton Courthouse | 39-F1 | 2 | Elevator - Replace failing main brake, and emergency brake control modules. Clean hoistway interlock contacts. Cab is variably not responding to call button, not opening doors, and running at too fast a speed indicating failed control modules. | \$ 15,814 | \$ | 15,814 | In Work | 100 |
| 63 | FM-2004130 | Santa Clara | Hall of Justice (East) | 43-A1 | 2 | Grounds - Remove (1) dying Japanese maple tree, and trim dead and overhanging limbs from (7) Raywood Ash trees. Trees are located in the secure parking area presenting a safety hazard to people and vehicles. | \$ 6,329 | \$ | 6,329 | In Work | 100 |
| 64 | FM-2004133 | Kings | Kings Superior Court | 16-A5 | 2 | Elevators, Escalators, & Hoists - Replace seismic switch for elevators #1, #2 & #5. Existing switches are failing and need to be replaced for continuing operation of elevators. | \$ 6,399 | \$ | 6,399 | In Work | 100 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|--|-------------|----------|--|--------------------|---|------------|--|
| 65 | FM-2004136 | Orange | North Justice Center | 30-C1 | | HVAC - Replace failed cooling tower sealer and tape with new two-part urethane membrane sealant. The cooling tower is currently leaking from the seams. Replacement is necessary to avoid further water loss and damage/degradation to the cooling tower. | \$ 12,252 | \$ 11,06 | 5 In Work | 90.31 |
| 66 | FM-2004137 | San Diego | Juvenile Court | 37-E1 | | Interior Finishes - Replace (1) cipher key pad lock with key access override option to womens employee restroom on the 2nd floor. The current lock failed due to age and prevented staff from accessing the restroom. | \$ 2,437 | \$ 1,81 | 8 In Work | 74.62 |
| 67 | FM-2004140 | Los Angeles | Glendale Courthouse | 19-H1 | 2 | Interior Finishes - Replace (1) exit door floor closer. Door closure failed due to age causing the door to slam, creating a safety hazard. | \$ 3,655 | \$ 3,30 | 9 In Work | 90.54 |
| 68 | FM-2004141 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 2 | HVAC - Replace (1) supply fan motor bearing set. Parts have failed due to age. This was found during rounds & readings. | \$ 4,570 | \$ 3,67 | 8 In Work | 80.48 |
| 69 | FM-2004144 | Santa Clara | Family Justice Center Courthouse | 43-B5 | | Exterior Shell - Replace failed ADA balance door closer. Remove door, replace built in closer, reinstall door and set ADA opening pressure and closing speed. Front entrance ADA door closer failed due to use. | \$ 11,222 | \$ 11,22 | 2 In Work | 100 |
| 70 | FM-2004149 | Orange | Harbor Justice Center- Newport Beach Facility | 30-E1 | | Plumbing - Replace (2) failed water isolation valves, (1) hot and (1) cold, that supply water to two restrooms in the District Attorney office. The valves were exercised and did not turn off. Required to address sink and toilet issues within the restroom. Work includes full drain down of the building, re-fill and bleeding the system of air, and checking for leaks. | \$ 3,467 | \$ - | In Work | 0.00 |
| 71 | FM-2004150 | Madera | Main Courthouse - Madera | 20-F1 | | Elevators, Escalators, & Hoists - Replace outdoor clutch on Elevator #5. Clutch failed due to age and elevator is inoperable without repairs. | \$ 4,369 | \$ 4,36 | 9 In Work | 100 |

| 72 | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|-------------|--|-------------|----------|---|--------------------|--|------------|--|
| 72 | FM-2004151 | Fresno | Fresno County Courthouse | 10-A1 | 2 | HVAC - Repair fan housing for return fan for 6th floor AHU serving court exclusive area. Return fan motor is currently non-operational. Repair includes shaft repair, bearing, motor, sheaves, belts, and fan housing. | \$ 30,428 | \$ 30,428 | In Work | 100 |
| 73 | FM-2004152 | Fresno | Fresno County Courthouse | 10-A1 | 2 | HVAC - Replace failed air-drier on control air compressor. Heater in air-drier has failed due to age. | \$ 8,085 | \$ 7,754 | In Work | 95.91 |
| 74 | FM-2004153 | Orange | Harbor Justice Center- Newport Beach Facility | 30-E1 | 2 | HVAC - Replace (2) failed motor cooling solenoids and (1) butterfly valve of chiller. One solenoid and the butterfly valve are leaking refrigerant. One solenoid is stuck open and does not regulate the refrigerant. Work includes recovering and re-charge of existing refrigerant. | \$ 10,601 | \$ 8,939 | In Work | 84.32 |
| 75 | FM-2004157 | San Mateo | Central Branch | 41-B1 | 2 | Security - Replace (1) failed drive belt, and install (2) new surface mounted sweeps. The facility was recently reopened after 5 years. Lack of use caused the rubber drive belt to crack and break during operation. The sweeps were replaced due to age. | \$ 5,170 | \$ 5,170 | In Work | 100 |
| 76 | FM-2004159 | Santa Clara | Palo Alto Courthouse | 43-D1 | | Holding cell - Replace (1) 33 x 32 inch broken security window, and install (3) new institutional security hinges. Door from Sheriffs work area to holding hallway was stuck closed due to misalignment from ground shifting. Window broke when door was forced open. | \$ 8,732 | \$ 8,732 | In Work | 100 |
| 77 | FM-2004160 | Los Angeles | Santa Monica Court Annex | 19-AP3 | 2 | HVAC - Replace (1) A/C split system condensing unit. The unit is failing due to age and is not providing cooling. Parts are no longer available. | \$ 21,401 | \$ 16,798 | In Work | 78.49 |
| 78 | FM-2004161 | Los Angeles | Bellflower Courthouse | 19-AL1 | 2 | Fire Protection - Replace (2) 4 inch gate valves and associated fittings for fire sprinkler system in 2nd and 3rd floor fan rooms. Gate valves are leaking and corroded due to age. | \$ 7,057 | \$ 5,500 | In Work | 77.94 |
| 79 | FM-2004165 | Fresno | Fresno County Courthouse | 10-A1 | 2 | Fire Protection - Replace 30 self-illuminating exit signs throughout building. Exit signs failed during fire inspection and need to be replaced due to age. | \$ 28,406 | \$ 27,244 | In Work | 95.91 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|--------------|---|-------------|----------|---|--------------------|---|------------|--|
| 80 | FM-2004166 | Monterey | Salinas Courthouse- North Wing | 27-A1 | | Elevator - Replace the hydraulic jack packing on Elevator #4. Required to prevent failure of the only working in-custody elevator. A study is being undertaken for the modernization of the elevators at this facility. | \$ 18,023 | \$ 18,023 | In Work | 100 |
| 81 | FM-2004168 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 2 | HVAC - Replace (2) flex connectors on condenser water lines on Chiller #2. Flex couplings on chiller have cracks and need to be replaced due to age. | \$ 4,679 | \$ 3,721 | In Work | 79.52 |
| 82 | FM-2004170 | Santa Clara | Hall of Justice (East) | 43-A1 | 2 | Plumbing - Isolate 2nd floor water main, replace isolation valve, and restore water flow. Isolation valve failed due to age, preventing water from coming into the combi toilet unit for holding cell. | \$ 5,563 | \$ 5,563 | In Work | 100 |
| 83 | FM-2004171 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | HVAC - Replaced (6) 12 x 12 in. ceiling tiles in 5th floor courtroom. Cold deck damper actuator was seized in place and would not open and close based on temperature set point causing cold temperatures in courtroom. Replaced existing thermostat, pneumatic line kit, and calibrated thermostat. Remediation and environmental oversight required to complete work. | \$ 13,201 | \$ 13,201 | Complete | 100 |
| 84 | FM-2004173 | Kings | Kings Superior Court | 16-A5 | 2 | Elevators, Escalators, & Hoists - Replace failed batteries (one 7AH and two 3.3 AH) on Elevators #1 through #5 which failed due to age. | \$ 6,826 | \$ 6,826 | In Work | 100 |
| 85 | FM-2004175 | San Joaquin | Stockton Courthouse | 39-F1 | 2 | Elevators, Escalators, & Hoists - Replace damaged handrail on Escalator #3. Handrail has a large crack in it from an unknown cause. | \$ 15,763 | \$ 15,763 | In Work | 100 |
| 86 | FM-2004176 | Contra Costa | Richard E. Arnason Justice Center | 07-E3 | 2 | Elevators, Escalators, & Hoists - Replace failing oil scavenger pump/tank from pit to the tank that failed and caused oil to leak onto the floor. | \$ 7,198 | \$ 7,198 | In Work | 100 |
| 87 | FM-2004179 | Los Angeles | Downey Courthouse | 19-AM1 | 2 | HVAC – Replace chemical feeder system for cooling towers. Existing chemical delivery system has failed due to age restricting water flow to the cooling towers affecting the HVAC throughout building. | \$ 4,789 | \$ 4,008 | Complete | 83.70 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|----|------------|----------|------------------------------------|-------------|----------|--|------|--------------------|--|------------|--|
| 88 | FM-2004180 | | George D. Carroll Courthouse | 07-F1 | | HVAC - Replace Compressor #2 contactor (right side) and Compressor #1 crankcase heater on Chiller in 3rd floor mechanical room. Found to have failed during annual preventative maintenance. | \$ | 5,444 | \$ 4,203 | In Work | 77.20 |
| 89 | FM-2004182 | _ | Beverly Hills Courthouse | 19-AQ1 | | HVAC - Replace (2) flex connectors on condenser water lines on Chiller #1. Flex couplings on chiller have cracks and need to be replaced due to age. | \$ | 4,679 | \$ 3,721 | In Work | 79.52 |
| 90 | FM-2004193 | | Fremont Hall of Justice | 01-H1 | | Roof - Patch/repair 830 SF waterproofing at roof and parapet walls above chiller. Roof is leaking above chiller due to age, causing minor flooding. | | 10,235 | | In Work | 79.40 |
| | | | | | | | \$1, | 077,809 | \$ 1,005,938 | | |



Meeting Date: 4/10/2023

Action Item 3 – (Action Required) - List C – Cost Increases Over \$50K

Action Requested:

Approve cost increases of over \$50K for four (4) facility modification projects, for a total cost increase to the Facility Modification program budget of \$4,094,506.

Supporting Documentation:

• List C – Cost Increases Over \$50K Report

| | LOCATIONB3 | FACILITY NAME | BUILDING ID | FM NUMBER | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF TCFMAC FUNDED COST | CURRENT COST ESITMATE | FACILITY MODIFICATION | PROGRAM BUDGET SHARE OF CURRENT COST ESTIMATE | NOTES | TOTAL COST INCREASE | FACILITY MODIFICATION PROGRAM COST INCREASE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|---|------------|------------------------|-------------|----------------|----------|---|--------------------|-------------|--|-----------------------|-----------------------|---|---|---------------------|--|------------|--|
| | | Courthouse Annex | 40-A1 | 2002598 | | COUNTY MANAGED - Roof - Replace appx. 16,500 sq ft of single ply roof system, replace appx. 3,400 sq ft of compromised skylight roofing system. The existing roof is at the end of its life-cycle and roof replacement is recommended based on a building | \$ 392,449 | > | \$ 392,449 | \$ 892,449 | \$ | 892,449 | The original approval was based on the estimate; the cost increase is based on the actual bid. | \$ 500,000 | \$, | In Work | 100 |
| 3 | | Whittier Courthouse | 19-AO1 | FM- 0142703 | 2 | assessment done by the county in February 2017. HVAC - Phase 2 - Phase 2 is the completion of the miscellaneous HVAC and plumbing work to make the equipment compatible with the new BMS system, as well as the installation of the new BMS system. | 1,216,855 | \$ | \$ 1,051,728 | \$ 1,323,522 | \$ | | The work was delayed by 20 months due to ongoing supply chain issues with the mechanical and electrical systems material and equipment. This delay to the project | \$ 106,667 | \$ 92,192 | In Work | 86.43 |
| | | | | | | | | | | | | | schedule has resulted in additional soft costs for the Judicial Council. | | | | |

| | LOCATIONB3 | FACILITY NAME | BUILDING ID | FM NUMBER | PRIORITY | SHORT TITLE | TCFMAC FUNDED COST | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF TCFMAC FUNDED COST | CURRENT COST ESITMATE | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF CURRENT COST ESTIMATE | NOTES | TOTAL COST INCREASE | FACILITY MODIFICATION PROGRAM COST INCREASE | JOB STATUS | FACILITY MODIFICATION PROGRAM BUDGET % OF COST |
|---|------------|-------------------------------|-------------|----------------|----------|--|--------------------|--|-------------------------------|---|--|---------------------|--|------------|--|
| 3 | | Compton Courthouse | 19-AG1 | FM- 2002964 | | HVAC - GCI - General Contractor to provide construction services for the removal and replacement of two failing cooling towers. The existing cooling towers have failed causing hot temperatures throughout the building and the chillers are unable to cool the building. Temporary cooling towers are to be provided for temporary relief and replacement. The existing cooling tower structural support has also corroded and will be replaced. The cooling towers and structural support have failed due to age. | \$ 4,883,277 | \$ 3,229,311 | \$ 4,943,890 | \$ 3,269,394 | Cost increase is due to additional abatement scope that is required for the existing roof, fire-proofing, and ceiling tile in the courtroom below to accommodate the structural framing. | \$ 60,613 | \$ 40,083 | In Work | 66.13 |
| 4 | Solano | Solano Justice Building | 48-B1 | FM- 2000173 | | COUNTY MANAGED PROJECT - HVAC - Construction Phase - Full Air Handler and Controls Replacement, including 58 VAV boxes, energy management system upgrade, and roofing haz-mat abatement. Equipment is beyond end of life and replacement will eliminate downtime, increase court occupant comfort, and be more energy efficient. Design phase was completed under FM-0142543. | | \$ 2,876,580 | \$ 6,338,811 \$ 13,498,672 | | Due to the ongoing energy savings and infrastructure project, the county did not go out to bid on this project until now. | \$ 3,462,231 | \$ 3,462,231 | In Work | 100 |

Action Item 4 – (Action Required) - List D – Facility Modifications Over \$100K (Priority 2)

Action Requested:

Approve 12 Priority 2 FMs over \$100K for a total cost to the Facility Modification Program budget of \$5,126,197.

Meeting Date: 4/10/2023

Supporting Documentation:

• List D – Facility Modifications Over \$100K Report

Priority 2—Necessary, but Not Yet Critical. Condition requires correction to preclude deterioration, potential loss of function or service, or associated damage or higher costs if correction is further deferred.

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION | PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | CUMULATIVE TOTAL OF | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM % OF COST |
|---|------------|------------------|--|-------------|----------|--|----------------------|-----------------------|--|---------------------|---|--|
| 1 | FM-2004119 | | North County Regional Center - North | 37-F2 | | Interior Finishes - GCI - Perform repairs to the ceiling attachment clips that are currently supporting ceiling panels, lights, pipes and conduits; provide compression posts and lateral seismic bracing and supports for water lines based on recommendations from the assessment report by the structural engineer. | \$ 487,500 | \$ | 487,500 | \$ | 487,500 | 100 |
| 2 | FM-2003952 | San Diego | North County Regional Center - North | 37-F2 | | Interior Finishes - GCI - Perform repairs to Department No. 12 which involves the repair and/or replacement of failed/fallen damaged ceiling, HVAC, Electrical, Lighting, Fire Alarm System, Interior Finishes, and path of travel improvement at front entrance. | \$ 651,617 | \$ | 651,617 | \$ | 1,139,117 | 100 |
| 3 | FM-2004115 | Santa Cruz | Main Courthouse | 44-A1 | | Plumbing - Replace 140 feet of 6-in. cast iron sewer line with new plastic pipe, and install (3) new clean-out wyes. 60-yr old sewer line has failed in several sections with root intrusion and low spots, it continues to clog causing interruption to court operations. Hydro-flush and auger failed to eliminate line clogs. | \$ 122,827 | \$ | 121,734 | \$ | 1,260,851 | 99.11 |
| 4 | FM-2004262 | San Francisco | Hall of Justice | 38-B1 | | County Managed - HVAC - Repair boilers 1, 2 & 3. Existing 64-year old boilers require repairs to the boiler refractory and replacement of the tubes. Repairs are required to keep the boilers operational as they have exceeded their useful lifespan. | \$ 848,990 | \$ | 848,990 | \$ | 2,109,841 | 100 |
| 5 | FM-2004118 | San Diego | East County Regional Center | 37-I1 | | Exterior Shell - AEI - Design to provide construction documents and permitting for the replacement of the exterior insulation finish system (EFIS). The existing EIFS is in poor condition with numerous open holes and splits in the exterior finish allowing for water entry. | \$ 375,000 | \$ | 253,913 | \$ | 2,363,754 | 67.71 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION | PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | CHIMILI ATIVE TOTAL OF | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM % OF COST |
|----|------------|----------------|--|-------------|----------|---|----------------------|-----------------------|--|------------------------|---|--|
| 6 | FM-2002256 | Merced | Los Banos Division - The Robert M. Falasco Justice Center | 24-G1 | | Interior Finishes - GCI - Replace existing wood ceiling panels roughly 500 SF above the entries of Rm 208 and 227 at 2nd floor hallway 205. The decorative ceiling has fallen down in the lobby because of the attachment failure. | \$ 140,532 | \$ | 140,532 | \$ | 2,504,286 | 100 |
| 7 | FM-2003953 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | | Electrical - Emergency Light and Power Systems - Generator #1, Diesel Replacement. The existing generator does not meet the requirements for the Air Quality Management District (AQMD) and is failing due to age. | \$ 495,000 | \$ | 481,437 | \$ | 2,985,723 | 97.26 |
| 8 | FM-2003926 | Los Angeles | Airport Courthouse | 19-AU1 | | Interior Finishes - Replace 116 audience chairs in Department 31 courtroom. More than 35 chairs in various rows are broken, posing a health and safety risk. Fixed chairs in each row are connected and cannot be replaced individually. Environmental testing and oversight required. | \$ 100,001 | \$ | 100,001 | \$ | 3,085,724 | 100 |
| 9 | FM-2002139 | Los Angeles | Burbank Courthouse | 19-G1 | | Exterior Shell - Excavate, remove, and install waterproofing at the exterior of the building. Water intrusion at the sub-grade level around the perimeter of the building is causing damage to the interior areas including entryway, basement tunnel, and cafeteria. | \$ 701,399 | \$ | 636,590 | \$ | 3,722,313 | 90.76 |
| 10 | FM-2003077 | San Diego | North County Regional Center - South | 37-F1 | | COUNTY MANAGED - Exterior Shell - Design and Construction - Repair failed glazing and exterior reveal/reglet strips of windows and stucco cracks on walls of the 5-Story building. During wet weather events, the windows leak, due to age, resulting in water intrusion and damage to interior drywall. Work includes testing to ensure proper building envelope protection. Most areas will be accessible by building facade swing-stage and roof davits with some sections requiring a lift. | \$ 537,920 | \$ | 537,920 | \$ | 4,260,233 | 100 |

| | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | MOLENDING WAY WELLING AT | FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE | CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM % OF COST |
|----|------------|----------|--|-------------|----------|--|----------------------|--------------------------|--|---|--|
| 11 | FM-2004174 | Ventura | Hall of Justice | 56-A1 | 2 | COUNTY MANAGED - Grounds and Parking Lot - Phase II of IV - Remove and replace 2,024 SF of concrete side walk. Remove and replace 8,206 SF of concrete pavers. Remove 6 trees & replace w/3 new trees & wrought iron grates. Re-compaction of subgrade and replacement as needed. A large section of walkway pavers were demolished to replace damaged storm drain in the underground parking. The existing tiles are over 45 yrs old & no longer available. The subgrade has failed throughout the walking areas. | \$ 202,460 | \$ | 202,460 | \$ 4,462,693 | 100 |
| 12 | FM-2003499 | Orange | Harbor Justice Center- Newport Beach Facility | 30-E1 | 2 | Grounds and Parking Lot - GCI - Replace 170,000 sf (4 inches deep) of deteriorated, loose and uneven asphalt pavement. This is a heavily travelled area by both automobile and pedestrian traffic and is a safety hazard with documented tripping incidents. Work includes replacement of 180 LF of 6 inch broken concrete curb, removal and stump grinding of (7) trees with roots impacting asphalt and concrete, restriping of approx. 621 public and 20 secured parking stalls (per existing layout) and repainting of the fire curbs. | \$ 786,888 | \$ | 663,504 | \$ 5,126,197 | 84.32 |
| | | | | | | | \$ 5,450,134 | \$ | 5,126,197 | | |

Meeting Date: 4/10/2023

Action Item 5 – October Meeting Travel Plans (Action Required)

Action Requested:

Approve one of the following options for October off-site courthouse tours and committee meeting on October 26th and 27th:

Option 1 (Los Angeles)

- Day 1 Tour Compton, Stanley Mosk, and Clara Shortridge Foltz courthouses
- Day 2 Committee meeting and tour of the Van Nuys courthouse

Option 2 (Orange)

- Day 1 Tour Central Justice Center and North Justice Center courthouses
- Day 2 Committee meeting and tour of the Long Beach courthouse

Supporting Documentation:

• See presentation

Action Item 5 October Meeting – Travel Plans

Option 1 (Los Angeles)

- Day 1 Tours
 - Compton Courthouse
 - Stanley Mosk Courthouse
 - Clara Shortridge Foltz Criminal Justice Center
- Day 2 Committee Meeting and Tour
 - Tour Van Nuys East/West Courthouse Approx. 8:00 AM
 - Meeting at Van Nuys East/West Courthouse 10:00 AM 3:00 PM

Action Item 5 October Meeting – Travel Plans

Option 2 (Los Angeles/Orange)

- Day 1 Tours
 - Central Justice Center (Santa Ana)
 - North Justice Center (Fullerton)
- Day 2 Committee Meeting and Tour
 - Tour Long Beach Courthouse Approx. 8:00 AM
 - Meeting at Long Beach Courthouse 10:00 AM 3:00 PM

Action Item 5 October Meeting — Travel Plans Option 1 — Los Angeles Option 2 — Los Angeles / Orange Van Nuys Van Nuys Separation Separation Separation Separation Stanton Anahelim Anahelim Stanton Anahelim Anahelim Stanton Anahelim Anahelim Anahelim Anahelim Anahelim Anahelim Anahelim Anahelim



Meeting Date: 4/10/2023

Action Item 6 – (Action Required) – Trial Court Facility Modifications Report for Quarter 3 of Fiscal Year 2022–23

Action Requested:

Approve draft *Trial Court Facility Modifications Report for Quarter 3 of Fiscal Year* 2022–23, to be submitted to the Judicial Council as an Information-Only item.

Supporting Documentation:

• Draft Trial Court Facility Modifications Report for Quarter 3 of Fiscal Year 2022–23



Judicial Council of California

455 Golden Gate Avenue · San Francisco, California 94102-3688

www.courts.ca.gov

REPORT TO THE JUDICIAL COUNCIL

Item No.: 23-003
For business meeting on: May 11–12, 2023

Title

Court Facilities: Trial Court Facility Modifications Report for Quarter 3 of Fiscal Year 2022–23

Submitted by

Trial Court Facility Modification Advisory
Committee
Hon. Donald Cole Byrd, Chair

Hon. William F. Highberger, Vice-Chair

Agenda Item Type Information Only

Date of Report March 30, 2023

Contact

Pella McCormick, 916-643-7024 pella.mccormick@jud.ca.gov Tamer Ahmed, 916-643-6917 tamer.ahmed@jud.ca.gov Jagan Singh, 415-865-7755 jagandeep.singh@jud.ca.gov

Executive Summary

This informational report to the Judicial Council outlines the allocations of facility modification funding made to improve trial court facilities in the third quarter (January through March) of fiscal year 2022–23. To determine allocations, the Trial Court Facility Modification Advisory Committee reviews and approves facility modification requests from across the state in accordance with the council's *Trial Court Facility Modifications Policy*.

Relevant Previous Council Action

This report is submitted quarterly as required by the Judicial Council's *Trial Court Facility Modifications Policy* (see Link A). Most recently, on March 24, 2023, the council received the quarterly report for the second quarter for fiscal year (FY) 2022–23 (see Link B).

¹ Per this policy, each quarterly report includes a list of all facility modifications funded during the quarter as well as any reallocation of funds between the funding categories (i.e., facility modification priority categories 1–6).

Analysis/Rationale

Funding review

Funding decisions were based on the prioritization and ranking methodologies of the *Trial Court Facility Modifications Policy*. There are six priority categories of facility modifications (FM):

- Priority 1, Immediately or Potentially Critical;
- Priority 2, Necessary, but Not Yet Critical;
- Priority 3, Needed;
- Priority 4, Does Not Meet Current Codes or Standards;
- Priority 5, Beyond Rated Life, but Serviceable
- Priority 6, Hazardous Materials, Managed but Not Abated.

The current level of funding allows the Trial Court Facility Modification Advisory Committee (TCFMAC) to address only the most critically needed Priority 1 and 2 and some Priority 3 facility modifications statewide.

FM requests are also reviewed and approved in accordance with the Judicial Council's *Court-Funded Facilities Request Policy* (see Link C). This policy presents the procedures and requirements to allow trial courts to make court-funded facilities requests (CFRs). Trial courts may assist with the funding of certain facilities costs (i.e., facility modifications and lease-related costs) by contributing funds toward urgent facilities costs—not including capital-outlay expenses—through allocation reductions from the Trial Court Trust Fund.

Allowable facilities costs that a trial court can fund through a CFR include (1) FMs as defined in the *Trial Court Facility Modifications Policy*; (2) court operations costs allowable under rule 10.810 of the California Rules of Court, such as equipment, furnishings, interior painting, flooring replacement or repair, furniture repair, and records storage; and (3) lease-related costs, such as lease payments and operating costs, repairs, and modifications authorized by a lease. CFRs are approved by Judicial Council staff, with the following exceptions, which require TCFMAC review and approval: ongoing operational cost increases to the Judicial Council beyond the initial outlay for the project (e.g., additional utility or maintenance costs); staff concerns about whether the CFR meets the policy's criteria or whether the proposed budget is accurate; and appeals of staff determinations.

Fiscal Impact and Policy Implications

Third quarter FY 2022-23

During the third quarter of FY 2022–23, the TCFMAC reviewed and approved 433 FMs for a total estimated cost of \$16.1 million (see Attachment A). Of these, 243 were Priority 1 FMs, and 190 were Priority 2 FMs. The Judicial Council's Facility Modification Program's share of the estimated cost was \$12.2 million, with the affected counties responsible for the balance. Most of these FMs involved elevator, roofing, plumbing, and HVAC (heating, ventilation, and air conditioning) repairs or replacements.

In addition, council staff approved and the TCFMAC reviewed 31 CFRs totaling \$60.7 in the third quarter of FY 2022–23 (see Attachment B).

Completed project spotlights

Examples of FM projects completed during the third quarter of FY 2022–23 are shown below.

Priority 2: Plumbing—Storm Drain Repair at Norwalk Courthouse, Los Angeles County

Concrete was found cracked during rounds and readings and risked water intrusion into building. Mechanically, 65 linear feet (LF) of storm drain main line was cleared, and 140 square feet (SF) of concrete drain basin in the north end exterior of building was cleaned and epoxy painted. The final project cost was \$11,132.

Storm drain water due to crack in concrete.



Before



After

Newly repaired and epoxy - painted concrete drain basin.





Priority 1: Exterior Shell—Ceiling Repair at Kearny Mesa Court, San Diego County

Replace 288 SF wet acoustic ceiling tiles from water intrusion caused by rain and delaminated rooftop air duct seams. Rainwater traveled from the rooftop air duct affecting the public corridor, courtroom, and office spaces. Environmental containment was performed because of the known environment of asbestos-containing materials. Over 500 LF of hard surfaces and carpet was cleaned, dried, and sanitized. The final project cost was \$88,907.

Before





Waterdamaged ceiling tiles.

After





Newly replaced ceiling tiles.

Attachments and Links

- 1. Attachment A: TCFMAC-Funded Project List: Quarter 3, Fiscal Year 2022–23
- 2. Attachment B: Court-Funded Facilities Requests (CFRs): Quarter 3, Fiscal Year 2022–23
- 3. Link A: *Trial Court Facility Modifications Policy* (rev. Mar. 15, 2019), https://www.courts.ca.gov/documents/jc-facility-modification-policy.pdf
- Link B: Court Facilities: Trial Court Facility Modifications Report for Quarter 2 for Fiscal Year 2022–23 (Feb. 22, 2023), https://jcc.legistar.com/View.ashx?M=F&ID=11694260&GUID=F06C0B4E-42EC-4FE6-92AD-8350A17FDABB
- 5. Link C: Court Facilities: Court-Funded Facilities Request Policy (Aug. 15, 2016), https://jcc.legistar.com/View.ashx?M=F&ID=4625695&GUID=15BB7747-C300-48DA-A81-5546168A1991

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------------|----------------------------------|-------------|----------|---|----------------------|---|----------------------|---|
| 1 | FM-2003081 | San Diego | Kearny Mesa Court | 37-C1 | 1 | Exterior Shell - Replace 288 SF wet acoustic ceiling tiles due to water intrusion caused by rain and delaminated rooftop air duct seams. Rainwater traveled from the rooftop air duct affecting the public corridor, courtroom, and office spaces. Environmental containment was set up due to the known ACM environment. Area was cleaned, dried, and sanitized 508 LF of hard surfaces and carpet. Work included ACM environmental oversight. | \$ 88,908 | \$ | 88,908 | 100 |
| 2 | FM-2003143 | San Bernardino | San Bernardino Justice Center | 36-R1 | 1 | HVAC - Replaced (1) 24 x 48-inch ceiling tile, cleaned, dried and sanitized 78 SF of carpet and hard surfaces, and removed dirt and debris from condensate drain with 1/4-inch snake. Drain became clogged due to dirt and debris from condensate pan building up. Environmental testing was performed. | \$ 4,182 | \$ | 4,182 | 100 |
| 3 | FM-2003371 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | HVAC - Replace (1) 2-1/2-inch chilled water Y-strainer, 12 grade 8 (high strength) bolts, nuts and washers. Replace (6) LF of insulations. Replace (1) clean-out valve and threaded coupler. Clean-out valve failed due to rust and corrosion. Bolts on strainer and strainer housing are rusted and need to replacement. | \$ 7,121 | \$ | 6,063 | 85.14 |
| 4 | FM-2003374 | Los Angeles | Airport Courthouse | 19-AU1 | 1 | Elevator - Remove and repair the power supply for shared Elevators #8 and #9. Elevators lost power following a power surge and were unable to be reset. 19-AU1 currently scheduled for modernization. | \$ 2,849 | \$ | 2,199 | 77.17 |
| 5 | FM-2003375 | Los Angeles | Bellflower Courthouse | 19-AL1 | 1 | Elevators, Escalators, & Hoists - Replace (1) door spring and (1) fuse in custody Elevator #3. Door spring and fuse failed due to age. | \$ 2,690 | \$ | 2,690 | 100 |
| 6 | FM-2003376 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Mechanically clear 250 SF of clogged floor drain in 4th floor air handler room. Clogged floor drain in 4th floor leaked onto 3rd floor hallway. Clog was caused by heavy debris (rags and rust) build-up in drain system, affecting 3rd and 4th floors. Remediation and environmental testing included. Installed (1) $4 \times 12 \times 8$ high containment decon chamber on 3rd and 4th floors. | 32,566 | \$ | 21,536 | 66.13 |
| 7 | FM-2003377 | Los Angeles | Airport Courthouse | 19-AU1 | 1 | HVAC - Replace (1) 20HP motor, (1) pulley, (3) belts, (1) fan bushing, and various parts to reconnect motor to indoor Evaporative Cooler #3. Excessive vibration caused by failed bushing caused motor failure and cracked motor housing. | \$ 5,377 | \$ | 4,149 | 77.17 |
| 8 | FM-2003380 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | HVAC- Replace (1) shaft seal on condenser water pump #4 and isolate pump drain pump, (1) 3/4 inch threaded coupler and (1) 3/4 inch brass valve located at the basement chiller room. Condenser pump shaft seal failed due to age. | \$ 3,373 | \$ | 2,872 | 85.14 |
| 9 | FM-2003383 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Install (3) 20-gallon chemical tanks, and (1) chemical feeder water meter for new water treatment system on 13th floor. Existing water treatment equipment is now obsolete and no longer repairable. | \$ 9,235 | \$ | 6,107 | 66.13 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|---|----------------------|---|---|
| 10 | FM-2003386 | Los Angeles | Norwalk Courthouse | 19-AK1 | 1 | Plumbing - Sewer Line Leak - Replaced (1) 3-1/2 in. clean out and 23 ceiling tiles due to water damage from leak caused by clog in main sewer line on the 3rd floor mens public restroom. Sanitize 570 SF of vinyl flooring, 250 SF ceramic flooring, (2) window blinds, (1) wood desk, (1) gray metal filing cabinet, 800 SF of vinyl floor and 200 SF of plaster wall in 2nd and 3rd floor hallways and 3rd floor mens restroom. Category 3 water intrusion was caused by debris clogging main line. Environmental testing, containment and remediation work was performed including (3) decontamination chambers in the 3rd floor mens public restroom, 3rd floor hallway and 2nd floor secured hallway. | \$ 54,239 | \$ 46,119 | 85.03 |
| 11 | FM-2003389 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Fixture Leak - Replace (1) 2-in plumbing trap and (2) 2-in no hub couplings. Disinfect 620 SF of hard surface on 10th floor, mens employee restroom. A urinal overflowed causing the floor drain to overflow. The 2-in pipe connected to the floor drain cracked in the plenum of the 9th floor break room. Ceiling tiles, wooden tables and vinyl floor tiles were affected by Category 2 water. Remediation and environmental oversight are included, installed (1) $12 \times 12 \times 8$ -ft H containment with/1-stage decontamination chamber, (1) $1 \times 1 \times 15$ -ft L water diverter and (1) $6 \times 10 \times 20$ -ft H scaffolding. | \$ 20,651 | \$ 20,651 | 100 |
| 12 | FM-2003397 | Santa Clara | Downtown Superior Court | 43-B1 | 1 | Electrical - Replace (1) failed 10KVA transformer, (1) power supply for fire won doors, and (1) refurbished breaker. Main emergency power breaker failed due to age, causing transformer and door power supply to fail during testing of the transformer. | \$ 9,262 | \$ 9,262 | 100 |
| 13 | FM-2003399 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Domestic Water Pipe Leak - Installed 2-inch water valve, isolated 2-inch copper supply line, replaced (8) SF of ceiling tile, cleaned, dried, and sanitized (4) SF of flooring. Combination fixture in lock-up was leaking from behind mounting bracket, flooding cell, overflowing floor drain. 10th floor cell #4 floor drain was clogged. Water penetrated ceilings into 9th floor public Elevator lobby. Environmental testing required due to known ACM Environment. | \$ 31,729 | \$ 21,826 | 68.79 |
| 14 | FM-2003401 | Los Angeles | Airport Courthouse Parking Structure | 19-AU2 | 1 | Elevator - Replace overload switch for shared Elevator #12 at the Parking Structure. Overload switch failed due to age. | \$ 2,647 | \$ 2,043 | 77.17 |
| 15 | FM-2003402 | Los Angeles | Airport Courthouse | 19-AU1 | 1 | Elevator - Replace drive on shared Elevator #8. Elevator operation impacted due to failed drive component. Drive failed due to age. | \$ 55,547 | \$ 42,866 | 77.17 |
| 16 | FM-2003403 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Domestic Water Pipe Leak - Replace (2) 2-inch no hub couplings and a 10 foot section of 2-inch supply pipe. Critical moisture barriers and environmental testing, oversight, and containment required. Corroded water supply line to previously removed drinking fountain in courtroom holding cell developed a leak impacting multiple areas on the 7th, 6th, and 5th floors. | \$ 26,594 | \$ 18,294 | 68.79 |
| 17 | FM-2003408 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing – Domestic Water Pipe Leak - Replace (1) 3-inch OS and Y gate valve and associated bolts. Domestic water supply valve located in the basement steam room. Gate valve failed due to age. Access to the valve is difficult requiring additional labor to reach the valve. | \$ 8,814 | \$ 6,063 | 68.79 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|---|----------------------|------|---|---|
| 18 | FM-2003410 | Los Angeles | Inglewood Courthouse | 19-F1 | 1 | Plumbing - Domestic Water Pipe Leak - Replaced 12 LF of 1/2-inch copper pipe and associated fittings, installed straps, struts and strut clamps for the line leading to floor drain. Approx. 210 SF of hard surfaces were cleaned and disinfected. Installed (1) 6 x 8 x 10 ft containment and 36 x 76-inch decontamination chamber. Remediation and environmental oversight are included. Source of water was domestic water pump blow-down function on the expansion tanks. The original blow down pipe was not piped correctly to the drain. | \$ 10 | ,927 | \$ 8,147 | 74.56 |
| 19 | FM-2003411 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 1 | Elevators, Escalators, & Hoist - Replace (1) hoist rope on Passenger Elevator #1 elevator. Rope was frayed due to wear and tear of equipment. | \$ 41 | ,881 | \$ 33,304 | 79.52 |
| 20 | FM-2003413 | Los Angeles | | 19-C1 | 1 | Fire Protection - Replace (1) wet chemical cylinder and chemicals and modify piping to cover area located at the 1st Floor Cafeteria. Wet chemical system failed semi-annual inspection. Cylinder was found over-pressurized and due for hydro test. Replacement is equal to cost of testing and ensures compliance. Piping required modification to properly place nozzles over cooking grill exhaust hood to provide proper fire suppression coverage. | \$ 4 | ,016 | \$ 3,419 | 85.14 |
| 21 | FM-2003415 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Grounds and Parking Lot - Replace 12 damaged door slats and door safety edge located on service level lock up Bay 2. Ambulance hit gate preventing it from closing. Seeking restitution through insurance claim. | \$ 20 | ,279 | \$ 20,279 | 100 |
| 22 | FM-2003416 | San Diego | East County Regional Center | 37-11 | 1 | Interior Finishes - Remove 50 SF of buckled ceramic floor tiles, install 50 SF of temporary ram board, and place caution barriers on 1st floor, public corridor due to lifting which is-preventing occupants from being able to access or exit office. The existing floor tiles have no expansion joint to allow for expansion or contraction resulting in tiles buckling under certain weather conditions. Permanent repairs will be performed as a P2. | \$ 13 | ,437 | \$ 9,098 | 67.71 |
| 23 | FM-2003417 | San Diego | Central Courthouse | 37-L1 | 1 | Electrical - Replace (1) 4-port fiber optical transceiver module on the emergency Distributed Antenna System (DAS) due to failure to transmit or receive calls from the 16th through 22nd floors over the handheld radios, cellular services, or emergency system. The DAS is part of the building infrastructure required to maintain the emergency response system in high-rise. Module is 7 years old. | \$ 6 | ,430 | \$ 6,430 | 100 |
| 24 | FM-2003418 | San Diego | Central Courthouse | 37-L1 | 1 | Vandalism - Sewer Line Leak - Remove obstruction in main sewage pipeline, utilizing mechanical drain snake machine, 25 feet into line. Clean, dry, and sanitize all hard surfaces, perform clearance testing in all spaces contaminated by Category 3 black water. Toilets in 3rd floor Mens and Womens public restrooms backed up due to main sewage line obstruction. Remediation and environmental oversight required to complete work. The mechanical clearing extracted a shirt from the main sewer line. | \$ 11 | ,878 | \$ 11,878 | 100 |
| 25 | FM-2003420 | Riverside | Southwest Justice Center | 33-M1 | 1 | HVAC - Replace failed and rotted/leaking chilled water fan coils on #9 and #11. The coils are leaking water and have been shut off in order to prevent flood damage. Work includes new connections and testing of operation to ensure restored function. Temperatures currently cannot be regulated. | \$ 14 | ,098 | \$ 14,098 | 100 |
| 26 | FM-2003421 | Los Angeles | Santa Monica Courthouse | 19-AP1 | 1 | Vandalism - Replace (2) 29 x 29 inch tempered $1/4$ inch glass. First floor exterior window appears to have be broken by a rock based on impact point. | \$ 2 | ,369 | \$ 1,859 | 78.49 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|--|----------------------|---|---|
| 27 | FM-2003422 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | Plumbing - Domestic Water Pipe Leak – Replaced 6 LF of $3/4$ -inch copper pipe hot water supply line, 8 LF of insulation, and (16) 12×12 -inch ceiling tiles located at 4th floor public hallway. Cleaned and disinfected 340 SF of hard surfaces. Installed (1) $4 \times 6 \times 11$ ft containment, 40×90 -inch critical moisture barrier and 36×76 -inch decontamination chamber. Remediation and environmental oversight required. Failed hot water supply pipe showed signs of corrosion due to age. | \$ 24,223 | \$ 20,6 | 23 85.14 |
| 28 | FM-2003423 | Los Angeles | Santa Monica Courthouse | 19-AP1 | 1 | Plumbing - Replace (1) gate valve, (1) ball valve, (1) 1-inch Sloan and (1) tail piece with vacuum breaker. Install (1) $8 \times 8 \times 8$ -inch containment chamber; remove 18×18 inch in plaster wall, and install (1) 18×18 inch access door panel. In chambers restroom, the Sloan valve assembly and seals were corroded beyond their use. Environmental testing performed. | \$ 10,172 | \$ 7,9 | 78.49 |
| 29 | FM-2003424 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 1 | HVAC - Replaced (1) pneumatic damper actuator, 3-inch stroke 8 to 13 PSI spring range, and (1) dual pipe direct acting pneumatic thermostat located in Jury room on the 2nd floor. Existing damper actuator failed due to age and is beyond repair. Existing thermostat was not able to calibrate. Environmental testing was required to complete this work. | \$ 3,423 | \$ 3,4 | 23 100 |
| 30 | FM-2003425 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 1 | HVAC - Replace (1) pressure relief valve. Boiler #1 was not operating due to hard water deposits preventing the valve from opening. | \$ 3,007 | \$ 2,3 | 79.52 |
| 31 | FM-2003426 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 1 | HVAC - Replace (1) epoxy pan seal, (1) 2 x 55 x 30 inch galvanized custom sheet metal, 2 x 2 inch galvanized custom sheet metal brackets, (1) 8 x 36 inch galvanized custom sheet metal, and 20 SF condensate drain pan surface. Water leaked onto the floor by AHU #1 on roof due to corroded condensate pan. Environmental testing and oversight required to completed this work. | \$ 16,132 | \$ 12,8 | 79.52 |
| 32 | FM-2003434 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Elevators, Escalators, & Hoists - Replaced brake contactors, auxiliary contacts, door locks, and oilers for Elevator #1. Elevator door was found off track leaving doors stuck in the open position. Door contact and lock failed due to typical wear and tear. | \$ 17,356 | \$ 11,9 | 39 68.79 |
| 33 | FM-2003435 | Los Angeles | Alhambra Courthouse | 19-11 | 1 | HVAC - Replace (1) oil temperature switch and (1) gal of oil on Chiller #2. Oil switch has failed due wear, affecting the HVAC throughout the entire building. | \$ 4,972 | \$ 4,2 | 76 86.00 |
| 34 | FM-2003436 | Los Angeles | | 19-C1 | 1 | Plumbing - Domestic Water Pipe Leak - Replace 6 feet of 1-inch copper pipe, (1) 1-inch Pro Press 90 degree fitting, and (2) 1-inch Pro Press couplings. Install (1) chilled water valve, and (1) valve controller. Install (2) 36 x 76 containments. Remove (12) LF cove base and (8) LF of ACM. Replace (4) SF of ceiling plaster. Sanitize 110 SF of framing, 1,050 SF of hard surface in copy room, and 930 SF hard surface. Leak was caused by corroded copper pipe within ceiling space. Environmental containment and remediation required to complete repair. | \$ 37,533 | \$ 31,9 | 56 85.14 |
| 35 | FM-2003437 | San Diego | Central Courthouse | 37-L1 | 1 | Electrical - Replace (4) lighting switch controllers, (4) zone lighting switch power modules, and perform (1) system reset on lighting control system. The 4th floor, north side of building was completely dark due to loss of all lights, with the exception of emergency lighting, due to short circuit in power module. | \$ 16,916 | \$ 16,9 | 16 100 |
| 36 | FM-2003439 | Fresno | Fresno County Courthouse | 10-A1 | 1 | Plumbing - Replace the South sewage sump pump and laser align pump and motor shaft. Replace both the high and low level float switches. Pump and floats have failed and need to be replaced. Sewage pump system is down to one pump and vulnerable to complete failure. | \$ 18,503 | \$ 17,7 | 95.91 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|---|----------------------|--------|---|---|
| 37 | FM-2003440 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Domestic Water Pipe Leak - Erected (1) 10 x 10 x 20 containment and scaffolding, repaired plaster, replaced 25 SF of carpet, conducted remediation clean up. Environmental testing required. Work completed within a known ACM area. Domestic water supply valve within plenum above 3rd floor courtroom leaked. Valve was repaired and sealed, did not require replacement. | \$ 2 | 24,122 | \$ 16,594 | 68.79 |
| 38 | FM-2003445 | Los Angeles | Metropolitan Courthouse | 19-T1 | 1 | Plumbing - Sewer Line Leak - Replace (3) containment pans and (3) mixing valves. Leak was caused by a failed mixing valve continuously leaking in 1st floor Sheriffs shower facility. Water was found permeating the corroded containment pans through to the Basement level. Remediation and environmental oversight required to complete work. | \$ 5 | 51,186 | \$ 48,391 | 94.54 |
| 39 | FM-2003447 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 1 | Fire Protection - Replace (1) Intelligent Duct Smoke Detector, (2) 12Volt 55AMP Batteries, and (2) 12AMP Fuses. The smoke detector and batteries failed due to age (original to the building 1967) causing the fire panel to go into alarm and preventing it from being reset. | \$ | 5,954 | \$ 5,343 | 89.74 |
| 40 | FM-2003448 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | HVAC - Replace (1) fan shaft, (1) fan shaft assembly, bearings, pulleys, bushings, and (1) 7.5 H.P. 1800 RPM motor. Existing motor and shaft have failed due to material fatigue and age. Located in mechanical room on the 4th floor. | \$ 4 | 10,694 | \$ 27,993 | 68.79 |
| 41 | FM-2003451 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Domestic Water Pipe Leak - Replace (1) 2-inch copper shut off valve and (1) coupling. Set up (1) $8 \times 8 \times 8$ foot critical containment, extract water from 80×8 of carpet. Environmental oversight and remediation required. Leak originated from within the wall cavity on the 7th floor Judicial Chambers. | \$ 2 | 22,198 | \$ 15,270 | 68.79 |
| 42 | FM-2003452 | Yolo | Yolo Superior Court | 57-A10 | 1 | Vandalism – Dry and repair water damage to 35 SF of drywall, 43 SF of cove base, 84 SF of ceiling tiles, 460 SF of carpet, and 103 SF of tile flooring on 2nd Floor including (2) courtrooms, (2) attorney conference rooms, and stairwell #2 spanning basement, 1st, and 2nd floors. Complete hazardous substances review and remediation as necessary to complete work. Unidentified person trespassed after hours and opened the second floor stairwell fire hose valve causing a flood. | _ | 37,990 | \$ 37,990 | 100 |
| 43 | FM-2003453 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | 1 | HVAC - Replace (1) 15 HP 1180 RPM motor, and (1) 3 HP motor on Supply Fan #7. Motor failed creating a loud grinding noise and was unable to provide sufficient air flow to areas on the 3rd and 4th floors impacting court operations. This motor was original to building and failed due to age. | \$ 2 | 10,098 | \$ 9,821 | 97.26 |
| 44 | FM-2003454 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | 1 | HVAC - Replace (1) pneumatic air pressure regulator, oil separator and (1) pressure gauge that serves HVAC pneumatic air components. Pneumatic air pressure regulator has a blown diaphragm and is not providing enough air, causing several spaces to become hot on the 4th floor. | \$ | 5,794 | \$ 5,635 | 97.26 |
| 45 | FM-2003457 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | Electrical - Emergency Generator - Rebuild (1) fuel injection pump and fuel injectors. Perform diagnostic test, install (6) nozzles and seals, and (1) valve cover gasket. Cylinder #3 on emergency generator failed due to excessive wear and tear on nozzles and injection pump. | \$ 2 | 17,647 | \$ 15,025 | 85.14 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|---|----------------------|---|---|
| 46 | FM-2003458 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Grounds and Parking Lot - Replace (4) new ground loops sensors with associated conduit and sawcut concrete slab for loop access and electrical junction box access. Roll up door is inoperable due to failed ground loop sensors. Sensors failed due to continuous wear and tear. This is the exterior main roll up gate to access Service Level and Lock-up bus bays. | \$ 13,253 | \$ 9,11 | 7 68.79 |
| 47 | FM-2003459 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Plumbing - Fire Protection Systems Leak - Replace (1) 6-inch Fire Main Backflow. Backflow was found leaking and would not pass annual inspection. Parts are obsolete and backflow failed due to age, affecting the fire sprinkler system throughout the building. | \$ 12,488 | \$ 9,70 | 5 77.72 |
| 48 | FM-2003460 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Unclogged 60 LF of main sewer line on first floor. Clog caused water to leak onto the secured parking basement, 1st floor public restrooms and sheriffs restrooms. Sanitized 2,350 SF of hard surfaces in 1st floor public restrooms and sheriffs restrooms due to Category 2 water. Main line was clogged due to large amount of tree roots. Environmental testing/containment and remediation work was performed including (2) 40 x 90 inch containments. | \$ 31,314 | \$ 20,70 | 66.13 |
| 49 | FM-2003464 | Solano | Old Solano Courthouse | 48-A3 | 1 | Interior finishes - Rain Water Leak - Contain and extract 70 gallons of water, dry out 800 SF of drywall, and replace 400 LF of baseboard. Required environmental oversight and testing. Due to historic storm event, ground water was able to penetrate wall envelope along the perimeter of the basement. | \$ 26,034 | \$ 26,03 | 100 |
| 50 | FM-2003466 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | HVAC - Replaced (2) 6-inch ring gasket sets, (2) 8 inch ring gasket sets, (1) 2-3/16 x 28 1/2 inch long steel motor shaft, (1) 1-3/4 inch seal kit, and (1) stainless steel slotted shim set. Condenser Pump #3 gaskets and seals failed due to age affecting cooling throughout the building and causing water on the deck, creating a potential slip hazard. | 22,229 | \$ 14,70 | 66.13 |
| 51 | FM-2003472 | Los Angeles | Inglewood Courthouse | 19-F1 | 1 | Grounds and Parking Lot - Replace 35 LF of 3-inch cast iron drain line and fittings. Replace 60 LF of 4-inch cast iron storm drain and fittings. Install (1) clean-out. Water is leaking from 1st floor electrical room due to corroded pipes in planter area. | \$ 13,040 | \$ 9,72 | 74.56 |
| 52 | FM-2003475 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 1 | Plumbing - Domestic Water Pipe Leak - Replace (1) 1/2 in. hot/cold water mixing valve and install (1) 2 x 2 ft. access panel in 2nd floor judges lounge mens restroom vestibule. The mixing valve failed within the wall due to age and corrosion. Remove and dispose of ACM, (4) SF of plaster and (2) SF of ceramic tiles. Complete building shutoff of domestic hot and cold water was coordinated. Environmental oversight included. | \$ 20,208 | \$ 18,13 | 5 89.74 |
| 53 | FM-2003476 | Los Angeles | San Fernando Courthouse | 19-AC1 | 1 | Elevator, Escalators, & Hoist - Public Elevator #4 - Replace (2) 30 amp fuses and (1) latching relay to the elevator controller for the call-button/lamp-indicator/traveling sequencing circuit. The latching relay failed due to age and the blown fuses are causing the elevator car to remain stuck on the 4th floor with the doors ajar. Due to the obsolete latching relay the elevator service technician modified the controller by adding (3) relays to do the same as the (1) obsolete relay, elevator was tested several times prior to placing it back in service. | 13,221 | \$ 11,02 | 83.41 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION | PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|---------------------------------|-------------|----------|--|----------------------|-----------------------|---------------------------------------|---|
| 54 | FM-2003477 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 1 | Plumbing - Sewer Line Leak - Replace 5 ft. of 4-in. cast-iron pipe, 5ft. of 2 in. cast-iron pipe, 2 x 4 in combination tee-wye along with no-hub connection couplings. Install (1) pipe hangar support and (20) 1 x 1 ft. ceiling tiles. Mitigate bacterial Category 3 water, clean and sanitize 50 SF of hard surface. There were cracks along the cast-iron drainpipe between the 2nd and 3rd floors within the attic-space which caused sewage water to leak down through ceiling tiles and unto resilient flooring on the 2nd floor. Environmental testing and oversight included. | \$ 25,132 | \$ | 22,553 | 89.74 |
| 55 | FM-2003479 | Contra Costa | George D. Carroll Courthouse | 07-F1 | 1 | Interior Finishes - Remove carpet from the Judges bench to address and clear odor. Air testing and moisture testing were conducted. Carpet was removed due to odor at the request of the judge and court. Replace carpet, clean bench, air and moisture test, and air scrubber installation to resume courtroom normal operations. There was a consistent odor which prevented use of the courtroom. | \$ 24,034 | \$ | 24,034 | 100 |
| 56 | FM-2003480 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Storm Drain Leak - Replaced (5) 12 \times 12 inch ceiling tiles, cleared (5) down pipes, cleaned (5) roof drains and sanitized 460 SF of hard surfaces in basement janitorial office due to a ceiling leak. Leak was caused by clogged drain downspouts. Environmental testing, containment and remediation work was performed including (1) 10 \times 10 \times 15 scaffolding, and (1) decontamination chamber containment. | \$ 28,109 | \$ | 18,588 | 66.13 |
| 57 | FM-2003481 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | Plumbing - Sewer Line Leak - Mechanically snaked 60 LF of sewer line. Drain line was clogged by a large amount of plastic bags. Sanitized 160 SF of hard surface due to CAT-3 black water contamination in the Judges mens and womens employee restrooms. Environmental oversight included. | \$ 8,597 | \$ | 6,919 | 80.48 |
| 58 | FM-2003484 | Los Angeles | Hollywood Courthouse | 19-S1 | 1 | Vandalism - Replace (1) $1/4$ in. x 24 in. x 42 in. exterior bronze tempered glass with .07 film tint located on the 1st floor public waiting room. The window was shattered by an unidentified person. Removal of shattered window and temporary 4 x 4 ft plywood was installed until window is replaced under a separate P2. | \$ 4,988 | \$ | 4,544 | 91.09 |
| 59 | FM-2003485 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | HVAC - Replaced (1) 2 inch coupling for Chilled Water Pump #1, replaced (1) wet end filter. Coupling failed due to age, causing water to leak onto the deck affecting the HVAC throughout the building. Technician aligned pump and motor and recharged system. Issue was discovered during rounds and readings. | \$ 7,408 | \$ | 5,757 | 77.72 |
| 60 | FM-2003486 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Plumbing - Fixture Leak - Replace (1) cast iron 1 inch P-Trap for the sink, 10 LF of 1/2 inch copper pipe, 30 SF of ceramic floor tiles, and 10 SF of plaster. Sanitize (5) SF of surfaces. Cast iron p-trap failed due to age causing the trap primer to leak affecting the 2nd and 3rd floor mens public restrooms. Remediation and environmental protocols used for lead and category 2 grey water. Issue was reported after hours by custodial service. | \$ 25,831 | \$ | 20,076 | 77.72 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|--|----------------------|---|---|
| 61 | FM-2003490 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | Plumbing - Domestic Water Pipe Leak - Replaced (2) 1-1/2 in. restrictor fittings, (1) 4 in. pressure regulating valve (PRV) internal components kit, (1) 3/4 in. pilot operated air control valve, (1) 1-1/4 in. PRV internal components kit, (1) 2-1/2 in. PRV internal components kit, (7) 2 x 2ft. ceiling tiles, and 20 SF of duct insulation. Mitigated bacterial Cat-2 water, cleaned and sanitized 990 SF of carpet and hard surfaces. PRV bypass station leaked from the 3rd floor mechanical room into the 2nd floor Clerks office. Leak was caused by failed restrictor fittings and PRV internal components due to wear and tear. Environmental oversight included. | \$ 25,480 | \$ 20,506 | 80.48 |
| 62 | FM-2003491 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Grounds and Parking - Irrigation Leak - Replace (1) 2-1/2 in. ball valve, 6 LF of 2 in. pipe, and 10 LF of 3/4 in. PVC. Main PVC irrigation piping failed due to age affecting irrigation throughout the entire grounds and flooding the secured parking. | \$ 7,410 | \$ 5,759 | 77.72 |
| 63 | FM-2003492 | Orange | Central Justice Center | 30-A1 | 1 | Plumbing - Sewer Line Leak - Replace (2) sections of cast iron pipe (20 ft of 3-inch and 10 ft of 2-inch) in addition to multiple fittings and other supplies. Cracks in the pipes resulted in grey water leaks affecting the kitchen and a courtroom below. Work includes replacement of 8 x 15 ft section of drywall on a 20 foot high ceiling section, and environmental oversight and remediation. | \$ 30,344 | \$ 27,665 | 91.17 |
| 64 | FM-2003497 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Domestic Water Pipe Leak - Replaced 3-feet of 3/4-inch copper piping, (2) 3/4-inch couplings, (30) 12 x 12 ceiling tiles, 6 SF of carpet, erected (1) 8 x 8 x 10 containment, and conducted remediation and environmental oversight. Crack on domestic cold-water line leaked above the ceiling in 13th floor jury room. | \$ 20,732 | \$ 14,262 | 68.79 |
| 65 | FM-2003501 | Los Angeles | Pasadena Courthouse | 19-J1 | 1 | HVAC - Replace 25 LF of 1/4 in. pneumatic air-line, (1) thermostat, and associated pneumatic fittings. Sanitize 550 SF of surfaces. Pneumatic line failed due to age becoming brittle and allowing air to escape, impacting temperatures in the 6th floor courtroom. Environmental and remediation protocols used due to known ACM environment. | \$ 16,860 | \$ 11,692 | 69.35 |
| 66 | FM-2003503 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | HVAC - Replaced (1) heating actuator, (1) strainer with brass pipe fittings, (3) direct acting thermostats, and (14) 12 x 12 in. ceiling tiles in 11th floor judges chambers. The existing VAV box was unable to detect ambient temperature making room extremely cold. Actuator failed due to age. Environmental testing, containment and remediation work was performed including (1) 36×76 in. decontamination chamber and (1) $5 \times 11 \times 10$ ft. containment and sanitized 340×10 of hard surfaces. | \$ 15,593 | \$ 15,593 | 3 100 |
| 67 | FM-2003505 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Sewer Line Leak - Replaced 5 feet of 3 inch cast iron drain line, (3) leaking angle stops, (20) 12×12 ceiling tiles, 2 inch cast iron trap, and (1) water diverter. Extracted 35 gallons of water and installed $5 \times 15 \times 8$ containment. Remediation and environmental testing performed. Leak from 6th floor janitor closet due to a failed angle and P trap above 5th floor ceiling. | \$ 26,345 | \$ 18,123 | 68.79 |
| 68 | FM-2003506 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Elevators, Escalators, & Hoists - Replace brake contactors, auxiliary contacts, and door locks for incustody Elevator #12. Failed brake contactors caused elevator to be inoperable. Failure due to normal wear and tear. | \$ 16,606 | \$ 16,606 | 5 100 |
| 69 | FM-2003507 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Interior Finishes - Replace (1) 3 x 7 ft door, and associated hardware. Clerks office door would no longer secure to hinges (failed due to wear and tear) posing a safety and security issue. | \$ 2,626 | \$ 2,626 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION | PROGRAMI SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|---|-------------|----------|--|----------------------|-----------------------|--|---|
| 70 | FM-2003508 | Los Angeles | Pasadena Courthouse | 19-J1 | 1 | HVAC - Mechanically cleared 20 ft of condensate drain line and sanitized 40 SF of surfaces. Condensate blockage was pushed through line and was not recovered. Condensation water overflowed and leaked down to probation office. Environmental and remediation protocols used due to known ACM and Category 2 grey water. | \$ 17,914 | \$ | 12,423 | 69.35 |
| 71 | FM-2003509 | Los Angeles | Mental Health Court | 19-P1 | 1 | Vandalism - Boarded up (6) 4×4 ft windows, and (4) 2×2 ft. windows. Property was broken into by unidentified person, and front entrance glass doors and windows were broken and vandalized. Building is currently vacant. | \$ 2,857 | \$ | 2,037 | 71.31 |
| 72 | FM-2003519 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Replaced (15) 12 x 12 in. ceiling tiles and sanitized 1,000 SF of hard surfaces in the 8th floor secure hallway and the 9th floor mens restroom and hallway due to a leak in the 9th floor custodial closet. The leak migrated to the adjacent public hallway before penetrating down to the 8th Floor, secure hallway. Leak was due to a clogged drain. Environmental testing, containment and remediation work was performed including (2) decontamination chambers, (1) $7 \times 15 \times 10$ ft containment and (1) $10 \times 15 \times 8$ ft containment on the 8th and 9th floors. | \$ 15,452 | \$ | 10,218 | 66.13 |
| 73 | FM-2003521 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 1 | Elevators, Escalators, & Hoists - Replace (1) door edge on Custody Elevator #14. Door Edge failed due to age, causing safety concerns and rendering it out of service. | \$ 7,000 | \$ | 7,000 | 100 |
| 74 | FM-2003522 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 1 | Elevators, Escalators, & Hoists - Replace (1) control board on Elevator #7. Board failed due to age, causing the elevator to shut down. | \$ 7,894 | \$ | 5,803 | 73.51 |
| 75 | FM-2003523 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Fire Protection - Replaced (12) 12 x 12 in. ceiling tiles, (3) LF of 3/4 in. pipe, (2) 3/4 in. 90-degree elbows, and (2) 3/4 in. slip connectors in 12th and 13th floor due to a drain leak. Leak was caused by clogged drain line on Fire Pump #2 causing water to overflow onto the floor and into ceiling below on 12th floor. Environmental testing, containment and remediation work was performed including (1) decontamination chamber and (1) 12 x 15 x 10 ft containment. Sanitized 760 SF of hard surfaces. | \$ 15,352 | \$ | 10,152 | 66.13 |
| 76 | FM-2003526 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Plumbing - Condensation Leak - Mechanically clear chiller floor drain 10 ft, replace (4) 1 x 1 ft ceiling tiles, 20 SF of drywall and sanitized 500 SF of surfaces. Chiller floor drain was clogged with dirt and debris which caused basin to overflow and flood the 4th floor machine room, and leak down affecting 3rd floor secured hallway. Environmental and remediation protocols used due to category 2 gray water. | \$ 20,002 | \$ | 15,546 | 77.72 |
| 77 | FM-2003527 | Los Angeles | Pasadena Courthouse | 19-J1 | | HVAC - Replace 13 LF of 1/4 in. pneumatic air-line and associated pneumatic fittings. Sanitize 310 SF of surfaces. Pneumatic line failed due to age becoming brittle, allowing air to escape, impacting temperatures throughout the 3rd floor. Environmental and remediation protocols used due to known ACM environment. | \$ 7,692 | \$ | 5,334 | 69.35 |
| 78 | FM-2003528 | Los Angeles | Pasadena Courthouse | 19-J1 | 1 | HVAC - Replace (1) 5hp 40-gallon 3-phase air compressor, (1) In-Line air dryer and associated fittings. Compressor and air dryer failed due to wear and tear affecting temperatures throughout the building. | \$ 21,809 | \$ | 15,125 | 69.35 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|--|-------------|----------|--|----------------------|---------------------------------------|---|
| 79 | FM-2003531 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 1 | HVAC - Replace (1) VAV box reheat coil, and (6) LF of 3/4 inch copper pipe. Re-heat coil was leaking and failed due to age. Copper pipes failed due to corrosion. | \$ 8,143 | \$ 5,699 | 69.99 |
| 80 | FM-2003532 | Orange | Central Justice Center | 30-A1 | 1 | Plumbing - Hydronic Mechanical Leak - Replace failed water sanitizer tank, and control valve of the hot water heating system. The existing tank burst due to the failed control valve. Failure to replace the tank will result in calcium build up in the water heat exchangers. | \$ 7,887 | \$ 7,191 | 91.17 |
| 81 | FM-2003536 | Los Angeles | Pasadena Courthouse | 19-J1 | 1 | HVAC - Replace (1) 2-in 3-way valve, pneumatic actuator, 10 LF 2-inch of copper pipe, 10 LF of pipe insulation, (1) pressure gage and associated fittings for Air Handler #4. Three-way valve failed due to age affecting the heating hot water flow to AHU #4, affecting temperatures throughout the 3rd floor. While conducting repairs is was also discovered that the hot deck actuator had failed due to age affecting hot air flow. Environmental and remediation protocols used due to known ACM area. | \$ 35,042 | \$ 24,302 | 69.35 |
| 82 | FM-2003538 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Fixture Leak - Replaced 60 SF of carpet, (10) 12 x 12 ceiling tiles, (1) 2-1/2 inch flange pressure regulator, (1) 2-inch 600HR regulator, (1) 1-1/4 inch 600 HR regulator, 10 ft of 2-1/2 inch copper pipe, 10 ft of 2 inch copper pipe, and 1-1/4 inch copper pipe with associated hardware. Erected (1) 8 x 20 x 8, (1) 30 x 30 x 8, (1) 5 x 5 x 8, and (2) 5 x 5 x 8 containments, extracted water, and conducted environmental oversight. Toilet was continuously running due to failed pressure regulator valve, causing continuous flush in chambers on 9th floor. | \$ 79,656 | \$ 79,656 | 100 |
| 83 | FM-2003540 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | HVAC - Replaced (14) 12 x 12 ceiling tiles, 60 SF of carpet, extracted 20 gallons of water, erected (1) containment, conducted environmental oversight, and cleaned clogged drain line to drip pan. 14th floor AHU unit drain pan backed up and water leaked down to 13th floor courtroom damaging ceiling tiles. | \$ 22,461 | \$ 15,451 | 68.79 |
| 84 | FM-2003542 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | HVAC - Replace (1) inducer draft motor for Boiler #2. Draft motor has failed due to age and is preventing boiler from responding, affecting the heating throughout the building. | \$ 3,402 | \$ 2,644 | 77.72 |
| 85 | FM-2003543 | Los Angeles | Pasadena Courthouse | 19-J1 | 1 | Plumbing - Sewer Line Leak - Mechanically cleared 30 ft of sewer line and sanitized 910 SF of surfaces. 2nd floor in-custody holding cell had backed up, blockage was cleared and debris was not recovered. Water leaked through the walls affecting 2nd Floor public hallway. Environmental and remediation protocols used from known ACM and category 3 black water. | \$ 18,259 | \$ 12,663 | 69.35 |
| 86 | FM-2003544 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | HVAC - Replaced (2) actuators, and (20) 12 x 12 in. ceiling tiles in the 10th floor judges chambers. The VAV box was unable to detect ambient temperature making room extremely cold. Actuator failed due to age. Environmental testing, containment and remediation work was performed including (1) 36×76 in. decontamination chamber and (1) $10 \times 10 \times 8$ ft containment. | \$ 15,010 | \$ 15,010 | 100 |
| 87 | FM-2003546 | Contra Costa | George D. Carroll Courthouse | 07-F1 | 1 | Plumbing - Replace 150 feet of main water line and replace (1) backflow including piping. Excavate approximately 1,500 feet of concrete and bricks to access damaged water line. Main water line and backflow had failed due to age. | 295,243 | \$ 227,928 | 77.20 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | NOTE OF STREET | PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|--|-------------|----------|--|----------------------|----------------|---------------------------------------|---|
| 88 | FM-2003547 | San Diego | Kearny Mesa Court | 37-C1 | 1 | Roof - Replaced (8) SF of wall plaster with skim coat, (4) SF of fireproofing, sanitized (16) SF of hard surface, and sealed (5) SF of exterior stucco with epoxy at mail room on 1st Floor. Category 2 roof leak caused a crack between the exterior stucco and interior plaster skim coat. Work includes (1) $4 \times 4 \times 9$ -ft containment w/1 stage decontamination chamber, environmental testing and oversight due to known ACM environment. | 22,125 | \$ | 22,125 | 100 |
| 89 | FM-2003548 | Solano | Hall of Justice | 48-A1 | 1 | Plumbing - Sewer Line Leak - Clear sewer line blockage in restroom line. Remove 16 x 12 inch section of carpet located in adjacent staff hallway to access sanitary drain line. Required ACM abatement. Needed to clear drain line blockage and restore use of restroom. | \$ 7,566 | \$ | 7,566 | 100 |
| 90 | FM-2003550 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | HVAC - Replace (1) fan motor control relay and (1) 24volt power supply model. Parts failed due to an electrical short. System failure affected the cooling of the telecommunication room AC Unit on the 1st floor. The room was extremely hot which affected the IT equipment in the room. | \$ 4,427 | \$ | 3,563 | 80.48 |
| 91 | FM-2003551 | San Diego | North County Regional Center - Annex | 37-F3 | 1 | HVAC - Replace communications board, (3) water sensors, and the 3-way valve with actuator on boiler. Communications board and water sensors are failing due to age causing boiler to shut off and sound alarm. Failure to address this will leave the building with insufficient heating. | \$ 13,419 | \$ | 13,419 | 100 |
| 92 | FM-2003553 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Fixture Leak - Clean, dry and sanitize 97 individual areas from floor 18 through 11. All construction materials, offices, courtrooms, grand jury and (2) elevators were impacted by the Category 3 water intrusion event. Replace (2) elevator cab top control cards, (2) controllers and ropes on Elevators #16 and #19. Inspect all electrical panels and replace all breakers that were affected by water intrusion. Replace (3) relays and (1) smoke detector affected by water intrusion. Environmental protocol required for all areas impacted Category 3 water intrusion event. Substantial build-back required upon clearance to return Court operations. Leak originated in County exclusive space 18th floor employee restroom, continuous flushing toilet over weekend 11/19 to 11/20/22. | \$ 2,125,000 | \$ | - | 0.00 |
| 93 | FM-2003555 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 1 | HVAC - Replace (1) fan shaft, (1) pillow block bearing, (1) roller bearing, and (1) inlet cone. Bearings failed due to age causing the shaft to break on AHU #3. | \$ 32,705 | \$ | 24,041 | 73.51 |
| 94 | FM-2003560 | Contra Costa | Richard E. Arnason Justice Center | 07-E3 | 1 | HVAC - Replace (2) failed contactors for Chilled Water Pumps #1 and #2. Variable Frequency Drive (VFD) contactors are not functioning, preventing the chilled water pump within the unit from starting. Contactors failed due to age. | \$ 7,586 | \$ | 7,586 | 100 |
| 95 | FM-2003562 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 1 | Elevators, Escalators, & Hoists - Replace (1) Control Board #4 on Elevator #6. Board failed due to age, causing the elevator to shut down. | \$ 6,659 | \$ | 4,895 | 73.51 |
| 96 | FM-2003564 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 1 | Security - Replace (1) encoder for sally port door. Door encoder failed due to power surge causing a short. | \$ 5,522 | \$ | 3,865 | 69.99 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|--|-------------|----------|--|----------------------|----|---|---|
| 97 | FM-2003569 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | Plumbing - Domestic Water Pipe Leak - Replace (2) 3/8 in brass couplings, (1) 1/4 in reducing adapter, (1) 1/4 in brass cap fitting, (1) 3/8 in brass bussing, 15 ft of copper pipe, 36 SF of ceiling tiles, and (1) 15amp GFCI with cover plate. Mitigated, dried and sanitized Cat-2 water, 500 SF of hard flooring, 10 SF of carpet, and 100 SF of drywall. Water intrusion affected multiple floors and rooms from the 4th to the 1st floors. Leak was caused by a cracked water supply fitting to a drinking fountain. Fitting failed due to corrosion. Environmental oversight and testing included. | \$ 105,99 | 94 | \$ 85,304 | 80.48 |
| 98 | FM-2003571 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 1 | Fire Protection - Replace 7 feet of 8 in. sprinkler pipe line with associated fittings, and 70 SF of drywall. A leak started on an 8 inch water supply line within the plenum of the secured hallway in the basement affecting the fire sprinkler lines throughout the building. Environmental and remediation protocols required due to Category 2 gray water. The sprinkler pipe has failed due to age. | \$ 29,72 | 23 | \$ 20,803 | 69.99 |
| 99 | FM-2003572 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 1 | Plumbing - Sewer Line Leak - Snaked 140 LF to clear unknown obstruction in cafeteria drain lines. Cleaned, dried and sanitized 10 SF of metal ceiling tile, 35 SF of carpet and (1) desk chair. Environmental testing and oversight included for CAT 2 water mitigation. | \$ 20,64 | 16 | \$ 15,177 | 73.51 |
| 100 | FM-2003573 | Ventura | East County Courthouse | 56-B1 | 1 | Grounds and Parking Lot - Replace (1) 3-inch slip coupling, (1) 2-inch adapter, (1) 3-inch to 2-inch bushing, (1) 2-1/2 inch to 2-inch bushing, (1) 2-inch 90 degree elbow, (1) 2-1/2 inch 90 degree elbow, (1) 3-inch coupling, (1) 2-inch coupling, (1) 2-1/2 inch coupling and (1) 3-inch tee connection. Irrigation main waterline failed due to age and corrosion. | \$ 2,94 | 16 | \$ 1,819 | 61.75 |
| 101 | FM-2003578 | Los Angeles | Pomona Courthouse South | 19-W1 | 1 | Elevators, Escalators, & Hoists - Replace (1) set of hoist cables on Public Elevator #5. Hoist cables have failed due to age. The issue was identified during the annual inspection and preventive maintenance. | \$ 17,50 |)4 | \$ 15,953 | 91.14 |
| 102 | FM-2003580 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | Plumbing - Sewer Line Leak - Remove 4-inch clean-out in sink wall. Run 1/4-inch cable to mechanically clear passage from 1st Floor employee restroom. Install (2) 40 x 90 inch environmental containments on 1st floor and basement. Extract water and disinfect 3,180 SF of hard surfaces in 1st floor and 630 SF of hard surface in basement. Main line sewer stoppage between basement and 1st floor caused flooding. Object was not recovered by mechanical clearing. Environmental containment and remediation required to complete work. | \$ 15,54 | 10 | \$ 13,231 | 85.14 |
| 103 | FM-2003584 | Los Angeles | Pomona Courthouse South | 19-W1 | 1 | Elevators, Escalators, & Hoists – Replace (1) set of hoist cables on Public Elevator #2. Hoist cables have failed due to age which was identified during the annual inspection and preventive maintenance. | \$ 19,26 | 66 | \$ 17,559 | 91.14 |
| 104 | FM-2003588 | Contra Costa | Family Law Center | 07-A14 | 1 | HVAC - Replace (1) air flow switch on boiler and test for operation. Heating hot water valve was leaking. Air flow switch was found to have failed due to age. | \$ 4,53 | 34 | \$ 4,534 | 100 |
| 105 | FM-2003590 | Los Angeles | Glendale Courthouse | 19-H1 | 1 | HVAC - Replaced (1) 20 HP motor, belt and pully for Air Handler Unit #5. Motor bearings failed due to age, affecting temperatures throughout the 2nd floor. | \$ 3,07 | 77 | \$ 2,786 | 90.54 |
| 106 | FM-2003592 | Los Angeles | Pomona Courthouse South | 19-W1 | 1 | Elevators, Escalators, & Hoists – Replace 14 relays for custody Elevator #1. Relays failed due to wear and tear. Elevator is not responding, preventing in-custodies from being transported throughout the building. | | 15 | \$ 2,845 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|--|----------------------|---|---|
| 107 | FM-2003593 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Interior Finishes - Replace (2) stainless steel detention stools in 4th floor lock up. Existing detention stools were damaged due to age. | \$ 5,364 | \$ 5,364 | 100 |
| 108 | FM-2003595 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Replace (2) stainless steel sinks and (2) air controls in 6th floor lock up. Sink and controls are original to building (1977) and failed due to age. Parts for repairs are obsolete. Modification of existing drain and water lines is required to fit new fixture. | \$ 10,131 | \$ 10,131 | 100 |
| 109 | FM-2003598 | San Diego | East County Regional Center | 37-I1 | 1 | Plumbing - Sewer Line Leak - Replace inverted combo wye fitting on 5-inch cast iron pipe, (2) 5-inch No hubs, (40) SF of spline ceiling tiles, (20) SF of carpet, (12) SF of affected vinyl cove base, (2) Sloan valve assemblies and 12-inch access panel. Cracked sewer pipe between 1st and 2nd floor leaked through ceiling tile and onto carpet an estimated 1-gallon of category 3 water extracted. Remediation and environmental oversight required to complete work. | 19,234 | \$ 13,023 | 67.71 |
| 110 | FM-2003599 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Replace (1) stainless steel sink and air controls in 9th floor lockup cell. Sink and controls are original to building (1977) and failed due to age. Parts for repairs are obsolete. Modification of existing drain and water lines is required to fit new fixture. | \$ 5,011 | \$ 5,011 | 100 |
| 111 | FM-2003600 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | HVAC - Hot Water Loop - Replaced (2) 1-1/2 inch isolation valves, (2) strainers, 20 ft of 1-1/2 inch piping and (4) couplings. Erected (1) containment, extracted 40 gallons of water, conducted ACM abatement, and removed 20 LF of ACM piping insulation. Environmental oversight and remediation required. Water leak originated due to cracked HVAC hot water loop return line for AHU 17 on the 6th floor. | \$ 40,101 | \$ 27,585 | 68.79 |
| 112 | FM-2003601 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | HVAC - Hot Water Loop - Replace 10 ft of 3/4-inch copper piping, (5) couplings, (1) copper tee, and (1) 90-degree copper elbow. Extract 20 gallons of water, erect scaffolding, erect (1) containment, conduct ACM abatement, and remove 10 LF of piping insulation. Environmental oversight and remediation included. Failed piping leaking from HVAC hot water loop in S-level mechanical room was caused by normal tear and wear. | \$ 30,349 | \$ 20,877 | 68.79 |
| 113 | FM-2003604 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Grounds and Parking Lot - Replace (1) 2 in. ball valve press, (1) 2 in. 90-degree press, and associated fittings, 11 LF of copper pipe, 5 LF of PVC pipe in water supply line in basement parking structure due to a pipe leak. Parts failed due to age. | \$ 2,482 | \$ 1,641 | 66.13 |
| 114 | FM-2003605 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Fixture Leak - Replace (2) angle stops and cap off (2) drinking fountain water supply lines in 7th floor secured hallway. Previous water fountain failed due to age. Supply lines and angle stops must be capped. | \$ 2,427 | \$ 2,427 | 100 |
| 115 | FM-2003607 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 1 | Electrical - Generator - Replace (1) ball valve, (1) elbow, (2) threaded couplers - ball valve, and associated hardware that failed due to corrosion and inability to seal at the threads. Leak was identified during rounds and readings preventive maintenance and is preventing the cooling system from operating as designed during a power outage. | \$ 4,636 | \$ 3,245 | 69.99 |
| 116 | FM-2003617 | San Diego | Central Courthouse | 37-L1 | 1 | Elevators, Escalators, & Hoists - Replace (1) upthrust roller on door of Elevator #8. Elevator is making a loud noise when traveling due to a damaged upthrust roller. Damage was caused by a flood on the 4th floor in 2021 which caused the roller to rust. | \$ 5,147 | \$ 5,147 | 100 |

| Item Number | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|----------------|-------------|--------------------------------|-------------|----------|---|----------------------|---|---|
| 117 FM-2003618 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Replace (20) 12 x 12-in. ceiling tiles. Mechanically clear 50 LF of drain line due to a drain leak in cafeteria. Water leaked through the plenum and into an occupied space and traveled down the wall and onto ceiling tiles. Sanitized 20 SF of metal and wood cabinetry, plaster wall and flooring. Environmental oversight and testing including (1) $8 \times 13 \times 10$ ft. containment and (1) 36×76 in. decontamination chamber. | \$ 17,447 | \$ 17,447 | |
| 118 FM-2003627 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Replace 10 LF of 4in. cast iron pipe and associated fittings and (10) 12 x 12 in. ceiling tiles in 9th floor clerks office due to drain line leak. Pipe cracked due to corrosion and age. Water leaked Category 3 water into plenum space. Environmental testing and oversight included. Sanitized 729 SF of hard surface and installed (1) 36×76 in. decontamination chamber and (1) $8 \times 8 \times 8$ ft. containment. | 21,052 | \$ 13,922 | 66.13 |
| 119 FM-2003629 | San Diego | Juvenile Court | 37-E1 | 1 | HVAC - Replace (1) network automation engine. BAS is not able to communicate with air handlers 1, 2, 3 and 4 affecting HVAC operations throughout the building. Automation engine failed due to age affecting comprehensive equipment monitoring and control to air handlers. | \$ 9,068 | \$ 6,767 | 74.62 |
| 120 FM-2003630 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Replace (10) 12 x 12 in. ceiling tiles. Sewage drain line backed up and overflowed in the 3rd floor, mens and womens employee restrooms. Category 3 water traveled down through the plenum of the 2nd floor, passing through 1 x 1 ft. ceiling tiles and stopped on floor tile and carpet. Mechanically cleared 15 LF of main sewage line. Sanitized 500 SF of flooring. Environmental oversight and testing performed including (1) 36×76 in. decontamination chamber and (1) $11 \times 11 \times 1$ ft. containment. | \$ 16,408 | \$ 10,851 | 66.13 |
| 121 FM-2003631 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 1 | Plumbing - Sewer Line Leak - Replaced (6) 1 x 1 ft. ceiling tiles, 210 SF of carpet, mitigated CAT-2 water, HEPA vacuumed, wet wiped, cleaned, and sanitized and dried 720 SF of hard surface. Mechanically snaked 100 ft to clear unknown obstruction within the mainline which caused two toilets in the 4th floor jury room womens restroom to overflow. Water traveled down to the 3rd floor office. Environmental testing and oversight included. | \$ 25,466 | \$ 22,853 | 89.74 |
| 122 FM-2003632 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Replace (1) stainless steel sink and (1) air controls in basement lockup. Sink and controls are original to building and failed due to age, parts for repairs are obsolete. Modification of existing drain and water lines is required to fit new fixture. | 5,338 | \$ 5,338 | 100 |
| 123 FM-2003633 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | HVAC – Replace (3) belts, (2) pulleys and (2) bushings for Exhaust Fan #7. Parts failed due to age. | \$ 3,150 | \$ 2,083 | 66.13 |
| 124 FM-2003634 | San Diego | East County Regional Center | 37-I1 | 1 | Plumbing – Storm Drain Leak - Replace 20 feet of 4-inch cast iron pipe, (2) 4-inch no-hubs, 16 SF of wet ceiling tiles, and sanitized 60 SF of carpet, and 100 LF of T-bar in 8th floor area due to a roof leak. A cast iron drain line from the roof cracked and leaked rainwater into the 8th floor plenum space. Category 2 water traveled down the interstitial space and saturated non-ACM 2 x 4 ft ceiling tiles and carpet. Remediation and environmental oversight required to complete work. | \$ 13,975 | \$ 9,462 | 67.71 |
| 125 FM-2003644 | San Diego | Central Courthouse | 37-L1 | 1 | Exterior Shell – Install temporary (1) 5 x 8 ft plywood sheet on 12th floor interior window frame. 12th floor public area Exterior glass pane spontaneously broke, collapsed and fell to the 4th floor roof over the weekend, no one was injured, and contractor has replaced glass under warranty. | \$ 3,413 | \$ 3,413 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--------------------------------|-------------|----------|---|----------------------|---|---|
| 126 | FM-2003646 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | Vandalism - Reinstalled and mounted phone on wall in lockup Cell #4 1st floor Main Lockup. Repaired and patched 2 SF of Non-ACM concrete, and drilled and installed (6) 1/2 inch archers to resecure phone. In-custody yanked the phone off the wall damaging the wall. Environmental oversight and testing included. Sheriff department was not able to provide the name of the incustody and therefore, no restitution is being sought. | \$ 2,639 | \$ 2,124 | 80.48 |
| 127 | FM-2003647 | San Diego | East County Regional Center | 37-I1 | 1 | HVAC – Install (2) 5-gallon chemical filter/feeder pots, 10 of 3/4 inch copper pipe, (1) bleed/feed controller with 4 probes, 25 LF of 2-inch PVC pipe, (1) controller enclosure, (2) Biocides and (1) inhibitor. Current chemical delivery system has failed due to age. System must be repaired to prevent scaling and growth of biologic materials in the chillers and cooling towers. | \$ 31,304 | \$ 21,196 | 67.71 |
| 128 | FM-2003650 | Los Angeles | Hollywood Courthouse | 19-S1 | 1 | Exterior Shell - Roof - Patched and sealed 55 SF of roofing mastic that was compromised during recent heavy rain. Mitigated CAT-2 water and cleaned 20 SF of hard lid, vinyl flooring and one ceiling light fixture. No court property was affected. Due to age the mastic was deteriorated, water traveled into the plenum onto the hard lid ceiling and dripped onto vinyl flooring on the 2nd floor inside storage room. Environmental testing and oversight included. | \$ 7,204 | \$ 6,562 | 91.09 |
| 129 | FM-2003651 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 1 | HVAC - Replace (1) failed supply fan VFD, (15) 1 x 1ft ceiling tiles, mitigated CAT-2 water, HEPA vacuumed, dried, and wet wiped and sanitized 210 SF of hard surface and resilient flooring. Water overflowed from the 2nd floor AHU condensate drain pan due to excessive condensation caused by failed VFD. VFD was replaced and reprogrammed under warranty. Condensate pan pitch and drain were adjusted in order to properly route drain flow of water directly into the nearest floor drain. Water traveled from the 2nd floor HVAC mechanical room down into the 1st floor sheriffs office. Environmental testing and oversight included. | \$ 27,422 | \$ 24,609 | 89.74 |
| 130 | FM-2003652 | Solano | Law and Justice Center | 48-A2 | 1 | Plumbing - Fixture Leak - Replace (1) toilet flushometer in public restroom in court exclusive space. Flushometer failed due to age causing Category 2 water to migrate to two adjacent courtrooms. Contain water, dry out 150 SF of carpet, and replace 60 LF of baseboard. Damage was limited to a single floor. Remediation and environmental oversight required to complete work. | \$ 19,782 | \$ 19,782 | 100 |
| 131 | FM-2003653 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 1 | Plumbing - Sewer Line Leak - Replaced 5 ft. of 4 in. cast-iron pipe, (2) 4 in. couplings, (4) 1 x 1 ft. ceiling tiles, remediated ACM/CAT-2 water, cleaned, dried and sanitized 380 SF of hard surface. Cast-iron pipe located between the 4th and 3rd floor plenum had a crack along the pipe which caused water to leak down into the 3rd floor secured hallway. Environmental testing and oversight included. | \$ 39,161 | \$ 35,143 | 89.74 |
| 132 | FM-2003654 | San Diego | East County Regional Center | 37-l1 | 1 | Plumbing - Storm Drain Leak - Replace 10 feet of 5-inch cast iron pipe and (1) 5-inch no-hub. Disinfect 16 LF of metal T-bar and (9) SF of carpet. A storm drain line located inside plenum leaked into the 6th floor childrens waiting room. Remediation and environmental oversight included. | \$ 12,335 | \$ 8,352 | 67.71 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--------------------------------|-------------|----------|--|----------------------|---|---|
| 133 | FM-2003655 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 1 | Plumbing - Mechanical System Leak - Heating Hot Water - Replace (1) 1 in. ball valve, 6 ft. of 1 in. copper pipe and fittings, 5ft. of 2in. copper pipe and fittings, 4 SF of 1 x 1 ft. ceiling tiles, mitigated CAT-2 water, cleaned and sanitized 10 SF of carpet and hard surfaces. Water leaked between the 1st and 2nd floor plenum down into the 1st floor clerks office cubicle area. Environmental testing and oversight included. The existing piping and fittings failed due to age and corrosion. | \$ 18,898 | \$ 16,959 | 89.74 |
| 134 | FM-2003657 | San Diego | East County Regional Center | 37-I1 | 1 | Plumbing – Storm Drain Leak - Replace 20 feet of 3-inch cast iron pipe and (4) 4-inch husky no-hubs bands. Set up (2) 20-foot-high A-frame ladders and disinfect 50 SF of carpet. The 4-inch cast iron storm drain pipe inside plenum leaked (3) gallons of category 2 water in 1st floor employee breakroom. Remediation and environmental oversight required to complete work. | \$ 19,799 | \$ 13,406 | 67.71 |
| 135 | FM-2003659 | Los Angeles | Pasadena Courthouse | 19-J1 | 1 | Vandalism - Replace 20 SF of plaster in courtroom. Environmental testing included. No lead or ACM was detected. Plaster was damaged due to in-custody kicking the wall. Restitution is being sought. | \$ 2,997 | \$ 2,997 | 100 |
| 136 | FM-2003664 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 1 | HVAC - Boiler Unit - Replace (3) gaskets on hot water pump. Hot water pump is leaking water due to failed gaskets at end of life. Pump was isolated to prevent chemical loss. Cold temperatures are impacting court operations. | \$ 10,189 | \$ 8,102 | 79.52 |
| 137 | FM-2003665 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Fire Protection Systems Leak - Replace (13) 12 x 12 in. ceiling tiles in 12th floor court waiting room due to a fire pump leak. Fire pump #1 on the 13th Floor leaked causing category 2 water to travel through flooring and ceiling tiles onto the 12th floor court waiting room. Sanitized 50 SF of flooring. Environmental oversight and testing performed including (1) 36×76 in. decontamination chamber and (1) $12 \times 15 \times 10$ ft containment. | \$ 15,406 | \$ 10,188 | 66.13 |
| 138 | FM-2003667 | Kern | Bakersfield Superior Court | 15-A1 | 1 | Plumbing - Condensation Leak - Replaced 40 SF of carpet squares, (3) SF of 1 x 1 foot ceiling tiles, and cleaned/sanitized 430 SF of hard surface. Unclogged condensation drain line above the ceiling. Environmental testing and oversight included for ACM and CAT 2 water. | \$ 14,569 | \$ 9,106 | 62.50 |
| 139 | FM-2003670 | San Diego | East County Regional Center | 37-11 | 1 | Plumbing - Fixture Leak - Replaced (1) wall toilet w/seat and gaskets and (5) LF of cove base. Cleaned, dried and sanitized 150 SF of hard surface, removed non-ACM materials 24 SF of ceiling tiles, (1) LF of cove base. Water originated from a broken toilet that, when flushed, caused supply water to leak through the broken porcelain affecting 1st Floor Womens Public restroom and Ground floor offices. The Category 2 water traveled through the plenum along the exterior of a drainpipe affecting non-ACM fireproofing, ceiling tile, drywall, and carpet on the Ground Floor. Remediation and environmental oversight are included. | \$ 16,646 | \$ 11,271 | 67.71 |
| 140 | FM-2003671 | Los Angeles | Bellflower Courthouse | 19-AL1 | 1 | Elevators, Escalators, & Hoists - Replace (1) board assembly for Public Elevator #2. Control board assembly failed due to age. | \$ 4,816 | \$ 3,754 | 77.94 |
| 141 | FM-2003672 | Los Angeles | | 19-AX2 | 1 | Fire Protection - Fire Alarm Control Panel - Replace (1) FACP CPU board. The CPU failed due to age and is obsolete. During testing of the FACP, the panel would not reset after fire life safety devices were triggered. Fire watch was required until the FACP could be repaired (14 days). | \$ 88,551 | \$ 71,266 | 80.48 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|--------------------------------|-------------|----------|---|----------------------|---|---|
| 142 | FM-2003673 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | Plumbing - Sewer Line Leak - Replaced 10 ft of 2 in. cast-iron pipe, (6) 2 in. couplings, (1) 2 in. cast-iron p-trap and (35) 1 x 1 ft. ceiling tiles. Mitigated CAT-2 water, cleaned and sanitized 480 SF of hard surface. There was a crack along the cast-iron drainpipe and p-trap located between the 6th and 5th floor within the plenum, water leaked in the plenum down into IT Office. Environmental testing and oversight included. | \$ 13,578 | \$ 10,928 | 80.48 |
| 143 | FM-2003674 | Los Angeles | Norwalk Courthouse | 19-AK1 | 1 | Grounds and Parking - Replace (1) irrigation sprinkler line on north side of building due to a leak in the exterior planter that entered the basement server room through a conduit in the wall. Replace 200 SF of 9 x 9 in. floor tiles and sanitize 50 SF of concrete flooring in the basement motor control room. Work includes environmental testing and remediation including (1) 36×76 in., (1) stage decontamination chamber, (1) dehumidifier, and (1) $10 \times 15 \times 8$ ft. containment. | \$ 50,958 | \$ 43,330 | 85.03 |
| 144 | FM-2003675 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 1 | Plumbing - Fixture Leak - Replace (5) 1 x 1 ft. ceiling tiles, (1) 3 in. tank-to-bowl rubber gasket kit, and (1) toilet refill supply valve and kit. Mitigated CAT-2 water, cleaned, dried and sanitized 585 SF of hard surface. Water leak caused by failed refill supply due to age. Water leaked from the 7th floor jury room mens restroom down through the plenum into the 6th floor public corridor. Environmental testing and oversight included. | \$ 14,552 | \$ 13,059 | 89.74 |
| 145 | FM-2003676 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | HVAC - Replace (1) make up water pressure relief valve (PRV), (1) gasket condenser barrel cover, 15 ft. of copper drain line and associated fixtures. The PRV and the gasket cover failed due to age and corrosion. During the trouble shooting stage it was discovered that systems had excessive buildup requiring the chiller to be descaled. The entire building was affected due to clogged tubes causing a decrease in the heat transfer capabilities impacting the chiller efficiency. | \$ 29,171 | \$ 22,672 | 77.72 |
| 146 | FM-2003679 | Imperial | Imperial County Courthouse | 13-A1 | 1 | Elevators, escalators, and hoists - Replace failed control board in the elevator cart on public elevator #1 and calibrate. Existing control board limits the elevator from reaching the second floor. Work is needed as this is the only elevator in the building providing ADA access. | \$ 7,000 | \$ 7,000 | 100 |
| 147 | FM-2003681 | Contra Costa | Wakefield Taylor Courthouse | 07-A2 | 1 | Interior finishes - Remove front glass door and remove and replace the failed pivot hinge and pin, rehang the door and align for operation. Pivot pin broke due to age. Replacement hinge and pin were needed to restore proper function of main entrance door. | \$ 6,744 | \$ 6,744 | 100 |
| 148 | FM-2003683 | San Diego | Central Courthouse | 37-L1 | 1 | Exterior Shell - Replace (6) davit trolleys & backing plates, (4) 80 LF of 5/16-inch of galvanized wire ropes, swedged, crimped, and delivered to the roof. Re-Swedge (4) 470 LF of wire ropes on the catwalk, re-swedge (4) 320 LF of wire ropes on the 23rd Floor. Deficiencies found during Annual Certification inspection of the swing stage equipment and need to be corrected to obtain Annual Certification. | \$ 22,883 | \$ 22,883 | 100 |
| 149 | FM-2003687 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 1 | Plumbing - Sewer Line Leak - Waste Pipe - Replace (2) 2 in. no-hub couplings, (1) 2 in. cast-iron wye fitting, (1) cast-iron 90-degree elbow fitting and 10 SF of 2 in. cast-iron pipe. Mitigated CAT-2 water, cleaned, dried and sanitized 445 SF of hard surface. There was a crack along the drainpipe and fittings within the plenum of the 6th and 7th floors which leaked water down into the 6th floor public lobby. Environmental testing and oversight included. The existing piping and fittings failed due to age. | 18,565 | \$ 16,660 | 89.74 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|---|----------------------|----|---|---|
| 150 | FM-2003688 | Los Angeles | Norwalk Courthouse | 19-AK1 | 1 | Interior finishes - Replace (1) 1 x 1 ft ceiling tile. Erected (1) 6 x 6 x 7 ft containment on the 1st floor clerks office. Work was completed in known ACM environment. Ceiling tile fell due age (original to build, 1965). | \$ 9,69 | 99 | \$ 9,699 | 100 |
| 151 | FM-2003693 | San Diego | North County Regional Center - South | 37-F1 | 1 | Plumbing - Domestic Water Pipe Leak – Replace (2) angle stops, 75 SF of carpet and 20 SF of saturated dry wall. Water supply line to the sink in the employees restroom failed due to age and caused a Category 2 leak that spread into foyer, jury room, and secure corridor at courtroom on the 4th floor. Work includes cleaning, drying, and sanitization of 300 SF of hard surfaces, carpet, and 20 SF of painting. Remediation and environmental oversight required to complete work. | \$ 31,9 | 63 | \$ 31,963 | 100 |
| 152 | FM-2003694 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | Plumbing - Domestic Water Pipe Leak - Replace (1) 1-1/2 in. domestic water supply pressure regulating valve (PRV) which failed due to age. Mitigated CAT-2 water, cleaned, dried and sanitized 1,950 SF of hard surfaces and office furniture. Water leak was caused by a ruptured PRV affecting multiple areas in the basement sump pump room, fire pump room, westside secured corridor, mens sheriff locker room, womens sheriff locker room, northwest secured corridor, basement file room, DA offices and kitchenette, northside public corridor and janitorial closet room. Environmental testing and oversight included for multiple locations. | \$ 45,5 | 06 | \$ 36,623 | 80.48 |
| 153 | FM-2003707 | Los Angeles | Hollywood Courthouse | 19-S1 | 1 | Vandalism - Replace (1) 42 in. X 63 in. tempered glass and (1) 42 in. X 24 in. tempered glass. Glass panels were shattered by unidentified person. Removed broken glass and boarded up window until new glass was installed. | \$ 2,8 | 63 | \$ 2,608 | 91.09 |
| 154 | FM-2003712 | Los Angeles | Chatsworth Courthouse | 19-AY1 | 1 | Plumbing - Domestic Water Pipe Leak - Replace (1) 1/2 in. trap primer device and connections which failed due to age and corrosion. Mitigated CAT-2 water, cleaned, dried and sanitized 420 SF of hard surfaces within the 1st floor mens and womens public restrooms. Water leak occurred within the pipe-chase plenum between the 1st floor mens and womens public restrooms. Environmental testing and oversight included. | \$ 17,6 | 27 | \$ 14,771 | 83.8 |
| 155 | FM-2003713 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Sewer Line Leak - Replace 6 feet of 3-inch cast iron pipe with (2) 3-inch couplings, and (4) 12 x 12 inch ceiling tiles. Erected (1) containment. Environmental oversight and remediation required. Cracked drain line leak above ceiling 15th floor secure hallway. Drain pipe cracked due to age. | \$ 10,5 | 31 | \$ 7,244 | 68.79 |
| 156 | FM-2003714 | San Diego | East County Regional Center | 37-l1 | 1 | Fire Protection - Replace (1) run contactor on fire pump controller in 1st floor fire pump room. The controller is showing a fault and will not clear. Controller cannot be re-started and needs to be replaced for pump operation. Controller failed due to age. This issue was found during the annual preventive maintenance testing. | \$ 17,5 | 83 | \$ 11,905 | 67.71 |
| 157 | FM-2003715 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Sewer Line Leak - Replace 10 feet of a 3-inch drain line, (2) 3-inch couplings, (5) ceiling tiles, erected (1) containment, conducted environmental oversight, placed drying equipment, and completed build back. Cracked 3-inch drain line above ceiling caused condensate water to leak from mechanical room on the 16th floor down to the courtroom on the 15th floor. | \$ 30,34 | 49 | \$ 20,877 | 68.79 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|-----------|-------------|--|-------------|----------|---|----------------------|-----|---|---|
| 158 F | M-2003716 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Elevator - Replace (1) door operator board, (1) set of door operator belts and (1) door motor on Public Elevator #2. Parts failed due to age. Elevator doors were reported to be slamming shut. Due to safety concerns, elevator was placed out of service. | \$ 7,7 | 725 | \$ 6,004 | 77.72 |
| 159 F | M-2003717 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Domestic Water Pipe Leak - Replace 10 ft of 1-1/2 inch copper pipe, (1) 1-1/2 inch elbow, and (1) 1-1/2 inch coupling. Erected (1) 12 x 12 x 8 ft containment, and removed (5) LF of thermal insulation. Environmental testing and drying equipment required. Domestic hot water piping failed behind wall of Sheriffs Service level and caused water to leak through wall into service level. | \$ 33,0 |)31 | \$ 22,722 | 68.79 |
| 160 F | M-2003744 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 1 | Plumbing - Sewer Line Leak - Mechanically clear 50 LF of unknown obstruction from mainline affecting 1st floor public restrooms and jury assembly restroom. Cleaned, dried and sanitized 100 SF of hard surface. Environmental testing and oversight included for mitigation of CAT 3 water. The obstruction was pushed through and could not be identified. | \$ 9,7 | 733 | \$ 7,155 | 73.51 |
| 161 F | M-2003745 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 1 | Exterior Shell - Replace 30 LF of sealant around exterior emergency exit door. Sealant failed due to age and elements, causing water intrusion by heavy rains. Water accumulated along the exterior wall and seeped in the hallway. Mitigated CAT 2 water, cleaned, dried, and sanitized 80 SF of hard surface. Environmental testing and oversight included. | \$ 14,7 | 764 | \$ 10,333 | 69.99 |
| 162 F | M-2003748 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Sewage Ejector Pumps - Replace (4) float switches, (1) check valve, (2) flap assemblies, (4) gaskets kits, (1) pump propeller, (1) alarm vibrator for panel, and fuses for Sewage Ejector Pumps #1 and #2. Deteriorated floats caused pumps to continuously run. Excessive run time caused failure requiring rebuild. | \$ 25,2 | 295 | \$ 17,400 | 68.79 |
| 163 F | M-2003749 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Fixture Leak - Mechanically cleared stoppage from toilet in 4th floor holding cell #6, erected (1) 6 x 12 x 8 containment, replaced (6) 24 x 24 inch ceiling tiles, conducted environmental testing, and placed drying equipment. Unidentified debris caused stoppage and water subsequently overflowed toilet. | \$ 21,1 | 112 | \$ 21,112 | 100 |
| 164 F | M-2003433 | Madera | Main Courthouse - Madera | 20-F1 | 1 | Security - Replace broken spring assembly inside barrel of sallyport exit roll-up door and rebuild barrel. Replace failed circuit board and contactors, make adjustment to limits and test for proper operation. Security roll-up door is non-operational due to failed parts. | \$ 18,4 | 149 | \$ 18,449 | 100 |
| 165 F | M-2003463 | Los Angeles | Airport Courthouse | 19-AU1 | 1 | Security - Replace (1) barrel assembly, (1) broken spring, and (1) bearing. Rebuild head plates, motor assembly, and reconnect electrical component for Judges Parking, West Entry Gate. Barrel assembly lost tension from the springs due to age causing the roll-up curtain failure to become inoperable. | \$ 6,8 | 372 | \$ 6,872 | 100 |
| 166 F | M-2003597 | Los Angeles | Eastlake Juvenile Court | 19-R1 | 1 | Security - Replace (1) safety edge and (1) battery for the roll-up door. Safety edge and battery failed due to age preventing the roll-up door from closing and securing the judges parking. | \$ 5,7 | 776 | \$ 5,776 | 100 |
| 167 F | M-2003666 | San Diego | Central Courthouse | 37-L1 | 1 | Security – Replace (1) Panic hardware on the main exit doors on 1st floor lobby doors. The exit door is not operational and stuck shut due to panic push bar internal components damaged from use. | \$ 12,4 | 104 | \$ 12,404 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|-----------------------------------|-------------|----------|--|----------------------|---|---|
| 168 | FM-2003067 | San Diego | Central Courthouse | 37-L1 | 1 | Interior Finishes - GCI - Secure existing wood soffits to steel studs and continuous Z strip with screws in all areas above public seating throughout the 22-story courthouse. Work includes a mockup for approvals by the engineer. The original underlying Z clip connectors were insufficiently attached with glue and not structurally fastened to the substrate steel stud framing, creating a safety hazard. Z clip connectors failed in one instance, falling on a member of the public. | \$ 142,876 | \$ 142,876 | 100 |
| 169 | FM-2003269 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Replaced 576 SF of carpet, 240 LF of cove base, and (3) SF of 1 x 1 ceiling tiles. Set up (2) 40 x 90 inch containments, and (2) 36 x 76 inch containments. Sanitized 980 SF of hard surface on 4th and 5th floors due to a toilet clog on the 5th floor. A toilet within the 5th Floor, mens restroom backed up and flooded through the walls of the mens and womens restroom vestibules. The water then traveled down through the floor and plenum of the 4th floor, pooling on the floor of the womens restroom vestibule and traveling into the womens restroom floor and adjacent office. The water on the 5th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and careful of the careful of the water on the 5th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and the water on the 4th floor was treated as category 3 and 4CCM. | \$ 56,245 | \$ 37,195 | 66.13 |
| 170 | FM-2003319 | Sutter | Sutter County Superior Courthouse | 51-C1 | 1 | HVAC - Replace failed boiler burner that was found not functioning correctly during preventive maintenance inspections. This appears to have been end of life cycle for the burner. | \$ 6,931 | \$ 6,931 | 100 |
| 171 | FM-2003498 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | 1 | Plumbing - Sewer Line Leak - Mechanically cleared 80 feet into branch sewer line removing unidentified stoppage. Replaced 300 SF of ACM flooring, repaired 20 SF of damaged concrete subflooring, replaced 100 SF of 2 x 4 ft ceiling tiles, cleaned, dried, and sanitized 350 SF of impacted surfaces including floors, walls, and ceiling. Asbestos remediation required on 300 SF of flooring. Includes (2) containments, drying equipment, and remediation. Environmental testing and oversight required to complete build back of impacted areas. Clogged branch sewer line caused toilet to overflow in 3rd floor judges chambers. Water travelled through ceiling to the 2nd floor. This occurred prior to the preventative power washing and videotaping of the sewer lines. | \$ 60,559 | \$ 58,900 | 97.26 |
| 172 | FM-2003552 | San Joaquin | Stockton Courthouse | 39-F1 | 1 | Electrical - Diagnose and repair the power control system for the 12kV primary distribution switchgear. Main building power is not protected from faults and resultant system damage when control system is out of service. | \$ 38,774 | \$ 38,774 | 100 |
| 173 | FM-2003753 | Los Angeles | Hollywood Courthouse | 19-S1 | 1 | HVAC - Replace (1) main control board, and (2) condenser fan relay contactors on Package Unit #3. Parts failed due to age, preventing two stage compressors from operating as designed. The issue is preventing the contactors are from receiving required voltage to operate, and is affecting 1st floor AC unit. | \$ 9,767 | \$ 8,897 | 91.09 |
| 174 | FM-2003754 | Contra Costa | Wakefield Taylor Courthouse | 07-A2 | 1 | Grounds - Remove (6) inches of drain rock from around enclosure and pour 147 SF of concrete within the generator enclosure. Concrete around the generator pad is necessary to allow set up of ladders for generator maintenance. | \$ 12,877 | \$ 12,877 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|---------------------------------|-------------|----------|--|----------------------|--------|---|---|
| 175 | FM-2003756 | Contra Costa | George D. Carroll Courthouse | 07-F1 | 1 | Plumbing - Sewer Line Leak - Replace (8) feet of 2-inch cast iron piping and associated fittings. Work includes abatement, removal, and replacement of a 3 x 2 foot section of the 3rd floor womens staff restroom wall. Wall has to be removed to access the piping behind the wall. Sink drain pipe corroded over time causing leak. Containment chamber, monitoring, and oversight required. | \$ | 41,809 | \$ 32,27 | |
| 176 | FM-2003760 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | Vandalism - Mechanically clear blockage from in custody toilet, clean, sanitize and dry 200 SF concrete floors and surfaces, and isolate water supply valve to lockup area. Environmental testing and oversight required. Blockage was caused by in custody within 4th floor lock up. Judicial Council is seeking restitution. | \$ | 2,324 | \$ 2,32 | 4 100 |
| 177 | FM-2003763 | Contra Costa | George D. Carroll Courthouse | 07-F1 | 1 | Plumbing - Condensation Leak - Replaced (5) LF of drain line and p-trap. Repair 60 SF of water damaged wall sheetrock and 60 SF of ceiling sheetrock in the womens sheriffs locker room. Water damage occurred due to condensate line leak from above ceiling air handling unit interview room. Testing and repair of wall needed to restore normal operation. | \$ | 22,016 | \$ 16,99 | 6 77.20 |
| 178 | FM-2003764 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | Interior Finishes - Mold assessment was conducted after it was reported that several air vents had a suspect substance along the surfaces of the registers in the 2nd floor Clerks Office and 3rd floor Public Lobby. Testing discovered a fungal growth was present posing a potential safety concern for the occupants. Cleaned, dried and sanitized (20) 2 x 2 ft AC vents, (1) 10 in. x 120 ft AC vent, 4,310 SF of plaster-wall, 4,310 SF of carpet, 4,409 SF of marble tile, 2,300 SF of modular furniture, (21) 7 x 7 x 7 ft cubicle walls and used (6) HEPA air scrubbers. Environmental testing and oversight required. | \$ | 26,445 | \$ 21,28 | 3 80.48 |
| 179 | FM-2003765 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | HVAC - Replaced (1) 110v condensate pan float switch and secondary sensor on 5-ton computer room air conditioning unit. The switch and the sensor failed due to age causing the water level and float to rise in the pan which caused the AC unit to trip and shut down. The issue caused high temperatures in the telecom server room. The condensate pan is located high in the ceiling with limited accessibility. | \$ | 6,915 | \$ 5,56 | 5 80.48 |
| 180 | FM-2003767 | San Diego | East County Regional Center | 37-I1 | 1 | HVAC - Replace (2) hot water valves and (2) valves with actuator assembly on AHU #9, and (1) transformer on AHU #22. The AHUs are not responding to the BAS system resulting in cold calls throughout multiple floors. The failed components are preventing the heating hot water loop from functioning properly in both air handlers. | \$ | 18,219 | \$ 12,33 | 6 67.71 |
| 181 | FM-2003771 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | Plumbing - Domestic Water Pipe Leak - Replace (2) 6-inch valves, (2) 6-inch adapter flanges to 3-inch connection, (2) 3-inch grooved rigid copper couplings, (5) 3-inch 90-elbows, (3) 3-inch copper adapter flanges, (1) 3-inch 45-elbow, (1) 3-inch coupling, (1) 3-inch shutoff valve, 21 ft. of 3-inch copper pipe, and install (4) adjustable support brackets. Water leak was caused by a ruptured 6-inch flanged flexible braided connector. The 6-inch pipe also collapsed due to a failed support strap causing additional damage to a 3-inch supply pipe. This is the main domestic water supply to the building. The main line into the building had to be secured and water completely drained down to the basement to complete the repairs. Water leak was contained to the mechanical room and into the floor drain. | \$ | 21,568 | \$ 17,35 | 8 80.48 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | DREI IMINARY ECTIMATE | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|---|-----------------------|--------|---|---|
| 182 | FM-2003772 | San Diego | North County Regional Center - North | 37-F2 | 1 | Plumbing - Condensation Leak - Replace (1) 10 x 8 ft condensate drain pan, coil housing, transitions, isolations, and hangers. Install new isolation valve on AHU #08. Parts failed due to age and work was required to restore isolated AHU #08 mechanical equipment due to ACM after 11/08/21 ceiling collapse. Drill water channels in coil support for AHU #05 due to Category 2 water leak from condensate pan overflow through hard lid ceiling onto floor and carpet. Remediation work required to complete work including setting up containment, removal and replacement of 12 SF of affected drywall hard lid, cleaning, drying, and sanitization of 20 SF of carpet on 1st floor. | • | 80,044 | \$ 80,044 | 100 |
| 183 | FM-2003774 | El Dorado | Johnson Bldg. | 09-E1 | 1 | HVAC - Replace 20 feet of recirculation lines for hot water system on the mechanical penthouse, repair seal at the recirculating pump, and insulate piping as needed. The mechanical seal on the recirculating pump was leaking, this caused it to fail and the 20 feet of recirculation pipe froze and leaked. Part failed due to age. | \$ | 11,921 | \$ 11,921 | 100 |
| 184 | FM-2003775 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | Plumbing - Domestic Water Pipe Leak - Replaced 3 feet of 4-inch copper pipe, (1) 4-inch copper coupling, (1) 4-inch steel flange x copper adapter fitting, and welded (4) 1/8 x 5 x 5 inch steel patches onto 1,500 gal storage tank. Replaced 295 SF of ceiling tiles, and 100 SF of tank insulation. Mitigated CAT-2 water, cleaned, dried, sanitized 4,670 SF of hard surfaces, office furniture and equipment on the 9th, 10th, and penthouse floors. Water leaked from multiple cracks on the hot water storage tank and cracked copper supply pipe. The pipe failed due to age. Water leaked down through the plenum and wall cavities from the penthouse down to the 9th floor affecting multiple areas. Environmental testing and oversight required. | \$ | 50,776 | \$ 40,865 | 80.48 |
| 185 | FM-2003792 | San Diego | East County Regional Center | 37-I1 | 1 | HVAC - Replace (1) network control module with built-in power supply on building automated system, and (1) 8-inch butterfly isolation valve on hot water loop for purpose of restoring communication between the BAS and boilers. Court operations are affected by 62-degrees temperatures on the 1st, 2nd, and 3rd floors. The cause of failure is due to age. | \$ | 47,940 | \$ 32,460 | 67.71 |
| 186 | FM-2003794 | Los Angeles | Pasadena Courthouse | 19-J1 | 1 | Plumbing - Sewer Line Leak - Mechanically cleared 100 feet of sewer line and sanitized 50 SF of surfaces. Sewer main line backed up affecting the 1st floor mens public restroom. Clog was mechanically cleared and pushed through the drain line. Remediation and environmental protocols required due to category 3 black water. | \$ | 10,279 | \$ 7,128 | 69.35 |
| 187 | FM-2003798 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Plumbing - Replace (2) 8 inch valve packing, (1) 3/4 inch bypass repair kit for check valve, (1) 8 inch check valve, (1) 8 inch relief valve cover and associated fittings on Backflow #8. Main 8 inch domestic backflow was found leaking during annual test from both #1 & #2 shut-off valves. Parts failed due to age. | \$ | 8,921 | \$ 6,933 | 77.72 |
| 188 | FM-2003800 | Los Angeles | Inglewood Courthouse | 19-F1 | 1 | Vandalism - Replace (2) 18 x 72 inch mirrors, (4) 18 x 35 inch mirrors, (1) 24 x 36 inch mirror, and (4) 18 x 33 inch mirrors. Replace (1) 2 x 4 ft side urinal partition. Fill, sand, and restore (9) vandalized double-sided marble partitions. Fill, sand, and paint (5) double-sided vandalized plastic partitions. Damage identified throughout a total of 12 mens and womens public restrooms. Graffiti damage to mirrors and partition walls was caused by unidentified persons. | \$ | 21,132 | \$ 15,756 | 74.56 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|------------------|-----------------------------------|-------------|----------|---|----------------------|--------|---|---|
| 189 | FM-2003803 | Placer | Howard G. Gibson Courthouse | 31-H1 | 1 | Exterior Shell - Repair 16 x 30 feet of expansion joint on the exterior wall in the Sally Port. The joint failure allowed water to leak inside the building. Water leaked into the Fire Alarm Panel (FAP) and caused failure of one circuit board in panel. Replaced (1) circuit board in FAP. Repaired cracks in expansion joint with a sealant product, then applied (2) coats of elastomeric paint to match existing color. The expansion joint failed due to age. | \$ | 9,437 | \$ 9,437 | 100 |
| 190 | FM-2003808 | Santa Barbara | Santa Maria Courts Bldgs C + D | 42-F1 | 1 | HVAC - Replace (2) 5-Ton 100,000 BTU furnaces and associated fittings. Furnace heat exchangers have failed due to age and replacement parts are obsolete. Units are not operating at full capacity affecting temperatures in courtrooms. | \$: | 12,865 | \$ 12,865 | 100 |
| 191 | FM-2003809 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Plumbing - Sewer Line Leak - Mechanically cleared 50 LF of drain line. Replaced (2) LF of cast iron pipe, and associated fittings, (3) 12 x 12 in. VCT tiles, and (6) LF of cove base. Replaced 12 SF of drywall and 36 SF of concrete floor. The drain line for the water fountains located in the hallways of the 2nd and 1st Floor backed up and caused water to release from the fountains. Leak was caused by a broken cast iron drain line, affecting multiple areas in the basement, stairwell, hallway 1st and 2nd Floor. Set up (3) containments and (2) floor barriers, 120 SF in 1st floor hallway and 120 SF on 2nd floor hallway. Includes (6) days of monitoring dehumidifiers. Build back and released of areas. Remediation and environmental required. | \$ | 40,101 | \$ 31,166 | 77.72 |
| 192 | FM-2003810 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Replace (1) flush valve assembly, (2) 2-1/2 in gate valves, and (1) 6-in. butterfly valve in 9th floor Mens public restroom toilet due to mainline backup. Mainline backup was caused by accumulated debris from usage. Flush valve assembly was stuck causing toilet to continuously flush. Butterfly and gate valves were nonoperational due to age. Remediate by sanitizing 670 SF of hard surface and replacing 12 SF of ceiling tiles across multiple rooms on the 8th floor due to Category 2 water intrusion. Environmental and remediation work was completed. | \$ 4 | 43,587 | \$ 28,824 | 66.13 |
| 193 | FM-2003811 | Los Angeles | Inglewood Courthouse | 19-F1 | 1 | Elevator - Replace (1) brake module on Public Elevator #2. Brake module failed due to wear and tear. Not under warranty. | \$ | 5,497 | \$ 4,099 | 74.56 |
| 194 | FM-2003814 | Los Angeles | Hollywood Courthouse | 19-S1 | 1 | HVAC - Replace (1) 30-ton compressor, (1) 60 amp, 3 pole contactor, (1) auxiliary switch, and (1) filter drier. Parts failed due to age. Compressor was found inoperable affecting cooling of the courthouse. Compressor rotor locked causing internal damage. Equipment is on the roof and requires a crane lift. Work includes replenishing system with 57 lbs of refrigerant. | \$: | 39,986 | \$ 36,423 | 91.09 |
| 195 | FM-2003819 | Los Angeles | Inglewood Juvenile Court | 19-E1 | 1 | Vandalism - Replace (2) 1/4 x 18 x 24 inch mirrors with (6) mm anti-graffiti film in 1st floor public restrooms. Graffiti damage to mirrors was caused by unidentified persons. | \$ | 963 | \$ 778 | 80.78 |
| 196 | FM-2003828 | Los Angeles | Pomona Courthouse South | 19-W1 | 1 | Elevators, Escalators, & Hoists - Replace (1) door restrictor clutch for Public Elevator #2. Door restrictor clutch has failed due age preventing elevator from responding with doors open. | \$ | 6,217 | \$ 5,666 | 91.14 |
| 197 | FM-2003829 | 1 | East County Regional Center | 37-I1 | 1 | Plumbing - Sewer Line Leak - Replaced 10 feet of 2-inch cast iron pipe, (1) 4-inch cast iron p-trap, 10 feet of 4-inch cast iron pipe, (1) 4-inch floor drain clean-out assembly, 20 SF of ceramic tile, 20 SF of slab concrete, and (4) 1/2-inch re-bar steel. The basement collapsed floor drain in cafeteria kitchen is corroded due to age resulting in the ceramic floor tiles from slab to buckle and cause a strong sewer odor to permeate throughout sections of the courthouse. | | 36,230 | \$ 24,531 | 67.71 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--------------------------------|-------------|----------|--|----------------------|--------|---|---|
| 198 | FM-2003832 | San Diego | Kearny Mesa Court | 37-C1 | 1 | Plumbing - Sewer Line Leak - Replaced (2) SF of drywall, and (1) LF of cove base, and mechanically snaked (4) feet of shower floor drain that backed up to east wing basement to employee breakroom sink. Category 3 water from clogged shower drain pipe traveled to restroom, hallway, and cafeteria. Remediation and environmental oversight required to complete work, consisting of containment, cleaning, drying and sanitization of (90) SF of hard surfaces affected by back up. The cause of clog is unknown. | \$ 1 | 17,005 | \$ 17,005 | 100 |
| 199 | FM-2003835 | Los Angeles | San Fernando Courthouse | 19-AC1 | 1 | Roof - Replaced (4) SF of drywall, sealed 1,273 SF of roof on northeast side with a silicone coating, mitigated Non-ACM/CAT-2 water, cleaned, dried and sanitized 155 SF of hard surface in (2) courtrooms on the 4th floor. Rainwater intrusion occurred from a leak on the roof, water traveled from the roof through drywall ceiling into courtrooms. Environmental testing and oversight required to complete work. | \$ 4 | 14,117 | \$ 36,798 | 83.41 |
| 200 | FM-2003841 | Los Angeles | San Fernando Courthouse | 19-AC3 | 1 | Plumbing - Sewer Line Leak - Replaced (6) SF of 2 x 2 ft ceiling tiles, mitigated CAT-3 sewage water, cleaned, dried and sanitized (6) SF of T-bar ceiling grid, 125 SF of laminate & stainless steel countertops, 125 SF of resilient flooring and 70 SF of cafeteria equipment. Installed (1) 6-mil double wall plastic-poly containment $20 \times 30 \times 10$ ft along with (1) drying fan, (1) HEPA air scrubber and (1) dehumidifier. The City 8-inch mainline was clogged which caused sewage water to back up into the building and overflow from the floor drains in the cafeteria on the 1st floor. This incident has happened before in the past where debris is flushed by in-custodies and then accumulates within the City mainline which causes the back up into the building. Environmental testing and oversight required to complete the work. | | 34,998 | \$ 29,192 | 83.41 |
| 201 | FM-2003843 | Los Angeles | Santa Monica Court Annex | 19-AP3 | 1 | Fire Protection - Replace (1) fire alarm control panel, (1) LCD annunciator, (1) fire panel dialer unit, (2) 10 Amp 24 volt power supply (7) manual pull stations, (47) smoke detectors, (2) heat detectors, 49 smoke/heat/CO detectors, and (9) monitor modules. Fire alarm panel failed due to age, and repeatedly sent false alarms to dispatch. Firewatch was required while work was being performed. | \$ 23 | 34,070 | \$ 183,722 | 78.49 |
| 202 | FM-2003844 | San Diego | East County Regional Center | 37-l1 | 1 | Plumbing - Fixture Leak - Clean, sanitize, and dry 40 SF of carpet, (4) SF of carpet cove base, 100 SF of ceramic floor tile, 15 SF ceramic wall tile. A sink on the 2nd Floor, public womens restroom sink faucet was left in the on position overpowering the drain. The water traveled through the adjacent wall leading into adjacent courtroom. The category 2 water required remediation and environmental oversight to complete work. | \$ 1 | 11,423 | \$ 7,735 | 67.71 |
| 203 | FM-2003850 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | HVAC - Replace 325 SF of duct insulation. Insulation adhesive failed due to age and exposed areas of cold air ducting. This caused condensation to form on duct, saturating the duct and dripped onto the ceiling tiles and down through to the floor located at 5th Floor, court exclusive space. Environmental containment and testing required. | \$ 2 | 20,751 | \$ 20,751 | 100 |
| 204 | FM-2003852 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Replaced 30 ft of 8 inch cast iron sewer main and associated fittings in basement secure parking structure. Cracked cast iron pipe was discovered during monthly rounds and readings and failed due to age. | \$ | 9,288 | \$ 6,142 | 66.13 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION | PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|--|----------------------|-----------------------|---------------------------------------|---|
| 205 | FM-2003859 | Kern | Bakersfield Superior Court | 15-A1 | 1 | Plumbing - Domestic Water Leak - Replace (2) 3/4-inch couplings, (1) 3/4-inch ball valve, (1) 3/4-inch adapter and 10 LF of galvanized pipe. Replace 85 SF of drywall in restrooms. Remove 85 SF of ceiling tile and plaster ceiling. Clean, dry and sanitize 530 SF of hard surfaces. Remediation and environmental oversight required due to Category 2 / ACM water in public restrooms. Domestic hot water supply pipe has failed due to age and is leaking. | \$ 33,820 | \$ | 21,138 | 62.50 |
| 206 | FM-2003860 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | HVAC - Hydronic Mechanical Pipe Leak - Installed 30 containments, extracted 300 gallons of water, replaced 100 LF of piping insulation, 100 ft of 1-1/4-inch piping, control valve, (2) ball valves, circuit setter, 2,500 SF of carpet, and 1,500 SF of ceiling tiles. Environmental testing, remediation, and oversight required. HVAC hydronic mechanical piping failed under insulation within the 4th floor mechanical room after hours. Water traveled from the 4th floor to the 1st floor, impacting operations in (1) courtroom, 1() chambers, (1) jury room, (2) restrooms, (6) offices, (1) cafeteria/kitchen, (2) secured hallways, (5) elevator landings, and (1) mechanical room. | 593,859 | \$ | 408,516 | 68.79 |
| 207 | FM-2003861 | Los Angeles | San Fernando Courthouse | 19-AC1 | 1 | Exterior Shell - Sealed 200 SF of roof top (on West side of building) with flood coat emulsion, mitigated Non-ACM/CAT-2 water impacted surfaces, cleaned, and dried and sanitized 29 SF of hard surface. Rainwater intrusion occurred from cracks and penetrations around a roof drain. Water traveled through the plenum onto the hard-lid drywall ceiling on the 4th floor into secured hallway. Environmental testing and oversight required to complete work. | \$ 13,827 | \$ | 11,533 | 83.41 |
| 208 | FM-2003867 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Elevators, Escalators, & Hoists – Repaired 12 failed connections to emergency help button phone lines on public elevators. Connections failed due to normal wear and tear and were identified through testing and state inspection. | \$ 2,429 | \$ | 1,671 | 68.79 |
| 209 | FM-2003868 | Riverside | Southwest Juvenile Courthouse | 33-M4 | 1 | Plumbing - Domestic Water Pipe Leak - Replace 20 feet of 2-inch leaking copper piping and restore power to lighting system. Leaks have developed in the heating system above the Childrens room causing the lighting system to fail requiring reset of the breaker and system inverter check to ensure proper operation. Work includes installation of (10) 2-in couplings, (10) 90 degree couplings and (4) reducers. | \$ 7,653 | \$ | 7,653 | 100 |
| 210 | FM-2003871 | Ventura | East County Courthouse | 56-B1 | 1 | HVAC - Replace (1) power suppler converter to chiller controls. Converter failed due to age and is affecting temperatures throughout the building. | \$ 6,368 | \$ | 3,932 | 61.75 |
| 211 | FM-2003872 | Los Angeles | | 19-AQ1 | 1 | Plumbing - Domestic Water Pipe Leak - Replace (1) 4-inch isolation valve, (2) flanges, (3) press coupling, (4) LF of copper pipe, (2) bolts and gaskets, (1) ball and (1) press valve, and (1) 2-inch water gate valve. Erect containment and decontamination chamber on 3rd floor employee restroom. Cut (4) SF of ceramic tile, (4) SF of plaster and remove (3) LF of TSI. Sanitize 930 SF of hard surface. There was a leak at the 3rd floor restroom and after the water was shut off, additional leak was detected at 4-inch main isolation valve. Environmental testing and oversight required. | \$ 29,047 | \$ | 23,098 | 79.52 |
| 212 | FM-2003875 | Los Angeles | Airport Courthouse | 19-AU1 | 1 | Elevator - Replace input rack and buffer board for Elevator #7, reset communication for Elevator #2, and reset both elevators and release all entrapments. Power outage in building caused all elevators to stop and entrapments to occur. | \$ 5,892 | \$ | 4,547 | 77.17 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|--|----------------------|---|---|
| 213 | FM-2003876 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | HVAC - Replaced (2) chemical pumps, (1) chemical controller, (1) flow switch and (1) shuttle assembly. Chemical pumps failed due to age causing the controller, flow switch and shuttle assembly to fail, restricting water flow to the cooling towers affecting the HVAC throughout building. | \$ 3,342 | \$ 2,210 | 66.13 |
| 214 | FM-2003878 | Kern | Bakersfield Superior Court | 15-A1 | 1 | Fire Protection - Replace (1) 208V, 20HP, fire pump motor, (1) Fire Pump Controller, (1) 1-3/4-inch casing pressure relief valve, (1) 208V, Jockey pump, (2) 3-1/2 inch suction and discharge pressure gauges, and perform start up testing. The pump and its components failed due to age and have reached their end of life. The pump deficiencies were discovered during the annual preventative maintenance. | \$ 102,545 | \$ 64,091 | 62.50 |
| 215 | FM-2003882 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Fixture Leak - Replaced (1) 2 1/2-inch isolation valve with bolt kit and associated hardware, drained/filled water to entire building. Cleaned out flushometer diaphragms. 5th floor holding cell toilet was continuously flushing and isolation valve failed due to age. | \$ 4,087 | \$ 4,087 | 100 |
| 216 | FM-2003883 | Calaveras | Calaveras Superior Court | 05-C1 | 1 | HVAC - Replace failed VFD, condenser fan motor, and crankcase heater on Chiller #1. Replace failed VFD on Chiller #2. Install load phase monitors on both chillers. Main incoming power suffered a severe phase imbalance due to issues with the main grid. This imbalance damaged components of both chillers rendering both non-functional. | \$ 23,009 | \$ 23,009 | 100 |
| 217 | FM-2003885 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Grounds and Parking Lot - Roll up door - Replaced bottom rail, guide cover top/bottom, corner plate top/bottom, spring cover, spring cove top, reversing edge retainer, side belt drive cover, and controller board. Terminated safety loop wiring, remounted guide rails, and straightened bent slats. Sheriff custody vehicle, at loading dock, hit rollup door upon entering. Seeking reimbursement. | 33,509 | \$ 33,509 | 100 |
| 218 | FM-2003888 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Electrical - Replace (6) strip light fixtures and 500 LF of #12 stranded wire. Light fixtures failed due to bird nesting causing electrical short, affecting all lighting in sally-port and holding cells. | \$ 9,704 | \$ 9,704 | 100 |
| 219 | FM-2003894 | Los Angeles | | 19-AX2 | 1 | Plumbing - Sewer Line Leak - Replace 20 ft of 2-inch cast-iron drainpipe, installed (4) 4-band 2-inch no-hub couplings, and replaced (25) 1 x 1 ft ceiling tiles. Mitigated CAT-3 water, cleaned, dried and sanitized 100 SF of hard surfaces. Drainpipe failed due to age and corrosion and a crack along the pipe caused water to leak from within the plenum between the 2nd and 1st floors down into the 1st floor Sheriffs Office. The pipes were 20 ft high within the plenum, with the module office layout, ladders could not be used, and therefore required scaffolding to complete the repairs. Environmental testing and oversight was required. | 23,457 | \$ 18,878 | 80.48 |
| 220 | FM-2003895 | Sacramento | Gordon Schaber Sacramento Superior Court | 34-A1 | 1 | Exterior Finishes - Replace (1) 60 x 121 inch window in office space. Glass broke over a weekend, this is an exterior glass window that is on the roof parapet side. Window was boarded up with plywood while glass was ordered, replaced ceiling tiles and blinds that were damaged. This was not vandalism, there is no public access. Breakage cause is uncertain. | \$ 10,099 | \$ 10,099 | 100 |
| 221 | FM-2003897 | Riverside | Hemet | 33-F1 | 1 | Plumbing - Replace (2) failed electric water heaters. Replacement required to restore hot water to both public restrooms and workplace sink. Work includes replacing all piping, fittings, and pressure relief valves. Water heaters failed due to age. | \$ 5,780 | \$ 5,780 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|--------------------------------|-------------|----------|--|----------------------|---|---|
| 222 | FM-2003898 | Los Angeles | San Fernando Courthouse | 19-AC1 | 1 | Roof - Exterior Leak - Patched 670 SF of roof top (on East side of building) with flood coat emulsion, mitigated CAT-2 water, cleaned, dried, and sanitized 80 SF of hard surfaces. Rainwater leaked from the roof though the plenum and down into the 4th floor. Environmental testing and oversight required to complete work. | \$ 13,257 | \$ 11,058 | 83.41 |
| 223 | FM-2003900 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | 1 | Interior Finishes - Replace (3) 2×2 ft ceiling tiles, and adjust and secure several surrounding ceiling tiles. The ceiling tiles dislodged from the support grid, by unknown means. Environmental oversight and testing required. | \$ 2,706 | \$ 2,632 | 97.26 |
| 224 | FM-2003901 | Contra Costa | Wakefield Taylor Courthouse | 07-A2 | 1 | Grounds - Remove (1) cypress tree that was uprooted blocking public sidewalk. Remove(2) branches on adjacent cypress tree which lean over public sidewalk. Grind Stump to 6-8 inches underground and haul away wood. Both trees were damaged during recent storm and are obstructing public sidewalk causing a hazard. | \$ 5,298 | \$ 5,298 | 100 |
| 225 | FM-2003902 | Los Angeles | Inglewood Courthouse | 19-F1 | 1 | HVAC - Replace (2) control dampers on the hot and cold duct assembly VAV box serving 4th floor courtroom. Replace 40 SF of 1 \times 1 ft. ceiling tiles and rebuild ceiling support grid. Hot and cold deck dampers on VAV box were seized and failed due to age. | \$ 8,144 | \$ 6,072 | 74.56 |
| 226 | FM-2003903 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | HVAC - Replace (1) condenser water pump and (1) chilled water temperature sensor on Chiller #1. Condenser water pump failed due to age. Issue was discovered during rounds and readings when chiller failed to start. | \$ 15,731 | \$ 10,403 | 66.13 |
| 227 | FM-2003912 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 1 | Plumbing - Fixture Leak - Replace (6) 1 x 1 ft ceiling tiles, (1) 1-inch control-stop valve, (2) vacuum breaker assembly kits, and (1) hydraulic closet flushometer. Mitigated CAT-2 water, cleaned, dried and sanitized 6 SF of T-bar grid, and 65 SF of hard surface. Water leak started in the 3rd floor lock-up pipe-chase due to a failed concealed toilet flush valve. Water traveled through the plenum down through ceiling tiles and into the 2nd floor clerks office. Environmental testing and oversight was required. Parts failed due to age. | \$ 11,337 | \$ 9,124 | 80.48 |
| 228 | FM-2003913 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Elevators, Escalators, & Hoist - Replace (1) control board in custody elevator #9. Control board failed due to age causing elevator to stop working. | \$ 2,515 | \$ 2,515 | 100 |
| 229 | FM-2003914 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Plumbing - Fixture Leak - Replace (3) 2 x 2 ceiling tiles, (2) toilet wall mount plates, (2) carrier gasket kits, and associated fittings. Sanitize 160 SF of surfaces. Water leak originated in 4th Floor Jury Assembly restroom and it was identified that the mounting plate in the adjacent Judges chambers restroom also failed. Toilet mounting plates failed due to age causing water to leak down to the 3rd Floor restroom, secured hallway, and ground floor. Set up (5) containments in these areas. One (1) critical wall barrier was set up from 4th floor hallway to access Judges chambers due to ceramic tiles in Judges chambers restroom being positive for lead. Remediation and environmental oversight required to complete work. | \$ 20,901 | \$ 20,901 | 100 |
| 230 | FM-2003915 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | HVAC - Replace (1) set of bearings, and (1) bearing temperature sensor, rebuilt 200 horsepower motor windings and associated parts for Chiller #2. Bearings failed due to age causing motor and temperature sensor to fail affecting the HVAC throughout the building for 4 months. During this time, Chiller #1 was run at maximum capacity. | \$ 94,844 | \$ 73,713 | 77.72 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|---|----------------------|---|---|
| 231 | FM-2003919 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Mechanically cleared 125 LF of clogged main sewage line in basement parking lot, and sanitized 330 SF of concrete floor. Clog was due to root intrusion causing mainline to back up into basement level parking. Remediation and environmental oversight was required due to Cat 3 black water. | 12,763 | \$ 8,440 | 66.13 |
| 232 | FM-2003921 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | 1 | Roof - Erected (1) containment, repaired 80 SF of separated built up roofing, replaced (8) 2 x 4 ceiling tiles, and (5) SF of T-bar above ceiling. Conducted environmental testing, set up containment, added drying equipment, and performed build back of affected area. Separation, and punctures to the built-up roofing material caused water to travel to Judicial Chambers on the 6th floor during rain event. | \$ 24,831 | \$ 24,151 | 97.26 |
| 233 | FM-2003922 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 1 | Plumbing - Sewer Line Leak - Replace (3) 2 x 2 ceiling tiles, (1) flush valve assembly (1) carrier mounting face plate, (1) angle stop, and associated fittings. Sanitize 30 SF of surfaces in 4th Floor jury deliberation Restroom #1. Flush valve failed and, at the time it was discovered, the toilet mounting plate also failed due to age causing water to leak down to the 3rd Floor judges chamber. Remediation and environmental oversight required. | \$ 15,960 | \$ 12,404 | 77.72 |
| 234 | FM-2003924 | Los Angeles | Whittier | 19-AO1 | 1 | HVAC - Replace (1) motor for Cooling Tower #1. Motor failed due to affecting the cooling in the | \$ 3,466 | \$ 2,996 | 86.43 |
| 235 | FM-2003925 | Santa Clara | Courthouse Hall of Justice (East) | 43-A1 | 1 | HVAC - Replace failed t-stats and drier, and purge condensation from pneumatic control lines. Air compressor drier failed due to age, allowing moisture to contaminate t-stats causing loss of cooling at the jury assembly area. | \$ 11,175 | \$ 11,175 | 100 |
| 236 | FM-2003931 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Fire Protection - Fire Sprinkler Leak - Replace (1) 4-inch check valve and associated fittings in fire sprinkler system in basement employee parking structure. Parts failed due to age. | \$ 11,162 | \$ 7,381 | 66.13 |
| 237 | FM-2003932 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Plumbing - Sewer Line Leak - Mechanically clear 150 LF of main sewage line in basement lock up cells D, E, F, and G. Clog was pushed through and was not recovered. Sanitized 480 SF of surfaces. Remediation and environmental oversight required to complete work. | \$ 9,092 | \$ 6,013 | 66.13 |
| 238 | FM-2003935 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | 1 | Plumbing - Domestic Water Pipe Leak - Erected (3) containments, extracted 50 gallons of water, replaced (1) foot of copper piping, (1) copper 90-degree elbow, and (25) 2 x 4 ceiling tiles. Environmental testing and oversight required. Water supply line leaked due to age-related corrosion at 90 degree elbow, behind mop sink in janitor closet impacting judges chambers. | \$ 40,949 | \$ 39,827 | 97.26 |
| 239 | FM-2003940 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | HVAC - Hydronic Mechanical Pipe Leak - Erected (2) containments, extracted 100 gallons of water, replaced heating coil, and 15 ceiling tiles, re-sealed drain pan, and mechanically cleared drain line. Environmental testing required. Utilized drying equipment, drained system. Heating coil in AHU #16-4 leaked causing water to travel from 16th floor mechanical room to 15th floor. | \$ 76,626 | \$ 52,711 | 68.79 |
| 240 | FM-2003806 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 1 | Security - Replace (1) 120-volt 3/4 HP hoist operator motor, and (1) push button control for roll-up gate. Roll-up gate for judges parking lot continues to get stuck. Motor is failing due to age and wear and tear. | \$ 6,502 | \$ 6,502 | 100 |
| 241 | FM-2003858 | Riverside | Larson Justice Center | 33-C1 | 1 | Grounds and Parking Lot - Replace (6) failed guide rollers to secured judicial parking exit gate. The gate fails to close automatically and stays open after vehicle exit creating a safety concern due to the exits exposure to the public. Work includes securing of the motor frame, adjustments and lubrication to ensure proper operation. | \$ 4,212 | \$ 4,212 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|------------------------------------|-------------|----------|--|----------------------|---|---|
| 242 | FM-2003893 | Orange | North Justice Center | 30-C1 | 1 | Vandalism - Remove 30 x 10 feet of vandalized chain link fence, replace with vertical ribbed metal panels and attach to existing steel fence frame. An unidentified person cut the existing fencing in an area obstructed from view (blocked by building generator outside fencing) creating a breach in the chain link at the sally port/in custody detention area. Work includes the installation of 20 feet of 24-inch razor wire coil at top of adjoining wall to prevent further unauthorized access. | \$ 12,060 | \$ 12,060 | 100 |
| 243 | FM-2003934 | Los Angeles | Compton Courthouse | 19-AG1 | | Security - Replaced (1) door floor closer and window seal on south side exit door. Door closer failed due to corrosion. The seal failed due to age. | \$ 5,740 | \$ 3,796 | 66.13 |
| 244 | FM-2003020 | Fresno | B.F. Sisk Courthouse | 10-01 | 2 | Grounds and Parking Lot - Replace approx. 30 LF of damaged and unsafe perforated metal screening at (2) entry-gate locations off city sidewalks to employee parking lot and install handle guards on gate handles to prevent unauthorized persons from entry to employee lot. Screening is damaged in several locations and unsafe in others, requiring replacement with safe attachment points. | \$ 20,000 | \$ 20,000 | 100 |
| 245 | FM-2003038 | Lake | South Civic Center | 17-B1 | 2 | Grounds and Parking Lot - Restripe Safety - Repaint 33 standard parking stalls and (3) handicap parking stalls. Work includes required identification stenches, stop bars, Do Not Enter and (3) directional arrows. Existing striping is no longer visible. | \$ 10,946 | \$ 10,946 | 100 |
| 246 | FM-2003049 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 2 | Plumbing - Replace (1) pump coupling, (1) high temp seals and bearing (1) overhauled pump and (1) set of gaskets. Hot water pump bearing and seals failed due to age, affecting heating throughout the building. | \$ 9,254 | \$ 6,477 | 69.99 |
| 247 | FM-2003335 | Ventura | East County Courthouse | 56-B1 | 2 | HVAC - Replace (1) central plant controller, (4) air handling unit controllers and 2,000 LF of CAT5 cable for the BAS system. The central plant controller is original to building and failed due to age. (1) air handling controller failed due to age and the other (3) air handling controllers are longer compatible with the replaced central plant controller. BAS is currently being operated manually. | \$ 64,110 | \$ 39,588 | 61.75 |
| 248 | FM-2003350 | Los Angeles | Inglewood Courthouse | 19-F1 | 2 | Fire Protection - Replace 20 failed carbon dioxide sensor modules and rewire each module to existing fire alarm wiring throughout parking garage. Work requires fire alarm carbon dioxide testing and calibration in underground parking lot. Existing CO sensors failed and are past life expectancy requiring replacement. CO sensors failed during annual State Fire Marshal inspection. State Fire Marshal has submitted a corrective action to the Judicial Council. | \$ 34,947 | \$ 26,056 | 74.56 |
| 249 | FM-2003378 | Los Angeles | Norwalk Courthouse | 19-AK1 | 2 | Elevator - Replace internal components for the starter motor on in-custody Elevator #5. Internal components have worn on the starter motor, causing intermittent failure to elevator operation. Internal components are worn due to age. | \$ 5,059 | \$ 5,059 | 100 |
| 250 | FM-2003379 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | Elevators, Escalators, & Hoists - Replace elevator shoes and brakes on staff Elevator #8. Elevator went down due to brake and shoe wear loss due to age. | \$ 6,625 | \$ 6,625 | 100 |
| 251 | FM-2003381 | Madera | Main Courthouse - Madera | 20-F1 | 2 | HVAC - Replace failed combustion-air motor for boiler #1. Motor has internal short and is not reparable. | \$ 2,834 | \$ 2,834 | 100 |
| 252 | FM-2003382 | Los Angeles | Norwalk Courthouse | 19-AK1 | 2 | Plumbing - Storm Drain Line - Mechanically cleared 65 LF of storm drain main line, cleaned and epoxy painted 140 SF of concrete drain basin in north end exterior of building. Concrete was found cracked during rounds and readings and risked water intrusion into building. | \$ 11,133 | \$ 9,466 | 85.03 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|------------------|--|-------------|----------|--|----------------------|---|---|
| 253 | FM-2003384 | Santa Clara | Morgan Hill | 43-N1 | 2 | HVAC - Isolate water and replace failed OEM water flow switch for Boiler #1, test operation and | \$ 3,420 | \$ 3,420 | 100 |
| 254 | FM-2003387 | Imperial | Courthouse Winterhaven Court | 13-D1 | 2 | return to service. Flow switch failed due to age causing partial loss of heating. HVAC - Replace (1) 5-ton package AC unit and (1) 4-ton package AC unit that have been found to be failing with compressors and condenser coil leaks. Units are of age making it difficult to find parts and are having a difficult time keeping up in hottest months of the summer of 115 degree weather. These are the only two AC units supplying the building. Replacement of the package units will ensure adequate cooling for the courtroom, judges chambers, and clerks/service counter. | \$ 24,259 | \$ 24,259 | 100 |
| 255 | FM-2003388 | San Diego | East County Regional Center | 37-I1 | 2 | HVAC - Condensation Leak - Replaced 15 SF of duct insulation and (7) 24 x 24-inch saturated acoustic ceiling tiles due to condensation water intrusion affecting the 5th floor public elevator lobby. Extracted approx. 20 gallons of water, and sanitized 100 SF of affected carpet and hard surfaces. The cause was due to excessive outside humidity. Environmental testing, containment, and remediation work was required. | \$ 6,175 | \$ 4,181 | 67.71 |
| 256 | FM-2003390 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | Fire Protection - Replace (1) cylinder, (1) cartridge, (1) hose, 4.9 LF conduit, (3) brackets & (3) scissor links. Install (1) 1.5-gallon cylinder & dependent box to cover flow points, dependent box, and hose in kitchen hood #1 for kitchen fire suppression system. All items were found deficient during annual inspection and must be replaced to meet fire code. | \$ 6,326 | \$ 4,183 | 66.13 |
| 257 | FM-2003391 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 2 | HVAC - Replace (1) actuator (1) hot deck damper, and (1) thermostat. Calibrate all thermostats in (3) zones. Thermostat and original actuator failed due to age. Hot deck damper failure triggered zone calibration. Environmental testing, remediation and containment was required to complete work in known ACM environment. | \$ 28,144 | \$ 19,360 | 68.79 |
| 258 | FM-2003393 | Merced | Los Banos Division - The Robert M. Falasco Justice Center | 24-G1 | 2 | HVAC - Replace failed compressor #1 on AC-1. Unit supplies 50% of the building and is critically impaired with failed compressor. | \$ 11,894 | \$ 11,894 | 100 |
| 259 | FM-2003395 | Alameda | Wiley W. Manuel Courthouse | 01-B3 | 2 | Vandalism - Replace 8 in x 34 in holding cell glass in Cell #106-2. Glass broke due to vandalism. Court is impacted and holding cell is unusable until glass is replaced. Sheriff Department is seeking restitution for damage. | \$ 4,767 | \$ 4,767 | 100 |
| 260 | FM-2003396 | Santa Barbara | Santa Maria Courts, Bldg G | 42-F5 | 2 | HVAC Replace (1) heat exchanger for package unit #1. Heat exchanger failed due to age and multiple cracks and corrosion in the heat exchanger causing the package unit to fail affecting building temperatures. | \$ 3,125 | \$ 3,125 | 100 |
| 261 | FM-2003400 | Orange | Betty Lou Lamoreaux Justice Center | 30-B1 | 2 | HVAC - Replace (1) failed 60 HP variable frequency drive for the air handler #7 supply fan. The supply fan shut off on high temperature and there was loss of cooling to the Southeast section of the building floors 1 - 7. The existing VFD is aged and parts are no longer available. Work includes programming, start up, testing and verification of operations. | \$ 16,137 | \$ 12,902 | 79.95 |
| 262 | FM-2003404 | Fresno | Fresno County Courthouse | 10-A1 | 2 | Elevators, Escalators, & Hoists - Replace motor generator brushes and several LED push buttons on in-custody Elevator #4. Replace (4) door rollers, (2) door operator belts, upgrade door operator, and replace motor generator brushes on Staff Elevator #5 (court exclusive area). Parts are wearing out and need to be replaced to avoid service failure. | 10,528 | \$ 10,528 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|------------------|------------------------------------|-------------|----------|---|----------------------|---|---|
| 263 | FM-2003405 | Fresno | Fresno County | 10-A1 | 2 | Elevators, Escalators, & Hoists - Replace machine kit and seals on Staff Elevator #5 (court exclusive | \$ 33,151 | \$ 33,151 | 100 |
| 264 | FM-2003406 | Los Angeles | Courthouse Santa Monica Courthouse | 19-AP1 | 2 | area). Unit is leaking, and parts need to be replaced to avoid service failure. Plumbing - Replaced (1) chemical delivery system and (1) wall mount hardware kit. Existing chemical delivery system was not compatible for liquid delivery to the cooling towers. Existing system was removed, and new system installed. | \$ 4,343 | \$ 3,409 | 78.49 |
| 265 | FM-2003412 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 2 | HVAC - Replace (1) 3-inch gate valve and (1) 3-inch ball valve. Replace 30 LF of 1-inch copper pipe and 1-inch copper fittings. Install (5) cushion clamps, (2) 1-inch brass threaded couplers, (2) air vents and (4) gaskets. Drain approximately 200 gallons of water from loop. Boiler #2 on first floor has leak due to failed valves. Environmental testing performed. | \$ 12,358 | \$ 9,827 | 79.52 |
| 266 | FM-2003419 | Santa Barbara | Figueroa Division | 42-B1 | 2 | HVAC Replace (1) triometer, (1) low water cut out sensor and damaged firewalls for boiler #1. Components failed due to age. During Annual preventative maintenance. The firewall around Boiler #1 was discovered cracked and deteriorated. | \$ 6,249 | \$ 6,249 | 100 |
| 267 | FM-2003428 | Madera | Main Courthouse - Madera | 20-F1 | 2 | HVAC - Replace motor cooling solenoid valves/coils, serial card, and suction pressure transducer on chiller #1. Leak test and evacuate insolated compressor on circuit #2, perform start and test on both circuits, and recharge circuit #2 back to normal. Parts failed due to age, causing inverter temp alarms. Chiller is at 50% with circuit #2 down. | 15,350 | \$ 15,350 | 100 |
| 268 | FM-2003429 | Los Angeles | San Fernando Courthouse | 19-AC1 | 2 | Plumbing - Domestic Water Gate Valve - Replace (1) 2-1/2 in. OS&Y gate valve. The gate valve failed due to age, seized in the open position, and cannot be closed during routine maintenance. | \$ 4,234 | \$ 3,532 | 83.41 |
| 269 | FM-2003432 | Los Angeles | Inglewood Courthouse | 19-F1 | 2 | Fire Protection - Replace 84 emergency exit sign fixtures and (8) emergency light fixtures. Existing fixtures are no longer functioning to code, and all have failed annual test. Existing wiring will be utilized. | \$ 21,106 | \$ 15,737 | 74.56 |
| 270 | FM-2003438 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 2 | Interior Finishes - Fire Door - Replace (1) 3×9 ft. hollow metal door frame, (1) 90 min. fire rated 3×9 ft. door, (1) 6 in. door jamb, (1) 4 in. door frame throat, (1) $1-3/4 \text{ in.}$ door edge, (2) $1-1/2 \text{ in.}$ door returns, (4) $4-1/2 \text{ in.}$ hinges, (1) mortise lockset, and (1) door closer. The door was damaged by the Los Angeles Fire Department responding to a fire alarm after hours. The integrity of the door was compromised after forceable entry. The fire alarm panel was reset. | \$ 16,273 | \$ 13,097 | 80.48 |
| 271 | FM-2003441 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 2 | HVAC - Replace (1) controller circuit board, flow, switch, sensor, and tee. Replace (1) 1-inch plastic water meter, (2) wal-chem pumps, (3) 35-gallon double containment tanks, and (1) corrosion coupon rack with 3-station PVC 3/4-inch pipe, strainer and adjustable flow indicator. Coupon rack for delivery system is required to maintain and monitor water chemical balance. Previous controller and system failed due to age. | \$ 13,911 | \$ 11,062 | 79.52 |
| 272 | FM-2003444 | Santa Clara | Historic Courthouse | 43-B2 | 2 | Plumbing - Replace failed storm duplex lift station pumps, install (2) new 3/4 hp submersible pumps, (3) 35 ft float switches, (1) new control panel w/alarm and 50 ft of new 2-inch piping. Storm pumps failed due to age during preventive maintenance testing. | \$ 18,330 | \$ 18,330 | 100 |
| 273 | FM-2003446 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | HVAC - Replace (1) controller with circuit board, flow switch, sensor, and tee, (1) 35 gallon double containment tank, (1) metering pump, (1) corrosion coupon rack, pipe, and Y strainer for water treatment system. Water treatment system failed due to age and is no longer supported with replacement parts. | \$ 4,404 | \$ 2,912 | 66.13 |

| Item Number FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|--------------------------|--------------|--------------------------------------|-------------|----------|---|----------------------|---|---|
| 274 FM-2003455 | Los Angeles | Central Arraignment Courts | 19-U1 | 2 | County Managed - HVAC- Replace 21 wall mounted thermostats, calibrate, and adjust to adequate temperatures. Multiple thermostats are broken/damaged not allowing for proper calibration and multiple areas are extremely cold. | \$ 9,971 | \$ 9,971 | 100 |
| 275 FM-2003456 | Los Angeles | County Records Center | 19-AV3 | 2 | County Managed - Fire protection- Replace (30) fire hoses, repair (2) fire hose cabinets, and replace leaking spool piece with seismic braces. Building failed and the following deficiencies need to be repaired/replaced, leaking pipe connections, all fire hoses, and broken glass on two fire cabinets. | \$ 27,900 | \$ 27,900 | 100 |
| 276 FM-2003461 | Contra Costa | Richard E. Arnason Justice Center | 07-E3 | 2 | HVAC - Replace 40 horsepower Supply Fan #1. Bearing failed due to age causing noise to be heard inside courthouse. Replacement needed to restore proper component operation. | \$ 16,943 | \$ 16,943 | 100 |
| 277 FM-2003462 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 2 | HVAC - Replace (1) burner on the boiler and (1) refractory insulation cover. The burner is cracked and the refractory cover failed due to age causing the boiler to shut down. | \$ 2,996 | \$ 2,689 | 89.74 |
| 278 FM-2003465 | Los Angeles | San Fernando Courthouse | 19-AC1 | 2 | Plumbing - 6 in. Domestic Water Backflow Device - Replace (2) check valve seats, (2) check valve rubber kits, and (1) relief valve internal parts. Backflow failed during annual preventative maintenance. During the pressure check, valve #2 failed and leaked. | \$ 5,174 | \$ 4,316 | 83.41 |
| 279 FM-2003467 | San Diego | Central Courthouse | 37-L1 | 2 | Fire Protection - Replace missing firestop/mineral wool in (7) locations of opening on existing vertical cable-wiring conduits. Conduits must be sealed with fireproofing to be in regulatory compliance with NFPA. Deficiency was identified during annual State Fire Marshal visit. | \$ 3,501 | \$ 3,501 | 100 |
| 280 FM-2003468 | Los Angeles | Airport Courthouse Parking Structure | 19-AU2 | 2 | Elevator, Escalators, & Hoists - Replace (2) elevator contacts. Elevators #11 and #12 are inoperable because of the damaged contacts which failed due to age. | \$ 4,121 | \$ 3,180 | 77.17 |
| 281 FM-2003469 | Fresno | Fresno County Courthouse | 10-A1 | 2 | HVAC - Replace the pump seal kit, shaft sleeve and gasket in the South chiller condenser pump. Pump is leaking at the seal. | \$ 3,131 | \$ 3,003 | 95.91 |
| 282 FM-2003470 | Lassen | Hall of Justice | 18-C1 | 2 | HVAC - Replaced (6) failed cooling tower media pads. The existing pads are brittle and falling apart causing the pump to plug and run water over the side. | \$ 2,865 | \$ 2,865 | 100 |
| 283 FM-2003471 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | Fire Protection - Replace internal components of fire pump in the fire pump room. Fire pump internal components are worn and need to be replaced. | \$ 2,313 | \$ 1,530 | 66.13 |
| 284 FM-2003474 | Los Angeles | Glendale Courthouse | 19-H1 | 2 | Fire Protection - Install new fire penetration assemblies in Comm Room (Lock up), Comm Room (TT-2), 1st Floor electrical closet, 2nd Floor electrical closet, basement stairwell and MCR room in basement. Also includes installation of new fire penetration assemblies throughout basement and library for all conduit and wall penetrations as per the annual State Fire Marshal inspection report. These penetrations were never installed as fire penetration assemblies and are a fire, life, safety issue. | \$ 20,629 | \$ 18,677 | 90.54 |
| 285 FM-2003478 | Los Angeles | Torrance Courthouse | 19-C1 | 2 | Grounds and Parking Lot- Replace (1) pendant light fixture and (1) LED retrofit lamp in the Judges parking area. The lights in the parking lot shorted out due to rainwater entering the light fixture. | \$ 9,484 | \$ 9,484 | 100 |
| 286 FM-2003482 | Los Angeles | Santa Clarita Courthouse | 19-AD1 | 2 | County Managed - Vandalism - Patch and paint walls, doors and partitions in mens public restroom. Restroom was vandalized with graffiti. | \$ 2,652 | \$ 2,652 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|---|----------------------|---|---|
| 287 | FM-2003488 | Alameda | Fremont Hall of Justice | 01-H1 | 2 | Plumbing - Replace 10 feet of 2-inch drainpipe, install (3) no-hub connectors, and replace (6) stained ceiling tiles, area cleared for work from previous HAZMAT survey. Sanitary drainpipe cracked at connection due to age, causing minor leak at DA Office Lobby ceiling. | \$ 6,865 | \$ 5,45 | T 79.40 |
| 288 | FM-2003489 | Orange | Betty Lou Lamoreaux Justice Center | 30-B1 | 2 | Plumbing - Replace failed 100-gallon water heater. The water heater has developed a leak at the bottom and is unrepairable. The work includes installation of a new drain pan. | \$ 10,252 | \$ 8,19 | 79.95 |
| 289 | FM-2003493 | Lassen | Hall of Justice | 18-C1 | 2 | HVAC - Reseal accessible seams on Cooling Tower #1. Remove all accessible casing panels and old sealants, clean panels and seams, apply new sealant and reseal panels. Remove and clean upper fan deck and replace top seals where accessible. Perform final clean up and final operational testing. | \$ 8,050 | \$ 8,050 | 100 |
| 290 | FM-2003495 | Orange | West Justice Center | 30-D1 | 2 | HVAC - Replace failed boiler temperature controller. The boiler is only providing 80 degree water to phase 3 of the building and will only function in the manual position. Work includes replacement of boiler well, as it is in poor condition. | \$ 4,473 | \$ 4,05 | 90.68 |
| 291 | FM-2003496 | Tuolumne | Tuolumne County Courthouse | 55-D1 | 2 | HVAC - Replace the motor in roof exhaust fan #6. Motor internal electrical junction box had loose connection causing a short and arc which rendered the motor non-repairable. | \$ 4,027 | \$ 4,02 | 7 100 |
| 292 | FM-2003502 | Los Angeles | Pasadena Courthouse | 19-J1 | 2 | Plumbing - Replace (2) 4 in. shut off valves for backflow #6. Shut off valves were discovered to be leaking during preventative maintenance, preventing the backflow from passing the annual test. | \$ 6,843 | \$ 4,74 | 69.35 |
| 293 | FM-2003504 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | HVAC - Replace one (1) pump motor assembly for Boiler #5. Existing motor has failed due to age. | \$ 5,559 | \$ 3,67 | 66.13 |
| 294 | FM-2003510 | Los Angeles | County Records Center | 19-AV3 | 2 | County Managed - HVAC- Replace (3) steam traps, (1) condensate return pump, (1) relief valve, and re-pipe condensate return system. Repair steam line that has several leaks and system is not functioning with many areas without comfort heating. | \$ 39,060 | \$ 39,060 | 100 |
| 295 | FM-2003511 | Orange | Central Justice Center | 30-A1 | 2 | Plumbing - Replace (3) failed shower valves to remediate leak in the Sheriffs 1st floor locker room. Work includes replacement of 420 SF of tile on the floor, walls and curb, installation of water proofing membrane on approximately 120 SF of concrete surface, and installation of isolation valves. The leaking valves have caused damage to the shower floor and walls and a leak into the basement below. Work included remediation of lead paint on the damaged wall surfaces. | \$ 37,125 | \$ 37,12 | 5 100 |
| 296 | FM-2003514 | San Diego | Kearny Mesa Court | 37-C1 | 2 | HVAC - Replace one (1) failed variable frequency drive for Supply Fan of package unit #30. The variable frequency drive failure was discovered during rounds and readings. Failure to replace the variable frequency drive will prevent unit from regulating temperatures, impacting court operations. | \$ 3,818 | \$ 3,81 | 3 100 |
| 297 | FM-2003516 | Fresno | Fresno County Courthouse | 10-A1 | 2 | Fire Protection - Adjust the location of two fire sprinkler heads in one office and add a fire sprinkler head in another office, and obtain any required permits. Issues were cited in the 2022 City of Fresno Fire annual inspection report. | \$ 7,563 | \$ 7,25 | 95.91 |
| 298 | FM-2003517 | | East Los Angeles Courthouse | 19-V1 | 2 | Plumbing - Replace (1) 1/2 inch isolation valve, (1) 3/4 inch isolation valve, 40 LF of 1/2 inch copper pipe and (8) 1/2 inch 90-degree elbows. Isolation valves and parts failed due to age and corrosion. | \$ 2,834 | \$ 2,203 | 3 77.72 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--------------------------------|-------------|----------|--|----------------------|---|---|
| 299 | -M-2003518 | Orange | West Justice Center | 30-D1 | 2 | Exterior Shell - Replace one (1) failed set of retractable awning mechanical arms for Window #2. The failed arm is not able to open or close causing glare from sun and creating hot, unsafe surfaces for users. The awning covers a queuing area along the service windows. | \$ 2,602 | \$ 2,0 | 502 100 |
| 300 [| -M-2003524 | Fresno | B.F. Sisk Courthouse | 10-01 | 2 | Vandalism - Replace broken swing gate in courtroom with new double action solid core wood gate approximately 35 1/4 in. x 28 in. Gate was broken by a defendant and the court is seeking restitution. | \$ 3,841 | \$ 3,8 | 341 100 |
| 301 | FM-2003525 | Lassen | Hall of Justice | 18-C1 | 2 | HVAC - Reseal accessible seams on Cooling Tower #2. Remove all accessible casing panels and old sealants, clean panels and seams, apply new sealant and reseal panels. Remove and clean upper fan deck and replace top seals where accessible. Perform final clean up and final operational testing. | \$ 8,050 | \$ 8,0 | 100 |
| 302 | FM-2003530 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | HVAC - Replace (1) thermowell on the piping and install (1) new temperature transmitter and (1) transducer at the Chiller Room located on the 10th floor. Chiller is in low evaporator refrigerant temperature alarm identified during rounds and readings. Condition will cause overheating of the motor and poor performance of air conditioning system. | \$ 2,933 | \$ 2,2 | 77.17 |
| 303 | -M-2003533 | Fresno | Fresno County Courthouse | 10-A1 | 2 | Vandalism - Replace (1) 46 \times 75 \times 1/4 in. bronze anneal glass window on the 5th floor. A member of the public broke the window. Restitution is being sought. | \$ 3,841 | \$ 3,0 | 95.91 |
| 304 | -M-2003534 | Fresno | Fresno County Courthouse | 10-A1 | 2 | Vandalism - Replace (1) 51 x 113 x 1/4 in. gray tempered glass exterior window on the first floor, and (1) 51 x 75 x 1/4 in. gray anneal glass exterior window on the B-1 level Windows were broken by unidentified persons. | \$ 7,563 | \$ 7,2 | 95.91 |
| 305 [| FM-2003537 | Orange | Central Justice Center | 30-A1 | 2 | Interior Finishes - Abate approx. 180 SF of ACM fireproofing from multiple locations in the basement. The fire proofing has been compromised by water and is at risk of falling. Failure to remove this ACM material could result in a hazardous emergency release. Replacement fireproofing to be completed under separate FM. Containment and oversight required. | \$ 26,499 | \$ 24,: | .59 91.17 |
| 306 | FM-2003541 | Orange | Central Justice Center | 30-A1 | 2 | Plumbing - Replace (2) failed 3 inch valves on the heat exchangers. The heat exchangers require different pressures and the valves to control these pressures are no longer functioning for the tower and the West Wing of the building. Work includes installing new pressure gauges and after hours work. | \$ 14,909 | \$ 13,5 | 91.17 |
| 307 | FM-2003549 | Solano | Old Solano Courthouse | 48-A3 | 2 | Electrical - Replace (5) parking and (3) walkway lights at building exterior. Requires use of scissor lift. The parking lights are being supplied under warranty. Lights have failed due to age and are needed to restore proper lighting to ensure safety and security. | \$ 12,345 | \$ 12,3 | 100 |
| 308 | FM-2003554 | San Diego | East County Regional Center | 37-I1 | 2 | HVAC - Replace (3) 1/2 inch water vent valves and (2) 2-inch 200-psi pressure gauges. Reset (1) expansion tank and clean (1) air separator. Temperatures in 6th floor court offices and judges chamber are 80 degrees, affecting court operations. Chiller water loop pump #7 has air in the supply line causing higher temperatures to affected area due to damaged components. | \$ 13,076 | \$ 8,8 | 67.71 |
| 309 | -M-2003556 | Fresno | Fresno County Courthouse | 10-A1 | 2 | Fire Protection - Perform 12-year hydrostatic testing on the kitchen hood fire protection system, replace fire suppression cartridge, and replace outdated nozzles. Deficiencies were noted during annual preventive maintenance inspection. | \$ 3,509 | \$ 3,5 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|--------------------------------------|-------------|----------|---|----------------------|---|---|
| 310 | FM-2003557 | Contra Costa | Family Law Center | 07-A14 | 2 | Fire Protection - Replace (1) concealed sprinkler head cover and sprinkler support. During the annual preventative maintenance, the sprinkler head was found to be protruding from the ceiling due to failed sprinkler mount and support. The mount and support for the sprinkler are located above the ceiling. Repairs are needed to restore proper building fire safety. | \$ 4,391 | \$ 4,391 | 100 |
| 311 | FM-2003558 | Mendocino | County Courthouse | 23-A1 | 2 | Elevator - Replace (1) control board. Intermittent failures over the past month were traced to 40 year old circuit board. Work to be completed on court holiday. | \$ 6,280 | \$ 4,204 | 66.94 |
| 312 | FM-2003561 | Fresno | B.F. Sisk Courthouse | 10-01 | 2 | Vandalism - Replace 33 X 65 x 1-1/4 inch clear annealed glass window on the 1st floor front of building on south end Window was broken during the night by unidentified person. | \$ 3,293 | \$ 3,293 | 100 |
| 313 | FM-2003563 | Tulare | South County Justice Center | 54-I1 | 2 | Exterior Shell - Replace door pivots on the automatic exit doors. Door pivots have failed and the exit doors are not opening automatically. | \$ 2,466 | \$ 2,466 | 100 |
| 314 | FM-2003566 | Alameda | Fremont Hall of Justice | 01-H1 | 2 | HVAC - Replace (1) failed VFD at mechanical room and install new 7.5 VFD with bypass to support supply fan. VFD failed due to age causing loss of heat/cool air supply. | \$ 11,760 | \$ 9,337 | 79.40 |
| 315 | FM-2003570 | San Diego | Juvenile Court | 37-E1 | 2 | Interior Finishes - Replace (2) 3 \times 4-ft \times 1-1/2 inch swinging wood doors and hinge assemblies in courtroom. The solid wood swing doors that separate the gallery from the well have split and fell causing a safety hazard to occupants. | \$ 3,534 | \$ 3,534 | 100 |
| 316 | FM-2003574 | Santa Clara | Family Justice Center Courthouse | 43-B5 | 2 | Security - Replace (1) failed door closer at restraining order office, remove 10-foot glass door and replace (1) floor mounted closer, reinstall door, set and adjust closer. Door closer at restraining order office failed due to use (cycles 300 times per day) causing security issue. | \$ 9,100 | \$ 9,100 | 100 |
| 317 | FM-2003575 | Fresno | Fresno County Courthouse | 10-A1 | 2 | HVAC - Replace mini-split air conditioning unit in south elevator room serving passenger elevators 1, 2, 3. Compressor has failed due to age and unit will not start. Unit is obsolete refrigerant and should be replaced. | \$ 16,438 | \$ 15,766 | 95.91 |
| 318 | FM-2003577 | Los Angeles | Chatsworth Courthouse | 19-AY1 | 2 | Electrical - Replace 16 failed parking lot pole lighting assemblies that do not turn on due to failed 277v power supply drivers. The current parking lot light fixtures are obsolete and will be replaced with 100w LED 13,400 Lumens 5,000k CCT light fixtures. Due to the 30 foot height of the pole lights a boom lift will be required. | \$ 12,642 | \$ 10,594 | 83.80 |
| 319 | FM-2003579 | Contra Costa | Richard E. Arnason Justice Center | 07-E3 | 2 | HVAC - Replace failing contactor and auxiliary contactors for Cooling Tower #1. The current contactor and auxiliary contactors are no longer available or warrantied. Like for like replacement with available contactor and auxiliary contactor. Will require modification/relocation of components inside panel so new contactors will fit. | \$ 4,763 | \$ 4,763 | 100 |
| 320 | FM-2003581 | San Diego | Central Courthouse | 37-L1 | 2 | Interior Finishes - Install 10 concrete 1/4 anchors, erect (1) 24-foot scaffolding, and apply 10 SF of epoxy glue on the acoustic soundproof panels on ceiling in basement generator room. The acoustic panels serve as a sound barrier and had become detached due to water intrusion caused by ground level planter. | \$ 6,708 | \$ 6,708 | 100 |
| 321 | FM-2003582 | Los Angeles | County Records Center | 19-AV3 | 2 | County Managed - Plumbing - Replace 6-foot section of damaged main sewer line, saw/cut concrete, excavate soil 9-feet deep to expose line, install shoring, backfill/compact, and hydro jet line. Main sewer line is backing up and can potentially flood multiple areas. | \$ 39,765 | \$ 39,765 | 100 |

| Item Number FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION | PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|--------------------------|-------------------|--|-------------|----------|---|----------------------|-----------------------|---------------------------------------|---|
| 322 FM-2003583 | Los Angeles | County Records Center | 19-AV3 | 2 | County Managed - HVAC - Abate ACM insulation on piping, replace (1) chill water supply line, (1) chill water return valve, drain line and conduct environmental testing. Chill water supply & return lines area leaking on 3rd floor mechanical room and are unable to shut lines due to corrosion build up. | \$ 58,590 | \$ | 58,590 | 100 |
| 323 FM-2003586 | Fresno | Fresno County Courthouse | 10-A1 | 2 | Vandalism - Replace broken 47 x 75 inch window on 2nd floor public hallway with clear annealed 1/4 inch bronze glass. An unidentified member of public broke window. | \$ 3,841 | \$ | 3,684 | 95.91 |
| 324 FM-2003587 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | HVAC - Replace shaft bearings and motor bearings in Exhaust Fan #4. Parts failed due to age. | \$ 6,072 | \$ | 4,015 | 66.13 |
| 325 FM-2003603 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | Elevator - Disassemble and repair (1) brake relining, reinstall, adjust, and test new brakes. Staff Elevator #8 brakes needed relining due to wear and tear. | \$ 34,037 | \$ | 34,037 | 100 |
| 326 FM-2003606 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 2 | Plumbing - Replace (1) 6 in. backflow #10. Backflow failed during preventive maintenance / annual testing due to wear/tear. | \$ 4,396 | \$ | 3,077 | 69.99 |
| 327 FM-2003609 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 2 | Fire Protection - Replace fire alarm control panels and devices, and (1) fire alarm module. Fire alarm panel displays trouble mode and has failed due to age/end of life. | \$ 2,650 | \$ | 2,107 | 79.52 |
| 328 FM-2003610 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 2 | Plumbing - Replace (1) 2.5 in. backflow #9. Backflow failed during preventive maintenance / annual testing due to wear/tear. | \$ 8,519 | \$ | 5,962 | 69.99 |
| 329 FM-2003612 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 2 | Elevators - Replace (4) car rollers and 24 hoist way rollers for Elevator #5. Rollers have failed due to age, preventing the elevator from responding with the doors open. | \$ 7,430 | \$ | 5,462 | 73.51 |
| 330 FM-2003613 | Butte | Butte County Courthouse | 04-A1 | 2 | Elevator - Elevator #2 - Replace shaft seal, refill system, and perform operational testing. Elevator has failed shaft seal and oil in pit. Elevator is not operating. | \$ 7,083 | \$ | 7,083 | 100 |
| 331 FM-2003614 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | 2 | Interior Finishes - Loading dock exterior door - Replace non-fire rated door with 34 x 77 x 1-3/4 inch 18 gauge hollow galvanized steel door. Polystyrene Insulated, 90 Min Fire Rated UL Label, continuous hinge is required, and mortise lever emergency egress hardware. Deficiency was found during annual State Fire Marshal inspection and documented in corrective action report. | \$ 2,660 | \$ | 2,587 | 97.26 |
| 332 FM-2003615 | San Bernardino | Rancho Cucamonga Courthouse | 36-F1 | 2 | Interior Finishes - Remove 458 SF of carpeting (2 layers). Demo and buildback (2) cubicle workstations in Jury call center and a 2 x 2 section of carpeting in the Appeals file room. Apply 234 SF of self-leveling filler compound to concrete. Flooring is uneven causing desks and chairs to sit at different elevations, creating a trip hazard in walkways. Perform environmental testing, remediation, and containment as needed. | \$ 16,678 | \$ | 16,678 | 100 |
| 333 FM-2003616 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | 2 | Elevators, Escalators, & Hoists - Replaced defective start coil and fuses on Escalator #18. Escalator will not start and is currently out of service. Start coil failed due to wear and tear. No longer covered under warranty. | \$ 6,127 | \$ | 5,959 | 97.26 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|---|----------------------|---|---|
| 334 | FM-2003623 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | HVAC - Replace (2) actuators, (1) thermostat and (4) 12 x 12 in. ceiling tiles in 4th floor judges chambers. Actuators and thermostat failed due to age causing cold temperature in chambers. Environmental testing and oversight was included. Installed (1) 6 x 112 x 8 ft containment and (1) 36×76 in. decontamination chamber. | \$ 10,571 | \$ 10,571 | 100 |
| 335 | FM-2003624 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | Holding Cell - Replace (1) overhead concealed closer for existing door at Cell #9 at NE basement, court exclusive space, to meet ADA regulations. Door closer was reported not operational by the Sheriff. Existing door closer failed due to normal use and age. | \$ 4,671 | \$ 4,671 | 100 |
| 336 | FM-2003625 | Santa Clara | Family Justice Center Courthouse | 43-B5 | 2 | Electrical - Emergency Generator - Replace (1) failed electronic control unit (ECU)and program ECU. Run test and complete a 2 hour resistive load bank test. Replace crank case sensor and reflash controllers. Return unit to normal operation. Unit failed due to age. | \$ 35,550 | \$ 35,550 | 100 |
| 337 | FM-2003626 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 2 | HVAC - Replace (2) canvas connectors for supply fan #1 and #2. Canvas connectors failed due to age, affecting temperatures throughout the building by losing static pressure throughout the HVAC duct. | \$ 4,918 | \$ 3,442 | 69.99 |
| 338 | FM-2003628 | Los Angeles | Bellflower Courthouse | 19-AL1 | 2 | Fire Protection - Replace (1) 4-inch gate valve, (8) bolts, (8) nuts, and (2) gaskets in 4th floor fire sprinkler riser in fan room #7. Parts were corroded and failed due to age. | \$ 6,688 | \$ 5,213 | 77.94 |
| 339 | FM-2003635 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | Elevator, Escalators & Hoists - Replace (3) control system relays on Elevator #9 located at the 10th floor penthouse, court exclusive space. Relays failed due to normal usage and age causing elevator to shut down. | \$ 3,380 | \$ 3,380 | 100 |
| 340 | FM-2003394 | Del Norte | Del Norte County Superior Court | 08-A1 | 2 | Security - Replace 10 x 10 heavy duty rolling steel West Sally Port door, hood included, with commercial operator, 1/2hp, 110v/1ph, safety beam, momentary contact, single push to close activation, auxiliary chain hoist & brake included, cut off switch installed in ceiling. Proximity to the ocean has caused the door and track to rust and failure is imminent. | \$ 34,508 | \$ 34,508 | 100 |
| 341 | FM-2003431 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 2 | Grounds and Parking Lot - Replace (13) 16-ft slats on Sheriffs roll up exit gate. Sheriffs bus hit the main exit/entrance roll up gate damaging the roll up gate. The county will reimburse the Judicial Council for this cost. | \$ 5,956 | \$ 5,956 | 100 |
| 342 | FM-2003473 | Del Norte | Del Norte County Superior Court | 08-A1 | 2 | Security Door - Replace 10×10 heavy duty rolling steel East Sally Port door, hood included, with commercial operator, $1/2hp$, $110v/1ph$, safety beam, momentary contact, single push to close activation, auxiliary chain hoist & brake included, cut off switch installed in ceiling. Proximity to the ocean has caused the door and track to rust and failure is imminent. | \$ 34,508 | \$ 34,508 | 100 |
| 343 | FM-2003545 | Los Angeles | Whittier Courthouse | 19-AO1 | 2 | Security - GCI - Replace existing door closers for the main court entrance and exit with (2) powered door operators. Run 65 ft. of flex conduit & electrical wire and tie it to electrical panel. Numerous adjustments and repairs have been made to existing closers. Doors continually fail to secure due to high outdoor winds consequently creating security risk. Scope includes electrical load test, shop drawings, plan review, inspection and environmental testing/oversight. | \$ 76,125 | \$ 65,795 | 86.43 |
| 344 | FM-2003267 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 2 | Electrical - Replace (1) spill bucket for the underground fuel storage tank. The current spill bucket failed annual Preventive Maintenance due to age, affecting the underground emergency generator fuel storage tank. The cost includes the permitting fee of the LA County Department of Public Works. | \$ 10,925 | \$ 7,646 | 69.99 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|------------------|-----------------------------|-------------|----------|---|----------------------|---|---|
| 345 | FM-2003594 | Tehama | Tehama County Courthouse | 52-E1 | 2 | Electrical - DAS System - Troubleshoot and establish repair requirements. Replace failed power supply and perform satisfactory operational testing. | \$ 15,000 | \$ 15,000 | 100 |
| 346 | FM-2003636 | Los Angeles | | 19-AP1 | 2 | HVAC - Replace (1) seal and (4) gaskets on HVAC boiler pump. Hot water pump seal failed and leaked from pump seal requiring a rebuild. Failure is due to age and normal use. Heating will be impacted if pump fails. | \$ 6,594 | \$ 5,176 | 78.49 |
| 347 | FM-2003639 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | Vandalism - Replace (2) 24 x 36 inch and (1) 96 x 48 inch mirror and apply anti-graffiti film on 12 mirrors throughout the building mens and womens public restrooms. Existing mirrors have been vandalized by the public. | \$ 5,771 | \$ 4,453 | 77.17 |
| 348 | FM-2003640 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | Electrical - Replace (1) circuit board and (1) back-up battery power pack for master clock. Circuit board and battery pack failed due to age. | \$ 5,296 | \$ 3,502 | 66.13 |
| 349 | FM-2003641 | Yolo | Yolo Superior Court | 57-A10 | 2 | HVAC - Replace (1) blower motor for the Fan Coil Unit in the IDF Room. The blower motor has failed and is beyond repair. | \$ 4,366 | \$ 4,366 | 100 |
| 350 | FM-2003642 | Solano | Solano Justice Building | 48-B1 | 2 | Plumbing - Replace corroded faucet and reinforce framing to secure sink base. Patch and paint. Sink base is loose inside wall and has failed due to age. Requires ACM/Lead testing. The work is needed to restore operation of sink in jury restroom. | \$ 6,213 | \$ 6,213 | 100 |
| 351 | FM-2003643 | San Diego | Juvenile Court | 37-E1 | 2 | Roof - Install 40 SF of roof sealant/liquid membrane. During a walk for the roof project, several holes were discovered on the membrane, due to age. This is a temporary patch and the roof will be replaced as a DMF project. | \$ 3,940 | \$ 2,940 | 74.62 |
| 352 | FM-2003645 | San Joaquin | Stockton Courthouse | 39-F1 | 2 | Interior Finishes - Replace like-for-like top/bottom offset pivot hinges, door stop limit arms, and new sweep seals on the (4) eastern-most doors at front entrance. Perform full adjustment to bring into proper operation. Doors are failing at the pivot hinges causing cascading damage to moving parts and resulting in operational deficiencies including a bolt shearing off suddenly, and doors not closing when they get caught on the thresholds or when pivot hinges wedge the doors in place. | \$ 10,184 | \$ 10,184 | 100 |
| 353 | FM-2003658 | Los Angeles | Santa Monica Courthouse | 19-AP1 | 2 | HVAC - Replaced (1) gas valve, (1) gas regulator, (1) gas solenoid valve, (1) linkage assembly for the air actuator, and (1) flame rod. Adjusted and calibrated the boiler with a flue analyzer and recorded readings. Boiler flame failure is happening intermittently, due to failure of gas valve and regulator. Combination gas valve and gas regulator failed due to age, original to unit. | \$ 9,732 | \$ 7,639 | 78.49 |
| 354 | FM-2003660 | San Francisco | Hall of Justice | 38-B1 | 2 | Elevators - Replace (4) cable mounting brackets w/new heavy-duty steel brackets on (4) in-custody elevators, #9 through #12. Original 60 yr old mounting brackets were installed w/sheet metal screws and have failed causing units to stop due to safety sensor issues. | \$ 23,158 | \$ 23,158 | 100 |
| 355 | FM-2003661 | San Diego | Central Courthouse | 37-L1 | 2 | Fire Protection - Install 15 LF of galvanized steel flashing, mineral wool, and fire caulking around the existing fire/smoke damper located in the 23rd floor elevator machine room. The existing fire/damper was missing the required fire caulking that could result in smoke migration in the event of a fire. Deficiency identified by State Fire Marshal during annual inspection. | 4,012 | \$ 4,012 | 100 |
| 356 | FM-2003662 | Solano | Law and Justice Center | 48-A2 | 2 | HVAC - Replace main BAS controller, program all VAVs, and provide commissioning. Controller is failing due to age and needs to be restored. | \$ 17,354 | \$ 17,354 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION | PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|--|-------------|----------|--|----------------------|-----------------------|---------------------------------------|---|
| 357 | FM-2003677 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 2 | Fire Protection - Replace 500 SF of drywall, remove and relocate (6) fire sprinkler heads on the 1st Floor, 4th Floor Elevator #7/8 Lobby, 5th Floor Elevator #7/8 Lobby, and North Juvenile Storage Room. Deficiencies were identified per annual State Fire marshal inspection report. | \$ 17,426 | \$ | 12,196 | 69.99 |
| 358 | FM-2003678 | San Diego | Hall of Justice | 37-A2 | 2 | COUNTY MANAGED - Elevators Escalators, Hoists - Replace the entire step chain and (3) damaged steps on Escalator 1 - 2 (up). The escalator from 1st floor to 2nd floor is shutdown completely due to failure. System is non-operational. | \$ 4,112 | \$ | 4,112 | 100 |
| 359 | FM-2003682 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | Fire Protection - Replace (1) 60 minute fire rated door including standard cylindrical lock and (3) 4- $1/2 \times 4-1/2$ in. ball bearing hinges in courtroom lock up. Existing door has failed due to age. | \$ 5,991 | \$ | 5,991 | 100 |
| 360 | FM-2003685 | Los Angeles | Bellflower Courthouse | 19-AL1 | 2 | Plumbing - Replace internal bearings, sleeve, seal, gaskets, and associated fittings on Condenser Pump #2. Parts failed due to age. | \$ 5,197 | \$ | 4,051 | 77.94 |
| 361 | FM-2003689 | Los Angeles | Santa Monica Courthouse | 19-AP1 | 2 | Plumbing - Replace (2) 2-inch backflow devices, and 10 feet of corroded 2-inch galvanized pipe. Install 10 feet of 2-inch copper pipe to prevent pipe corrosion. (2) 2-inch backflow devices have failed due to end of life and corrosion. | \$ 11,606 | \$ | 9,110 | 78.49 |
| 362 | FM-2003691 | Contra Costa | Wakefield Taylor Courthouse | 07-A2 | 2 | Grounds - Remove (1) Cypress tree that is leaning over the public sidewalk. Remove (2) branches on adjacent Cypress tree which lean over public sidewalk. Grind Stump to 6-8 inches underground and haul away wood. Trees have grown to obstruct public sidewalk causing a hazard to the public. | \$ 5,464 | \$ | 5,464 | 100 |
| 363 | FM-2003692 | San Diego | North County Regional Center - South | 37-F1 | 2 | COUNTY MANAGED - HVAC - Replace chilled water Pump #3. Pump bearings have failed and pump is at the end of its useful life. Failure to replace will leave the building with insufficient cooling. | \$ 5,290 | \$ | 5,290 | 100 |
| 364 | FM-2003695 | Madera | Main Courthouse - Madera | 20-F1 | 2 | Plumbing - Isolate and drain down existing cold-water supply to the domestic booster pump skid and replace the existing 4-inch lug style butterfly valve on the skid bypass. Valve is leaking and needs to be replaced. | \$ 4,710 | \$ | 4,710 | 100 |
| 365 | FM-2003696 | Tulare | South County Justice Center | 54-I1 | 2 | HVAC - Repair leak at compressor for circuit #1 on Chiller #1. Leak at compressor head seal caused loss of refrigerant and oil from system. | \$ 11,790 | \$ | 11,790 | 100 |
| 366 | FM-2003698 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 2 | HVAC - Replace (1) Variable Frequency Drive (VFD) for Air Handler Unit Supply Fan #5. VFD unit is past its useful life and beginning to fail. VFD is not responding, causing the supply fan motor to run too slow creating comfort cooling and heating issues. | \$ 12,292 | \$ | 9,775 | 79.52 |
| 367 | FM-2003710 | Sacramento | Gordon Schaber Sacramento Superior Court | 34-A1 | 2 | Interior Finishes - Replace (1) defective door sensor and related hardware on the electric exit door at the West entrance. Person detecting sensor is malfunctioning at the west electric door. Sensor failed due to age. | \$ 4,393 | \$ | 4,393 | 100 |
| 368 | FM-2003711 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 2 | Elevators, Escalators & Hoists - Shortened the governor rope for Public Elevator #4 to have the elevator cart stop level with the floor, preventing a trip hazard. Elevator was recently red tagged by Fire Marshall for being out of compliance. | \$ 9,334 | \$ | 6,533 | 69.99 |
| 369 | FM-2003757 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | Elevator - Repair for West custody elevator #10 and public elevator #3 reported not responding. Engineers provided access coordinator to elevators top and bottom pits, electrical circuits for the elevators, and elevator machine rooms for vendor completing the repair throughout building. | \$ 9,769 | \$ | 7,539 | 77.17 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|--------------|--------------------------------------|-------------|----------|--|----------------------|---|---|
| 370 | FM-2003759 | Contra Costa | Richard E. Arnason Justice Center | 07-E3 | 2 | Electrical - Repairs needed for Power Inverter #3. Computer board has failed needing replacement. This is the backup power for the parking lot lights. Unit was found to have failed. | \$ 3,872 | \$ 3,872 | 100 |
| 371 | FM-2003766 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 2 | HVAC - Replace (1) water treatment flow rack, (1) control panel, (1) bleed off valve, and (2) water pumps which failed due to age. Failed water treatment equipment is not feeding chemicals to the HVAC systems which is causing water levels to have high conductivity and causing sediment buildup that is affecting the water quality. The installation of the new chemical delivery system will improve the efficiency of the HVAC equipment which will help with water quality and conservation. | \$ 4,558 | \$ 3,668 | 80.48 |
| 372 | FM-2003768 | Alameda | Wiley W. Manuel Courthouse | 01-B3 | 2 | Security - Replace (1) failed motor box at secure sliding door. Sliding door motor failed due to age causing loss of access to/from County connected building. | \$ 5,821 | \$ 4,878 | 83.80 |
| 373 | FM-2003769 | Alameda | Wiley W. Manuel Courthouse | 01-B3 | 2 | Exterior Shell - Replace (1) set of failed ADA wireless buttons at front lobby. Existing ADA buttons have failed due to age. | \$ 5,144 | \$ 4,311 | 83.80 |
| 374 | FM-2003778 | Santa Clara | Downtown Superior Court | 43-B1 | 2 | HVAC- Replace (1) failed 3HP supply fan motor on AHU #44, verify VFD settings, run, and test. AHU supply fan motor failed due to age causing loss of HVAC to the facility. | \$ 8,886 | \$ 8,886 | 100 |
| 375 | FM-2003779 | Lassen | Hall of Justice | 18-C1 | 2 | Elevators, Escalators, & Hoists - Replace (4) belt monitors that have failed due to age of the electronic/device. | \$ 14,099 | \$ 14,099 | 100 |
| 376 | FM-2003781 | Lassen | Hall of Justice | 18-C1 | 2 | HVAC - Replace failed boiler control board . Control board has failed and the boiler is not operational. | \$ 8,263 | \$ 8,263 | 100 |
| 377 | FM-2003793 | Los Angeles | Metropolitan Courthouse | 19-T1 | 2 | Plumbing – Replace 10 LF of 1/2-inch copper pipe, (1) 1/2-inch ball valve, (2) 1/2-inch couplings, and (1) 1/2-inch brass adapter. Hot water supply leaked due to corrosion requiring replacement. Remediation and environmental oversite required. | \$ 12,410 | \$ 11,732 | 94.54 |
| 378 | FM-2003797 | Riverside | Hemet | 33-F1 | 2 | Plumbing - Replace(6) gallon electric water heater that supports the holding cells. Due to age, the water heater failed to heat the domestic water to an acceptable temperature during a health inspection. Work includes associated valve replacement. | \$ 3,193 | \$ 3,193 | 100 |
| 379 | FM-2003799 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 2 | Elevators, Escalators, & Hoists - Replace brake pads on public Elevator #1. Pads failed due to age and wear and tear. Elevator was shaking and bouncing. | \$ 23,289 | \$ 18,100 | 77.72 |
| 380 | FM-2003801 | Yolo | Yolo Superior Court | 57-A10 | 2 | HVAC - Perform refrigerant tube inspection inside of (2) chillers, checking for leaks. Sand blast the inside of (2) end bells of chiller to remove the corrosion and apply epoxy coat. Corrosion will cause the chillers to suffer premature failure. | \$ 55,194 | \$ 55,194 | 100 |
| 381 | FM-2003802 | Alameda | Fremont Hall of Justice | 01-H1 | 2 | Electrical - Replace (6) failed LED lights at staff parking lot and repair parking lot lighting timer. Scissor lift is required. Parking lot lights are out causing a safety issue. | \$ 6,181 | \$ 4,908 | 79.40 |
| 382 | FM-2003804 | Alameda | Wiley W. Manuel Courthouse | 01-B3 | 2 | Vandalism - Replace (1) 8 x 34-inch poly-temper-glass window at holding cell. In-custody broke window. District Attorney is seeking restitution. | \$ 4,767 | \$ 4,767 | 100 |
| 383 | FM-2003805 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 2 | HVAC - Replace (1) fan prop assembly on Cooling Tower #2, (1) 2-speed motor, (1) banded belt, (1) cooling tower vibration switch, (1) water fill, (1) drift eliminator, (1) external cooling tower float, with clay valve, and (1) pressure regulator. Preventive maintenance inspection identified Cooling Tower #2 required repairs to multiple components within both towers due to wear and tear. | \$ 57,119 | \$ 45,421 | 79.52 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BULLDING ID SHORT TITLE | | | | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------------------|---|---|----|--------|---|---|
| 384 | FM-2003812 | Los Angeles | Torrance Courthouse | 19-C1 | 2 | HVAC - Replace (2) pressure relief valves, (2) flow switches, (2) hot surface ignitors, and (2) control devices on heating boilers. The devices have failed due to end of life. Heating boilers are offline and not providing heating to the building. | | 8,920 | \$ 7,5 | 85.14 |
| 385 | FM-2003813 | Los Angeles | Beverly Hills Courthouse | 19-AQ1 | 2 | HVAC - Replace (1) fan prop assembly on Cooling Tower #1, (1) 2-speed motor, (1) banded belt, and (1) cooling tower vibration switch, (1) water fill, (1) drift eliminator, (1) external cooling tower float, with clay valve, and (1) pressure regulator. Preventive maintenance identified Cooling Tower #1 required repairs to multiple components due to wear and tear. | \$ | 57,239 | \$ 45,5 | 79.52 |
| 386 | FM-2003815 | Madera | Main Courthouse Parking Structure | 20-F2 | 2 | Grounds and Parking Lot - Replace guide track and damaged rods on parking garage roll down gate. Install new safety edge with retainer and take-up rail, align and reset limit on motor. Parking garage roll down gate is not closing. | \$ | 4,559 | \$ 4,5 | 59 100 |
| 387 | FM-2003816 | San Diego | Central Courthouse | 37-L1 | 2 | Vandalism - Replace (1) 25-1/2 x 34-inch window in holding cell door. Window was broken by incustody and poses safety hazard to personnel. Seeking restitution. | \$ | 2,850 | \$ 2,8 | 50 100 |
| 388 | FM-2003817 | Tehama | Tehama County Courthouse | 52-E1 | 2 | HVAC - AHU1 return fan has failed bearings, excessive wear on shaft and wheel is degraded. Remove and replace fan wheel, shaft, and bearings. | \$ | 9,668 | \$ 9,6 | 58 100 |
| 389 | FM-2003820 | Sacramento | Gordon Schaber Sacramento Superior Court | 34-A1 | 2 | Exterior Shell - Replace (1) 60 x 121 inch cracked glass at 6th floor cafeteria. Plywood was placed over broken glass while replacement glass is on order. This window is an exterior window to the roof. The cause of the breakage is unknown. | \$ | 11,528 | \$ 11,5 | 28 100 |
| 390 | FM-2003821 | Alameda | Fremont Hall of Justice | 01-H1 | 2 | HVAC - Repair leaks on (2) compressors, install (1 each) lip seal bypass kit on compressors #1 and #2, and (1) new oil safety switch on compressor #2. Leaks were found during rounds and readings. | \$ | 6,077 | \$ 4,8 | 25 79.40 |
| 391 | FM-2003822 | San Mateo | Northern Branch Courthouse | 41-C1 | 2 | Vandalism - Emergency board up and replace (1) 4 x 6 ft. grey annealed glass pane. Defendant broke window outside the courtroom. DA is seeking restitution. | \$ | 7,203 | \$ 5,9 | 94 83.21 |
| 392 | FM-2003823 | Alameda | Hayward Hall of Justice | 01-D1 | 2 | HVAC - Replace (3) failed current transformers, (1) chilled water sensor, and purge (2) driers. Deficiencies were found during chiller preventive maintenance. | \$ | 3,706 | \$ 3,2 | 72 88.30 |
| 393 | FM-2003824 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 2 | Grounds and Parking Lot - Replace 10 feet of 2-1/2 inch irrigation PVC pipe and associated fittings. Excavate 48 SF in grass area adjacent to Judges parking lot. Pipe failed due to age affecting landscaping throughout grounds. | \$ | 10,000 | \$ 7,7 | 72 77.72 |
| 394 | FM-2003827 | San Diego | East County Regional Center | 37-l1 | 2 | HVAC - Replace (1) 50HP motor and coupling on chilled water pump #7 to allow for sufficient cooling. The motor failed due to age. | \$ | 8,469 | \$ 5,7 | 67.71 |
| 395 | FM-2003831 | Tulare | South County Justice Center | 54-l1 | 2 | Electrical - Replace failed block heater on emergency generator. Block heater needed for proper operation of the generator. | \$ | 4,748 | \$ 4,7 | 100 |
| 396 | FM-2003839 | Los Angeles | Van Nuys Courthouse West | 19-AX2 | 2 | Vandalism - Replace (1) $68 \times 54 \times 1/2$ inch protective window to the in-custody interview and holding area in courtroom on the 3rd floor. The protective window between the in-custody and court staff has been damaged over time due to inmates hitting the window with their handcuffs causing multiple cracks to the surface of the glass. The damaged window poses a danger to incustody personnel and staff if the window breaks. | \$ | 6,058 | \$ 6,0 | 58 100 |
| 397 | FM-2003840 | Alameda | Fremont Hall of Justice | 01-H1 | 2 | Electrical - Retrofit 10 failed metal halide light fixtures to LEDs at parking area under the solar panels, and replace (3) 4-pole lighting contactors with (1) 12-pole contactor. Lighting failed due to age causing safety issues at parking area. | \$ | 7,182 | \$ 5,7 | 79.40 |

| LOCATION FACILITY N | | | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|---------------------|-------------|--|-------------|----------|---|----------------------|---|---|
| 398 FM-2003842 | Los Angeles | Chatsworth Courthouse | 19-AY1 | 2 | Grounds and Parking Lot - Apply 450 LF of hot rubberized crack sealant filler to asphalt. Cracks have formed in the asphalt along the Northside employee parking due to age as well as vehicle traffic wear and tear. An incident report has been documented due to a court employee trip and fall on the northside employee parking. Cracks along the asphalt were noted as the possible cause. | \$ 7,802 | \$ 6,538 | 83.80 |
| 399 FM-2003847 | Ventura | East County Courthouse | 56-B1 | 2 | HVAC - Replace (1) controller for buildings boiler. The boiler controller failed due to age affecting boiler controls from operating as designed. | \$ 7,218 | \$ 4,457 | 61.75 |
| 400 FM-2003849 | San Diego | Kearny Mesa Court | 37-C1 | 2 | Fire Protection - Install (5) self-luminous wireless exit signs. Current locations are missing required signage and need to be installed per State Fire Marshal annual inspection. Work includes containments, environmental testing and oversight due to known ACM environment. | \$ 3,457 | \$ 3,457 | 100 |
| 401 FM-2003851 | Calaveras | Calaveras Superior Court | 05-C1 | 2 | Electrical - Replace failed central clock transmitter. Initial troubleshooting and repair attempts failed necessitating replacement. | \$ 11,183 | \$ 11,183 | 100 |
| 402 FM-2003856 | San Diego | Central Courthouse | 37-L1 | 2 | Electrical - Replace (4) 8D size 24 volt 25 AMP batteries for emergency generator. Existing batteries amperage level has fallen below required levels which will prevent the generator from starting in emergency situations. Failures were caused by age and identified during routine preventative maintenance. | \$ 3,642 | \$ 3,642 | 100 |
| 403 FM-2003866 | San Diego | East County Regional Center | 37-I1 | 2 | HVAC - Condensation Leak - Replace 10 SF of acoustic ceiling tiles and disinfect 10 SF of hard surfaces. The air handler condensate drain line clogged and overflowed from above the mechanical room onto the 1st floor public corridor between courtrooms. Remediation and oversite was required to complete work. | \$ 3,473 | \$ 2,352 | 67.71 |
| 404 FM-2003873 | Siskiyou | New Yreka Courthouse | 47-H1 | 2 | Exterior Finishes - Replace 32 x 96 inch exterior window in secure hallway. Cause of breakage is unknown. | \$ 13,859 | \$ 13,859 | 100 |
| 405 FM-2003877 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | HVAC - Replace failed shaft, bearings, air inlet cone, and belts on HVAC Fan #1. Perform air balance test at completion of replacement. Preventative Maintenance identified Air Handler #1 was off its axis causing improper function and failure of the rear bearing which caused damaged to other parts of the air handler. AHU #1 is located at the 10th floor, mechanical room servicing the West side of the building. | \$ 50,849 | \$ 39,240 | 77.17 |
| 406 FM-2003887 | Los Angeles | Alfred J. McCourtney Juvenile Justice Center | 19-AE1 | 2 | County Managed - Grounds and Parking Lot - Remove (1) large ash tree and stump in front of the courthouse. Tree is dead and branches have fallen due to rainstorms, creating a safety hazard to public. | \$ 4,504 | \$ 4,504 | 100 |
| 407 FM-2003889 | Riverside | Hemet | 33-F1 | 2 | Plumbing - Replace (2) failed staff toilets with new pressure assisted models. The current toilets are continually backing up due to insufficient flushing pressure. Work includes installation of new seals. | \$ 3,895 | \$ 3,895 | 100 |

| Item Number | FM NUMBER | FM NUMBER LOCATION FACILITY NAME | | | | SHORT TITLE | PRELIMINARY ESTIMATE | | PRELIMINARY ESTIMATE | | PRELIMINARY ESTIMATE | | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|----------------------------------|---|--------|---|---|----------------------|--------|----------------------|-------|----------------------|--|---|---|
| 408 | FM-2003892 | San Diego | Central Courthouse | 37-L1 | 2 | Plumbing - Sanitized and dried 150 SF of concrete floor, 30 SF of ceramic base tile, (4) SF of metal raised floor drain, (7) SF of gray plastic grease trap, (2) SF of metal decking, (4) SF of gray vinyl sheet flooring and dried in place 10 SF of fireproofing. Grease trap clogged, causing water to spill out and travel-through two floor penetrations, down to B1 level affecting fire proofing and pooling on the vinyl sheet flooring and laminated desk. The grease trap maintenance is the responsibility of the cafeteria operator and the Judicial Council will seek reimbursement. | • | 7,722 | \$ 7,722 | 100 | | | | |
| 409 | FM-2003896 | Santa Clara | Morgan Hill Courthouse | 43-N1 | 2 | Roof - Remediate roof leak at chambers restroom and first floor hallway, patch roof, run dryers, repair 45 SF of damaged walls and 200 SF of ceiling tiles. Rainwater leaked into building. | \$ | 6,423 | \$ 6,423 | 100 | | | | |
| 410 | FM-2003904 | San Francisco | Civic Center Courthouse | 38-A1 | 2 | Fire Protection - Replace (1) failed tamper switch, (1) horn/strobe, and (8) backup batteries on the fire alarm system. Fire inspection corrective issues. | \$ 1 | .0,440 | \$ 10,440 | 100 | | | | |
| 411 | FM-2003917 | Tulare | South County Justice Center | 54-l1 | 2 | Fire Protection - Replace failed tamper switches on main fire sprinkler system backflow preventor. Tamper switches were exposed to water when the vault in which the backflow is housed flooded due to a failed seal on one of the valves. | \$ | 2,636 | \$ 2,636 | 100 | | | | |
| 412 | FM-2003918 | Los Angeles | Torrance Courthouse | 19-C1 | 2 | Vandalism - Replace (1) 6 in x 12 ft metal trim, weld in place, install trim piece to cover exposed edges at bottom of wall paneling, replace damaged drywall and re-anchor wall to floor and adjacent concrete wall at the Basement lock-up hallway interview room. An in-custody ripped the metal trim from the wall and kicked adjacent wall causing it to push out from anchor points. Environment/ACM testing will be conducted. | - | 9,175 | \$ 9,175 | 100 | | | | |
| 413 | FM-2003920 | Contra Costa | Walnut Creek Courthouse | 07-C1 | 2 | Fire Protection -Replace fire panel radio dialer for the holding cell fire panel with like for like replacement. Dialer is unable to consistently perform the daily dial-out to the monitoring company. Dialer failed due to age. | \$ | 3,840 | \$ 3,840 | 100 | | | | |
| 414 | FM-2003923 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 2 | HVAC - Replace (1) chemical controller circuit board, flow switch sensor, flow switch, and associated fittings. Water treatment system failed due to age due to age. Chemical feeder is needed to prevent corrosion throughout all HVAC equipment. | | 5,359 | \$ 4,165 | 77.72 | | | | |
| 415 | FM-2003927 | Santa Cruz | Watsonville Courthouse | 44-B2 | 2 | HVAC - Replace (1) 5-ton condensing unit supporting server room. Rooftop condensing unit failed due to age causing loss of cooling for server room equipment. | \$ | 3,822 | \$ 3,822 | 100 | | | | |
| 416 | FM-2003928 | San Mateo | Northern Branch Courthouse | 41-C1 | 2 | Plumbing - Repair leaking domestic water supply pipe at court staff restroom, isolate pipe, replace failed elbow, end cap, patch/paint ceiling and wall. Small leak from water pipe caused water damage to ceiling and wall by sink. | \$ | 4,917 | \$ 4,917 | 100 | | | | |
| 417 | FM-2003936 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 2 | Grounds and parking - Replace 30 ft of 6 in. ABS pipe for exterior main line, and remove (3) trees. Hydro-jetted line to clear clog affecting jury assembly room restrooms on ground floor. Ran camera back in line and identified break in the line located (9) ft down exterior of building under 2nd row of trees. Used an excavator to trench 30 x 10 ft. deep area. Shoring required for trench to remove broken sewer line which failed due to tree roots located above line. | | 9,249 | \$ 36,203 | 73.51 | | | | |
| 418 | FM-2003937 | Solano | Hall of Justice | 48-A1 | 2 | Plumbing - Replace (1) 3-inch domestic backflow assembly. Unit has failed due to age and parts are no longer available. Needed to restore proper operation. | \$ 1 | .2,663 | \$ 9,221 | 72.82 | | | | |
| 419 | FM-2003938 | Tulare | South County Justice Center | 54-l1 | 2 | Fire Protection - Install remote test switch for basement smoke control system. Failed State Fire Marshal Inspection which requires a manual method of testing the smoke control system for I-3 occupancies. | \$ | 6,983 | \$ 6,983 | 100 | | | | |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|--|----------------------|---|---|
| 420 | FM-2003947 | Los Angeles | East Los Angeles Courthouse | 19-V1 | 2 | Utilities - Replace (2) 40-gallon tanks, and (1) 20-gallon tank. Chemical delivery system tanks failed due to age. The installation of the chemical delivery tanks will improve the efficiency of the equipment and help with water conservation. Environmental testing and oversight not required. | \$ 3,192 | \$ 2,481 | 77.72 |
| 421 | FM-2003899 | San Diego | North County Regional Center - South | 37-F1 | 2 | COUNTY MANAGED - Electrical - Phase 1 Design - Replace interior lighting control software system, relays, controllers, and modules at all (5) stories including exterior parking lot. Existing lighting relays, controllers, and modules are beyond their useful life and can no longer be updated or maintained. Failure to replace equipment will result in loss of bldg. automation to control lighting throughout campus. | \$ 67,240 | \$ 67,240 | 100 |
| 422 | FM-2003686 | Santa Clara | Hall of Justice (East) | 43-A1 | 2 | Security - Replace (1) door closer on public exit door. Exit door closer failed due to age and wouldn't latch causing a security issue. | \$ 5,654 | \$ 5,654 | 100 |
| 423 | FM-2003825 | Alameda | Fremont Hall of Justice | 01-H1 | 2 | Vandalism - Replace (1) 6 x 7 ft broken exterior sliding glass door at 2nd floor chambers balcony. Unidentified person used ladder to access the balcony and break into the building through the exterior sliding glass door. | \$ 7,876 | \$ 6,254 | 79.40 |
| 424 | FM-2003500 | Shasta | Justice Center Court Modular | 45-A9 | 2 | Exterior Shell - GCI - Disconnect and cap utilities. Remove site fencing, and guard rails, patch and repair existing site to prior condition. Coordinate with modular vendor to disassemble courtroom modular. The lease for the modular has expired and the County is planning on extending the existing building to the current location of the modular. | \$190,000 | \$ 190,000 | 100 |
| 425 | FM-2003568 | Alameda | Wiley W. Manuel Courthouse | 01-B3 | 2 | Plumbing - Remove 10 existing flush valves and retrofit with 10 Sloan flushometer valves, (10) push buttons, and(4) control modules. The existing Sloan valves serving the holding cell toilets allow the in custodies to purposely back up the toilets then repeatedly press the push buttons, causing flooding inside the holding cells. This issue has been recurring and is causing costly damage and loss of operational time for the courts. | \$107,270 | \$ 107,270 | 100 |
| 426 | FM-2004086 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | Exterior Shell - GCI - Replace plaza stairwell roofs and planter waterproofing including any abatement, install interior walls and finishes within stairwell towers and adjacent storage rooms. Water is coming into the building and damaging interior finishes. Existing exterior stairwell roof has failed due to age. | \$ 660,635 | \$ 436,878 | 66.13 |
| 427 | FM-2003539 | Los Angeles | Bellflower Courthouse | 19-AL1 | 2 | HVAC - GCI - Replace heating and cooling coils on Air Handling Units 1 through 8 which are beyond their useful life. The existing air handlers are failing and not providing adequate heating and cooling. | \$ 581,430 | \$ 453,167 | 77.94 |
| 428 | FM-2003830 | San Diego | North County Regional Center - North | 37-F2 | 2 | HVAC - GCI - Replace 10 Air Handling Units (AHUs). Existing AHUs are at the end of their life cycle. The existing equipment is full of rust, bacterial growth and completely falling apart and needs to be replaced. | \$3,440,600 | \$ 3,440,600 | 100 |
| 429 | FM-2003807 | Placer | Howard G. Gibson Courthouse | 31-H1 | 2 | HVAC - Replace (1) 8-ton and (1) 5-ton A/C units for IT room. The current units are failing due to age. | \$ 166,684 | \$ 166,684 | 100 |
| 430 | FM-2004040 | Monterey | Salinas Courthouse- North Wing | 27-A1 | 2 | Elevator Modernization - AEI - PHASE 1 DESIGN - Provide construction documents and permitting for the modernization of (3) public elevators and (1) in-custody elevator. Modernization will include making elevators accessible. Existing elevators are failing due to age. | \$ 183,304 | \$ 183,304 | 100 |

| Item Number | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-------------|------------|-------------|--|-------------|----------|--|----|----------------------|---|---|
| 431 | FM-2003512 | San Diego | Trailer - Dept 34 | 37-F4 | 2 | Exterior Shell - Replace 193 LF of metal fence extension at top of secured area stucco wall, prime and paint metal frames, and screen. Existing metal screens and metal framework are severely corroded due to exposure to the elements and have caused severe rust stains on stucco walls. Environmental testing for hazardous materials will be performed. Containment and remediation work may be required. | \$ | 116,956 | \$ 116,956 | 100 |
| 432 | FM-2003414 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 2 | Exterior Shell - Window and door systems - Replace approx. 250 glass panel silicone bead of the rotunda entrance of the building. Utilize (2) 80ft boom lifts to reach the 4-story courthouse. Window seals leak in the rotunda entrance during heavy rains. | \$ | 155,000 | \$ 113,941 | 73.51 |
| 433 | FM-2003870 | Los Angeles | Stanley Mosk Courthouse | 19-K1 | 2 | Interior Finishes - GCI- Replace 183 individual spectator seats in (2) courtrooms on 5th and 7th floors. Replace damaged vinyl floor tiles and remove mounting bolts to receive new seating. Environmental testing, remediation and oversight required. Original spectator seating is damaged beyond repair due to age and use. All salvageable parts will be used to make repairs throughout the building. | \$ | 299,060 | \$ 299,060 | 100 |
| | | | | | | Total: | \$ | 16,066,022 | \$ 12,189,937 | |

| Item Number | CFR NUMBER | COUNTY | BUILDING ID | FACILITY | LEASE, LICENSE, OR FM | CFR DESCRIPTION | CFR TERM | FUND SOURCE | TOTAL APPROVED |
|-------------|------------|-------------|-------------|--------------------------------|-----------------------------|--|----------|-------------|-------------------|
| 1 | 03-CFR005 | Amador | 03-C1 | Amador Superior Court | Facility Modification | The court needs a fourth courtroom. We need to meet with an architect to determine if if it is feasible to reconfigure our current space or if we need to add a courtroom. | n/a | TCTF | \$150,000 |
| 2 | 06-CFR006 | Colusa | 06-A2 | Courthouse Annex | Facility Modification | Funds to cover material and labor to repair the public service lobby including repairing the public service counter, and interior wall painting and trim. | n/a | TCTF | \$29,983 |
| 3 | 09-CFR006 | El Dorado | 09-A1 | Main St. Courthouse | Facility Modification | Cost will complete the replacement of torn and tattered carpeting throughout the South Lake Tahoe facility, removal and installation of new rubber base, asbestos testing and removal and/or reinstallation of fixtures, seating and other furniture. | n/a | TCTF | \$135,848 |
| 4 | 15-CFR030 | Kern | 15-C1 | Bakersfield Juvenile Center | Facility Modification | Install walk up window to include fire curtain per fire code. The Probate Department will use the window to serve the public. | n/a | TCTF | \$97,593 |
| 5 | 15-CFR031 | Kern | 15-A1 | Bakersfield Superior Court | Facility Modification | Re-landscape flowerbed at the front and west side of the court facility. The space currently has sparse vegetation and insufficient irrigation. Project includes water saving irrigation and vegetation. | n/a | TCTF | \$67,587 |
| 6 | 19-CFR106 | Los Angeles | 19-00 | Multiple | Facility Modification | This is a CFR from LA court intended to address locations that require ADA improvements to gain entry into the building for Staff and/ or Judicial Officers from within Staff and Secured parking areas. The project is budgeted at \$1,593,200. | n/a | TCTF | \$1,593,200 |
| 7 | 19-CFR107 | Los Angeles | 19-00 | Multiple | Facility Modification | This is a CFR from LA court intended to address locations that have been identified as needing security fencing or modifications to the property to control pedestrian and/ or vehicular access. Locations identified are: Stanley Mosk, Compton, Glendale, San Fernando, Norwalk, West Covina, El Monte, and McCourtney. | n/a | TCTF | \$4,910,000 |
| 8 | 19-CFR108 | Los Angeles | 19-00 | Multiple | Facility Modification | Proposed project will provide the infrastructure at a total of 211 courtrooms in Santa Monica, Stanley Mosk, Whittier, Chatsworth, Beverly Hills, Pomona South, Long Beach, and Pasadena courthouses which are required to support upgraded courtrooms technologies and associated equipment. The equipment will be provided and installed by the court. | n/a | TCTF | \$27,906,000 |
| 9 | 19-CFR109 | Los Angeles | 19-U1 | Central Arraignment Courts | Facility Modification | Funding to secure the parking spaces for the judicial Officers at Central Arraignment Courts. | n/a | TCTF | \$237,000 |
| 10 | 19-CFR110 | Los Angeles | 19-00 | Multiple | Facility Modification | Funds intended to address multiple sites that have been identified for landscaping, and exterior improvements. As part of improvements all new plants are to be California native and drought tolerant and existing irrigation sprinkler heads are to be replaced with drip system heads. | n/a | TCTF | \$1,180,150 |
| 11 | 19-CFR111 | Los Angeles | 19-00 | Multiple | Facility Modification | Funding intended to fund installation of all required electrical work, data cabling raceways and related modifications, patching and repairs where existing directories are removed. Cost also includes furnishing and installation of Court specified monitors. | n/a | TCTF | \$735,000 |
| 12 | 19-CFR112 | Los Angeles | 19-00 | Multiple | Facility Modification | Proposed project includes the revision of exterior signage at courthouses (San Fernando, Sylmar, Inglewood Juv., Antonovich, Norwalk, Van Nuys East, Santa Monica, Mosk, Foltz). Signage revisions are intended to address courthouses that are not using the standard wording of "" Courthouse Superior Court of California County of Los Angeles. Existing signage wording and scope varies from site to site. | n/a | TCTF | \$400,000 |
| 13 | 19-CFR113 | Los Angeles | 19-00 | Multiple | Facility Modification | Proposed funding contribution from the court in the amount of \$1,100,000.00 is intended to address electrical deficiencies, at Foltz Courthouse, which have been cited by the State Fire Marshal. | n/a | TCTF | \$1,100,000 |
| 14 | 19-CFR114 | Los Angeles | 19-AV1 | Hall of Records | Facility Modification | The proposed project will develop three meeting/conference rooms on the ground floor of the Hall of Record with adequate storage space. Cost is intended to fund all required aspect of design and construction of this project. | n/a | TCTF | \$2,750,000 |

| Item Number | CFR NUMBER | R115 Los Angeles 19-K1 Stanley Mosk | | FACILITY | LEASE, LICENSE, OR FM | CFR DESCRIPTION | CFR TERM | FUND SOURCE | TOTAL APPROVED |
|-------------|------------|-------------------------------------|--------|--|-----------------------------|--|----------|-------------|-------------------|
| 15 | 19-CFR115 | Los Angeles | 19-K1 | Stanley Mosk Courthouse | Facility Modification | Reactivate courtrooms and chambers within Stanly Mosk Courthouse for more efficient operations. A rough order of magnitude of \$10,100,000 has been budgeted for the Courtrooms Reactivation Project. | n/a | TCTF | \$10,100,000 |
| 16 | 19-CFR116 | Los Angeles | 19-AV1 | Hall of Records | Facility Modification | The proposed project realigns Court spaces and departments within Stanly Mosk Courthouse and Hall of Records to consolidate departments for more efficient operations. | n/a | TCTF | \$3,200,000 |
| 17 | 19-CFR117 | Los Angeles | 19-AX1 | Van Nuys Courthouse East | Facility Modification | Funding for construction and reconfiguration of the Van Nuys East first floor Clerk's Office and offices/rooms within that space. This includes but not limited to construction, demo, removal of furniture, inspection fees, FACS fees and all other stated work on the construction/bid documents. | n/a | TCTF | \$847,673 |
| 18 | 19-CFR118 | Los Angeles | 19-Q1 | Edmund D. Edelman Children's Court | Facility Modification | Funds intended for construction for the future build-out of two courtrooms, ancillary spaces and restroom on the 6th floor of the Edmund D. Edelman Children's Courthouse. Also included is construction of a fire rated corridor on the same floor down the east hallway. | n/a | TCTF | \$3,646,853 |
| 19 | 24-CFR030 | Merced | 24-A1 | Old Court | Facility Modification | Courtroom 8 Judicial Officer and Courtroom Clerk bench needs to be redesigned to due to significant increased workers' compensation claims and to be ADA compliant. | n/a | TCTF | \$15,000 |
| 20 | 28-CFR005 | Napa | 28-B1 | Historic Courthouse | Facility Modification | Installation of court provided TV wall mount in conference room. | n/a | TCTF | \$2,432 |
| 21 | 34-CFR027 | Sacramento | 34-D1 | Carol Miller Justice Center Court Facility | Facility Modification | Facility maintenance project utilizing the JCC building maintenance provider, Pride Industries, to coordinate with outside vendor to install rod-iron fencing around the employee parking lot. | n/a | TCTF | \$372,596 |
| 22 | 35-CFR005 | San Benito | 35-C1 | San Benito County Superior Court | Facility Modification | Install one Pelcro camera to tie into current VideoXpert CCTV, and include a new video license for the addition of one camera. | n/a | TCTF | \$5,873 |
| 23 | 51-CFR006 | Sutter | 51-C1 | Sutter County Superior Courthouse | Facility Modification | Proposed funding contribution from would cover costs associated with the plan to renovate the current inactive records rolling storage area located on the 1st floor (suite 138). This would include, but is not limited to, design, permitting, demolition, electrical/data/low voltage, construction, new office configuration, furniture installation and relocation, flooring, audio video, lighting, fire, access control, and HVAC work. | n/a | TCTF | \$360,000 |
| 24 | 52-CFR007 | Tehama | 52-E1 | Tehama County Courthouse | Facility Modification | Funds would add a new power circuit in order to hang a monitor outside the Court's Self Help area. Refers to Work Order 1741336. | n/a | TCTF | \$3,909 |
| 25 | 52-CFR008 | Tehama | 52-E1 | Tehama County Courthouse | Facility Modification | Funds for installation of a new dedicated circuit to run a new receptical that would power two new monitors at the Courts front main entrance. This funding would also include the mounts and brackets to install the monitors. | n/a | TCTF | \$3,910 |
| 26 | 01-CFR009 | Alameda | 01-J1 | East County Hall of Justice | Facility Modification | The funding contribution would cover the costs of replacement of the uninterrupted power supply (UPS) failed power module. | n/a | TCTF | \$28,204 |
| 27 | 15-CFR032 | Kern | 15-A1 | Bakersfield Superior Court | Facility Modification | Remove floor plumbing/electrical, and two office to create a larger and safer area for public seating. | n/a | TCTF | \$54,282 |
| 28 | 19-CFR119 | Los Angeles | 19-00 | Multiple | Facility Modification | Funding for Project Management Services to be provided to the Los Angeles Superior Court for projects including, but not limited to lighting improvements, ADA ramp additions, tenant alteration projects and landscaping. | n/a | TCTF | \$580,431 |
| 29 | 19-CFR121 | Los Angeles | 19-00 | Multiple | | | | | \$0 |
| 30 | 30-CFR040 | Orange | 30-A1 | Central Justice Center | Facility Modification | Feasibility study for a new Collaborative Courts facility located in the Super Block parking lot adjacent to the Central Justice Center (30-A1). | n/a | TCTF | \$109,920 |
| 31 | 48-CFR016 | Solano | 48-00 | Multiple | Small Project | Annual Budget of \$50,000 to address multiple small projects. | n/a | TCTF | \$50,000 |
| | | | | | | Total: | | | \$ 60,673,444 |



Meeting Date: 4/10/2023

Action Item 7 – List E – Court-Funded Requests (CFRs)

Summary:


- 1. Review CFR projects approved by the Facilities Services Director since the last meeting and CFR projects cancelled.
- 2. Approve ongoing O&M costs associated with CFR No. 36-CFR081 for installation of electric vehicle charging stations at the San Bernardino Justice Center (36-R1).

| Facility Modification CFRs | 36 |
|----------------------------|----|
| Lease CFRs: | 2 |
| Small Project CFRs: | 1 |
| Total Approved CFRs | 39 |
| Cancelled CFRs: | 1 |

Supporting Documentation:

- List E Approved Court-Funded Facilities Requests; Cancelled Court-Funded Facilities Requests
- CFR and Supplemental Form from San Bernardino Superior Court for the installation of 74 EV charging pedestals at San Bernardino Justice Center.

List E Distribution





Open Meeting Items Meeting Date: 4/10/2023

| Item # | CFR Number | County | Building ID | Facility Name | Lease, License, or FM | CFR Description | Lessor | Lessee | CFR Term | Fund Source | Total Approved | Status | Date Approved |
|--------|------------|--------------|-------------|------------------------------------|-----------------------------|--|--|---------------------|----------------------|-------------|-------------------|----------|------------------|
| Ope | n CFRs | | | | | | | | | | | | |
| 1 | 04-CFR022 | Butte | 04-F1 | North Butte County Courthouse | Facility Modification | Funds to order and install manually operated roller blinds within the Chico Courthouse Administrative Offices. | N/A | N/A | n/a | TCTF | \$11,723 | Accepted | 03/20/23 |
| 2 | 06-CFR007 | Colusa | 06-A2 | Courthouse Annex | Facility Modification | Funds would cover the construction costs to remodel and reconfigure an existing file room into offices and/or a conference/training room facility, as well as the materials and labor to remodel and repair aspects of an existing judge's chambers and breakroom. | N/A | N/A | n/a | TCTF | \$215,000 | Accepted | 03/28/23 |
| 3 | 07-CFR013 | Contra Costa | 07-A3 | Bray Courts | Facility Modification | CFR will fund facilities modifications to the holding cells located in the A.F. Bray Courthouse. Estimated Budget \$ 2,109. | N/A | N/A | n/a | TCTF | \$2,109 | Accepted | 03/20/23 |
| 4 | 07-CFR014 | Contra Costa | 07-F1 | George D. Carroll Courthouse | Facility Modification | CFR will fund facilities modifications to the holding cells located in the George D. Carroll Courthouse. | N/A | N/A | n/a | TCTF | \$12,748 | Accepted | 03/20/23 |
| 5 | 07-CFR015 | Contra Costa | 07-C1 | Walnut Creek Courthouse | Facility Modification | CFR will fund facilities modifications to the holding cells located in the Walnut Creek Courthouse. | N/A | N/A | n/a | TCTF | \$10,165 | Accepted | 03/20/23 |
| 6 | 08-CFR006 | Del Norte | 08-A1 | Del Norte County Superior Court | Facility Modification | Move, redesign, construction costs for public counters. | N/A | N/A | n/a | TCTF | \$63,000 | Accepted | 03/20/23 |
| 7 | 10-CFR020 | Fresno | 10-R1 | M Street Courthouse | Lease | The cost covered all tenant improvements to build a holding cell restroom for in-custody defendants. | Wolfsen Land & Cattle Compan y | Judicial Council | 1/1/23 - 12/31/28 | TCTF | \$206,286 | Accepted | 12/12/22 |
| 8 | 15-CFR033 | Kern | 15-B1 | Bakersfield Justice Bldg. | Facility Modification | Install eight interior secured walk up window in the Family Law Department. | N/A | N/A | n/a | TCTF | \$257,125 | Accepted | 03/13/23 |
| 9 | 15-CFR034 | Kern | 15-A1 | Bakersfield Superior Court | Facility Modification | Install a restroom at the east wing of the second floor. | N/A | N/A | n/a | TCTF | \$229,625 | Accepted | 03/13/23 |
| 10 | 15-CFR035 | Kern | 15-A1 | Bakersfield Superior Court | Facility Modification | Install fencing to include one vehicle gate and one pedestrian gate to secure the exterior middle area of the court. | N/A | N/A | n/a | TCTF | \$312,125 | Accepted | 03/13/23 |

Open Meeting Items Meeting Date: 4/10/2023

| Item # | CFR Number | County | Building ID | Facility Name | Lease, License, or FM | CFR Description | Lessor | Lessee | CFR Term | Fund Source | Total | Status | Date Approved |
|--------|------------|-------------|-------------|--|-----------------------------|--|--------|--------|----------|-------------|--------------|----------|------------------|
| 11 | 15-CFR036 | Kern | 15-K1 | 3131 Arrow Street | Facility Modification | Install canopy to shelter public while receiving court services. | N/A | N/A | n/a | TCTF | \$98,313 | Accepted | 03/13/23 |
| 12 | 15-CFR037 | Kern | 15-B1 | Bakersfield Justice Bldg. | Facility Modification | Install a second exterior public help window. Install canopy to shelter public while receiving court services. | N/A | N/A | n/a | TCTF | \$199,375 | Accepted | 03/13/23 |
| 13 | 15-CFR038 | Kern | 15-J2 | Ridgecrest - Division B Courtroom | Facility Modification | Cost to create plans to expand Ridgecrest Division B to be a full service court | N/A | N/A | n/a | TCTF | \$57,000 | Accepted | 03/16/23 |
| 14 | 15-CFR039 | Kern | 15-C1 | Bakersfield Juvenile Center | Facility Modification | Installation of Mini Split HVAC Unit. | N/A | N/A | n/a | TCTF | \$49,230 | Accepted | 03/20/23 |
| 15 | 16-CFR010 | Kings | 16-A5 | Kings Superior Court | Facility Modification | Funds to cover the costs of construction and includes contingency and inspections, etc., to increase the count of parking lot spaces available for Courthouse visitors conducting business, individuals responding to jury summons and Court and Sheriff employees that report to work daily. | N/A | N/A | n/a | TCTF | \$433,624 | Accepted | 03/20/23 |
| 16 | 16-CFR011 | Kings | 16-A5 | Kings Superior Court | Facility Modification | Funds to cover the cost of the Working Drawings phase associated with completing one courtroom, otherwise designated as Department 12, and all related adjacent operational areas within the Kings County Courthouse, located in Hanford, CA. | N/A | N/A | n/a | TCTF | \$143,000 | Accepted | 03/20/23 |
| 17 | 17-CFR011 | Lake | 17-B1 | South Civic Center | Facility Modification | Remodel the public lobby space and replace the monument sign. | N/A | N/A | n/a | TCTF | \$80,000 | Accepted | 03/20/23 |
| 18 | 19-CFR120 | Los Angeles | 19-L1 | Clara Shortridge Foltz Criminal Justice Center | Facility Modification | Funds would cover the costs associated with construction plan for the Foltz 2nd floor Civil Appeals department in a space currently occupied by a different court department. This would include but not limited to; a new layout, plans for electrical, data paths, security paths, new finishes, lighting plan, occupancy load, and room designations based on the courts needs and request. | N/A | N/A | n/a | TCTF | \$20,000,000 | Accepted | 03/28/23 |

Open Meeting Items Meeting Date: 4/10/2023

| Item # | CFR Number | County | Building ID | Facility Name | Lease, License, or FM | CFR Description | Lessor | Lessee | CFR Term | Fund Source | Total Approved | Status | Date Approved |
|--------|------------|-------------|-------------|--|-----------------------------|--|---------------------------|---------------------|---------------------|-------------|-------------------|----------|------------------|
| 19 | 19-CFR121 | Los Angeles | 19-00 | Multiple | | | | | | | \$500,000 | Accepted | |
| 20 | 19-CFR121 | Los Angeles | 19-00 | Multiple | Facility Modification | This is for the construction of the multiple Clerk's Office locations. This would be to construct but not limited to; a new constructed layout, electrical, data paths, lighting, signage, finishes, flooring, and all other build outs in the original bid. | N/A | N/A | n/a | TCTF | \$20,100,000 | Accepted | 03/28/23 |
| 21 | 19-CFR122 | Los Angeles | 19-L1 | Clara Shortridge Foltz Criminal Justice Center | Facility Modification | Funds would cover the costs associated with construction plan for the Foltz 2nd floor Civil Appeals department in a space currently occupied by a different court department. This would include but not limited to; a new layout, plans for electrical, data paths, security paths, new finishes, lighting plan, occupancy load, and room designations based on the courts needs and request. | N/A | N/A | n/a | TCTF | \$2,123,000 | Accepted | 03/28/23 |
| 22 | 22-CFR026 | Mariposa | 22-A1 | Mariposa County Courthouse | Facility Modification | Cost to improve the courts workspace layout for the court offices including a more conducive and ergonomically set up to allow more efficiencies within the office and better flow for the public. | N/A | N/A | n/a | TCTF | \$88,753 | Accepted | 03/20/23 |
| 23 | 24-CFR031 | Merced | 24-F2 | 810 West Main Street | Lease | Court's funding will be used for renewing the existing lease with McAuley Properties for storage. | McAuley Properti es | Judicial Council | 1/14/23- 1/15/28 | TCTF | \$232,200 | Accepted | 11/17/22 |
| 24 | 27-CFR006 | Monterey | 27-B1 | Marina Courthouse | Facility Modification | Installation of bollards for the front entrance of the Marina Courthouse. | N/A | N/A | n/a | TCTF | \$20,000 | Accepted | 03/23/23 |
| 25 | 31-CFR019 | Placer | 31-H1 | Howard G. Gibson Courthouse | Facility Modification | Installation of six new power outlets in the court's server room. | N/A | N/A | n/a | TCTF | \$10,000 | Accepted | 03/20/23 |
| 26 | 31-CFR020 | Placer | 31-H1 | Howard G. Gibson Courthouse | Facility Modification | Purchase and installation of five (5) water bottle filling stations at the Gibson Courthouse and adjacent jail courtroom. Locations: adjacent to: 1st/2nd floor staff restrooms; 1st/2nd floor public restrooms; jail courtroom staff restroom. | N/A | N/A | n/a | TCTF | \$60,000 | Accepted | 03/20/23 |

Open Meeting Items Meeting Date: 4/10/2023

| Item # | CFR Number | County | Building ID | Facility Name | Lease, License, or FM | CFR Description | Lessor | Lessee | CFR Term | Fund Source | Total Approved | Status | Date Approved |
|--------|------------|----------------|-------------|--------------------------------------|-----------------------------|---|--------|--------|----------|-------------|-------------------|----------|------------------|
| 27 | 31-CFR021 | Placer | 31-H1 | Howard G. Gibson Courthouse | Facility Modification | Purchase and installation of manual window coverings in the Gibson Courthouse jury assembly room. | N/A | N/A | n/a | TCTF | \$20,000 | Accepted | 03/20/23 |
| 28 | 31-CFR022 | Placer | 31-H1 | Howard G. Gibson Courthouse | Facility Modification | Install vision windows in two doors located in the secure area of the courthouse. | N/A | N/A | n/a | TCTF | \$4,250 | Accepted | 03/20/23 |
| 29 | 35-CFR006 | San Benito | 35-C1 | San Benito County Superior Court | Facility Modification | Design costs, construction documents, bidding assistance, construction support, and concept layout & field investigations to convert resource room into Judges Chambers and modify Jury Assembly room into new courtroom to accommodate large jury panel. | N/A | N/A | n/a | TCTF | \$223,814 | Accepted | 03/23/23 |
| 30 | 36-CFR082 | San Bernardino | 36-S2 | Temporary Parking Lot | Facility Modification | Funds would cover the cost to install a chain link perimeter fence and two lockable driveway gates at the entries. | N/A | N/A | n/a | TCTF | \$50,000 | Accepted | 03/28/23 |
| 31 | 36-CFR083 | San Bernardino | 36-R1 | San Bernardino Justice Center | Facility Modification | Funds would cover the design build cost associates with tenant improvement needs at the SBJC district. These improvements include: the removal of select walls and doors to accommodate an expansion in space to support the employee growth needed | N/A | N/A | n/a | TCTF | \$500,000 | Accepted | 03/28/23 |
| 32 | 39-CFR017 | San Joaquin | 39-F1 | Stockton Courthouse | Facility Modification | Costs are for solar film on interior glazing at the second floor overlooking the lobby. | N/A | N/A | n/a | TCTF | \$10,123 | Accepted | 03/20/23 |
| 33 | 39-CFR018 | San Joaquin | 39-F1 | Stockton Courthouse | Facility Modification | Funds will cover the base exterior window cleaning, interior atrium, all sides, floor to ceiling cleaning. These costs will include all the safety training as well. | N/A | N/A | n/a | TCTF | \$259,835 | Accepted | 03/20/23 |
| 34 | 42-CFR028 | Santa Barbara | 42-00 | Multiple | Small Project | This funding is to cover small projects that come up throughout the year. | N/A | N/A | n/a | TCTF | \$40,000 | Accepted | 03/20/23 |
| 35 | 42-CFR029 | Santa Barbara | 42-F1 | Santa Maria Courts Bldgs C + D | Facility Modification | Funds would cover enhancements to a courtroom recently the victim of arson. The Court will remove fixed theatre style seating and the bar. | N/A | N/A | n/a | TCTF | \$250,000 | Accepted | 03/20/23 |

| Item # | CFR Number | County | Building ID | Facility Name | Lease, License, or FM | CFR Description | Lessor | Lessee | CFR Term | Fund Source | Total Approved | Status | Date Approved |
|--------|------------|---------------|-------------|---|-----------------------------|---|--------|--------|----------|-------------|-------------------|-----------|------------------|
| 36 | 42-CFR030 | Santa Barbara | 42-G1 | Santa Barbara Jury Assembly Bldg. | Facility Modification | Funds would cover the replacement of public audience seating and carpeting in buildings where the current conditions create safety hazards and liability issues. | N/A | N/A | n/a | TCTF | | Accepted | 03/20/23 |
| 37 | 42-CFR031 | Santa Barbara | 42-F1 | Santa Maria Courts Bldgs C + D | Facility Modification | Funds would cover the relocation of the Superior Court's primary server room outfitted with appropriate HVAC, raised floor, enhanced electrical. | N/A | N/A | n/a | TCTF | \$400,000 | Accepted | 03/20/23 |
| 38 | 46-CFR004 | Sierra | 46-A1 | Courthouse/Sheriff Station-Jail | Facility Modification | Courtroom repairs: Refinish bench and clerks desktop, wood pony wall caps, gallery pews, jury & witness chairs, replace carpet and vinyl base, paint walls. | N/A | N/A | n/a | TCTF | \$108,933 | Accepted | 03/20/23 |
| 39 | 49-CFR017 | Sonoma | 49-B2 | 3055 Cleveland Avenue | Facility Modification | Removal of existing shelving units and Installation of 9 cubicles. | N/A | N/A | n/a | TCTF | \$129,389 | Accepted | 03/20/23 |
| 40 | 50-CFR032 | Stanislaus | 50-A1 | Modesto Main Courthouse | Facility Modification | | N/A | N/A | n/a | TCTF | \$15,000 | Accepted | 03/20/23 |
| | | | | | | | | | | Total: | \$47,725,745 | | |
| Cano | elled CFRs | | | | | | | | | | | | |
| 41 | 31-CFR023 | Placer | 31-H1 | Howard G. Gibson Courthouse | Facility Modification | Costs to demolish existing walls, patch, and stub electrical to provide better use of the facility. Current wall was constructed to create a clerk's window that is no longer used. | N/A | N/A | n/a | TCTF | \$24,288 | Cancelled | 03/20/23 |
| | | | | | | | | | | Total: | \$24,288 | | |

Judicial Council - Court-Funded Facilities Request (CFR) Form

| Superior Court of California, County of | San Bernardino | Building ID:36-R1 | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|--|
| Building Name: | San Bernardino Justice Center | | | | | | | | | |
| Building Address: | 247 West Third Street, San Bernardin | no, CA 92415 | | | | | | | | |
| Court Contact Name: | Nate Lemley | Title: Facilities Project Manag | | | | | | | | |
| Court Contact E-mail: | NLemley@sb-court.org | Phone: (909) 708-8760 | | | | | | | | |
| 1. Indicate nature of urgent request (check one): Lease-related cost (excluding records storage) Lease costs only, OR Lease costs including tenant improvement costs Lease for records storage only Lease costs only, OR Lease costs including tenant improvement costs Facilities-related cost allowable under rule 10.810 (i.e., equipment, furnishings, interior painting, flooring replacement or repair, or furniture repair) Other facility improvements that are not allowable court operations expenditures under rule 10.810 (i.e. facilities operations, maintenance, repairs, and modifications, but not capital projects), if they either improve a court facility's functionality or improve court operations Annual budget to address multiple small projects, under \$50,000 each (for either non-rule 10.810 and/or rule 10.810 allowable) 2. Provide documentation reflecting the court's ability to meet its financial commitment through the term of the | | | | | | | | | | |
| | • | _ | | | | | | | | |
| | ental form (estimated court financial | commitment). | | | | | | | | |
| CFR Supplemental F | orm is attached | | | | | | | | | |
| 3. Describe the costs that court's p | proposed funding contribution woul | d cover (attach additional pages if needed). | | | | | | | | |
| This CFR is for a total amount of \$394, to install 74 EV charging pedestals for t service and networking under this CFR \$15,300 per year for the annual service for ten years. A new CFR will need to be | 523.00. The court will cover the entire the amount of \$333,323. The court and . The court's portion of these cost are and networking. SCE has a requirem the submitted for years 6 through 10. It rvice and networking per the 2021 res | cost of material, labor and contingency costs of the JCC will split the cost of the annual \$15,300 per year. The JCC will also pay ent that the chargers must remain operable will be appropriate for the JCC and the Court ponsibility matrix since the charges would be | | | | | | | | |
| 4. If the request would fund a lease 4.1 Describe the planned use of be separated by use with per | | urtroom, office); multi-use space should each. | | | | | | | | |
| N/A | | | | | | | | | | |
| 4.2 State the start and ending dat | es of the lease term and any option | s for renewal (if known). | | | | | | | | |
| N/A | | | | | | | | | | |
| 4.3 State the scope and cost of a | Il tenant improvements to be perfor | med on facility if lease is approved. | | | | | | | | |
| N/A | | | | | | | | | | |

Judicial Council - Court-Funded Facilities Request (CFR) Form

| 4.4 | State the number of court officers and staff to be located in the space. Note: For space to be designated as rule 10.810 records storage, the duties of the staff in the building need to support records storage. |
|---|---|
| N/A | |
| | cribe why the court deems the request urgent as well as the manner in which operations would be improved |
| The us state's | ers of the court will have the ability to charge their EV vehicles; and the court will be taking active steps to meet the EV initiatives. This funding would contribute to the overall project. |
| rep floo fun | is is not an allowable court operations expenditure under rule 10.810 (i.e. facilities operations, maintenance airs, and modifications that are not rule 10.810 costs such as equipment, furnishings, interior painting, pring replacement or repair, or furniture repair), describe how the project either improves a court facility's actionality or improves the court operations and any special considerations or features of the desired wices that the court's contribution would fund. |
| This pr | oject would provide access to modern electric vehicle chargers for both staff and public user of the court. |
| yea | the court received a loan or advance from the TCTF or other judicial branch fund in the current or last fisca r, or anticipate requesting one in the current fiscal year? If so, indicate amount and fiscal year, and loan ayment plan. |
| No. | |
| with thi applica as othe contrib | sing below, the court certifies that it has verified its ability to meet the financial commitments associated is request. The court agrees that its TCTF allocation will be reduced, during the period specified in the tion to meet the full financial commitment, notwithstanding any other court financial needs that may arise, in court facilities funding sources are fully committed and therefore not available to replace a court ution. The court agrees that it has verified its ability to meet the financial commitments associated to request in the tion to meet the full financial commitments associated to request in the tion to meet the full financial commitments associated as request. |

Date

Court Funded Request (CFR) Supplemental Form

(Estimated Court Financial Commitment)

In the table below, please provide the estimated costs, where the funding is from, and the fund for the costs for all applicable years for Court's estimated financial commitment.

Supplemental Form Prepared by: Mark-Anthony Coombs, Finance Manager Contact Name and Phone Number: Mark-Anthony Coombs (909) 363-4618

Date: March 8, 2023

| ter Facility Name and Facility ID: SBJC- 36-R1 | Fiscal Year I (Current Year) | Fiscal Year 2 | Fiscal Year 3 | Fiscal Year 4 | Fiscal Year 5 | Fiscal Year 6 | Total |
|--|---------------------------------|-----------------------|------------------|------------------|------------------|------------------|----------|
| Lease-rela | ated costs (exc | luding record | ds storage) | | | | |
| Estimated Annual Rent Including Escalation | | | | | | | |
| (Enter effective & termination date here) | | | | | | | |
| Estimated Annual Maintenance | | | | | | | |
| Localities / Milan Preliment | | | | | | | |
| Estimated Annual Utilities | | | | | | | |
| Fraince d Accord to the city | | | | | | | |
| Estimated Annual Janitorial | | | | | | | |
| Estimated Tenant Improvements (if applicable) | | | | | | | |
| Total Lease-related costs including tenant improvements | | | | | | | |
| (excluding records storage): | | 50 | \$0 | 50 | 50 | \$0 | |
| | lated costs for | r <u>records stor</u> | rage only | | | | |
| Estimated Annual Rent Including Escalation | | | | | | | |
| (Enter effective & termination date here) | | | - | | | _ | |
| Estimated Annual Maintenance | | | | | | | |
| | | | | | | | |
| Estimated Annual Utilities | | | | | | _ | |
| Estimated Annual Janitorial | | | | | | | |
| | | | | | | | |
| Estimated Tenant Improvements (if applicable) | | | | | | | |
| Total Lease-related costs including tenant improvements for records storage only | \$0 | 50 | SO | \$0 | \$0 | SO | |
| | ilities-related | | | 30 | 30 | 30 | |
| rac | miles-i ciateu | costs of 110j | ccis | | - | | |
| Facilities-related cost allowable under rule 10.810 | | | | | | | |
| Facilities-related costs not allowable under rule 10.810 | | | | | | | |
| (e.g., facility modification) | 333,323 | 15,300 | 15,300 | 15,300 | 15,300 | | 394,52 |
| Multiple small projects annual budget, under \$50,000 each | | | | | | | |
| Manupic sinan projects annual budget, dider \$50,000 caen | | | | | | | |
| Total Facilities-related costs or Projects | \$333,323 | \$15,300 | \$15,300 | \$15,300 | \$15,300 | SO | \$394,52 |
| Total Cost Estimate: | \$333,323 | \$15,300 | \$15,300 | \$15,300 | \$15,300 | 50 | \$394,52 |
| | Fund Source | e Amounts | | | | | |
| | | | | | | | |
| General Fund - TCTF | 394,423 | | | | | | 394,42 |
| General Fund - Non-TCTF | | | | | | | |
| Special Revenue Non-Grant* | | | | | | | |
| (Identify Special Revenue and code statute) | | | | | | | |
| Special Revenue Grant** | | | | | | | |
| (Identify Special Revenue Grant) | | | | | - | | |
| Capital Project | | | | | | | |
| Total Fund Source: | \$394,423 | 50 | 50 | SO | SO | \$0 | \$394,42 |
| Total Costs vs. Total Funding Variance: | \$61,100 | -\$15,300 | -\$15,300 | -\$15,300 | -\$15,300 | \$0 | -\$10 |
| Source of Funding | | | | | | | |
| | | 1 | T | | | T | |
| Operating Budget | 394,523 | | | | | | 394,5 |
| | | | | | | | |
| Fund Balance | | | | | | | |
| Total Source of Funding: | | 50 | 50 | -50 | 50 | \$0 | \$394,52 |

 $[\]mbox{\ensuremath{^{\bullet}}}$ Please identify Special Revenue Non-Grant and statutory code section (if applicable):

^{**} Please identify Special Revenue Grant:



Discussion Item 1 – List F – Funded Facility Modifications on Hold

Summary:

Standard list of previously funded facility modification projects on hold.

Supporting Documentation:

• List F – Funded Facility Modifications on Hold



| FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | TCFMAC FUNDED COST | FACILITY | MODIFICATION PROGRAM SHARE OF COST | FACILITY MODIFICATION PROGRAM BUDGET % | TCFMAC APPROVAL DATE | DAYS PENDING* | ON HOLD FOR SHARED COST? | PROJECT MANAGER ASSIGNED? | COMMENTS |
|------------|----------------|--------------------------------|-------------|----------|---|----|--------------------|----------|--|--|-------------------------|---------------|--------------------------|------------------------------|----------|
| FM-0143274 | Riverside | Southwest Justice Center | 33-M1 | | Fire Protection - DMF 3 - GCI - Survey, Design and Installation of Fire Alarm Control Panel and necessary devices in order to bring the building to code for the time of original construction. | \$ | 252,764 | \$ | 193,112 | 76.40 | 7/1/2019 | 308 | YES | Joy Sissom | |
| FM-2003539 | Los Angeles | Bellflower Courthouse | 19-AL1 | 2 | HVAC - GCI - Replace heating and cooling coils on Air Handling Units 1 through 8 which are beyond their useful life. The existing air handlers are failing and not providing adequate heating and cooling. | \$ | 581,430 | \$ | 453,167 | 77.94 | 3/10/2023 | 18 | YES | Amit Jogade | |
| FM-2004086 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | Exterior Shell - GCI - Replace plaza stairwell roofs and planter waterproofing including any abatement, install interior walls and finishes within stairwell towers and adjacent storage rooms. Water is coming into the building and damaging interior finishes. Existing exterior stairwell roof has failed due to age. | \$ | 660,635 | \$ | 436,878 | 66.13 | 3/10/2023 | 18 | YES | Kenneth Street | |
| | | | | | | \$ | 1,494,829 | \$ | 1,083,156 | | | | | | |

*Days Pending, as of 3/28/2023 1 of 1



Discussion Item 2 – Sustainability Update

Summary:

Update on sustainability initiatives.

Supporting Documentation:

• See presentation

Discussion Item 2 Sustainability Update

2020 Sustainability Plan for Trial Court Facilities

Existing Buildings

Reduce greenhouse gas (GHG) emissions, energy usage, utility costs, and conserve natural resources

New Construction

Ensure compliance with state sustainability initiatives in all new construction and major renovation projects

Discussion Item 2 Sustainability Update

Sustainability Practices in Existing Buildings



Energy Efficiency



Water Conservation



Minimize Waste & Increase Recycling



Renewable Energy Systems



EV Charging Infrastructure





Education and Communication

Discussion Item 2 Sustainability Update

Sustainability Education and Communication

- Energy and water usage reports
 - · Monthly distribution
 - JCC regional staff and O&M service providers






| Judicial Counc | il-Managed | Utility Usag | je Breakdov | vn FY20 to FY22 |
|-------------------------------|------------|---------------------|----------------------|--|
| Energy Usage (million Btu) | FY20-21 | FY21-22 | FY22-23 Projected | FY22-23 Projected Change vs FY21-22 |
| Electricity | 659,881 | 654,322 | 651,071 | -0.50% |
| Natural Gas | 334,522 | 355,607 | 344,394 | -3.20% |
| District Energy | 30,200 | 38,196 | 37,611 | -1.50% |
| Propane 3, | 3,000 | 6,320 | 5,292 | -16.30% |
| Total | 1,027,603 | 1,054,445 | 1,038,368 | -1.50% |
| Water Usage (MGal) | FY20-21 | FY21-22 | FY22-23 Projected | FY22-23 Projected Change vs FY21-22 |
| Water | 450 | 329 | 342 | 3.90% |

Discussion Item 2 – Sustainability Update

Judicial Council-Managed Utility Cost Breakdown FY20 to FY22



Discussion Item 2 Sustainability Update

Energy Efficiency

- Deep Energy Retrofit Study
 - Twenty long-term facilities were evaluated for the most effective approaches
- FY24-25 Deep Energy Retrofit DM Budget Change Proposal request
 - \$75M over three fiscal for five facilities with critical needs:
 - Compton Courthouse (Los Angeles)
 - Bellflower Courthouse (Los Angeles)
 - Torrance Courthouse (Los Angeles)
 - Betty Lou Lamoreaux Justice Center (Orange)
 - Barstow Courthouse (San Bernardino)

Discussion Item 2 Sustainability Update

Renewable Energy

 Statewide Solar RFP Update - RFP is being optimized for reposting in August 2023

Discussion Item 2 Sustainability Update

Electric Vehicle Infrastructure

| Location | Court | # Ports | Status | Estimated Date of Activation | Note |
|--|-------------|---------|---------------------------------|------------------------------|---|
| 19-AG1 Compton | Los Angeles | 24 | Engineering Design | LICTOPER 71173 | Approved by TCFMAC, January 31, 2022 |
| 19-O1 El Monte | Los Angeles | 38 | Engineering Design | | Approved by TCFMAC, January 31, 2022 |
| 19-W3 Pomona | Los Angeles | 40 | Engineering Design | LICTODAY JULYS | Approved by TCFMAC, January 31, 2022 |
| 19-Y5 Governor George Deukmejian Courthouse | Los Angeles | 150 | Conceptual Redesign underway | TBD | Project managed by Long Beach Judicial Partners |

Discussion Item 2 Sustainability Update

Water Conservation

- FY24-25 Budget Change Concept for \$47M over 3 years:
 - Building level leak detection at 160 buildings
 - Audit & replace water fixtures at 136 buildings
 - Implement landscape conversions at nine buildings
- Department of Water Resources Urban Drought Grant
 - \$4.7M Grant application submitted on 01/31/2023
 - Pursuing funding for building-level leak detection at 160 buildings
 - Non-DWR Cost-share of \$405K

Discussion Item 2 – Sustainability Update

Education and Communication: Sustainability Partnership

- Launched in July 2022
- 19 Trial Courts currently represented
- Hour-long Monthly Virtual Meeting
 - Educational Components
 - Court Guest Speakers





Discussion Item 3 – Facilities Maintenance Performance Report

Summary:


Facilities Maintenance Performance Report.


Supporting Documentation:


• See presentation


Discussion Item 3 Facilities Maintenance Performance Report Two "Models" for Maintenance and Operations Service Providers NCRO - Pride **BANCRO** - Enovity **BANCRO** - Enovity SRO - Pride NCRO - Pride Imperial • SRO - Pride Orange **Delegation Program** Imperial San Luis Obiso Orange Riverside San Luis Obispo






















Delegated Court Performance Report























Discussion Item 4 – Stanley Mosk Courthouse Power Washing and Replacement Project

Summary:

Update on the sewer power washing and replacement project at the Stanley Mosk Courthouse.

Supporting Documentation:

• See presentation



PROJECT INFORMATION

FM-2002640 Plumbing - GCI - perform a power washing (i.e. hydro jetting) and then video taping of existing sewer lines in an effort to determine where pipe is corroding and susceptible to leaking. Applying spray coating to repair any existing corrosion in the sewer system to approximately 18% of the existing piping.

| Description | Original Cost | Final Cost | Delta |
|--------------------|---------------|------------|-----------|
| Total Project Cost | \$1,823,500 | \$987,780 | \$835,720 |
| Judicial Cost | \$1,773,536 | \$960,715 | \$812,821 |
| County Cost | \$49,964 | \$27,065 | \$22,899 |

KEY MILESTONES

| Milestone Descriptions | Milestone Dates |
|------------------------------|-------------------|
| Project Approval | July 18, 2022 |
| NTP | October 5, 2022 |
| Power washing of sewer lines | December 7, 2022 |
| Videotaping of sewer lines | December 20, 2022 |
| Replacement of sewer lines | April 9, 2023 |
| Project Completion | Est. May 16, 2023 |

Discussion Item 4 Stanley Mosk Courthouse Sewer Power Washing & Replacement

KEY FINDINGS

- 6,100 LF of sewer line power washed & videotaped
- 700 LF of sewer line replacement
- 180 LF of sewer line epoxy coated

PHOTOS







Discussion Item 4 Stanley Mosk Courthouse Sewer Power Washing & Replacement

PHOTOS







PHOTOS







Discussion Item 4 Stanley Mosk Courthouse Sewer Power Washing & Replacement PHOTOS







SEWER LEAKS

| Fiscal Year | Number of FMs | Project Costs | Judicial Council Costs |
|----------------|---------------|------------------|---------------------------|
| FY 18-19 | 2 | \$37,584 | \$36,554 |
| FY 20-21 | 9 | \$226,631 | \$220,422 |
| FY 21-22 | 3 | \$88,455 | \$86,031 |
| FY 22-23 | 2 | \$89,765 | \$87,306 |
| | 16 | \$442,435 | \$430,313 |



Information Item 1 – Deferred Maintenance Funding – DMF-2 Projects Update

Summary:

Update on the status of DMF-2 projects. DMF-2 projects are funded by a one-time general fund budget allocation in July 2018 of \$50 million. \$5 million was earmarked specifically for facility assessments and \$45 million for roof, BAS, elevator, and HVAC projects.

Supporting Documentation:

• Progress report for DMF-2 projects.



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF II Monthly Report No. 27 April 10, 2023

| Project Management | Judicial Council of California - Facilities Services - Administrative Division | | |
|-------------------------|--|--|--|
| Construction Management | Kitchell CEM, Cumming Corporation | | |
| Architect | Development One, Inc. | | |
| Contractors | MTM Construction, Mark Scott Construction, Mackone Development, Enovity, Vincor. | | |


Deferred Maintenance Fund Projects Status: For all work associated with roofs, elevators, wheelchair lifts, and Building Automation Systems repairs, refurbishment, or replacement.

| Project Status | Number | Original Estimate | | | Encumbered | | |
|----------------------|-------------|-------------------|------------|----|------------|--|--|
| | of Projects | | | | Amount | | |
| Roof Projects | | | | | | | |
| Completed | 6 | \$ | 7,242,114 | \$ | 4,587,588 | | |
| Deferred to next DMF | 4 | \$ | 5,857,919 | \$ | 143,326 | | |
| Subtotal | 10 | \$ | 13,100,033 | \$ | 4,730,914 | | |
| Elevator Projects | | | | | | | |
| Construction | 3 | \$ | 3,966,517 | \$ | 10,751,081 | | |
| Completed | 14 | \$ | 15,928,507 | \$ | 18,767,369 | | |
| Deferred to next DMF | 2 | \$ | 720,203 | \$ | 356,024 | | |
| Subtotal | 19 | | 20,615,227 | | 29,874,474 | | |
| | | | | | | | |
| BAS Projects | | | | | | | |
| Construction | 2 | \$ | 3,569,000 | \$ | 3,286,528 | | |
| Cancelled | 1 | \$ | 124,000 | \$ | - | | |
| Completed | 2 | \$ | 3,492,000 | \$ | 5,174,588 | | |
| Deferred to next DMF | 22 | \$ | 18,528,000 | \$ | 1,933,497 | | |
| Subtotal | 27 | | 25,713,000 | | 10,394,612 | | |
| HVAC Cooling System | | | | | | | |
| Deferred to next DMF | 1 | \$ | 537,636 | \$ | - | | |
| Subtotal | 1 | \$ | 537,636 | \$ | - | | |
| Building Assessment | | | | | | | |
| Completed | 1 | \$ | 5,000,000 | \$ | 5,000,000 | | |
| Subtotal | 1 | \$ | 5,000,000 | \$ | 5,000,000 | | |
| Grand Total | 58 | \$ | 64,965,896 | \$ | 50,000,000 | | |



Trial Court Facility Modification Advisory Committee


Judicial Council Deferred Maintenance Projects – DMF II Monthly Report No. 27 April 10, 2023





Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF II Monthly Report No. 27 April 10, 2023



Cancelled

| # | County | Facility Location | Project Title | Original Estimate | Encumbered Amount |
|----|---------|------------------------------------|---------------|-------------------|----------------------|
| 41 | Alameda | George E. McDonald Hall of Justice | BAS Upgrades | \$ 124,000 | \$ - |
| | | | Total | \$ 124,000 | \$ - |



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF II Monthly Report No. 27 April 10, 2023

Completed

| # | County | Facility Location | Project Title | Original | Estimate | En | cumbered Amount |
|----|----------------|--------------------------------------|-----------------------------|------------|-----------|----|--------------------|
| 2 | San Diego | East County Regional Center | Roof Replacement | \$ 3 | 3,855,749 | \$ | 1,577,245 |
| 7 | Contra Costa | Wakefield Taylor Courthouse | Elevator Replacement | \$ 1 | L,118,468 | \$ | 2,413,056 |
| 8 | Contra Costa | Walnut Creek Courthouse | Elevator Replacement | \$ | 524,983 | \$ | 717,418 |
| 9 | Contra Costa | George D. Carroll Courthouse | Elevator Replacement | \$ | 338,998 | \$ | 776,998 |
| 10 | San Bernardino | Barstow Courthouse | Elevator Replacement | \$ | 181,343 | \$ | 360,521 |
| 11 | Los Angeles | Bellflower Courthouse | Wheelchair Lift Replacement | \$ | 50,000 | \$ | 521,598 |
| 12 | Los Angeles | Downey Courthouse | Wheelchair Lift Replacement | \$ | 140,000 | \$ | 742,558 |
| 13 | Los Angeles | Beverly Hills Courthouse | Elevator Replacement | \$ 2 | 2,688,288 | \$ | 2,557,283 |
| 15 | Los Angeles | Torrance Courthouse | Elevator Replacement | \$ 2 | 2,953,248 | \$ | 2,721,622 |
| 16 | Los Angeles | Burbank Courthouse | Elevator Replacement | \$ | 679,558 | \$ | 831,885 |
| 17 | Los Angeles | El Monte Courthouse | Elevator Replacement | \$ 2 | 2,060,363 | \$ | 1,513,410 |
| 18 | Los Angeles | Edmund D. Edelman Children's Court | Elevator Replacement | \$ 3 | 3,368,223 | \$ | 3,141,467 |
| 19 | Orange | North Justice Center | Elevator Replacement | \$ 1 | L,278,203 | \$ | 648,203 |
| 21 | San Diego | North County Regional Center - North | Elevator Replacement | \$ 254,838 | | \$ | 766,647 |
| 22 | San Mateo | Northern Branch Courthouse | Elevator Replacement | \$ 291,998 | | \$ | 1,054,703 |
| 23 | Santa Clara | Santa Clara Courthouse | Roof Replacement | \$ 196,000 | | \$ | 116,694 |
| 24 | Los Angeles | Santa Clarita Courthouse | Roof Replacement | \$ | 556,857 | \$ | 596,633 |
| 25 | San Diego | Kearny Mesa Court | Roof Replacement | \$ | 442,000 | \$ | 936,954 |
| 33 | Los Angeles | Van Nuys Courthouse East | BAS Upgrades | \$ 1 | L,432,000 | \$ | 2,272,699 |
| 34 | Los Angeles | Van Nuys Courthouse West | BAS Upgrades | \$ 2 | 2,060,000 | \$ | 2,901,889 |
| 55 | Los Angeles | Torrance Annex | Roof Replacement | \$ | 515,478 | \$ | 535,224 |
| 57 | Los Angeles | Inglewood Courthouse | Roof Replacement | \$ 1 | L,676,030 | \$ | 824,839 |
| 58 | Statewide | Statewide | Assessment | \$ 5 | 5,000,000 | \$ | 5,000,000 |
| | | | Total | \$ 31 | 1,662,621 | \$ | 33,529,545 |



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF II Monthly Report No. 27 April 10, 2023

Construction

| # | County | Facility Location | Project Title | Origi | inal Estimate | E | Encumbered Amount |
|----|-------------|--------------------------|----------------------|-------|---------------|----|----------------------|
| 5 | Alameda | Hayward Hall of Justice | Elevator Replacement | \$ | 2,814,355 | \$ | 4,239,359 |
| 6 | Alameda | Fremont Hall of Justice | Elevator Replacement | \$ | 947,163 | \$ | 1,803,142 |
| 14 | Los Angeles | Van Nuys Courthouse West | Elevator Replacement | \$ | 205,000 | \$ | 4,708,580 |
| 28 | Los Angeles | Compton Courthouse | BAS Upgrades | \$ | 1,945,000 | \$ | 1,635,624 |
| 38 | Los Angeles | Metropolitan Courthouse | BAS Upgrades | \$ | 1,624,000 | \$ | 1,650,904 |
| | | | Total | \$ | 7,535,517 | \$ | 14,037,609 |



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF II Monthly Report No. 27 April 10, 2023



Judicial Council Deferred Maintenance (DMF II) Project Schedule April 2023

| County | Facility Location | Project Title | Project Approv | val Project | Initiation | Design | Procurei | ment/Bid | I/Award | Agency | Review | Constructio | on Close | -Out | On Hold | | | | | | | | | | | | | | |
|-------------------|-------------------------------------|----------------------------|----------------|-------------|------------|-----------|----------|----------|---------|--------|---------|-------------|-----------|---------|-----------|---------|---------|---------|---------|--------|-----------|------------|------------|--------|-----------|-----------|--------------|-----------|--------|
| | | | | | 020 | | | | | 20 | | | | | | 2022 | | | | | | 2023 | | | | | 2024 | | |
| | | | Jan Feb Mar A | pr May Jun | Jul Aug | Sep Oct 1 | Nov Dec | Jan Feb | Mar Apr | MayJun | Jul Aug | Sep Oct N | ov Dec Ja | n Feb M | ar Apr Ma | Jun Jul | Aug Sep | Oct Nov | Dec Jan | eb Mar | Apr May J | lun Jul Au | ıg Sep Oct | Nov De | Jan Feb I | Mar Apr M | ay Jun Jul A | ug Sep Oc | t Nov |
| 8 Contra Costa | Walnut Creek Courthouse | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10 San Bernardino | Barstow Courthouse | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 2 San Diego | East County Regional Center | Roof Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 7 Contra Costa | Wakefield Taylor Courthouse | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 9 Contra Costa | George D. Carroll Courthouse | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 11 Los Angeles | Bellflower Courthouse | Wheelchair Lift Replacemen | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 12 Los Angeles | Downey Courthouse | Wheelchair Lift Replacemen | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 13 Los Angeles | Beverly Hills Courthouse | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | \Box |
| 15 Los Angeles | Torrance Courthouse | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 16 Los Angeles | Burbank Courthouse | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 17 Los Angeles | El Monte Courthouse | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 18 Los Angeles | Edmund D. Edelman Children's Cour | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 19 Orange | North Justice Center | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 21 San Diego | North County Regional Center - Nort | h Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 22 San Mateo | Northern Branch Courthouse | Elevator Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 23 Santa Clara | Santa Clara Courthouse | Roof Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 24 Los Angeles | Santa Clarita Courthouse | Roof Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 25 San Diego | Kearny Mesa Court | Roof Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 33 Los Angeles | Van Nuys Courthouse East | BAS Upgrades | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 34 Los Angeles | Van Nuys Courthouse West | BAS Upgrades | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 55 Los Angeles | Torrance Annex | Roof Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 57 Los Angeles | Inglewood Courthouse | Roof Replacement | Completed | | | | | | | | | | | | | | | | | | | | | | | | | | \Box |
| 5 Alameda | Hayward Hall of Justice | Elevator Replacement | | | | | | | | | | | | | | | | | | | | | | | | | | | \Box |
| 6 Alameda | Fremont Hall of Justice | Elevator Replacement | | | | | | | | | | | | | | | | | | | | | | | | | | | \Box |
| 14 Los Angeles | Van Nuys Courthouse West | Elevator Replacement | | | | | | | | | | | | | | | | | | | | | | | | | | | \Box |
| 28 Los Angeles | Compton Courthouse | BAS Upgrades | | | | | | | | | | | | | | | | | | | | | | | | | | | \Box |
| 38 Los Angeles | Metropolitan Courthouse | BAS Upgrades | | | | | | | | | | | | | | | | | | | | | | | | | | | \Box |



Meeting Date: 4/10/2023

Information Item 2 – Deferred Maintenance Funding – DMF-3 Projects Update

Summary:

Update on the status of DMF-3 projects. DMF-3 projects are funded by a one-time general fund budget allocation in July 2019 of \$15 million which is earmarked for fire alarm system projects.

Supporting Documentation:

• Progress report for DMF-3 projects



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF III Monthly Report No. 20 April 10, 2023

| Project Management | Judicial Council of California - Facilities Services - Administrative Division |
|--------------------|--|
| Contractors | MTM Construction, Pride, MS Construction |

Deferred Maintenance Fund Projects Status: For all work associated with roofs, elevators, wheel-chair lifts, and Building Automation Systems repairs, refurbishment, or replacement.

| Project Status | Number of Projects | Oı | riginal Estimate | Cu | rrent Amount |
|----------------------------|--------------------|----|------------------|----|--------------|
| Fire Alarm System Projects | | | | | |
| In Construction | 5 | \$ | 10,115,687 | \$ | 12,775,172 |
| Design | 1 | \$ | 192,236 | \$ | 192,236 |
| Agency Review | 1 | \$ | 1,065,606 | \$ | 377,611 |
| Cancelled | 1 | \$ | 1,620,180 | \$ | - |
| Completed | 3 | \$ | 2,824,599 | \$ | 1,654,982 |
| Subtotal | 11 | \$ | 15,818,308 | \$ | 15,000,000 |
| | | | | | |
| Grand Total | 11 | \$ | 15,818,308 | \$ | 15,000,000 |






Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF III Monthly Report No. 20 April 10, 2023







Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF III Monthly Report No. 20 April 10, 2023

Agency Review

| # | County | Facility Name | Project Title | Original Estimate | Current Amount |
|---|-----------|--------------------------|-------------------|-------------------|----------------|
| 1 | Riverside | Southwest Justice Center | Fire Alarm System | \$ 1,065,606 | \$ 377,611 |
| | | | Total | \$ 1,065,606 | \$ 377,611 |

Cancelled

| # | County | Facility Name | Project Title | Original Estimate | Current Amount |
|---|-------------|-------------------------|-------------------|-------------------|----------------|
| 7 | Los Angeles | Stanley Mosk Courthouse | Fire Alarm System | \$ 1,620,180 | \$ - |
| | | | Total | \$ 1,620,180 | \$ - |

Completed

| # | County | Facility Name | Project Title | Original Estimate | Current Amount |
|----|-------------|---|-------------------|-------------------|-----------------|
| 2 | Los Angeles | Pomona Courthouse South | Fire Alarm System | \$ 1,065,281 | \$ 555,566 |
| 3 | Fresno | Fresno County Courthouse | Fire Alarm System | \$ 1,133,246 | \$ 412,758 |
| 11 | Sacramento | Carol Miller Justice Center Court Facility | Fire Protection | \$ 626,072 | \$ 686,658 |
| | | | Total | \$ 2,824,599 | \$ 1,654,982 |

Design

| # | County | Facility Name | Project Title | Original Estimate | Current Amount |
|----|----------------|------------------------|-----------------|-------------------|----------------|
| 10 | San Bernardino | Victorville Courthouse | Fire Protection | \$ 192,236 | \$ 192,236 |
| | | | Total | \$ 192,236 | \$ 192,236 |



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF III Monthly Report No. 20 April 10, 2023

In Construction

| # | County | Facility Name | Project Title | Original Estimate | Current Amount |
|---|-------------|---|-------------------|-------------------|------------------|
| 4 | Alameda | Hayward Hall of Justice | Fire Alarm System | \$ 1,000,000 | \$ 398,628 |
| 5 | Orange | Betty Lou Lamoreaux Justice Center | Fire Alarm System | \$ 1,250,000 | \$ 829,550 |
| 6 | Alameda | Wiley W. Manuel Courthouse | Fire Alarm System | \$ 1,300,000 | \$ 386,634 |
| 8 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | Fire Alarm System | \$ 1,947,450 | \$ 443,242 |
| 9 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | Fire Alarm System | \$ 4,618,237 | \$ 10,717,118 |
| | | | Total | \$ 10,115,687 | \$ 12,775,172 |



JUDICIAL COUNCIL OF CALIFORNIA Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF III Monthly Report No. 20 April 10, 2023

| # | County | Facility Location | Project Title | Project App | roval Pro | ject Initiat | ion Desigr | n Procurei | ment/Bio | d/Award / | Agency Re | view Const | ruction C | ose-Out | On Hold | | | | | | | | | | | | | |
|----|----------------|--|-------------------|-------------|-----------|-------------------|------------|------------|----------|-----------|------------|------------|------------|-------------|-----------|-------------|-----------|------------|------------|-------------|-----------|------------|---------|--------|-----------|------------|-------------|-------------|
| | | | | | | 2020 | | | | | 2021 | | | | | 2022 | | | | | 2023 | | | | | 2024 | | |
| | | | | Jan Feb Ma | ar Apr Ma | yJun Jul <i>A</i> | Aug Sep Oc | ct Nov Dec | Jan Feb | Mar Apr N | lay Jun Ju | Aug Sep (| Oct Nov De | c Jan Feb I | Mar Apr N | lay Jun Jul | Aug Sep C | ct Nov Dec | Jan Feb Ma | r Apr May J | un Jul Au | ıg Sep Oct | Nov Dec | Jan Fe | b Mar Apı | May Jun Ju | I Aug Sep C | Oct Nov Dec |
| 1 | Riverside | Southwest Justice Center | Fire Alarm System | | | | | | | | | | | | | | | | | | | | | | | | | |
| 4 | Alameda | Hayward Hall of Justice | Fire Alarm System | | | | | | | | | | | | | | | | | | | | | | | | | |
| 5 | Orange | Betty Lou Lamoreaux Justice Center | Fire Alarm System | | | | | | | | | | | | | | | | | | | | | | | | | |
| 6 | Alameda | Wiley W. Manuel Courthouse | Fire Alarm System | | | | | | | | | | | | | | | | | | | | | | | | | |
| 8 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | Fire Alarm System | | | | | | | | | | | | | | | | | | | | | | | | | |
| 9 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | Fire Alarm System | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10 | San Bernardino | Victorville Courthouse | Fire Protection | | | | | | | | | | | | | | | | | | | | | | | | | |
| 2 | Los Angeles | Pomona Courthouse South | Fire Alarm System | Completed | | | | | | | | | | | | | | | | | | | | | | | | |
| 3 | Fresno | Fresno County Courthouse | Fire Alarm System | Completed | | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | Los Angeles | Stanley Mosk Courthouse | Fire Alarm System | Cancelled | | | | | | | | | | | | | | | | | | | | | | | | |
| 11 | Sacramento | Carol Miller Justice Center Court Facility | Fire Protection | Completed | | | | | | | | | | | | | | | | | | | | | | | | |



Meeting Date: 4/10/2023

Information Item 3 – Deferred Maintenance Funding – DMF-4 Projects Update

Summary:

Update on the status of DMF-4 projects. DMF-4 projects are funded by a one-time general fund budget allocation in July 2021 of \$180 million (reduced to \$132.6) for trial court facilities. Funding is earmarked primarily for HVAC, roof, elevator, electrical, and fire protection projects.

Supporting Documentation:

• Progress report for DMF-4 projects



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10 April 10, 2023

| Project Management | Judicial Council of California - Facilities Services - Administrative Division |
|--------------------------------|--|
| Construction Management | Kitchell CEM |


Deferred Maintenance Fund Projects Status: For all work associated with roofs, elevators, BMS systems, HVAC, electrical and Fire protection systems.


| Project Status | Number | Ori | ginal Estimate | Cu | rrent Amount |
|---|-------------|-----|----------------|----------|--------------|
| Roof Projects | of Projects | | | | |
| Agency Review | 7 | \$ | 4,651,665 | \$ | 11,120,281 |
| Construction | 2 | \$ | 972,297 | \$ | 1,441,845 |
| Close-Out | 1 | \$ | 54,544 | \$ | 325,587 |
| Completed | 1 | \$ | 1,096,944 | \$ | 2,455,362 |
| Cancelled | 2 | \$ | 2,175,371 | \$ | 124,028 |
| Deferred for the next DMF due to funding restraints | 16 | \$ | 10,750,512 | \$ | 1,733,250 |
| Subtotal | 29 | Ą | 19,701,333 | ۶ | 17,200,353 |
| Subtotal | 23 | | 19,701,333 | | 17,200,333 |
| Elevator Projects | | | | | |
| Agency Review | 4 | \$ | 17,913,485 | \$ | 19,997,372 |
| Construction | 6 | \$ | 32,648,439 | \$ | 15,606,805 |
| Deferred for the next DMF due to funding restraints | 7 | \$ | 20,204,515 | \$ | 2,085,274 |
| Subtotal | 17 | Τ | 70,766,439 | <u> </u> | 37,689,450 |
| | | | 10,100,100 | | 51,000,100 |
| Fire Protection Projects | | | | | |
| Agency Review | 2 | \$ | 346,304 | \$ | 1,950,412 |
| Cancelled | 1 | \$ | 12,712 | \$ | - |
| Deferred for the next DMF due to funding restraints | 1 | \$ | 12,740 | \$ | 14,331 |
| Subtotal | 4 | • | 371,757 | | 1,964,743 |
| | | | | | 2,00 ,,1 10 |
| Electrical Projects | | | | | |
| Cancelled | 2 | \$ | 267,711 | \$ | 12,131 |
| Deferred for the next DMF due to funding restraints | 19 | \$ | 5,109,039 | \$ | 1,864,812 |
| Subtotal | 21 | | 5,376,750 | | 1,876,943 |
| | | | | | |
| BMS Projects | | | | | |
| Construction Design | 1 | \$ | 110,459 | \$ | 745,851 |
| Agency Review | 12 | \$ | 17,199,165 | \$ | 30,779,739 |
| Construction | 11 | \$ | 15,858,865 | \$ | 35,741,211 |
| Completed | 2 | \$ | 585,385 | \$ | 715,554 |
| Cancelled | 2 | \$ | 9,491,112 | \$ | 238,455 |
| Deferred for the next DMF due to funding restraints | 10 | \$ | 22,245,764 | \$ | 1,152,776 |
| Subtotal | 38 | | 65,490,749 | | 69,373,586 |
| | | | | | |
| HVAC Projects | | | | | |
| Agency Review | 3 | \$ | 1,500,195 | \$ | 2,438,145 |
| Cancelled | 1 | \$ | 2,765,405 | \$ | 50,631 |
| Deferred for the next DMF due to funding restraints | 14 | \$ | 14,027,373 | \$ | 1,973,114 |
| Subtotal | 18 | | 18,292,973 | | 4,461,890 |
| | | | | | |
| Grand Total | 127 | \$ | 180,000,000 | \$ | 132,566,965 |



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10 April 10, 2023








Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10 April 10, 2023





Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10 April 10, 2023

Agency Review

| 0 , | keview | | | | | | |
|-------|----------------|--|-----------------|-------|---------------|-----|-------------|
| Item# | County | Facility Name | Project Title | Origi | inal Estimate | Cur | rent Amount |
| 1 | Los Angeles | Compton Courthouse | HVAC (BMS) | \$ | 4,531,642 | \$ | 4,945,757 |
| 10 | Los Angeles | Pomona Courthouse South | HVAC (BMS) | \$ | 1,325,467 | \$ | 2,770,929 |
| 11 | Orange | Civil Complex Center ("CXC") | HVAC (BMS) | \$ | 81,620 | \$ | 813,648 |
| 15 | San Bernardino | Barstow Courthouse | HVAC (BMS) | \$ | 127,200 | \$ | 845,090 |
| 18 | Riverside | Larson Justice Center | HVAC (BMS) | \$ | 1,778,409 | \$ | 3,231,327 |
| 20 | Los Angeles | East Los Angeles Courthouse | HVAC (BMS) | \$ | 1,904,093 | \$ | 2,074,229 |
| 50 | Orange | Betty Lou Lamoreaux Justice Center | HVAC (BMS) | \$ | 2,619,101 | \$ | 4,977,725 |
| 51 | Orange | Central Justice Center | Elevators | \$ | 7,257,755 | \$ | 9,043,906 |
| 52 | San Francisco | Civic Center Courthouse | Elevators | \$ | 6,521,289 | \$ | 5,737,830 |
| 60 | Riverside | Larson Justice Center | Elevators | \$ | 4,073,424 | \$ | 2,888,550 |
| 63 | San Mateo | Central Branch | Fire Protection | \$ | 84,384 | \$ | 907,056 |
| 64 | San Mateo | Northern Branch Courthouse | Fire Protection | \$ | 261,920 | \$ | 1,043,356 |
| 66 | San Bernardino | Barstow Courthouse | HVAC | \$ | 220,226 | \$ | 632,233 |
| 69 | San Bernardino | Barstow Courthouse | HVAC | \$ | 83,799 | \$ | 189,128 |
| 71 | Sacramento | Carol Miller Justice Center Court Facility | HVAC (BMS) | \$ | 1,066,169 | \$ | 1,114,707 |
| 74 | Monterey | Salinas Courthouse- North Wing | HVAC (BMS) | \$ | 1,052,462 | \$ | 3,294,083 |
| 75 | Santa Barbara | Figueroa Division | HVAC (BMS) | \$ | 81,950 | \$ | 1,989,519 |
| 90 | Orange | Harbor Justice Center-Newport Beach | HVAC (BMS) | \$ | 1,118,140 | \$ | 1,916,698 |
| 92 | Contra Costa | Wakefield Taylor Courthouse | HVAC (BMS) | \$ | 1,512,911 | \$ | 2,806,028 |
| 95 | Los Angeles | El Monte Courthouse | HVAC | \$ | 1,196,170 | \$ | 1,616,784 |
| 102 | Alameda | Wiley W. Manuel Courthouse | Roof | \$ | 241,897 | \$ | 1,165,017 |
| 104 | Contra Costa | Wakefield Taylor Courthouse | Roof | \$ | 570,810 | \$ | 4,181,866 |
| 110 | Orange | Harbor Justice Center-Newport Beach | Roof | \$ | 1,295,858 | \$ | 1,404,117 |
| 113 | Riverside | Southwest Justice Center | Roof | \$ | 655,279 | \$ | 1,701,868 |
| 115 | San Diego | Juvenile Court | Roof | \$ | 807,138 | \$ | 1,080,526 |
| 120 | Fresno | B.F. Sisk Courthouse | Roof | \$ | 775,572 | \$ | 844,201 |
| 122 | San Joaquin | Manteca Branch Court | Roof | \$ | 305,110 | \$ | 742,685 |
| 127 | Los Angeles | Whittier Courthouse | Elevators | \$ | 61,016 | \$ | 2,327,085 |
| Total | | | | \$ | 41,610,813 | \$ | 66,285,949 |

Cancelled

| Item# | County | Facility Name | Project Title | Ori | ginal Estimate | Curr | ent Amount |
|-------|--------------|------------------------------------|-----------------|-----|----------------|------|------------|
| 42 | Alameda | Wiley W. Manuel Courthouse | Electrical | \$ | 227,400 | \$ | 3,816 |
| 65 | Contra Costa | Jail Annex | Fire Protection | \$ | 12,712 | \$ | - |
| 83 | Los Angeles | Edmund D. Edelman Children's Court | HVAC | \$ | 2,765,405 | \$ | 50,631 |
| 88 | Ventura | Ventura Hall of Justice | HVAC (BMS) | \$ | 3,637,692 | \$ | - |
| 89 | Orange | Central Justice Center | HVAC (BMS) | \$ | 5,853,420 | \$ | 238,455 |
| 94 | Kern | Bakersfield Superior Court | Roof | \$ | 1,503,042 | \$ | - |
| 99 | Los Angeles | Whittier Courthouse | Electrical | \$ | 40,311 | \$ | 8,315 |
| 106 | Santa Clara | Santa Clara Courthouse | Roof | \$ | 672,329 | \$ | 124,028 |
| Total | | | | \$ | 14,712,311 | \$ | 425,245 |



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10 April 10, 2023

Close-Out

| Item# | County | Facility Name | Project Title | Origi | nal Estimate | Cur | rent Amount |
|-------|----------|-------------------|---------------|-------|--------------|-----|-------------|
| 103 | Imperial | Winterhaven Court | Roof | \$ | 54,544 | \$ | 325,587 |
| Total | | | | \$ | 54,544 | \$ | 325,587 |

Completed

| Item# | County | Facility Name | Project Title | Original Estimate | Current Amoun |
|-------|-------------|----------------------------|---------------|-------------------|----------------------|
| 12 | Napa | Criminal Court Building | HVAC (BMS) | \$ 191,860 | \$ 689,698 |
| 23 | Kern | Bakersfield Superior Court | HVAC (BMS) | \$ 393,525 | \$ 25,856 |
| 105 | Santa Clara | Morgan Hill Courthouse | Roof | \$ 1,096,944 | \$ 2,455,362 |
| Total | | | | \$ 1,682,329 | \$ 3,170,916 |

Construction

| Item# | County | Facility Name | Project Title | Orig | ginal Estimate | Cur | rent Amount |
|-------|-------------|-------------------------------------|---------------|------|----------------|-----|-------------|
| 2 | Los Angeles | San Fernando Courthouse | HVAC (BMS) | \$ | 986,707 | \$ | 5,975,709 |
| 3 | Los Angeles | Norwalk Courthouse | HVAC (BMS) | \$ | 2,031,571 | \$ | 5,124,563 |
| 4 | Los Angeles | Bellflower Courthouse | HVAC (BMS) | \$ | 1,080,039 | \$ | 3,169,796 |
| 6 | Los Angeles | Glendale Courthouse | HVAC (BMS) | \$ | 382,930 | \$ | 2,733,222 |
| 7 | Los Angeles | Alhambra Courthouse | HVAC (BMS) | \$ | 902,484 | \$ | 3,680,835 |
| 8 | Los Angeles | Pasadena Courthouse | HVAC (BMS) | \$ | 1,586,783 | \$ | 4,385,292 |
| 9 | Los Angeles | Metropolitan Courthouse | HVAC (BMS) | \$ | 1,627,449 | \$ | 530,645 |
| 16 | Orange | West Justice Center | HVAC (BMS) | \$ | 1,881,040 | \$ | 3,807,372 |
| 19 | Alameda | Hayward Hall of Justice | HVAC (BMS) | \$ | 1,505,056 | \$ | 2,295,962 |
| 21 | Alameda | Fremont Hall of Justice | HVAC (BMS) | \$ | 2,774,186 | \$ | 2,121,136 |
| 46 | Los Angeles | Airport Courthouse | Elevators | \$ | 5,431,206 | \$ | 5,756,042 |
| 53 | Los Angeles | East Los Angeles Courthouse | Elevators | \$ | 9,954,279 | \$ | 2,349,570 |
| 54 | Los Angeles | Glendale Courthouse | Elevators | \$ | 3,865,096 | \$ | 880,772 |
| 57 | Orange | Harbor Justice Center-Newport Beach | Elevators | \$ | 1,069,097 | \$ | 1,375,472 |
| 58 | Los Angeles | Hollywood Courthouse | Elevators | \$ | 5,202,013 | \$ | 1,401,814 |
| 61 | Los Angeles | San Fernando Courthouse | Elevators | \$ | 7,126,748 | \$ | 3,843,135 |
| 70 | Sacramento | Sacramento Juvenile Courthouse | HVAC (BMS) | \$ | 1,100,620 | \$ | 1,916,680 |
| 107 | Orange | Betty Lou Lamoreaux Justice Center | Roof | \$ | 797,706 | \$ | 949,844 |
| 109 | Humboldt | Humboldt County Courthouse (Eureka) | Roof | \$ | 174,591 | \$ | 492,001 |
| Total | | | | \$ | 49,479,601 | \$ | 52,789,861 |



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10 April 10, 2023

Construction Design

| ltem# | County | Facility Name | Project Title | Origi | nal Estimate | Curi | rent Amount |
|-------|-------------|--------------------------|---------------|-------|--------------|------|-------------|
| 14 | Los Angeles | Inglewood Juvenile Court | HVAC (BMS) | \$ | 110,459 | \$ | 745,851 |
| Total | | | | \$ | 110,459 | \$ | 745,851 |

Deferred for the next DMF due to funding restraints

| Item# | County | Facility Name | Project Title | Origi | inal Estimate | Cu | rrent Amount |
|-------|----------------|--------------------------------------|-----------------|-------|---------------|----|--------------|
| 5 | Los Angeles | Airport Courthouse | HVAC (BMS) | \$ | 3,388,461 | \$ | 117,198 |
| 13 | San Diego | North County Regional Center - North | HVAC (BMS) | \$ | 795,000 | \$ | 76,947 |
| 17 | Riverside | Riverside Juvenile Court | HVAC (BMS) | \$ | 492,135 | \$ | 32,360 |
| 22 | San Diego | East County Regional Center | HVAC (BMS) | \$ | 1,072,283 | \$ | 80,603 |
| 24 | Orange | Central Justice Center | Roof | \$ | 2,000,467 | \$ | 203,873 |
| 25 | San Diego | North County Regional Center - South | Roof | \$ | 1,163,747 | \$ | - |
| 26 | Alameda | Wiley W. Manuel Courthouse | HVAC | \$ | 624,310 | \$ | 122,387 |
| 27 | Los Angeles | Airport Courthouse | Electrical | \$ | 472,396 | \$ | 124,163 |
| 28 | Los Angeles | Bellflower Courthouse | Electrical | \$ | 274,588 | \$ | 105,854 |
| 29 | Los Angeles | Whittier Courthouse | Electrical | \$ | 181,399 | \$ | 99,966 |
| 30 | Los Angeles | Beverly Hills Courthouse | Electrical | \$ | 187,759 | \$ | 4,825 |
| 31 | Los Angeles | Van Nuys Courthouse East | Electrical | \$ | 247,638 | \$ | 121,220 |
| 32 | Los Angeles | Van Nuys Courthouse West | Electrical | \$ | 413,662 | \$ | 121,050 |
| 33 | Los Angeles | Pasadena Courthouse | Electrical | \$ | 163,746 | \$ | 96,652 |
| 34 | Los Angeles | Pomona Courthouse South | Electrical | \$ | 239,106 | \$ | 93,050 |
| 35 | Santa Clara | Hall of Justice (East) | Electrical | \$ | 347,256 | \$ | 185,706 |
| 36 | Los Angeles | Norwalk Courthouse | Electrical | \$ | 223,076 | \$ | 90,650 |
| 37 | Alameda | Fremont Hall of Justice | Electrical | \$ | 235,050 | \$ | 120,949 |
| 38 | Los Angeles | East Los Angeles Courthouse | Electrical | \$ | 287,406 | \$ | 82,765 |
| 39 | Fresno | B.F. Sisk Courthouse | Electrical | \$ | 368,562 | \$ | 170,587 |
| 40 | Santa Clara | Morgan Hill Courthouse | Electrical | \$ | 366,548 | \$ | 63,835 |
| 41 | Santa Clara | San Jose Historic Courthouse | Electrical | \$ | 231,504 | \$ | 165,739 |
| 43 | Amador | Amador Superior Court | Electrical | \$ | 189,528 | \$ | 135,912 |
| 44 | Santa Clara | Palo Alto Courthouse | Electrical | \$ | 583,948 | \$ | 66,733 |
| 45 | San Bernardino | Rancho Cucamonga Courthouse | Electrical | \$ | 52,238 | \$ | - |
| 47 | Fresno | B.F. Sisk Courthouse | Elevators | \$ | 7,080,630 | \$ | 310,035 |
| 48 | Kern | Bakersfield Justice Bldg. | Elevators | \$ | 1,964,807 | \$ | - |
| 49 | Kern | Bakersfield Juvenile Center | Elevators | \$ | 2,044,843 | \$ | 114,937 |
| 55 | San Diego | San Diego Hall of Justice | Elevators | \$ | 1,040,085 | \$ | - |
| 56 | Riverside | Riverside Hall of Justice | Elevators | \$ | 6,306,540 | \$ | 267,305 |
| 59 | Los Angeles | Inglewood Courthouse | Elevators | \$ | 586,982 | \$ | 108,846 |
| 62 | Santa Clara | Palo Alto Courthouse | Fire Protection | \$ | 12,740 | \$ | 14,331 |
| 67 | Santa Cruz | Santa Cruz Main Courthouse | HVAC | \$ | 428,505 | \$ | 43,275 |
| 68 | San Diego | San Diego Hall of Justice | HVAC | \$ | 2,177,410 | \$ | - |



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10 April 10, 2023


| 72 | San Bernardino | Rancho Cucamonga Courthouse | HVAC (BMS) | \$ 2,689,897 | \$ - |
|-------|-----------------|---------------------------------------|------------|------------------|-----------------|
| 73 | Fresno | Fresno County Courthouse | HVAC (BMS) | \$ 6,770,730 | \$ 296,391 |
| 76 | Los Angeles | Santa Monica Courthouse | HVAC | \$ 1,962,889 | 103,418 |
| 77 | Riverside | Riverside Hall of Justice | HVAC | \$ 1,745,836 | \$ 134,395 |
| 78 | Contra Costa | George D. Carroll Courthouse | HVAC | \$ 582,640 | \$ 587,241 |
| 79 | Los Angeles | Chatsworth Courthouse | HVAC (BMS) | \$ 3,172,554 | \$ 284,167 |
| 80 | Los Angeles | Torrance Courthouse | HVAC (BMS) | \$ 2,491,364 | \$ 209,913 |
| 81 | San Bernardino | Fontana Jury Assembly Building | Roof | \$ 350,000 | \$ - |
| 82 | Los Angeles | Downey Courthouse | HVAC | \$ 2,275,201 | \$ 272,386 |
| 84 | Los Angeles | Eastlake Juvenile Court | HVAC | \$ 483,211 | \$ - |
| 85 | Santa Barbara | Santa Maria Courts Bldgs C + D | HVAC (BMS) | \$ 77,775 | \$ 55,197 |
| 86 | Kern | Bakersfield Justice Bldg. | HVAC (BMS) | \$ 1,295,565 | \$ - |
| 87 | San Joaquin | Manteca Branch Court | HVAC | \$ 72,326 | \$ 44,703 |
| 91 | Kern | Bakersfield Superior Court | HVAC | \$ 2,303,595 | \$ 71,700 |
| 93 | Contra Costa | Walnut Creek Courthouse | HVAC | \$ 92,738 | \$ 29,183 |
| 96 | Los Angeles | West Covina Courthouse | HVAC | \$ 1,000,061 | \$ - |
| 97 | Humboldt | Humboldt County Courthouse (Eureka) | HVAC | \$ 178,737 | \$ 451,935 |
| 98 | Alameda | Hayward Hall of Justice | HVAC | \$ 99,914 | \$ 112,491 |
| 100 | Los Angeles | Burbank Courthouse | Electrical | \$ 43,629 | \$ 15,154 |
| 101 | Los Angeles | San Fernando Courthouse | Roof | \$ 676,619 | \$ 42,130 |
| 108 | Santa Barbara | Santa Maria Courts Bldgs C + D | Roof | \$ 495,150 | \$ 76,554 |
| 111 | San Diego | Kearny Mesa Traffic Court KM5 & KM6 | Roof | \$ 19,572 | \$ - |
| 112 | Riverside | Larson Justice Center | Roof | \$ 787,875 | \$ - |
| 114 | San Luis Obispo | San Luis Obispo Courthouse Annex | Roof | \$ 624,510 | \$ - |
| 116 | San Diego | South County Regional Center | Roof | \$ 477,911 | \$ - |
| 117 | Los Angeles | Michael D. Antonovich Antelope Valley | Roof | \$ 1,709,595 | \$ 152,050 |
| 118 | Los Angeles | East Los Angeles Courthouse | Roof | \$ 530,237 | \$ 932,296 |
| 119 | Los Angeles | Alfred J. McCourtney Juvenile Justice | Roof | \$ 92,002 | \$ - |
| 121 | Del Norte | Del Norte County Superior Court | Roof | \$ 446,304 | \$ 39,482 |
| 123 | Amador | Amador Superior Court | Roof | \$ 192,560 | \$ 89,179 |
| 124 | Napa | Napa Historic Courthouse | Roof | \$ 939,501 | \$ 107,272 |
| 125 | Santa Barbara | Santa Maria Juvenile Court (new) | Roof | \$ 244,464 | \$ 90,414 |
| 126 | San Diego | South County Regional Center | Elevators | \$ 1,180,629 | \$ 1,284,150 |
| Total | | | | \$ 72,349,943 | \$ 8,823,557 |



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10 April 10, 2023


Progress Photos



Harbor Justice Center-Newport Beach - Elevators



Harbor Justice Center-Newport Beach - Elevators



Harbor Justice Center-Newport Beach - Elevators



Harbor Justice Center-Newport Beach - Elevators



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10 April 10, 2023


Progress Photos



Harbor Justice Center-Newport Beach - BMS

Harbor Justice Center-Newport Beach - BMS







Harbor Justice Center-Newport Beach - BMS



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10

April 10, 2023

Project Schedules


| Project Scried | | | | 20 | 24 | | | | | | | | _ | 20 | 22 | | | | | | | | | | | | _ | 201 | 2 | | | | | | | | - | | | | 202 | 1 | _ | | | _ | |
|----------------|-------------|---|---|----|----|--------|------|-----|---|--------------|---------|--------|---|----|----|---|---|------|----|----|----|---|---|---|---|---|---|--------|---|---|---|----|----|----|---|-------------------------|---|---|--------|---|-----------|---|---|---|----|----|----------|
| DMF 4 Sch | | | | 20 | | | | | | | | | | | 22 | | | | | | | | | | | | _ | 202 | | | | | | | | 2024 1 2 3 4 5 6 7 8 | | | | | | | | | | | |
| | Item Number | 7 | 8 | 9 | 10 |) 11 | 1 12 | 2 1 | 2 | 2 3 | 3 . | 4 | 5 | 6 | 7 | 8 | 5 |) 1 | 10 | 11 | 12 | 1 | 2 | 3 | 4 | | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 1 | 2 | 3 | 4 | 4 3 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| FM-0142716 | 1 | | _ | | L | Ļ | 4 | ╄ | + | + | 4 | | | | | | | | | | | | | L | L | 4 | 4 | 4 | | | | | | | | | | | _ | 4 | | | | | | | <u> </u> |
| FM-0142729 | 2 | | | | | L | | ╀ | _ | 4 | 4 | 4 | | | | | | | | | | | | L | ╄ | 4 | 4 | _ | | | | L | | | | L | 1 | 1 | 1 | 4 | 4 | | | | | L | <u> </u> |
| FM-0142718 | 3 | | | | | L | _ | ┸ | Ļ | \downarrow | 4 | 4 | | | | | | | | | | | | L | L | 4 | 4 | \Box | | | | L | | | | | | | | | | | | | | | <u> </u> |
| FM-0142721 | 4 | | | | | | | | | ┸ | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FM-0142734 | 6 | | | | | | | | | ↓ | \perp | | | | | | | L | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FM-0142738 | 7 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FM-0142730 | 8 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FM-0142708 | 9 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FM-0142727 | 10 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FM-0142715 | 11 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FM-0142725 | 14 | | | | | | | | | | | | | | | | Т | | | | | | | | | | П | | | | | | | | | | | Τ | | | | | | | | | |
| FM-0142726 | 15 | | | | | П | | | | | | | | | | | | Т | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FM-0142742 | 16 | | | | | П | | | | | | Т | | | | | | T | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FM-0142719 | 18 | | | | | Т | | | | | T | | | | | | | T | | | | | | | | | | | | | | | | | | Т | | Т | | Т | | | | | | Г | |
| FM-0142741 | 19 | | | | | | | | | Τ | T | \top | | | | | Τ | Т | | | | | | | | | | | | | | | | | | Г | | Т | | | | | | | | | |
| FM-0142745 | 20 | | | | Г | П | | | | | | T | | | | Π | Τ | Т | | | | | | Г | | | | | | | | | | | | | | | | | | | | | | | |
| FM-0142744 | 21 | | | | | Т | | Т | T | T | | T | | | | Π | T | T | | 一 | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FM-2001131 | 46 | | | | Г | Т | | | Т | Т | | Т | | | | Τ | T | | T | | | | | Г | Т | T | П | | | | | | | | | | | | | | | | | | | | |
| FM-2001176 | 50 | | | | | Т | | | | T | | | | | | Г | T | Т | T | | | | | Γ | Т | T | T | ╗ | | | | | | Γ | Τ | T | T | T | T | T | | | | | | П | |
| FM-2001178 | 51 | | | | | T | | | | | | | | | | Г | Т | T | | | | | | Γ | T | T | T | ╗ | | | | Γ | T | Т | Τ | T | T | T | T | T | T | | | | | | |
| FM-2001090 | 52 | | | | | | Т | | | Т | | 1 | | | | Т | T | T | | | | | | Γ | Т | | | T | | | | | | | Т | T | Т | T | | 1 | T | T | | | | | |
| FM-2001172 | 53 | | | | | Т | | | | T | Ť | T | | | | Т | Т | Ť | | | | | | | | T | T | ┪ | | | | Г | | Т | | Г | | Т | | T | | | | | | | П |
| FM-2001166 | 54 | | | | | Ť | | | | | Ť | | | | | | | T | | | | | | | | | | | | | | | | | | | | | | T | | | | | | | |
| FM-2001179 | 57 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | \top | 7 | | | | | | | |
| FM-2001170 | 58 | | | | | Ť | | | | | | | | | | | Ī | Ť | | | | | | | | | | T | | | | | | | | | | | | | \forall | | | | | Т | |



Trial Court Facility Modification Advisory Committee

Judicial Council Deferred Maintenance Projects – DMF 4 Monthly Report No. 10

April 10, 2023





Meeting Date: 4/10/2023

Information Item 4 – Architectural Revolving Fund Projects Update

Summary:

Update on the status of facility modification projects in the Architectural Revolving fund.

Supporting Documentation:

• Report – CFARF Funds Update – Open Projects



| Transfers | Location (County) | Facility Name | • | TCFMAC Approved Funds | s A | Total mount cumbered | Date of TCFMAC Approval | Current Status |
|-------------|----------------------|--------------------------------|--|--------------------------|-----|----------------------------|-------------------------------|---|
| AOC-11-027 | | | | | | | | |
| FM-0040733 | Solano | Hall of Justice | Construct 1,070 If of concrete retaining wall, 525 If of earthen berms, 575 If of access ramps; install drainage pipe and 2 pumps to extract water trapped within the prevention area. Relocate existing utilities infrastructure where the footings will be excavated for the retaining walls. New asphalt will be installed along the retaining wall in the parking areas. New fencing and gate will be installed after excavation is complete.\$1.7M was spent in 2005 for flood damage and \$146K was spent in FY 10/11 on flood prevention measures. Emergency exiting must be sealed during flood conditions. | \$ 1,114,874 | \$ | 691,916 | 1/30/2012 | In Progress (Design / Assessment) & Deferred for Construction |
| JCC-14-019 | | | | | | | | |
| FM-0011923 | San Diego | East County Regional Center | Elevator - Elevator Renovation - Complete renovation of nine (9) gearless traction elevators. Work will include but not be limited to, car frames and platforms, buffers and safeties, hoistway entrance frames, doors and pit equip., new AC gearless machines, micro-processor control systems, regenerative VVVF AC drives, governors (elevators 1,2&3 only), closed loop heavy duty high speed operators, current code required wiring, interior and lobby control panels, counterweights and roller guides (Elevators 7&9 only), hoist and governor ropes, cab ceilings with LED down lights, rope compensation and seismic provisions. | \$ 2,742,062 | \$ | 2,672,142 | 12/15/2014 | Completed (Awaiting Invoice) |
| FM-0017040 | Los Angeles | Compton Courthouse | Fire Alarm System - Phase 1 - Installation of a new Fire Detection and Notification Alarm system, building alarm system is not code compliant and must be replaced to comply with State Fire Marshal notice to comply. Work includes design and ACM abatement as needed. | \$ 540,943 | \$ | 540,943 | 4/13/2015 | In Work (Construction) |
| FM-0028322 | Orange | Central Justice Center | Fire Alarm System - Phase 1 -Replace/Renovate/Upgrade the existing Fire Alarm System - The existing building alarm system is not code compliant and must be brought to compliance per the State Fire Marshals notice to comply. Work includes design and ACM abatement as needed. | \$ 833,269 | \$ | 839,723 | 4/13/2015 | In Progress (Construction) |
| JCC-15-014 | | | | | | | | |
| FM-0017040c | Los Angeles | Compton Courthouse | Fire - Phase 2 - Building alarm system is not code compliant and must be renovated to comply with State Fire Marshal notice to comply. | \$ 1,213,353 | \$ | 1,255,425 | 1/17/2015 | In Work (Construction) |
| FM-0028322c | Orange | Central Justice Center | Fire - Phase 2 - Building alarm system is not code compliant and must be renovated to comply with State Fire Marshal notice to comply. | \$ 1,666,539 | \$ | 1,343,064 | 7/17/2015 | In Progress (Construction) |
| JCC-17-018 | | | | | | | | |
| FM-0011923e | San Diego | East County Regional Center | Elevator - Elevator Renovation - Complete renovation of nine (9) gearless traction elevators. Work will include but not be limited to, car frames and platforms, buffers and safeties, hoistway entrance frames, doors and pit equip., new AC gearless machines, micro-processor control systems, regenerative VVVF AC drives, governors (elevators 1,2&3 only), closed loop heavy duty high speed operators, current code required wiring, interior and lobby control panels, counterweights and roller guides (Elevators 7&9 only), hoist and governor ropes, cab ceilings with LED down lights, rope compensation and seismic provisions. | \$ 5,048,597 | \$ | 4,309,543 | 4/9/2018 | Completed (Awaiting Invoice) |



| Transfers | Location (County) | Facility Name | • | TCFMAC Approved Funds | Total Amount Encumbered | Date of TCFMAC Approval | Current Status |
|------------|----------------------|-----------------------------|--|--------------------------|-------------------------------|-------------------------------|------------------------------------|
| JCC-18-018 | | | | | | | |
| FM-0061175 | Riverside | Southwest Justice Center | Energy Efficiency - Electrical - Implement energy efficiency upgrade of interior and exterior lighting to LED (approx. 3172 fixtures) | \$ 476,354 | \$ 666,014 | 5/17/2019 | Completed (Awaiting Invoice) |
| JCC-19-012 | | | | | | | · |
| FM-0062195 | Los Angeles | | HVAC - Replace entire pneumatic and DDC control system with non-proprietary, BAS system, including new T-stats throughout. Existing system does not work and temperature for twenty (2) separate zones, the air handler /airflow speed, chiller temperature, and dampers must be adjusted manually and not able to control building temperatures. Experiencing several hold/cold calls daily in the entire building. | \$ 449,262 | \$ 449,262 | 7/19/2019 | Completed (Closed Task) |

Shaded region shows an update to the information