

#### TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

#### OPEN MEETING WITH CLOSED SESSION AGENDA

Open to the Public Unless Indicated as Closed (Cal. Rules of Court, rule 10.75(c)(1))

OPEN PORTION OF THIS MEETING IS BEING RECORDED

Date:December 15, 2014Time:12:00 PM - 1:30 PMLocation:Teleconference

Public Call-in Number: 1-877-820-7831 Listen Only Code: 4502468

Meeting materials for open portions of the meeting will be posted on the advisory body web page on the California Courts website at least three business days before the meeting. Agenda items are numbered for identification purposes only and will not necessarily be considered in the indicated order.

#### OPEN MEETING (CAL. RULES OF COURT, RULE 10.75(C)(1))

#### Call to Order and Roll Call 12:00 PM

#### **Approval of Minutes**

Approve minutes of the November 3, 2014, Trial Court Facility Modification Advisory Committee meeting.

#### II. ACTION ITEMS (ITEMS 1-6)

#### Action Item 1 – (Action Required)

**Summary:** List A – Emergency Facility Modification Funding (Priority 1)

**Action Requested:** Staff recommends 104 projects for a total of \$1,514,714 to be paid from

funds previously encumbered for emergency funding.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### Action Item 2 – (Action Required)

**Summary:** List B – Facility Modifications Less than \$50k (Priority 2)

**Action Requested:** Staff recommends 101 projects for a total of \$895,558 to be paid from funds

previously encumbered for facility modifications less than \$50k.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### Action Item 3 – (Action Required)

**Summary:** List C – Cost Increases Over \$50k

**Action Requested:** Staff recommends three projects for a total cost increase to the Facility

Modification Program Budget of \$586,442.

**Presenter:** Mr. Patrick McGrath, Facilities Operations Manager

#### Action Item 4 – (Action Required)

**Summary:** List D – Facility Modifications Over \$50k

Action Requested: Staff recommends 12 projects for a total cost to the Facility Modification

Program Budget of \$11,933,621.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### Action Item 5 – (Action Required)

**Summary:** List F – Court-Funded Facilities Requests (Facility Modifications)

Action Requested: Staff recommends two Court-Funded Facilities Requests for review and

approval.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### Action Item 6 – (Action Required)

**Summary:** Review and discussion of the *Annual Report of the Trial Court Facility Modification Advisory Committee for Fiscal Year 2013-2014* 

**Action Requested:** Provide input and additions to draft document post court comment and approve release to E&P upon revision.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

#### III. ADJOURNMENT

#### **Adjourn to Closed Session**

# IV. CLOSED SESSION (CAL. RULES OF COURT, RULE 10.75(d)) (ITEMS 1-3)

#### **Closed Action Item 1**

Facility Modification Security Projects (Action Required)

Pursuant to California Rules of Court, Rule 10.75(d)(5) Security plans or procedures or other matters that if discussed in public would compromise the safety of the public or of judicial branch officers or personnel or the security of judicial branch facilities or equipment, including electronic data.

**Summary:** Security Related - Emergency and Priority 1 (List A)

**Action Requested:** Staff recommends three projects for a total cost to the Facility Modification Program Budget of \$18,782, to be paid from funds previously encumbered.

#### **Closed Action Item 2**

Facility Modification Security Projects (Action Required)

Pursuant to California Rules of Court, Rule 10.75(d)(5) Security plans or procedures or other matters that if discussed in public would compromise the safety of the public or of judicial branch officers or personnel or the security of judicial branch facilities or equipment, including electronic data.

**Summary:** Security Related - FMs Less Than \$50K (List B)

**Action Requested:** Staff recommends two projects for a total cost to the Facility Modification Program Budget of \$9,818, to be paid from funds previously encumbered.

#### **Closed Action Item 3**

**Facility Modification Security Projects (Action Required)** 

Pursuant to California Rules of Court, Rule 10.75(d)(5) Security plans or procedures or other matters that if discussed in public would compromise the safety of the public or of judicial branch officers or personnel or the security of judicial branch facilities or equipment, including electronic data.

**Summary:** Security Related – FMs Greater Than \$50K (List D)

**Action Requested:** To continue limiting over \$50k expenditures to Priority 2 projects only at this time.

#### **Adjourn Closed Session**



#### TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

#### MINUTES OF OPEN MEETING WITH CLOSED SESSION

November 3, 2014 10:00 a.m. - 4:00 p.m. Sacramento Field Office

Advisory Body Hon Members Present: Don

Hon. David Edwin Power, Chair, Hon. William F. Highberger, Vice-Chair, Hon. Donald Cole Byrd, Hon. James L. Stoelker, Hon. Vanessa W. Vallarta, Ms. Linda

Romero-Soles, Ms. Christina M. Volkers, and Mr. Michael M. Roddy

Advisory Body Members Absent: Ms. Jeanine D. Tucker

Others Present:

Mr. Curt Soderlund, Mr. Patrick McGrath, Ms. M.R. Gafill, Mr. Nick Turner, Mr. Kenneth Kachold, Mr. Dan Hutton, Ms. Gisele Corrie, Mr. Price Eres, Ms. Christa Jennings, Ms. Maura Clark, Ms. Peggy Symons, Mr. Rob Uvalle, Ms. Michele

Allan, Ms. Angela Guzman, Ms. Tish Allan, Mr. Eric Schnurpfeil

#### **OPEN MEETING**

#### Call to Order and Roll Call

The chair called the meeting to order at 10:00 a.m., and took roll call.

#### **Approval of Minutes**

The advisory body reviewed and approved the minutes of the August 25, 2014, Trial Court Facility Modification Advisory Committee meetings.

#### PUBLIC WRITTEN COMMENT

No public written comments were received.

#### DISCUSSION AND ACTION ITEMS (ITEMS 1-11)

#### Item 1

#### Facility Modification Project List Review and Discussion (Action Required)

The advisory committee reviewed and discussed Facility Modifications (FMs) categorized in the identified lists below.

- List A Emergency FM Funding (Priority 1);
  - 52 Priority 1 FMs were approved with an estimated cost to the Facility Modification Program budget of \$2,019,539.
- List B FMs Less than \$50k;
  - 91 FMs less than \$50k were approved with an estimated cost to the Facility Modification Program budget of \$687,710.

- List C Cost Increases Over \$50k;
  - 5 FMs required cost increases over \$50k, for a total increase to the Facility Modification Program budget of \$542,521.
- List D FMs Over \$50k; and
  - Items 1-21 were recommended for funding with a total potential cost to the Facility Modification Program budget of \$6,306,462.
- List F Court-Funded Facilities Requests FMs
  - One Court-Funded Facilities Request was received from San Joaquin Superior Court.

Action: The advisory committee unanimously approved lists A, B, C, D, and F, after review and discussion. FM-0036208 for Santa Cruz Main Courthouse was removed from List D - FMs Over \$50K after discussion among the advisory committee. The advisory committee agreed that this facility modification seemed to be a system enhancement and not a like-for-like replacement, therefore, more information is needed before this project can be approved for funding.

#### Item 2

#### Facility Modification Requested from Placer Superior Court (Action Required)

Report on the status of project scope evaluation and program potential for funding Priority 3 projects.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action: This project is prioritized as a Priority 3. The committee will consider the project at its January 2015 meeting, as the facility modification budget may allow limited Priority 3 funding in January.

#### Item 3

#### Facility Modification Requested Merced Superior Court (Action Required)

Report on the status of project scope evaluation and program potential for funding Priority 3 projects.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action: This project will considered again in January 2015. Currently, security enhancements have not been approved for funding by the committee due to budget limitations.

#### Item 4

#### Fiscal Year 2015-2016 Budget Change Proposals – Status Update (No Action Required)

Status updates on the Department of Finance response to the FY 15-16 Budget Change Proposals.

Presenter: Ms. Gisele Corrie, Senior Financial Manager

Action: No action required.

#### Item 5

Fiscal Year 2013-2014 Operational Budget - Expenditure Review (Action Required)

Informational presentation as requested by the advisory committee to review expenditures from fiscal year 2013-2014 relative to the operational budget.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action: The advisory committee reviewed and approved staff recommendations to request an increase in Appropriation Authority for FY 14-15 and FY 15-16, develop and awareness campaign to potentially include Department of Finance, Legislative Analyst Office, Court Executives Advisory Committee, and Trial Court Presiding Judges Advisory Committee, and to enlist support for program advocacy from the Judicial Council and Trial Court Leadership.

#### Item 6

#### Fiscal Year 2013-2014 Utility Expenditure Review (No Action Required)

Informational presentation as requested by the advisory committee to review expenditures from fiscal year 2013-2014 relative to utility expenditures.

Presenter: Ms. Laura Sainz, Manager

Action: No action required.

#### Item 7

#### Solar Power Purchase Agreements (No Action Required)

Informational presentation as requested by the advisory committee to review process involved in obtaining a solar power purchase agreement.

Presenter: Ms. Laura Sainz, Manager

Action: No action required.

#### Item 8

#### Department of Finance Deferred Maintenance Report (Action Required)

Review and discuss the Department of Finance deferred maintenance report. Staff is requesting approval to release the report to the Department of Finance.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action: The advisory committee approved the format of the report and directed staff to release the report to the Department of Finance.

#### Item 9

#### Staffing – Facilities Management Program (No Action Required)

Informational presentation as requested by the advisory committee to review current staffing status and constraints.

Presenter: Mr. Jerry Pfab, Senior Manager

Action: No action required.

#### Item 10

### California Rule of Court 10.65 (Trial Court Facility Modification Advisory Committee) (No **Action Required)**

Review and discuss CRC 10.65 and implications to advisory body.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action: No action required.

#### Item 11

#### **Confirm 2015 Meeting Dates (Action Required)**

Discuss any scheduling conflicts with the proposed 2015 meeting dates.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action: The advisory committee unanimously approved a meeting schedule for 2015.

#### ADJOURNMENT

There being no further meeting business, the meeting was adjourned at 2:00 p.m.

Approved by the advisory body on enter date.

Trial Court
Facility Modification
Advisory Committee
Meeting

Teleconference Meeting

December 15, 2014

# Call to Order and Roll Call

- Chair Call to Order and Opening Comments
- Roll Call
  - Trial Court Facility Modification Advisory
     Committee Chair
  - Trial Court Facility Modification Advisory Committee Members
  - Real Estate and Facility Management
  - Capitol Program Staff
  - Guests



# **Approval of Minutes**

Minutes from meeting on November 3, 2014

# **Action Item 1 – (Action Required)**

## **Summary:**

List A – Emergency Facility Modification Funding (Priority 1)

Total Project Count:	104
Total Potential FM Budget Share of Cost:	\$1,514,714

Meeting Date: 12/15/2014

# **Supporting Documentation:**

- List A Emergency Facility Modifications (Priority 1)
- Supporting PowerPoint Slides

# **Action Requested:**

Ratify Judicial Council Staff preliminary decision for execution approval of List A – Emergency Facility Modifications (Priority 1).

FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	10DIFICA		JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
	Los	Clara Shortridge Foltz Criminal		l							
53423 <i>A</i>	Angeles	Justice Center	19-L1	1		\$	20,000	\$	13,758	In Work	68.79
					- '						
		·	40.404	l		,	40.000	_	6.642		66.40
53424			19-AG1	-	emergency generator bundle PM.	<b>\$</b>	10,000	<b>\$</b>	6,613	in work	66.13
					Plumbing / Snake and clean out main line due to blockage. Currently						
1-	_	-			-						
		<b>'</b>	19-AZ1	1		Ś	10.000	Ś	7.351	In Work	73.51
						7		-	700		
1-   Լ	Los	Glendale			Remove and replace Motor Control Center (MCC). AHU #3 has						
53432	Angeles	Courthouse	19-H1	1	refrigerant leak, no signal from MCC, not cooling.	\$	79,300	\$	71,798	Complete	90.54
		Modesto									
1-		Main			HVAC - Replace supply and return fan VFD and Chiller #1 upgrades to						
53435	Stanislaus	Courthouse	50-A1	1		\$	50,000	\$	38,910	In Work	77.82
					, c						
		Dala Cili			·						
,											
1- 52452		·	15 1	1	, , , , , , , , , , , , , , , , , , ,	لي ا	2.047	ے ا	1 000	Complete	62.64
00400 l	KEIII	Court	12-HI	<u> </u>		γ	3,047	٦	1,909	Complete	62.64
1-		Criminal Court									
			28-A1	l		Ś	3.500	Ś	3.500	In Work	100
5: 1-5: 1-5: 1-1-5:	3423 3424 3426 3435	Los Angeles Los Angeles Los Angeles Los Angeles Los Angeles Stanislaus  Stanislaus	Clara Shortridge Foltz Criminal Justice Center  Los Compton Courthouse Michael D. Antonovich Antelope Los Valley Courthouse  Los Glendale Angeles Courthouse  Modesto Main Stanislaus Courthouse  Bakersfield Superior Court  Criminal Court	Clara Shortridge Foltz Criminal Justice Center  Los Compton Courthouse Justice Center  Michael D. Antonovich Antelope Valley Courthouse Justice Center  Michael D. Antonovich Antelope Valley Courthouse Justice Center  Justi	Clara Shortridge Foltz Criminal Justice Center  Los Compton Courthouse Justice Center  Michael D. Antonovich Antelope Valley Angeles Courthouse Justice Center  Justice Center	Clara Shortridge Foltz Criminal Justice Center 19-L1 1 containment and environmental testing.  Los Compton Justice Courthouse 19-AG1 1 emergency Generator Fuel Leak - Replaced a defective gaskets. This work was completed as a P1 due to diesel fuel being discover inside the generator engine block and oil pan during the emergency generator bundle PM.  Angeles Courthouse 19-AG1 1 emergency generator bundle PM.  Los Valley sewage is coming up from the floor drains and causing slip hazard to the kitchen workers.  HVAC - Replace Shaft Seals, Head Gaskets and O-Rings on compressor. Remove and replace Motor Control Center (MCC). AHU #3 has refrigerant leak, no signal from MCC, not cooling.  Modesto Main Stanislaus Courthouse 50-A1 1 Circuit A Plumbing - Water line extored, judge's chambers and clerk's offices scrubbed/dried out over 48 hour period. Small paint touch up to Clerk's office wall. In custody in Holding Cell #2 damaged water line to toilet (clean water) causing water intrusion to judge's chambers and clerk's offices.  Earthquake P1 Response - Plumbing - There are 3 water leaks throughout the building, and some electrical and lighting to be	Clara Shortridge Foltz Criminal Angeles Los Compton Courthouse Los Angeles Los Angeles Los Courthouse Los Angeles Los Angeles Los Courthouse Los Angeles Los Angeles Los Courthouse Los Angeles Los Courthouse Los Angeles Los Angeles Los Courthouse Los Angeles Los Courthouse Los Antelope Valley Angeles Los Courthouse Los Courthouse Los Angeles Courthouse Los Courthouse Los Angeles Courthouse Los Glendale Los Courthouse Los Los Courthouse Los Courthouse Los Los Courthouse Los Courthouse Los Los Los Courthouse Los Los Los Los Los Courthouse Los	Los Foltz Criminal Foltz Courthouse 19-AG1 1 Plumbing / replace cracked 2" waste line utilizing lift, includes ACM containment and environmental testing. \$ 20,000 Electrical - Emergency Generator Fuel Leak - Replaced a defective gaskets. This work was completed as a P1 due to diesel fuel being discover inside the generator engine block and oil pan during the emergency generator bundle PM. \$ 10,000 Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to 1 the kitchen workers. \$ 10,000 Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to 1 the kitchen workers. \$ 10,000 Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to 1 the kitchen workers. \$ 10,000 Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to 1 the kitchen workers. \$ 10,000 Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to 1 the kitchen workers. \$ 10,000 Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to 5 10,000 Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to 5 10,000 Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to 5 10,000 Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to 5 10,000 Plumbing / Snake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to 5 10,000 Plumbing / Snake and clean out main line due to blockage. Currently se	Clara Shortridge Foltz Criminal Los Compton Angeles Los Compton Michael D. Antonovich Antelope Los Angeles Courthouse 19-AG1 Los Glendale Courthouse 19-AG1 Los Shortridge Foltz Criminal Antonovich Antelope Los Antonovich Antelope Los Shortridge Foltz Criminal Los Compton Michael D. Antonovich Antelope Los Angeles Courthouse 19-AG1 Los Glendale Glendale Gourthouse 19-AG1 Los Gourthouse 19-AG1 Los Gourthouse 19-AG1 Los Gourthouse 19-AG1 Los Glendale Gourthouse 19-AG1 Los Gourt	SHORT TITLE   SHORT TITLE	No. Los Compton Los Compton Los Courthouse 19-AG1 1 emergency generator bundle PM. Short was completed as a P1 due to diesel fuel being discover inside the generator engine block and oil pan during the mergency generator bundle PM. S 10,000 \$ 13,758 In Work Antelope Valley Antenovich Antelope Valley Antenovich Antelope Valley Angeles Courthouse 19-AG1 1 emergency generator bundle PM. S 10,000 \$ 7,351 In Work Emergency Generator Fuel Leak Replaced a defective gaskets. This work was completed as a P1 due to diesel fuel being discover inside the generator engine block and oil pan during the emergency generator bundle PM. S 10,000 \$ 6,613 In Work Antelope Valley Shake and clean out main line due to blockage. Currently sewage is coming up from the floor drains and causing slip hazard to the kitchen workers. S 10,000 \$ 7,351 In Work Emergency Generator Emergency Generator Fuel Leak Replaced a defective gaskets. This work was complete as a P1 due to diesel fuel being discover inside the generator engine block and oil pan during the emergency generator bundle PM. S 10,000 \$ 6,613 In Work Interventional PM. S 10,000 \$ 7,351 In Work Interventional PM. S 10,0

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
	FM-	Los	Downey			Plumbing - Repair leaking hot water domestic pipe (3/4" Copper Pipe) includes ACM containment and environmental testing. Currently there					
8	0053466	Angeles	Courthouse	19-AM1	1	is water leaking from the ceiling into the 1st floor clerk's area.	\$	10,000	\$ 8,3	70 In Work	83.7
9	FM- 0053467	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	1	Plumbing / Cracked water pipe. Currently water is dripping from the ceiling into the 2nd floor secured hallway causing a hazard the employees.	\$	10,000	\$ 6,9	99 In Work	69.99
						HVAC - Replace return shaft and front and back bearings on AHU #2	<u> </u>	<u> </u>	,		
10	FM-	Los	Inglewood	10 -1		and balance return fan. Currently the 3rd floor has no return air and it		10.000		-	
10	0053471	Angeles	Courthouse Michael D.	19-F1	1	is affecting the temperature on the entire floor.	\$	10,000	\$ 7,4	56 In Work	74.56
11	FM- 0053480	Los Angeles	Antonovich Antelope Valley Courthouse	19-AZ1	1	Plumbing - Failing Sewage Pump - Replace discharge piping on Pump #1 & #2 and replace floats. Sewage ejector pump went into high level alarm; Sewage pit pumps not working and sewage is building up in the pit	ς.	14,392	\$ 10,5	80 Complete	73.51
	FM-	Los	Van Nuys Courthouse	13 7121		Plumbing - Demo and build back of wall after replacing cracked pipe, includes ACM containment and environmental testing. Currently water is dripping from the angle-stop in the wall of the woman's restroom	7	14,332	10,5	So   Complete	73.31
12	0053483	Angeles	East	19-AX1	1	onto the floor under the sink in the restroom creating a slip hazard.	\$	12,000	\$ 10,7	69 In Work	89.74
13	FM- 0053484	Los Angeles	Pasadena Courthouse	19-J1	1	HVAC - Replace failed piping on condensate for the AHU includes ACM containment, leak remediation equipment and environmental testing. Currently there is condensate water leaking through the roof into room 209.	\$	10,000	\$ 6,9	35 In Work	69.35
	FM-		County			HVAC - Replace Power Modular Equipment Controller (MEC). Units will not operate in automatic. Departments 4 and 5 temperature was too					
14	0053503	San Diego	Courthouse	37-A1	1	warm.	\$	8,753	\$ 6,7	77 In Work	77.42

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
15	FM- 0053506	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-11	1	HVAC - Install new bearings and sleeve on the blower shaft, remove deteriorated piping and replace with new copper piping. Remove frozen isolation valves and replace with new butterfly valves. Replace Chilled Water line and insulation on the Chilled Water line. AHU 14-2 Vibrating due to worn shaft and bearings on the blower, vibration caused water leak on Chilled Water piping, 2 isolation valves found seized and replaced.	Ś	35,500	\$ 24.42	0 In Work	68.79
	FM- 0053507	Los Angeles	Clara Shortridge Foltz Criminal Justice Center			Plumbing - Replace failed and corroded flush valve assembly & pipe from above ceiling area. Water remediation, set up containments, disinfect area. Dehumidifiers and fans were placed to remove moisture in the leak affected area. Install new 1-1/2" Pneumatic Flush Valve Assembly, new pipe with fittings. Remove damage ceiling and build back. Water Leak/Flood on 3rd fl Dept. 41,	\$	21,987		5 In Work	68.79
17	FM- 0053508 FM-	Los Angeles	Clara Shortridge Foltz Criminal Justice Center		1	Plumbing - Install (3) VFDs, Pump Repairs, Pressure Sensors. Hot water pumps are leaking, pumps run 100% due to no VFD's. If pumps not repaired there will be no hot water to entire building.	\$	47,144		0 In Work	68.79
18	FM- 0053510	Los Angeles Los Angeles	Compton Courthouse  Bellflower Courthouse	19-AG1 19-AL1		HVAC - Clean tubes on Chiller #2, repair leaks, install new purge pump. Chiller is not working, building is hot.  HVAC - Replace leaking valve on reheat coil above ceiling includes ACM containment and environmental testing. Demo and rebuild failing ceiling areas. Water was dripping through the ceiling into the Woman's public restroom creating a slip hazard.	\$	58,602 10,000		4 In Work	66.13 77.94

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE	INARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						HVAC / Rebuild leaking chilled water pump #23 includes ACM containment and environmental testing and abatement. Currently						
						water is leaking through the seals and this is the second of the three						
	FM-	Los	Stanley Mosk			pumps available to circulate chilled water through the cooling loop for						
20	0053511	Angeles	Courthouse	19-K1	1	the HVAC.	\$	10,000	\$	9,726	In Work	97.26
						HVAC - Replace leaking valve on reheat coil above ceiling includes ACM		<u> </u>	·			
						containment and environmental testing and abatement. Water was						
	FM-	Los	Bellflower			dripping through the ceiling into the court reporters office creating a						
21	0053512	Angeles	Courthouse	19-AL1	1	safety hazard.	\$	10,000	\$	10,000	In Work	100
			Van Nuys			Plumbing / Set-up containment, drying equipment, and conduct						
	FM-	Los	Courthouse			environmental testing. Currently water is dripping from the ceiling into	١.					
22	0053513	Angeles	West	19-AX2	1	the secure hallway on the 10 floor creating a safety hazard	\$	10,000	\$	8,048	In Work	80.48
						Plumbing / Replace failed 90 degree elbow behind the wall of the sink						
			Ctapley Mask			includes ACM containment and environmental testing. Currently water						
22	FM-	Los	Stanley Mosk	10 1/1	1	is dripping down from the 7th floor to the 5th floor, room 546 court	ے ا	10 000	ا د	10.000	In Work	100
23	0053514	Angeles	Courthouse	19-K1	1	counsel room, damaging the ceiling tiles.  Plumbing - Replace failed seal on janitors sink area on the second floor	<u>ې</u>	10,000	\$	10,000	In Work	100
						and replace damaged/fallen ceiling tiles includes ACM containment						
						and environmental testing. Water spilled from Janitor's sink and the						
	FM-	Los	Inglewood			water leaked through to the 1st floor ceiling causing ceiling tiles to fall						
24	0053515	Angeles	Courthouse	19-F1	1	on the lobby floor.	Ś	10,000	\$	7.456	In Work	74.56
		l				Plumbing - Replace cracked drain pipe includes ACM containment and	<del>                                     </del>		*	7,100		
	FM-	Los	Norwalk			environmental testing. Janitor closet on the 4th floor has cracked drain						
25	0053516	Angeles	Courthouse	19-AK1	1	pipe, leaking water into 3rd floor secured hallway.	\$	10,000	\$	8,503	In Work	85.03
						· · · · · · · · · · · · · · · · · · ·	<u> </u>	•		<u>-</u>		
			Clara			Plumbing - Set up sump pumps in tunnel to drain water, set up						
			Shortridge			containment in lower gym, test for ACM, repairs were completed by						
	FM-	Los	Foltz Criminal			County ISD. Steam leak (Flex line) in tunnel causing leak in lower gym						
26	0053524	Angeles	Justice Center	19-L1	1	room B-302	\$	4,836	\$	3,327	In Work	68.79

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION DROGRAM BLIDGET SHARE	INARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Plumbing / Set-up containment & drying equipment, conduct						
	FM-	Los	Stanley Mosk			leak in the ceiling. This work was completed as a P1 emergency due to						
27	0053526	Angeles	Courthouse	19-K1	1	water leaking through the ceiling tiles above the entrance of room 258.	\$	8,937	\$	8,692	Complete	97.26
28	FM- 0053527	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	10-11	1	Plumbing / Replace failed Sloan valve assembly includes ACM containment and environmental testing, vacuum all water in Dept.121 and sanitize carpet dry. Toilet continuously flushing causing water to flood the jury room, courtroom, and water to leak down to the 12 floor hallway.	ć	10,087	\$	6 030	Complete	68.79
	FM-	Los	Compton			Fire Protection - Replace fire pump motor, batteries, wiring, battery cables, and auto relays 3D5 & 4D2. This work was completed as a P1 emergency due to the motor starter failing (burning up) causing the batteries and battery cables to fail as well as other wiring inside fire				•		
29	0053530 FM-	Angeles	Clara Shortridge Foltz Criminal	19-AG1		Holding Cell - Set-up containment and drying equipment, conduct environmental testing, secure water to cell #8, and auger/clear clogged toilet to stop water from overflowing. This work was completed as a P1 due to an inmate clogging his cell toilet causing water to overflow and	\$	14,994	\$	9,916	In Work	66.13
30	0053531	Angeles	Justice Center	19-L1	1	leak down to the 13th floor public hallway.  Grounds and Parking Lot - Isolated control valve and replaced valve, pumped area to prevent water from entering the building. Landscaping	\$	10,225	\$	7,034	In Work	68.79
	FM-	Los	Stanley Mosk	40.44		control valve stuck open over the weekend flooding area, causing		2.222	,	2 722		07.00
31	0053532 FM-	Angeles	Courthouse Compton	19-K1	1	water to enter the building rm-119 Plumbing - Flood Remediation - Set-up containment and drying equipment, conduct environmental testing, and replaced 40' of 4" cast iron sewer drain pipe, no-hub couplings, and miscellaneous fittings.	\$	3,900	\$	3,793	Complete	97.26
32	0053533	Angeles	Courthouse	19-AG1	1	Water is leaking into the basement from the cracked pipe.	\$	16,765	\$	11,087	In Work	66.13

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE	INARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
			Clara			Interior Finishes / Set-up containment and drying equipment, perform					
	FM-	Loc	Shortridge Foltz Criminal			environmental testing, remove ceiling tiles, and check for leak above cubicle. This work was completed as a P1 emergency due to an					
33	0053534	Los Angeles	Justice Center	19-L1	1	employee stating a leak was coming from the ceiling above her.	\$ 5,406	\$	3,719	In Work	68.79
							· ·		<u> </u>		
			Clara			HVAC - 3 HP Exhaust Fan - Remove and replace the failing kitchen					
			Shortridge			exhaust fan, the new fan will include a timer, for more efficient					
	FM-	Los	Foltz Criminal			operation. The kitchen exhaust fan has a high vibration causing the					
34	0053535	Angeles	Justice Center	19-L1		exhaust fan to not work properly.	\$ 14,998	\$	10,317	Complete	68.79
						Plumbing - Drain building cold water to 5th floor to stop leak, once					
						secure Cut out section 2-1/2 copper that was leaking, installed ball valve with new 2-1/2 copper line and pro press secure. Re-fill entire					
						building and check all toilets, urinals for proper operation and repair as					
			Clara			needed. Checked new plumbing for leaks, once cold water was filled.					
			Shortridge			5th Floor Women's public restroom had leak in ceiling, located source					
	FM-	Los	Foltz Criminal			leaking coming from 2-1/2 copper pipe cold water supply. Shut off					
35	0053536	Angeles	Justice Center	19-L1	1	valve would	\$ 19,350	\$	13,311	Complete	68.79
						Interior Finishes - Water remediation, set up containments, dry areas					
						with proper drying equipment. Build back, replace ceiling tiles, floor					
	FM-	Los	Inglewood			tiles, drywall ceiling. Remove all debris associated within scope of work. Water leak from roof to 2nd flr court room # 241, 2nd flr men's public					
36	0053537	Angeles	Juvenile Court	19-E1	1	restroom and the 1st flr court room # 240.	\$ 29,051	\$	23,467	In Work	80.78

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	MODIFICA	PROGRAM BODGE! SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Interior Finishes - Water remediation, set up containments, disinfect areas. Dehumidifiers/fans were placed to remove moisture in the leak						
						affected areas. Remove drywall for access to drain pipe, remove and						
						replace damaged drain pipe. Install drywall after pipe installation and						
						complete finish work (painting and cove base). Tear out wet ceiling tile						
			Van Nuys			and replace ceiling tile (108 pcs). Cracked 2" black steel pipe leaking						
	FM-	Los	Courthouse			through walls on 10th floor down to the 9th floor ceiling. Carpet in						
37	0053539	Angeles	West	19-AX2	1	room	\$	36,811	\$	29,625	In Work	80.48
						Plumbing / Set-up containment, conducted environmental testing,						
						create larger access panel in restroom wall, and replaced the hot & cold						
			Canantan			isolation valve. This work was completed as a P1 emergency due to the						
38	FM- 0053553	Los	Compton Courthouse	19-AG1	1	valves breaking in the off position and the restroom having no access	ا ر	9,249	۲	C 11C	Complete	66.13
36	0055555	Angeles	Courtilouse	19-AG1	1	to water.	Ş	9,249	Ş	0,110	Complete	00.13
						HVAC - Removed the old, faulty External Float Switch and installed a						
						New External Float Switch. Checked the Cooling Towers, Chillers, and						
						Condenser Water Pumps to ensure the system is in normal working						
						conditions. Building was very hot due to a faulty External Float Switch						
	FM-	Los	Bellflower			on the Cooling Towers. Chillers #1 and #2 were tripped due to						
39	0053556	Angeles	Courthouse	19-AL1	1	restricted condenser water flow. This was a health and safety issue.	\$	2,348	\$	1,830	Complete	77.94
						HVAC - Replace Chilled Water Valve and piping, new insulation was						
			Facility (			wrapped on the new sections of piping. The chilled water valve for AHU						
	[ F. 4		East Los			# 4 seized up and would stroke properly. This caused the AHU to not						
40	FM-	Los	Angeles Courthouse	19-V1	1	cool properly. The chilled water piping adjacent to the unit was deteriorated and leaked water.	ر ا	10.061	ا د	Q E10	Complete	77 72
40	0053557	Angeles	Courtilouse	172-17	$L_T$	Jucteriorateu anu leakeu water.	٦	10,961	٦	0,519	Complete	77.72

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	IODIFICA	PROGRAM BUDGEI SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
41	FM- 0053560	Los Angeles	Van Nuys Courthouse West	19-AX2	1	Plumbing - Drain building cold water to 5th floor to stop leak, once secure Cut out a 3' section of 2-1/2" copper line that was leaking, installed ball valve with new 2-1/2" copper line and pro press secure. Re-fill entire building and check all toilets, urinals for proper operation and repair as needed. Checked new plumbing for leaks, once cold water was filled. 5th Floor Women's public restroom had leak at the ceiling, isolated the leak coming from a 2-1/2" copper cold water supply pipe. Extract water from bathroom floor, remove and replace approximately 16SF of damaged drywall and seal and paint approximately 80 SF of the ceiling	\$ 19,588	\$	15,764	Complete	80.48
42	FM- 0053562	Los Angeles	Pomona Courthouse South	19-W1	1	Plumbing - Water remediation, set up containments, abated insulation from the pipes. Replaced deteriorated sections of pipe. New fiberglass insulation was wrapped on the new sections of pipes. Water supply and return water lines from buildings boiler system have multiple leaks, leaking is from deterioration of lines. This caused safety issues with electrical panels and slippery floor surfaces.	\$ 66,361	\$	60,481	In Work	91.14
	FM- 0053565 FM- 0053573	Los Angeles Los Angeles	Clara Shortridge Foltz Criminal Justice Center  Norwalk Courthouse	19-L1 19-AK1		Plumbing - Set-up Containment, drying equipment, and conduct environmental testing. Currently water is dripping from the ceiling into the public hallway in front of the entrance Dept 32 courtroom causing a slip hazard.  HVAC - Failing AHU #7 - Replace supply fan motor, variable frequency drive, pulleys, and fan belts. AHU #7 had a faulty bearing and the variable frequency drive is tripping on the ground fault protection. If the unit had failed completely, there would have been no air conditioning to the entire seventh floor, impacting the courts operations.	\$ 10,000		•	In Work  Complete	68.79 85.03

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Plumbing - Ran fiber optic camera through the drain line in order to locate the stoppage and clear the drain line. Removed all debris and						
						pumped water from sump pits to prevent water from backing up and						
						causing a flood in the basement. The floor drain line in the basement						
			Nomicalle			got clogged not allowing water to drain properly. Water is pooling in						
45	FM- 0053579	Los	Norwalk Courthouse	19-AK1	1	the basement presenting a safety hazard to damage our electrical panels and a slipping hazard to ABM personnel.	ا د	6,162	ر	5 240	Complete	85.03
43	0033373	Angeles	Courtilouse	19-AK1	╀	Elevators, Escalators, & Hoists - Control Panel - Replaced bad circuit	<del>ا ؟</del>	0,102	٦	3,240	Complete	63.03
						that had a short and restored elevators 1-4 back to normal working						
						conditions. Call Stations for Elevators 1-4 were not responding. The						
						public as well as court employees were overcrowding and congesting						
	FM-	Los	Norwalk			public elevator lobbies on all floors. This was a safety and security						
46	0053580	Angeles	Courthouse	19-AK1	1	hazard.	\$	2,239	\$	1,904	Complete	85.03
						HVAC - Remove, rebuild, then re-install fuel injector pump and reseal						
						oil return line. The generator has leaks at both the oil return line and						
	FM-	Los	El Monte			the fuel injector pump while under load. Hazards include possible fire						
47	0053581	Angeles	Courthouse	19-01	1	due to the fuel igniting.	\$	11,801	\$	6,859	Complete	58.12
			Van Nuys			HVAC / Repair supply trunk lines and install new VFDs to AHU #21.						
	FM-	Los	Courthouse			Currently there is no A/C to the 2nd floor Clerk's area creating	١.		١.			
48	0053945	Angeles	West	19-AX2	1	uncomfortable work conditions for the employees.	\$	15,000	\$	12,072	In Work	80.48
						HVAC - Rebuild failed CW Pump #22, replace CW Pump motor,						
	E					remediate ACM pipe insulation and replace. #22 Chilled water pump						
10	FM-	Los	Stanley Mosk	10 1/1		motor has bad bearings and pump does not provide proper discharge	_	27 202	_	26 622	la Made	07.26
49	0054037	Angeles	Courthouse	19-K1	1	pressure.	\$	27,382	\$	26,632	In Work	97.26
						Grounds and Parking Lot - Motor Failure - Remove and replace						
			Clara			damaged Sally Port Door with new Custom Built Door. Install new						
			Shortridge			tubing, hardware and re-wire controls/push button/card reader and						
	FM-	Los	Foltz Criminal			assured door work for proper operation. Sally Port door motor failed						
50	0054038	Angeles	Justice Center	19-L1	1	and the door dropped and was damaged beyond repair.	\$	106,109	\$	72,992	In Work	68.79

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BLIDGET SHARE	INARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
		Los	Inglowood			Elevator / Replace selector tape and sheave on elevator #1. Currently Elevator #1 is stuck on the 3rd floor with the doors closed and is not						
51	FM- 0054039	Los Angeles	Inglewood Courthouse	19-F1	1	functioning.	ر	10,000	ڕ	7.456	In Work	74.56
31	0034033	Aligeies	Clara Shortridge	1311		Exterior - Install and secure metal grills so the homeless will not enter areas beneath the facility. The homeless have accessed an area under the building leaving hazardous materials and trash, under and around	,	10,000	7	7,430	III WOIK	74.30
	FM-	Los	Foltz Criminal			the building, creating contamination risks on the east side of the						
52	0054047	Angeles	Justice Center	19-L1	1	building.	\$	23,794	\$	16,368	Complete	68.79
	FM-	Los	Pomona Courthouse			Electrical - Water remediation, dehumidifiers and fans were placed to remove moisture in the affected area. HVAC -Restore Chiller operations; Plumbing - Restore pumps to full operations; Electrical - Replace Control Transformer, replace electrical wiring to compressor. An electrical transformer short circuited causing power failure to the injector pumps to the building drainage system that the current cooling tower drains into. As a result of loss of power the injector pumps were						
53	0054048	Angeles	South	19-W1	1	not online.	\$	46,931	\$	42,773	In Work	91.14
54	FM- 0054050	San Diego	County Courthouse	37-A1	1	Exterior Shell - Elevator 4B replaced Power Supply Board, ran car and verified, tested okay. Elevator not responding to call, stuck on 2nd floor, getting stuck on random floors.  Plumbing / Set-up Containment, drying equipment, shampoo carpet,	\$	2,965	\$	2,296	Complete	77.42
	FM-	Los	Alhambra			clean upholstery, & replace ceiling tiles. Currently there is water						
55	0054054	Angeles	Courthouse	19-I1	1	dripping from the snack bar into the basement call center.	\$	10,000	\$	8,600	In Work	86
56	FM- 0054051	Los Angeles	Beverly Hills Courthouse	19-AQ1	1	Plumbing / Set-up containment, Conduct Environmental Testing, and replace fittings for the 2 1/2" domestic cold water supply line that is leaking. Water leak has been isolated and contained.  Plumbing / Set-up containment, conduct environmental testing, and replace cracked 4" main cast iron drain pipe in ceiling. Water dripping from the soiling into the self help center on the 1st floor. Currently the	\$	10,000	\$	7,952	In Work	79.52
57	FM- 0054055	Los Angeles	Inglewood Courthouse	19-F1	1	from the ceiling into the self help center on the 1st floor. Currently the leak from the ceiling has been contained.	Ś	12,500	Ś	9.320	In Work	74.56
	1000 1000	1,	Jour Chouse	1-2 1-		lear nom the centing has been contained.	١ ٧	12,500	<u> </u>	3,320	** 011	7 7.50

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
58	FM- 0054058	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing / Set-up Containment, disinfect area, set-up Drying equipment, and conduct environmental testing. Currently water is dripping into the 15th floor, public hallway from the employee's Men's restroom on the 16th floor.	\$	10,000	\$ 6,879	In Work	68.79
59	FM- 0054059	Los Angeles	Pasadena Courthouse Van Nuys	19-J1	1	Plumbing - Water remediation, set up containments, contain leaking, and dried leak affected areas. Water leaking from 4th floor through to the ceiling on 3rd floor, Room 319 Public Defender's Office.  Electrical - Trace electrical wires to assure there are not shorts in	\$	10,000	\$ 10,000	In Work	100
60	FM- 0054057	Los Angeles	Courthouse West	19-AX2	1	system. Currently the lights in Rooms 233, 237, & 238 will not function even though there is electrical power going to the space.	\$	7,500	\$ 7,500	In Work	100
61	FM- 0054060	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1		Grounds / Replace burnt out motor, bottom guide rail, and bent/broken rods. The gate came down on top of the bus transporting the in-custodies creating a safety situation since the gate no longer opens correctly.	Ś	10,000	\$ 10,000	In Work	100
	FM- 0054061	Los Angeles	Torrance Courthouse	19-C1		Plumbing / Replace broken toilet, replace telephone, and repair holes in wall. Currently an inmate has torn out the phone for the holding cell, broken the toilet, and punched holes in the wall creating a safety situation for all deputies.	\$	10,000		In Work	100
63	FM- 0054063	Placer	South Placer Justice Center	31-H1	1	HVAC - Airco Mechanical and crew removed the burnt compressor and all lock out and tag out will be performed in a safe manner. All of the executive staffing were informed of the of the install and when they will receive cooling - Air handler # 1 that serves the executive staffing went into alarm and shut down.	\$	28,932	\$ 28,932	In Work	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
	FM-					Earthquake Restoration - Interior Finishes - Patch, paint and seal cracked wall, ceiling and baseboard surfaces throughout building,					
64	0054065	Napa	Juvenile Court	28-C1	1	Replace damaged fire sprinkler heads, carpet and ceiling tile.	\$	50,000	\$ 50,000	In Work	100
			Michael D. Antonovich Antelope			HVAC - Replaced vane actuator shaft control pre-rotation device, vane actuator and associated linkages. Installed (3) new gaskets and (3) new			7 33,555		200
	FM-	Los	Valley			0-ring seals, and recharged Chiller. Compressor on the chiller not	١.				
65	0054076	Angeles	Courthouse	19-AZ1	1	functioning due to a failed vane actuator to the vane linkage arm.	\$	36,461	\$ 36,461	In Work	100
66	FM- 0054077	Los Angeles	Metropolitan Courthouse	19-T1	1	Elevators, Escalators, & Hoists - Replace bearings, motor shaft and Exciter Armature, restore elevator to normal operations. Judge's elevator #12 bearings over heated. Elevator was on the 8th floor and out of service.	Ś	40,730	\$ 40,730	In Work	100
	FM- 0054078	Los Angeles	Burbank Courthouse	19-G1	1	Plumbing - Excavate concrete around meter vaults and planter in front of the courthouse to expose water line. Sidewalk removed. Installed new copper piping, valves, and regulators. New sidewalk poured, dirt removed is replaced. Water Main Leak under sidewalk and into planter, vault containing the water meters was flooded. Additional leak located in the planter area coming from a clay-valve and gate valve.	\$	43,324		In Work	90.76
60	FM- 0054079	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	10.14	4	Interior Finishes - Water remediation, set up containments, dehumidifiers and fans were placed to remove moisture in the leak affected areas. ACM & Bacterial testing & clearance. Install new Cast iron pipe with fittings and install support hangers for pipes to meet current building codes. Major drain line water leak on the 7th floor; areas affected due to this water leak include secured hallways, court rooms, judge's chambers, restrooms, and clerk's areas.	ć	46,803	\$ 32,196	In Work	68.79

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE	INARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						HVAC - Water remediation, set up containment, contain leaking, and dried leak affected area. Replace floor drain and pipe in ceiling. Replace						
						2 custom Chilled Water Coils including copper piping. Build back of Snack Bar area including drywall and paint to match existing paint. 2nd						
						floor Mechanical Room floor drain is cracked and leaking into the						
	E. 4					ceiling below. Also the coils on AHU-2 have deteriorated and are						
69	FM- 0054081	Los Angeles	Norwalk Courthouse	19-AK1	1	leaking on the floor of the Mechanical Room and seeping through to the ceiling below. W	ς .	75,210	\$	63 951	In Work	85.03
0.5	0034001	Aligeies	Courtificuse	IJ AKI	-	Plumbing - Set-up containment, conduct environmental testing, and	١,	73,210	7	03,331	III VVOIR	05.05
						replace leaking portion of domestic hot water pipe. Currently water is						
	FM-	Los	Glendale			dripping from the ceiling of the traffic clerk's area creating a safety			_		l	
70	0054084	Angeles	Courthouse	19-H1	1	hazard.	\$	12,500	\$	11,318	In Work	90.54
						Interior Finishes - Water remediation, set up containments, restroom						
						wall opened up to make repairs, wall repaired to match existing.						
						Replaced failed valve with copper pipe and fittings. Replace damaged						
74	FM-	Los	Metropolitan	40 T4		ceiling tiles and install access panel. Water leak in Judges rest room on	,	20.052	۲	20.222	la Mante	04.54
71	0054080	Angeles	Courthouse	19-T1	1	the 6th floor, water leak also affected Dept. #66 on the 5th floor.  HVAC - Boiler 1 & 2 will not stay online, control boards have failed and	<b>\</b>	29,852	\$	28,222	In Work	94.54
			New			the building cannot be heated. Replace control boards and add heat						
	FM-		Susanville			tape and windshield to unit housing to protect and help prevent						
72	0054087	Lassen	Courthouse	18-C1	1	reoccurrence.	\$	2,000	\$	2,000	In Work	100
						Plumbing - Set-up containment, conduct environmental testing, and						
	FM-	Los	Metropolitan			replace cracked drain pipe. Currently water is dripping from the ceiling						
73	0054088	Angeles	Courthouse	19-T1	1	into the 8th floor Jury office room causing a safety hazard.	\$	10,000	\$	9,454	In Work	94.54
						Parking Lot - Repair bent grill and rods on main roll-up gate. The gate						
						was hit by a car and is not operational which is a safety hazard for the						
74	FM- 0054089	Los	Compton Courthouse	19-AG1	1	employees and staff of the courthouse. The vehicle has not been identified at this time.	ر	10,000	خ ا	G G12	In Work	66.13
/4	10034003	Angeles	Courtilouse	TAYOT	1	nachuneu at uns ume.	ا ک	10,000	۲	0,013	IIII AAOIK	00.13

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	INARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Interior Finishes - Set up containment, ACM testing/clearance, replace						
						drywall, and remount the light fixture. Suspended ceiling light fixture						
	E N 4					fell in northwest end of basement. A portion of the plaster from						
75	FM-	Can Diago	Kearny Mesa	27.61		ceiling's hard lid broke loose, due to potential ACM disturbance a	_ ا	4 400	۲ ا	4.400	Camanlata	100
75	0054092	San Diego	Traffic Court	37-C1	1	containment was set-up and environmental testing performed.  Elevator / Replace malfunctioning door edge sensor. This work was	>	4,498	\$	4,498	Complete	100
						completed as a P1 emergency due to the door edge sensor not sensing						
	FM-	Los	Torrance			when someone was in the door way and closing which was causing a						
76		Angeles	Courthouse	19-C1	1	safety situation.	ر	2,474	Ś	2 106	Complete	85.14
70	0034034	Aligeles	Van Nuys	19-01	1	Electrical - Repaired generator 3/8" fuel line connection to the fuel	٦	2,474	٦	2,100	Complete	83.14
	FM-	Los	Courthouse			filter and placed generator back into service. Fuel line broke while						
77		Angeles	East	19-AX1	1	generator was running (outage due to DWP power issues).	ر	2,606	رخ	2 330	In Work	89.74
' '	0034033	Aligeies	Last	IJ AKI		generator was running (outage due to DWT power issues).		2,000	٦	2,333	III VVOIK	03.74
						Plumbing - Water Leak - Set-up containment, conduct environmental						
						testing, and located the source of leak, removed and replaced a 15'						
						section of 4" cast iron that had cracked. Removed and replaced						
	FM-	Los	Metropolitan			approximately 10 wet ceiling in storage room 3 and where water						
78	0054097	Angeles	Courthouse	19-T1	1	dripped through the ceiling tiles in storage room 4.	\$	10,000	\$	9,454	In Work	94.54
						Elevator - Replace buffer circuit boards on top of the elevator car.	†	· · · · · · · · · · · · · · · · · · ·	<u> </u>	-		
	FM-	Los	Bellflower			Currently the elevator is not stopping on the designated floors which is						
79	0054096	Angeles	Courthouse	19-AL1	1	causing a safety situation.	\$	10,000	\$	7,794	In Work	77.94
						Exterior Finishes / Replace panic hardware on ADA front entrance						
	FM-	Los	Airport			doors. Currently the doors are not securing at night making the						
80	0054098	Angeles	Courthouse	19-AU1	1	courthouse unsafe.	\$	5,000	\$	3,859	In Work	77.17
						HVAC - Replace (3) Variable Frequency Drives to the cold deck, hot deck						
			Van Nuys			and return fan. This work was completed as a P1 emergency due to the						
	FM-	Los	Courthouse			9th floor not having any heating which made it uncomfortable for the						
81	0054100	Angeles	West	19-AX2	1	visitors and employees.	\$	9,646	\$	7,763	Complete	80.48

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Plumbing - Set-up containment, conduct environmental testing and drying equipment, replace angle stops from the 5th floor Jury					
						restroom. This work was completed as a P1 emergency due to water					
			Van Nuys			leaking from the 5th floor Depart 420, Jury Restroom into the 4th floor					
	FM-	Los	Courthouse			lawyer's interview room, the audience seating adjacent to the lawyer's	_				
82	0054102	Angeles	East	19-AX1	1	interview room, and the jury room.	\$	15,851	\$ 15,85	1 In Work	100
						Plumbing - Replace leaking cap for the 4" domestic cold water supply					
		Loc	Airport			pipe. This work was completed as a P1 emergency due to water leaking					
02	FM-	Los	Airport	10 111		into the pump room which could become a flood if the work was not	ا د	2 466	t 100	Complete	77 17
83	0054104	Angeles	Courthouse	19-AU1	1	completed immediately.  Plumbing / Set-up containment, conduct environmental testing,	٦	2,466	\$ 1,90	3 Complete	77.17
						replace 3" cracked pipe leaking from ceiling into the secure hallway					
						adjacent from the DA's office, replace damaged drywall, and ceiling					
			Van Nuys			tiles. This work was completed as a P1 emergency due to a sewage pipe					
	FM-	Los	Courthouse			cracking and leaking water into the secure hallway creating a slip and					
84	0054105	Angeles	West	19-AX2	1	safety hazard.	Ś	12,800	\$ 10,30	1 Complete	80.48
		U				Plumbing - Replace faulty control valve to toilet in the men's lock-up	Ė	•	,		
	FM-	Los	Santa Clarita			area. This work was completed as a P1 emergency due to water leaking					
85	0054107	Angeles	Courthouse	19-AD1	1	from the base of the toilet and sink creating a slip hazard.	\$	2,320	\$ 2,32	Complete	100
						Grounds and Parking Lot - Potential Hazardous Material Leak- contain					
						and mitigate environmental hazard. Saw cut and hand demo 8'x8' area					
						of concrete where the Glycol is seeping through concrete fissures and					
			New			determine the source of the leak. Replace the leaking PVC couplers					
	FM-		Susanville	10.61		with Shark Bite brass couplers. Retrieve and properly dispose of	_	40.000	40.00		400
86	0054111	Lassen	Courthouse	18-C1	1	ponded Glycol. Restore concrete to existing conditions	۱ ۶	10,000	\$ 10,00	0 In Work	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE	OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						HVAC - Water remediation, set up containments, contain leaking, disinfect and dried leak affected area. ACM testing. 8 sq. ft. of ceiling						
						tiles were removed and replaced. Installed new custom manufactured						
						hot water and chilled water coils along with new piping, and a new						
			Pomona			custom manufactured stainless steel drain pan and pipe. Replace 4 gate valves and replace insulation from piping. Water leak from 2nd floor air	1					
	FM-	Los	Courthouse			handler room, is going into 1st floor lobby affecting employee						
87	0054115	Angeles	South	19-W1	1	entrance. Condensate	Ś	72,689	\$	66.249	In Work	91.14
		l mgaras			<del>                                     </del>	Plumbing - Water Leak - Set-up containment, drying equipment, and			T			
						conduct environmental testing. Removed and replaced one broken						
						hose bib, remove and replace approximately 35 sf of damaged plaster						
						ceiling and 100sf of plaster walls. Water from the janitorial sink ran						
	FM-	Los	San Fernando			down from the 4th floor to the 2nd floor effecting rooms 4046, 4045,						
88	0054119	Angeles	Courthouse	19-AC1	1	3096, 3095, 2102, & 2104.	\$	10,000	\$	8,341	In Work	83.41
						Plumbing / Construct containment, set-up drying equipment, conduct						
						environmental testing, and replace fallen ceiling tiles. Initial work will						
		Los	Compton			be conducted under hot conditions until testing results are received.						
90	FM-	Los	Compton	10 461		Water leaked from the janitorial hose from the 11th floor down to the 8th floor.	ے ا	12 500	ا د	0 266	In Work	66 12
89	0054120	Angeles	Courthouse	19-AG1	1	Plumbing - Flood Water Mitigation - Construct containment, conduct	<del>&gt;</del>	12,500	\$	8,200	III WOIK	66.13
						environmental testing, and replaced a 5 foot section of 2 inch cracked						
						drain line and replaced one 2x2 ceiling tile in room 106 which has a 14						
	FM-	Los	Stanley Mosk			foot ceiling.						
90	0054122	Angeles	Courthouse	19-K1	1		\$	10,000	\$	9,726	In Work	97.26
						HVAC - Replace Pneumatic control valves and actuators AHU-1 & AHU-						
						2. Control valves are broken and non-operational. There is no way of						
						controlling the cooling at these units because of this issue. Also the						
	FM-	Los	Compton			chilled water isolation valves and bypass valves are non-operational at						
91	0054116	Angeles	Courthouse	19-AG1	1	this unit and will have to be replaced.	\$	44,313	\$	29,304	In Work	66.13

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	CILITY MOD OGRAM BUI	OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
92	FM- 0054123	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing / Set-up containment, drying equipment, conduct environmental testing, and replace ceiling tiles. Water leaked from an overflowing toilet in the 3rd floor men's public restroom through the ceiling into the 2nd floor room 206R which created a safety situation.	\$ 10,000	\$	8,503	In Work	85.03
93	FM- 0054124	Los Angeles	Pasadena Courthouse	19-J1	1	HVAC - Set Up Containment, heppa Vacuum, change out filters, and abate loose fire proofing. Loose fire proofing was found in the air filters of AHU #2 which could have caused a health and safety issue.	\$ 10,000	\$	6,935	In Work	69.35
94	FM- 0054129	Madera	Madera County Superior Court	20-A1	1	HVAC - Remove the two defective fire tubes and install two new tubes in their place. Once the new tubes are in place they will be rolled to create the seal. After the tubes have been rolled and the seal created; a Hydro-static test will be performed to insure that the new tubes and the remaining tubes will hold pressure and the boiler has no further leaks. The price will include the ASME documentation and the installation of a new fire gasket on the main access panel.	\$ 4,075	\$	2,934	In Work	72
95	FM- 0054130	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing - Water remediation, set up containments, secure water supply and disassemble Sloan assembly, re-build removed all calcium, installed new 3.5 master re-build kit with master vacuum break re-build kit. 4th floor Cell #1 Sloan assembly has calcium build up causing leak when flushed in pipe chase. causing flood to 3rd floor in front Dept.32.	\$ 11,400		7,842	Complete	68.79
96	FM- 0054132	Los Angeles	East Los Angeles Courthouse	19-V1	1	HVAC - Water remediation, set up containments, vacuumed carpets to remove water and dried leak affected rooms. Replace ceiling tiles. Water leaked on the floor of the central plant from chiller. The water seeped thru the concrete floor and leaked into the 3rd floor offices 301S and 301T. The water damaged ceiling tiles in both offices.	\$ 5,635	\$	4,380	Complete	77.72

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	&	PROGRAM BUDGEI SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Elevators, Escalators, & Hoists - Build containment and enclose basement elevator door area, wiped clean and set up negative air						
						machine. Replace brake coil Judge's elevator #5. Brake coil in Judge's						
07	FM-	Los	Pasadena	10 11	1	elevator has failed. Elevator was shut down for safety reasons and locked out.	ے ا	7 670	ے ا	E 22E	Complete	60.25
97	0054131	Angeles	Courthouse	19-J1	╀	HVAC - Remove defective 15HP motor. Installed new 15HP motor, drive	) 	7,679	\$	5,323	Complete	69.35
	FM-	Los	Inglewood			pulley, bushing and 3 new B79 belts. Cooling tower fan motor not						
98	0054133	Angeles	Courthouse	19-F1	1	operational.	\$	3,493	\$	2,604	In Work	74.56
99	FM- 0054134	Los Angeles	Van Nuys Courthouse East	19-AX1	1	Plumbing - Water remediation, set up containment, and remove existing failed copper water supply line and replace it. Water leaking from pipe within space between floors above women's restroom.	\$	12,186	\$	10,936	In Work	89.74
	FM-	Los	Norwalk			HVAC - Replace compressors, condenser fan motor, and evaporator coil. Repair leak in the 1st stage and charge with refrigerant. This work was completed as a P1 emergency due to Package Unit #1 had a grounded compressor, the other had bad valves, and a faulty condenser fan motor. The first stage refrigerant was also flat. The evaporator coil had an internal restriction inside the metering devise.						
100	0054135	Angeles	Courthouse	19-AK1	1	The unit was not supplying cooling to the elevator mechanical room.	\$	15,610	\$	13,273	Complete	85.03
101	FM-	Los	Inglewood	10 51	1	Plumbing - Domestic hot water is not operable, no hot water to all	۲	4 000	ے ا	2 570	In Mark	74.56
101	0054179	Angeles	Courthouse	19-F1	+	public restrooms. Need to restore hot water.  HVAC / Replace motor for cooling tower #2 and diagnose VFDs for	ب ا	4,800	\$	3,3/9	In Work	74.56
	FM-	Los	East Los Angeles			Cooling Towers 1 & 2. Currently the motor has failed and could affect the cooling for the courthouse. The VFDs have been placed out of auto						
102	0054181	Angeles	Courthouse	19-V1	1	due to the trouble that must be diagnosed.	\$	10,000	\$	7,772	In Work	77.72

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST		PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						HVAC - Valve was opened to restore water flow into the cooling towers.  ACM fireproofing was abated from the central plant ceiling to install a						
						rental chiller if needed. Chiller #2 when off line due to high head						
	FM-	Los	Pasadena			pressure. The cause of the high head pressure was low water level in						
103	0054188	Angeles	Courthouse	19-J1		the cooling towers.	\$	9,263	\$	6,424	In Work	69.35
					1	HVAC - Replace condenser fan motors and blades, also installed new						
			Koorny Moso		1	wires to motors for AHU #2. Tested and placed unit back in operation.						
	FM-		Kearny Mesa	27.61	1	HVAC #2 not providing cool air. Two condenser fans went out at the	_ ا	2 412	_ ا	2 442	In Morts	100
104	0054198	San Diego	Traffic Court	37-C1	1	same time, need to replace.	>	3,413	>	3,415	In Work	100
							\$	1,855,075	\$	1,514,794	,	

Meeting Date: 12/15/2014

# **Action Item 2 – (Action Required)**

## **Summary:**

List B – Facility Modifications Less than \$50k (Priority 2)

Total Project Count:	101
Total Potential FM Budget Share of Cost:	\$895,558

# **Supporting Documentation:**

- List B Facility Modifications Less than \$50k (Priority 2)
- Supporting PowerPoint Slides

# **Action Requested:**

Ratify Judicial Council Staff preliminary decision for execution approval of List B – Facility Modifications Less than \$50k (Priority 2).

FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
		Fl Monte									
FM-0036206			19-01		•	\$	40,828	\$	23,729	Unfunded	58.12
					Safety - Prep and patch any areas of spalled concrete, prime and finish paint the						
					entire area under the soffits and the fascia/front face of the roof overhangs - The						
FM-0051815	Merced	Old Court	24-A1			\$	42,611	\$	42,611	Unfunded	100.00
					•						
		Metropolitan									
FM-0052899	Ins Angeles	<u>-</u>	19-T1			\$	31 711	ς .	29 980	Unfunded	94.54
FM-0052995	San Diego	County Courthouse	37-A1		State Fire Marshal Correction Notice items 7b, 8a, and 8b. Install four (4) pull station installations; tie-in two (2) existing tamper switches to Notifier panel; install two (2) enunciators (1 each) for Sheriff and Engineering office; install two (2) new smoke	\$	29,049	\$	22,490	Unfunded	77.42
FM-0053417	Santa Cruz	1 .				\$	7,105	\$	7,105	Complete	100.00
	San	Bernardino	36-A1	2	outside of the scuppers, install new down spouts, and install 5 roof vent caps and tighten 5 existing. 3 existing roof drains are leaking, work is needed to prevent additional roof leaks which where observed during recent torrential rains	\$	5,169	\$	4,941	Complete	95.58
					·						
		West Justice									
FM-0053419	Orange	Center	30-D1		•	\$	9,384	\$	8,509	In Work	90.68
FM-0053420	Orange	West Justice Center	30-D1		Lot to prevent further deterioration and failure due to rust. Evidence of invasive rust	Ś	8.429	Ś	8.429	ln Work	100.00
	FM-0051815 FM-0052899 FM-0053417 FM-0053418 FM-0053419	FM-0036206         Los Angeles           FM-0051815         Merced           FM-0052899         Los Angeles           FM-0052995         San Diego           FM-0053417         Santa Cruz           San         San	FM-0036206 Los Angeles El Monte Courthouse  FM-0051815 Merced Old Court  FM-0052899 Los Angeles Courthouse  FM-0052995 San Diego Courthouse  FM-0053417 Santa Cruz Room  San Bernardino Courthouse  FM-0053418 Bernardino Courthouse  FM-0053419 Orange West Justice Center  West Justice	FM-0036206 Los Angeles El Monte Courthouse 19-01  FM-0051815 Merced Old Court 24-A1  FM-0052899 Los Angeles Courthouse 19-T1  FM-0052995 San Diego Courthouse 37-A1  FM-0053417 Santa Cruz Room 44-A3  San Bernardino Courthouse 36-A1  FM-0053419 Orange West Justice FM-0053419 Orange West Justice Center 30-D1  West Justice	## PNOJECT   PNO	El Monte FM-0036206 Los Angeles Old Court Old Court Ocurrhouse FM-0052899 Los Angeles Courthouse FM-0052995 San Diego Courthouse Jury Assembly FM-0053417 Santa Cruz FM-0053418 Bernardino San Bernardino FM-0053418 Bernardino San Bernardino FM-0053419 Orange  El Monte El Monte El Monte Courthouse I9-01  Plumbing - Replace Leaking 250 Gallon Water Heater in Rm. B27 - Needed to maintain the buildings potable hot water supply to all restrooms and entire facility for the comfort and cleanliness of the court Safety - Prep and patch any areas of spalled concrete, prime and finish paint the entire area under the soffits and the fascia/front face of the roof overhangs - The underside of the existing eaves have several areas that are showing signs of the Concretor spalling that could fall onto passers-by below Electrical - Drain coolant from Generator, re-core radiator, replace, all hoses and connectors to generator, and refill with new coolant. Currently the generator wradiator is leaking coolant which is causing a safety situation if the generator were to 2 be used in an emergency and it over heats due to the coolant being low.  Fire Protection - Fire Alarm System-system has code required upgrades based on State Fire Marshal Correction Notice items 7b, 8a, and 8b. Install four (4) pull station installations; tie-in two (2) existing tamper switches to Notifier panel; install two (2) enunciators (1 each) for Sheriff and Engineering office; install two (2) enunciators (1 each) for Sheriff and Engineering office; install two (2) news smoke Post Courthouse  Pest Control - Full building termite fumigation, tenting required - termites found in 2 several locations causing structural and cosmetic damage.  Roof - Seal under interior counter flashing of (3) existing roof drain sumps, seal the outside of the scuppers, install new down spouts, and install 5 roof vent caps and tighten 5 existing. 3 existing roof drains are leaking, work is needed to prevent additional roof leaks which where observed during recent torrential rains  HA	Plumbing - Replace Leaking 250 Gallon Water Heater in Rm. B27 - Needed to maintain the buildings potable hot water supply to all restrooms and entire facility   \$	Plumbing - Replace Leaking 250 Gallon Water Heater in Rm. B27 - Needed to maintain the buildings potable hot water supply to all restrooms and entire facility for the comfort and cleanliness of the court safety. Prep and patch any areas of spalled concrete, prime and finish paint the entire area under the soffits and the fascia/front face of the roof overhangs - The underside of the existing eaves have several areas that are showing signs of the court safety. Prep and patch any areas of spalled concrete, prime and finish paint the entire area under the soffits and the fascia/front face of the roof overhangs - The underside of the existing eaves have several areas that are showing signs of the concrete spalling that could fall onto passers-by below  Electrical - Drain coolant from Generator, re-core radiator, replace, all hoses and connectors to generator, and refill with new coolant. Currently the generator radiator is leaking coolant which is causing a safety situation if the generator were to be used in an emergency and it over heats due to the coolant being low.  FM-0052899 Los Angeles  Courthouse  19-T1  2 be used in an emergency and it over heats due to the coolant being low.  County  County  County  County  County  County  And Courthouse  37-A1  2 detectors in lobby of North tower and two (2) horns / strobes in holding areas.  Pest Control - Full building termite fumigation, tenting required - termites found in several locations causing structural and cosmetic damage.  Roof - Seal under interior counter flashing of (3) existing roof drain sumps, seal the outside of the scuppers, install new down spouts, and install 5 roof vent caps and tighten 5 existing, as existing roof drains are leaking, work is needed to prevent driven centrifyal units. Both are prone to frequent dilure requiring excessive FM-0053419 Orange  Center  30-01  2 maintenance to retain operational condition.  FM-054819 Orange  Center  30-01  Courthouse  30-01  Courthouse  30-01  Courthouse  30-01  Courthouse  40-053418  Courthouse  40-0534	Plumbing - Replace Leaking 250 Gallon Water Heater in Rm. 827 - Needed to maintain the buildings protable hot water supply to all restrooms and entire facility maintain the buildings protable hot water supply to all restrooms and entire facility safety - Prep and patch any areas of spalled concrete, prime and finish plaint the entire area under the Soffiss and the facility of the court of the entire area under the Soffiss and the facility of the court of the entire area under the Soffiss and the facility of the entire area under the Soffiss and the facility of the entire area under the Soffiss and the facility of the entire area under the Soffiss and the facility of the existing eaves have several areas that are showing signs of the 2 concrete spalling that could fall onto passers-by below \$ 42,611 \$ Electrical - Drain coolant from Generator, re-core radiator, replace, all hoses and connectors to generator, and refill with new coolant. Currently the generator radiator is leaking coolant which is causing a safety stand in fit we generator were to State Fire Marshal Correction Notice Items 7b, 8a, and 8b. Install flour (4) pull station installations; tite-in two (2) existing tamper switches to the coolant by enunciators (1 each) for Sheriff and Engineering office; install two (2) new smoke 2 detectors in lobby of North tower and two (2) horns / strobes in holding areas. \$ 29,049 \$ End of the supplemental of the supplemental towards	PM-0036206 Los Angeles  El Monte FM-0036206 Los Angeles  Courthouse  19-01  Plumbing - Replace Leaking 250 Gallon Water Heater in Rm. B27 - Needed to maintain the buildings potable hot water supply to all restrooms and entire facility entire area under the scientification of the conflort and cleanliness of the court  Safety - Prep and patch any areas of spalled concrete, prime and flinish paint the entire area under the softfs and the facility on the court of the roof overhangs - The underside of the existing eaves have several areas that are showing signs of the 2 concrete spalling that could fall all onto passers-by below  Electrical - Drain coolant from Generator, re-core radiator, replace, all hoses and connectors to generator, and refill with new coolant. Currently the generator radiator is leaking coolant which is causing a safety situation if the generator were to 2 be used in an emergency and it over heats due to the coolant being low.  FM-0052899 Los Angeles  Courthouse  19-71  2 be used in an emergency and it over heats due to the coolant being low.  Fire Protection - Fire Alarm System-system has code required upgrades based on State Fire Marshall Correction Notice items 7b, 8a, and 8b. Install four (4) pull station installations; tie-in two (2) existing tamper switches to Nation grade; install two (2) enunciators (1 each) for Sheriff and Engineering office; install two (2) new smoke enunciators (1 each) for Sheriff and Engineering office; install two (2) new smoke 2 detectors in lobby of North tower and two (2) horns / strobes in holding areas.  San  San  San  San  San  San  San  Sa	### Piumbing - Replace Leaking 250 Gallon Water Heater in Rm. B27 - Needed to maintain the buildings postable hot water supply to all restroors and entire facility for the comfort and deanliness of the court    FM-0036206 Los Angeles   FM-0036206

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Lighting - Main Lobby - Arch Ceiling - Remove and retrofit 18 canned 400w mercury vapor bulbs and ballasts with new 100w LED, 5500k cluster. Currently nearly half of the bulbs are dead and in need of replacement. The lights are housed in the second floor arched ceiling and require a lift to replace the mercury vapor bulbs. LED replacement would allow change out from above lights via a catwalk. Mercury bulbs					
9	FM-0053421	Riverside	Hall of Justice	33-A3		and ballasts last approx. 20k hours, while LED will increase the life to 50k Interior Finishes - Restore damaged concrete sub floor - Perform initial ACM testing, remove a 6' X 9' section of carpet over the affected area. Remove the failing concrete section of sub floor in the 6' X 9' area. Level concrete sub floor and install	\$ 7,369	\$	7,369	In Work	100.00
10	FM-0053422	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	approximately 54SF of new carpet. All work to be performed after-hours. The damaged floor patch beneath the carpet is near the attorney's table and is a trip hazard.	\$ 5,817	\$	5,817	Complete	100.00
						Plumbing - Replace failed Sloan Flushometer. Water remediation, set up containments, Extract water from carpets throughout affected area. Disinfect/deodorize area. Set multiple dehumidifiers throughout chambers until dry. Test carpet/walls before final clean up and returned furniture back in place. Flooding					
11	FM-0053425	San Diego	County Courthouse Downtown	37-A1		occurred throughout Judges' chambers 51 and 50 and entering chambers' 38 restroom ceiling.	\$ 12,164	\$	12,164	Complete	100.00
12	FM-0053428	Santa Clara	Superior Court Salinas	43-B1	2	Vandalism - Replace 7x 3 shattered safety laminated glass at public entry.  Electrical - Install (3) 2 X 4, T-8 3-LAMP 18CELL FIXTURES in judges chamber. Judge is	\$ 1,571	\$	1,571	In Work	100.00
13	FM-0053429	Monterey	Courthouse- North Wing	27-A1		experiencing headaches from eye strain - doctors note and light readings indicate inadequate lighting in room.	\$ 3,191	\$	3,191	Complete	100.00
14	FM-0053436	Los Angeles	Stanley Mosk Courthouse East County	19-K1		Elevators, escalators, & hoist - Public elevator #3 - Remove and replace bad bearings on the generator set, the elevator is out of service due to leveling issues.	\$ 35,651	\$	34,674	In Work	97.26
15	FM-0053438	San Diego	Regional Center	37-l1		Elevators, Escalators, & Hoists - Remove existing generator, rewire and rebuild, install back into place. Elevator #3 generator needs to be rebuilt, stopped working.	\$ 13,131	\$	8,891	In Work	67.71

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
			Solano Justice			HVAC - Replace failed two ton split air-conditioning unit that cools Court IT (MDF)						
16	6 FM-0053439	Solano	Building	48-B1	2	room 118 - Work to be performed afterhours	\$	14,950	\$	14,950	In Work	100.00
			Downtown Superior			Plumbing - Replace (1) failed ejector pump motor and check valves. Pump is						
17	7 FM-0053440	Santa Clara	Court	43-B1		overflowing and flooding the basement area.	\$	8,106	\$	8,106	In Work	100.00
						Elevators, Escalators, & Hoists - Failing Motor Starter - Install new Solid State Starter,		<u> </u>				
						reducing potential damaging high inrush current and starting torque. Motor starter is						
18	8 FM-0053441	San Diego	Juvenile Court	37-E1	2	worn and failing.	\$	4,337	\$	3,236	In Work	74.62
			Edmund D. Edelman Children's			Electrical - Replace 2500 amp breaker - Currently a 2500 amp breaker at the main panel is not resetting properly, this breaker controls the power to the penthouse on the roof where the chiller plant and boiler plants are located. If the breaker trips there is high probability that it will not reset and the court will lose the cooling and			_			
19	9 FM-0053445	Los Angeles		19-Q1	2	heating to the building.	\$	18,285	\$	12,/98	Unfunded	69.99
20	D FM-0053446	Los Angeles	Edmund D. Edelman Children's Court	19-Q1		Fire Protection - Replace one set of fire doors with new 45 min rated fire doors to meet code. Currently the fire doors have a crack on the side of the doors and they do not meet the fire code.	\$	5,301	\$	3,710	In Work	69.99
		San	San Bernardino Courthouse -			Roof - Cut and reseal roof blisters. Seal multiple roof penetrations, fabricate and install (3) drain baskets, and install vent covers on 11 roof vents. This work is						
2.	1 FM-0053447		Annex	36-A2		necessary in order to prevent future roof leaks.	Ś	3,558	ς	3 403	Complete	95.64
	2 FM-0053448		South Placer Justice Center			HVAC - Install new 3 ton Split HVAC system for Electrical room E0034 - Reduce run time on 27 ton chiller by 108 hours per week	\$	11,708			In Work	100.00
23	3 FM-0053449		West Justice Center	30-D1		Grounds - Raised Concrete - Saw cut and remove approximately 105 sq. ft. of concrete sidewalk that became uneven as a result of tree roots. Remove tree roots as necessary, construct new sidewalk and apply broom finish. Trip hazard/safety risk to employees and court tenants who use sidewalk to gain access to courthouse.	\$	3,007	\$	2,727	In Work	90.68

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Exterior Shell - Replace 5 single glazed window & 2 door panes with opaque dual						
						glazed units and install 2 dual glazed doors/fame. Current conditions leave room too						
24	FM-0053450	El Dorado	Johnson Bldg.	09-E1		cold even after repeated HVAC adjustments that cannot overcome thermal loss from the exterior conditions.	ا د	11,000	ر	11 000	In Work	100.00
24	1101-0033430	Li Doi au	Johnson Blug.	03-L1		HVAC - Install a new 1.5 ton split system that serves the 2nd floor A/V room. The	٦	11,000	٧	11,000	III VVOIK	100.00
		San	  Fontana			current split system has failed, has a bad compressor as well as an un-repairable leak						
25	FM-0053452		Courthouse	36-C1		on the evaporator coil.	\$	7,241	\$	7,241	In Work	100.00
			Pomona			HVAC - Disassemble Chiller #1 and replace seals, gaskets, and O-rings. Chiller #1 leaks		,		,		
			Courthouse			thru deteriorated seals, gaskets, and O-rings. Chiller #1 is not operational due to the						
26	FM-0053454	Los Angeles	South	19-W1	2	refrigerant leaks.	\$	25,031	\$	22,813	In Work	91.14
			North County									
			Regional									
			Center -									
			Department			Roof - Install fall protection/guardrail system in areas of fall risk. The rooftop air						
27	FM-0053455	San Diego	34 Trailer	37-F4		conditioners are too close to the edge of the roof. Roof requires fall protection rails.	\$	4,489	\$	4,489	In Work	100.00
			LILLI -£			HVAC - Replace Failed Mini-split unit for Tech Print Room. Existing condenser unit has						
20	EN4 005245C		Hall of	[ A 2		failed beyond repair. Replacement parts not feasible and replacement condensing	_ ا	0.154	ے ا	0 1 5 4	In Monte	100.00
28	FM-0053456	Stanisiaus	Records North County	50-A2		unit not available with R-22 refrigerant (replacement is required).	\$ 	8,154	\$	8,154	In Work	100.00
			Regional									
			Center -									
			Department			Roof - Install fall protection/guardrail system in areas of fall risk. The rooftop air						
29	FM-0053457	San Diego	35 Trailer	37-F5		conditioners are too close to the edge of the roof. Roof requires fall protection rails.	\$	4,489	\$	4,489	In Work	100.00
			Modesto					-		-		
			Main			Plumbing - Replace failed hot water heater for main courthouse. Main tank is cracked						
30	FM-0053458	Stanislaus	Courthouse	50-A1	2	and unable to be repaired.	\$	5,310	\$	4,132	In Work	77.82
						Plumbing - Cut out all old solder fittings and failed fittings and replace with pro press						
			Manteca			fittings - Old fittings are failed and causing leaks throughout older section of	<b> </b>					
31	FM-0053462	San Joaquin	Branch Court	39-C1	2	courthouse.	\$	10,706	\$	10,706	In Work	100.00

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY	PROGRAM BUDGET SHARE OF PRELIMINARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Fire Protection - Correct deficiencies identified during 5 year system inspection and						
						Fire Marshal inspection - Remove and replace three (3) 300psi gauges, five (5) non						
			South Placer			compliant sprinkler heads, five escutcheons, fire caulk two (2) areas of wall penetration and install a hydraulic placard at the fire riser. Current installation does						
32	FM-0053470	Placer	Justice Center	31-H1		not meet code requirements	Ś	14,451	\$	14 451	In Work	100.00
32	1101 0033 170	rideer	Justice Cerrier	31 111		Fire Protection - Provide and install one (1) upgraded fire beam detector in the	Υ	11,131	<u> </u>	11,131	III VVOIK	100.00
						atrium; Provide Start-up, testing, and verification of operation; Work to be						
						performed by a specialty fire alarm company; Work to be done off hour and requires						
						a lift to access the detector location - Present beam detector creates false alarm						
		Contra	Arnason			conditions. System adjustments completed since construction have not resolved						
33	FM-0053473	Costa	Justice Center	07-E3	2	initial design deficiency.	\$	14,238	\$	14,238	In Work	100.00
						HVAC - Replace defective VFDs to the return fans on the 10th and 12th floors.						
			Compton			Currently both of the return fans are running at 100% causing air flow to be						
34	FM-0053478	Los Angeles	Courthouse	19-AG1		unbalanced and wasting energy.	\$	5,883	\$	3,890	In Work	66.13
						HVAC - Remove and Replace (1) 15 HP VFD. Currently the VFD drive is tripping on						
			Chatsworth			common lose and DC over load, effecting major operation of cooling for all floors in		- 460	_	4		00.00
35	FM-0053479	Los Angeles	Courthouse	19-AY1	2	the southeast side of the building.	\$	5,460	\$	4,5/5	In Work	83.80
			Clara			Plumbing - Shut off and drain entire building, replace duel backflow preventers and						
			Shortridge			isolation valves, restore water service to the building and restart buster pumps. The						
			Foltz Criminal			duel domestic water backflow preventers did not pass annual inspection and the						
36	FM-0053481	Los Angeles	Justice Center	19-I 1		isolation valves are bypassing water when in the close position.	\$	24,032	ς	16 532	Unfunded	68.79
	1111 0033 101	2007ge.es	Justice Cerrier	13 21	_	COUNTY MANAGED - Grounds- Remove dead grass, trees, plants, and old landscape	ļ <del>-</del>		7	10,002	• manaca	00.73
			San			materials, level mounds & holes in dirt area, and replace with gravel / dryscape to						
			Bernardino			meet current city water restrictions. Existing area is currently a trip hazard due to the						
		San	Courthouse -			unevenness of the dirt & debris and also a fire hazard due to the dead landscape and						
37	FM-0053482	Bernardino	Annex	36-A2	2	dryness of the area as a result of missing irrigation.	\$	16,375	\$	16,375	In Work	100.00
										_		
			Compton			Exterior Shell - Repair concrete and sure railing. Currently the exterior ledge railing						
38	FM-0053486	Los Angeles	Courthouse	19-AG1		located on the Westside of the building has broken concrete causing a safety hazard.	\$	4,944	\$	3,269	In Work	66.13
			Bakersfield			HVAC - Replace burnt out supply fan motor, pulley w/hub and 2 new belts.						
	ENA 0050407	W = 1112	Superior	45 44		Reconnect wiring to new motor. Burnt out supply fan motor not providing cooling to	_	2 600	_ ا	4 604	Camaral	62.64
39	FM-0053487	kern	Court	15-A1	2	AHU 04.	<b>\</b>	2,699	>	1,691	Complete	62.64

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Plumbing - Remove and replace all defective wye strainer and pressure reducer						
40	5.4.0053400		Chatsworth	40 41/4		valves. Currently the water pressure is not regulated throughout the building and	,	7.760		6 505		00.00
40	FM-0053488	Los Angeles	Courthouse	19-AY1		could cause the main pipes to break down, causing a flood.	\$	7,763	\$	6,505	In Work	83.80
						Interior Finishes - Replace defective vinyl floor tiles approx. 60 sq ft. Currently the						
	EN 4 00E 3 400		Compton	40.404		vinyl tile flooring is breaking and coming up off the floor. It is causing a trip and safety	_	2.047	۸ .	4 005		66.42
41	FM-0053489			19-AG1	2	hazard on occupants.	\$	3,017	\$	1,995	In Work	66.13
			Edmund D.			Exterior Chall Banks (2) 0/11" v 0/7" heavy duty stock rolling do one with double						
			Edelman			Exterior Shell - Replace (2) 9' 11" x 9'7" heavy duty steel rolling doors with double						
42	EN4 00E3400		Children's	10.01		angle foot piece and new motor operators with eclectic miller safety edges. Currently	۲	12 220	۲	0.200	lin Manle	CO 00
42	FM-0053490	Los Angeles	Court	19-Q1	2	the rolling doors have broken spring and are not working properly.	\$	13,239	\$	9,266	In Work	69.99
			Clara Shortridge Foltz Criminal			Fire Protection - Repair (35) pull stations that failed to activate alarm during annual test and (1) fire bell that sounded poorly. This repairs must be completed before the						
43	FM-0053491	Los Angeles	Justice Center	19-L1		annual fire alarm test can be completed due to it being a safety issue.	\$	16,375	\$	11,264	Unfunded	68.79
			County			Plumbing - Replace 20 section of failed cast iron pipe and a 10 section of copper pipe,			1			
44	FM-0053497	San Diego	Courthouse	37-A1		fittings and bands.	\$	4,173	\$	3,231	In Work	77.42
45	FM-0053498	Los Angeles	Compton Courthouse	19-AG1		Plumbing - Replace defective sump pump and test for proper operation. Currently one of the sump pumps for storm water has failed and must be replaced. Heavy rain or any other form of heavy water going into basement area could cause flooding in Basement.	\$	14,634	\$	9,677	In Work	66.13
46	FM-0053499		Clara Shortridge Foltz Criminal Justice Center	19-11		Elevator - Install generator start up controls to all 23 elevators. This installation must be completed to make sure the generator transfers power to the elevators in case of an emergency as per the State Inspector and Fire Marshall. (Compliance Issue)	ς.	6,573	\$	4 522	In Work	68.79
10	5555 455		Compton			Parking Lot - Install up to 50 feet of new 6" no hub piping. Currently the storm drain	7	3,373	7	1,522		33.73
47	FM-0053500	Los Angeles	Courthouse	19-AG1		is cracked and the water drips on the cars parked in the parking garage.	\$	5,570	Ś	3.683	In Work	66.13
			Metropolitan			HVAC - Replace shaft and bearing on Air Handler Unit #9. Currently the Air Handler is being controlled manually and the motor had to be ramped down so no further damage would take place. This repair is necessary due to this air handler provides air						
48	FM-0053501	Los Angeles	Courthouse	19-T1	2	to the entire 8th floor.	\$	11,845	\$	11,198	In Work	94.54

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET	SHARE OF PRELIMINARY FSTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
			Santa Monica			Elevators - Replace chicken legs for elevator #2 at the 2nd & 3rd floors and elevator #3 at the 3rd floor. This repair must be completed to ensure the doors close as						
49	FM-0053504	Los Angeles	Courthouse	19-AP1		intended per DIR preliminary orders.	\$	4,581	\$ 3	,596	In Work	78.49
			Betty Lou Lamoreaux			HVAC - Variable Frequency Drive (VFD) - Replace the existing 20 HP Return Fan VFD with a new ABB 20 HP VFD. The existing VFD has three blown fuses and has ceased to function properly in automatic mode. The VFD is currently in bypass mode to run at 100% capacity all the time. The VFD controls the Return Fan for AHU #8 and needs to be replaced to avoid disruption to operations and prolong the life of the equipment.						
50	FM-0053517	Orange	Justice Center	30-B1	2	Related JO 1361775.	\$	6,933	\$ 5	,543	In Work	79.95
51	FM-0053518	San Bernardino		36-C1		Roof - Leak remediation. Replace pipe seals, fabricate and install 12 drain screens, seal and coat white (2) splits, install 360LF of walk pads around mechanical equipment, vents, and drains. Replace old asphalt repairs/coat with white coating at N&S wall tie-in, 80' tie-in, (3) vent flashings, and 3 pipe flashings.	\$	11,934	\$ 9	,921	In Work	83.13
52	FM-0053519	Santa Barbara	Santa Maria Courts Building G	42-F5		HVAC - Replace failing 8.5 Ton HVAC unit (PKU 11) - PKU servicing Department 7 Courtroom is failing and no longer functioning as designed.	\$	16,207	\$ 16	,207	In Work	100.00
53	FM-0053523	Santa Barbara	Santa Barbara Jury Assembly Bldg.	42-G1	2	Elevator - Restore elevator, replace seal and install to hydraulic system casing for elevator to function properly. Elevator has a seal that broke and detached from the casing of the hydraulic system.  Electrical - Lights and Ballast - Remove and properly dispose of 15 burnt out lights	\$	2,636	\$ 2	,636	Complete	100.00
	<b>5.</b> 4. 0052525	c 5:	County			and failed ballast, and replace with new T-8 lights and ballast. Various lights are	_	6 222				100.00
54	FM-0053525	San Diego	Courthouse North County	37-A1	2	burned out in Department 28, Safety and trip hazard.	<b>\$</b>	6,232	\$ 6	,232	In Work	100.00
55	FM-0053528	San Diego	Regional Center - Vista Center	37-F2		Holding Cell - Replace touch screen. The touch screen operation is not functioning/freezes. This prevents automatic opening and closing of certain holding cell doors.	\$	10,349	\$ 10	,349	In Work	100.00
			East County Regional			HVAC - Remove and replace evaporator and condenser with new. Split unit in Civil Business Office IT room non-functional. IT equipment could be damaged due to						
56	FM-0053529	San Diego	Center	37-I1	2	excessive heat in room.	\$	5,612	Ş = 3	,800	In Work	67.71

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	CILITY ODIFICATION OGRAM BUDGET	SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Exterior Shell - Repair the exterior damaged grout of 4 existing carrot wood brick planters. Damaged or loose bricks on planters need to be repaired to prevent bodily						
57	FM-0053540	San Diego	Juvenile Court	37-E1		injury, this is an immediate safety risk.	\$	2,262	\$ 1,	688	In Work	74.62
						Interior Finishes - Set-up containment and drying equipment due to water leaking						
						into Room 202B file storage room, conduct environmental testing, replaced 2 ft of 1						
			Santa Monica	10.454		1/2" piping and fitting, replaced one 90 and coupling, repaired hangers and supports,	_	10.056				<b>-</b> 0.40
58	FM-0053541	Los Angeles	Courthouse	19-AP1		and installed new ceiling tiles.	\$	18,356	\$ 14,	108	Unfunded	78.49
			Compton			Interior Finishes - Removal and disposal of loose and flaky paint and plaster from the 12th floor N/E stairwell, replaster approximately 30 sq ft. and color match paint. This						
59	FM-0053543	Los Angeles	•	19-AG1	2	is a slip hazard at the stairway	\$	2,889	\$ 1	910	Complete	66.13
60	FM-0053544		Compton Courthouse	19-AG1		Interior Finishes - Build containment 11X6 feet and removed and replace VCT floor tiles 12x12. Repair a piece of concrete on the 9th floor 4x4 feet. Currently there are floor tiles missing and some that are ready to break causing a trip hazard. Also, a small piece of concrete has broken off causing a trip hazard.	\$	2,774	\$ 1,	834	Complete	66.13
61	FM-0053545	Orange	North Justice Center	30-C1		HVAC - Replace failing cooling tower manual Mag Starter with 40 HP ABB 3R VFD in a weather-proof enclose. The project is eligible for SCE Rebates of \$85 per HP	ر د	12 0/16	\$ 12 I	505	In Work	90.31
	FM-0053548		Annex No. 2	52-A3	2	Fire Protection - Replace four fire sprinkler heads (two corroded fire sprinkler heads, two painted fire sprinkler heads), replace the drain valve with an approved valve, and relocation of the gauges on the riser to an approved location - Annual FMS PM failed HVAC - Correct inadequate airflow resulting from additional heat load (staff and IT		3,152			In Work	100.00
63	FM-0053558	San Bernardino	San Bernardino Courthouse	36-A1		equipment) following court reductions and realignment of resources. Tie into ductwork after existing VAV. Install 35' of rigid 12" ductwork, 80' of flexible 12" ductwork, 25' of 10" flexible duct work, (1) balancing damper, (1) new VAV box with Belimo actuator, and (1) thermostat. Provide and install power from existing 120V junction box and connect to transformer. Insulate all ductwork and support all rigid duct	Ś	16,634	\$ 15	909	In Work	95.64
	333330		West Justice			HVAC - Replace the failing A/C Package Unit that serves the Sheriffs locker room and basement areas. Deterioration of the coils and indoor fan motor/compressor makes	7		7 20)			33.0.
64	FM-0053564	Orange	Center	30-D1	2	system unable to maintain space temperature.	\$	6,628	\$ 6,	010	In Work	90.68

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Parking Structure - Replacement and installation of 20 gate drains in the upper parking structure. The homeless have stolen the floor drain covers for the upper						
			Whittier			levels of the parking area. This leaves a 10 inch by 24 inch gap for each one that is						
65	FM-0053566	Los Angeles	Courthouse	19-AO1		missing on the floor. This is a safety hazard.	\$	4,745	\$	4,101	In Work	86.43
						Plumbing - Remove material surrounding elbow joint in contained environment and						
						area to be cleared per JCC/ABM protocol. Once cleared, replace leaking section of						
			Santa Maria			hot water pipe and restore area to pre-leak conditions. Leaking pipe in Depart. 2						
			Courts			Courtroom above jurors box to be replaced. Questionable material wrapping elbow						
66	FM-0053567		Building C + D	42-F1	2	joint.	\$	10,946	\$	10,946	In Work	100.00
			North County									
			Regional			Fire Protection - Refurbish 5 Fire Doors, re-wire and re-string, tighten all loose						
67	<b>514</b> 0053560		Center -	27.52		mountings and fasteners, lube all points of friction, balance and align doors. The fire	_	4.600	_	4.600		400.00
6/	FM-0053568	San Diego	Traffic Annex	37-F3		curtains are not operating. Curtains will not drop in a fire alarm event.	\$	4,699	\$	4,699	In Work	100.00
						Electrical - Change Lighting - change 6 recessed 8"x8" lights to new single tube 4'						
			County			florescent fixture in ground floor Hallways, fixture to be security type as this hallway						
60	FM-0053570		Courthouse	22 11		is used for transportation of in-custody individuals. Current lighting not compliant	۲	E 26E	۲	2 620	In Mork	67.62
00	FIVI-0053570	Mendocino	Courthouse	23-A1		with holding standards.	۶	5,365	Ş	3,028	In Work	67.62
						HVAC / Replace Pneumatic Air Compressor #3. Currently the air compressor has a						
			Stanley Mosk			seized which supplies air to the HVAC system and the building will not be able to						
69	FM-0053577		Courthouse	19-K1		control the air to the air handlers used to maintain comfort throughout the building.	\$	18,870	\$	18 353	In Work	97.26
	333377	200711160100	Salinas	13 KI	_	control the air to the air handlers used to maintain connoct throughout the sandings	-	10,070	· ·	10,000	III WOTK	37.20
			Courthouse-			Fire Protection - Replace failed NAC 4 unit on Fire Annunciator Panel. Program and						
70	FM-0053944			27-A1		perform operational testing of new NAC.	\$	3,565	\$	3,565	In Work	100.00
		1	<u> </u>			Roof - Perform a minor renovation to the buildings roof which will include repairing		•		•		
						the following components. Membrane, Blister & Drain Repairs -Main Deck. Blister &						
						Penetration Repairs -Penthouse. Pitch Pocket & Drain Repairs -Lower Decks.						
						Membrane Repair, Condensate Drain -Rear Lower Deck. Clear Leaves -Lower						
			Glendale			Canopy. Insert Membrane Blanket -Penthouse/Rear Lower Deck. Approx. 2,850						
71	FM-0053946	Los Angeles	Courthouse	19-H1	2	SQ/FT of repairs	\$	19,010	\$	17,212	Unfunded	90.54

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Roof - A minor roof renovation will be done to the following areas (Main Deck & Lower Deck). Main Deck-Coated Area of Repair, Caulk Metal Laps, Caulk Stucco,						
						Three-Course Ceramic Roof Drain, Reset Ladders. Lower Decks- Three-Course Hole in						
			Torrance			Membrane, Re-Caulk Perimeter Edge Metal, Re-Caulk Counter-Flashing. Approx.						
72	FM-0053947	Los Angeles	Courthouse	19-C1	2	2,300 SQ/FT of repairs.	\$	15,145	\$	12,894	Unfunded	85.14
						Elevators, Escalators, & Hoists - Remove and replace worn out packing. Install new						
						hydraulic packing on the jack and make sure that all leaks are addressed properly.						
						Replace and properly disposed off old oil/fill system with fresh hydraulic oil. Elevator						
			Santa Monica			#3 has a worn out/leaking hydraulic jack packing. Oil is leaking on the floor and will						
73	FM-0053949	Los Angeles	Courthouse	19-AP1		burn out the motor if leak is not corrected.	\$	6,921	\$	5,432	In Work	78.49
	EN 4 00 E 20 E 0	Calana		40.44		Electrical - Replace failed secure door lock control relay - Work to be performed after	_ ا	C 720	ے ا	C 720	La Manta	100.00
/4	FM-0053950	Solano	Hall of Justice	48-A1	2	hours with escort	\$	6,729	\$	6,729	In Work	100.00
			Arvin/ Lamont			Fire Protection - Fire curtain door at window 5 tension wheel assembly replaced and						
75	FM-0053951		Branch	15-H1		installed onto shutter. Fire curtain at window # 5 in clerk's office will not open.	Ś	2,731	Ś	1.663	Complete	60.91
			Fremont Hall			Remove and replace failed twenty five horsepower motor for the pneumatic tube	7		1			
76	FM-0054040	Alameda	of Justice	01-H1		transport system blower - Work to be performed after hours.	\$	14,845	\$	11,787	In Work	79.40
						Roof - A minor roof renovation will be done to the following areas Pitch Pan Repairs,						
			Chatsworth			Roof Drain Repairs & Remove Loose Granules. Approx. 3,500 SQ/FT of repairs / Roof						
77	FM-0054042	Los Angeles	Courthouse	19-AY1	2	is in fair condition at best.	\$	23,482	\$	19,678	Unfunded	83.80
			Carol Miller			HVAC - Replace pillow block bearings for cooling tower fan - Chillers cannot run						
/8	FM-0054044	Sacramento	Justice Center	34-D1		without cooling tower fan, chillers trip out on high head	\$	3,583	\$	3,502	In Work	97.75
						HVAC - Secure HVAC vent with additional ceiling hangers and replace broken ceiling						
70	FM-0054049	San Diego	Juvenile Court	  27_F1		tiles in grid. The ceiling air vent outside of D-5 in public corridor are loose and at risk of falling, this is a safety concern.	خ	2,682	ر	2 001	In Work	74.62
73	1101-0034049	Jan Diego	Juverille Court	37-LI	۷	or failing, this is a safety concern.	٦	2,002	٦	2,001	III VVOIK	74.02
						Grounds and Parking Lot - Relocate (3) irrigation controllers (currently without						
						power). Install (1) new 24 zone controller to serve all zones and tie to JCC controlled						
						electrical circuit. The existing controllers are located in County managed areas and						
						are powered by County circuits. Power has been disrupted for almost 4 weeks as a						
		San	Fontana			result of County work. The landscaping is currently dying and will result in significant						
80	FM-0054056	Bernardino	Courthouse	36-C1	2	replacement costs if the irrigation system is not restored soon.	\$	4,475	\$	3,720	In Work	83.13

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Interior Finishes - Remove approximately 270 sq. ft. of lead-based and non-lead-based paint at areas of efflorescence and wall damage in Library and DCSS office.						
						Perform clearance test of abated areas to ensure no lead paint left behind. Patch and paint approximately 350 sq. ft. of wall space - Moisture intrusion through outside						
			Firebaugh			wall from sprinkler system has caused efflorescence and wall damage. Environmental						
81	FM-0054064	Fresno	Court	10-K1		tests have been conducted and are attached.	\$	6,575	\$	3,815	In Work	58.02
			New San									
			Andreas			Elevator - Elevator #4 stuck in basement with entrapment, Documentation SWO only,	١.		١.			
82	FM-0054066	Calaveras	Courthouse	05-C1		work completed on 7/29/2014	\$	2,812	\$	2,812	Complete	100.00
			Nowth Luctice			HVAC- Replace the failed Variable Frequency Drive (VFD) for Air Handler Unit #5 with						
83	FM-0054067		North Justice Center	30-C1		a new 20 HP ABB VFD with Johnson NE, Siemens FLN, MODBUS RTU, and BACNET Controls embedded in drive.	ر	6,222	\$	5 610	In Work	90.31
83	1101-0034007	Orange	Center	30-61		Roof - Perform immediate maintenance requirements. Replace Missing Vent Caps.	7	0,222	٧	3,013	III VVOIK	50.51
						Approx. 200 SQ/FT of repairs. / Roof is in poor condition. Immediate removal &						
			Alhambra			replacement is recommended. IF removal & replacement is not done, immediate						
84	FM-0054068	Los Angeles	Courthouse	19-I1	2	maintenance is strongly recommended.	\$	2,247	\$	1,932	In Work	86.00
85	FM-0054069		Airport Courthouse	19-AU1		Roof - Perform a minor renovation to the buildings roof which will include repairing the following components. Re-Caulk Lead Flashings, Clear Loose Granules From Roof Surface, Repair Expansion-Joint Hole & Re-Tighten Roof Drains. Approx. 1,500 SQ/FT of repairs / Roof system is in poor to fair condition at best.	\$	10,011	\$	7,725	In Work	77.17
		<u> </u>										
			County			HVAC - Replace failing blower motor and place system back in service. Motor is failing						
86	FM-0054071	San Diego	Courthouse	37-A1		and needs to be replaced before it fails. This units supplies D-24 and D-25.	\$	3,434	\$	3,434	In Work	100.00
			Modesto			Safety - Carpet: Remove knock down strips - re-stretch carpeting in courtrooms 1 and						
07			Main	EO 41		2 and replace knockdown with rubber molding - The carpet is bunching up causing a	ے ا	2 276	۲	2 276	In Mort	100.00
8/	FM-0054075		Courthouse George D.	50-A1		potential trip hazard	<b>&gt;</b>	3,276	<b>&gt;</b>	3,2/6	In Work	100.00
			Carroll									
88	FM-0054085		Courthouse	07-F1	2	HVAC - Replace Qty 1 failing burning on boiler #2 - The burner is a safety issue	\$	4,616	\$	3,462	In Work	74.99

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY MODIFICATION	SHARE OF PRELIMINARY	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						HVAC - Removed damaged Variable Frequency drive for cooling tower #1 50 HP fan motor. Replace with new Drive ABB Model # ACH550-UH-072A-4 - Variable						
			Juvenile			Frequency drive controls fan speed which regulates the water temperature required						
89	FM-0054090	Sacramento		34-C2		for chillers to function correctly.	\$	8,211	\$	8,211	In Work	100.00
			Van Nuys			HVAC - Repair (3) non-functioning domestic hot water boilers. Currently there is no	<u> </u>	,				
			Courthouse			hot water supply throughout the entire building. This includes showers and faucets,						
90	FM-0054091	Los Angeles	West	19-AX2	2	not allowing judges and employees to shower.	\$	4,999	\$	4,023	In Work	80.48
						HVAC - Remove pump and pump motor for heating water system. Install new viton						
			Fresno County			pump seal, sleeve the seal race and remove grease from the motor. Reinstall pump						
91	FM-0054093	Fresno	Courthouse.	10-A1	2	and pump motor - Pump had failed and was badly leaking.	\$	2,895	\$	2,777	In Work	95.91
						Plumbing / Replace malfunctioning toilet in 5th floor lock up area. Inmate clogged						
			Torrance			the toilet and flooded the lock up area on the 5th floor and water ran down to the						
92	FM-0054099	Los Angeles	Courthouse	19-C1		4th floor Dept P courtroom.	\$	2,325	\$	2,325	Complete	100.00
						Interior Finishes / Replace broken and loose floor tiles in the 1st floor snack bar.						
			Compton			Currently the floor tiles are beginning to break and loosen up from the floor creating			_			
93	FM-0054112	Los Angeles	Courthouse	19-AG1	2	a trip hazard to the staff and the public.	\$	4,844	\$	3,203	In Work	66.13
			Carreti			Elevators, Escalators, & Hoists - Replaced step roller wheels and tightened up guide						
0.4			County	27 11		plates. Escalator 2-3 is thumping in operation, step roller wheels need replacement.	۲	2 252	۲	1 7/12	Complete	77.42
94	FM-0054117		Courthouse New Santa	37-A1		Loose guide plates are tearing up step rollers.	۶	2,252	Ş	1,/43	Complete	77.42
			Barbara									
			Criminal			Grounds and Parking Lot - Parking Lots A, B & C - Install Safety Lighting -						
95	FM-0054125			42-M1		Safety/Security for Court Staff in JCC-managed Parking Lots	ς .	4,000	ς	4 000	In Work	100.00
	111 0004120		Coartifloase	12 1711		Holding Cells - Rehabilitate a large section of wall in the detention hallway that	-	1,000	7	1,000	III VVOIR	100.00
						exhibits large cracks. There are approximately 32LF of large random cracks that need						
			West Justice			to be filled with Slka 31 Epoxy Grout. This work is to be completed during non-						
96	FM-0054127			30-D1		working	\$	3,500	\$	3,500	In Work	100.00

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		TCFMAC FUNDED COST	FACILITY	MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
						Elevator - Install (1) emergency battery back-up power supply unit for the 110 volt						
						elevator cab lighting circuit on each elevator. The installation will entail the mounting						
						of the power supply unit on the elevator car top, piping and wiring between the						
			A U			power supply unit and the emergency light fixture mounted in the ceiling area of the						
07	FM-0054128		Alhambra	19-I1		elevator cab, and piping and wiring to the car top alarm bell. This unit will activate	ر	15,819	۲	12 604	Unfunded	86.00
97	FIVI-0034128	LOS Aligeles	Courtilouse	19-11		during loss of supply power to the emergency light and emergency alarm bell Plumbing - Replace cracked 3 bolt toilet with 4 bolt toilet. The toilet was cracked and	<u>ې</u>	15,619	Ş	15,004	Omanaea	80.00
			Torrance			was about to break off the wall and needed to be replaced for the safety of the						
98	FM-0054138	Los Angeles		19-C1		visitors to the restroom.	\$	4,821	\$	4.105	In Work	85.14
			Downey			Elevators, Escalators, & Hoists - Dismantle generator, remove, rebuild, and		,	†	,		
99	FM-0054180	Los Angeles	Courthouse	19-AM1	2	reassemble. Elevator #3, generator #2 failed and needs to be rebuilt.	\$	37,042	\$	31,004	Unfunded	83.70
			Monrovia			Roof - Install guardian roof railing system including (30) ground plates, (15) 10 safety						
			Training			rails, (11) 6 safety rails & painted safety striping to comply with Cal-OSHA fall						
100	FM-0054183	Los Angeles	Center	19-N1		protection / Current roof is missing guard rails for fall protection.	\$	24,539	\$	17,248	Unfunded	70.29
						Grounds and Parking Lot - Remove approximately 1,620 SF of existing 6 inch						
						concrete, re-grade for bus clearance and water flow, pour new 6 inch thick concrete						
						with No. 4 rebar at 18 inch on center in both directions at 4,000 PSI. Existing						
			Nouth Listin			Driveway is steep and uneven. The Sheriff bus scrapes along the driveway every day						
101	EN4 00E419E		North Justice	30-C1		as it drives into/out of the bus bay. Water run-off from the street pools along the bottom of the driveway contributing to the deficiency.	ر	22 010	ر	20 E/11	Unfundad	90.31
101	FM-0054185	Oralige	Center	30-C1		polition of the universal contributing to the deficiency.	٦	33,818	<u>ې</u>	50,541	Unfunded	30.31
							\$ 1	,037,299	\$	895,558		



## **Action Item 3 – (Action Required)**

#### **Summary:**

List C – Cost Increases Over \$50k

Total Project Count:	3
Total Potential FM Budget Share of Cost:	\$586,442

#### **Supporting Documentation:**

- List C Cost Increases Over \$50k
- Supporting PowerPoint Slides

#### **Action Requested:**

Approve Judicial Council Staff recommendation to execute projects on List C – Cost Increases Over \$50k.

FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF TCFMAC FUNDED COST	CURRENT COST ESITMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF CURRENT COST ESTIMATE	NOTES	MODIFI	PROGRAM COST INCREASE JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
1 FM-0050012 2 FM-0045271	Los	Fresno County Courthouse Compton Courthouse		Electrical - Replace 50 year old emergency generator with new 500KW system - Generator is beyond useful life and is no longer serviceable due to age; existing unit is not capable of supporting current building requirements in an emergency situation  HVAC - Remove and replace four each 14 year old non-compliant boilers on the 13th floor, due to AQMD regulations, failure to replace these boilers will lead to heavy daily fines; HEATING HOT WATER BOILERS, 2 @ 4.1 Million BTU and 2 @ 2.8 million BTU	\$ 1,900,000		\$ 2,121,404 \$ 1,150,000		Cost increase due to final design and bid process and commissioning requirements.  Project scope initially included 4 boilers. Each ranging between 3.5M and 5.5M BTU. Since project approval, South Coast Air Quality Management District has issued a notice of correction forcing the project schedule to escalate. Project was designed to limit future exposure to SCAQMD rules by limiting boiler size. This resulted in additional smaller boilers and piping being installed. Also, units required special handling and additional labor to move to the roof due to lack of access for crane or helicopter lifts.		221,404 In Work 250,038 Complete	100.00
3 FM-0053416	Los Angeles	Glendale Courthouse	19-H1	HVAC - Compressor #1 is not running at it ful capacity due to oil leak. Compressor #2 is no functioning and has tripped the main power supply to the compressor. Currently certain areas of the building are warm and will be affected later in the day.		\$ 25,000	\$ 140,000	\$ 140,000	Installation of temporary cooling equipment and additional MCS Controller, pressure sensors and temperature sensors discharge and suction, oil and air presure sensors. Conduit and wiring for new controller as well were required in order to permanently restored operational capacity.	\$	115,000 In Work	100.00
					\$ 2,696,900	\$ 2,435,457	\$ 3,411,404	\$ 3,021,899		\$	586,442	

### **Action Item 4 – (Action Required)**

#### **Summary:**

List D – Facility Modifications Over \$50k

Total Project Count:	12
Total Potential FM Budget Share of Cost:	\$11,933,621

#### **Supporting Documentation:**

- List D Facility Modifications Over \$50k
- Supporting PowerPoint Slides

#### **Action Requested:**

Approve Judicial Council Staff recommendation to execute projects on List D – Facility Modifications Over \$50k.

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	M BUDG	CUMULATIVE TOTAL OF	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
	ΓN 4		Municipal Court			HVAC - Replace Ten (10) failed hot water reheat coils, associated valves								
	FM- 0054074	San Mateo	Building - Northern Branch	41-C1	2	and piping at New Wing side - Active and temporarily remediated leaks at (7) coils; (3) additional coils clogged and inactive	\$	88,703	\$	73,810	\$	73,810	55	83.21
	SWO-	Los Angeles	Edmund D. Edelman Children's Court - Parking	10.02		Elevator - Elevator Renovation - Complete renovation of two (2) traction and one (1) hydraulic elevators. Work will include but not be limited to, car frames and platforms, buffers and safeties, hoistway entrance frames, doors and pit equipt., new AC gearless machines, micro-processor control systems, regenerative VVVF AC drives, fly ball govenors, current code required wireing, interior and lobby control panles, car and hall door panels with new doors, counterwieghts and roller guides, hoist and govenor ropes, cab ceilings with LED down lights, rope compensation, new submersible pump units and underground cylinders encased in PVC for hydraulic elevators, and seismic provisions. Install new machine room air	<b>.</b>	024.670	¢	747 726	ć	924 546		90.00
2	1368822	Los Angeles	Structure	19-Q2	2	conditioning.  Exterior Shell - Replace the failed outdoor steel staircase, guardrails, and	\$	934,670	\$	747,736	\$	821,546	55	80.00
	FM-		Hayward Hall of	04.54		hand rails, with an industrial aluminum staircase, guardrails, and hand rails, located outside of the basement mechanical room - Rusted to a	<b>4</b>	F2 022	<b>A</b>	40.010		060.100		22.22
	0054046 FM-	Alameda	Justice  Wakefield Taylor	01-D1	2	HVAC - Remove and dispose of existing cooling tower; Re-slope and re-roof 800 sq ft of roofing; Install one (1) new 227 ton cooling tower.  Provide and install 40 LF of 8 steel piping and 20 LF of 1 copper piping including fittings, valves and supports; Provide a new VFD; Connect cooling tower to the existing BAS. Work requires a crane and is to be done off hours - Existing Cooling tower is rotting and leaking. The water pools	\$	52,822	\$	46,642	\$	868,188	55	88.30
		Alameda	·	07-A2	2	on the roof due to slope problems.	\$	429,416	\$	429,416	\$	1,297,604	57	100.00

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CHAIN ATIVE TOTAL OF		TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
FM- 5 00534 FM-		Contra Costa	Danville District	07-F1	2	HVAC - Remove and replace one (1) 40 Ton roof top condenser, (1) 40 Ton indoor condenser, and (4) 10 ton scrolls and heat exchanger; removal and replacement of (16) seismic spring isolators, (2) water pumps, (2) 3 triple duty valves and suction diffusers and (6) 3 flex connections, (2) thermometers and pressure gauge valve kits, (2) 1 1/4 and 1 3/8 flex connections, (1) Pot Feeder, (100) LF of 3 chilled water piping and (100) LF of refrigerant piping; New refrigerant Leak detection system HVAC - Remove and dispose of (4) failing rooftop AHUs; Install (4) new units, (1) 7.5 ton, and (3) 12.5 ton; Install 4 new roof curbs; Install (4) economizers and (4) smoke detectors; Install and wire (4) new thermostats (200 ft of wire); Modify 240 sq ft of ductwork to fit new units; Requires a crane and off hours installation Units are past useful life and	\$ 567,603	425,645	\$	1,723,249	58	74.99
6 00534 FM- 7 00493		Contra Costa  Los Angeles	Stanley Mosk Courthouse	07-C1 19-K1		Elevator - Elevator Renovation - Complete renovation of eight (8) gearless traction elevators, six 3,000 lb capacity and two 8,000 lb capacity. Work will include but not be limited to, car frames and platforms, buffers and safeties, hoistway entrance frames, doors and pit equipt., new AC gearless machines, micro-processor control systems,regenerative VVVF AC drives, fly ball govenors, closed loop heavy duty high speed operators, current code required wireing, interior and lobby control panles, counterwieghts and roller guides, hoist and govenor ropes, cab ceilings with LED down lights, rope compensation and seismic provisions.	294,518 3,851,000	\$ 294,518 3,745,483	\$	2,017,767 5,763,250	59 62	97.26
FM- 8 00539		San Francisco	Civic Center	38-A1		HVAC - Replace the upper section of the heating hot water (HHW) and chilled water (CHW) coils on AHU #4, balance the supply fan (SF) on air handler (AHU) #3, increase the max CFM from 75% to 100%, achieve duct static pressure from 1.13" to 1.5", and provide vibration analysis report.	\$ 57,707	\$ 57,707	\$	5,820,957	70	100.00

FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	EACH ITY MODIEICATION	/ 7	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
FM- 0035537		Pasadena Superior Court	19-J1	2	Elevator - Elevator Renovation - Complete renovation of five (5) traction and two (2) hydraulic elevators. Work will include but not be limited to, car frames and platforms, buffers and safeties, hoistway entrance frames, doors and pit equipt., new AC gearless machines, micro-processor control systems, regenerative VVVF AC drives, fly ball govenors, closed loop heavy duty high speed operators, current code required wireing, interior and lobby control panles, counterwieghts and roller guides, hoist and govenor ropes, cab ceilings with LED down lights, rope compensation, new submersible pump units and underground cylinders encased in PVC for hydraulic elevators, and seismic provisions. Provide new air conditioning to the machine rooms.	\$ 3,893,560	\$	3,163,518	\$ 8,984,474	70	81.25
FM- 0053472	Los Angeles	West Covina Courthouse	19-X1	2	County Managed - HVAC - Install four ductless air-conditioning systems in hallway to ensure the court with adequate cooling in a consistent warm part of the building throughout the year.	\$ 84,255		84,255	\$ 9,068,729	70	100.00
FM- 0011923	San Diego	East County Courthouse	37-I1	2	Elevator - Elevator Renovation - Complete renovation of ten (10) gearless traction elevators. Work will include but not be limited to, car frames and platforms, buffers and safeties, hoistway entrance frames, doors and pit equip., new AC gearless machines, micro-processor control systems, regenerative VVVF AC drives, governors (elevators 1,2&3 only), closed loop heavy duty high speed operators, current code required wiring, interior and lobby control panels, counterweights and roller guides (Elevators 7&9 only), hoist and governor ropes, cab ceilings with LED down lights, rope compensation and seismic provisions.	\$ 3,494,260	\$	2,817,422	\$ 11,886,151	75	80.63

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
						Interior Finishes - Remove existing window film where necessary, clean interior glass surface, and install high performance window film to 433					
						panels of glass on south, east, and west facing exterior windows. The					
						window tinting throughout the building is faded, torn in places, has etched					
						graffiti in places, and is in generally poor shape. Installation of new					
	FM-		North Justice			window tint is an energy-cost saving project. SCE is currently offering					
12	0053546	Orange	Center	30-C1	2	rebates up to \$1.35 per square foot.	\$ 52,563	\$ 47,470	\$ 11,933,621	82	90.31



## **Action Item 5 – (Action Required)**

#### **Summary:**

List F – Court-Funded Facilities Requests (Facility Modifications)

#### **Supporting Documentation:**

- List F Court-Funded Facilities Requests (Facility Modifications)
- Supporting PowerPoint Slides

#### **Action Requested:**

Approve Judicial Council Staff recommendation to execute projects on List F – Court-Funded Facilities Requests (Facility Modifications).

ITEM #	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	REQUEST TYPE	CFR DESCRIPTION	CFR TERM	FUND SOURCE	ESTIMATED CURRENT YEAR	COSTS FY 14-15 (Includes existing costs prior to CFR term)	ESTIMATED BUDGET YEAR COSTS	ESTIMATED TOTAL CFR COMMITMENT (CFR Term)	REVIEW NOTES - Real Estate and Facilities Management, Capital Program, and Finance
1	19-CFR024	Los Angeles	Multiple	e Multiple	FM	One-Time	Electrical upgrades at El Monte Courthouse and Stanley Mosk Courthouse. These upgrades are deemed urgent because they are needed to support the new case management system.	NA	Operating Budget	\$	225,000	0	\$ 225,000	No Concerns
	11-CFR003			Resource Center			(Utility costs are court funded) Lease extension from 5/1/2015-12/31/2016. The leased space houses the Family Court Facilitator, FCS Mediator, Self Help Center and court records storage. This request is considered urgent because this space is needed until the new courthouse is completed, estimated completion date is 10/31/16.		CCF for Lease Costs, Operating Budget for Utility Costs	\$	-		\$ 129,533	No
									·	\$			\$ 354,533	



### **Action Item 6 – (Action Required)**

#### **Summary:**

Review and discussion of the *Annual Report of the Trial Court Facility Modification Advisory Committee for Fiscal Year 2013-2014*.

#### **Supporting Documentation:**

- Draft Annual Report
- Supporting PowerPoint Slides

#### **Action Requested:**

Provide input and additions to draft document post court comment and approve release to E&P upon revision.

## Annual Report of the Trial Court Facility Modification Advisory Committee for Fiscal Year 2013-2014

- 1. Posted for Court comment on Dec 9, 2014.
- 2. Court comment closure date is December 19, 2014.
- 3. No specific comments on report received to date.
- 4. Targeted for January JCC Meeting.

# Annual Report of the Trial Court Facility Modification Advisory Committee for Fiscal Year 2013-2014

## **Action Requested:**

- 1. Provide input and additions to draft document post court comment.
- 2. Approve release to E&P upon revision.