

TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

OPEN MEETING WITH CLOSED SESSION AGENDA

Open to the Public Unless Indicated as Closed (Cal. Rules of Court, rule 10.75(c)(1))

OPEN PORTION OF THIS MEETING IS BEING RECORDED

Date: January 15, 2016 **Time:** 10:00 AM - 4:00 PM

Location: Sacramento/Teleconference for Public Access **Public Call-in Number:** 1-877-820-7831 Listen Only Code: 4502468

Meeting materials for open portions of the meeting will be posted on the advisory body web page on the California Courts website at least three business days before the meeting. Agenda items are numbered for identification purposes only and will not necessarily be considered in the indicated order.

OPEN MEETING (CAL. RULES OF COURT, RULE 10.75(C)(1))

Call to Order and Roll Call 10:00 AM

Approval of Minutes

Approve minutes of the December 7, 2015 Trial Court Facility Modification Advisory Committee meeting.

II. ACTION ITEMS (ITEMS 1-9)

Action Item 1 – (Action Required) – List A – Emergency Facility Modification Funding (Priority 1)

Summary: Ratify emergency facility modifications from List A.

Action Requested: Staff recommends 27 projects for a total of \$431,550 to be paid from funds

previously encumbered for emergency funding.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action Item 2 – (Action Required) – List B – Facility Modifications Less than \$50K (Priority 2)

Summary: Ratify facility modifications less than \$50K from List B.

Action Requested: Staff recommends 56 projects for a total of \$459,491 to be paid from funds

previously encumbered for facility modifications less than \$50K.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action Item 3 - (Action Required) - List C - Cost Increases Over \$50K

Summary: Ratify facility modifications requiring cost increases over \$50K from List C. **Action Requested:** Staff recommends five projects for a total cost increase to the Facility Modification program budget of \$304,680.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action Item 4 – (Action Required) – List D – Facility Modifications Over \$50K

Summary: Review recommended facility modifications over \$50K from List D.

Action Requested: Staff recommends 15 projects for a total cost to the Facility Modification Program Budget of \$2,844,759 with items #5 and #10 – FM-0055034 and FM-0057213 respectively being held for shared cost approval.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action Item 5 – (Action Required) – Energy Efficiency Projects

Summary: Review recommended energy efficiency facility modifications from List D.

Action Requested: Staff recommends three projects – items #16, 17, & 18 on List D – for a total cost to the Facility Modification Program Budget of \$139,830.

Presenter: Ms. Laura Sainz, Environmental Compliance & Sustainability Manager

Action Item 6 – Action Required) – List E – Court-Funded Facilities Requests (Facility Modifications)

Summary: Review Court-Funded Facilities Requests (Facility Modifications) from List E.

Action Requested: Staff recommends two CFRs for review and approval.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action Item 7 – (Action Required) – TCFMAC 2016 Annual Agenda

Summary: Review draft TCFMAC 2016 Annual Agenda.

Action Requested: Provide input and additions to draft document and approve release to E&P upon revision.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action Item 8 – (Action Required) – Quarterly Activity Report, Quarter 2 of Fiscal Year 2015-2016

Summary: Review and discuss the draft *Trial Court Facility Modification Advisory Committee Activity Report for Quarter 2, Fiscal Year 2015-2016.*

Action Requested: Provide input and additions to draft document and approve release to E&P upon revision.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Action Item 9 – (Action Required) – Fiscal Year-End Process for Court-Funded Facilities Requests

Summary: Review and discussion of FY 15-16 CFR processing deadlines and overview of how the program has progressed this year.

Action Requested: Staff recommends approving the recommended year-end CFR deadline of

March 14, 2016.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

III. DISCUSSION ITEMS (ITEMS 1-5)

Discussion Item 1 – Water Conservation Efforts Update

Summary: Update on water conservation policy implementation efforts.

Presenter: Ms. Laura Sainz, Environmental Compliance & Sustainability Manager

Discussion Item 2 – List F – Funded Facility Modifications on Hold

Summary: Review and discuss projects that have previously been funded by the committee, but that are on hold for various reasons.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager

Discussion Item 3 – Placer Arraignment Court Project Update

Summary: Overview of facility modification progress to build arraignment court in Placer

County, previously funded by the committee in January 2015.

Presenter: Mr. Nick Turner, Regional Manager

Discussion Item 4 - Seismic Study

Summary: Overview of Seismic Study findings previously introduced to the committee in April

2015.

Presenter: Mr. Jim Mullen, Senior Facilities Risk Manager

Discussion Item 5 – Prioritization Methodology

Summary: Update on revisions to Prioritization Methodology/Implementation Guideline.

Presenter: Mr. Patrick McGrath, Facilities Operations Manager, and Mr. Ken Levy, Attorney, Legal Services

IV. INFORMATION ONLY ITEMS (ITEMS 1-3)

Information Item 1 – Court Facilities Trust Fund Report on Q2 Expenditures

Summary: Informational report on FY 15-16 Q2 expenditures from CFTF.

Information Item 2 – Report on Budget Reconciliation

Summary: Informational report on FY 15-16 budget reconciliation and spending plan, as well as completed and canceled facility modifications during the reporting period.

Information Item 3 – Judge So's memorandum on Deadlines for Judicial Council-Sponsored Legislation

Summary: Memorandum from Judge So for all JCC committees on the timelines associated with the submittal of legislative proposals for possible Judicial Council sponsorship in 2017, together with the timeline for this year.

V. ADJOURNMENT

Adjourn to Closed Session



TRIAL COURT FACILITY MODIFICATION ADVISORY COMMITTEE

MINUTES OF OPEN MEETING WITH CLOSED SESSION

December 7, 2015 12:00 p.m. – 1:30 p.m. Teleconference

Advisory Body Members Present:

Hon. Donald Cole Byrd, Chair, Hon. William F. Highberger, Vice-Chair, Hon. James L. Stoelker, Hon. Vanessa W. Vallarta, Hon. Jennifer K. Rockwell, Ms. Jeanine D. Tucker, Ms. Linda Romero Soles, and Ms. Christina M. Volkers

Advisory Body Members Absent:

Mr. Michael M. Roddy, Hon. Brad Hill, and Hon. Patricia Lucas

Others Present:

Mr. Curt Soderlund, Mr. Gerald Pfab, Mr. Patrick McGrath, Ms. M.R. Gafill Malloy, Mr. Nick Turner, Mr. Ken Kachold, Mr. Dan Hutton, Ms. Angela Guzman, Ms. Eunice Calvert-Banks, Mr. Kenneth Levy, Mr. Paul Menard, Mr. Brad Boulais, Ms. Karen Baker, Mr. Price Eres, Ms. Jamie Nguyen, Mr. Robert Cresswell and Ms.

Hilda lorga

OPEN MEETING

Call to Order and Roll Call

The chair called the meeting to order at 12:05 p.m. and took roll call.

Approval of Minutes

The advisory body reviewed and approved the minutes of the October 23, 2015 Trial Court Facility Modification Advisory Committee meeting.

PUBLIC WRITTEN COMMENT

No public comments were received.

ACTION ITEMS (ITEMS 1-6)

Action Item 1 – (Action Required) – List A – Emergency Facility Modification Funding (Priority 1)

Summary: Ratify emergency facility modifications from List A.

Action: Reviewed and ratified 36 projects for a total of \$714,778 to be paid from funds previously encumbered for emergency funding.

Action Item 2 – (Action Required) – List B – Facility Modifications Less than \$50K (Priority 2)

Summary: Ratify facility modifications less than \$50K from List B.

Action: Reviewed and ratified 144 projects for a total of \$1,558,464 to be paid from funds previously encumbered for facility modifications less than \$50K.

Action Item 3 – (Action Required) - List C – Cost Increases Over \$50K

Summary: Ratify facility modifications requiring cost increases over \$50K from List C.

Action: Reviewed and ratified four projects to receive cost increases. FM-0044237 was partially approved at this meeting for \$1.2 million. The remainder will be reviewed at a subsequent meeting date. The total cost increase to the Facility Modification Program Budget for all four projects is \$1,497,778.

Action Item 4 – (Action Required) - List D – Facility Modifications Over \$50K

Summary: Review recommended facility modifications over \$50K projects from List D.

Action: Reviewed and approved 16 projects for funding for a total cost to the Facility Modification Program Budget of \$3,477,639.

Action Item 5 – (Action Required) – List E – Court-Funded Facilities Requests (Facility **Modifications**)

Summary: Review Court-Funded Facilities Requests (Facility Modifications) from List E.

Action: Reviewed and approved five Court-Funded Facilities Requests, including Alameda Superior Court's request for a self-help center conversion (\$20,000); Courtroom modifications at Fresno Superior Court (\$22,686); Building assessments for Orange Superior Court (\$80,694); Entry modifications (Phase I) for San Bernardino Superior Court (\$19,300); and a Small Projects Annual Budget for San Francisco Superior Court (\$120,000).

Action Item 6 – (Action Required) – CFR Approval Authority

Summary: Review staff findings from committee's direction to mitigate delays in the execution of the CFR process.

Action: The committee directed staff to (1) develop a proposal for changes to small project budget values, and (2) engage all approval processes in parallel.

DISCUSSION ITEMS (ITEMS 1-4)

Discussion Item 1

Summary: Reviewed List F – Funded Facility Modifications on Hold. As of this meeting, there are 32 projects on hold with a total Facility Modification Program Budget Share of \$12,350,124. These projects are primarily on hold pending county share of funding commitment or a project manager assignment.

Discussion Item 2

Summary: Reviewed and discussed fines distribution examples as they relate to the facilities program. Court fines fund capital construction and facility modifications.

Discussion Item 3

Summary: Judicial Council staff gave an overview of the Judicial Council office consolidation. The Burbank office is scheduled to close in June 2017; satellite offices will close as leases expire before then. Facilities Management staff will be placed within court facilities, if they are not there already.

Discussion Item 4

Summary: Judicial Council staff indicated that the January 15, 2016 TCFMAC meeting will be held in a different room in the same building in Sacramento due to Judicial Council conference room meeting conflicts. Further details will be provided closer to the meeting date.

INFORMATION ONLY ITEMS (No ACTION REQUIRED)

Approved by the advisory body on _____.

Information Item 1

Summary: Informational report on FY 15-16 budget reconciliation and spending plan, as well as completed and canceled facility modifications during the reporting period.

ADJOURNMENT

There being no further open meeting business, the meeting was adjourned at 1:16 p.m.	

Meeting Date: 1/15/2016

Action Item 1 – (Action Required) - List A – Emergency Facility Modification Funding (Priority 1)

Summary:

List A – Emergency Facility Modification Funding (Priority 1)

Total Project Count:	27
Total Potential FM Budget Share of Cost:	\$431,550

Supporting Documentation:

• List A - Emergency Facility Modifications (Priority 1)

Action Requested:

Staff recommends 27 projects for a total of \$431,550 to be paid from funds previously encumbered for emergency funding.

FM NUMBER	EM NUMBER LOCATION FACILITY NAME BUILDING ID		PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST	
1 514 0057440	l aa Awaalaa	Compton	10.461	4	Plumbing - Replace 20' of 2" Black cast iron pipe & fittings under ACM conditions. Employee restroom drain	Ć 42 040	Ć0 420	Camadaka	66.12
1 FM-0057118	Los Angeles	Courthouse	19-AG1	<u> </u>	line cracked and leaked from 2nd flr to ground level. Plumbing - Replaced approx. 15 ft. of 2 inch black cast iron drain piping. Replace (30) 12x12x 5/8 damage	\$ 13,819	\$9,139	Complete	66.13
2 FM-0057119	Los Angeles	Norwalk Courthouse	19-AK1	1	ceiling tiles and remediate water damage. Water is dripping from 4th floor ceiling inside Department J Courtroom.	\$ 12,561	\$12,561	In Work	100
					Plumbing - Replace 4' of failed 6" ductile piping on the incoming main fire supply line. Excavate 7'x10' area to				
					provide access and remediate water damage once replacement line is installed. Work is immediately				
2 514 0057425		Pasadena	40.14	4	adjacent to 480 electrical supply lines so special cutting equipment is required during installation. Work is	¢ 75 400	ć52.002		60.25
3 FM-0057125	Los Angeles	Courthouse New San	19-J1	1	required to maintain fire system in the facility.	\$ 75,100	\$52,082	In Work	69.35
	San	Bernardino			Plumbing - Replace approx. 96 SF of drywall ceiling. Remediate water damaged in the 1st floor HR storage				
4 FM-0057150		Courthouse	36-R1	1	room caused by a leaking supply line fitting in the 2nd floor Women's staff restroom.	\$ 7,461	\$7 <i>4</i> 61	Complete	100
4 1101-0037130	Demarano	Courtifouse	30-111	т	Toom caused by a leaking supply line litting in the Zha hoor women's stan restroom.	7 7,401	77,401	Complete	100
5 FM-0057155	Los Angeles	San Fernando Courthouse	19-AC1	1	Electrical - Building ATS failed to transfer power to emergency generator. Replace 600A ATS, replace (10) 500 MCM copper lugs, install 20 LF of 500 MCM copper wire, and install (10) 500 MCM compression connections.		\$27,856	Complete	83.41
6 FM-0057159	I os Angeles	Van Nuys Courthouse East	19-AX1	1	HVAC - Replace (1) failed actuator. Failed actuator is causing Room 110 to be extremely cold. ACM environment.	\$ 6,520	\$5 851	In Work	89.74
0 1101-0037133	LO3 Aligeles	Norwalk	13-471	т	Roof - Water leak through the 7th floor into the 6th floor ceiling of Department S. Replace (6) 1'x1'tiles on	7 0,320	75,651	III VVOIK	83.74
7 FM-0057160	Los Angeles	Courthouse	19-AK1	1	both floors. Replace (1) damaged smoke detector within an ACM environment.	\$ 16,585	\$16,585	In Work	100
7 1111 0007 200	200780.00	Norwalk	10 / 11		both needs replace (1) damaged emeric detected within any term emilient	Ψ 10,000	Ψ = 0,000		
8 FM-0057161	Los Angeles	Courthouse	19-AK1	1	Plumbing - Remove and replace a 35 LF of leaking 2inch drain pipe within an ACM environment.	\$ 16,291	\$16,291	In Work	100
		Hollywood			Vandalism - Replace (1) broken main entrance glass door (31.5x71) in front of the courthouse. A person				
9 FM-0057163	Los Angeles	Courthouse	19-S1	1	threw a rock breaking one of the glass doors.	\$ 10,025	\$9,132	Complete	91.09
					Plumbing - Replace 4 ft section of the main sewage line on the 1st floor, in the public hallway. Remediation				
		Mental Health			within ACM Environment of 8Wx15Lx8H are. Main sewage line is cracked and the public restrooms had to be				
10 FM-0057193	Los Angeles	Court	19-P1	1	closed due to the back-up.	\$ 44,438	\$31,689	In Work	71.31
14 514 0057404		Compton	10.464	4	Elevators, Escalators, & Hoists - Shorten elevator hoist ropes 16" on Elevator #5. The ropes is overstretched	¢ 0.005	¢6 527		66.40
11 FM-0057194	Los Angeles	Courthouse	19-AG1	1	and tripping the comp sheave safety switch.	\$ 9,885	\$6,537	In Work	66.13
12 FM-0057196	Los Angeles	Pasadena Courthouse	19-J1	1	Plumbing - Replace failed lines from the water cooler including work in an ACM environment. Water remediation required in 4th fl. Dept. A chambers, 5th fl. Dep. D and Dep. D-1 chambers, ceiling into the 4th Floor, Dept. A - Supervising Judge's Chambers, damaging (16) 2'x2' ceiling tiles and the wall.	\$ 22,653	\$15,710	In Work	69.35
42 54 225 125		Wiley W. Manuel	04.53		Plumbing - Remediate flood damage in 5th floor holding area 108 and 4th floor holding area 104. Flooding		A= a==		400
13 FM-0057199	Alameda	Courthouse	01-B3	1	was caused intentionally by in-custody.	\$ 5,375	\$5,375	In Work	100
14 FM-0057201	Los Angeles	Inglewood Courthouse	19-F1	1	Elevators - Custody elevator #5. Remove and restore Generator, strip and rewind armature, dip and bake parts, strip and rewind A/C end, dip and bake parts, replace all D/C field wires, replace 2 sleeve bearings, and replace brushes and lead wires.	\$ 65,000	\$48,464	In Work	74.56

	FM NUMBER	LOCATION FACILITY NAME BUILDING ID PRIORITY			PRIO	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
		_	Stanley Mosk			Elevators, Escalators, & Hoists - Replace handrail guides/brackets for Escalator 2-1. Handrail and guide failed.				
15	FM-0057205	Los Angeles	Courthouse	19-K1		This is a safety hazard.	\$ 7,650	\$7,440	In Work	97.26
			A lib a rea la rea			Plumbing - Replace a cracked pressure regulator valve and remediate water damage in an ACM environment.				
16	FN4 00F7309	Los Angolos	Alhambra	10.11		A leak was reported coming from the sink in a cell on the second floor and leak onto the 1st floor public	¢ 9.672	¢7.4E0	In Mark	96
10	FM-0057208	LOS Angeles	Courthouse Van Nuys	19-I1		hallway. Plumbing - Replace failed toilet gaskets and remediate water damage in an ACM environment. Water is	\$ 8,673	\$7,459	In Work	86
17	FM-0057209	Los Angolos	Courthouse East	19-AX1		leaking from the ceiling into the 4th floor Department U, affecting (4) 2" x 2" tiles.	\$ 14,567	\$13,072	In Work	89.74
17	1 101-0037209	LUS Aligeles	Courtilouse Last	13-471		HVAC - Chiller #1 tripping on high motor temperature - Rebuild existing chiller; work to include two (2) new	Ş 14,307	\$13,072	III VVOIK	89.74
			Chatsworth			filter driers, a new sight glass, "O" rings and gasket, 10 Lf. Of 1 5/8" copper tubing and associated couplings				
18	FM-0057217	Los Angeles	Courthouse	19-AY1		and elbows, and four (4) new 1 5/8" refrigeration ball valves.	\$ 33,885	\$28,396	In Work	83.8
10	1101 0037217	20371186163	Alfred J.	13 / (12		and cloows, and roar (1) new 1 5/6 Temperation ban valves.	Ψ 33,003	γ20,330		33.5
			McCourtney			County Managed - Exterior Finishes - Replace 3 broken exterior window. All (3) window are 2x4 in size. This				
19	FM-0057219	Los Angeles	Juvenile Center	19-AE1	1	includes emergency response.	\$ 2,348	\$2,348	In Work	100
20	FM-0057221	Los Angeles	Van Nuys Courthouse West Metropolitan	19-AX2		Plumbing – Install (1) ¾ 90 deg. elbow, and ¾ copper cap and remediate water damage, remove & replace 160 lineal feet of cove base, and prepped/mudded/sanded 25'x10' wall. Water is leaking from a 3/4" copper supply line, saturating the wall of the Basement conference room and breakroom B129. Electrical - Replace failed switch handle to ATS that controls the elevators. Due to brief power outage, no	\$ 14,505	\$11,674	In Work	80.48
21	FM-0057227	Los Angeles	Courthouse	19-T1	1	elevators at the courthouse are functioning. The ATS can't reset.	\$ 12,565	\$11,879	In Work	94.54
22	FM-0057231	Los Angeles	Stanley Mosk Courthouse Compton	19-K1	1	Plumbing - Mechanical RM-823 domestic hot water tank has a quarter size hole at bottom of tank. Weld plate to cover hole and 2 additional areas. Replace approx. 1,300sf of ceiling tiles. Tank supplies hot water to 9th flr restrooms and kitchen. Work is done under ACM environment. Elevators, Escalators, & Hoists - Shorten Elevator hoist ropes 16" on Elevator #4. The ropes are overstretched	\$ 48,500	\$47,171	In Work	97.26
23	FM-0057232	Los Angeles	Courthouse	19-AG1		& tripping the comp sheave safety switch.	\$ 9,885	\$6,537	In Work	66.13
24	FM-0057233	Los Angeles	Compton Courthouse	19-AG1	1	Elevators, Escalators, & Hoists - Elevator #11 is leaking hydraulic fluid from the jack shaft packing. Repack shaft to stop leaking. Plumbing - Replace failed push button for drinking fountain and replace (19) ceiling tiles. In custody jammed	\$ 9,986	\$6,604	In Work	66.13
25	FM-0057234	Los Angeles	Van Nuys Courthouse West	19-AX2		push button to drinking fountain on the fourth floor causing water to leak down pipe chase into the 2nd floor ceiling above the window #7 Clerk's Area.	\$ 9,880	\$7,951	In Work	80.48
26	FM-0057235	Los Angeles	Compton Courthouse	19-AG1		Plumbing - Replace 20' of 2" Black Cast Iron drain Pipe/Fittings. Replace 4' of 1" ceiling tiles. Remediate black water contamination. Water Leaked from the 7th flr public women's RR to 6th flr Dept. P Courtroom.	\$ 14,887	\$9,845	In Work	66.13
27	FM-0057239	Riverside	Banning	33-G1		Elevators, Escalators & Hoists – Remove and replace obsolete and damaged door operator and replace with new MOVFR II door operator; including new gate switch, door linkage, and all necessary wiring to the existing controller. This is the only elevator in the building and its outage is severely affecting operations within.	\$ 16,256 \$542,697	_	In Work	39.63

Action Item 2 – (Action Required) - List B – Facility Modifications Less than \$50K (Priority 2)

Summary:

List B – Facility Modifications Less than \$50K (Priority 2)

Total Project Count:	56
Total Potential FM Budget Share of Cost:	\$459,491

Meeting Date: 1/15/2016

Supporting Documentation:

• List B – Facility Modifications Less than \$50K (Priority 2)

Action Requested:

Staff recommends 56 projects for a total of \$459,491 to be paid from funds previously encumbered for facility modifications less than \$50K.

FM NUMBER LOCATION FACILITY NAME BUILDING ID PRIORITY		PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST		
		Compton			Elevator - The ropes for Elevator #6 is overstretched and tripping the comp sheave safety switch which is causing entrapments. Elevator hoist ropes must shortened and tested for			
1 FM-0057117	Los Angeles	Courthouse	19-AG1	2	proper operation before releasing back into service.	\$3,761	\$2,487 In Work	66.13
2 FM-0057120	Los Angeles	Metropolitan Courthouse	19-T1	2	Interior Finishes - Reinforce approx. 25ft ceiling tile support brackets in an ACM environment. Spline Ceiling tiles; support brackets are not holding creating a safety issue. Ceiling is located in a court exclusive space.	\$4,847	\$4,847 In Work	100
3 FM-0057121	Los Angeles	Beverly Hills Courthouse	19-AQ1	2	Exterior Shell -Remove and replace approximately 15 linear feet and 6 wide damaged concrete and adjacent asphalt. Bottom of ramp at the loading dock in the rear of the building has damaged concrete, this is a trip hazard and a safety concern.	\$4,392	\$3,493 Complete	79.52
4 FM-0057122	San Diego	South County Regional Center	37-H1	2	COUNTY MANAGED Plumbing: Replace storm water pumps and approximately 300 linear feet of deteriorated storm drains and sewer piping from roof top to detention level. Scope of work includes permitting, inspection and county project management fees. Due to age and current condition of plumbing system had resulted in water intrusion throughout the facility.	\$30,464	FMU Final \$30,464 Review	100
5 FM-0057130	Los Angeles	Parking Structure- Edelman Court	19-Q2	2	Elevators, Escalators, & Hoists - Install new governor cable and re-babbit cable. Elevator #1 governor cable is worn and stretched.	\$4,499	\$3,149 In Work	69.99
	Los Angeles	Edmund D. Edelman Children's Court		2	Elevators, Escalators, & Hoists - Install carbon generator brushes for eight elevators. Elevator generator brushes are deteriorating and need replacing for Parking Elevator #1, Public Elevators #2 through #6, and Children's Elevators #7 & #8. Elevators will begin to fail and could lead to potential entrapments, and downed elevators.	\$3,299	\$2,309 In Work	69.99
7 FM-0057132	Alameda	Wiley W. Manuel Courthouse	01-B3	2	Vandalism - Replace (1) Tempered / laminated security glass 7" X 32 3/4" X 1" thick glass pane window in holding cell 110-1. Window was broken by in custody causing a security issue.	\$1,307	\$1,307 In Work	100
8 FM-0057133	San Joaquin	Manteca Branch Court	39-C1	2	Plumbing - Install 2" backflow prevention device (with concrete pad, cage, and bollards) on the domestic water system as required by the City of Manteca oer code. Item identified during the water audit.	\$10,279	\$10,279 In Work	100
9 FM-0057134	Calaveras	New San Andreas Courthouse	05-C1	2	Fire Protection - Install three new remote test switches to currently inaccessible duct detectors (1-2-150, 1-2-157 & 1-2-138) to facilitate completion of code required testing of the fire protection system.	\$6,287	\$6,287 In Work	100
10 FM-0057135	Santa Cruz	Watsonville Courthouse	44-B2	2	Elevators - Remove and replace jack seals on five (5) elevators cars - Elevator packing is leaking from (5) Elevator hydraulic ram seals and can cause elevator to shut down if not replaced, any number of elevator reduction would have a direct impact on access to the courts for staff/public/Judicial Officers.	\$15,838	\$15,838 In Work	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
			Rancho			Electrical - Install (2) 2pole 208/240 - 30amp circuits with twist lock outlets and (1) 120V -				
			Cucamonga			receptacle in the 1st floor civil department. This work is needed to accommodate Appellate				
11	FM-0057141	San Bernardino	Courthouse	36-F1	2	Court equipment.	\$3,511	\$3,511	In Work	100
						Exterior Shell - Restore (2) pair of rear entry exit doors that have failed due to building settling.				
12	5.4 00 57.4 40		Southwest Justice			Doors at this time do not open and are limiting public and employee access/egress to the	46.706	45.022		7400
12	FM-0057142	Riverside	Center	33-M1	2	building.	\$6,726	\$5,032	In Work	74.82
4.2	EN 4 00E 74 40	0	Central Justice	20.44		HVAC - Replace 2 HP water heating pump. Bearings are failing. Failure would result in loss of	¢0.000	ć7.27F	1 - 1471	04.47
13	FM-0057143	Orange	Center	30-A1	2	domestic hot water for areas of the 3rd floor.	\$8,089	\$7,375	In Work	91.17
			Law And Justice			HVAC - Remove and replace (1) return fan motor and associated drive belts on Air Handler #16	4	4		
14	FM-0057149	Solano	Center	48-A2	2	- Motor bearings are beginning to fail and would affect courtrooms and chambers.	\$5,667	\$5,667	In Work	100
15	FM-0057157	Los Angeles	Santa Monica Court Annex	19-AP3	2	HVAC - Replace burnt economizer communication modules and fan motor. BAS system is non-functional which is affecting the A/C system of the entire Annex Building.	\$5,148	\$4,041	Complete	78.49
			South County			Exterior - Vandalism - Replace (1) broken window (47 1/4" x 105 7/8") on 2nd floor				
16	FM-0057158	Tulare	Justice Center	54-I1	2	overlooking the sallyport. Existing window was shot at and had both panes cracked.	\$5,837	\$5,837	In Work	100
			Edmund D.			Plumbing - Replace a failed 3/4" ball valve and install new copper fitting. Hot water is				
17	FM-0057162	Los Angeles	Edelman Children'	s 19-Q1	2	constantly leaking from a bathtub faucet located in the Shelter Care Restroom. ACM	\$2,303	\$1,612	In Work	69.99
			South County			Elevators, Escalators, & Hoists - Shorten Hoist Ropes on Car #9. During a service call it was found that the stretching of the cable ropes do not meet with code or operational				
18	FM-0057164	San Diego	Regional Center	37-H1	2	specifications.	\$7,200	\$7,200	Complete	100
10	FN4 00F746F	0,000,000	Harbor Justice Center-Newport	20.54	2	LIVAC - Develope foiled substitute for Develope and legislands for foiled for	Ć4 COO	¢2.0 7 0	In Manue	04.22
19	FM-0057165	Orange	Beach Facility	30-E1		HVAC - Replace failed exhaust fan. Parts are no longer available for failed fan.	\$4,600	\$3,879	In Work	84.32
20	EM_0057166	Riverside	Larson Justice Center	32_C1	2	Elevators, Escalators, & Hoists - Lighting -Replace failed lighting controller, ceiling mount, and power supply. 90% of the lighting have failed and is a safety hazard to employees, jurors, and public	\$12 172	\$10,645	In Work	0N 01
20	FM-0057166	Riverside		33-C1	2	public. HVAC - Replace faulty Main Base Board and Auxiliary Contacts. Chiller is experiencing	\$13,173	\$10,045	III VVOIK	80.81
			Rancho			intermittent faults for compressor overload. This work must be performed to ensure reliable				!
21	FM-0057169	San Bernardino	Cucamonga Courthouse	36-F1	2	cooling for the Courts MDF room.	\$7,467	¢5 670	In Work	76.05
<u></u>	1111 0037 103	Jan Bernaramo		3011		COUNTY MANAGED - HVAC - Install (2) new mini-split HVAC units 20 x 15 ft glass store front to enclose the weapon screening area with double doors. Current building design does not	77,407			70.03
33	EN 4 0057470		Sylmar Juvenile	40.454		support cooling requirements for weapons screening. Work impacts common space and	633.000		FMU Final	400
22	FM-0057170	Los Angeles	Court	19-AF1	2	county is absorbing 65% of overall project cost.	\$32,080	\$32,080	Keview	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST
23	FM-0057171	Los Angeles	Airport Courthouse	e 19-AU1	2	Elevator, Escalators, & Hoists - Key switches for custody elevators #5 & #10 are worn and non-operational. Key switches are required for elevator operation to access floors in custody elevators. Replace high security key switches on custody elevators #5 & #10 Car Operating Panels and hall fixtures for basement, 3rd, 7th, 8th, and 9th floors.	\$26,475	\$20,431	n Work	77.17
			Harbor Justice Center-Newport		2	HVAC - Cooling Tower - Replace fan propeller assembly, bushings, shaft, bearings and belt. Fan		F	MU Final	94.22
	FM-0057174 FM-0057175	Orange Fresno	Beach Facility Fresno County Courthouse.	30-E1 10-A1	2	assembly and bearings are near failure. Graffiti - Remove graffiti etched in the wood veneer on doors and courtroom entrance vestibules in 28 locations throughout the facility. Graffiti is visible in public areas of the courthouse.	\$25,591 \$28,278	\$21,578 F F \$28,278 F	MU Final	100
			Whittier		2	Elevators, Escalators, & Hoists - Replace failed door detector edge and sight guard on Elevator				
26	FM-0057176	Los Angeles	Courthouse West Justice	19-AO1	2	#1. Elevator #1 is not working due to damaged door detector edge and sight guard. Plumbing - Replace failed domestic hot water heater with a new 75 gallon hot water heater. A hole developed in the bottom of the existing hot water heater causing the burner assembly to get wet, the pilot light will not stay lit resulting in complete loss of hot water to the entire	\$3,550	\$3,550	n Work	100
27	FM-0057177	Orange	Center	30-D1	2	facility. HVAC - Replace damaged chilled water pump coupling inserts and condenser water pump	\$4,000	\$3,627	n Work	90.68
28	FM-0057178	Los Angeles	Compton Courthouse	19-AG1	2	motor coupling inserts. Coupling inserts are damaged, worn and cracked and needs to replaced to prevent system failure.	\$3,023	\$1,999	n Work	66.13
29	FM-0057179	San Bernardino	Fontana Courthouse	36-C1	2	Elevators, Escalators, & Hoists - Public Elevator #1 the data port on the CPU is bad. Currently computer diagnostics cannot be performed. Replace existing CPU #CP27C with failed comm port with new #CP37 CPU complete with software.	\$14,999	\$12,325	n Work	82.17
20	ENA 00E7191	San Mateo	Municipal Court Building - Northern		2	HVAC - Remove and replace failed, existing 11" inline duct blower (1) - Blower motor seized and overheated causing smoke, setting off alarm.		\$2.1241	n Work	92.21
		Santa Clara	Branch Hall of Justice (West)	41-C1 43-A2	2	Plumbing - Replace (1) failed storm water sump pump - Possible flooding due to failed pump.	\$2,553 \$7,844	\$2,124 \$7,844		100
32	FM-0057184	San Fernando		19-AC1	2	Fire Protection - 6" FEBCO Series 860 Domestic Backflow has check valve seats damage. Replace (2) check valve seat assemblies. Deficiencies found during PM SWO# 2504987.	\$3,973	\$3,314	n Work	83.41
		Santa Clara	Morgan Hill Courthouse	43-N1	2	HVAC - Replace (1) failed 4 burner assembly - Failed boiler currently impacting the court's heating capacity.	\$1,769	\$1,769		100
34	FM-0057186	Santa Clara	Morgan Hill Courthouse	43-N1	2	HVAC - Replace (1) failed impeller and (1) pump volute housing. Failed boiler currently impacting the court's heating ability.	\$3,931	\$3,931	n Work	100

FM NUMBER LOCATION FACILITY NAME BUILDING ID PRIORITY		◙	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST		
					Elevator - Replace failed advancing motor and remediate damage to contactors and associated				
		Van Nuys			circuits. Elevator #3 was not landing properly at floors and the doors would open fully as car				
35 FM-0057188	Los Angeles		19-AX1	2	was 4 -6 away from landing and was still in motion.	\$4,477	\$4,018	In Work	89.74
		North County							
		Regional Center -			COUNTY MANAGED - HVAC - Replace ceramic fiber module panels on side and rear of boiler #				
36 FM-0057195	San Diego		37-F1	2	1 in Central Plant. This work was performed by the County under Emergency Repairs.	\$2,492	\$2,492	In Work	100
		Hayward Hall of		_	Electrical - Replace (6) failed holding cell interview phones. Existing phones damaged by in-	4	4		
37 FM-0057197	Alameda	Justice 0	01-D1	2	custodies causing inability to communicate with attorneys.	\$2,457	\$2,457	In Work	100
					Grounds and Parking Lot - Remove 21 dead trees. The current drought and water restrictions				
		Larson Justice			created unsafe conditions such as trip, fire, pest infestation, and security issues. Work is to be	4	40.0-0		
38 FM-0057198	Riverside	Center 3	33-C1	2	executed after hours.	\$11,110	\$8,978	In Work	80.81
					Grounds and Parking Lot - Replace current roller drive operators with (2) chain drive slide gate				
		North County			operators with loop detectors and modify gate to work with the new operators. The gate				
		Regional Center -			operators frequently fail trapping Judges in the secure parking area. Roller drive system slips	4	44.040		
39 FM-0057210	San Diego		37-F1	2	on the rail during high humidity and wet conditions.	\$14,919	\$14,919	In Work	100
40		Pasadena			Plumbing - Replace damaged and non-functioning sump tank and pump. The sump pump is	40 -04	42 500		
40 FM-0057211	Los Angeles		19-J1	2	cracked and not functioning which could cause a flood if not replaced.	\$3,724	\$2,583	In Work	69.35
14 5.4 005-7040		East Los Angeles	40.14	_	HVAC - Install (1) new Blast Tube, (1) new Flange and (1) new Diffuser. Boiler #2 has a	47.004	65.674		
41 FM-0057212	Los Angeles		19-V1	2	damaged blast-tube and diffuser.	\$7,301	\$5,674	In Work	77.72
42 514 0057240		Compton	10.464	2	Elevator - Shorten 16" of overstretched Elevator ropes. Custody Elevator #7 got stuck on the	62.764	¢2.407	1 - 14/1	66.43
42 FM-0057218	Los Angeles		19-AG1	2	7th floor with 2 deputies entrapped due to overstretched ropes.	\$3,761	\$2,487	In Work	66.13
42 514 0057330	Los Angolos	Santa Monica	10 401	2	Interior Finishes - Replace (1) 60"x72" Bullet Resistant Glass at Teller/Traffic window. Existing	ĆO 125	ĆO 12E	In Morle	100
43 FM-0057220	Los Angeles	Courthouse 1	19-AP1	2	glass has a 60" crack, compromising the glass integrity.	\$9,125	\$9,125	In Work	100
		Chatawarth			Electrical - Replace Main Power and Processor Board . UPS System is on alarm and circuit				
	Los Angolos	Chatsworth	10 41/1	2	board is burnt and shorted out. System failure affects the emergency lights in the court rooms	¢0.222	¢7 726	In Mork	02.0
44 FM-0057223	Los Angeles	Courthouse 1 Burbank	19-AY1		and some hallways. Plumbing - Install new 3" gate valve and factory repair kit. The device failed and does not	\$9,232	\$7,730	In Work	83.8
45 FM-0057224	Los Angeles		19-G1	2	comply with health/water department regulations.	\$5,228	¢1 71E	In Work	90.76
+3 IVI-003/224	Los Aligeles	Clara Shortridge	19-01		compry with health, water department regulations.	<i>ې۵,۷۷</i> ٥	74,743	III VVOIK	30.76
		Foltz Criminal			Plumbing - Installed new Comfort heating make-up water line and plumbing. Water line is				
46 FM-0057226	Los Angeles		19-L1	2	damaged and is leaking.	\$6,931	\$ 4 76Ջ	In Work	68.79
10 1101 0037220	Los Angeles	Metropolitan	-		Fire Protection - Replace (33) defective & aged smoke detectors; Replacement is code	70,231	γ 1 ,700	III VV OIR	00.73
47 FM-0057229	Los Angeles	- I	19-T1	2	required.	\$9,074	\$2 570	In Work	94.54
1, 1141 003/223	2007 (1180103	Pasadena	-> 11		Fire Protection - Replace (3) 75 feet fire hoses, and replace (1) fire hose nozzle. Units failed	73,074	70,575	III VV OIK	37.37
48 FM-0057230	Los Angeles		19-J1	2	testing must be replaced for compliance.	\$3,442	ć2 20 7	In Work	69.35

LOCATION EACILITY NAME BUILDING ID		PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % of COST		
40 514 0057240	Los Angolos	Pomona	10 \\\1	r	HVAC - Boiler #2 restoration - Install Six (6) boiler tube plugs. Boiler #2 tubes have deteriorated		¢2	01 14
49 FM-0057240	Los Angeles	Courthouse South	19-W1	2	and required the tubes to be plugged.	\$3,879	\$3,535 In Work	91.14
		South Placer			Electrical - Replace 36 fixtures and ballasts in confined space above the ceiling with LED conversion fixtures - 10% of the lights have failed. The ballast for these fixtures are in an inaccessible area that does not permit safe access to change out the ballast if required, this			
50 FM-0057241	Placer	Justice Center	31-H1	2	project will remove the need to replace any ballast in the future.	\$7,681	\$7,681 In Work	100
51 FM-0057243	Alameda	George E. McDonald Hall of Justice	01-F1	2	Fire Protection - Fire suppression system - Replace two failed and leaking inspector test valves discovered during quarterly inspection.	\$3,210	\$3,210 In Work	100
52 FM-0057244	Los Angeles	Pasadena Courthouse	19-J1	2	Electrical - Replace defective exit and bug eye lights. Multiple emergency lights (exit signs and bug eyes) not working throughout the building. Defects found from annual EML-level IV PM.	\$4,580	\$3,176 In Work	69.35
53 FM-0057245	San Diego	North County Regional Center - Vista Center	37-F2	2	HVAC - Replace existing valve and actuator, with one (1) two-way shut off valve and (1) electronic actuator. Chilled water isolation valve is not closing all the way and cannot supply air warmer than 55 degrees.	\$7,580	\$7,580 In Work	100
54 FM-0057246	San Bernardino	San Bernardino Courthouse - Annex	36-A2	2	Elevators, Escalators, & Hoists - Replace faulty worm shaft seal and brake shoes at Public Elevator #1. Restore elevators Recall Peek-a-Boo function so that doors will not automatically open when in fireman recall mode. The existing worm shaft seal is defective and allowing worm gear oil to leak from the gear case.	\$14,640	\$14,640 In Work	100
55 FM-0057247	San Diego	North County Regional Center -	37-F1	2	Elevators, Escalators, & Hoists - Replace failing Communication Circuitry between the car top controls and the main controller in the equipment room, replace the floor selector wiring and tape selector guides. Communication between car and control equipment above is intermittent, causing intermittent operation and rider entrapment.	\$5,434	\$5,434 In Work	100
		Courthouse/Sheriff		2	Interior Finishes - 2nd Floor ADA Restroom - Construct (1) ADA accessible restroom on the second floor near the elevator - The building does not currently have an ADA accessible		FMU Final	
56 FM-0057248	Sierra	Station-Jail	46-A1	2	restroom.	\$49,500	\$49,500 Review	100
						\$502,537	\$459,491	

Meeting Date: 1/15/2016

Action Item 3 – (Action Required) - List C – Cost Increases Over \$50K

Summary:

List C – Cost Increases Over \$50K

Total Project Count:	5
Total Potential FM Budget Share of Cost:	\$304,680

Supporting Documentation:

• List C – Cost Increases Over \$50K

Action Requested:

Staff recommends five projects for a total cost increase to the Facility Modification program budget of \$304,680.

The project was delayed dute to the Country delay on required approvals. After that, the project was mobilized, but then there was a two-month delay twice during construction start-up. The project was originally designed under 2010 GBC and additional changes were required when it was originally designed under 2010 GBC and additional changes were required when it was restarted and submitted to accommodate the entry screening, county 2 portion of building will have separate entry. \$ 375,000 \$ 375,000 \$ 439,082 \$ 439,082 \$ 439,082 \$ 439,082 \$ 439,082 \$ 439,082 \$ 64,0		FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION	PROGRAM BUDGET SHARE OF TCFMAC FUNDED COST	CURRENT COST ESITMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF CURRENT COST ESTIMATE	NOTES	FACILITY MODIFICATION PROGRAM COST INCREASE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
HYAC - Remove and replace 39 year old non-compliant boilers due to AQMD regulations, failure to replace these boilers will lead to heavy daily fines; HEATING BOILER #1 and BOILER #2, 2,000,000 BTU each. Work will include the removal and replacement of the existing boiler pads, removal of ACM's and the 2 addition of a dedicated electrical panel. HYAC - Replace failed HYAC chillers - Replace two ea. 40 ton chillers that have failed, provide temp chiller until replacements are on site (6-8 weeks) including encroachment permit form city of Ukiah and required sound control elements, Replace damaged and failing cold water coils (8), and Steam Coils (8) at mechanical room, replace end of life control valves at Steam coils (8), Replace 4 failed reheat coils, 2 in mechanical space, 1 at DA office space and 1 on the 1st floor. Remediate ACM as required at the reheat coils approx. 60		FM-	Santa				new entrances needed - Currently building has no entry screening and needs to be renovated						County's delay on required approvals. After that, the project was mobilized, but then there was a two-month delay twice during construction start-up. The project was originally designed under 2010 CBC and additional changes were required			
HVAC - Replace failed HVAC chillers - Replace two ea. 40 ton chillers that have failed, provide temp chiller until replacements are on site (6-8 weeks) including encroachment permit form city of Ukiah and required sound control elements, Replace damaged and failing cold water coils (8), and Steam Coils (8) at mechanical room, replace end of life control valves at Steam coils (8), Replace 4 failed reheat coils, 2 in mechanical space, 1 at DA office space and 1 on the 1st floor. Remediate ACM as required at the reheat coils approx. 60	1				42-H1	2	portion of building will have separate entry. HVAC - Remove and replace 39 year old non- compliant boilers due to AQMD regulations, failure to replace these boilers will lead to heavy daily fines; HEATING BOILER #1 and BOILER #2, 2,000,000 BTU each. Work will include the removal and replacement of the	\$ 375,000	\$	375,000	\$ 439,082	\$	It was determined through plan review that a dedicated electrical panel, new circuit runs and conduit would be needed to support the new boilers. Also, the	\$ 64,082	Complete	100
FM- County sq. and at the mechanical room approx. 120sq unforeseen ACM & lead abatement, and unforeseen ACM & lead abatement, and sq. and at the mechanical room approx. 120sq sq. and at the mechanical		FM-		County			HVAC - Replace failed HVAC chillers - Replace two ea. 40 ton chillers that have failed, provide temp chiller until replacements are on site (6-8 weeks) including encroachment permit form city of Ukiah and required sound control elements, Replace damaged and failing cold water coils (8), and Steam Coils (8) at mechanical room, replace end of life control valves at Steam coils (8), Replace 4 failed reheat coils, 2 in mechanical space, 1 at DA office space and 1 on the 1st floor. Remediate				\$		This was originally two distinct FMs for reheat coils (FM-0049125) and Chiller/main coils (FM-0051702). During the significant delay in attaining county shared cost commitment, the systems failed, creating a P1 situation that were better dealt with combined than separately. Both original costs were approved by the committee, creating a combined cost amount of \$827,832. The cost increase covers the P1 response, unforeseen ACM & lead abatement, and	\$		67.62

Roof - Replace 22,000 sq. ft. of deteriorated roof, coping metal (1000 sq. ft.), Gravel stops (250 sq. ft.), Surface mount (450 sq. ft.), Twelve (12) roof drains, deteriorated over flow drains and remove twenty (20) existing 1" eye bolts. The roof is showing signs of cracking, ponding and roof leaks are evident in the building; the eye bolts are breaching the cant 4 0053442 Santa Clara Courthouse 43-D1 Roof - Replace 22,000 sq. ft. of deteriorated or deteriorated over flow drains, deteriorated over flow drains, deteriorated over flow drains, deteriorated over flow drains and remove twenty (20) existing 1" eye bolts. The roof is showing signs of cracking, ponding and roof leaks are evident in the building; the eye bolts are breaching the cant 2 strip and will void the new roof warranty. \$ 824,415 \$ 544,444 \$ 880,159 \$ 581,257 included in the original scope. Solution Project estimate only included immediate water remediation. Upon completion of remediation work, additional scope identified was the	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF TCFMAC FUNDED COST	CURRENT COST ESITMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF CURRENT COST ESTIMATE	NOTES	FACILITY MODIFICATION PROGRAM COST INCREASE	JOB STATUS	FACILITY MODIFICATION PROGRAM BUDGET % OF COST
immediate water remediation. Upon completion of remediation work, Plumbing - A main water line break resulted in		Santa Clara		43-D1		roof, coping metal (1000 sq. ft.), Gravel stops (250 sq. ft.), Surface mount (450 sq. ft.), Twelve (12) roof drains, deteriorated over flow drains and remove twenty (20) existing 1" eye bolts. The roof is showing signs of cracking, ponding and roof leaks are evident in the building; the eye bolts are breaching the cant	\$ 824,415	\$ 544,444	\$ 880,159	\$ 581,257	barricade of the courthouse perimeter in order to perform work during normal business hours due to the City of Palo Alto's noise restrictions, and the replacement of 12 failing roof drains not included in the original scope.	\$ 36,813	In Work	66.04
FM- Courthouse 13-A1 1 containment, and overnight crew supervision. \$45,000 \$45,000 \$161,700		Imperial	County	13-A1		a flood. Isolate the affected area, drain the domestic water system, and replace approximately 2' of 3/4" copper pipe. The initial P1 response effort will include emergency responder mobilization, extraction,		\$ 45,000	\$ 161,700	\$	immediate water remediation. Upon completion of remediation work, additional scope identified was the relocation and restoration of critical court documents, as well as testing for and treatment of identified mold issues. Property damage from flood exceeded original estimates. Accounting now	\$ 116,700) In Work	100

Action Item 4 – (Action Required) - List D – Facility Modifications Over \$50K

Summary:

List D – Facility Modifications Over \$50K

Total Project Count:	15
Total Potential FM Budget Share of Cost:	\$2,844,759

Meeting Date: 1/15/2016

Supporting Documentation:

• List D – Facility Modifications Over \$50K

Action Requested:

Staff recommends approving 15 projects for a total cost to the Facility Modification Program Budget of \$2,844,759, with items #5 and #10 – FM-0055034 and FM-0057213 respectively – being held for shared cost approval.

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	Σξ	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
			Santa Clara			HVAC - Replace leaking, rusted 40 year old 65 ton Cooling Tower, VFD included. Existing equipment has							
1	FM-0056888	Santa Clara	Courthouse	43-G1	2	leaks and failed component replacements. Increased number of hot calls is affecting operations.	\$	260,489	\$	260,489	\$ 260,489	30	100
						Plumbing - Replace duplex domestic water skid with Grundfos Duplex domestic water skid, install (2)							
			Juvenile			5HP VFD drives, replace 15 LF of 2" copper pipe, replace (2) 2" brass unions, replace (2) 4.5" aluminum							
		San	Dependency			pressure gauges, replace (2) 2" copper tees, and replace (2) 2" ball valves. Duplex booster pump's							
2	FM-0057152	Bernardino	Courthouse	36-P1	2	main board has failed and parts are no longer available.	\$	57,952	\$	31,601	\$ 292,090	35	54.53
			Downey			Plumbing - Replace existing 8" Fire Main Check Valves and 4" Domestic Water Line Check Valves with Backflow Preventers. Perform fire watch and engineering study. During PMs for the domestic and fire							
3	FM-0057236	Los Angeles	Courthouse	19-AM1	2	main backflows it was discovered that both systems had been missing the backflow preventers.	\$	96,125	\$	80,457	\$ 372,547	35	83.7
						Elevators, Escalators, & Hoists - Complete Elevator System Renovation - Work to include doors, operators, and controllers, hydraulic power units and associated equipment. Code upgrades will also be included which consist of HVAC, FACP and Fire Suppression Equipment. Evaluation by our third							
4	FM-0010335	El Dorado	Johnson Bldg.	09-E1	2	party consultant has found the system to be at risk and in a poor operating condition.	\$	385,000	\$	385,000	\$ 757,547	40	100
5	FM-0055034	Orange	Harbor Justice Center-Newport Beach Facility	30-E1	2	HVAC - BAS - Replace failed Siemens chiller control system with new non-proprietary Automated Logic system. Multiple components of the current system are failing on a daily basis and have resulted in complete shutdown and difficult restarts of the vital building system. Work to be completed on off-hours to not impact operations.	Ś	535,000	\$	451.112	\$ 1,208,659	45	84.32
			Santa Monica		_	HVAC - Roof top hot water piping has deteriorated. Replace 200 LF of 2" copper piping, install (10) 2" copper couplings, install (2) 2" butterfly valves, install (1) 2" ball valve, install (16) pipe saddles and	Y						0.02
6	FM-0057094	Los Angeles	Courthouse	19-AP1	2	clamps, reinsulate 200 LF of hot water piping, and replace 210 SF of aluminum insulation jacket.	\$	78,596	\$	61,690	\$ 1,270,349	45	78.49
		San	Big Bear	26.14		COUNTY MANAGED- Roof- Remove existing deteriorated three layer roof approx. 20,000SF and replace with new 20 year warranty, Title 24 compliant, roof system. Replace several roofing systems and counter flash ducting and mechanical roof penetrations as needed to make 100% weather tight. Work		76.404	,	76.404	Ć 4 24C 452	5 0	100
/	FM-0057123	Bernardino	Courthouse	36-I1	2	is necessary to prevent water intrusion in the rainy season.	\	76,104	\$	76,104	\$ 1,346,453	50	100
R	FM-0052826	Ventura	Hall of Justice	56-A1	2	COUNTY MANAGED - Security - Basement Holding Area - Camera System Upgrade. Upgrade Basement Holding Camera System Recommended by County/MP.	ζ	374,616	¢	374 616	\$ 1,721,069	55	100
	1111 0032020	Vericula	Tian of Justice	20 71		Interior Finishes - 30% of Dept 105 Public seating are damaged, un-repairable & a safety hazard to	 	37 7 ,010	7	J, 1 ,010	Y 1,721,000	33	100
			Compton			public attempting to use. Conduct Environmental testing & set-up 29'x15'x8' containment. Demo 93 existing damaged chairs. Existing anchoring bolts have sheared off requiring drilling new anchoring points. Drill 168 holes (42ft x 4 holes per ft) for new chair anchoring. Install 93 new American Seating							
9	FM-0056971	Los Angeles	Courthouse	19-AG1	2	plastic seating (similar style to existing) & secure w/epoxy.	\$	90,973	\$	90,973	\$ 1,812,042	60	100
			Dinuba Division of			Roof - Install new 30,000 sf, 80 mil PVC membrane roofing system to replace existing built-up asphalt							
10	FM-0057213	 Tulare	the Tulare Superior Court	54-E1	2	roof. Install new coping cap and raise all roof curbs to a minimum of 8. Existing roofing is failing with severe blistering and cracks.	\$	665,000	\$	332.500	\$ 2,144,542	60	50
			1		<u> </u>		1 "	- /	<u>. ' </u>	,	. , ,		

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	ILITY MODIFICATION	PROGRAM BUDGE I SHAKE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
			Humboldt County			HVAC - Replace failed AHU Hot and Cold Coils and Condensate Pans- Install new stainless steel							
1	FM-0057216	Humboldt	Courthouse (Eureka)	12-A1		condensate Drain pans (AHU 6,7 &8), install new Heating & Cooling coils (AHU 4,5,6,7 & 8)including ACM abatement and condensate pumps for Pans in AHU 5,6,7 & 8.	خ	379,860	\$ 37	70 960	\$ 2,524,402	60	100
1	1 1101-0037210	Transolat	(Luieka)	12-A1		Interior Finishes - Remove 5 existing sound wall panels and install new fixation system to back of	٧	373,800	γ 3,	7 3,800	Ş 2,324,402	00	100
						panels to prevent delaminating from walls, restore material on edges of panels and reinstall in							
			South County			courtroom. Sound panels are falling off walls, fabric on panels is detaching. Panels are contacting							
1	P FM-0057187	San Diego	Regional Center	37-H1		patrons/staff and is a safety issue.	\$	57,943	\$ 5	57,943	\$ 2,582,345	65	100
						HVAC BAS - Upgrade the building automated system (BAS) to allow full function control of all HVAC							
						equipment throughout the building. The upgrade will allow full control access the maintenance shop desktop computer and by remote access via the internet, and resolve overheating in the first floor							
						security office, trend before and after. This remote courthouse experiences harsh climate and frequent							
			New Susanville			equipment outages. Full functioning control access through the BAS is critical to maintain court							
1	B FM-0055154	Lassen	Courthouse	18-C1		operations.	Ś	90,000	s s	90.000	\$ 2,672,345	67	100
			Bakersfield			Interior finish - Floor tile - Remove and Replace 1926 SF of loose, cracked and lifting ACM floor tiles	*		<u> </u>	,,,,,,,	+ -///		
1	FM-0057200	Kern	Superior Court	15-A1	2	with new 12"x12" vinyl tiles and 180 LF of wall base. Floor tiles are cracked and lifting.	\$	83,676	\$ 5	52,415	\$ 2,724,759	75	62.64
						Exterior Shell - Restore exterior building shell. Caulk windows (96 ea), retexture exterior stucco. Apply							
			New Downtown			an elastomeric paint coating to entire exterior (26,400 sf), including the Sally Port to be coated with an							
			Merced			elastomeric paint. Exterior has extensive damage from water penetration and ledges have deteriorated							
1.	FM-0057173	Merced	Courthouse	24-A8		allowing water penetration into the building.	\$	120,000	\$ 12	20,000	\$ 2,844,759	85	100
			Carol Millor			Grounds and Parking - Parking lot lighting - Retrofit the existing parking lot lighting from high pressure							
1	FM-0031636	Sacramento	Carol Miller Justice Center	34-D1		sodium lighting to new more efficient LED lighting. Remove and replace total of 13 light poles with two fixtures per pole. Better Energy Efficiency.	ا د	35,000	ς :	2/1 2/12	\$ 2,878,972	20	97.75
1	1101-0031030	Sacramento	Justice Center	34-01	<u> </u>	initures per pole. Better Ellergy Efficiency.	٧_	33,000	7 .	74,213	Ş 2,070,372	20	37.73
			West Justice			HVAC - Install four (4) 15 HP and one (1) 10 HP 480V ABB Variable Frequency Drive (VFD) with bypass							
1	FM-0057144	Orange	Center	30-D1		for Chillers #1, 2, and 3. Abrupt starts have damaged couplings between the pumps and motors.	\$	41,475	\$ 3	37,618	\$ 2,916,590	38	90.7
						Electrical - Replace existing Compact Fluorescent lamps (CFLs) in all Courtrooms and Elevator Lobbies							
			Gordon Schaber			throughout the court with R-30 LED lamps - The existing CFLs throughout the building have failed, by							
			Sacramento			replacing the existing CFLs with LED, this project will significantly reduce energy consumption and heat							
1	8 FM-0056913	Sacramento	Superior Court	34-A1	3	load throughout the facility.	\$	68,000	\$ 6	58,000	\$ 2,984,590	40	100
						Security Enhancement - Clerk's County BR Resistance - Relocate existing counter to provide room for							
						security door, Install BR Level 3 glass with rated speaker grills on top of counter, apply BR protection to lower portion of counter, and patch back carpet as required. Existing counter is not protected and							
			Modesto Juvenile			court wants to relocate screening such that public have direct access to the clerk's without screening							
10	FM-0055186	Stanislaus	Court	50-B1		(necessitating the proposed protection).	5	55,000	s c	55.000	\$ 3,039,590	40	100
	3333100	3 53.1131443				/		22,000		-,555	+ 0,000,000		
			Humboldt County										
			Courthouse			Furniture and Equipment - Replace Jury Box seating in courtroom 1 & 4 (26 chairs). Current chairs are							
12	FM-0056974	Humboldt	(Eureka)	12-A1	3	failing and replacement parts are no longer available.	\$	65,000	\$ 6	55.000	\$ 3,104,590	43	100

EM NUMBER LOCATION BUILDING ID PRIORITY		PRELIMINARY ESTIMATE	TION	PROGRAM BUDGE I SHAKE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
Interior Finishes - Transaction casework and layout - Install a glass enclosure on top of the foot long transaction counter, including replacement of adjacent half door with full length	_						
include modification of counter to allow for an ADA window and four additional transactio							
and barrier between the public and staff / money drawer. Current counter and layout cited	d in a						
21 FM-0052321 Nevada Joseph Center 29-B1 3 security evaluation and through court audit.	Ş	25,800) \$ 2	25,800	\$ 3,130,390	45	100
New Downtown Electrical-Energy lighting initiative to replace three (3) wall pack units, twelve (12) shoe box	y fivturos						
New Downtown Electrical-Energy lighting initiative to replace three (3) wall pack units, twelve (12) shoe box Merced four (4) in ground lights, eighteen (18) fluorescents lamps and install one (1) LED light fixtue							
22 FM-0055001 Merced Courthouse 24-A8 3 lighting fixtures will be upgraded to energy efficient fixtures for cost saving on utilities.	خ (۱۳۰۰)	33,300) \$ 3	3.300	\$ 3,163,690	45	100
			7		7 2,23,333		
HVAC - Restore operations to Cooling Towers #1 & #2. Cooling Tower #1: Replace shaft, (2	2) bearings,						
bushing, driven sheave, electric water level probe assembly and drain valve. Cooling Towe	er #2: Replace						
Whittier 7 1/2 hp. fan motor, shaft, (2) bearings, driven sheave, driver sheave and belt. Provide Fan	_						
23 FM-0056533 Los Angeles Courthouse 19-AO1 3 on Chillers 1 & 2 once all mechanical work has been completed. Deficiencies were found d	during PM. \$	102,349	9 \$ 8	38,460	\$ 3,252,150	45	86.43
Electrical - Retrofit 128 light fixtures to receive new LED light bulbs which will require conta	rainment for						
Pasadena an included encapsulation of existing fire proofing above light panels. 60% of the lights are							
24 FM-0057136 Los Angeles Courthouse 19-J1 3 lobby which is a safety concern for weapons screening and walking traffic.	ع ا	86,500) \$ 5	9.988	\$ 3,312,138	45	69.35
Interior Finishes - Entrance doors to courtrooms 285 & 426 rattle when closed and are con	nsidered		7		7 2,5 = 2, = 5		
disruptive. Replace (4) sets of custom uneven 5'x7' double 90 minute fire rated doors, repl	lace (4) Von						
Alfred J. Duprin 9947LF 36" less bottom rod push bars with 26D finish, replace (4) special order Vor	n Duprin						
McCourtney 9947LF 24" less bottom rod push bars with 26D finish, install (4) sets of Pemko aluminum i	meeting						
25 FM-0057138 Los Angeles Juvenile Center 19-AE1 3 stiles, and install (4) 4-1/2" x 4-1/2" ball bearing pin hinges.	Ç	85,000) \$ 8	35,000	\$ 3,397,138	45	100
New Amador Security- Safety - Remove the 4 existing exterior windows on the east exterior wall of the k County replace them with 4 new dark tinted ballistic resistant units - The existing window glazing of							
County replace them with 4 new dark tinted ballistic resistant units - The existing window glazing (does not	23,622	5 2	23 622	\$ 3,420,760	50	100
20 1 W 0031042 Amador Courthouse 03 C1 3 provide any banistic resistant protection.		23,022	. , y <u> </u>	.5,022	7 3,420,700	30	100
Grounds and Parking Lot - Court employee parking lot is deteriorated and severely cracked	d. Several						
areas present safety/trip/liability hazards. Due to deterioration it is recommended to cold	mill						
approximately 1,100 SF down to the sub grade (4" depth) in (2) areas to correct pavement	t failure. The						
remaining 14,400 SF will be cold milled down to 1 1/2" to provide a level base for the new	surface	ı			_		
27 FM-0056760 San Diego Juvenile Court 37-E1 3 course of asphalt; apply prime coat, waterproofing and tack coat to 14,400 SF.	D A d mind sins s	70,850) \$ 7	70,850	\$ 3,491,610	50	100
Plumbing - Remove and replace 7 recessed wall drinking fountains and 1 surface mount Al	_						
Alhambra fountain. Eight drinking fountains in the public areas of the courthouse are deteriorated ar	iiu ai e iiut	37,098	2 5 2	21 QN/I	\$ 3,523,514	55	86
	una drinkina	, 37,030	, , , <u> </u>	,1,504	7 3,323,314		- 50
Chatsworth Plumbing - Remove and replace 8 high-low recessed drinking fountains and 3 ADA wall hui	ing arinking i						

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	EACH ITY MODIEICATION	NM BUDGET SI	CUMULATIVE TOTAL OF FACILITY MODIFICATION	OGRAM SHARE OF ELIMINARY ESTIM	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
						Energy Efficiency - Lighting - Replace a total of 305 light fixtures throughout the facility. Remove: (19)								
			Manteca Branch			T12 light fixtures, (73) Compact Fluorescents, (201) T8 Light Fixtures, (2) Incandescent Light Fixtures								
30	FM-0053476	San Joaquin	Court	39-C1	3	and (10) Metal Halide Light Fixtures. All fixture will be replaced with LED fixture	\$	69,115	\$	69,115	\$ 3,6	42,962	55	100
						Energy Efficiency - Lighting - Replace a total of 141 light fixtures throughout the facility. Remove: (16)								
24	ENA 0053403	Cara Lagarria	Lodi Branch -	20.52		Compact Fluorescents, (109) T8 Light Fixtures, and (12) Incandescent Light Fixtures. All fixtures will be	۲,	25.055	۲ ا	25.055	 	70 047		100
31	FM-0053492	San Joaquin	Dept. 2	39-D2	3	replaced with LED fixture	\$	35,955	\$	35,955	\$ 3,6	78,917	55	100
22	FM-0054905	Los Angolos	Torrance Courthouse	19-C1	2	Grounds and Parking Lot - Replace asphalt, Slurry coat and restripe parking lot (285,000sq)	ڔ	265,000	\$	225,621	\$ 20	ιΩ4 52 9	55	85.14
32	1101-0034303	LOS Aligeles	Courtifouse	19-01	+	COUNTY MANAGED - Plumbing - **Water Conservation Project** - Replace all domestic water fixtures	٦	203,000	٧	223,021	7 3,3	704,336	33	65.14
33	FM-0057042	San Mateo	Hall of Justice	41-A1		w/new water saving fixtures; Install sub meters (2) at Water Cooling Towers.	ς	156,229	\$	82,333	\$ 30	86 871	55	52.7
33	1111 00370 12	San Mates	New Amador	11 / (1		Withew water saving fixtures, install sub-ineters (2) at water cooling rowers.	7	130,223	7	02,333	7 3,3	700,071	33	32.7
			County			Energy Efficiency - Electrical - Replace 339 T-8 Fluorescent Bulbs with LED, Replace 271 CFL Bulbs								
34	FM-0057137	Amador	Courthouse	03-C1		(Various 2 and 4 pin bases and 13-42watt) with LED.	\$	36,000	\$	36,000	\$ 4,0	22,871	55	100
					1	Exterior Walls - Prepare and apply anti-graffiti coating to all exterior walls from grade to 10ft high		,		,	, ,	,		
			Civic Center			(approx. 6700sqft) - janitorial efforts are having minimal results, time consuming and causing public								
35	FM-0052775	San Francisco	Courthouse	38-A1	3	hazard at sidewalks	\$	62,248	\$	62,248	\$ 4,0	85,119	58	100
						Grounds and Parking Lot - Slurry coat, re-stripe the parking lot and paint the curbs as required. The								
			Kearny Mesa			striping is fading to where directional arrows and lane markings are, making it difficult for people to								
36	FM-0052331	San Diego	Traffic Court	37-C1	3	see.	\$	18,771	\$	18,771	\$ 4,1	.03,890	60	100
		Santa	Santa Maria											
37	FM-0052763	Barbara	Courts Building G	42-F5	3	Roof Access - Replace Roof Access Window with Door/Landing/Handrailing - Safety Hazard.	\$	28,896	\$	27,882	\$ 4,1	.31,771	60	96.49
						Convitor Interior Finishes Converted and action converted Install approximately 100 linear foot of bourier								
						Security - Interior Finishes - Secure transaction counter - Install approximately 100 lineal feet of barrier								
						wall and public transaction counter with twelve (12) 4 wide forced entry resistant laminated glass								
20	FM-0052781	Colono	Hall of Justice	48-A1		transaction windows, to ensure the safety of the family law clerks. There have been numerous security incidents involving disgruntled public customers including punching, spitting and verbal altercations.	۲	260,145	Ś	260,145	¢ 43	01 016	60	100
36	FIVI-0032761	Solario	nail of Justice	40-A1	3	Security - Replace the courthouse storefront glass with shatter proof Lexan materials. The courthouse	γ	200,143	ې ا	200,143	<i>ې</i> 4,3	91,910	00	100
						has been vandalized with the front door glass broken out several times the past few years. This project								
39	FM-0056719	Shasta	Main Courthouse	45-A1	3	will minimize damage to the storefront and eliminate broken glass shards.	Ś	11,922	Ś	11,922	\$ 4.4	03.838	60	100
	00007 20		Historic	10 712	-	HVAC - Two (2) Carrier Split Systems - Install two (2) Carrier or equivalent split systems to provide air to	7		7		Ψ .,			
40	FM-0045287	Glenn	Courthouse	11-A1		the Judge's Office and CEO's Office - SAFETY, ENERGY.	\$	24,579	\$	24,579	\$ 4,4	28,417	65	100
						Holding Cell - Construct (3) new holding cell. The single in-custody holding cell located in the older		,			, ,	,		
						section of the courthouse is currently holding criminal cases and will be use for the expansion. The								
			Butte County			project goal is to accommodate larger number of simultaneous in-custody classifications and increase								
41	FM-0052382	Butte	Courthouse	04-A1	3	overall holding capacity.	\$	288,960	\$	288,960	\$ 4,7	17,377	65	100
			Manteca Branch											
42	FM-0053493	San Joaquin	Court	39-C1	3	Energy Efficiency- HVAC; Replace 15 year old 3-ton package unit with energy efficient model.	\$	9,871	\$	9,871	\$ 4,7	27,248	65	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	NO ITACIEI COM VEI II OM	PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
			Glendale			Grounds and Parking Lot - Replace concrete employee patio (1,000sf). Concrete patio is cracked and not level in several areas. In addition, of section of the patio is missing concrete. Health and Safety risk						
43	FM-0054927	Los Angeles	Courthouse	19-H1	3	to employees, that could trip and fall.	\$ 16,000	\$	14,486	\$ 4,741,735	65	90.54
	FM-0055147		Parking Structure Lot 94 Airport Courthouse West Covina	19-AU2		Exterior Shell - Restore stairways (15,00 sq. ft. of surface area). Stairways are badly rusted and need to be restored, rust starting to eat through metal frame causing damage to the metals integrity. Elevator (Wheelchair lift) - Units 1 - 3, Replace defective parts, make adjustments, service and return to safe operation. Currently units operate with the door open which is unsafe to the public. This work is	\$ 127,757	\$		\$ 4,840,325		77.17
	FM-0051535 FM-0053551	3	Courthouse Solano Justice Building	19-X1 48-B1	3	Interior Finishes - EARTHQUAKE - Remediate all cracks and aesthetic damage created by earthquake throughout building in secured hallways, courtrooms 101-104, and jury courtyard scaffolding is required. Epoxy injection at concrete wall, 35 lin ft. and approx. 650 sq ft of drywall and stucco repairs.	\$ 28,184	\$	20,099	\$ 4,863,720 \$ 4,883,819	68	
47	FM-0051115	Santa Clara	Downtown Superior Court	43-B1	3	Energy Efficiency measure - Install 1 new Variable Frequency Drive (VFD) on the existing chilled water pump, install a deferential pressure sensor (DP) and re-program the BAS to modulate the chilled water flow- this will reduce energy consumption-expected pay back is 19.6 years.	\$ 58,896	\$	58,896	\$ 4,942,715	70	100
48	FM-0051519	Contra Costa	George D. Carroll Courthouse	07-F1	3	Energy Efficiency Project - Electrical - Install new lighting control system; Install 66 new occupancy sensors; Retrofit 36 four lamp light fixtures to 2 lamp fixtures; Engineering and design - Energy savings \$14,000.00 per year	\$ 222,699	\$	167,002	\$ 5,109,717	70	74.99
49	FM-0051527	San Luis Obispo	Courthouse Annex Clara Shortridge	40-A1	3	Interior Finishes - Replace existing warn and defective seating with new auditorium style fixed seating - 16 standard seats and 2 ADA seats. Work is needed to maintain acceptable courtroom seating.	\$ 22,941	\$	22,941	\$ 5,132,658	70	100
50	FM-0051776	Los Angeles	Foltz Criminal Justice Center	19-L1	3	Plumbing - Rebuild drinking fountains' water supply piping lines, filtration system and cooling (optional)system to put back drinking fountains in operational condition in all floors' public hallways	\$ 95,293	\$	65,552	\$ 5,198,210	70	68.79
	FM-0052782		New Downtown Merced Courthouse	24-A8	3	Security - Expand the vestibule and add a covered staging area - Remove the existing store front and provide a separate storefront in the new location, level the existing alcove concrete to expand the new interior security vestibule, construct a new 1,800 SF covered walkway and staging area, this will require a single 400 SF tilt concrete panel, sixteen (16) column footings, two (2) new 3'6" power activated storefront doors, transparent roof panels at the covered walkway and staging areas, two new cameras at the staging area and approximately 800 SF of flooring and t-bar ceiling at the lobby and vestibule. This work is required to alleviate security issues at the main entry due to inadequate circulation.	704,856	\$		\$ 5,903,066	70	

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF	ИАТЕ	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
						Exterior Shell - Remove, replace, or restore approximately 80 lf of 2 1/2" x 11" bottom ledger, 48 lf of							
						2" x 6" fascia and trim, and 96 lf of 1" x 12" fascia; remove small section of existing white gutter and							
						install 25 If gutter and 1 down spout to match as close to exterior brown color; caulk and patch trim							
 -2	EN4 00F2920	Vings	Avenal Court	16 61		areas as required to receive paint; paint all exterior brown color only - Existing wood fascia and trim is	ے ا	22 167	<u>ر م</u>	0.00	¢	70	F9 01
52	FM-0052829		Avenal Court S. Bay Municipal	16-C1	3	cracking, splitting, and deteriorating due to fungus and weather damage. Roof - Overlay existing roof with new PVC roof system approximately 4,00 sq. ft. Due to roof system	Ş	22,167	\$ 12	2,859	\$ 5,915,925	70	58.01
			Traffic Court			currently being in poor to fair condition, remaining service life is less than 5 years. Overlay of existing							
53	FM-0053393	Los Angeles	Trailer	19-C4	2	roof system will bring the building to good condition.	ر	47,678	\$ 10	1 502	\$ 5,956,518	70	85.14
33	1 101-0033393	LOS Aligeles	Tranei	19-04	3	HVAC - Fall Protection - Design, build and install a custom service platform w/catwalk to access the top	٦	47,076	γ 40	,,,,,,,	\$ 3,330,318	70	03.14
						of the cooling tower during routine & predictive maintenance. Provide access ladder w/safety cage and							
			West Justice			gate to access elevated walkway. Add fall protection where necessary to provide safe access and to							
5/	FM-0052420	Orange	Center	30-D1	2	comply with OSHA regulations.	۲	70,878	\$ 60	1,272	\$ 6,020,791	74	90.68
34	1101-0032420	Orange	Center	30-01	3	Interior Finishes - Earthquake Restoration of cracks and aesthetic damages to approx. 7100 sq ft of the	٦	70,878	γ 0 ²	+, ∠ / ∠	Ş 0,020,791	74	30.08
55	FM-0053444	Contra Costa	Bray Courts	07-A3	2	interior building	۲	46,812	¢ Λ(0,034	\$ 6,060,824	75	85.52
33	1101-0055444		Mental Health	07-A3	3	Roof - Overlay existing roof with new PVC roof system approximately 27,000 sq. ft. Due to roof	٦	40,012	γ 40	7,034	Ş 0,000,824	73	65.52
56	FM-0052941		Court	19-P1	2	currently being in poor to fair condition, overlay of existing roof will bring it to good condition.	ڔ	327,681	\$ 23	3,669	\$ 6,294,494	77	71.31
30	1101 0032341	LOS Aligeies	Court		-	Grounds and Parking Lot - Replace cracked and heaved/settled portions of concrete walkway to	7	327,001	γ 2 3.	,005	7 0,234,434		71.51
57	FM-0051874	Solano	Hall of Justice	48-A1	3	eliminate potential tripping hazards.	\$	26,081	\$ 19	3,992	\$ 6,313,486	79	72.82
57	1101 0031074	3010110	Hayward Hall of	10 / 1	+ -	Interior Finishes - Safety - Replace damaged carpet in Room 521 Jury assembly area. There's a 10' split	 	20,001	7 10	J,JJ2	γ 0,313,400	7.5	72.02
58	FM-0046917	Alameda	Justice	01-D1	3	in the carpet. Impact to Court-Jury deliberation room. Jurors can trip and fall	5	5,224	Ś	5,224	\$ 6,318,710	80	100
	1101 00 10317	7 Harricaa	Justice	01 01		COUNTY MANAGED - Interior Finishes - Replace All Interior Door Hardware Failing - Low Quality/Failing	7	3,221	Υ	3,221	7 0,310,710		100
			Juvenile			- County Managed Recommended by County/MP - Bldg was built in 2005. Per County, "Hardware is of							
59	FM-0052844	Ventura	Courthouse	56-F1	3	low quality, failing and is no longer being made.	\$	73,204	\$ 73	3,204	\$ 6,391,914	80	100
						Elevators, Escalators, & Hoists - Remove and replace laminate on doors of Elevator #1 on floors 1, 6, 7,	T	7 0/20 1	7	,,=0 :	+ 		
						and 8, Elevator #2 on floors 1, 5, 8 and 9, Elevator #3 on floors 3, 6, 7, 8 and 9 and Elevator #4 on							
						floors 1, 2, 5, and 8. Elevators 1-4 have several doorways on different floors delaminating. This is a							
			Airport			safety hazard as its possible for clothing to be caught in the door causing bodily harm or the door skins							
60	FM-0056759	Los Angeles	Courthouse	19-AU1	3	falling off and striking passengers outside the elevators.	\$	209,737	\$ 16:	1,854	\$ 6,553,768	80	77.17
					1	Energy Efficiency Retrofit Project - Install occupancy sensors for lighting control in core restrooms on		,	•	,	, ,		
61	FM-0050684	Santa Clara	Old Courthouse	43-B2	3	floors 1-3 - EEM 5	\$	16,727	\$ 16	5,727	\$ 6,570,495	85	100
			East County		1			·	-	-	,	+	
62	FM-0052843	Ventura	Courthouse	56-B1	3	ENERGY EFFICENCY - COUNTY MANAGED - Electrical - Interior Lighting Retrofit	\$	129,518	\$ 129	9,518	\$ 6,700,013	85	100
			County		1	Roof - Cut in five (5) 18" x 18" fire rated ceiling hatches to obtain visibility to roof drains from within							
63	FM-0057115	Mendocino	Courthouse	23-A1	3	the building in ACM Environment.	\$	16,528	\$ 13	L,176	\$ 6,711,189	85	67.62
			Fresno County		1	Electrical - Install a pole mounted solar panel and pole mounted LED light that will cast on the flag 24-7	-				-		
C 4	FM-0040499	Fresno	Courthouse.	10-A1	3	This will allow the flags to remain flying 24-7 and be consistent with the US Flag Code	\$	8,615	\$	8,615	\$ 6,719,804	90	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF		CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
						Elevator - Elevator Renovation - Complete renovation of fourteen (14) geared traction elevators. Work							
						will include but not be limited to, car frames and platforms, buffers and safeties, hoistway entrance							
			Edmund D.			frames, doors and pit equipment, new AC gearless machines, micro-processor control systems,							
			Edelman			regenerative VVVF AC drives, fly ball governors, current code required wiring, interior and lobby							
65	FM-0054462	Los Angeles	Children's Court	19-Q1	3	control panels, car and hall door panels with new doors, counterweights and (see addtl description)	\$ 4	1,741,771	\$ 3,318	3,766	\$ 10,038,570	90	69.99
			Clara Shortridge			Electrical - Installation of a Automatic A-B Transfer Switch from Generator #1 to back-up Generator #2							
			Foltz Criminal			for emergency power backup. Need to install an Automatic Transfer Switch, if Generator #1 fails,							
66	FM-0054723	Los Angeles	Justice Center	19-L1	3	Generator #2 will automatically start.	\$	60,340	\$ 41	,508	\$ 10,080,077	90	68.79
			Betty Lou			Exterior - Safety-Security - Install new metal awning with post and anchors. (126LF x 7'W) at front							
			Lamoreaux Justice			entrance and side of building. Members of the public are in long lines which causes discomfort for the							
67	FM-0044066	Orange	Center	30-B1	3	public during inclement and hot weather.	\$	62,598	\$ 50	,047	\$ 10,130,125	95	79.95
			Pasadena			Interior Finishes - Replace Aluminum molding channels throughout the 1st floor. Aluminum molding							
68	FM-0045291	Los Angeles	Courthouse	19-J1	3	channels are falling, personnel may get hurt or trip over, safety hazard.	\$	9,509	\$ 6	5,594	\$ 10,136,719	95	69.35
			Pasadena			HVAC - Pneumatic controls that control the HVAC unit are not working properly. Replace pneumatic							
69	FM-0045293	Los Angeles	Courthouse	19-J1	3	controls to improve overall system performance.	\$	14,634	\$ 10	,149	\$ 10,146,868	95	69.35
			Shafter/Wasco			Security - Enhance parking by adding Judges Secure Parking and Access to the Courthouse - Branch							
70	FM-0050343	Kern	Courts Bldg.	15-E1	3	suffers from lack of secure parking.	\$	76,230	\$ 76	,230	\$ 10,223,098	95	100
			Morgan Hill			Energy Efficiency Project - Retrofit Exterior Parking Lot Lighting from 250w Metal Halide to 150w LED							
71	FM-0050766	Santa Clara	Courthouse	43-N1	3	lamps	\$	63,508	\$ 63	,508	\$ 10,286,606	95	100
			Gordon Schaber										
			Sacramento			Plumbing - To abate and remove two (2) abandoned boilers and associated plumbing and equipment -							
72	FM-0051791	Sacramento	Superior Court	34-A1	3	Boilers have been decommissioned and abandoned in place and are occupying valuable space.	\$	100,104	\$ 100),104	\$ 10,386,710	95	100
			Parking Structure Lot 59- Whittier			Grounds and Parking Lot - Install new safety enclosures throughout the garages existing openings for the first 2 floors. Install new rolling safety gate (with card reader), electrical installation to the panel							
73	FM-0052978	Los Angeles	Admin CTR	19-AO2	3	and low voltage (for new gate motor) and approx. 550 LF of new welded iron fencing and mesh.	\$	153,654	\$ 132	2.803	\$ 10,519,513	95	86.43
					†		7		γ	,,,,,	+ _=,,==,,==		
			Butte County			Grounds and Parking Lot - Fence/Security - Install 990 linear feet of 9' gauge chain link fencing at 7'							
74	FM-0049852	Butte	Courthouse	04-A1	3	high. Install one 4' wide by 7' high swing gate on the West side of the fence line Security issues	Ś	35,015	\$ 35	.015	\$ 10,554,528	98	100
			Historical			Interior Finishes - Renovate jury assembly room - Remove fabric wall panels around air ducts and patch	'	/ -	,	,	1 2,22 ,2		
75	FM-0025783	Napa	Courthouse	28-B1	3	and paint walls, for soundproofing	\$	5,476	\$ 5	5.476	\$ 10,560,004	100	100
			Traffic/Small			Exterior Shell - Paint Exterior of Building at Awning over Doors Due to Rust and Items Removed from	7	7,11	7 -	,	+ _=,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
76	FM-0028850	San Mateo	_	41-A2	3	Walls	Ś	6,899	\$ 6	5.899	\$ 10,566,903	100	100
			County		†	Energy Efficiency Project - Electrical Lighting - Change Light bulbs, install photocell and sensors - Swap	T	-,	,	,	,,		
77	FM-0051344	Mendocino	·	23-A1	3	234 T12 Bulb and ballast to T8 install 3 occupancy sensors, install 3 photo cells	\$	66,703	\$ 45	.105	\$ 10,612,007	100	67.62
	5551517		333. 0.3000		+ -	Interior Finishes - Refurbish bench on the 2nd floor approximately 156 LF. These sections of bench	+	55,755	, 19	,	· _0,012,001		37.102
			New Mammoth			have become warped, split and cupped to the point where they are not only unsightly, but							
78	FM-0051155	Mono	Lakes Courthouse	26-B2	3	uncomfortable and potentially unsafe.	Ś	19,761	\$ 19	.761	\$ 10,631,768	103	100
, 0	1 5551155	1	1-220 0001 1110030	₁		1 miles man de la maria per contratiny announce	٢ _	10,,01	<u> </u>	,. • •	7 -0,001,700	-00	

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	~ ~ ~	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
70/			Central Justice	20.44		HVAC - Replace Air Handling units for improved control-efficiency - The air handlers are beyond their	١, ,	1 060 700		060 702	¢ 42 402 564	405	100
/9 F	-M-0040539	Orange	Center Clare	30-A1	3	replacement life cycle	\$ 1	1,860,793	\$ 1	.,860,793	\$ 12,492,561	105	100
	NA 0050696	Canta Clara	Santa Clara	43-G1	1	Energy Efficiency Detrofit Droject Install VED on cooling tower for and implement CMT reset. FEM 4	ے ا	22 000	۲	22 000	¢ 12 F26 260	110	100
80	FM-0050686	Santa Ciara	Courthouse	43-01	3	Energy Efficiency Retrofit Project -Install VFD on cooling tower fan and implement CWT reset - EEM 4	γ	33,808	ې ا	33,606	\$ 12,526,369	110	100
			Del Norte County			Energy Efficiency Project - Electrical - Modify/Change - Change existing T12 bulbs to T8 Bulbs, change							
81 6	M-0051356	Del Norte	Superior Court	08-A1	3	out existing Light Switches to Occupancy Sensors in courtrooms	Ś	19,683	\$	19.683	\$ 12,546,052	110	100
						COUNTY MANAGED - Electrical - 4160 Volt Breaker Upgrade. Replace 36yr old Breakers to improve	7		7		7 22,5 10,552		
82 F	-M-0052830	Ventura	Hall of Justice	56-A1	3	reliability of e-system	\$	91,073	\$	91,073	\$ 12,637,125	110	100
			Traffic/Small			Exterior Shell - Paint exterior of building (2 floors) Power wash, Prepare and Patch, Caulk - Due to	Ė	,		•	, , ,		
83 F	M-0034443	San Mateo	Claims Annex	41-A2	3	Concrete Spalling, Expansion Joint Deterioration, Faded Paint	\$	50,360	\$	50,360	\$ 12,687,485	115	100
			East County										
84 F	M-0039351	Ventura	Courthouse	56-B1	3	Plumbing - Install Low Flow Water Fixtures - Water Conservation & Efficiency	\$	13,128	\$	8,107	\$ 12,695,592	115	61.75
						Exterior Shell- Grind, sand and refinish rusted and damaged handrails on 2nd through 4th Floor							
			Bellflower			exterior balconies. Court Administrator concerned about condition. Paint flaking and sharp edges are a							
85 F	M-0041050	Los Angeles	Courthouse	19-AL1	3	problem	\$	42,813	\$	42,813	\$ 12,738,405	115	100
						Security - Install fencing for sheriff and staff secured parking - reduce potential custody escapes or							
86 F	M-0040339	Madera	Sierra Courthouse	20-D1	3	attacks - provide safety for court staff and patrons	\$	167,594	\$	113,964	\$ 12,852,369	118	68
						Grounds and Parking Lot - Fencing - 30K sf, Install secured fencing with card reader access for judges							
87 F	-M-0028372	Solano	Hall of Justice	48-A1	3	parking lot for security from the public - Contingency Only	\$	146,751	\$	146,751	\$ 12,999,120	120	100
	- 1 4 00 4 40 60		Central Justice	20.44		Exterior- Roof - replace deteriorated roof mounted non-OSHA compliant equipment tie offs with OSHA	_ ا	220.462	_	200.040	¢ 42 200 000	420	04.47
88	-M-0044063	Orange	Center	30-A1	3	approved roof equipment tie-offs.	\$	230,163	\$	209,840	\$ 13,208,960	120	91.17
			Miloy M. Manual										
100	M-0051373	Alamoda	Wiley W. Manuel Courthouse	01-B3	2	Energy Efficiency project - HVAC - Install VFD's - install (2) VFD for EF 1&2,	ر	176,372	خ	147 900	\$ 13,356,759	120	83.8
89 1	101-0031373	Alameda	Courtilouse	01-03	3	Energy Efficiency project - HVAC - Histail VPD's - Histail (2) VPD for EF 1&2,	Ą	170,372	ې ا	147,800	3 13,330,739	120	03.0
			Berkeley			Energy Efficiency Project - Electrical - Install Reflective window film, photo cells, occupancy sensors- 79							
100	M-0051385	Alameda	Courthouse	01-G1	3	windows of reflective tint, 2 photo cells at lobby and stairwell, install occupancy sensors in courtrooms		46,117	\$	46 117	\$ 13,402,876	120	100
	5551505	, darriedd	George E.	0- 0-	+ -	Energy Efficiency Project - HVAC - Restore Economizer Dampers and Actuators, install VFD (4) - Restore	1	.0,11		. 0, ± ± 1	7 23, 102,070	120	
			McDonald Hall of			Damper and Actuators (5), install 2 VFD to Supply and Return Fan on unit #1, install 2 VFD to Primary							
91 F	M-0051473	Alameda	Justice	01-F1	3	Chilled Water Pumps	\$	86,530	\$	86,530	\$ 13,489,406	120	100
	-					· · · · · · · · · · · · · · · · · · ·	<u> </u>	,	'	, -	, , , , , ,		
						HVAC-Demolish two (2) existing HVAC evaporator condensers-HVAC condensers are obsolete and were							
92 F	M-0040579	Merced	Old Court	24-A1	3	replaced with new energy efficient package units. Includes crane, trucking and dump fees	\$	12,922	\$	12,922	\$ 13,502,328	130	100

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM BUDGET SHARE OF PRELIMINARY ESTIMATE	CUMULATIVE TOTAL OF FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	TOTAL SCORE RANK	FACILITY MODIFICATION PROGRAM % OF COST
93	FM-0053022	Riverside	Larson Justice Center	33-C1	3	Grounds and Parking Lot - East Parking Lot - Create and install 80 parking stalls out of perimeter landscape around the current lot. The recent closure of the County lot behind the courthouse, closure of the Court Annex/County building next door and its parking lot, and the building of a County Law building next door have created a serious parking issue in the immediate area of the Larson Justice Center resulting in a 200+ parking stall loss. Customers are currently parking on the landscape.	Ś	485,040	\$ 391,961	\$ 13,894,289	130	80.81

Meeting Date: 1/15/2016

Action Item 5 – (Action Required) – Energy Efficiency Projects

Summary:

Energy Efficiency Projects from List D

Total Project Count:	3
Total Potential FM Budget Share of Cost:	\$139,830

Supporting Documentation:

• List D – Facility Modifications Over \$50K

Action Requested:

Staff recommends three projects – items #16, 17, & 18 on List D – for a total cost to the Facility Modification Program Budget of \$139,830.

Action Item 5 Energy Efficiency Projects

- 1. Gordon B. Schaber
 - Install LED lighting in courtrooms
- 2. Carol Miller Justice Center
 - Install LED lighting in parking lot
- 3. West Central Justice
 - Install VFDs

Action Item 6 – (Action Required) – List E – Court-Funded Facilities Requests (Facility Modifications)

Summary:

Review Court-Funded Facilities Requests (Facility Modifications) from List E.

• San Diego Superior Court requests a small project annual budget of \$15,000

Meeting Date: 1/15/2016

• Santa Barbara Superior Court requests one facility modification totaling \$128,653

Supporting Documentation:

• List E – Court-Funded Facilities Requests (Facility Modifications)

Action Requested:

Staff recommends two Court-Funded Facilities Requests for review and approval.

ITEM #	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	CFR DESCRIPTION	CFR TERM	FUND SOURCE	CURRENT YEAR COSTS FY 15-16	es existing	BUDGET YEAR COSTS	TOTAL CFR COMMITMENT (CFR Term)	REVIEW NOTES - Real Estate and Facilities Management, Capital Program, and Finance
		San			Annual	Convert existing Rule 10.810 MOU into Rule 10.810/Small Project IBA to allow for small	One-						
1	37-CFR023	Diego	37-A2	Hall of Justice	Budget	CFR FMs (less than \$15,000 each) throughout the fiscal year.	Time	TCTF	\$	15,000	\$ 15,000	\$ 15,000	Pending
		Santa		Santa Maria Courts, Bldg F	Facility	The wall separating the two existing jury assembly rooms severely limits the current needs of the jury operations. Removal of the wall and fixed theatre seating (and replacement with accordion wall and stackable seating) could turn the two rooms into one multi-purpose room better serving the public called to jury duty in Santa Maria as well as creating a flexible meeting and training facility on the court campus.	One- Time	Non-TCTF				\$ 128,653	

Action Item 7 – TCFMAC Annual Agenda

Summary:

Review draft TCFMAC 2016 Annual Agenda.

Supporting Documentation:

• Draft Annual Agenda

Action Requested:

Provide input and additions to draft document and approve release to E&P upon revision.

Meeting Date: 1/15/2016

<u>Trial Court Facility Modification Advisory Committee</u> Annual Agenda—2016

A	op	ro	ved	by	E&F	> :	

I. ADVISORY BODY INFORMATION

Chair:	Hon. Donald Cole Byrd, Presiding Judge of the Superior Court of California, County of Glenn						
Staff:	Mr. Patrick McGrath, Facility Operations Manager, Real Estate and Facilities Management						

Advisory Body's Charge: Rule 10.65. Trial Court Facility Modification Advisory Committee

(a) Area of focus

The committee makes recommendations to the council on facilities modifications, maintenance, and operations; environmental services; and utility management.

(b) Additional duties

In addition to the duties specified in rule 10.34, the committee:

- (1) Makes recommendations to the council on policy issues, business practices, and budget monitoring and control for all facility-related matters in existing branch facilities.
- (2) Makes recommendations to the council on funding and takes additional action in accordance with council policy, both for facility modifications and for operations and maintenance.
- (3) Collaborates with the Court Facilities Advisory Committee in the development of the capital program, including providing input to design standards, prioritization of capital projects, and methods to reduce construction cost without impacting long-term operations and maintenance cost.
- (4) Provides quarterly and annual reports on the facilities modification program in accordance with the council policy.

(c) Membership

The committee consists of members from the following categories:

- (1) Trial court judges; and
- (2) Court executive officers.

The committee includes the chair and vice-chair of the Court Facilities Advisory Committee, as non-voting members.

Advisory Committee Comment

The Judicial Council policy referred to in the rule is contained in the *Trial Court Facility Modifications Policy* adopted by the council. In the execution of Rule 10.65, the committee oversees and approves a \$65 million budget for facility modification expenditures at California courts.

Advisory Body's Membership: The committee consists of members from the following categories: Trial court judges and court executive officers. The committee includes the chair and the vice-chair of the Court Facilities Advisory Committee as non-voting members.

- Chair: Hon. Donald Cole Byrd, Presiding Judge of the Superior Court of California, County of Glenn (Voting Member)
- Vice-Chair: Hon. William F. Highberger, Judge of the Superior Court of California, County of Los Angeles (Voting Member)
- Hon. Jennifer K. Rockwell, Judge of the Superior Court of California, County of Sacramento (Voting Member)
- Hon. James L. Stoelker, Judge of the Superior Court of California, County of Santa Clara (Voting Member)
- Hon. Vanessa W. Vallarta, Judge of the Superior Court of California, County of Monterey (Voting Member)
- Mr. Michael M. Roddy, Court Executive Officer, Superior Court of California, County of San Diego (Voting Member)
- Ms. Linda Romero Soles, Court Executive Officer, Superior Court of California, County of Merced (Voting Member)
- Ms. Jeanine D. Tucker, Court Executive Officer, Superior Court of California, County of Tuolumne (Voting Member)
- Ms. Christina M. Volkers, Court Executive Officer, Superior Court of California, County of San Bernardino (Voting Member)
- Hon. Brad R. Hill, Chair of the Court Facilities Advisory Committee, Administrative Presiding Justice of the Court of Appeal, Fifth Appellate District (Non-voting Member)
- Hon. Patricia M. Lucas, Vice-Chair of the Court Facilities Advisory Committee, Judge of the Superior Court of California, County of Santa Clara (Non-voting Member)

Subgroups/Working Groups: N/A

Advisory Body's Key Objectives for 2016:

- Implement Rule 10.65 Trial Court Facility Modification Advisory Committee
- Implement Policy *Trial Court Facility Modifications Policy*;
- Implement Charge Trial Court Facility Modifications Working Group Charge; and
- Increase legislative and executive branch understanding of trial court facility operations and funding needs.
- Revise TCFMAC Implementation Guideline for the Facility Modification Policy and Court Funded Request Procedure
- Implementation and evaluation of an update to the Seismic data set developed during the Transfer Process
- Increase and implement water conservation and energy efficiency efforts and best practices

II. ADVISORY BODY PROJECTS

#	Project	Priority	Specifications	Completion Date/Status	Describe End Product/ Outcome of Activity
1.	Trial Court Facility Modification Advisory Committee (TCFMAC) provides continuous review of proposed facility modification projects that have been identified as potential projects by judges, court staff, regional service providers, VFA, Inc., and Judicial Council staff. These potential projects are evaluated by the Judicial Council's Real Estate and Facilities Management staff and are evaluated using specific criteria pursuant to the Judicial Council policy and then presented for review to the advisory committee. Judicial Council staff and the TCFMAC meet in-person or via teleconference every 30 to 60 days to review the proposed projects. The advisory committee does not always agree with staff recommendations and does not always agree with staff application of specific criteria resulting in the prioritization. The proposed project list is reviewed and upon concurrence of the advisory committee, projects are either approved or denied for execution by staff.		Judicial Council Direction: Trial Court Facility Modifications Policy, Section 5.B and Trial Court Facility Modifications Working Group Charge Origin of Project: Judicial Council direction Resources: Real Estate and Facilities Management (REFM), Capital Programs (CP), and Office of Security (OS). Key Objective Supported: Goal VI: Branchwide Infrastructure For Service Excellence - The judicial branch will enhance the quality of justice by providing an administrative, technological and physical infrastructure that supports and meets the needs of the public, the branch and its justice system and community partners, and that ensures business continuity.	Ongoing	Facility modifications are reviewed and either accepted or denied by the advisory committee. Approved projects receive funding allocations and then staff executes the projects.

#	Project	Priority	Specifications	Completion Date/Status	Describe End Product/ Outcome of Activity
2.	TCFMAC provides ongoing oversight to Judicial Branch facilities Operations & Maintenance spending via annual budget allocation approval and reevaluation as needed throughout the year. The committee also provides recommendations to the Judicial Council on facilities funding-related issues and policies.	1	Judicial Council Direction: Trial Court Facility Modifications Working Group Charge Origin of Project: Judicial Council direction Resources: Real Estate and Facilities Management (REFM), Capital Programs (CP), and Office of Security (OS). Key Objective Supported: Goal VI: Branchwide Infrastructure For Service Excellence - The judicial branch will enhance the quality of justice by providing an administrative, technological and physical infrastructure that supports and meets the needs of the public, the branch and its justice system and community partners, and that ensures business continuity.	Ongoing	Justify the ongoing operations and maintenance expenditures and submit annual budget allocation proposal in addition to policy proposals as needed.
3.	As of December 14, 2012, the advisory committee is responsible for providing ongoing oversight of policy issues related to the operations and maintenance of existing facilities, noncapital-related real estate transactions, energy management, and environmental management and sustainability. Typical duties include: • Review the Judicial Council Preventive Maintenance Plan • Support the Court Facilities Advisory Committee (CFAC) in the development of the	1	Judicial Council Direction: Trial Court Facility Modifications Policy, Section 5.B and Trial Court Facility Modifications Working Group Charge Origin of Project: Judicial Council direction Resources: Real Estate and Facilities Management (REFM), Capital Programs (CP), and Office of Security (OS). Key Objective Supported: Goal VI: Branchwide Infrastructure For Service Excellence - The judicial branch will enhance the quality of justice by providing an administrative, technological and physical infrastructure that supports and meets the needs of the public, the branch and its	Ongoing	Justify the ongoing operating expenses of the Judicial Council's existing building portfolio and assist the Capital Programs with design input that will reduce the long term operating and maintenance cost of future facilities.

#	Project	Priority	Specifications	Completion Date/Status	Describe End Product/ Outcome of Activity
	Capital Program with an emphasis on design methods to reduce construction cost without impacting long-term operations and maintenance cost. • Implement an energy management plan that will leverage utility rebates, energy saving materials, and other energy conservation tasks to make the California courts as sustainable as possible. Review and approve Court-Funded Facilities Requests including lease-related costs; allowable court operations expenditures under rule 10.810 of the California Rules of Court, and other facility improvements that are not allowable court operations expenditures under rule 10.810.		justice system and community partners, and that ensures business continuity.		
4.	The advisory committee will submit the following Court Facilities: Trial Court Facility Modification Quarterly Activity Reports to the Judicial Council as information only items: • Quarter 1 of Fiscal Year 2015—2016 in December 2015. The report will summarize actions taken by the advisory	1	Judicial Council Direction: Trial Court Facility Modifications Policy, Section 5.E and Trial Court Facility Modifications Working Group Charge Origin of Project: Judicial Council direction Resources: Real Estate and Facilities Management (REFM), Judicial Council Support Services (JCSS), and Editing/Graphics Group (EGG).	Submittal planned for the Judicial Council's December 2015 (Q1), February 2016 (Q2), June 2016 (Q3), and August 2016	Provide an information only report to the Judicial Council detailing the advisory committee's activities and a list of projects authorized for funding in the specified quarter.

#	Project	Priority	Specifications	Completion Date/Status	Describe End Product/ Outcome of Activity
	committee for the months of July 2015, August 2015, and September 2015. • Quarter 2 of Fiscal Year 2015—2016 in February 2016. The report will summarize actions taken by the advisory committee for the months of October 2015, November 2015, and December 2015. • Quarter 3 of Fiscal Year 2015—2016 in June 2016. The report will summarize actions taken by the advisory committee for the months of January 2016, February 2016, and March 2016. • Quarter 4 of Fiscal Year 2015—2016 in August 2016. The report will summarize actions taken by the advisory committee for the months of April 2016, May 2016, and June 2016.		Key Objective Supported: Goal VI: Branchwide Infrastructure For Service Excellence - The judicial branch will enhance the quality of justice by providing an administrative, technological and physical infrastructure that supports and meets the needs of the public, the branch and its justice system and community partners, and that ensures business continuity.	(Q4) meetings.	
5.	The advisory committee will submit the Court Facilities: Budget Allocations for Statewide Trial Court Facility Modifications and Planning in Fiscal Year 2016–2017 to the Judicial Council as an action item in July 2016.	1	Judicial Council Direction: Trial Court Facility Modifications Policy, Section 5.C and Trial Court Facility Modifications Working Group Charge Origin of Project: Judicial Council direction Resources: Real Estate and Facilities Management (REFM), Judicial Council Support Services (JCSS), and Editing/Graphics Group (EGG).	Submittal planned for the Judicial Council's July 2016 meeting	Request the Judicial Council review the facility modification and operations and maintenance budget report for fiscal year 2016-2017. If approved, staff will implement the budget.

#	Project	Priority	Specifications	Completion Date/Status	Describe End Product/ Outcome of Activity
			Key Objective Supported: Goal VI: Branchwide Infrastructure For Service Excellence - The judicial branch will enhance the quality of justice by providing an administrative, technological and physical infrastructure that supports and meets the needs of the public, the branch and its justice system and community partners, and that ensures business continuity.		
6.	The advisory committee will submit the Annual Report of the Trial Court Facility Modification Advisory Committee for Fiscal Year 2015-2016 to the Judicial Council as an information only item in December 2016.	1	Judicial Council Direction: Trial Court Facility Modifications Policy, Section 5.C and Trial Court Facility Modifications Working Group Charge Origin of Project: Judicial Council direction Resources: Real Estate and Facilities Management (REFM), Judicial Council Support Services (JCSS), and Editing/Graphics Group (EGG). Key Objective Supported: Goal VI: Branchwide Infrastructure For Service Excellence - The judicial branch will enhance the quality of justice by providing an administrative, technological and physical infrastructure that supports and meets the needs of the public, the branch and its justice system and community partners, and that ensures business continuity.	Planned for submittal to the Judicial Council's December 2016 meeting	Provide the Judicial Council a report detailing the advisory committee's activities and a list of projects authorized for funding from the past fiscal year.
7.	Develop and propose concepts for consideration for the branch Budget Change Proposals (BCPs). Submittal to the Judicial Council in July 2016.	1	Judicial Council Direction: Operational Plan Objective Origin of Project: To be proposed by REFM management team	Planned for submittal to the Judicial Council's July 2016 meeting	Increase funding allocations for the facility modification and operations and maintenance programs.

#	Project	Priority	Specifications	Completion Date/Status	Describe End Product/ Outcome of Activity
			Resources: Real Estate and Facilities Management (REFM), and Capital Programs (CP) Key Objective Supported: Goal VI: Branchwide Infrastructure For Service Excellence - The judicial branch will enhance the quality of justice by providing an administrative, technological and physical infrastructure that supports and meets the needs of the public, the branch and its justice system and community partners, and that ensures business continuity.		
8.	Finalize the Implementation Guideline for the Facility Modification Policy and Court Funded Request Procedure.	1	Judicial Council Direction: Operational Plan Objective Origin of Project: To be proposed by Real Estate and Facilities Management (REFM) Resources: Real Estate and Facilities Management (REFM), and Legal Services (LSO) Key Objective Supported: Goal VI: Branchwide Infrastructure For Service Excellence - The judicial branch will enhance the quality of justice by providing an administrative, technological and physical infrastructure that supports and meets the needs of the public, the branch and its justice system and community partners, and that ensures business continuity.	To be completed before July 2016	Update guidelines to align with updated Facility Modification Policy.
9.	Update the CFR procedure to increase the allowable expenditure threshold for Small Project Work.	1	Judicial Council Direction: Court-Funded Facilities Requests Procedure Origin of Project: To be proposed by Real Estate and Facilities Management (REFM)		

#	Project	Priority	Specifications	Completion Date/Status	Describe End Product/ Outcome of Activity
			Resources: Real Estate and Facilities Management (REFM) Key Objective Supported: Goal VI: Branchwide Infrastructure For Service Excellence - The judicial branch will enhance the quality of justice by providing an administrative, technological and physical infrastructure that supports and meets the needs of the public, the branch and its justice system and community partners, and that ensures business continuity.		

III. STATUS OF 2015 PROJECTS:

#	Project	Completion Date/Status
1	Advisory Committee Meetings	Ongoing
2	Operations and Maintenance Oversight	Ongoing
3	Court Facilities: Trial Court Facility Modification Quarterly Activity Report, Quarter 1 of Fiscal Year 2014-2015	Report submitted to Judicial Council as information only item on February 19, 2015
4	Court Facilities: Trial Court Facility Modification Quarterly Activity Report, Quarter 2 of Fiscal Year 2014-2015	Report submitted to Judicial Council as information only item on April 17, 2015
5	Court Facilities: Trial Court Facility Modification Quarterly Activity Report, Quarter 3 of Fiscal Year 2014-2015	Report submitted to Judicial Council as information only item on June 26, 2015
6	Court Facilities: Trial Court Facility Modification Quarterly Activity Report, Quarter 4 of Fiscal Year 2014-2015	Report submitted to Judicial Council as information only item on August 21, 2015
7	Court Facilities: Budget Allocations for Statewide Trial Court Facility Modifications and Planning in Fiscal Year 2015-2016	Judicial Council reviewed and approved the budget report on August 20, 2015
8	Court Facilities: Annual Report of the Trial Court Facility Modification Advisory Committee for Fiscal Year 2014-2015	Report submitted to Judicial Council as information only item on December 11, 2015

9	Budget: Fiscal Year 2016-2017 Budget Requests for Trial Court Facilities Operations	Completed August 20, 2015, results from DOF
	Needs	pending January 2016 release of Gov't budget
10	Status finalization of the Trial Court Facility Maintenance Pilot Program	Completed as of July 7, 2015. Results reported to the
		council as part of FY 14-15 Annual Report on
		December 11, 2015.
11	Finalization of the Implementation Guideline for the Facility Modification Policy and	Coordination with Legal Services; project completion
	Court Funded Request Procedure	extended to July 2016

IV. Subgroups/Working Groups - Detail

Subgroups/Working Groups: *N/A*

Action Item 8 – Quarterly Activity Report, Quarter 2 of Fiscal Year 2015-2016

Meeting Date: 1/15/2016

Summary:

Review draft *Trial Court Facility Modification Advisory Committee Activity Report for Quarter 2, Fiscal Year 2015-2016.*

Supporting Documentation:

• Draft Q2 Report

Action Requested:

Provide input and additions to draft document and approve release to E&P upon revision.



JUDICIAL COUNCIL OF CALIFORNIA

455 Golden Gate Avenue · San Francisco, California 94102-3688 www.courts.ca.gov

REPORT TO THE JUDICIAL COUNCIL

For business meeting on: February 26, 2016

Title

Court Facilities: Trial Court Facility Modification Quarterly Activity Report for Quarter 2 of Fiscal Year 2015–2016

Submitted by

Trial Court Facility Modification Advisory Committee Hon. Donald Cole Byrd, Chair Agenda Item Type Information Only

Date of Report January 4, 2016

Contact

Patrick McGrath, 916-643-8051 patrick.mcgrath@jud.ca.gov

Executive Summary

The Trial Court Facility Modification Advisory Committee (TCFMAC) has completed its facility modification funding for the second quarter of fiscal year 2015–2016. In compliance with the *Trial Court Facility Modifications Policy*, the advisory body is submitting its *Trial Court Facility Modification Quarterly Activity Report: Quarter 2, Fiscal Year 2015–2016* as information for the council. This report summarizes the activities of the TCFMAC from October 1, 2015, to December 31, 2015.

Previous Council Action

The Trial Court Facility Modification Working Group was established by Judicial Council policy in 2005. The working group first met in April 2006 and operated under the *Trial Court Facility Modifications Policy*, ¹ adopted by the Judicial Council in 2005 and revised on December 12, 2014. The working group's primary oversight responsibilities included reviewing statewide facility modification requests and approving facility modification funding.

The working group's charge was formalized by the Judicial Council on December 14, 2012, and the working group was assigned additional oversight responsibility for the operations and

¹ As adopted in 2005, the policy was known as the *Prioritization Methodology for Modifications to Court Facilities*. When it was revised in 2012, the name also changed. See www.courts.ca.gov/documents/jc-20120727-itemG.pdf.

maintenance of existing facilities, noncapital-related real estate transactions, energy management, and environmental management and sustainability. On April 25, 2013, the working group's status was elevated to that of advisory committee.

An updated Court-Funded Facilities Request (CFR) approval process was submitted and approved by the Judicial Council on August 23, 2013, requiring all CFRs to be reviewed and approved by the TCFMAC. These submittals may include lease-related costs (e.g., lease payments and operating costs, repairs, or modifications required by a lease); allowable court operations expenditures under rule 10.810 of the California Rules of Court (e.g., equipment, furnishings, interior painting, flooring replacement or repair, furniture repair, or records storage); and other facility improvements that are not allowable court operations expenditures under rule 10.810 (e.g., facilities operations, maintenance, repairs, and modifications, but not capital projects), if they would improve a court's functioning or reduce ongoing court operating costs.

Reports previously approved by the Judicial Council are available at www.courts.ca.gov/2567.htm under Research and Reports: Conditions in Our Courts.

Methodology and Process

Funding decisions were based on the prioritization and ranking methodologies in accordance with the *Trial Court Facility Modifications Policy*. Facility modifications are assigned one of six priority categories: Priority 1–Immediate or Potentially Critical; Priority 2–Necessary, but Not Yet Critical; Priority 3–Needed; Priority 4–Does Not Meet Current Codes or Standards; Priority 5–Beyond Rated Life, but Serviceable; and Priority 6–Hazardous Materials, Managed but Not Abated. These categories are based on methods commonly used by private-sector facility management firms. Facility modifications that are determined to be Priority 1 are to be addressed immediately and regardless of whether the court occupies a shared-use facility. With current budget constraints, the TCFMAC predominantly approves facility modification projects at the Priority 1 and Priority 2 levels. Delaying TCFMAC approval of these projects would cause continued court closures, operational failures, and undue risk to continued court operations.

Policy and Cost Implications

During the second quarter of fiscal year (FY) 2015–2016, the TCFMAC reviewed and approved a total of 362 facility modifications for a total projected cost of \$21,492,723. The Facility Modification Program's share of these projects totals \$18,123,570. These approved projects are limited to Priority 1 emergency projects and Priority 2 critical needs projects. Among other urgently needed projects, the committee approved 12 roof replacement projects in addition to the regular roof maintenance and repair projects. The committee also ratifies emergency projects, including a significant number of HVAC and electrical repairs. Please see Attachment A for a detailed list of all approved projects during the second quarter of FY 2015–2016.

During this quarter, 11 projects required additional funds in excess of \$50,000 from their original estimates. The Facility Modification Program's share of these cost increases totals \$2,487,473.

Projects that required excess costs of this magnitude were largely projects where project managers encountered unforeseen site or equipment conditions.

During this quarter, 12 Court-Funded Facilities Requests (CFR) were reviewed and approved by the TCFMAC. These included leases for the Superior Courts of San Diego, Santa Clara and Tulare Counties, and small-project CFRs for the Superior Courts of Alameda, Fresno, Humboldt, Los Angeles, Orange, San Bernardino, and San Francisco Counties. See Attachment B for a detailed list of CFRs approved by the TCFMAC during the second quarter of FY 2015–2016.

Implementation Efforts

The TCFMAC saw a change in leadership this quarter with the Chief Justice's appointment of existing member Judge Donald Cole Byrd to the role of committee chair after the retirement of previous chair Judge David Power. The committee also welcomed new member Judge Jennifer K. Rockwell of the Sacramento Superior Court this quarter. Prior to her appointment as judge in the traffic division, Judge Rockwell was Chief Counsel for the California Department of Finance. Under the new chair, the committee conducted two meetings—one in person in Sacramento on October 23, 2015, and one via teleconference on December 7, 2015—to review facility modification (FM) funding requests and to discuss the topics below.

- The committee conducted its regular review of facility modification projects lists: A (Emergency and Priority 1); B (FMs Under \$50K); C (Cost Increases Over \$50K); D (FMs Over \$50K Eligible for Funding); E (Court-Funded Facilities Requests); and F (Funded FMs on Hold).
- The committee received an update on water conservation efforts in support of the Judicial Council's Water Conservation Policy adopted earlier this year. These efforts include usage audits and regular meetings with courts on conservation practices.
- The committee prepared and submitted its FY 2014-2015 Annual Report to the Judicial Council. The report provides an overview and details on the committee's activities and budget expenditures over the course of the year.
- The committee reviewed and approved the *Trial Court Facility Modification Quarterly Activity Report for Quarter 1 of Fiscal Year 2015-2016.*
- The committee received an informational overview and update on the Facilities Policies Working Group's charge and activities.

Finally, please see the examples on the next pages of facility modifications projects that have been completed during this quarter. These examples illustrate the varied problems that California courthouses face on a regular basis, from emergency repairs and mitigation to projects identified during preventive maintenance rounds and readings. In any circumstance, it is the committee's emphasis, with Judicial Council facility management staff, to provide dedicated service and resolution to court users and employees throughout the state.

Completed Courthouse Project Spotlights

Priority 2 Project—Elevator Renovations at Santa Clara County Hall of Justice West—FM-0022152

The elevators at the Hall Of Justice West in Santa Clara County were in poor running condition and the court staff, the public, and the Sherriff's while transporting in custody's were suffering from multiple elevator entrapments. A Facility Modification project was awarded to Enovity under the JOC contract to refurbish the elevators which included the replacement of pulleys, belts, motors and other major components. The replacement of the obsolete, worn-out 30 year old gear wheels to gearless and the addition of smoke guards to the cabs, per the State Fire Marshal's inspection, were included in this project. Due to the complexity of their only being (1) in-custody and (1) public/staff elevator over the four-month duration of the project, there was huge coordination and teamwork with the JCC Facilities Management Unit, Court Management Staff and the Sherriff's Office to schedule the in-work rotation of the elevators. Weekly meetings took place thorough completion of this project to ensure the Court and the transportation of In-Custodies was not affected.

Final project cost was \$679,541.





Far Left:
Before –
photo of
the
mechanical
room while
removing
the old,
obsolete
gear
wheels.

Near Left: After – new gearless wheels.

Priority 2 Project—Construction of New Courtroom in Existing Space at Betty Lamoreaux Justice Center, Orange County—FM-0050564

With the closure of the Harbor Justice Center – Laguna Hills Facility, the Orange County Superior Court lost four courtrooms in July 2013. The Betty Lou Lamoreaux Justice Center was not able to absorb the additional Family Law hearings with its given courtroom space and necessitated an additional courtroom. Existing Domestic Violence Assistance Program work space was converted into the new courtroom and the DVAP was relocated to an alternate location.

Final project cost was \$828,251.





Left: Before – court-exclusive work space.

Right: After – new courtroom.

Next Steps

The *Trial Court Facility Modification Quarterly Activity Report: Quarter 3, Fiscal Year 2015–2016* will be submitted to the Judicial Council in June 2016.

Attachments

- 1. Attachment A: TCFMAC-Funded Project List: Quarter 2, Fiscal Year 2015–2016
- 2. Attachment B: Court-Funded Facilities Requests (CFR): Quarter 2, Fiscal Year 2015–2016

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Security - Replace the existing and antiquated Identification card access control system to a DSX access control system. The buildings' Identification card system is no longer manufactured or supported. The current servers				
1	FM-0009593	Butte	Butte County Courthouse	04-A1	2	and operating systems are outdated and will not support an updated access control system. System failures have had adverse effect on Court operations.	\$	74,672	\$74,672	100
2	FM-0017557	Los Angeles	Compton Courthouse	10-AG1	2	Plumbing - Replace failed Pressure Relief Valves on 2nd, 4th, 6th & 8th floors; valves are inoperable and require replacement. Replace failed Domestic Water Booster Pump package.	ڔ	389,860	\$257,814	66.13
	1101-0017337	LOS Aligeles	Compton Courthouse	13-AG1		Electrical - Replace two (2) 3.15M BTU Boilers and one (1) 750Kw Generator. Replacement is required in order	٦	383,800	7237,814	00.13
3	FM-0019392	Los Angeles	Downey Courthouse	19-AM1	2	to comply with current AQMD standards.	\$	796,699	\$ 666,837	83.70
						COUNTY MANAGED - Audience Seating, Dept 22 Ceremonial Courtroom - Remove and replace 102 audience				
	EN 4 0035653	Maraka wa	Hall of hoods	FC A4	_	seats (all) in this Courtroom. Damage includes torn fabric, exposed framework and 18 seats damaged beyond	_ ا	70.000	ć70 000	100
4	FM-0025652	Ventura	Hall of Justice	56-A1	2	repair. Interior Finishes - Refurbish a 65+ year old Terrazzo lobby floor that is approximately 2,000 square feet. Floor	\$	70,000	\$70,000	100
						has numerous cracks where many are more pronounced than others. Floor presents a higher risk to high heeled				
5	FM-0037757	Merced	Old Court	24-A1	2	shoes then flatware shoes.	Ś	101,008	\$101,008	100
			Edmund D. Edelman				†		, , , , , , ,	
6	FM-0041057	Los Angeles	Children's Court	19-Q1	2	HVAC - Replace metal front filters - System failure imminent	\$	11,522	\$ 11,522	100
			Alhambra	,		Electrical - Replace one (1) 250Kw Generator. ACM abatement required. Replacement is required in order to	<u> </u>	,,	,	
7	FM-0041137	Los Angeles	Courthouse	19-I1	2	comply with current AQMD standards.	\$	448,388	\$385,614	86
			Santa Barbara							
8	FM-0050594	Santa Barbara	Figueroa Division	42-B1	2	Security - Add handcuff portals to 8 cell doors - Security Risk/High	\$	3,096	\$ 3,096	100
			Santa Barbara			Interior Finishes - Reinstall electronic high volume record filing system. System was removed as part of a P1			4	
9	FM-0051229	Santa Barbara	Figueroa Division	42-B1	2	effort re-installation is required to return court to fully operational status.	Ş	50,000	\$50,000	100
10	FN4 00F2070	Los Angolos	Mhittian Counth auga	10 401	,	Roof - Remove and replace existing one story section of roof with new and overlay 5 story section of roof with	ے ا	742.000	¢641 211	96.42
10	FM-0052970	Los Angeles	Whittier Courthouse East Los Angeles	19-AU1		torch applied system. Renovation required due to age and water penetration.	Ş	742,000	\$641,311	86.43
11	FM-0052981	Los Angeles	Courthouse	19-V1	2	Roof - Remove and replace existing failing roof system with new PVC roof system (30,625).	5	715,093	\$555,770	77.72
	1111 0032301	Los / mgeres	Courtificase	13 11	_	Roof - Remove and replace existing failing roofing systems on main deck, 2nd and 3rd floor Northeast decks as	ļ ,	7 13,033	ψ333)770	,,,,_
			San Fernando			well as machine room roofs at the main roof (approximately 38,000) with a SBS roof System. Roof metal will be				
12	FM-0052988	Los Angeles	Courthouse	19-AC1	2	replaced as needed.	\$	807,176	\$673,266	83.41
						Roof - Remove and replace existing roof system at eleven different areas (20,000 SF). Due to the poor condition				
			Monrovia Training			of these areas, recommended removal and replacement of existing and building metal will bring entire building				
13	FM-0053002	Los Angeles	Center	19-N1	2	roof to good condition.	\$	450,000	\$316,305	70.29
			Albambra			Doof Domovo and replace existing roof with new CDC roof existent. Demove and replace approximately				
11	FM-0053003	Los Angeles	Alhambra Courthouse	19-I1	2	Roof - Remove and replace existing roof with new SBS roof system - Remove and replace approximately 31,800sf of failing built up roof system. Work will include new building metal, vents and walk pads as needed.	ر	699,821	\$601,846	86
14	1 101-0033003	LU3 Aligeles	Courtilouse	13-11		Roof - Remove and replace existing failing roof with new SBS roof system - Work to include replacing	٦	033,041	ουτ,ο 4 0	00
			Van Nuys Courthouse			approximately 25,000sf of failing built up roof, two roof drains, re-coat the Heli-Stop and replace building metal				
15	FM-0053004	Los Angeles	West	19-AX2	2	as needed.	\$	585,070	\$470,864	80.48

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Roof - Remove and replace existing roof with new SBS roof system - Work to include replacing approximately 34,000sf of failing built up roof, restore roof drains, install tapered insulation as needed and replace building				
16	FM-0053030	Los Angeles	Glendale Courthouse	19-H1	2	metal if not re-usable.	\$	757,338	\$685,694	90.54
17	FM-0053394	Los Angeles	Torrance Courthouse	19-C1	2	Roof - Remove and replace 40,000 square feet of the existing main deck and lower deck sections with new SBS roof system / Due to roof decks currently failing and leaking. Work to include new building metal, vent jacks and equipment curbs as needed	\$	845,633	\$719,972	85.14
						Roof - Remove and replace 43,000 sf of existing roof with new SBS roof system, currently the existing roof is in				
10	ENA 0053460	Los Angolos	Edmund D. Edelman	10.01	,	poor to fair condition at best, work will replace the roof at three building sections at various levels. New	ے ا	046 000	¢cc2 105	60.00
18	FM-0053460	Los Angeles	Children's Court	19-Q1	2	building metal and curbs will be replaced as needed. (No work to be done on the Heli - Stop). Roof - Remove and replace existing main deck, lower east deck and lower west deck (approximately 34,000 sf)	\	946,000	\$662,105	69.99
						with a SBS type roof system - Due to main and lower decks are past due and beginning to leak during rainy				
19	FM-0053549	Los Angeles	Downey Courthouse	19-AM1	2	weather.	\$	753,487	\$630,669	83.7
20	FM-0053554	Los Angeles	Pomona Courthouse South	19-W1	2	Roof - Remove and replace existing roof with new SBS roof system at main deck (23,220 sq. ft.), lower north deck (2,838 sq. ft.), and lower south deck (2,838 sq. ft.). Roofing metal will be replaced as needed.	\$	682,895	\$622,391	91.14
21	FM-0053561	Los Angeles	Metropolitan Courthouse	19-T1	2	Electrical - Failed Exterior Lighting - Replace a total of 98 exterior Mercury Vapor, High Pressure Sodium, and Fluorescent Light fixtures with high efficient LED fixtures. Remove and replace the failed lights and ballasts in 16 soffit areas (Each approximately 8'x8'). Building exterior lighting fixtures/poles have broken lenses, sockets, bulbs and ballasts making the area dark at night, safety issue. Parts are no longer available due to fixtures being outdated.		176,525	\$166,887	94.54
		J				Roof - Remove and replace 53,000 sf of existing roof with new SBS roof system, currently the existing roof is in		,		
			Santa Monica			poor to fair condition at best, work will replace the roof at three building sections at various levels. New				
22	FM-0054101	Los Angeles	Courthouse	19-AP1	2	building metal and curbs will be replaced as needed.	\$	1,114,341	\$874,646	78.49
23	FM-0054644	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	Grounds and Parking Lot - Replace waterproof membrane, sprinklers, and landscaping in planter on the exterior of the Courthouse near County Council Chambers. Due to years of deterioration the waterproofing membrane in the planter leaks through when there is excessive water present. This was the cause of a serious leak into the County Council Chambers in January 2014.		30,000	\$ 20,997	69.99
		J				Vandalism - Glass on elevators #1-4, glass panes on flrs 3 & 8 and men's public restrooms mirrors (all floors) have been vandalized by graffiti being etched into them. Need to remove etching to help prevent future vandalism/safety hazards. Resurface 24 windows and 33 mirrors with multistage polishing to remove graffiti, approximately 2 hrs per window. Remove 3 windows on 3rd flr due to deep etching and install (3) 105" x 65" x		,		
24	FM-0054783	Los Angeles	Airport Courthouse	19-AU1	2	1/2" laminated clear green Solex windows.	\$	72,260	\$55,763	77.17
-		Solano Solano	Hall of Justice Hall of Justice	48-A1 48-A1	2 2	Interior finishes - Atrium Doors - Replace worn-out and failing atrium door hardware on eight doors to include closers and pull handles and locks and pivot hinges and stops -Doors don't close causing a security issue. Roof - Replace roof. Phase II of existing/funded Phase I FM#50740	\$	41,011 1,341,198	\$ 29,864 \$ 976,660	72.82 72.82
						Exterior Shell - South Side Rotary Exit Door - Door Mechanism Failed/Non-Op - Repairs not possible due to age	Ť	. ,	,	
27	FM-0055052	Ventura	Hall of Justice	56-A1	2	and condition. Replacement is required.	\$	93,813	\$93,813	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
28	FM-0056596	Lassen	New Susanville Courthouse	18-C1	2	Security - Supply and install new Daikin mini split FTX24LVJU to monitoring office including all Electrical, line set and roof jack - The existing security is required to maintain site monitoring 24/7. Building design does not provide 24x7 support to this area. High weekend temps will cause the equipment premature equipment failure.	24,494	\$ 24,494	100
29	FM-0056653	Los Angeles	Torrance Courthouse Juvenile Justice	19-C1	1	Elevator - Custody elevator #4 - Replace defective parts (1) earthquake plate, (4) cover plate kits, (4) elsco seismic retainers, (8) stud support washers, (24) hex nuts, (4) roller glides and (1) can of LPS cutting fluid. Elevator had cracked roller guide and durng the replacement other critical renovations were identified. Plumbing - Water leak - Remediate wet interior finishes to include approximately 300 square feet of carpet and lower parts of adjacent sheetrock walls with dehumidifiers and fans - Work was performed on off hours and a	\$ 10,050	\$10,050	100
30	FM-0056654	Alameda	Center	01-C3	1	Sunday.	\$ 4,538	\$4,538	100
31	FM-0056655	Shasta	Justice Center Metropolitan	45-A2	2	COUNTY MANAGED - HVAC Controls Upgrade - The pneumatic controls that operated the HVAC system at the Jail/Justice Center are leaking and obsolete. This project replaces the original control system with Johnson digital controls. Interior Finish - Remove furniture and stretch carpets in 4 Depts. The carpets are lifting and creating ridges	\$ 25,000	\$25,000	100
32	FM-0056657	Los Angeles	Courthouse	19-T1	2	causing a tripping hazard.	\$ 7,720	\$7,720	100
			Santa Clara	42.04		Plumbing - Water heater has failed - Replace 1 each 74 gal. domestic hot water heater - Hot water is	4.006	44.006	100
		Santa Clara Los Angeles	Courthouse Compton Courthouse	43-G1	2	intermittent. Electrical - Replace (40) Defective 175W HID bulbs with 32W CFL bulbs by modifying existing wiring & conduit directly to bulb sockets and bypassing the defective ballasts on a total of 6 different floors in (14) court exclusive depts.	\$ 4,896 3,956	\$4,896 \$3,956	100
		San Bernardino	New San Bernardino Courthouse	36-R1	2	Security - Secure parking gate was hit by a sheriff's bus and bus damaged the sensor. Gates were inoperable due to failed photo eye. and the gate door was stuck open. Replaced two failed photo eyes on the rolling gates to the secured parking lot. ABM manually secured and opened gates daily until delivery of the replacement photo eye sensors.	\$ 2,671	\$2,671	100
	FM-0056662		Pomona Courthouse South	19-W1	2	Plumbing -Install (1) new Acorn stainless steel sink, (1) new Acorn stainless steel toilet; modify existing drain & water lines to accommodate new fixtures. The current porcelain sink & toilet in lock up cell #1 on the first floor are broken and need to be replaced by stainless steel.	\$ 9,603	\$8,752	91.14
37	FM-0056664	Los Angeles	Compton Courthouse	19-AG1	2	HVAC - Replace (2) deteriorated canvas flex connectors for Supply Fan #1 & Exhaust Fan #2. The canvas flex connector are breaking & the connectors have no more flex in them; this condition allows air to escape which can cause damage to ducting & can also cause motor strain. HVAC - The Indoor evaporator fan motor is deteriorated. Replace one existing 3 ton evaporator fan coil and	\$ 3,273	\$2,164	66.13
38	FM-0056666	San Diego	Kearny Mesa Traffic Court Kearny Mesa Traffic	37-C1	2	install one new required R-22 Thermostatic Expansion Valve (TXV). Need to replace the fan coil to prevent future downtime. Plumbing - Leaking Water Heater - Remove and replace one, 100 Gallon Water Heater, and extract water from	\$ 5,556	\$5,556	100
39	FM-0056667	San Diego	Court	37-C1	2	the public hallway. Plumbing - Provide remediation for flood on the second and third floors caused by a malfunctioning toilet; Provide two laborers for 6 hours to dry out the second and third floor jury rooms and hallways; Provide 2	\$ 3,208	\$3,208	100
40	FM-0056668	Contra Costa	Bray Courts	07-A3	2	dehumidifiers, 12 fans for three days - Toilet malfunctioned and flooded the hallways and jury rooms on two floors.	\$ 6,485	\$6,485	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Electrical - Install (2) new 20amp 120v electrical outlets in marked out spots on the wall in the old pay phone				
			Inglowed Invenile			area; run approx. 20LF of conduit & wiring inside wall, over top, and down to new dedicated 20amp breakers				
11	TN4 0056671	Los Angolos	Inglewood Juvenile	19-E1	2	installed on existing breaker box located inside nearby IT closet. Currently two vending machines are poorly	۲	4 420	¢2 E0E	80.78
41	FM-0056671	Los Angeles	Court North County	19-61		located in 2 separate areas on the first floor and the location is away from departments & public waiting areas. Electrical - Exit signs are dim and may not be visible in case of an emergency. Need to replace the exit signs as	Ş	4,438	\$3,585	80.78
			Regional Center -			this a potential safety issue. Isolate electrical circuit and replace 50 exit signs. Install 50 exit signs with battery				
42	FM-0056672	San Diego	Vista Center	37-F2	2	backup.	\$	4,775	\$4,775	100
'-	1101 0030072	San Biego	Vista Center	37.12		buckup.	<u> </u>	1,773	Ÿ 1,7 7 3	100
						Interior Finishes - Smoke Restoration - Replacement of 30 sq ft drywall, 260 pieces of 12x12 ceiling tiles, primer				
			North County			all painted walls with Kilz and apply final coat of paint, install 240 sq ft new carpet, replacement of 6 light				
			Regional Center -			fixture lens and thermostat. Short in personal fan unit creted a fire impacting Attorney / Client Mediation				
43	FM-0056676	San Diego	Vista Center	37-F2	1	Room between Dept. 15 and 17. Room is unavailable and restoration is needed to restore room to use.	\$	55,463	\$55,463	100
			Bellflower			HVAC - Condenser pump has failed and bearings seized, causing Chiller #2 to trip due to high pressure. Need to				
44	FM-0056682	Los Angeles	Courthouse	19-AL1	1	replace condenser pump and motor.	\$	20,443	\$15,933	77.94
						Grounds and Parking Lot - Cut down and remove (13) 25 ft trees that have grown to where they are blocking the				
						views of the security cameras; Grind the stumps and remove the debris; Plant 13 small, drought tolerant shrubs				
						in place of the trees. The trees are blocking camera views of the entry to the Judges parking lot, the sally port				
			Arnason Justice			entrance, the employee parking lot, and two public entrances to the Courthouse. This work is recommended by	_		4	
45	FM-0056683	Contra Costa	Center	07-E3	2	JCC Security Operations.	\$	5,843	\$5,843	100
						Diverbing Durin Line Leak, Demove and replace FO! of 3!! analysed Cost incoming and systmest approximately 10.				
						Plumbing - Drain Line Leak - Remove and replace 50' of 3" cracked Cast iron pipe and extract approximately 10				
			Metropolitan			gallons of water. Drain restriction in the 1st floor snack bar creating water to leak down to the Level A Sheriff's Women's Locker Room affecting 9'x7' hard lid ceiling. 9'x7'x9.5' ACM containment erected in locker room and 3				
16	FM-0056684	Los Angeles	Courthouse	19-T1	1	a stage wipe down on 12'x10' area on the 1st floor was required.	¢	15,000	\$14,181	94.54
		Lake	South Civic Center	17-B1	2	Interior Finishes - Install a baby changing station in both men's and women's restrooms.	ς ς	1,268	\$938	74
''	1111 0030003	Lake	South Civic Center	17 51		Plumbing - Rebuild booster pump #3 that is leaking. Currently the pump is leaking water and if it is not rebuilt,	Υ	1,200	7330	7 1
			Metropolitan			the pump could fail effecting water pressure to the upper floors which include all the bathrooms, cooling				
48	FM-0056687	Los Angeles	Courthouse	19-T1	2	towers and boilers.	\$	4,992	\$4,719	94.54
						Electrical - Uninterrupted Power Source (UPS) - Replace the Syncron AC Power Board, DC Power Board and	•		. ,	
						Inverter Control Board for Emergency Egress Lighting UPS 4. The emergency lights in Courtrooms W10 and W12				
49	FM-0056688	Orange	West Justice Center	30-D1	2	have failed. This was very disruptive to the Courtrooms.	\$	4,802	\$4,354	90.68
			Clara Shortridge Foltz			Plumbing - Toilet and Urinal Angle shut off valves replacement. Replace approx. 30 failed and damaged 1.5"				
			Criminal Justice			angle shut off on urinals and 3.5" angle shut off valves on toilets in various restrooms from P-Level up to the				
50	FM-0056689	Los Angeles	Center	19-L1	2	15th floor.	\$	4,978	\$3,424	68.79
						HVAC - The motor on AHU #4 has bad bearings & is ready to fail; if AHU#4 goes down the entire 4th floor will be				
			Alhambra			without air flow for heating/cooling. Replace (1) 25HP motor on Air Handler Unit #4 inside roof top mechanical				
51	FM-0056690	Los Angeles	Courthouse	19-I1	2	room using special rigging; re-use existing guards, belts, pulley, & commission motor to operate.	\$	4,539	\$3,904	86

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			East County Regional			Plumbing - Piping above the T-bar ceiling grid in the 5th floor D.A. office area was cracked and needed				
52	FM-0056691	San Diego	Center	37-I1	2	replacing. Replaced 10' section of 2" piping and fittings.	\$	2,454	\$1,662	67.71
						HVAC - Boiler #2 motor and pump have failed. Re-build one (1) pump and replace one (1) motor; install re-built				
53	FM-0056692	San Diego	Juvenile Court	37-E1	2	pump.	\$	4,524	\$3,376	74.62
						Fire Protection - Replace Fire Pump #1 heat exchanger core, install new gaskets & seals, thermostats and				
						alternator belts. Fire Pump #1 heat exchanger has a water leak. Heat exchanger is meant to keep diesel engine				
54	FM-0056693	Los Angeles	Compton Courthouse	19-AG1	2	at an allowable temperature while running.	\$	30,761	\$ 20,342	66.13
55	FM-0056695	Solano	Hall of Justice	48-A1	2	Elevators -Remove protruding wires from concrete wall inside hoist way based on DIR notice.	\$	3,432	\$2,499	72.82
						HVAC - AHU-3 is not operating properly - AHU-3 solenoid valve must be replaced and strainer must be				
						unclogged. The failed system is affecting the cooling of the elevator - mechanical room. Excessive heat in the				
56	FM-0056696	Los Angeles	Downey Courthouse	19-AM1	1	elevator room can affect the performance of the elevator equipment.	\$	6,145	\$5,143	83.7
57	FM-0056697	Los Angeles	Bellflower Courthouse	19-AL1	1	HVAC - Replace failed VFD & Motor. AHU #3 Return fan 5HP VFD is not operating and 5 HP Motor has shorted out. Currently the third floor has inadequate cooling due to the air handler not functioning properly.	\$	9,435	\$7,354	77.94
58	FM-0056698	Riverside	Larson Justice Center	33-C1	1	Fire Protection- Remove and replace failed 10" fire service DCDS backflow assembly device (N. side of building) with new 10" backflow and relocate above ground per CA plumbing code. Current backflow is located in below ground vault and is leaking. Vault will be back-filled and compacted prior to new installation. Fire Protection - Remediate non-code compliant conduit penetrations - Install fire stopping at several areas in	\$	35,236	\$28,474	80.81
59	FM-0056699	Los Angeles	Glendale Courthouse	19-H1	2	the basement ceiling/floor concrete at conduit penetrations. The concrete spawled when drilled exposing rebar in areas and fire stopping was never installed. Spawled areas to be patched with a cementious material. Work was identifide by the State Fire Marshal.	\$	4,298	\$3,891	90.54
						COUNTY MANAGED- Roof- Replace / reseal roof as needed in an approx. 7,200SF area, replace and counter				
			Needles Courthouse-			flash ducting and mechanical roof penetrations as needed to make 100% weather tight. Work is necessary to				
60	FM-0056700	San Bernardino	Dept. N-1	36-K2	2	prevent water intrusion in the rainy season.	\$	10,249	\$10,249	100
61	FM-0056701	Los Angeles	Bellflower Courthouse	19-AL1	1	Elevators, Escalators, & Hoists - Remove damaged and broken Elevator car doors; install new 42"x93" Stainless steel elevator doors. Elevator #2 has cracked welds and damaged doors that are beyond repair and non-operational. This leaves the Court public elevators down to 50% operable and elevator lobbies overcrowded.	Ś	8,344	\$6,503	77.94
01	0030701	-00,11160100	Arnason Justice	10 / 161		Exterior Shell - Vandalism - Replace damaged ADA powered door opener/closer. An angry member of the public	 	0,344	70,303	,,,,,,
62	FM-0056702	Contra Costa	Center	07-E3	2	slammed the door open, damaging the exit door.	\$	9,006	\$9,006	100
		San Mateo	Municipal Court Building - Northern Branch	41-C1	2	HVAC - Expansion Tank - Replace failed existing expansion tank w/new bladder tank - Existing expansion tank has failed forcing blow off valve to vent hot water.	\$	6,191	\$5,152	83.21
			Alhambra		_	Vandalism - Prime and paint (16) 10' tall aluminum columns - (8) on the 2nd floor, (8) on the 3rd floor. The			,	
64	FM-0056704	Los Angeles	Courthouse	19-I1	2	aluminum columns have been vandalized with offensive & obscene words & pictures.	\$	3,756	\$3,230	86
			Pomona Courthouse			Elevators, Escalators, & Hoists - Elevator will not power up. Swing panel boards and power supply for elevator #3 have failed. Replace faulty swing panel boards and power supply for elevator #3 and return elevator to				
65	FM-0056706	Los Angeles	South	19-W1	2	service.	\$	10,495	\$9,565	91.14
	5555,00	105.00	1				<u> </u>	, .55	75,505	J = 1 = 1

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
66	FM-0056708	Los Angeles	Downey Courthouse	10 4141	2	Elevators, Escalators, & Hoist - Elevator Failure - Remove and replace 1 emergency light and 1 alarm board in the elevator, validate proper operation of seismic derailment wire in the elevator hoist way.	ر	3,331	\$2,788	83.7
		Los Angeles	Pasadena Courthouse	19-AW1	1	Holding Cell - The inner door inside Lock Up holding cell B in the basement is not closing properly due to a very old & defective automatic door closer that has worn out internal gears; this affects the Sheriff's safety. Fabricate failed hardware and rebuild the automatic door closer. Original unit is no longer manufactured.	\$	10,453	\$7,249	69.35
68	FM-0056710	San Diego	North County Regional Center - Department 34 Trailer	37-F4	2	HVAC - Chronic Look - Isolate look and replace failed parts. Thermal Energy Storage Tank #2 is looking 20% glycol	\$	2,865	\$2,865	100
			South County Justice			HVAC - Glycol Leak - Isolate leak and replace failed parts. Thermal Energy Storage Tank #2 is leaking 30% glycol mixture into the tank. Tank #2 is not operational due to the leak and the ice system is not providing necessary				
69	FM-0056712	Tulare	Center	54-I1	1	cooling to the building.	\$	30,000	\$30,000	100
								,		
70	FM-0056713	Santa Clara	Old Courthouse	43-B2	2	HVAC- Boiler has failed- Replace (2) pressure gauges, (1) liquid fill gauges, (1) PRV, Re-wire 1 controller and Re- program for proper operation Required to maintain the required heating capability	\$	5,103	\$5,103	100
71	FN4 00F6714	Santa Clara	Downtown Superior	42 D1	,	HVAC - Replace (4) failed& leaking heating hot water isolation valves and (1) Bearing assembly -Insufficient	ے	4 990	¢4 990	100
/1	FM-0056714	Santa Clara	Court Van Nuys Courthouse	43-B1	2	heating capacity Exterior Shell - Broken glass in the secured clerk's area. Removed broken glass and temporarily boarded up affected area with (2) sheets of 3/4 inch plywood. Install (1) 1/4" grey safety laminated glass in customers	Ş	4,889	\$4,889	100
72	FM-0056715	Los Angeles	East	19-AX1	2	gasket storefront system approx. 48" x 30".	\$	5,000	\$4,487	89.74
72	FM-0056716	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing - Replace cracked water pipes inside of the wall in the Law Library Conference Room #602-8. Remove and renovate 4ft x 3ft damaged area and a new cut-off valve to minimize future damage. ACM work required. Leak was caused by water the pipes "hammering" inside the wall. Approximately 80 gallons of water leaked into affected areas. Water leaked down to the 5th floor Clerks area.		65,665	\$45,171	68.79
/3	1101-0030710	LOS Aligeles	Center	19-61		Plumbing - Failing Backflow Preventer – Remove and replace one failing backflow preventer in the 10th floor	٦	03,003	\$45,171	08.79
74	FM-0056717	Los Angeles	Airport Courthouse	19-AU1	2	chiller room. Code required.	\$	2,488	\$1,920	77.17
75	FM-0056718	Los Angeles	Metropolitan Courthouse	19-T1	2	HVAC - Replace failed motor to Cooling tower #2. Motor has grounded out and non-operational. Currently cooling tower #1 is in operation but to maintain the comfort cooling in the building, the Cooling Tower #2 motor must be replaced.	\$	9,972	\$9,428	94.54
76	FM-0056720	Los Angeles	Chatsworth Courthouse	19-AY1	2	Electrical - The inverter board & power supply for the Uninterruptible Power System (UPS) are not working and need to be replaced; the UPS backs up power to multiple areas of the courthouse including the emergency lights which are critical. Replace (1) inverter board & power supply for 7KW DSPM Inc. power panel for the UPS.	\$	10,806	\$9,055	83.8
77	FM-0056721	Los Angeles	Bellflower Courthouse	19-AL1	2	Elevators, Escalators, & Hoists: Renovate Generator Motors- The Generator and Motors on Elevators 1, 2, 3, & 4 have accumulated a large amount of carbon dust build up over time which can cause the generators / motors to fail to ground. The failure of these elevators may result in passenger entrapments.		20,954	\$ 16,332	77.94

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Parking Structure Lot			Floatrical Remove and replace 40 LIPS batteries to the emergency sirewit backup invertor system for the				
70	EN4 0056722	Los Angolos	94 Airport	10 112	2	Electrical - Remove and replace 40- UPS batteries to the emergency circuit backup inverter system for the	۲	26 770	\$20.665	77 17
/8	FM-0056722	Los Angeles	Courthouse	19-AU2		parking structure. They no longer accept a charge.	\$	26,779	\$20,665	77.17
79	FM-0056723	Los Angeles	Compton Courthouse	19-AG1	2	Plumbing - Rebuild deteriorated/failing Hot water pumps 1 & 2. Hot water pump isolation valves have failed necessitating draining the buildings hot water loops to replace the pumps. Demo insulation and (4) 4in gate valves, replace with new 4in lug type butterfly isolation valves. Remove and rebuild (2) existing hot water pumps and re-install pumps.	\$	40,224	\$26,600	66.13
80	FM-0056725	San Diego	East County Regional Center	37-11	2	Plumbing - Boiler #3 has failed due to flue gas condensing in system as a result of boiler not reaching 110 degree inlet temperature within 2-4 minutes of start-up. Demo existing failed boiler and install (1) new Raypak MVB 2003 1,999,000 BTU boiler. Install (1) Raypak Z12 Condensate Neutralizer Kit, (1) Raypak Cold Water Starter Kit (to eliminate flue gas condensing), 10LF of 2-1/2" copper pipe, 10LF of 1-5/8 " x 1-5/8" channel framing and (6) copper elbows.	\$	77,329	\$52,359	67.71
			Pasadena			Plumbing - Replace leaking sink and drain pipe. 6th Floor Janitor's Closet sink drain pipe leaked and water has		,	. ,	
81	FM-0056726	Los Angeles	Courthouse	19-J1	1	leaked down into the 5th Floor Judges Lounge.	\$	5,000	\$3,468	69.35
82	FM-0056727	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	HVAC - Chiller #2 will not operate properly due to high motor bearing temperature due to a blockage in the motor cooling line. Remove and replace failed economizer. HVAC - Restore chiller#1 with a Rydlyme treatment and tube brushing on Chiller #1. Scale and calcium buildup	\$	5,540	\$3,877	69.99
02	FN4 00FC720	Los Angeles	Edmund D. Edelman	10.01	1	inside of the condenser tubes which is causing poor heat transfer at condenser barrel. Building system not	_	15 254	¢10.676	60.00
0.5	FM-0056728	Los Angeles	Children's Court Arvin/ Lamont	19-Q1	1	cooling the facility. Court is impacted. Plumbing - Replace failed 3" 90 degree pipe in the main domestic water. Line is located in the lawn area on the	Ş	15,254	\$10,676	69.99
2/1	FM-0056729	Kern	Branch	15-H1	2	north side. Install new 90, pipe and fittings.	خ	3,783	\$2,304	60.91
07	1101 0030723	Kem	Criminal Court	13 111		HVAC - Failed Condenser Fan on Condenser 2 of Mammoth AC1; replace bearings, shaft, blade, pulley, belts and	 	3,703	72,304	00.51
85	FM-0056730	Napa	Building	28-A1	2	motor sheave. Bearing and sheaves failed, damaging condenser fan.	Ś	8,494	\$8,494	100
						Electrical - The diesel transfer pump is currently leaking during operation and has a bad motor. Replace existing pump and motor with skid mounted 4GPM diesel pump and 1/3HP 120V AC motor; includes new filter &	T			
86	FM-0056731	Los Angeles	El Monte Courthouse	19-01	2	assembly.	\$	5,714	\$3,321	58.12
87	FM-0056732	Contra Costa	Arnason Justice Center	07-E3	2	Elevator - Install three (3) Expanding doorway flood barriers and cove base for wall barrier - Remove the sound proofing approximately 12" off the floor; Seal electrical penetrations in the three (3) elevator mechanical rooms; Label the annular sensor in the generator belly tank's secondary containment - Work is required by code.	\$	14,410	\$14,410	100
						HVAC - Restore AHU 21 to full functionality, bearings and shaft were damaged/worn on AHU 21 rendering	+	,	+,	
88	FM-0056733	Kern	Bakersfield Superior Court	15-A1	2	Public Defender's offices and Jury Services lobby with minimal cooling. Installed a new shaft, (2) new bearings and removed existing long shaft from blower wheel.	\$	11,030	\$6,909	62.64
			Fremont Hall of			Plumbing - HVAC - Replace two (2) each failed and leaking isolation valves and one (1) each failed pneumatic	1.			
89	FM-0056736	Alameda	Justice	01-H1	2	control valve for hot water heating coil in ceiling.	\$	4,992	\$3,964	79.4
90	FM-0056737	Mendocino	County Courthouse	23-A1	2	Interior Finishes - Sound deadening material - install sound deadening material in vestibule between courtrooms A & B on 1st floor, and landing, approx 480 Sq ft. currently this vestibule is producing noise that is disrupting court proceedings.	\$	2,354	\$1,592	67.62

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			North County Regional Center -			HVAC - Package Units #1 & #2 supply HVAC to interior spaces and were non-operational causing uncomfortable				
			Department 34			conditions and potential health issues. Removed and replaced compressors and fan motors in Package Units #1				
91	FM-0056738	San Diego	Trailer	37-F4	2	and #2.	Ś	5,612	\$4,345	77.42
5 -	1111 0030730	Jan Biego	Tranci	37 1 1		HVAC - Replace damaged Vent/Louver - Remove the existing rusted and failing outside air intake vent/Louver	<u> </u>	3,012	ψ 1,3 13	77.12
			Del Norte County			and replace with a new stainless steel version to matchthe the existing unit. Stainless steel required due to the				
92	FM-0056739	Del Norte	Superior Court	08-A1	2	location of the building next to the ocean.	\$	2,800	\$1,716	61.27
						Elevators, Escalators, & Hoists - Power supply to Elevator #4 is not working and needs to be replaced. Replace		,	, ,	
93	FM-0056740	Los Angeles	Airport Courthouse	19-AU1	2	non-working Power Supply on Elevator #4.	\$	4,121	\$3,180	77.17
						Plumbing - A sewer line above the ceiling failed - Remove and replace 10 ft. section of 4 inch cast iron sewer				
						line. Extract black water resulting from the failed sewer line, disinfect all horizontal and vertical surfaces, office				
						equipment and carpet in Room 3005. Remove and replace all ceiling tiles in room 3005. Work is per ACM				
94	FM-0056741	San Diego	County Courthouse	37-A1	1	protocols.	\$	11,658	\$11,658	100
			North County							
			Regional Center -			Plumbing - Septic sump pumps have failed, this will cause backup in the supported trailers plumbing system.				
95	FM-0056743	San Diego	Traffic Annex	37-F3	2	Replace (2) existing 100V, 1/2HP sump pumps including new check valves, and 4ft of 2 inch ABS piping.	\$	4,994	\$4,994	100
						Plumbing - Domestic water line was leaking on the 6th floor. Replace 6 feet of defective 1/2" copper water				
			Inglewood			supply line above the ceiling inside Room 603. Enclosed barrier 6' x 6'x 10' for AVCM. Replaced 4 - damaged				
96	FM-0056745	Los Angeles	Courthouse	19-F1	1	ceiling tiles.	\$	30,055	\$22,409	74.56
			Stanley Mosk			Plumbing - Replace failed domestic water handle and remediate water damage in Room 105E break room.				
97	FM-0056746	Los Angeles	Courthouse	19-K1	1	Water saturated 300 sq feet.	\$	12,102	\$11,770	97.26
			Hayward Hall of			HVAC - Replace failed HV cable splices on chiller line power in control panel, includes (3) 760 amp terminal				
98	FM-0056747	Alameda	Justice	01-D1	2	blocks in starter cabinet, and (6) copper feeders.	\$	5,433	\$5,433	100
						Plumbing - Failing Sewage Ejector Pumps #1 & #2 - Restore Ejector Pump #1 and replace cracked leaking piping				
		l	Metropolitan		_	for Ejector Pump #2. Sewage Ejector Pump #1 motor is not working and Sewage Ejector Pump #2 has a cracked		•••	***	
99	FM-0056748	Los Angeles	Courthouse	19-T1	1	discharge line.	\$	20,067	\$18,971	94.54
						Grounds and Parking Lot - Judges' secure exit gate will not open. The overhead wheels that support the door				
			North County			are seized. The main control circuit board and control relay have failed. In the event of an emergency situation,				
100	ENA 005 6740	Cara Diagra	Regional Center -	27.54	2	egress could be inhibited. Damage to vehicles could occur using the entry gate as an exit. Replace (1) main	۸ ا	6 000	ć 4 00 4	67.24
100	FM-0056749	San Diego	South	37-F1	2	circuit board, (1) control relay and (4) truck rollers.	\$	6,088	\$4,094	67.24
101	ENA 00E67E1	Can Parnardina	San Bernardino	26 11	2	Plumbing - Abandoned 8" cast iron drain line is leaking into court space. Cleanly cut 8" break and concrete filled	خ	10 471	\$10.014	05.64
101	FM-0056751	San Bernardino	Courthouse	36-A1		waste line. Install permanent cap. Utilities - Replace failed hardware on exterior sprinkler system. Remediate water damage in courtroom office	٦	10,471	\$10,014	95.64
102	FM-0056753	Yolo	Traffic Court	57-A3	1	area within ACM protocals.	¢	6,287	\$6,287	100
102	141 0030733	1010	Trainic Court	J1-MJ	Т.	COUNTY MANAGED- Parking Lot- Demo approx. 205,938SF 3 inch depth of asphalt and resurface with approx.	۲	0,207	70,267	100
						205,938SF 3 inch thick asphalt & re-stripe. Demo concrete sidewalks and pour new ADA sidewalks and parking				
			Victorville			approx. 1,750SF, install truncated domes, and signage to bring up to code. Slurry seal new asphalt. Currently				
			Courthouse-Dept. N-			parking is not up to ADA code in some areas and the asphalt in the parking lot has numerous cracks, pot holes,				
103	FM-0056755	San Bernardino	1	36-L1	2	and uneven areas that pose a tripping hazard.	Ś	342,744	\$342,744	100
	1 5555755	15a Bernaranio				Inner anner an an and trust base a mikking matariar	۲ ۲	J .=,, +→	75 12,7 TT	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Fire Protection - State Fire Marshal inspection deficiencies - Throughout courthouse, Seal (120) 6" penetrations with intumescent fire caulking, install 120 glow-in-the-dark one sided exit signs; replace 25 damaged labels on				
			Edmund D. Edelman			fire doors. Kitchen area replace damaged fire door with 90 minute fire rated door and a 6' door coordinator.				
104	FM-0056756	Los Angeles	Children's Court	19-Q1	2	Loading dock replace (1) pair of double doors with mortis locks, 2 closers and door vision glass.	\$	49,959	\$34,966	69.99
			Edmund D. Edelman			Interior Finishes - Stairwell #3 stair risers/nosing have deteriorate over time with many breaking off. Broken risers/nosing present a tripping/safety hazard in stairwell and need to be replaced with ADA/OSHA compliant tread. Demo existing tread/riser covers and addition 6" of tile/linoleum per step. Drill 1/4" holes in concrete for countersunk masonry screws, 4 screws per stair (628 fasteners). Install (157) 4.5' W Flexmaster black/yellow				
105	FM-0056757	Los Angeles	Children's Court	19-Q1	2	safety renovation treads.	\$	71,602	\$50,114	69.99
			Santa Clarita			County Managed - HVAC - Remove and Replace failing boiler #2 at the Santa Clarita Civic Center Power Plant.				
106	FM-0056758	Los Angeles	Courthouse	19-AD1	2	Remove and replace expansion tank. Install new burners and controls.	\$	40,720	\$ 40,720	100
107	FM-0056762	Orange	Central Justice Center	30-A1	2	HVAC - Remove and replace failed ABB-VFD for HVAC unit #13 (OM00015825) with a new Nema 1 ABB-VFD (with bypass), current damaged VFD is in by-pass mode and is requiring immediate replacement to avoid system failure.	\$	5,109	\$4,658	91.17
100	FM-0056763	Los Angeles	Airport Courthouse	19-AU1	1	Grounds and Parking Lot -Sally Port Roll up motor failed. Installed (1) new SGH motor operator, a new loop detector, photo eye, and coil cord.	خ	4,858	\$3,749	77.17
108	<u> </u>	Los Aligeles	South County	19-A01	1	Elevators, Escalators, & Hoists - Elevator #9 car equipment replacement. Elevator floor level buttons are malfunctioning and need to be replaced. Install 3 failing handrails using a bolt-through fastening system. Install	7	4,636	<i>\$3,749</i>	77.17
109	FM-0056764	San Diego	Regional Center	37-H1	2	2 car Level Indicator Buttons. Work is code required.	\$	9,087	\$9,087	100
110	FM-0056766	San Diego	Juvenile Court	37-E1	2	Grounds and Parking Lot -Damaged underground conduit causing light out above parking space #6 at Secured Judges parking. Underground conduit has been crushed/broken at several spots and the wiring is damaged. Install 45' new underground conduit and wiring to restore power to the affected parking lot pole. Hand dig required to protect irrigationand control wiring.	\$	7,951	\$7,951	100
						Exterior Shell - Sheriff's custody bus hit the sallyport gate and damaged the guiderails making the gate				
111	FM-0056768	Los Angeles	Stanley Mosk	19-C1	1	nonfunctional causing a safety/security situation for the court. Replaced 2- damaged guiderails. Plumbing - Water leak in Room 323 Judge's Lounge; Approx. 2 sq ft of carpet affected and 4 ceiling tiles. 4th floor Mechanical Room had water leak due to backed up floor drain. Replace 4 damaged ceiling tiles, remove	\$	12,677	\$10,793	85.14
112	FM-0056773	Los Angeles	Courthouse	19-K1	1	and replace 60 ft. of insulation under ACM conditions.	\$	15,195	\$14,779	97.26
113	FM-0056774	Los Angeles	Santa Monica Courthouse	19-AP1	1	HVAC - Chilled water pump #3 motor is burned out and the impeller is locked causing the pump to not operate, affecting the HVAC system to the building. Replace chill water pump and motor for proper operation.	\$	17,565	\$13,787	78.49
						HVAC - AHU #6 is very loud and disrupting court proceedings due to bad motor bearings. Replace 40 hp supply				
111	FM-0056775	Los Angeles	Compton Courthouse	19-ΔG1	2	fan motor, pulley and belts before the motor fails and causes further damage to the air handler.	ς .	9,384	\$6,206	66.13
114	1 141 0030773	LOS Aligeies	Stanley Mosk	12 701		Interior Finishes - Remove and replace third floor corridorfire doors. Units are cracked, missing proper	٧	J,304	70,200	00.13
115	FM-0056776	Los Angeles	Courthouse	19-K1	2	hardware, and is non-repairable. Replacement is code required.	Ś	6,640	\$6,458	97.26
110	5550770		200.0.000			HVAC - Return fan #3 has bad bearings and a worn out shaft, replacement will prevent down time and costly damage to additional components in the future. Replace (2) bad bearings & (1) custom built shaft, re-assemble	7	5,5 15	γο, 130	37.20
116	FM-0056777	Los Angeles	Torrance Courthouse	19-C1	2	pulleys & belts, and return to proper operation.	\$	9,029	\$7,687	85.14

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
117	ENA 005 6770	l os Angolos	Pasadena	10 11	2	Elevators, Escalators, & Hoists - Replace (3) hoistway limit switches on passenger elevators #1, #2, & #3. Current	ے ا	0.262	¢r 700	60.35
	FM-0056779	Los Angeles	Courthouse	19-J1		limit switches are not functioning properly and need to be replaced. Grounds and Parking Lot - Vandals/homeless continually break into the irrigation and gas meter cage leaving waste, creating health hazards and unplugging Irrigation timers. Need to demo existing fence and install heavy duty fence with security screen. Demo 57 LF existing chain link fence and posts. Install 57 LF of 14'H wrought iron fence with 1"x 1" pickets and (1) 14'H x 4'L matching gate. After installation of wrought iron fence weld on	\$	8,362	\$5,799	69.35
118	FM-0056782	Los Angeles	Compton Courthouse	19-AG1	2	7'H x 57'L 1/2" expanded steel security mesh.	\$	52,772	\$34,898	66.13
119	FM-0056783	Los Angeles	Compton Courthouse	19-AG1	2	Fire Protection - Sprinkler and Pipe Deficiencies Replace 10 LF of corroded 6" standpipe in 14th floor mechanical room. Replace PRVs on flrs 1 - 7. Install 100 Marc Star Model E sprinkler heads throughout building. Replace water flow switches on flrs 2, 6, and 7 and water flow detectors on flrs 4, 6, 11, and 12. Work found during Level IV PM.	\$	56,884	\$37,617	66.13
120	FM-0056784	Yuba	Yuba County Courthouse	58-A1	2	COUNTY MANAGED - ADA Compliance: Replace 5 sets of double outer doors, remove 5 pairs of inner Courtroom doors, install automatic openers/closers on new doors. Door frame modifications will require working within an ACM environment. An ADA accessibility complaint was received which has initiated this project. Interior Finishes - ACM Abatement - Abatement on fireproofing material on ceiling, 1-beam, and work down		100,000	\$100,000	100
			Pomona Courthouse			walls toward floor. Re-spray fireproofing. Debris to be disposed of in accordance with regulations. Abatement				
121	FM-0056785	Los Angeles	South	19-W1	2	to address Fire Safety Correction notice from State Fire Marshal.	\$	239,919	\$218,662	91.14
122	FM-0056786	San Diego	East County Regional Center	37-l1	2	Interior Finishes - Replace deteriorated spline ceiling tile with 760-sq. feet of 2 x 4 fire rated ceiling tiles and aluminum concealed spine T-bar grid system, replace current recess mercury vapor bulbs with eighteen (18) 36-Watt LED bulbs and 8-Inch recess light fixtures. Scope of work includes scaffolding set up and removal to access 40-foot ceilings, relocating fire sprinklers & smoke detectors below grid to remain compliance, and dispose of hazardous waste. Currently, 66% of antiquated mercury vapor bulbs are burned out, product is no longer available, and debris from deteriorated spline ceiling is falling and posing as a safety hazard.		56,874	\$ 56,874	100.00
123	FM-0056787	Los Angeles	Glendale Courthouse	10-H1	1	HVAC - Replace 2 defective compressors, replace defective TXV unit and install Electronic Expansion Value. Set- up temporary cooling(1-120 ton Chiller Unit, 2-Air Handlers, 1-222kva generator, 1-300kva generator). In addition, create a design for a new HVAC system. The following HVAC units failed and not able to provide cooling to the building.	¢	333,347	\$301,812	90.54
123	1141 0030707	LOS Aligeies	Gieriaaie Courtilouse	13 111	1	HVAC- Replace two (2) defective coils in AHU#2 and two (2) expansion valves. Provide and install new sheaves	7	JJJ,J+1	7301,012	50.54
124	FM-0056787	Los Angeles	Glendale Courthouse	19-H1	2	for AHU #1 & #3. County installed coil units are incorrectly sized and have caused chiller pump failures.	\$	65,000	\$ 58,851	90.54
125	FM-0056788	Los Angeles	Van Nuys Courthouse East	19-AX1	1	HVAC - 2nd floor DA (East) Wing, the entire wing has no HVAC circulation, office temperatures are too warm. Replace faulty damper, faulty damper actuator, blown damper access door and trunk line. Environmental testing, set up containment at HVAC access point and restore cooling to entire East Wing.	\$	20,110	\$18,047	89.74
1.5	EN 4 00= 0= 0		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	40.404		Elevator, Escalators, & Hoists - Remove and replace door hoist way gibs and door edge. Public Elevators 1 & 2		45.001	440 - 05	
126	FM-0056789	Los Angeles	Whittier Courthouse	19-AO1	1	are not operating and are stuck on the first floor.	Ş 	15,691	\$13,562	86.43
127	FM-0056791	Kern	Bakersfield Superior	15-A1	2	HVAC - Restore FAN Unit 6 to full functionality for Chilled Water Cooler, failed heat strip rendered FAN Unit 6 offline and prevented cooling to IT Server Room. Replace defective heater and faulty PSI switch.	ر	2,383	\$1,493	62.64
12/	ווויויווון ואויוווון	IVELLI	Court	12-HT	۷	Johnne and prevented cooling to it berver room, replace defective heater and faulty PSI Switch.	٦	2,303	\$1,493	02.04

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
128	FM-0056792	San Francisco	Civic Center Courthouse	38-A1	2	Security - Replace failed one (1) operator, one (1) Motor gear box, one (1) controller, one (1) 80' bronze header and multiple relays on ADA door located in courtroom 613 on 6th floor.	خ	6,775	\$6,775	100
		San Diego	East County Regional		2	Plumbing - Replace 30' of 2" Cast Iron pipe and 20' of 3" Cast Iron roof drain pipe and install (3) 2" Cast Iron fittings and bands and replace damaged ceiling tiles above meeting room. Second floor Family Law Office meeting room has cracked piping and fittings above the T-bar ceiling that leak and need to be replaced. Electrical - Install (3) new 20AMP electrical outlets in room 258, Administrator's office on the 2nd floor; remove (1) existing outlet currently mounted on the floor. Currently there is one electrical outlet mounted to the floor	\$	5,766	\$3,904	67.71
			Stanley Mosk			which is a tripping hazard as well as a potential fire hazard due to multiple extension cords & power bars all	١.		.	
130	FM-0056794	Los Angeles	Courthouse	19-K1	2	running through a single outlet.	\$	7,617	\$7,408	97.26
131	FM-0056795	San Diego	North County Regional Center - Vista Center Stanley Mosk	37-F2	2	Holding Cell - Remove existing non-working lock and install a new #12 deadlock with two new keys for access panel. Plumbing chase access panel is locked and there is no key to open it. Access is required in an emergency. Elevators, Escalators, & Hoists - Escalator 5 to 4 Hill Street side - Replace burnt coil and brake pads and returned		5,749	\$5,749	100
132	FM-0056796	Los Angeles	Courthouse	19-K1	1	escalator to service. Escalator 5 to 4 Hill Street side had a burnt coil causing the brake to pick and burn the pads.		5,737	\$5,580	97.26
_	FM-0056797	Los Angeles	Hall of Records	19-AV1	2	COUNTY MANAGED - Roof - Install new roof base over the elevator shaft.	\$	17,200		100
	FM-0056798	Monterey	Monterey Courthouse	27-C1	2	COUNTY MANAGED - Energy Management System (EMS) - Replace building EMS (server and operating system) to include: demo replace 2 plant controllers, 8 space temp sensors, 4 duct temp sensors, 4 strap on temp sensors, a current sensor relay, a mixed IO modular, 1 analog input module and relay, installation of set points, graphics, and training EMS currently inoperable. Plumbing - Holding Cells 1-5 - Replace leaking (5) Prison Toilet/Sink combination units to include; (4) new units, (1) new ADA unit, install pneumatic flushing mechanism (all units), new waste line for 3 units, core drilling, rebar installation where needed, remove current remote flush option, install master water shutoff at control board - Units are aged and failing regularly, parts are obsolete, ACM testing required, impact to court operations due to volume of in custodies is a constant threat, due to part availability units can be down weeks	\$	27,200		100
135	FM-0056799	Santa Cruz	Main Courthouse	44-A1	2	at a time even during P1 events.	ς .	172,897	\$172,897	100
			Pasadena		2	HVAC - Failing AHU 10 and AHU 11 - Remove and replace 1 cold water coil, 1 hot water coil, 4'x12 stainless steel drain pan, 4 gate valves, 2 balancing valves, 2 pressure gauges and 2 thermometers on each AHU #10 & #11. Air handler coils are leaking and the drain pans have deteriorated. ACM testing and containment required prior to				
136	FM-0056800	Los Angeles	Courthouse	19-J1	2	Work.	Ş	169,122	\$117,286	69.35
137	FM-0056802	San Bernardino	Barstow Courthouse	36-J1	2	Interior Finishes - Room 110 Self-help office expansion- Remove (96SF) wall between Rm 109 and 110. Manage with ACM contaminant requirements (10SF.patch carpet, touch up paint, and rewire light switch). Expansion needed since there will soon be significant additional traffic due to upcoming re-opening of the branch and reallocation of Court resources. Interior Finishes - Remove and replace audience, jury, and witness seating in Dept. H, J, and N. Dept H, N, and J (63) audience seating (14) jury box seating and (1) witness chair. Totaling (189) Audience seating (42) jury box		18,532	\$18,532	100
138	FM-0056803	Los Angeles	San Fernando Courthouse	19-AC1	2	(63) audience seating, (14) jury box seating, and (1) witness chair. Totaling (189) Audience seating, (42) jury box seating, and (3) witness chairs. Existing seating is old and constantly breaking, parts are not available for repairs. Safety hazard with seating failing with public use.	\$	114,000	\$114,000	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - Install (1) 2-ton 24,000 BTU Mitsubishi ductless split system with remote, condensate pump and drain				
						line. Install 150' of power wiring, 300' of 3/4" conduit, 30 AMP breaker, 30 AMP disconnect and (2) 30 AMP				
						fuses. Observation/control booth for Lockup was not in original HVAC design. Current use with full time staff				
139	FM-0056806	Los Angeles	Burbank Courthouse	19-G1	2	and increased electrical load than the original design makes area excessively hot.	\$	23,895	\$ 21,687	90.76
						Exterior Shell - Windows were vandalized by graffiti/etching. A safety concern, the windows need to be				
						replaced and install anti-graffiti film to prevent future graffiti. East 1st Flr: Replace 3 windows, Install film on 20				
			Clara Shortridge Foltz			windows (734SF). North 1st Flr: Replace 4 windows, Install film on 49 windows (1550SF). West 1st Flr: Install film				
			Criminal Justice			on 8 windows (284SF). South 1st Flr: Replace 12 windows, Install film on 31 windows (971SF). South 2nd Flr:				
140	FM-0056807	Los Angeles	Center	19-L1	2	Replace 6 windows, Install film on 20 windows (640SF).	\$	162,815	\$112,000	68.79
						COUNTY MANAGED - HVAC- Install a new 1.5 ton mini-split system unit to provide appropriate levels of cooling				
						and air flow to the Judge's Chambers. Relocate existing T-Stat & ducting in the chambers to supply 3 offices				
			Victorville			alone. Courthouse is in a desert area, reaching extreme hot temperatures in the summer months, making it				
			Courthouse-Dept. N-			uncomfortable for staff. County has made several attempts to have the existing unit adequately supply all 4			4	
141	FM-0056809	San Bernardino	1	36-L1	2	rooms all to which has not had success.	\$	4,500	\$4,500	100
						Interior Finishes - Floor tiles 108 sq.ft. of tile are coming unglued from the floor, the adhesive used to secure the				
143	EN 4 00E C044		Colored Lancarille Count	40 454	_	tiles to the floor contain ACM. Remove and replace along with 42 ft of cove base. Continuing degrading	_ ا	0.000	¢0.003	100
142	FM-0056811	Los Angeles	Sylmar Juvenile Court	19-AF1	2	condition is becoming hazardous.	\$	8,992	\$8,992	100
142	ENA 00E6913	Can languin	Manteca Branch	20.61	_ ا	Vandalism Cafaty, Danlaga brakan skulight window above public space. Lift required to replace glass	ے ا	2 500	¢2 F09	100
143	FM-0056813	San Joaquin	Court	39-C1		Vandalism - Safety - Replace broken skylight window above public space. Lift required to replace glass	Ş	3,508	\$3,508	100
						Exterior Shell - The In-Floor door closers for the cafeteria (leading to the parking meters) are worn out and do				
						not function properly. The doors do not close automatically and need new door closers/closing arms to be				
1//	FM-0056814	Los Angeles	Airport Courthouse	19-AU1	2	installed. Replace In-Floor door closers with (4) Rixson free swing arms and (4) surface mount closers.	خ	4,385	\$3,384	77.17
177	1101 0030014	LOS Angeles	Parking Structure Lot	IJ AOI		instance. Replace in Floor door closers with (4) kixson free swing arms and (4) sarrace mount closers.	7	7,303	73,304	77.17
			94 Airport			Plumbing - 10" Backflow failed and it is unrepairable. Remove existing backflow device and install a new				
145	FM-0056815	Los Angeles	Courthouse	19-AU2	2	backflow unit.	Ś	10,333	\$7,974	77.17
	2000020					HVAC - Cooling tower is running at very high temperatures due to a bad breaker that is tripping & pitted	<u> </u>		7.,5.	
146	FM-0056816	Los Angeles	Torrance Courthouse	19-C1	2	contactors that need to be replaced. Remove and Replace (3) bad contactors & (1) bad breaker.	\$	4,707	\$4,008	85.14
			Turlock Superior				<u> </u>	,	. , -	
147	FM-0056818	Stanislaus	-	50-D1	2	Interior Finishes - Stretch failing carpet. Anchor audience seating to concrete in the courtroom.	\$	6,345	\$6,345	100
	FNA 005 6040			40.444		Fire Protection - Replace Speaker near room 697 that does not sound upon activation of alarm. Adjust Tamper switch on Bypass Upstream Valve and Tamper switch on Main Pump Discharge Valve in the Fire Pump Room. Restore stairwell doors that do not unlatch upon activation of alarm in Stairwell #5 - Floors 9, 7, 3; Stairwell #4 -		2 264	42.50 5	
148	FM-0056819	Los Angeles	Airport Courthouse	19-AU1	2	Floors 9, 4, 2; Stairwell #3 - Floors 3 & 10; Stairwell #2 - 10th Floor; Stairwell #1 - 9. Work is code required.	Ş	3,364	\$2,596	77.17

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Fire Protection - Existing Simplex 2000 fire panel is ground faulting and reading false trouble calls that could lead to false alarms and subsequent court evacuations. Need to upgrade existing panel to a modern 4100ES				
149	FM-0056820	Los Angeles	Bellflower Courthouse	19-AL1	2	with capability of supporting future upgrades. Demo existing system & install new Simplex 4100ES, (1) addressable smoke detector above fire alarm control panel (FACP), (1) horn strobe above FACP and (1) LCD enunciator.	\$	48,064	\$ 37,461	77.94
			Harris a lab Carris a			HVAC - Replace (6) corroded and failed return air dampers, (5) corroded and failed outside air dampers and				
150	FM-0056821	Humboldt	Humboldt County Courthouse (Eureka)	12-A1	2	linkages on AHU-5,6,7,8 and 9. Replace (12) pneumatic damper actuators. Currently dampers are severely corroded and linkages are broken.	\$	77,551	\$77,551	100
								•	. ,	
151	FM-0056829	Los Angeles	Pomona Courthouse South	19-W1	1	Roof - Rain water penetrated the roof. Rain water leaked into the 5th and 4th floors and the 3rd floor Dept. C, Room 302. ACM remediation & containment, dry leak affected areas and replace wet and damaged ceiling tiles.	ڔ	20,150	\$18,365	91.14
131	FIVI-0030629	LOS Aligeles	South	13-441	1	HVAC - Chiller #2 - Remove and replace failed purge pump. The failed pump has rendered the chiller inoperable		20,130	\$10,505	91.14
152	FM-0056830	Riverside	Hall of Justice	33-A3	1	and leaving the building insufficiently cooled.	\$	7,255	\$7,255	100
			NA I III			Roof - Rain Water penetrating the roof of the 1st Floor Sheriff Vehicle Inspection Station. Replace				
153	FM-0056831	Los Angeles	Metropolitan Courthouse	19-T1	1	approximately 350 sq ft of ceiling tiles have been affected by the leak/rain water. 450sf ACM containment and remediation.	¢	25,100	\$25,100	100
133	1101 0030031	LOS Aligeres	Courtilouse	15 11		COUNTY MANAGED - Replace exhaust pipe on emergency generator at Central Plant, this generator supports	7	23,100	723,100	100
			South County			emergency power to South County Regional Center, current system has failed and is out of compliance with				
154	FM-0056832	San Diego	Regional Center	37-H1	2	local authorities.	\$	3,242	\$3,242	100
155	FM-0056833	Los Angeles	Pomona Courthouse South	19-W1	1	Roof - Rain water penetrating roof and leaking into the 6th floor Public Hallway Dept. P & Dept. R. Leak has been contained to the 6th floor.CM remediation & containment, dry leak affected areas.	ċ	15,050	\$13,717	91.14
133	1 101-0030833	LOS Aligeles	Monrovia Training	19-001		Roof - Rain water is penetrating and leaking into the 1st floor Large Lock-up Cell. CM remediation &	٦	13,030	713,717	91.14
156	FM-0056834	Los Angeles	Center	19-N1	1	containment, dry leak affected areas.Remediate damaged roofing penetrations and fan unit cowling.	\$	15,102	\$10,615	70.29
						Roof - Water is leaking into the 1st floor Lock-up Control Room. Rain water is leaking at the sergeants desk area;				
157	FM-0056835	Los Angeles	Mental Health Court	+	1	affecting an 8ft x 8ft area & 10x10ft ACM areas. Replaced failed drain hardware.	\$	15,075	\$10,750	71.31
1			Van Nuys Courthouse			Roofing - Renovate failed roofing seams and mitigate water damage to 7th floor Women's public restroom			4	
158	FM-0056836	Los Angeles	East Harbor Justice Center	19-AX1	1	creating a slip hazard and safety situation. Secure and clean up under ACM requirements.	\$	16,585	\$14,883	89.74
			Newport Beach			Electrical - Replace three severely rusted light poles in the parking lot. Two poles were in immediate danger of				
159	FM-0056838	Orange	Facility	30-E1	2	falling and have been removed. All parking lot lighting is necessary, so the poles must be replaced.	Ś	7,730	\$6,518	84.32
		orange .	- Comey			HVAC - Replace (1) each failed blower assembly - Boiler is currently out of service - Reduced heating capacity to	T	.,	φ 5/5 25	
160	FM-0056839	Santa Clara	Hall of Justice (East)	43-A1	2	the court - Boiler #04 has failed.	\$	3,615	\$3,615	100
						HVAC - Replace failed compressor, worn condenser motor and fan blade, filter drier, starter caps, and				
			C D ''			contactor. Split system serving the 1st floor data room is down due a filed compressor. Replacement required				
161	ENA 00E6040	Can Darnardina	San Bernardino	26.42		to ensure adequate cooling of the data room to prevent possible heat related damage to critical court network	ے ا	2 755	ć2 F00	05.50
101	FM-0056840	San Bernardino	Courthouse - Annex George D. Carroll	36-A2	2	equipment. Interior finishes - Vandalism Grind, sand, and buff out profanity and drawings etched into (10) steel beams	>	3,755	\$3,589	95.58
162	FM-0056841	Contra Costa	Courthouse	07-F1	2	Graffiti carved into the beams and window frames outside of the Jury Assembly Room.	\$	2,140	\$2,140	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Interior Finishes - Dept. S-53 Chambers the paint on plaster wall is bubbled due to condensate leak. Need to dry				
			 San Bernardino			wall and repaint, this work is necessary in order to restore the Courtroom to its original condition. Utilize an air injection system and dehumidifier to dry approximately 50SF of plaster wall that was dampened by a				
163	FM-0056842	San Bernardino	Courthouse	36-A1	2	condensate leak. Encapsulate lead blistered paint areas and repaint wall.	Ś	5,098	\$5,098	100
	55555 1		Criminal Court			HVAC - Remove existing EOL Drift Mist Eliminators and reinstall (7) mist eliminators on top and (14) each mist	<u> </u>	3,333	70,000	
164	FM-0056844	Napa	Building	28-A1	2	eliminators on side of the Mammoth Package Air Handler - Several (8) eliminators failed.	\$	3,519	\$3,519	100
			Humboldt County			COUNTY MANAGED - Fire System - Expand system - Install expansion pack for fire panel (Notifier NFS2-640), to				
165	FM-0056845	Humboldt	Courthouse (Eureka)	12-A1	2	allow existing AHU duct detectors (8) to be attached to Fire system.	\$	4,721	\$4,721	100
					_	COUNTY MANAGED - Electrical - Connect court UPS equipment to the emergency power supply per estimate	١,			
166	FM-0056846	San Mateo	Hall of Justice	41-A1	2	150232 Rev 2. This is a County responsibility.	\$	5,061	\$5,061	100
167	ENA 00EC947	l as Amaslas	Davin av Cavinth avaa	10 001	4	Elevators, Escalators, & Hoists - Renovate Judge's Elevator #5 leaking Worm Gear and Bad Shaft. Work required		ć20 024	¢22.462	02.7
167	FM-0056847	Los Angeles	Downey Courthouse	19-AIVI1	1	to preclude system failure. HVAC - Replace leaking, rusted 40 year old 75 ton Cooling Tower and 110 ton Chiller, Piping and VFD included.		\$28,031	\$23,462	83.7
168	FM-0056848	Santa Clara	Old Courthouse	43-B2	2	Existing equipment has continual leaks and failed component replacements. Increased number of hot calls is affecting operations.	\$	590,244	\$590,244	100
169	FM-0056849	Los Angeles	Stanley Mosk Courthouse	19-K1	2	Interior Finishes - Abate 825 SF of ACM linoleum flooring and ACM mastic between linoleum and floor. Install new linoleum tile. Remove and later replace 16 rows of 7 seats (112 seats). Dept. 11 Room 246 VCT flooring contains ACM and due to prior floods is delaminated and buckling. Flooring is a tripping hazard to public/court staff and a liability to the court.	\$	48,739	\$48,739	100
		<u> </u>				HVAC - Cooling Tower #1 VFD and 15 HP motor are not functioning creating Cooling Tower #2 to run at 60		,		
			East Los Angeles			degree chill water temp which is not sufficient for comfort cooling to support the building. Replace VFD and				
170	FM-0056854	Los Angeles	Courthouse	19-V1	1	motor for Cooling Tower #1.	\$	20,758	\$16,133	77.72
171	FM-0056855	Los Angeles	Monrovia Training Center	19-N1	1	HVAC - The DX system is leaking refrigerant which is causing the compressor to shut down on high head temperature. Not able to cool the building. Replace defective King Valve and restore system to operation.	\$	15,509	\$10,901	70.29
470	EN 4 005 605 6	N 4 1	New Downtown	24.40		Don't Double follow VED VED V	_	40.460	440 466	
1/2	FM-0056856	Merced	Merced Courthouse	24-A8	2	Roof - Replace failed VFD - VFD stopped working.	\$	10,469	\$10,469	100
172	FM-0056857	Stanislaus	Turlock Superior Court	50-D1) ,	HVAC: Replace Existing 5-Ton Package Unit. Unit is failed beyond repair (Compressor). Unit replacement required - Age 30+ years.	ا د	11,083	\$11,083	100
1/3	1 101 0030037	Stariisiaus	Court	30 01		required Age 301 years.	_ ر	11,003	711,003	100
174	FM-0056859	Shasta	Main Courthouse	45-A1	2	Interior Finishes - Remove failed existing floor closers, and furnish and install (4) new Rixson 27 90 degree floor closers with new offset arms and make adjustments for proper operation and locking. The glass doors leading into the admin floor lobby slam shut, this is a safety hazard as the glass may break.	\$	6,402	\$4,463	69.71
						Plumbing - Vandalism Holding cell #5, Remove previously fabricated and installed block off plate, Install new				
175		Canta Carra	Main Counth area	44.44		sink components and modify to fit existing combi unit. Sink compartment of unit is currently out of service, sink	_ ا	2 277	62.277	100
1/5	FM-0056860	Janua Cruz	Main Courthouse	44-A1		in not usable due to damage from vandalism.	>	3,377	\$3,377	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - Replace existing rooftop AHU to include integral VFD, install VAV controller and sensors for VAV				
						conversion, install VAV boxes in zones and integrate existing reheat coil, replace chilled water valve and roof piping insulation, integrate controls with new BAS, tie in new actuator and sensors into local controller - Existing				
						unit is constant volume zone reheat chiller water AHU, it is exhausted and at end of life, inefficient, ineffective.				
176	FM-0056862	Santa Cruz	Main Courthouse	44-A1	2	Replacement will enhance monitoring and control.	\$	68,425	\$67,816	99.11
			East County Regional			Interior Finishes - Dept. 1 Gallery seating is deteriorated posing public safety and health risk. Replace seating				
177	FM-0056866	San Diego	Center	37-I1	2	components and upholstery on 75 spectator seats, backs, and other miscellaneous hardware.	\$	11,458	\$ 11,458	100
			Van Nuys Courthouse			HVAC - 5th floor Supply motor for HVAC #5 has failed causing temperatures to rise. Replace bad supply motor			_	
178	FM-0056867	Los Angeles	East	19-AX1	1	and restore cooling to 5th floor.	\$	7,500	\$6,731	89.74
			Charalas Marak			Plumbing - 1st floor Room 111A, Remove and replace a 20' section of 4" inch cast iron sewage pipe and fittings.				
170		l os Angolos	Stanley Mosk	10 1/1	1	Pipe is cracked and leaking through the ceiling. Install (4) new 24"x24" ceiling tiles and restore the carpet. ACM	ے ا	15.075	¢14.662	07.26
1/9	FM-0056868	Los Angeles	Courthouse	19-K1	-	Work required. HVAC - Chiller #1 is failing - Fabricate shaft and 3 fan wheels to match existing cooling tower model. Chiller #1 is) > 	15,075	\$14,662	97.26
180	FM-0056869	Los Angeles	Burbank Courthouse	19-G1	1	failing and not providing cooling. Dept. 1G, Clerk's area and Civil area is too warm.	5	12,050	\$10,937	90.76
100	- W 0030003	Los / mgeres	Barbarik Coartiroase	13 61		Plumbing- Replaced pipes that were leaking. 3 section of ¾ inch copper pipe, (1) ¾ union, & (1) ¾ inch ball	<u> </u>	12,030	Ψ10,337	30.70
						valve,30x40 affected area (Men's public restroom, women's restroom, hallway to 272F, Dep. 5, Dep. F, traffic,				
						jury room, and hallway to public jury room), Prep ACM work in 10x10 area of plaster ceiling and (7) 7x7 critical				
181	FM-0056870	Los Angeles	Glendale Courthouse	19-H1	1	barriers, exctract 100 gallons of contaminated water.	\$	15,100	\$13,672	90.54
						Plumbing - Replace failed roof drain with new No-Hub 3" roof drain, drain ring. Replace 2-3 feet of failed drain				
			Pomona Courthouse			pipe under the roof deck, reseal roof deck around drain unit. Work required in ceiling area above Sheriff's				
182	FM-0056871	Los Angeles	South	19-W1	2	office.	Ş	5,281	\$ 4,813	91.14
			Chatsworth			Plumbing - Replace failed and leaking water supply hardware and install new 2 1/2 three piece ball valve in public men's restroom and 1 1/2 ball valve in the women's restroom. Work impacts Public Men's Restroom and				
183	FM-0056872	Los Angeles	Courthouse	19-AY1	2	2nd floor Women's Restroom inside Dept. 2700.	ς .	5,266	\$ 4,413	83.8
103	1101 0030072	LOS Angeles	Clara Shortridge Foltz			211d 11001 Women's Restroom inside Dept. 2700.	-	3,200	7 -,-15	05.0
			Criminal Justice			Fire Protection - Fire sprinkler located in Elevator Shaft is not to code and must be removed per SFM				
184	FM-0056873	Los Angeles	Center	19-L1	2	notification. Permit will not be released until work is complete.	\$	2,902	\$ 2,902	100
			Edmund D. Edelman			Fire Protection - Replace (52) Sprinkler Heads and Escutcheons and Replace (20) outdated pressure gauges				
185	FM-0056874	Los Angeles	Children's Court	19-Q1	2	throughout building. Also Fire Pump Room, Riser #2 replaced failed coupling.	\$	12,416	\$ 8,690	69.99
						Vandalism - Vandalism in the public restrooms on floors #5-8 is creating a safety issue to staff and public.				
			Motropolitar			Etching on sinks, bathroom partition walls, toilet seats and mirrors. Install graffiti mirror film on 16 mirrors,				
106	FM-0056875	Los Angeles	Metropolitan Courthouse	19-T1	ر ا	remove and replace 28 toilet seats, paint and epoxy sinks, and sand/paint the restroom walls and partition	٥	10,232	\$ 9,673	94.54
190	141-0030673	LOS ALIBEIES	Wakefield Taylor	13-11		doors. Electrical - Replace Failed 20 Amp circuit breakers on panels #E1 and #V1; Breakers were found to be failing	٦	10,232	7,073	34.34
187	FM-0056876	Contra Costa	· ·	07-A2	2	during IR scans.	Ś	4,344	\$ 4,344	100
	20000.0	20000			- -	Elevators, Escalators, & Hoists - Elevator cab interior panels are badly damaged and deteriorated. Current	<u> </u>	.,	.,	
						system delaminating including failure of metal fixtures creating potential safety issues. Install 7 new laminate				
188	FM-0056877	San Diego	Juvenile Court	37-E1	2	material on cab panels.	\$	7,848	\$ 5,856	74.62

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Elevators - Replace failed elevator components (2) communication boards, one (1) car operating panel interface board, seventeen (17) Floor push buttons, six (6) key switches, one (1) ADA phone, one (1) Emergency light board, two (2) PI boards, three (3) emergency light batteries, one (1) fire service cabinet fixture, and two				
			Downtown Superior			(2) seismic/fire button jewels (seismic, fire) Elevator #4 has failed due to water intrusion damaging controls				
189	FM-0056878	Santa Clara	Court	43-B1	1	and is non operational at this time.		\$39,371	\$39,372	100.00
100	5555575		Court	1.5 22		Electrical - Existing 2000A Westinghouse ATS has failed. Replacement parts are no longer available. Demo		Ψ00/07-	γου,σ.	100.00
						existing and install 1 new 2000A ATS with microprocessor controls and NEMA 1 cabinet. Install five 50 LF (250				
			Edmund D. Edelman			LF) runs of 500 MCM cable for low side and 120 LF of 500 MCM cable for high side. Install 9 500 MCM lugs.				
190	FM-0056879	Los Angeles	Children's Court	19-Q1	2	Building power will be shut off for 12 hours while ATS is replaced.	\$	108,896	\$ 76,216	69.99
						Security - Correct failed Andover Access Control System - Current system software, operating system,				
			Criminal Court			input/output and control modules are not operational, causing perimeter, holding cell, in-custody transport,				
191	FM-0056882	Napa	Building	28-A1	2	secure space and Courtroom security/safety issues.	\$	133,300	\$ 133,300	100
192	FM-0056883	Los Angeles	Pomona Courthouse South	19-W1	2	HVAC - Due to age/corrosion Cold & Hot Water Coils for 3rd, 6th and 7th flr Air Handler Units are leaking and need to be replaced. Leaking coils have caused deterioration of condensation pans and floor drains; both will be replaced. Spring Isolators on AHU-5 require replacement. Perform environmental testing, set up containments. Install 10 new 680lb Fail Safe Spring isolators. Replace 2 cold water coils, 1 hot water coils with custom made coils. Replace condensate drain pans with custom units.	\$	379,957	\$ 346,293	91.14
						Interior Finishes - Ceiling tiles in the Press Room are deformed, stained and have become weak and brittle due to past leaks. The potential for ceiling tiles to fall is present with resulting ACM contamination. Remove, dispose				
193	FM-0056884	San Diego	County Courthouse	37-A1	2	and replace approximately 1,050 sq. ft. of ceiling tiles per ACM protocols.	\$	17,411	\$ 17,411	100
			New Mammoth			HVAC - Redesign and install new components for the snow melt system. Modification are required in order to		40-01-	4	
194	FM-0056886	Mono	Lakes Courthouse	26-B2	1	allow safe ingress and egress to the building during the winter months.		\$35,247	\$35,247	100.00
105	ENA 00E (000	Nana	Historical Counth avec	30 D1	_	HVAC - Replace failed Package AC compressor (1 of 2), replace return air fan belts, bearings, shaft and sheaves -	ے ا	20.640	¢ 20.640	100
		Napa	Historical Courthouse		2	Unit is not operationally effective causing room temps of 78-85 degrees. Plumbing - Replace 9 valves, 12 flanges. Rebuild (2) 15HP pumps and (1) 7.5 HP pump. Replace (1) 15 HP ODP motor and (1) motor mounting. Domestic water pumps are deteriorated and require replacement. 60% of	Ş	30,649		
196	FM-0056890	Los Angeles	Airport Courthouse	19-AU1	2	system has failed. Loss of the last pump will result in the courthouse losing water supply.	\$	41,416	\$ 31,961	77.17
107	ENA 0056901	Mandacina	County Courthouse	22 41	2	Interior Finishes - Modification - Family Law In-custody Courtroom 'F' judicial officer, clerk and parties at high security risk due to small size and configuration of old Muni courtroom also with poor acoustics. Bench and witness stand modification to reconfigure and reorient for safe proceedings and accurate court reporter	خ	10 207	¢ 10.207	100
19/	FM-0056891	Mendocino	County Courthouse	23-A1		operations. Electrical - Relocate existing electrical outlets from the floor to the wall. Currently there are electrical outlets	٦	19,207	\$ 19,207	100
			Stanley Mosk			located on the floor in multiple workstations in room 102; chords and plugs in the floor outlets are being kicked				
109	FM-0056892	Los Angeles	Courthouse	19-K1	2	and damaged causing major safety hazards.	ر	7,069	\$ 6,875	97.26
130	TIVE OUDUCE	LO3 Aligeles	Courtilouse	10-NT		and damaged causing major sarety nazarus.	٧	7,009	0,675	37.20
199	FM-0056893	Santa Clara	Morgan Hill Courthouse	43-N1	2	HVAC - Replace (1) thermal expansion valve, system oil charge, filter dryer and (1) new isolation valve evacuate system. dedicated cooling system for IT equipment has failed components and is not operational at this time.	\$	6,779	\$ 6,779	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			B.F. Sisk Federal			HVAC - Replace failed heat exchange on boiler #3. Materials covered under warranty. Replacement labor is not,	١.			
200	FM-0056894	Fresno	Courthouse	10-01	2	replacement required to provide sufficient building heat.	\$	11,117	\$ 11,117	100
							١.			
201	FM-0056898	Los Angeles	Airport Courthouse	19-AU1	2	Elevator - Replace failed Amp traps and lower sheave switch on Elevator #4. Unit is inoperable at this time.	\$	2,290	\$ 1,767	77.17
						Plumbing - Replace failed Airtrol valve on heater water expansion tank (boiler) #2. Unit has failed and not	_		4	
202	FM-0056899	Los Angeles	Airport Courthouse	19-AU1	2	allowing water to pass through.	\$	2,814	\$ 2,172	77.17
202	FN 4 00 F 000	_	B.F. Sisk Federal	10.01	_	Electrical - Replace the bad underground wiring from the O Street pedestrian gate call box to inside the building	۸ ا	2.025	ć 2.025	100
203	FM-0056900	Fresno	Courthouse	10-01	2	with direct burial Cat 6 wire - Call box is not functioning due to damaged wiring.	\$	2,825	\$ 2,825	100
						Electrical - Run new conduit and install new UL rated exit signs with emergency lighting combo and replace power efficient exit signs with e-lighting where needed. Currently there are no UL rated Exit signs in the 1st & 2nd secured hallways (1953 side of building). The City of Burbank Fire Marshall has requested the installation of				
204	FM-0056901	Los Angeles	Burbank Courthouse	19-G1	2	exit signs with emergency lighting.	\$	2,750	\$ 2,496	90.76
205	FM-0056902	El Dorado	Johnson Bldg.	09-E1	2	Exterior Shell - Install Roof Access Ladder and walk off mat, to allow access to the Penthouse mechanical room from the exterior of the building - Currently access to the Penthouse mechanical room is through the county owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays contractor access.	\$	11,494	\$ 11,494	100
						Plumbing - Replace sink faucet broken by unknown vandal - Replace approximately 10 square feet of water				
			Hayward Hall of			damaged wallboard & six ceiling tiles Water damage in the 3rd floor jury assembly men's restroom and second				
206	FM-0056903	Alameda	Justice	01-D1	2	floor women's staff restroom.	\$	4,397	\$ 4,397	100
207	FM-0056905	San Diego	County Courthouse	37-A1	2	Electrical - Replace 25% (approx. 50 bulbs) of the light bulbs/ballast in D-16 courtroom, and re-lamp D-33 by replacing approx. 200 bulbs. Above ceiling work to occur per ACM protocols. Dept. 16 & 33 has poor lighting conditions due to burned out bulbs, ballast and a black substance/residue on the diffuser lenses. Exterior Shell - Remove and replace existing roof gutter system with new acrylic coated gal volume sheet steel rain gutter system at 5 locations. Install new downspouts and channel water away from building. Rain gutters	\$	16,845	\$ 16,845	100
						that serve the penthouse roofs are failing, loose and are no longer diverting water away from the building				
208	FM-0056907	San Diego	County Courthouse	37-A1	2	creating potential water intrusion and interior flooding.	\$	4,250	\$ 4,250	100
			Pomona Courthouse			Exterior Shell - Expansion joints have deteriorated allowing water to penetrate into the interior of the building flooding hallways and damaging ceilings during rainstorms. Set up (1) swing stage, grind out, clean, and acid etch 1450 SF of and around expansion joints. Install 5800 LF of polyurethane backer rod and caulk 5800 LF of	,			
209	FM-0056908	Los Angeles	South	19-W1	2	joints with single component polyurethane joint sealant.	\$	185,188	\$ 168,780	91.14
						Fire Protection - Replace 2 EA sets, 4 total, (12 x 30 each) of won doors at second and third floor elevator lobby.				
	F. 4 00=00=0			07.10	_	Replace existing track with new curved track system. Existing doors are literally falling apart. They do not close		004.05	A	
210	FM-0056909	Contra Costa	Bray Courts	07-A3	2	all the way. These are fire doors and this is a safety issue.	\$	264,961	\$ 226,595	85.52
211	FM-0056911	Los Angeles	San Fernando Courthouse	19-AC1	2	HVAC -Corrections needed for Chiller #1 & 2 due to deficiencies found during Level VIII PM 2462651 & 2462638. Overhaul recommended to prevent downtime, damage and loss of comfort cooling to the courthouse. Purge all refrigerant and lube oil piping. Replace compressor journal bearings and high and low speed thrust bearings. Replace compressor shaft seal, PRV control shaft seals and motor bearings. Install refrigerant cleanup kit. Replace (2) condenser water rubber vibration eliminator joints.		223,294	\$ 186,250	83.41
	1 0000011	1-00700100		1-5			7	,	100,200	55.11

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
212 FM	И-0056912 E	l Dorado	Juvenile Hall	09-G1	2	Roof - Install a new TPO 80 MIL Single Ply overlay (Approximately 2400 sf) over the existing membrane - The existing roof is leaking and needs to be repaired before any damage occurs	\$	49,000	\$ 49,000	100
		os Angeles	Inglewood Courthouse	19-F1	1	HVAC - Replace 25hp supply side drive motor, front and rear bearings, sheaves, and bushings on the supply drive shaft. Replacement of 15 & 25hp VFDs, that were defective. AHU#2 was not operational and a section of the building was hot. Plumbing - Remediate flood water damage in 2nd floor Clerk's Area, Window #7 under ACM protocols. In-	·	\$40,000	\$40,000	100.00
214 FM	И-0056916 L	os Angeles	Van Nuys Courthouse West	19-AX2	1	custody in the 4th floor Lock-up jammed a drinking fountain and stopped drain, causing water to run down pipe chase and leak into the 2nd floor.		\$15,080	\$12,136	80.48
		os Angeles	San Fernando Courthouse	19-AC1	1	Plumbing - Remediate water damage from failed plumbing inside wall between the Men's and Woman's restroom in the public defender's office on the second floor under ACM protocols. Replace damaged 30' x 30' area of failed ceiling tiles.		\$67,234		100.00
213 1 1 1	/I-0030917 L	US Aligeles	Courtilouse	13-AC1	1	HVAC - Replace failed Y Strainer on chill water pump#2. Leak impacted the Jury Assembly room affecting a 5' x		707,234	307,234	100.00
216 FM	И-0056919 L	os Angeles	Mental Health Court	19-P1	1	20' area of carpet. Remediate water damage per ACM protocols.		\$30,213	\$21,545	71.31
			Santa Clarita			County Managed - HVAC - Replace cooling tower pump. Install new gasket and mounting plate. Cooling tower				
217 FM	л-0056920 L	os Angeles	Courthouse	19-AD1	1	pump failed causing high temps in all the civic center buildings.		\$1,909	\$1,909	100.00
			Santa Clarita			County Managed - HVAC - Replace 5 leaking bundles to boiler and restore to normal operation. Boiler failed due				
218 FM	И-0056921 L	os Angeles	Courthouse	19-AD1	1	to the leaks.		\$2,545	\$2,545	100.00
219 FM	л-0056922 L	os Angeles	Edmund D. Edelman Children's Court	19-Q1	2	Interior Finishes -Replace failed 1 electrify panic exit device on the East Front Exit Door and 1 rim panic exit device on the West Front Exit Door. During after hours when the court personnel are leaving, the doors are not locking leaving the exit doors unlock and open.	\$	3,715	\$ 2,600	69.99
220 EN4	1-0056923 S	anta Barbara	Santa Barbara Figueroa Division	42-B1	2	HVAC - Replace failing Cooling Tower sheaves and bushings for fan motor and blower shaft. Replacement required to prevent further damage to Cooling Tower.	خ	2 207	¢ 2.297	100
220 5101-	1.0030223 3	anta Dalbala	San Fernando	→ 7_ΩŢ		HVAC - Remove and renovate leaking Condenser water pump motor. Water pump is leaking from the shaft seal	۲	2,287	\$ 2,287	100
221 FM	1-0056924 L	os Angeles	Courthouse	19-AC1	2	causing excessive loss of water and chemical.	Ś	7,980	\$ 6,656	83.41
			Pomona Courthouse			HVAC - Replace (1) failed cut-out water probe sensor. Current status will not allow unit to pass AQMD code		. ,555	, 3,030	33.11
222 FM	1-0056925 L	os Angeles	North	19-W2	2	requirements.	\$	2,396	\$ 2,306	96.25
		<u> </u>				Elevators, Escalators, & Hoists - Replaced failed shaft seal on elevator #9. Remove and dispose of oil within	·	,	,	
223 FM	1-0056926 S	an Diego	County Courthouse	37-A1	2	elevator pit per HAZMAT protocols.	\$	4,147	\$ 4,147	100
224 FM	1-0056927 S	olano	Old Solano Courthouse	48-A3	2	Electrical -Replace failed speed governing components on emergency generator. Work to include magnetic pick- up & speed switch and engine governor-actuator and main control circuit board. Generator trips out on over- speed and shuts down when needed during electrical power outages	\$	6,889	\$ 6,889	100
			C 5			HVAC - Replace (1) Shaft, (2) Bearings, (1) driver in Cooling Tower #1. Bearings and shaft have excessive rust				
225 514	4 00E6020	oc Angolos	San Fernando	10 461	2	build-up and are failing due to high temperatures. Resulting failure to condenser water cooling within this	ا د	11 043	¢ 0.310	02 44
223 FIVI-	1-0056928 L	os Angeles	Courthouse Pomona Courthouse	19-AC1		chillers creates warm HVAC supply temps. HVAC - Replace failed flame sensor and install new plugs on leaking water tubes. Continued delay in repair	٦	11,042	\$ 9,210	83.41
226 FM	1-0056929 L	os Angeles	South	19-W1	2	could flood mechanical room and take system off-line.	ς .	4,532	\$ 4,130	91.14
220 1111	1 0030323 L	0371180103	Kearny Mesa Traffic	10 VVI		Fire Protection - Install a new KOSO automatic natural gas shut off valve and pipe back into main. Work is	7	7,332	7,130	31.17
227 FM	1-0056932 S	an Diego		37-C1	2	required by code.	\$	3,877	\$ 3,877	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - Replace failed digital thermometers in the evaporator and condenser liquid "dry wells", Chilled water				
			Alhambra			supply sensor and defective feedback potentiometer on Chiller #2. Court operation would have been impacted				
228	FM-0056933	Los Angeles	Courthouse	19-I1	2	if Chiller #2 was not restored.	Ş	3,900	\$ 3,354	86
222				0- 44		HVAC - Replace failed leaking pump on the DFT Boiler Feed Water Pump for Boiler #1. Replacement required to		0.674		40
229	FM-0056934	San Diego	County Courthouse	37-A1	2	restore system back to full operation.	\$	3,671	\$ 2,842	77.42
			Dalamatial di la mandia			Security - Secured Sally Port West Entrance Rolling Steel Door, the motor for the 12' x 12' door is no longer				
220	EN 4 00E 002E		Bakersfield Juvenile	45.64		functioning and is preventing access to the secured Holding Garage. Replace burnt out Chain Hoist Motor		F 052	6 5.053	100
230	FM-0056935	Kern	Center	15-C1	2	Operator and mount with heavy duty brackets.	\$	5,052	\$ 5,052	100
						Vandalism - Remediate vandalism damage 2- restroom ceilings, entry doors (100 sqft) and (94 chairs) to				
224	EN 4 00E C02C	l os Angeles	Towns as Counth ous	10.61	2	remove graffiti. The etching/scribing must be removed due to the contents may be gang related which could	ے ا	4.202	ć 2.647	OF 14
231	FM-0056936	LOS Afigeres	Torrance Courthouse	19-C1		cause a safety situation to the courthouse	Ş	4,283	\$ 3,647	85.14
232	FM-0056937	San Diego	North County Regional Center - South	37-F1	2	COUNTY MANAGED - Grounds and Parking lot - Remove and replace 6 existing trees from the slope in the Judges secure parking lot and Replace with drought resistant, low-maintenance trees. Building occupants have expressed their concern numerous times stating that sap from existing trees is causing vehicle damage.	\$	19,422	\$ 19,422	100
						Elevators, Escalators, & Hoists - Rebuild failing electrical generators on Elevators #1, #2, #3, and #4. Unit failure				
233	FM-0056940	Los Angeles	El Monte Courthouse	19-01	2	could create entrapments and negative impact to court operations.	\$	30,375	\$ 17,654	58.12
234	FM-0056942	Los Angeles	Airport Courthouse	19-AU1	2	HVAC - Courtrooms are too hot. Dampers actuators for AHU#3 & 4 found to be faulty and 30 VAV boxes were not connected. Replace (3) damper actuators and (2) valve actuators for AHU 3 & 4. Reconnect wiring for 30 VAV boxes and recommission. Upgrade obsolete BAS software from Siemens Apogee Insight software from v3.10 to v3.13, install Remote Email Notification, install BAS Uninterrupted Power Supply, back up data for (9) Siemens controllers and replace (6) batteries for Siemens FLNC controller.	\$	58,347	\$ 45,026	77.17
		0.11				Electrical - Remove and cover obsolete/disconnected Duress Call devices (12) at all In-Custody elevator landings	<u>'</u>	/ -	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
235	FM-0056943	San Francisco	Hall of Justice	38-B1	2	- To prevent mistaking non-working devices for working devices	\$	2,000	\$ 2,000	100
			San Fernando			Plumbing - Water is leaking from the ceiling into the 2nd Floor, Men's Public Restroom affecting a 4' x 4' area of				
236	FM-0056945	Los Angeles	Courthouse	19-AC1	1	ceiling tiles. Remediate under ACM conditions.		\$13,565	\$11,315	83.41
237	FM-0056946	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	Interior Finishes - Install door in judge's room In Depart 22 - Cut and frame a new opening, install (1) custom aluminum frame, (1) custom laminated door, (1) mortise lock, (1) Norton closer and (3) 4.5" knuckle hinges. The Judge currently enters through the double entry courtroom doors near the public seating area. County Judicial Agency has concerns for Judge's safety and is requesting a separate door for entry/exit.	\$	9,914	\$ 9,914	100
			Edmund D. Edelman			Interior Finishes - Replace failed door closers on three cafeteria glass doors leading to the outside dining area.				
238	FM-0056947	Los Angeles	Children's Court	19-Q1	2	Doors are slamming. Work is required by ADA code and to mitigate risk to the public.	\$	4,216	\$ 2,951	69.99
230	FM-0056948	Los Angeles	Metropolitan Courthouse	19-T1	2	HVAC - Replace the non-functioning VFD and (1) 25HP US-Motor, pulley, bushing & belt to allow the air flow to be regulated throughout the 8th floor. The VFD is working on bypass and running full speed which could cause too much air to flow and over pressurize the ducting system causing damage.	¢	9,942	\$ 9,399	94.54
233	1 141 0030340	IFO3 VIIRCIES	Courtilouse	117 11		Too mach an to now and over pressurize the ducting system causing damage.	١٧	2,342	ر و و و و و	24.24

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Plumbing - Water leaked from the 4th flr deputies shower through ACM fireproofing into the 3rd flr court reporters office requiring a procedure 5. Replace 10SF of LCM ceramic tile & gypsum backing board, re-grout				
						50SF of tile, replace (2) shower valves & mixers, demo 6'x6' section of water damaged wall, install mold and				
			Metropolitan			mildew resistant drywall, install (1) 24"x24" access panel, paint and patch, replace 132 SF of ACM contaminated				
240	FM-0056949	Los Angeles	Courthouse	19-T1	1	carpet, and replace (26) 12"x12" ceiling tiles.		\$44,650	\$42,212	94.54
244	EN 4 005 C050	A la a al a	Wiley W. Manuel	04 D2	_	Vandalism - Replace (1) 7"X32 3/4" X 1/2 security glass view window on fifth floor cell 110-2 door. Window	_ ا	4 727	ć 4.727	100
241	FM-0056950	Alameda	Courthouse	01-B3	2	broken by an inmate. Plumbing - Redesign and modify strainer box from basement sewer discharge to lift station. Original design of	\$	1,737	\$ 1,737	100
			Modesto Main			strainer box is inconsistent with current jail operation and is creating obstruction to sewer discharge from				
242	FM-0056952	Stanislaus	Courthouse	50-A1	2	building to lift station.	Ś	2,279	\$ 2,279	100
	0030332		eeueuee	30712	_	Fire Protection - Replace a 4 - 6 ft section of 6" fire sprinkler, one 8" x 6" grooved coupling and one 6" grooved	<u> </u>		γ =,=3	
						coupling and two 6" OS&Y control valves (fire pump suction & discharge). Fire Pump Room has a section of 6"				
			East County Regional			Main Fire Pump Pipe rusting out and the 2 Main Shut off Valves are leaking and cannot properly secure the				
243	FM-0056953	San Diego	Center	37-I1	2	water.	\$	6,060	\$ 4,103	67.71
						HVAC - Replace failed canvas flex connectors in AHU01, AHU02, AHU04, AHU17, and AHU14. Canvas flex				
244	FM-0056954	Los Angeles	Compton Courthouse	19-AG1	2	connectors on these AHU are broken/deteriorated and need to be replaced.	\$	9,224	\$ 6,100	66.13
			South County			COUNTY MANAGED - Replace faulty gearboxes and fan motors for Cooling Tower at Central Plant, this				
245	FM-0056955	San Diego	Regional Center	37-H1	2	corrective measure is needed restore to normal efficiency.	\$	6,211	\$ 6,211	100
246	FM-0056956	Sacramento	Juvenile Courthouse	24-C2	2	HVAC - Upgrade existing BAS software system - Replacement of existing server requires higher level software in order to operate within new IOS.	ڔ	14,893	\$ 14,893	100
240	1101-0030330	Sacramento	Juverille Courtilouse	34-62		Electrical - Replace failed courtroom lighting (50%) within ACM ceiling plenum in Dept. #11. Courtroom lighting	٦	14,033	7 14,655	100
247	FM-0056957	San Diego	County Courthouse	37-A1	2	has failed to the point of impacting court operations.	Ś	8,293	\$ 8,293	100
						para grand and grand	т	3,23	7 3,23	
						Plumbing - Replace faulty and leaking basin faucet. During building water outage install new "in-line" ball valves				
			Van Nuys Courthouse			for this faucet and 4 other faucets/toilets 7th Floor secure hall. Janitor's wash basin has a leaking basin faucet,				
248	FM-0056958	Los Angeles	East	19-AX1	2	there is no shut off for hot & cold supply lines, there is a risk of flooding if basin sink plugs up or if faucets fail.	\$	2,972	\$ 2,667	89.74
						HVAC - Replace failed purge unit and inline refrigerant filters on Chiller #1. Hardware failure is causing Chiller #1	١.			
249	FM-0056959	Los Angeles	Torrance Courthouse	19-C1	2	to run at a high temperature.	Ş	8,738	\$ 7,440	85.14
						Interior Finishes - Replace 6 defective courtroom gallery seats in 2nd Floor Dept. 241 within ACM environment.				
			Inglewood Juvenile			The attachment points on the metal frame for seat #1, #2 and #3 are broken and cannot be repair. This is a safety hazard and the seats must be replaced. This row of seats is not modular and entire row of six seats must				
250	FM-0056960	Los Angeles	Court	19-E1	2	be replaced.	Ś	8,788	\$ 7,099	80.78
	FM-0056961	Los Angeles	Airport Courthouse	19-AU1	2	HVAC - Replace failed Refrigeration Leak Detection Monitor. Replacement required by code.	\$	9,339	•	77.17
		<u> </u>	, , , , , , , , , , , , , , , , , , , ,			HVAC - Remove and replace one (1) 4 bolt flanged bearing on Air Handler Unit #3. Air Handler Unit #3's supply	1	,	,	
			Pomona Courthouse			fan bearing is very noisy and has excessive amounts of vibration when running. Failure will result in system				
252	FM-0056962	Los Angeles	South	19-W1	2	down time and emergency repairs.	\$	2,087	\$ 1,902	91.14
						HVAC - Replace failed two way heating valve and two (2) thermostat controls The heat exchanger will only				
			Pomona Courthouse		_	provide domestic hot water at 100 degrees due to the two way heating valve is stuck in mid position and not	_		_	
253	FM-0056963	Los Angeles	South	19-W1	2	opening causing low water temperatures throughout the higher floors.	\$	7,546	\$ 6,877	91.14

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF		FACILITY MODIFICATION PROGRAM SHARE % OF COST
254	FM-0056965	Monterey	Monterey Courthouse	27-C1	2	County Managed - Electrical - install replacement generator - Current equipment has failed. A temp rental has been deployed during replacement.	\$	36,750	\$ 36	,750	100
		Los Angeles	Pomona Courthouse South	19-W1	2	Roof - Build-up roof area (400 sq. ft) around cooling towers, replace roofing material and install 1 new roof drain and divert all the water into new drain system. Rain water sits on the roof, under and around the cooling towers after each rain. The rain water leaks into the building and causes damage.	\$	16,688		,209	91.14
256	FM-0056968	Orange	Central Justice Center	30-A1	2	Interior Finishes - Elevator rooms 7 through 15 lack secondary containments required to complete CUPA permitting. Remove 1163 SF of epoxy paint, prep and epoxy fill 125 LF of cracks, construct 55 LF of new containment berms in rooms 7-15, acid wash and degrease 1163 SF of concrete, apply 825 SF of Petra Xtra-Kote TC to horizontal surfaces, and apply 338 SF of Petra Xtra-Kote TC to vertical surfaces.	\$	54,674	\$ 49	,846	91.17
257	FM-0056969	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	HVAC - Install (1) York Optiview board, (1) service trigger kit, (1) time clocks, and (1) Eprom on Chiller #2. Chiller is non operational due to failed circuit boards and microprocessors. Electrical - Replace main breaker handle, Kirk Keys, broken indicator lights on 4160 transformer. Main breaker	\$	26,875	\$ 19	,756	73.51
258	FM-0056970	Orange	Central Justice Center	30-A1	2	handle and kirk keys are missing and 8 indicator lights are out creating operational risk of building not being able to restore power in the event of the transformer tripping.	\$	27,755	\$ 25	,304	91.17
250	EN4 0056072	Los Angolos	Metropolitan Courthouse	19-T1	2	Interior Finishes - Dept. 70 Cashier's Public stadium seating; 14% of seats are completely broken & missing seat bottoms. Approx. 80% have broken or missing springs/bearings and replacement parts are obsolete. Seats need to be replaced as this is a safety issue for the public when trying to sit. Demo 101 existing damaged chairs, fill mounting holes and install 101 new American Seating Model 408 fiberglass seats and secure with epoxy. Perform environmental testing and set up 30'W x 32' L x 8' H containment.	٠	79 660	¢ 74	274	94.54
		Los Angeles Los Angeles	Metropolitan Courthouse	19-11 19-T1	2	Exterior Shell - Windows have been vandalized and are severely etched. Etching is deep and requires glass replacement and addition of anti-graffiti (A/G) film. East 1st Flr: Replace (12) 33-1/4"x33" tinted tempered glass panes; Install A/G film on 17 windows. North 1st Flr: Replace (3) 24"x78" tinted tempered glass panes; install A/G film on 4 windows. West 1st Flr: Install A/G film on 3 windows. Flrs 2 - 8 replace 174 tinted tempered glass panes (19"x90") and install A/G film on 199 windows.	\$	78,669 197,385		,608	94.54
	555575		25		_	HVAC - Replace six (6) failed 5/8 diameter x 4 long capillary tubes, install 1 filter dryer. Leaks causing unit to not	7	· · · · · · · · · · · · · · · · · · ·		,	3 1
261	FM-0056976	Contra Costa	Bray Courts	07-A3	2	provide sufficient cooling.	\$	8,766	\$ 7	,497	85.52
262	FM-0056977	Fresno	Firebaugh Court	10-K1	2	HVAC - Remove old leaking condenser water pump and replace with a new Gould 1 1/2 HP pump and motor.	\$	3,755	\$ 2	,179	58.02
		Orange	West Justice Center Pomona Courthouse	30-D1	2	Plumbing - Storm Drain Lines are cracked and damaged - Line two (2) 3" storm drain lines, approximately 40' per line. Drain lines are leaking into the detention tunnel creating a slip/fall safety issue. Plumbing - Replace 30ft of 4 cast iron pipe. Replace 2 cracked pipe coming from 7th floor janitorial mop sink and 30ft of sewer line on the 6th floor courtroom. A section of the building's water waste piping system has	\$	8,480		,690	90.68
264	FM-0056980	Los Angeles	South Delano/North Kern	19-W1	2	deteriorated, this is causing leaks into the court room. HVAC - Install (1) new evaporator coil, filter drier, txv (expansion valve). Current evaporator coil for PKU#10 is	\$	9,656	\$ 8	,800	91.14
265	FM-0056981	Kern	Court	15-D1	2	failed and no longer providing cooling to the main lobby and District Attorney's offices.	\$	11,629	\$ 9	,378	80.64

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
200	ENA 00EC002	Conto Doubous	Santa Barbara	42 D1	2	HVAC - Replace (2) inline centrifugal pumps, replace (2) pressure gauges, replace (2) copper flanges and (2)	_	26 242	ć 26.242	100
200	FM-0056982	Santa Barbara	Figueroa Division Stanley Mosk	42-B1	Z	copper 90s. Hot water pumps #1 and #2 and the pump flanges are badly corroded and leaking. Elevators, Escalators, & Hoists - Replace failed electrical generator on Elevator #2, Unit is stuck on the 2nd floor) 	26,313	\$ 26,313	100
267	FM-0056983	l os Angeles	Courthouse	19-K1	1	and not responding. Bearing failure caused grounding of the unit.		\$65,100	\$63,316	97.26
						HVAC - Replace (2) custom chilled water coils, (2) 2-1/2" butterfly valves and (2) 2-1/2" pneumatic control valves, perform hydrostatic test and re-insulate 60 LF of 2-1/2" pipe. Chilled water coil needs to be replaced as it is not cooling the area. The coil shows signs of severe blockage and condensate is carrying over onto the AHU				
268	FM-0056985	San Diego	County Courthouse	37-A1	2	floor creating a slip hazard.	 \$	37,139	\$ 37,139	100
260	FM-0056986	Los Angeles	Torrance Courthouse	10 C1	2	Elevators, Escalators, & Hoists - Rebuild elevator electrical generator. Generator #2 has begun to fail resulting in the car not leveling properly creating a trip hazard for passengers.	ا د	33,372	\$ 28,413	85.14
		Los Angeles	Airport Courthouse	19-AU1	2	HVAC - Replace 75HP VFD and combination starter bypass and program VFD into court house BAS system and update graphics. AHU #2's VFD shorted out after an over current. AHU #2 is currently operated exclusively in bypass mode.	\$	36,152		77.17
			Downtown Superior			Exterior Shell - Vandalism - Replace (1 each) 76 X 88 broken front window - Currently compromising the courts				
271	FM-0056988	Santa Clara	Court	43-B1	1	security access		\$5,117	\$5,117	100.00
272	FM-0056989	Santa Clara	Santa Clara Courthouse Fremont Hall of	43-G1	2	Plumbing - Replace (1) failed underground plumbing connection to sewer line, install (1) two way cleanout. Currently impacting the Courts storm sewer ability to drain and will cause flooding. Grounds and Parking - Remove (4) dead plum trees including stump grinding. Safety issue. Branches and dead trees have a huge potential to fall on people causing injury during the stormy weather. Limbs have fallen in the	\$	5,185	\$ 5,185	100
273	FM-0056990	Alameda	Justice	01-H1	2	past	5	3,502	\$ 2,781	79.4
		Alameda	Wiley W. Manuel Courthouse	01-B3	2	Grounds and Parking Remove (3) dead olive trees and stump. Trees having visible structural hazards and liabilities in stormy weather. Safety Issue. Branches have fallen in the past during rainy, windy storms. HVAC - Install cooling unit in first floor AV closet - Install (1) 120V/20A dedicated circuit for cooling unit - install	\$	5,991		83.8
275	EN 4 00E 0002	Carata Claria	11-11-6 1	42.42	2	20' of 6" flexible ductwork for condenser exhaust - fire caulk all penetrations. Lack of cooling in the space is	,	4.020	4.020	100
		Santa Clara	Hall of Justice (West)			causing Court AV equipment to shutdown HVAC - Install cooling unit in first floor AV closet - Install (1) 120V/20A dedicated circuit for cooling unit - install 20' of 6" flexible ductwork for condenser exhaust - fire caulk all penetrations - Lack of cooling in the space is	,)	4,030		100
276	FM-0056993	Santa Clara	Hall of Justice (East)	43-A1	2	causing Court AV equipment to shutdown	\$	5,923	\$ 5,923	100
277	FM-0056994	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	Interior Finishes – Replace 45 sq. ft. of epoxy paint flooring and 14 linear ft. of epoxy paint for the base. Courtroom holding cell flooring is starting to fail and it is easy to be broken off into pieces which creates a safety hazard due to in custody visitors creating cutting/stabbing type of weapons.	Ś	6,026	\$ 4,430	73.51
						Elevators, Escalators, & Hoists - Replace the failing generator brushes for Elevators 1, 2, 3 and 4. Replacement	+ -	2,023	., ., .,	1 3.3 2
278	FM-0056995	Los Angeles	Airport Courthouse	19-AU1	_2	required to maintain operations.	\$	4,027	\$ 3,108	77.17
279	FM-0056997	San Diego	County Courthouse	37-A1	2	HVAC - Exhaust Fan #38 bearing and shaft repair - Remove the existing (2) pillow-block bearings and replace with factory supplied pillow-block bearings type BB Size 330 1 15/16 for Exhaust Fan #38. The South Tower is without exhaust air in the restrooms due to bad bearing and shaft. Operational fan units are required by code.	\$	12,905	\$ 9,991	77.42

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
200	ENA ODECODO	Los Angolos	Clandala Courthousa	10 11	,	Electrical - Replace and rewire 1 defective light fixture under ACM protocols. Main lighting over the bench has	ے ا	4 690	¢ 4 245	00.54
280	FM-0056998	Los Angeles	Glendale Courthouse	19-01		failed and requires replacement. Elevators, Escalators, & Hoists - Replace failed emergency reset and amplifier circuit cards for Elevator 8. Install	Ş	4,689	\$ 4,245	90.54
281	FM-0056999	San Diego	County Courthouse	37-A1	2	one new drive contactor and for (4) new amp traps. The staff pedestrian traffic is delayed due to elevator being non-operational.	\$	7,474	\$ 5,786	77.42
202	FN4 00F7000	l os Angolos	Airport Courthouse	10 4111	1	HVAC - Replace failed 75 HP motor for Air Handler 1, and integrate into the Building Energy Management		¢17.762	¢12.707	77 17
282	FM-0057000	Los Angeles	Airport Courthouse	19-AU1	-	System. Air Handler Unit 1 main motor is not functioning.	1	\$17,762	\$13,707	77.17
283	FM-0057001	Santa Clara	Santa Clara Courthouse	43-G1	2	Grounds and Parking - Remove (5) hollowed out beetle infested dying pine trees with exposed roots. Trees are heavily leaning sideways into the parking lot. Remove (1) dead redwood tree near the gas meter and main. Safety issue when the storms begin. Dead and dry cracked limbs have already fallen during heavy winds.	\$	8,373	\$ 8,373	100
			Pasadena			Electrical - Replace 40 failed lobby lights. 60% of lights have failed. ACM containment and disposal required. No lights are on in front lobby, this creates a safety and security hazard for early morning at end of day weapon				
284	FM-0057002	Los Angeles	Courthouse	19-J1	1	screening processing.		\$33,818	\$23,453	69.35
285	FM-0057003	Santa Clara	Downtown Superior	43-B1	1	HVAC - Replace (1) failed condenser float valve and damaged components for the Cooling Tower that flooded two Courtrooms. Extracted approx. 330 gallons of clean water from approx. 1000 sq ft of court space. Remediated and replaced 224 square feet of damaged VCT tile including ACM abatement		\$36,901	\$36,901	100.00
206	FN4 00E7004	Los Angolos	Pomona Courthouse	10 \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	1	HVAC - Replace failed drain line for Chiller #2. Remediate flooding water throughout the mechanical room and		¢10 100	¢0.204	01 14
280	FM-0057004	Los Angeles	South	19-W1	1	basement under ACM procedures. Exterior - Renovate and waterproof approximately 825 sf of crack and molded stucco on the north exterior wall.		\$10,198	\$9,294	91.14
287	FM-0057005	El Dorado	Cameron Park Arnason Justice	09-C1	2	Work required to prevent water intrusion and potential interior flooding. HVAC - Replace one Failed Burner Controller Board on Boiler #2. Board has failed and the boiler will not	\$	4,550	\$ 4,550	100
288	FM-0057007	Contra Costa	Center	07-E3	2	operate.	\$	4,312	\$ 4,312	100
						Pest Control - Building exterior - Using a 40' boom truck Remove and remediate damage caused by a 3' x 4' beehive on the exterior eves of the west side of the building. The beehive creates an unsafe environment for				
289	FM-0057008	Solano	Hall of Justice	48-A1	2	court staff and visitors.	\$	5,461	\$ 3,977	72.82
290	FM-0057009	El Dorado	Main St. Courthouse	09-A1	2	HVAC - Replace the defective High Pressure Sensor Cut-Out device and the Discharge Temperature Sensor. Chiller compressor is not cycling and is causing the compressor to overheat. Grounds and Parking Lot - Install 80 skate stops at 3ft intervals on assigned planter beds on front and back	\$	4,079	\$ 4,079	100
			Turlock Superior			public entry to the courthouse. Closure and removal of City Skate Park in adjacent lot has had negative impact and recent change in skaters using court property. Skaters are creating a potential public hazard during court				
291	FM-0057010	Stanislaus	Court	50-D1	2	operational hours.	\$	3,583	\$ 3,583	100
	ENA 00E3011		George D. Carroll	07.54		Fire Protection - Replace (10) Damaged Sprinkler Heads, (4) missing escutcheons, and (12) Hoses that are out of		0.000	6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	7.00
		Contra Costa	Hayward Hall of	07-F1	2	HVAC - Replace Building Automation System (BAS) with new and current technology. Provide and install one (1) panel mounted BAS workstation configured with Windows 7 Pro and one (1) Automation Server. Upgrade installation to StruxureWare and migrate existing system configuration, sequence and graphics. Current system		8,089		74.99
293	FM-0057013	Alameda	Justice	01-D1		has failed components that are discontinued and no longer available or supported by the manufacture.	\$	18,229	\$ 16,096	88.3

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - Replace Building Automation System (BAS) with new and current technology. Provide and install one (1)				
						panel mounted BAS workstation configured with Windows 7 Pro and one (1) Automation Server. Upgrade				
204	ENA 0057044	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Davidaday Cayyethayya	01.61	_ ا	installation to StruxureWare and migrate existing system configuration, sequence and graphics. Current system	,	10 220	ć 10.220	100
294	FM-0057014	Alameda	Berkeley Courthouse Bellflower	01-G1	2	has failed components that are discontinued and no longer available or supported by the manufacture. Plumbing - Remove and renovate failed sump pump #1 and #2. Remediate black water overflow in the Lock-up	>	18,229	\$ 18,229	100
205	FM-0057016	Los Angeles	Courthouse	19-AL1	1	areas on 1st, 2nd, 3rd & 4th firs affecting 6,939sf. Inmate vandalism caused pumps to fail.		\$69,685	\$54,312	77.94
233	1101 0037010	LOS Aligeres	Courtilouse	IJ ALI		areas on 1st, 2nd, 5rd & 4th ms arrecting 0,555si. minate variation caused pumps to rail.		705,005	γJ - 7,512	77.54
						Plumbing - Replace a 20 ft section of 4" cast iron drain pipe under ACM protocols. North Side Exterior of				
296	FM-0057017	Los Angeles	Compton Courthouse	19-AG1	1	Building a 4" Cast Iron Drain Pipe is cracked and leaking into the employee lounge and maintenance office.		\$9,383	\$6,205	66.13
		<u> </u>						1-7	, , , , ,	
			Del Norte County			Exterior Grating - Replace rusted grates (2) - replace rusted grating at 2 locations, 1- approx. 240 sq ft with				
297	FM-0057018	Del Norte	Superior Court	08-A1	2	fiberglass grating due to location near ocean, 1- approx. 13 sq ft with frame and fiberglass grating with lock.	\$	11,513	\$ 7,054	61.27
						HVAC - Replace shorted compressor and malfunctioning thermostat control for ACU #1 that serves the				
						courtroom exclusively Compressor is not working due to winding wires being shorted and thermostat is not				
298	FM-0057020	Kings	Avenal Court	16-C1	2	functioning properly.	\$	3,122	\$ 3,122	100
			B.F. Sisk Federal			Elevators - Enhance elevator #3 programming to ensure that elevator will not allow public access to the secured				
299	FM-0057021	Fresno	Courthouse	10-01	2	area. Current operation allows intermittent access.	\$	4,956	\$ 4,956	100
						HVAC - Replace failed condensate pan. Pan failure caused condensate to run off through the elevator				
200	EN 4 00E 7022		N. II C. II	40.444		penthouse to the 7th floor mediation room #701 dripping through the ceiling tiles replace (6) 24"x24" ceiling		ć4F 220	ć42.02 7	05.03
300	FM-0057022	Los Angeles	Norwalk Courthouse	19-AK1	1	tiles and remediate water from approximately 6'x6' of carpet per ACM protocols.		\$15,320	\$13,027	85.03
201	EN4 00E7024	Los Angolos	Compton Courthouse	10 461	1	HVAC - Replace failed 40 HP VFD. Currently 40 HP motor is running at a 100% which is causing air noise in courtrooms and it may over pressurize and damage ducting.		¢10 01E	\$6,623	66.13
301	FM-0057024	Los Angeles	Pasadena	: 13-AG1		Elevators, Escalators, & Hoists - Replace relay on the main power supply to all elevators. All elevators are down,		\$10,015	Ş0,023	00.13
302	FM-0057025	Los Angeles	Courthouse	19-J1	1	there is no power going to the elevators.		\$10,100	\$7,004	69.35
302	6657625	2007ge.es		13 01	_	Grounds and Parking Lot - Judges secured parking gate - Remove and replace the failed gate openers (left and		Ψ10)100	Ψ7,001	03.33
303	FM-0057026	Riverside	Larson Justice Center	33-C1	2	right) with two new Liftmaster #SL585. Current units are obsolete and cannot be repaired.	\$	8,860	\$ 8,860	100
			Inglewood			HVAC - Remove and replace transducers to allow sensors. Chiller #1 & Chiller #2 has tripped off-line due to low				
304	FM-0057027	Los Angeles	Courthouse	19-F1	1	water flow which is leaving no cooling to the building.		\$8,652	\$6,451	74.56
						Roof - Restore Roof: Seal roof area with polyurethane chemlock to mitigate future rust, apply asphalt emulsion				
						and elastomeric coating. The roof has several penetrations throughout the surface that are allowing leaks to				
			Santa Barbara			develop inside the building during storms/rain. Some areas of the roof are rusting. Remove all penetrations to				
305	FM-0057029	Santa Barbara	Juvenile Court	42-C1	2	restore roof, making the roof fully sustainable against leaks and damage.	\$	4,120	\$ 3,667	89
						Plumbing - Replaced failed hardware on toilet fixture. Remediate 600 sq ft wet floor dried & 200 sq ft sheetrock				
200	EN 4 0057000	A1	Hayward Hall of	04.54		dried & 200 sq ft of ceiling tile replaced & 100 sq ft sheetrock ceiling opened and lacerated &, 20 ft of		A= ===	A= =0.5	400.00
306	FM-0057030	Alameda	Justice	01-D1	1	baseboard replaced under ACM protocols. Vandalism Replace (1) broken window at holding cell 101A interview room with like for like replacement glass.		\$5,726	\$5,726	100.00
			Miloy M. Manual			Vandalism - Replace (1) broken window at holding cell 101A interview room with like for like replacement glass				
207	FM-0057031	Alameda	Wiley W. Manuel	∩1_ ₽2	2	32"x62" 1/2 thick clad poly. Work is to be coordinated with Marshall's office for access during normal court	ر	A 2E2	¢	100
307	1,141-002/031	Alameda	Courthouse	01-B3		hours.	٦	4,252	\$ 4,252	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - Judges chambers room 312 and 313 lack independent zone control and are excessively hot during the summer. Install (2) VAV boxes, (2) steam reheat coils, 40LF of 8" spiral duct, 80 LF of 10" spiral duct, (2) spiral				
308	FM-0057032	San Bernardino	San Bernardino Courthouse	36-A1	2	reducers, (6) 10" sheet metal elbows, 50 LF of fiberglass round duct, 50 LF of 1-1/2" black pipe, 50 LF of 1" black pipe, (2) steam traps, (2) 1-1/2" basket strainers, (2) thermometers, (2) pressure gauges, (2) independent thermostats, integrate with county owned Siemens BAS.	Ś	73,252	\$ 73,252	100.00
300	1101 0037032	San Bernarame	Courtinouse	30 711		Interior Finishes - Install (17) 10" x 10" x 9/16" forced entry resistant laminated glass and (32) 12" x 16" x 1"	7	73,232	73,232	100.00
			Clara Shortridge Foltz			forced entry resistant laminated glass. Lock up cell viewing windows for cells #1-9 on each the 1st, 4th, 8th,				
300	FM-0057033	Los Angeles	Criminal Justice Center	19-L1	2	10th, and 14th floors have are damaged, crack, or heavily etched obscuring vision into the cells and presenting a safety issue for deputies conducting checks.	ć	35,294	\$ 35,294	100
309	FIVI-0037033	LOS Affgeles	Inglewood	19-L1		HVAC - Replaced a defective 5 amp fuse in the MCC control panel. The MCC control panels for AHU 2, 3, 4, & 5	Ş	33,234	3 33,294	100
310	FM-0057034	Los Angeles	Courthouse	19-F1	1	are not allowing the VFD's to operate which is making the temperature in the building rise.		\$9,320	\$6,949	74.56
			Hayward Hall of			Vandalism - Window - Single pane exterior door side-light approximately (1.5' x 7') - Replace window glass				
311	FM-0057035	Alameda	Justice	01-D1	1	broken out by thrown rock.		\$3,500	\$3,091	88.30
						Exterior Shell - Vandalism - Broken exterior glass window. Replace (1) 34 /12 X 52 X 1/4 thick window next to		1	4	
312	FM-0057036	Los Angeles	Compton Courthouse	19-AG1	1	the main entrance of the building. Add graffiti film and tinting on new window.		\$7,562	\$5,001	66.13
313	FM-0057037	Los Angeles	Pomona Courthouse South	19-W1	1	Plumbing - Cold water valve to sink in lock up has failed and water is leaking into the 2nd floor DA's woman's restroom. Remediate damage The affected areas is approximately 7'X5' of plaster ceiling and the east wall approximately 7'X 8', 2x2 area re-plastering required. This work was conducted in a ACM environment. HVAC - Chiller #2 has leaks on the Solenoid valve and liquid valve. Install one (1) new liquid line solenoid valve		\$10,205	\$9,301	91.14
			Santa Barbara			with coil to replace leaking valve. Replace liquid line drier core and sight glass. Replace old time delay in control				
314	FM-0057038	Santa Barbara		42-B1	2	panel with a new solid state timer and replace oil pressure safety control.	\$	7,157	\$ 7,157	100
			Metropolitan			Fire Protection - Replace (7) 75' failed Fire Hoses. Replace (5) defective sprinkler heads in parking structure to				
315	FM-0057039	Los Angeles	Courthouse	19-T1	2	maintain compliance. Extract and replace (2) leaking nipples on the South FDC Manifold.	\$	7,382	\$ 6,979	94.54
						Exterior Shell - Removed damaged window glass and installed one (1) insulated 45in x 80in window glass into				
216	ENA 00E7041	l os Angolos	Van Nuys Courthouse		,	the existing aluminum frame. Ground Level, West Side Main Entrance a person threw a rock at the building	۲	2.042	c 2.172	90.49
310	FM-0057041	Los Angeles	West Inglewood Juvenile	19-AX2		causing a corner window to break/crack. Roof - Remove and replace approximately 11,600 SF of failing built up roof. New roof to be a SBS multi-ply roof,	Ş	3,943	\$ 3,173	80.48
317	FM-0057043	Los Angeles	Court	19-E1	2	to include new building metal, and install new roof drain caps.	Ś	280,307	\$ 226,432	80.78
317	1101 00370 13	Los / mgeres	San Fernando	13		Interior Finishes - Replace (6) panes of 71" x 52-1/4" x 1-1/8" thick laminated bronze tinted glass. Judges	Υ	200,307	220,132	33.73
318	FM-0057044	Los Angeles	Courthouse	19-AC1	2	Chambers for Dept. D, G, J, L, N, and I have been broken or damaged window glass.	\$	30,832	\$ 25,717	83.41
						HVAC - Cooling towers #1 and #2 media has significant calcium build up causing water to escape and puddle at				
						the towers base. Floats do not provide adequate make up water causing pump surge. Replace (72) counter flow				
			Michael D.			eliminators, (8) 63-1/4 W x 35-1/2 H louvers, (16)44-5/8 W x 35-1/2 H louvers, (4) 8" butterfly valves, (2) gear				
240	ENA 0057045	1 4 1	Antonovich Antelope			operated 3" butterfly drain valves, 101"Wx252"L Cooling tower media, (2) EZ Float Kits, (2) 4B154 power band	_ ا	02.222	6 50 745	74 44
319	FM-0057045	Los Angeles	Valley Courthouse Chatsworth	19-AZ1	2	belts, and (2) grease line kits. HVAC - Replace failing liquid filter, oil filter, and install 5/8" isolation valves, replace suction elbow gaskets on	>	82,230	\$ 58,745	71.44
320	FM-0057046	I os Angeles	Courthouse	19-AY1	2	Chiller #2. Unit showing high levels of moisture which will cause premature system failure.	¢	29,580	\$ 26,723	90.34
320	1 101-003/040	Iros Viigeies	Courtiouse	172-WIT		permiter #2. Offic showing high levels of moisture which will cause premature system failure.	۲	29,360	۷ (۲۰٫۷۷۵	30.34

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Interior Finishes - Remove and replace failing lathe & plaster ceiling system (18' x 28' = 504 SF). The plaster and				
					_	lath ceiling in the main communications room has begun to collapse in several areas. Falling debris could result				
321	FM-0057047	Los Angeles	Norwalk Courthouse	19-AK1	2	in serious damage to employees and electronics.	\$	25,417	\$ 21,612	85.03
			Ch a tasses and b			Plumbing -Replace two Nibco LD-200 4" butterfly main domestic water isolation valves, replace four 4" flange				
222	ENA 0057040		Chatsworth	10 41/1	2	gaskets, four 4" and four 6" coupling gaskets, four 4" gasket isolators and bolts. Main Isolation valves in the	۲ ا	4 2 4 4	ć 2.55 <i>4</i>	02.0
322	FM-0057048	Los Angeles	Courthouse	19-AY1	2	basement are not closing completely and will not isolate the water if a leak were to occur.	\$	4,241	\$ 3,554	83.8
			Control Arraignment			**COUNTY MANAGED** Security - Intrusion Alarm; Replace Onboard Battery, Motion Sensors & check				
222	ENA 00E7040	l os Angolos	Central Arraignment	10 111	2	programming of Alarm Panel for Clerk's office, Back staff corridor, Judges Entry Doors, Elevator Lobby, Training	۲	2 205	¢ 2.20F	100
323	FM-0057049	Los Angeles	Court	19-U1	Z	room & Elevator/Stairwell.	Ş	3,305	\$ 3,305	100
			Rancho Cucamonga			Elevators Escalators & Hoists Poplace failing hoist machine worm shaft scale on Secure Elevator to provent				
224	FM-0057050	San Bernardino	Courthouse	36-F1	2	Elevators, Escalators, & Hoists - Replace failing hoist machine worm shaft seals on Secure Elevator to prevent	۲	4.404	¢ 2.419	76.05
324	FIVI-0037030	San Bernarumo	Morgan Hill	20-L1	Z	future failure and stop leaking. Work prevents damage to the hoist machine gear box by addressing it promptly. HVAC - Replace (1 each) failed 350 amp main breaker to building chiller. Main breaker to chiller failed and is	Ş	4,494	\$ 3,418	76.05
225	FM-0057052	Santa Clara	Courthouse	43-N1	2	affecting the courts cooling capacity	ċ	4,665	\$ 4,665	100
323	1101-0037032	Santa Ciara	North County	43-111		arrecting the courts cooling capacity	7	4,003	۷ 4,005	100
			Regional Center -			Fire Protection - Fire Alarm Panel is showing ground fault, six Horns/Strobes have failed. Replace (6) Horns /				
326	FM-0057053	San Diego	Vista Center	37-F2	2	Strobes. Locate source of fault on panel as panel must be free of deficiencies.	\$	4,010	\$ 4,010	100
320	1101 0037033	Jan Biego	Van Nuys Courthouse			Vandalism - The holding cell door's window was broken by in-custody creating a safety hazard. Replace (1) 30	<u> </u>	1,010	γ 1,010	100
327	FM-0057054	Los Angeles	West	19-AX2	2	1/4" X 49 1/2" 1" safety laminated glass in customers steel frame with security screws.	Ś	4,403	\$ 4,403	100
5			11001			Elevators - Rewire the oil heaters for the elevator #3 and #4 oil tanks to code. Wire to step-down transformer	7	.,	γ .,	
			Criminal Court			from the 480v disconnect so when the disconnect is turned off power to the heaters turns off as well Existing				
328	FM-0057056	Napa	Building	28-A1	2	oil heaters wiring does not conform to code	\$	7,092	\$ 7,092	100
329	FM-0057057	Los Angeles	Pasadena Courthouse	19-J1	1	Electrical - Replace 25 burnt out lights/ballasts in sally port bay and lock-up ramp with LED lighting, replace light covers that are deteriorated and can be used as a weapon by an inmate creating a safety situation.		\$17,265	\$11,973	69.35
		<u> </u>				Plumbing - Replace (4) non-mercury float switches, (2) 4" epoxy coated resilient disc check valves, and (2) 5HP		. ,	. ,	
						4" discharge sewage pumps with Tsurumi 5 HP cutter type sewage pumps. Existing 5 HP sewage ejector pumps				
			Bellflower			are damaged due to inmate generated debris in the sewage systems resulting in flooding sewage back into the				
330	FM-0057059	Los Angeles	Courthouse	19-AL1	2	building.	\$	41,305	\$ 32,193	77.94
		_				HVAC - 3rd Floor Ceiling - Remove 100 If of broken and separated fiberglass duct work in the 3rd floor public		·	•	
			Central Justice			hallway and court reporter/interpreter services space and replace with new sheet metal ducting and insulation				
331	FM-0057060	Orange	Center	30-A1	2	per ACM protocols. The duct work currently is noisy and inefficiently distributing air.	\$	25,500	\$ 23,248	91.17
			North County							
			Regional Center -			COUNTY MANAGED - Plumbing. Replace one Hot Water Holding Tank and two Expansion tanks that have failed				
332	FM-0057068	San Diego	South	37-F1	2	due to leaks that are beyond repair	\$	3,920	\$ 3,920	100
			Chatsworth			HVAC - Remove failing i2920 controller for AHU # 4 and install new i2920 controller for AHU #4 controller.				
333	FM-0057069	Los Angeles	Courthouse	19-AY1	2	Controller is failing, this will effect cooling for the entire section of building at the North East side.	\$	5,071	\$ 4,249	83.8
334	FM-0057070	San Francisco	Polk St. Annex	38-A2	2	Vandalism - Graffiti - Apply blackout film over existing at street level windows (20) - Glass etched with graffiti	\$	3,901	\$ 3,901	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
335	FM-0057071	San Diego	County Courthouse	37-A1	2	Plumbing - Install new copper piping between gate valves at the regulator station and 5 of the regulators. Replace 2" gate valves with ball valves in 12 locations. Install 12 gauges with quarter turn ball valves before & after regulators. Install a new copper union on the vertical. South basement Pressure Regulating Valves at Manifold are leaking onto the floor and not properly reducing the city water pressure. Over pressurization creates risk of piping failures.	Ś	13,821	\$ 10,700	77.42
		San Diego	County Courthouse	37-A1	1	Elevators, Escalators, & Hoists - Faulty drive was removed and replaced on public elevator 4B. Replace additional failed hardware including one (1) new CPU board and one (1) new Miprom 21 Relay Pilot board.	Υ	\$34,963		77.42
337	FM-0057073	Mendocino	County Courthouse	23-A1	2	Interior Finished - Replace Courtroom Door and hardware - Replace door in courtroom H damaged by in custody, new door to be finished to match existing and add hardware, auto flush bolt, closure.	Ś	4,652	\$ 4,652	100
	FM-0057074	Los Angeles	Compton Courthouse		2	HVAC - Install (2) 3/4" Black Steel coupon racks, 60LF 3/4" copper pipe assembly, (8) 3/4" ball valves, (2) 3/4" PVC coupon racks, install 60LF 3/4" PV. Installation is required in order to monitor system acid content in the HVAC water system. Parking Lot - Remove 275 sf of curb, gutter, and side walk to replace with a commercial driveway. Apply one	\$	21,893		66.13
339	FM-0057075	Yolo	Traffic Court - Modular	57-A8	2	coat of OverKote asphalt sealer to approximately 4600 sf of asphalt concrete. Restripe parking lot to original layout with one ADA stall and ADA signage. Install 14 concrete wheel work required in order to comply with turn-back conditions of the lease.	\$	47,123	\$ 47,123	100
340	FM-0057076	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing - Replace 30' of 4" & 20' of 2" failed black cast iron drain piping and fittings. 25' scaffolding required to address work location. Remediation of 5,76SF ACM water damage. Impacted area includes 2nd Flr Cafeteria to Public Lobby, RM-100 Traffic Court Clerks, RM-101 Small Office, Basement Employee Hallway & B-8 file rm. HVAC - Replace failed 40HP Supply Fan motor. AHU #12 Supply Fan has seized effecting air supply to the 12th		\$50,650	\$33,495	66.13
341	FM-0057082	Los Angeles	Compton Courthouse	19-AG1	1	floor.		\$10,116	\$6,690	66.13
342	FM-0057083	San Mateo	Hall of Justice	41-A1	2	Security - Install door closer at Courtroom 2M door to secure hallway - Original door closer was removed prior to transfer allowing Courtroom occupants access to secure areas; identified by SO security assessment.	\$	1,000	\$ 1,000	100
343	FM-0057084	Los Angeles	Norwalk Courthouse Hayward Hall of	19-AK1	1	Plumbing - Replace failed flush assembly in holding area which is concealed behind wall. Remediation required in 3rd flr Room 309. ACM and remediation include 8'x8' section of carpet and (6) 12"x12" ceiling tiles.		\$12,280	\$10,442	85.03
344	FM-0057085	Alameda	Justice	01-D1	2	Vandalism - Phones - Replace six holding cell interview phones damaged by inmates	\$	2,457	\$ 2,457	100
345	FM-0057086	San Diego	North County Regional Center - South Gordon Schaber	37-F1	2	COUNTY MANAGED - plumbing. Replace 6" water pressure reducing valve. Site is experiencing water pressure spikes due to existing valve being inoperable.	\$	5,232	\$ 5,232	100
346	FM-0057088	Sacramento	Sacramento Superior Court	34-A1	2	Vandalism - East Front entrance glass door is broken due to vandalism. Replace (1) 46 3/8 x 106 9/16 - 3/8" clear tempered glass with flat polish and add tinting to glass and repair broken door handle. HVAC - Daikin Heat Pump - Remove and replace failed PCB inverter circuit board (1) and condenser fan	\$	2,560	\$ 2,560	100
347	FM-0057089	San Francisco	Youth Guidance Center	38-C1	2	blades(2) and motors(2). Unit servers Department 3, Judges Chambers and reporters office. There is currently no cooling in these areas and supply air temps are at 77 in the afternoons.	\$	8,888	\$ 8,888	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			New San Bernardino							
348 F	M-0057090	San Bernardino	Courthouse	36-R1	1	HVAC - Replace 2 failed refrigerant monitoring probes. Work is code required.		\$9,830	\$9,830	100.00
			New Hollister			Vandalism - Exterior shell - Replace 1 each Broken Bullet resistant glass pane in room 269 utilizing a boom lift -		. ,	,	
349 F	-M-0057093	San Benito	Courthouse	35-C1	2	Bullet resistant glass is compromised and requires replacement.	\$	9,854	\$ 9,854	100
350 F	FM-0057101	Los Angeles	Compton Courthouse	19-AG1	1	Interior Finishes - Replace existing 30YD, 30yr old and failed Trash compactor. New system to include Hopper Open w/side modification flare, 42"x72" Safety Railing w/mounted dock, Guide island w/stops; Work is required to maintain current garbage removal process. No alternate location available for change to current process and workflow.		\$42,465	\$28,082	66.13
351 F	FM-0057102	Los Angeles	Central Arraignment Court	19-U1	1	COUNTY MANAGED - Fire Protection - Replace defective board on main Fire Alarm Panel, program the device points into the new panel, change power supplies & EOL resisters. Replace two failed Enunciators.		\$14,744	\$14,744	100.00
352 F	-M-0057103	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	Elevators, Escalators, & Hoists - Replace failed rope gripper pads on Elevator #5. Elevator is currently locked out due excessively worn rope gripper pads.	Ś	14,606	\$ 14,606	100
353 F	FM-0057104	San Bernardino	San Bernardino Courthouse	36-A1	2	Security - The gate barrier arm operator for the entrance/exit to the Judges' secured parking lot has failed. Replace failed 1/2 HP gate barrier arm operator with (1) new 1/2 HP gate barrier arm operator with 12' arm and (1) loop detectors. This work is required in order to ensure that the Judges' parking lot remains secure.	\$	3,106	\$ 3,106	100
354 F	FM-0057105	Sacramento	Gordon Schaber Sacramento Superior Court	34-A1	2	HVAC - Replace 2 failed HVAC control valves at Basement South. (1) 5" cold water valve, and (1) 3" hot water valve.	\$		\$ 6,721	100
355 F	FM-0057106	San Diego	Juvenile Court	37-E1	2	Interior Finishes - Replace 8 ft 6in x 7ft 6in size sheet vinyl flooring and 4 in base material in 2 restrooms. The linoleum flooring is damaged and needs to be replaced. Flooring is cracked and pieces of linoleum are coming off, creating possible trip hazards.	\$	3,368	\$ 2,513	74.62
356 F	FM-0057108	Los Angeles	Inglewood Juvenile Court	19-E1	2	Grounds - Perform corrosion control on the flag pole, replace the upper/lower pulleys, cable, and padlock. The flag pole in the front of the courthouse is rusted and has flaking paint. The rope pulleys are rusted and the cable to raise the flag is worn down due to age.	\$	4,250	\$ 3,433	80.78
357 F	FM-0057109	Contra Costa	George D. Carroll Courthouse	07-F1	2	Electrical - Replace one (1) failing 15 Amp breaker and install an upgraded 20 Amp breaker to replace 2nd failing 15 Amp breaker. Install 200 feet of wire and 40 feet of conduit. Existing electrical service is not sufficient and system trips when both pumps kick in.	\$	4,106	\$ 3,079	74.99
358 F	FM-0057110	Lassen	New Susanville Courthouse	18-C1	2	Exterior Shell – Remediate water intrusion by removing soil from adjacent planters and back fill with drain rock and install weather sealing on four faulty windows. Water Intrusion into the structure, presenting in the Sierra Room damaging wall and floor finishes.	\$	5,000	\$ 5,000	100
350 1	FM-0057111	Humboldt	Humboldt County Courthouse (Eureka)	12-A1	2	HVAC - Remove and replace motors on AHU 1 & 2 supply fan units. The motor bearings in AHU 2 are worn out and failure is imminent, causing a disruption to court. The supply fan motor on AHU 1 should also be replaced as it is the same age and it is anticipated that the unit will start to fail in the same way.	Ś	4,556	\$ 4,556	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE		FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Interior finishes - Install One (1) new 1/2 HP 115V Gear Head Motor Operator with three (3) button control				
			East County Regional			station, using heavy duty brackets. Run wire and conduit up to 5' electrical connection to the existing dedicated				
360	FM-0057112	San Diego	Center	37-I1	2	power supply. Loading Dock Gate # 4 the motor is inoperable and needs to be replaced.	\$	3,659	\$ 3,659	100
						HVAC - Remove and replace return fan, bearings, and shaft to HVAC system. The return fan is damaged and is				
			Butte County			out of balance. If continued operation without repairs, return fan will vibrate apart and cause collateral damage				
361	FM-0057113	Butte	Courthouse	04-A1	2	to interior of HVAC system.	\$	5,337	\$ 5,337	100
						Plumbing - Replace 3" & 1" corroded high pressure Gate Valves and Fittings that serve the domestic cold water				
						in the South Tower. The deteriorated valves are leaking water and currently at risk of failing while under high				
362	FM-0057114	San Diego	County Courthouse	37-A1	2	pressure. Repairs are needed to avoid potential risk of flooding.	\$	3,178		77.42
							\$	21,492,723	\$ 18,123,570	

ITEM #	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	CFR DESCRIPTION	CFR TERM	FUND SOURCE	ESTIMATED CURRENT YEAR COSTS	es existing costs prior	ESTIMATED BUDGET YEAR COSTS		TOTAL ESTIMATED CFR COMMITMENT (CFR Term)	REVIEW NOTES - OREFM, JBCPO, & FSO
						Minor renovations to convert first floor courtroom into Self-Help Center and								
						secure non-public space from the new public space. Currently, the Self-Help								ļ., l
	04 650007	A la a al a	04 54	1	Facility	space is located in the lobby of this building impacting court flow and function,	O Ti	TOTE	۸ ـ	20.000	,	_ ا	20.000	No
	01-CFR007	Alameda	01-D1	Justice	Modification		One-Time	ICIF	\$	20,000	\$ -	\$	20,000	Concerns
				Fraces County	Fo cility	Modify one trial courtroom to handle Dependency cases, which requires more								No
٦	10 CED012		10 11	1	Facility	space for court participants in the well, the removal of the jury box, and	One Time	TCTE	۲ ح	22.696	خ		22 696	No
	10-CFR013	Fresno	10-A1	Courthouse	Modification		One-Time	ICIF	\$	22,686	\$ -	 	22,686	Concerns
						Transfer of County Law Library to Court with tenant improvements for use as a								
				Humbaldt Caunty	Fo cility	courtroom to hold cases requiring security. This will require an amendment to the								
1	12 CEDO01	Uumbaldt	12 11	Humboldt County	•	JOA to begin January 1, 2016 as well as an additional fee for the Court's facilities	One Vear	тстг	۲	4 700	ċ	ے ا	24.460	Donding
3	12-CFR001	пиньони	12-A1	Courthouse	Modification	service provider to maintain the space. FM for interior improvements to the existing snack bar to meet and be in	One Year	ICIF	Ş	4,709	γ -	7	24,460	Pending
						compliance with Dept. of Public Health Inspection Report requirements. Until								
						facilities are in compliance the vendor is not allowed to be in full operation,								
				Inglewood	Facility	thereby creating an urgent need to be able to provide food/beverage services to								
4	19-CFR032	Los Angeles	19-F1	Courthouse	Modification		One Time	TCTF	\$	17,827	\$ 17,82	7 5	17.827	Pending
+	15 6111032	LOS / trigeres	13 1 1	Courtifouse	Ivioameation	FM to install exterior power outlets (and related electrical work/dedicated circuit)		1011	7	17,027	7 17,02	, , , , , , , , , , , , , , , , , , , 	17,027	renamb
						to accommodate the installation of Automated Bill Payment kiosks. The kiosks								
						will reduce congestion as well as provide easier access by allowing traffic citations								
			19-T1 &	Metropolitan &	Facility	and criminal payments to be paid outside of the courthouses. These will also								
5	19-CFR033	Los Angeles		·	Modification		One Time	TCTF	\$	60,000	\$ 60,00	0 \$	60,000	Pending
				,		FM for interior improvements to the existing cafeteria to meet and be in			<u>'</u>	· ·	,	<u> </u>	<u> </u>	
						compliance with Dept. of Public Health Inspection Report requirements. Until								
						facilities are in compliance the vendor is not allowed to be in full operation,								
				Torrance	Facility	thereby creating an urgent need to be able to provide food/beverage services to								
6	19-CFR034	Los Angeles	19-C1	Courthouse	Modification	court users and staff.	One Time	TCTF	\$	25,000	\$ 25,00	0 \$	25,000	Pending
						Comprehensive retrocommissioning assessment on the HVAC system. This FM is								
				Central Justice	Facility	an effort to identify and address issues prior to them becoming P1 events that								
7	30-CFR023	Orange	30-A1	Center	Modification	would be detrimental to court operations.	One-Time	Non-TCTF	\$	80,694	\$ -	\$	80,694	Pending
						Phase 1: Design - Modifications to the building's main entry to accommodate new								
						turnstile security equipment and refresh the appearance of the lobby.								
		San		Joshua Tree	Facility	The detailed execution scope of work will be developed by the JCC and approved								No
8	36-CFR032	Bernardino	36-E1	Courthouse	Modification		One-Time	Non-TCTF	\$	19,300	\$ -	\$	19,300	Concerns
						Renew parking lease for 175 overflow parking spaces (March 1, 2016 through								
						February 28, 2019). There is a current shortfall of parking at the courthouse and								
				East County		the lease renewal with MDA El Cajon One, LLC would allow court users and jurors	 							
				Regional Center	Lease	to park at the adjacent shopping center, thereby reducing delays in court	Three			_	_].		
9	37-CFR021	San Diego	37-16	Overflow Parking	Extension	proceedings.	Years	ı CTF	\$	84,982	\$ 87,96	2 \$	270,092	Pending

ITEM #	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	CFR DESCRIPTION	CFR TERM	FUND SOURCE	STIMANTED CLIBBENIT VEAB COSTS	ALED CURRENT YEAR C es existing costs prior t	ESTIMATED BUDGET YEAR COSTS	TOTAL ESTIMATED CFR COMMITMENT (CFR Term)	REVIEW NOTES - OREFM, JBCPO, & FSO
				Civic Center		Convert the current rule 10.810 MOU into a rule 10.810/Small Project MOU and							
		San	38-A1 &	Courthouse & Hall		designate an annual budget of \$120,000 for small projects for the Civic Center							No
10	38-CFR005	Francisco	38-B1	of Justice	Annual Budget	Courthouse and Hall of Justice.	Ongoing	TCTF	\$	-	\$ -	\$ 120,000	Concerns
				64 N. Market									
				Street (LAZ	Lease	Two-year lease extension to provide parking privileges for Superior Court	Two						
11	43-CFR008	Santa Clara	43-B6	Parking)	Extension	employees and jurors (approx. 1,300 SF of spaces). (1/1/16 - 12/31/17)	Years	TCTF	\$	50,884	\$ 50,884	\$ 101,76	8 Pending
12	54-CFR011	Tulare	54-J1	Visalia Convention Center		Two-year lease for rental of a conference room at the Visalia Convention Center to hold Small Claims Court on Mondays. (1/4/16 - 12/18/17)	Two Years	TCTF	\$	4,526	\$ 4,526	\$ 18,10	95 Pending



Action Item 9 – Fiscal Year-End Process for Court-Funded Facilities Requests

Summary:

Review and discussion of FY 15-16 CFR processing deadlines and overview of how the program has progressed this year.

Supporting Documentation:

- Slides
- Deadline memo sent to Courts

Action Requested:


Staff recommends approving the recommended year-end CFR deadline of March 14, 2016.

Action Item 9 Fiscal Year-End CFR Process

- Official Notice December 30, 2015
- Final Submittals March 14, 2016
- Final Approval Meeting April 4, 2016

CFR Program – FM Growth





Completed Court-Funded Requests



Chatsworth (19-AY1) 19-CFR014: Install tempered glass & telecoms at 16 workstations - \$61,613

Fresno Main (10-A1)10-CFR006: Install 225cameras - \$292,076





Completed Court-Funded Requests

 Fresno Main (10-A1) 10-CFR011: Modify Jury Clerks office public counter- \$15,575





San Diego HOJ (37-A2) 37-CFR020:
 Reconfigure 2nd floor
 for Small Claims
 Office - \$21,776

Action Item 9 Fiscal Year-End CFR Process

- The Good
 - · Great partnership with court stakeholders
 - 182 projects/ \$4.5M physically completed
 - 30 projects/ 11.5M are active today
 - Execution with minimal impact to court operations

22

Action Item 9 Fiscal Year-End CFR Process

- The Good
 - Streamlined Intra-Branch Agreements, Cost/Scope changes, Contract Encumbrances
 - 100% of all CFR in work prior to year end.
 - Improved Internal/External Communication

23

Action Item 9 Fiscal Year-End CFR Process

- Challenges
 - Continued lack of long range planning.
 - Lack of initial detailed scope impacts execution.
 - Project tasking capped at \$2.5M.
 - JCC Staff resources
 - Contracting Resources/Strategies

74

Action Item 9 Fiscal Year-End CFR Process

- Challenges
 - Customer Expectations/Project Duration
 - Movement of funding between task orders
 - Reversion of funding and impact to court budgets

25



JUDICIAL COUNCIL OF CALIFORNIA

2860 Gateway Oaks Drive, Suite 400 • Sacramento, California 95833-4336 Telephone 916-263-7885 • Fax 916-263-1966 • TDD 415-865-4272

MEMORANDUM

Date

December 30, 2015

To

Presiding Judges and Court Executive Officers of the Superior Courts

From

Patrick McGrath, Facilities Operations Manager, Judicial Council Real Estate and Facilities Management

Subject

Deadline for FY 2015-2016 Court-Funded Facilities Requests

Action Requested

For Your Information

Deadline

March 14, 2016

Contact

Patrick McGrath, Facilities Operations Manager 916-643-8051 patrick.mcgrath@jud.ca.gov

The Trial Court Facility Modification Advisory Committee (TCFMAC) has directed staff to inform you of the anticipated cutoff date for all Court-Funded Facilities Requests (CFRs) that are to be encumbered before the end of the fiscal year. Real Estate and Facilities Management staff recommends that the cutoff be **March 14**, **2016** in order to ensure adequate time is available to process all requests and complete all necessary legal and financial documentation. We expect the TCFMAC will confirm this cutoff at its next meeting in two weeks.

We have closely reviewed the steps necessary to fully execute the CFRs to ensure that the latest possible cutoff date is established. We also recognize that some courts may want to use available one-time funds for these projects and be certain that once projects are submitted to the Judicial Council, staff is capable of fully encumbering courts' funds before the end of the fiscal year. Over the last two years, and despite ongoing JCC staffing limitations, all CFR projects submitted by the courts to date have been processed and funding secured prior to fiscal year end. However, should a significant surge in CFR submittals, funding, or project complexity be received staff

may need to reach out to courts in order to prioritize their joint efforts to secure the funding for those projects most critical to the courts.

In FY 13-14, we confirmed with the California Department of Finance (DOF) that encumbering funds through the CFR process is permitted for the purposes of excluding those funds from the statutory 1% carry-over cap in Government Code 77203.

Additionally, the Judicial Council of California will be unable to execute any additional FY 2015-2016 CFRs requesting the Council execute work that is court allowable work under Rule of Court 10.810 (for example, flooring replacement or painting). Courts that find themselves in a situation where they can fund such repairs using their own general funds can contract directly for this type of work. Real Estate and Facility Management staff can assist with the development of specifications for these types of projects.

CFRs that do not need to be executed prior to June 30, 2016 will continue to be accepted and routed through the established process. Please contact me with any questions regarding this deadline or specific projects.

PM/hi

cc: Hon. Donald Cole Byrd, Chair, Trial Court Facility Modification Advisory Committee Martin Hoshino, Administrative Director
Jody Patel, Chief of Staff
Curt Soderlund, Chief Administrative Officer
Mark Dusman, Acting Chief Administrative Officer
Gerald Pfab, Senior Manager, Real Estate and Facilities Management
Angela Guzman, Financial Manager, Judicial Branch Capital Programs
Eunice Calvert-Banks, Manager, Real Estate and Facilities Management



Discussion Item 1

Summary:

Update on water conservation policy implementation efforts.

Supporting Documentation:

• Slide

Discussion Item 1 Update: Water Conservation Projects

- Judicial Council Adopted Water Policy June 2015.
- Over 30 water audits have been completed since adoption of the policy.
- Water audits identify inefficient water fixtures, landscaping, etc.
- Water audits also identify available rebates.
- May be opportunity to leverage rebates.



Discussion Item 2

Summary:

Review and discuss List F – Funded Facility Modifications on Hold

Total Project – Count:	27
Total FM Budget Share:	\$13,177,876

Supporting Documentation:

• List F – Funded Facility Modifications on Hold

FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM SHARE OF COST	FACILITY MODIFICATION PROGRAM BUDGET % OF COST	SHARED COST APPROVED?	PM ASSIGNED?	OTHER HOLD REASON?	COMMENTS
1 FM-0054617	Kern	Bakersfield Superior Court	15-A1	2	Elevators, Escalators, & Hoists - Rebuild Elevator #1 & #2 Generator, Sheave Deflector and Bearing Replacement. Elevator #1 & #2 Generators failed having reached the end of their useful life and need to be dismantled and rebuilt. Deflector Sheaves having reached the end of their useful life and need to be replaced.	\$ 257,000	\$ 160,985	62.64%	No	Yes		
2 FM-0052988	Los Angeles	San Fernando Courthouse	19-AC1	2	Roof - Remove and replace existing failing roofing systems on main deck, 2nd and 3rd floor Northeast decks as well as machine room roofs at the main roof (approximately 38,000) with a SBS roof System. Roof metal will be replaced as needed.	\$ 807,176	\$ 673,266	83.41%	Yes	No		
3 FM-0056911	Los Angeles	San Fernando Courthouse	19-AC1	2	HVAC -Corrections needed for Chiller #1 due to deficiencies found during Level VIII PM 2462651. Overhaul recommended to prevent downtime, damage and loss of comfort cooling to the courthouse. Purge all refrigerant and lube oil piping. Replace compressor journal bearings and high and low speed thrust bearings. Replace compressor shaft seal, PRV control shaft seals and motor bearings. Install refrigerant cleanup kit. Replace (2) condenser water rubber vibration eliminator joints.	\$ 223,294	\$ 186,250	83.41%	Yes	No		
4 FM-0019392	Los Angeles	Downey Courthouse	19-AM1	2	Electrical - Replace two (2) 3.15M BTU Boilers and one (1) 750Kw Generator. Replacement is required in order to comply with current AQMD standards.	\$ 796,699	\$ 666,837	83.70%	Yes	No		
5 FM-0053549	Los Angeles	Downey Courthouse	19-AM1	2	Roof - Remove and replace existing main deck, lower east deck and lower west deck (approximately 34,000 sf) with a SBS type roof system - Due to main and lower decks are past due and beginning to leak during rainy weather.	\$ 753,487	\$ 630,669	83.70%	Yes	No		
6 FM-0052970	Los Angeles	Whittier Courthouse	19-AO1	2	Roof / Remove and replace existing one story section of roof with new and overlay 5 story section of roof with torch applied system / Renovation required due to age and water penetration.	\$ 742,000	\$ 641,311	86.43%	Yes	No		
7 FM-0054101	Los Angeles	Santa Monica Courthouse	19-AP1	2	Roof - Remove and replace 53,000 sf of existing roof with new SBS roof system, currently the existing roof is in poor to fair condition at best, work will replace the roof at three building sections at various levels. New building metal and curbs will be replaced as needed.	\$ 1,114,341	\$ 874,646	78.49%	Yes	No		
8 FM-0056942	Los Angeles	Airport Courthouse	19-AU1		HVAC - Courtrooms are too hot. Dampers actuators for AHU#3 & 4 found to be faulty and 30 VAV boxes were not connected. Replace (3) damper actuators and (2) valve actuators for AHU 3 & 4. Reconnect wiring for 30 VAV boxes and recommission. Upgrade obsolete BAS software from Siemens Apogee Insight software from v3.10 to v3.13, install Remote Email Notification, install BAS Uninterrupted Power Supply, back up data for (9) Siemens controllers and replace (6) batteries for Siemens FLNC controller.	\$ 58,347	\$ 45,026	77.17%	Yes	No		

	1926 AI	JVISOKI	COMMITTEE										
	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM SHARE OF COST	FACILITY MODIFICATION PROGRAM BUDGET % OF COST	SHARED COST APPROVED?	PM ASSIGNED?	OTHER HOLD REASON?	COMMENTS
9	FM-0053004	Los Angeles	Van Nuys Courthouse West	19-AX2		Roof - Remove and replace existing failing roof with new SBS roof system - Work to include replacing approximately 25,000sf of failing built up roof, two roof drains, re-coat the Heli-Stop and replace building metal as needed.	\$ 585,070	\$ 470,864	80.48%	Yes	No		
10	FM-0057045	Los Angeles	Antonovich Courthouse	19-AZ1		HVAC - Cooling towers #1 and #2 media has significant calcium build up causing water to escape and puddle at the towers base. Floats do not provide adequate make up water causing pump surge. Replace (72) counter flow eliminators, (8) 63-1/4 W x 35-1/2 H louvers, (16)44-5/8 W x 35-1/2 H louvers, (4) 8" butterfly valves, (2) gear operated 3" butterfly drain valves, 101"Wx252"L Cooling tower media, (2) EZ Float Kits, (2) 4B154 power band belts, and (2) grease line kits.	\$ 82,230	\$ 58,745	71.44%	Yes	No		
11	FM-0053394	Los Angeles	Torrance Courthouse	19-C1		Roof - Remove and replace 40,000 square feet of the existing main deck and lower deck sections with new SBS roof system / Due to roof decks currently failing and leaking. Work to include new building metal, vent jacks and equipment curbs as needed.	\$ 845,633	\$ 719,972	85.14%	Yes	No		
12	FM-0057043	Los Angeles	Inglewood Justice Center	19-E1		Roof - Remove and replace approximately 11,600 SF of failing built up roof. New roof to be a SBS multi-ply roof, to include new building metal, clean all roof drains and supply and install new roof drain caps.	\$ 280,307	\$ 226,432	80.78%	Yes	No		
13	FM-0053030	Los Angeles	Glendale Courthouse	19-H1	2	Roof - Remove and replace existing roof with new SBS roof system - Work to include replacing approximately 34,000sf of failing built up roof, restore roof drains, install tapered insulation as needed and replace building metal if not re-usable.	\$ 757,338	\$ 685,694	90.54%	Yes	No		
14	FM-0041137	Los Angeles	Alhambra Courthouse	19-I1		Electrical - Replace one (1) 250Kw Generator. ACM abatement required. Replacement is required in order to comply with current AQMD standards.	\$ 448,388	\$ 385,614	86.00%	Yes	No		
15	FM-0052243	Los Angeles	Alhambra Courthouse	19-11		Energy Efficiency Project -19I1_02282013LV1 - Lighting and controls upgrade - Retrofit (1,533) F32T8 fluorescent fixtures with new 28-watt lamps and new ballast, (249) 3-lamp and 4-lamp fluorescent fixtures with new reflector, 28-watt lamps and new ballast, and (1) 2x2 fluorescent fixtures with new reflector, 17-watt lamps and new ballast. Install (2) Vending Miser sensors to control vending machines. Replace (32) Exterior HID fixtures on the with new lower wattage LED fixtures.	\$ 222,058	\$ 190,970	86.00%	Yes	No		
16	FM-0053003	Los Angeles	Alhambra Courthouse	19-I1		Roof - Remove and replace existing roof with new SBS roof system - Remove and replace approximately 31,800sf of failing built up roof system. Work will include new building metal, vents and walk pads as needed.	699,821	\$ 601,846	86.00%	Yes	No		

1926 A	DV100ICI	COMMITTEE										
FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM SHARE OF COST	FACILITY MODIFICATION PROGRAM BUDGET % OF COST	SHARED COST APPROVED?	PM ASSIGNED?	OTHER HOLD REASON?	COMMENTS
17 FM-0052129	Los Angeles	Foltz	19-L1	2	HVAC - Renovate the BAS - Convert the existing pneumatic controls to DDC, replace the front end control to the system, install VFD's on all AHU supply fans, Isolate and eliminate all leaks throughout the system, replace the worn bearings on AH 19-1 AHU fan, replace the failed return air sensor on AHU 1-9 and insulate the chilled and hot water piping at thirty-one (31) locations.	\$ 1,647,108	\$ 1,133,210	68.80%	Yes	No		
18 FM-0053002	Los Angeles	Monrovia Training Center	19-N1	2	Roof - Remove and replace existing roof system at eleven different areas (20,000 SF). Due to the poor condition of these areas, recommended removal and replacement of existing and building metal will bring entire building roof to good condition.	\$ 450,000	\$ 316,305	70.29%	Yes	No		
19 FM-0053460	Los Angeles	Edelman Children's Court	19-Q1		Roof - Remove and replace 43,000 sf of existing roof with new SBS roof system, currently the existing roof is in poor to fair condition at best, work will replace the roof at three building sections at various levels. New building metal and curbs will be replaced as needed. (No work to be done on the Heli - Stop).	\$ 946,000	\$ 662,105	69.99%	Yes	No		
20 FM-0056879	Los Angeles	Edelman Children's Court	19-Q1	2	Electrical - Existing 2000A Westinghouse ATS is beyond its life expectancy and requires replacement, parts are no longer available and lack of serviceability. Building power will be shut off for 12 hours while ATS is replaced. Demo existing 2000 A Westinghouse ATS and install 1 new GE Zenith ZTS series 2000A ATS with MX250 microprocessor controls and NEMA 1 cabinet. Install five 50 LF (250 LF) runs of 500 MCM cable for low side and 120 LF of 500 MCM cable for high side. Install 9 500 MCM lugs.	\$ 108,896	\$ 76,216	69.99%	Yes	No		
21 FM-0056972	Los Angeles	Metropolitan Courthouse	19-T1	2	Interior Finishes - Dept. 70 Cashier's Public stadium seating chairs are damaged, unrepairable and beyond their life expectancy. Seats need to be replaced as this is a safety issue for the public when trying to seat. Perform environmental testing and set up 30'W x 32' L x 8' H containment. Demo 101 existing damaged chairs, fill mounting holes and install 101 new American Seating Model 408 fiberglass seats and secure with epoxy.	\$ 78,669	\$ 74,374	94.54%	Yes	No		
22 FM-0052981	Los Angeles	East Los Angeles Courthouse	19-V1	2	Roof - Remove and replace existing failing roof system with new PVC roof system (30,625).	\$ 715,093	\$ 555,770	77.72%	Yes	No		
23 FM-0053554	Los Angeles	Pomona Courthouse South	19-W1		Roof - Remove and replace existing roof with new SBS roof system at main deck (23,220 sq. ft.), lower north deck (2,838 sq. ft.), and lower south deck (2,838 sq. ft.). Roofing metal will be replaced as needed.	\$ 682,895	\$ 622,391	91.14%	Yes	No		

	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	TCFMAC FUNDED COST	FACILITY MODIFICATION PROGRAM SHARE OF COST	FACILITY MODIFICATION PROGRAM BUDGET % OF COST	SHARED COST APPROVED?	PM ASSIGNED?	OTHER HOLD REASON?	COMMENTS
24	FM-0056883	Los Angeles	Pomona Courthouse South	19-W1	2	HVAC - Due to age/corrosion Cold & Hot Water Coils for 3rd, 6th and 7th flr Air Handler Units are leaking and need to be replaced. Leaking coils have caused deterioration of condensation pans and floor drains; both will be replaced. Spring Isolators on AHU-5 require replacement. Perform environmental testing, set up containments. Install 10 new 680lb Fail Safe Spring isolators. Replace 2 cold water coils, 1 hot water coils with custom made coils. Replace condensate drain pans with custom units.	\$ 379,957	\$ 346,293	91.14%	Yes	No		
25	FM-0031644	Santa Barbara	Santa Maria Courts Campus	42-F	2	(Phase 2) Site - Parking lot safety issues - Remove and replace existing campus parking lot areas where sink holes have developed, compaction around under ground pipes is failing and asphalt deterioration has created trip hazards. Recompact, Repave & Restripe to comply with ADA standards; Sinkhole/Surface Damage. Approximate area of renovation is 82,300 S.F. which includes general parking as well as secured parking areas.	\$ 422,600	\$ 313,400	74.16%	No	Yes		Shared Cost for design phase approved.
26	FM-0040733	Solano	Hall of Justice	48-A1	2	EXECUTION Construct 1,070 If of retaining wall, 525 If of earthen berms, 575 If of access ramps; install drainage pipe and 2 pumps to extract water trapped within the prevention area. \$1.7M was spent in 2005 for flood damage and \$146K was spent in FY 10/11 on flood prevention measures. Emergency exiting must be sealed during flood conditions.	\$ 1,211,241	\$ 882,026	72.82%	No	Yes		Shared Cost for design phase approved. Design effort is in work.
27	FM-0054960	Solano	Hall of Justice	48-A1	2	Roof - Replace roof. Phase II of existing/funded Phase I FM#50740.	1,341,198 16,656,846	976,660 13,177,876	72.82%	No	Yes		



Discussion Item 3

Summary:

Overview of facility modification progress to build arraignment court in Placer County, previously funded by the committee in January 2015.

Supporting Documentation:

- Slides
- Drawing

Discussion Item 3 Update: Placer Superior Court Project

FM-0044228 – Add Arraignment Court in new County Jail

Facility - Funded Jan. 2015 - \$2.9M



Address:

11801 Go For Broke Rd Roseville, CA 95678


Type:

Courthouse


Building SF:

South Building: 114,648 Courtroom Addition: 10.080 Total South Building: 124,728 space at the Placer South Jail.









Discussion Item 3 Update: Placer Superior Court Project

- Agreements drafted and in final review with Placer County
- Tentative schedule to be approved by Placer County Board of Supervisors in February 2016
- County confirms agreement of \$900,000 contribution for project, primarily holding area
- Construction to be completed December 2016
- County intends to move booking to new Jail in January 2017
- Court intends to start operations in New Arraignment court at the same time.



Discussion Item 4

Summary:

Overview of Seismic Study findings previously introduced to the committee in April 2015.

Supporting Documentation:

• Slides

TCFMAC Meeting Topic, 15 January 2016: Update of the 2002 – 2005 Seismic Study

EVALUATIONS OF COURT BUILDINGS FOR SEISMIC SAFETY RISKS, IN ACCORDANCE WITH THE TRIAL COURT FACILITIES ACT OF 2002

1926

Summary Report

Presentation Outline

- Summary of the Superior Courts of California, Seismic Assessment Program 2002-2005
- Description of Seismic Risk Levels Used
- Discussion of HAZUS Methodology
- Implementation of HAZUS Methodology by OSHPD and GSA
- Outline of Path Forward for JCC Using HAZUS Methodology to Update Seismic Ratings/Rankings
- Questions

- In accordance with the Trial Court Facilities Act of 2002 (SB 1732), all non-exempt California Court Buildings were evaluated for seismic safety risks 'using procedures developed by DGS'.
- A multi-step evaluation program was developed:
 - Initial screening workshop by experienced engineers,
 - Tier 1 Evaluation based on ASCE-31 methodology (including reviews of construction drawings and visits to the site),
 - Tier 2 Evaluation based on ASCE-31 methodology where warranted.

- Structures passing were assigned Risk Level IV (or Better)
- Structures failing were assigned Risk Level V (or Worse)
- All findings were peer reviewed to ensure consistency
- 225 Court Buildings (300 separate structures)
 representing approx. 20 million gsf were evaluated
 - 72 were assigned Risk Level IV or Better
 - 228 were assigned Risk Level V or Worse (note that 81 of these are technically listed as Pending due to a lack of information which was subsequently pursued).



Superior Courts of California Seismic Assessment Program



Superior Courts of California Seismic Assessment Program

. 193	26						1926	/	_					
County/						Building		% Court of						
,														
Bldg ID	Building Name		Building A	ddress	i	Gross Area	Court Area	Gross Area						
Alameda									Design Code Retrofit Date	ASCE 31 Bldg, Type		Other Work Rating Scope		
01-A1	Rene C. Davidson		1225 Fallo	n C+ (Oakland	284.120	114 . 6 17	40.3	Retrofft Date	Blag. Type	Level USA	Rating Scope		
			,		. , .	, -			S4	Tier 2	V C			
01-A2-ms	County Administrat	1221 Oak 9	St., Oak	land	208,146	36,126	17.4	100	Varies C2		IV, V CI			
01-A2-E	County Administration B	1221 Oak St	Oakland		196.850	-	-		S1A	Tior 2 Tier 2	IV CI			
01-A2-A	Vertical Addition	1221 Oak St.,	Oakland		11.296	_			\$1/\$4	Tier 2	V CI, G			
				Islam I			00.0	1973 UBC	S1 S4b	Tier 2 Screening	V G			
01-B1	County Probation C	400 BRd.way, Oakland			54,505	,	23.8		\$1	Tier 1	V G			
01-B3	Wiley W. Manuel Co	661 Washington St., Oakland			196,277	10 1,59 9	51.8	1955 UBC	C2	Tier 1	v -			
01-D1	Hayward Hall of Jus	tice	24405 Amador St., Hayward			184,785	110,534	59.8	1973 UBC	RM2	Tier 1	V C, G		
01-F1	George E. McDonal				r., Alameda	25,850	14,144	54.7		URM/C2A	Tier 1	V G		
				,	,	, , , , , ,			URM	Tier 1	VI C			
01-G1	Berkeley Courthous	е	2120 Mart	in Luth	er King, Jr. Way, Ber	14,900	5,523	37.1		Varies		IV, V		
0 1- H1	Fremont Hall of Jus	tice	39439 Paseo Padre Pkwy., Fremont			124,100	62,464	50.3	100	C2	Tier 1	IV -		
03-61-5	Amagor Phanita/Courtnouse	8 TO COURT SE., JACKSON	7.7				R2-01-1-1	1 1 1995	1982 UBC	G2 S1	Tier 1 Tier 2	V .		
Butte			2,000				03-B1-I	I 1950		C2	Tier 1	V		
	Butte County Courthouse Butte County Courthouse, Original	1 Court St., Oroville 1 Court St., Oroville	55,810 18.810	41,607	74.6		1							
	Downtown Courthouse, Original	1931 Arlin Rhine Dr., Oroville	5,177	3,546	68.5	County/	No.	Year	Design Code		ASCE 31	Evaluation		Other Work
04-C1 G	Gridley Courthouse	239 Sycamore, Gridley	4,679	1,983	42.4	Bldg ID	Stories	Complete	Retrofit Date		Bldg. Type	Level	DSA Rating	Scope
	Chico Courthouse Paradise Courthouse	655 Oleander Ave., Chico 747 Elliot Rd., Paradise	12,135 7,742	7,668 2,971	63.2 38.4	Alameda					5 71			
Calaveras	Paradise Courtilouse	747 Elliot No., Paradise	1,142	2,971	30.4									
	Legal Bidg.	891 Mountain Ranch Rd., San Andre	nas 18,488	6,259	33.9	0 1- A 1	13	1935			S4	Tier 2	V	С
Contra Costa 07-A2	Old Courthouse	725 Court St., Martinez	100,657	43,806	43.5	0 1- A 2 - ms	- 1	1961			Varies	Tier 2	IV, V	CI
	Bray Courts	1020 Ward St., Martinez	48,823	25,786	52.8	01-A2-E	5+B+PH	1961			C2	Tier 2	V	CI
	Jail Annex	10 10 Ward St., Martinez	12,843	7,805	60.8	01-A2-A		1982			S1A	Tier 2	IV	CI
	Danville District Courthouse Concord-Mt. Diablo District	640 Ygnacio, Walnut Creek 2970 Willow Pass Rd., Concord	37,104 8,509	26,199 6,702	70.6 78.8		1 '		-					
07-E1 P	Pittsburg-Delta	45 Civic Dr., Pittsburg	23,900	16,476	68.9	01-B1	4+B	1963	-		S1/S4	Tier 2	V	CI, G
07-F1 R	Richmond-Bay District	10 0 37th St., Richmond	76,462	37,047	48.5	01-B3	6+PH	1977	1973 UBC		S1	Tier 2	V	G
	Del Norte County Superior Court	450 'H' St., Crescent City	29,008	9,846	33.9	01-D1	5+B	1977			S4b	Screening	IV b	
El Dorado						01-F1	2	1985			S1	Tier 1	v	G
	Main St. Courthouse Superior Court	495 Main St., Placerville 3321 Cameron Park Dr., Cameron Pa	17,951 ark 7.834	11,662	65.0 72.7								•	G
	Johnson Bidg.	1354 Johnson Blvd., South Lake Tah		14,710	39.3	01-G1	2	19 58	1955 UBC		C2	Tier 1	V	-
Fresno						0 1- H1	3+PH	1976	1973 UBC		RM2	Tier 1	V	C, G
10 - A 1 F	Fresno County Courthouse. North Annex Jail	110 0 Van Ness Ave., Fresno 1255 M St. Fresno	213,687 25.667	110,430	51.7 43.2	Alnine								
10-C1 J	Juvenile Delinquency Court	742 South Tenth St., Fresno	18,180	9,394	51.7		10 - B 1	2+B 1985		C2c		IVb -		
10-F1 R	Reedley Court	815 G St., Reedly	6,208	3,621	58.3		10 - C 1 10 - F 1	2 1985 1 1965		W1A RM1	Screening Tier 1	IVb -		
	Orland Superior Court	821 E. South St., Orland	9,845	3,039	30.9		Glenn	1 1965		HM 1	Her 1			
Humb o It							11-B1	1 1965	1964 UBC	RM1	Tier 1	IV -		
12 - B 1 G	Garberville Courthouse	483 Conger St., Garberville	5,100	1,652	32.4		Humbolt 12-B1	1 1950		W1A	Screening	Vw -		
13 - A 1	Imperial County Courthouse	939 W. Main St., El Centro	66,000	26,782	40.6		Imperial				-0.00			
Inyo 14 - A 1	Independence Superior Court	168 N. Edwards St., Independence	22,683	5,153	22.7		13 - A 1	3+B 1923		C2	Tier 2	V C, CI		
Kern	mospendence superior court	-00 N. Edwards St., Independence	22,083	5,153	****		Inyo 14 - A 1	2+8 1922		C2	Tier 2	v c, g		
	Bakersfield Superior Court	1415 Truxtum Ave., Bakersfield	223,650	84,517	37.8		Kern							
	Bakersfield Superior Court, West Wing Bakersfield Superior Court, Central Wing	1415 Truxtum Ave., Bakersfield 1415 Truxtum Ave., Bakersfield	97,210 73,850		-		15- A 1- ms 15- A 1- A	- 1956 74B 1956		Varies S2/S4	Varies Tior 2	IV, V -		
15-A1-C B	Bakersfield Superior Court, Jury Services	1415 Truxtum Ave., Bakersfield	52,590				15-A 1-B	24B 1956		C2	Tier 2	IV .		
	Bakersfield Justice Bldg. Bakersfield Juvenile Center	12 15 Truxtun Ave., Bakersfield	125,783	55,956 22,359	44.5		15-A1-C	9+2B 1956		C2	Tier 1	IV -		
	Bakersfield Juvenile Center Delano/North Kern Court	2100 College Ave., Bakersfield 1122 Jefferson St., Delano	82,680 14,377	9,452	27.0 65.7		15-B1 15-C1	4+B 1980 4+B 1990		S4 S2/C2	Tier 2 Tier 2	V -		
15-E1 S	Shafter/Wasco Courts Bldg.	325 Central Valley Hwy., Shafter	16,836	12,887	76.5		15 - D 1	1 1985	1982 UBC	RM1	Tier 1	V CI, G		
	Taft Courts Bidg. East Kern Court-Lake isabella Branch	311 Lincoln St., Taft 7046 Lake Isabella Blvd., Lake Isabe	6,127 ell: 14.154	4,548	74.2		15-E1	1 1990	1985 UBC	RM 1/W2	Tier 1	IV -		
	East Kern Court-Lake Isabella Branch Arvin/ Lamont Branch	12022 Main St., Lamont	26,680	11,821	44.3		15-F1 15-G1	1 1984 1 1985	1979 UBC 1985 UBC	W1A RM1/W2	Screening Tier 1	V C,G		
15-I1 N	Mojave-Main Court Facility	1773 Hwy. 58, Mojave	12,112	3,141	25.9		15-H1	1 1988		RM1	Tier 2	ν		
	Mojave-County Administration Bldg. Bidgecrest-Main Facility	1775 Hwy. 58, Mojave 132 East Coso St., Ridgecrest	8,538 9,340	2,288	26.8 51.1		15-11 15-12	1 1974 1 1978	1970 UBC	RM1	Tier 1 Screening	V - Vw -		
			2,240	-,2			15-J1	1 1974	:	RM1	Tier 1	IV -		
Ne	ovember 2003 - Draft		Expanded Sur	nmary Ma	trix 50		Novem	ber 2003 - Draft			Es	panded Summary	Matrix	51
- 11			7									,		

III Building: Minor structural damage: repairable.

Moderate non-structural damage: extensive repair.

Risk to Life: Minor

Disruption of systems for days to months. Systems: Return within weeks, with minor disruptions. Occupancy:

IV Moderate structural damage: substantial repair. Building:

Substantial non-structural damage: extensive repair.

Risk to Life: Moderate

Disruption of systems for months to years. Systems: Partially to totally vacated during repairs. Occupancy:

V to VII Represent an "Unacceptable Seismic Safety Rating" Substantial structural damage: partial collapse likely: repair may not be cost effective. Risk Levels

Buildina:

Extensive non-structural damage: repair may not be cost effective.

Substantial. Risk to Life:

Total disruption of systems: repair may not be cost effective. Systems:

Totally vacated during repairs. Occupancy:

Extensive structural damage, partial to total collapse likely; repair may not be cost VI Building:

effective. Extensive non-structural damage: repair may not be cost effective.

Extensive, but not imminent. Extrication protracted and difficult. Risk to Life: Total disruption of systems: repair may not be cost effective. Systems:


Totally vacated during repairs (if repairable). Occupancy:

Unstable under existing vertical loads or earthquake. VII Building:

Imminent threat to occupants and/or adjacent property. Risk to Life: Total disruption of systems: most likely not repairable. Systems:

Should be vacated until structural upgrading is accomplished. Occupancy:

Superior Courts of California Seismic Assessment Program FEMA Building Performance Levels



Superior Courts of California Seismic Assessment Program

Level V buildings are not equally "dangerous"

- A building w/ an Unreinforced Masonry Bearing Wall (URM) system poses a higher risk compared to similar size building at same location with a Steel Moment Frame (SMF) system.
- A Pre-Northridge SMF building in Santa Rosa (high seismicity) has a higher risk compared to the same building in San Diego (lower seismicity).

- Starting in the 1970's, several communities performed seismic loss studies for emergency planning (and other reasons). Many different approaches were taken.
- FEMA wanted to develop a nationally applicable, consistent and more efficient method to conduct these studies.
- In the 1990's, the National Institute of Building Sciences was commissioned to develop such a method.
- An executive board was assembled to direct the development of this method, and they engaged consultants to support this effort.
- HAZUS (seismic) was launched in 1997. Flood & hurricane were added 2002-2005; AEBM (building-specific calculation of probability of collapse) was added in 2003.





Figure 2.4. Example Intersection of Demand Spectra and Building Capacity Curves

- Define EQ Demand (red).
- •Overlay EQ Demand over a "pushover curve" (black); the intersection gives a solution for structural displacement and acceleration.
- Structural displacement (drift) can be used to estimate structural damage using "fragility curves" (included within HAZUS program).

Drift is imposed on fragility curves to estimate structural damage



HAZUS program includes tables of fragilities for structural and nonstructural damage for each FEMA Model Building Type

Implementation of HAZUS AEBM by OSHPD (Prioritization of SPC-1 Buildings)

Implementation of HAZUS AEBM by OSHPD

- Following the Northridge EQ, CA passed SB 1953 requiring all CA hospitals to meet new code requirements by 2030. Intermediate deadlines were also set.
- Many hospitals, particularly in the central valley (low seismicity), were missing deadlines.
- OSHPD wanted a relatively simple, consistent, and credible method to measure risk to justify a logical extension of deadlines.
 - Determine Probability of Collapse (POC) as a measure of risk to Life-Safety (to determine hospital retrofit priorities);
 - HAZUS was a national "standard" (for loss estimation);
 - ASCE 31 evaluations were available for each building;
 - Transfer functions (tables) were needed to interpret ASCE 31 results to create HAZUS "pushover" characterizations.

Implementation of HAZUS AEBM by OSHPD

"Reduction" parameters based on deficiencies from ASCE 31

Categories of HAZUS parameters

Selected ASCE 31 deficiencies

	TA	BLE A6-	1—SIGNIFI	CANT ST	RUCTURAL	DEFIC	IENCY MA	TRIX				
	CAPAC	ITY	RESPO	NSE	STRUCT	COLLA	PSE					
	Over-Stre	ength	Durat	ion	Fra	gility Cu	rve Median ⁴		Fragility Curve			
SIGNIFICANT STRUCTURAL DEFICIENCY/CONDITION ¹	Gamma and Lambda Factors		Degradation (Kappa) Factor		Maximum Story Drift Ratio (Δ_c)		Mode Shape (Alpha 3) Factor		Variability - Beta Factor (β _c)		Collapse Facto (P[COL STR ₅]	
DEFICIENCE//CONDITION	SubBase	USB	SubBase	USB ⁵	SubBase	USB	SubBase	USB ⁶	SubBase	USB ⁵	SubBase	USB ⁶
Age (Pre-1933 buildings)	X	X ⁷										
Materials Testing (None)	X								X			
No Redundancy									X		X	X^6
Weak Story Irregularity					X		X	X ⁶			X	X ⁶
Soft Story Irregularity					X		X	X ⁶			X	X^6
Mass Irregularity					X							
Vertical Descontinuity	X				X							
Torsional Irregularity						X					X	X ⁶
Deflection Incompatibility ²					X				X		X	X ⁶
Short Column ³	X					X						
Wood Deterioration		X	X									
Steel Deterioration		X	X									
Concrete Deterioration		X	X									
Weak Column-Steel	X				X							
Weak Column-Concrete	X		X		X							
No Cripple Wall Bracing	_				X		Х	X ⁶			X	X ⁶
Topping Slab	X		X						X		X	X ⁶
Inadequate Wall Anchorage/Parapet Bracing		Х							Х			
Load Path/Diaphragm Openings									X		X	X^6
URM Wall Thickness Ratio											X	X^6

Implementation of HAZUS AEBM by OSHPD

- Structural Engineer reviewed an existing ASCE 31 evaluation and extracted data required for HAZUS analysis. The report was submitted to OSHPD.
- For consistency and credibility, OSHPD ran the "official" calculation to determine Probability of Collapse (POC).
- OSHPD ran 40 buildings that had been approved for an intermediate deadline and calculated their POC.
 - The highest POC in this set was used as a cut-off to justify the delay of retrofit (1.2%).
- Note that the POC should not be taken as an absolute value; it is useful as a relative means of comparison.

GSA Seismic Rating System

(HAZUS Methodology w/ OSHPD Modifications)

- In 1994, President Clinton signed Executive Order 12941, which lead to the creation of the Interagency Committee on Seismic safety in Construction (ICSSC).
- The ICSSC committee developed the Standard for Seismic Safety for Existing Federally Owned and Leased Buildings, currently ICSSC Recommended Practices 8 (RP8).
- RP8 references industry standard ASCE 31-03 for evaluation and ASCE 41-06 or seismic upgrading.
- All Government-owned buildings in GSA's inventory in high seismic areas and most in moderate seismic areas have been evaluated to RP8 or earlier versions of this Standard.

- As a result, most buildings in the GSA inventory have ASCE-31 (or 80% UBC force level) evaluations on file.
- These evaluations establish whether a building meets the desired standard or not; they do not address the level of risk for buildings not meeting the standard.
- GSA needed to develop a systematic methodology for assessing the seismic performance of individual buildings within their inventory and then rank them based upon this expected performance.

R+C was recently selected to perform the following tasks:

- Develop a seismic rating system that utilizes existing seismic evaluations.
 - The rating must be defensible and can be based on the 2013 California Administrative Code, Title 24, Part 1, Chapter 6, Section 1.8 Collapse Probability Assessment (OSHPD's Adaptation of HAZUS Methodology).
- Develop a database which includes a relative ranking of individual buildings.
- A key objective of this ranking is to prioritize retrofit funding.


SEISMIC R	ISK CALCULATOR		
INPUT			
Site Seism	icity		
BSE2E-S _{DS}		0.188	g
BSE2E-S _{D1}		0.073	g
Long Perio	od Transition period (T _L)	6	s
Minimum	distance to fault	279.8	km
Maximum	magnitude	6.63	
Building H	eight	0	ft
Stories Ab	ove Base	16	
Design Ye	ar	1965	
State		NJ	
UBC Seism	nic Zone	2A	
Building T	уре	S1	
Cs		0	
T _e		0	
seismic de	esign level	0	
Significant	t Structural Deficiency or (Condition	
Age (Pre-1	1933 buildings)		FALSE
No Redun	•		FALSE
Weak Stor	y Irregularity		FALSE
Soft Story	Irregularity		FALSE
Mass Irreg			FALSE
Vertical D	iscontinuity		FALSE
Torsional	Irregularity		FALSE
Deflection	n Incompatibility		FALSE
Short Colu	ımn		FALSE
Wood Det	erioration		FALSE
Steel Dete	erioration		FALSE
Concrete I	Deterioration		FALSE
Weak Colu	ımn - Steel		FALSE
Weak Colu	umn - Concrete		FALSE
No Cripple	Wall Bracing		FALSE
	lab Missing		FALSE
Inadequat	e Wall Anchorage		FALSE
	Deficiency		TRUE
URM wall	height to thickness ratio		FALSE
URM para	pets		FALSE
Openings	in diaphragm at shear wal	ls	FALSE

GSA SEISMIC RISK RATING (SRR) HAZUS Methodology W/ OSHPD Modifications

<u>SRR</u> for each building is based on Probability of Collapse (POC) Values calculated based on following parameters:

- Structural Capacity of each building
- Seismic Hazard Level at each site (BSE-2E, BSE-2, etc.)
- Significant Structural Deficiencies that influence structural capacity and building response

Database




Database




	BUILDING LOCATION INFORMATION NG USE BUIL			LDING	DAT	Ά			S	ITE SE	EISMIC	YTK	DATA						
Region	Location_Code	Building_Name	City	State	Building_GSF	Design Year	Bldg Height above ground (ft)	No. of Stories above	No. of Stories below	Model Building Type (used in POC calcs)	UBC zones	Seismic Design Level	BSE2E-Sds	BSE2E-Sd1	Tı	Fault Mag.	Fault Dist (km)	Cs	Те
						1932		4	1	URM	3		1.12	0.597	8	7	0.6		
						1916		3	1	URM	3		0.515	0.355	16	9.01	96.9		
						1911	61	4		URM	3		0.957	0.525	6	6.74	62.8		
						1933	63	4	1	C3	3		1.009	0.531	8	7.2	2.5		
						1932		1		C1	3		0.929	0.971	6	6.81	2.7		
						1933		8	1	S5	3		0.878	0.548	16	6.74	2		
						1970		6		C1	4		1.192	0.656	8	7.25	6.7		

Database



	STRUCTURAL DEFICIENCIES																				
Pre 1933	Load Path	Mass Irreg.	Vert. Discont.	Captive Col.	Deter. Wood	Deter. Steel	Deter. Conc.	Weak Col (conc)	Weak Col (Steel)	Wall Anch.	Redun.	Weak Story	Soft Story	Tors. Irreg.	Defl. Incomp.	Diaph. Open	Top. Slab	Cripple Walls	URM Wall h/t	URM Parap	Shear Failure C1 building only
TRUE	TRUE	FALSE	TRUE	FALSE	FALSE	FALSE	TRUE	FALSE	FALSE	TRUE	FALSE	TRUE	TRUE	FALSE	FALSE	TRUE	FALSE	FALSE	TRUE	FALSE	FALSE
TRUE	FALSE	FALSE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	TRUE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	TRUE	FALSE
TRUE	FALSE	FALSE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	FALSE	FALSE	TRUE	FALSE	FALSE
TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	FALSE	FALSE	TRUE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	FALSE
TRUE	FALSE	FALSE	FALSE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE
TRUE	FALSE	FALSE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	FALSE	TRUE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	FALSE	FALSE
FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE
FALSE	FALSE	TRUE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	TRUE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE
TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	FALSE	FALSE	TRUE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	FALSE
FALSE	FALSE	FALSE	TRUE	TRUE	FALSE	FALSE	FALSE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE
	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE
FALSE	FALSE	FALSE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	FALSE	TRUE	TRUE	FALSE	FALSE	TRUE	FALSE	FALSE	FALSE	FALSE	FALSE

Database



Seismic Risk Rating

Categories of seismic ratings (in progress):

- Green: Building meeting Seismic Safety Standards
- Yellow / Orange: Buildings not meeting the RP8 Seismic Standard, but of lower priority for retrofit compared to the others.
- Red: Buildings of High Risk recommended as a priority for action.
- Black: Buildings of Exceptional High Risk Hazard recommended as the highest priority for action (e.g. within 5 years).

_					
		BUILDING LOCATION INF			PRELIMINARY RESULTS
u	Location_Code	Building Name	Preliminary P[STR5]	Preliminary Seismic Risk Rating	Remarks
Region	cet	2	82.71%	49.6%	The rating is based on the original 1905 URM building
æ	೨	ng	52.24% 45.20%	31.3%	Deficiencies are based on FEMA-178 (Load path deficiency is not considered).
9			52.44%	27.1% 26.2%	
9		<u>}</u>	95.60%	23.9%	
9			73.59%	22.1%	
9			42.06%	21.0%	
9			25.14% 14.55%	12.6%	Deficiencies based on ST-Risk (very conservative)
g,			17.06%	8.7%	Complicated multisegmented structure. Detailed review needed.
9			56.07%	8.4%	Deficiencies based on ST-Risk (conservative)
9	\subseteq		15.81%	7.9%	·
9	\vdash	<u> </u>	52.03%	7.8%	
9			46.38% 45.46%	7.0%	Used Low code as seismic design level instead of Moderate code per table
9			12.13%	6.8%	Osed Low code as seismic design level instead of Moderate code per table
9			12.13%	6.1%	
9			12.13%	6.1%	
9			37.21%	5.6%	Used Low code as seismic design level instead of Moderate code per table
9			9.22%	5.5%	
9	\vdash		67.51% 66.14%	5.4%	
9			16.92%	5.1%	
9			8.87%	4.4%	Deficiencies based on ST-Risk (very conservative)
9			6.68%	4.0%	
9			21.31%	3.2%	
9			38.98% 10.29%	3.1%	
9		i .	19.99%	3.0%	
10	_	 	4.99%	3.0%	Complicated multisegmented structure. Detailed review needed.
10			10.16%	2.5%	Used Low code as seismic design level instead of Moderate code per table
10	_	<u> </u>	4.84%	2.4%	
10			29.22% 7.71%	2.3%	
10			15.97%	2.1%	
10			15.24%	2.0%	No deficiency based on Post Loma Prieta Damage Assessment Report
10			13.06%	2.0%	
10	=		3.43%	1.7%	
10			5.51% 19.32%	1.7%	
10			2.56%	1.5%	
10			3.01%	1.5%	
10			9.74%	1.5%	
10			8.63%	1.1%	
10			8.63% 2.24%	1.1%	
10			13.16%	1.1%	
10			7.89%	1.0%	Building was upgraded in 1987.
10			7.29%	0.9%	
10			1.87%	0.9%	Complicated multisegmented structure. Detailed review needed.
10			4.76%	0.7%	
10			1.41% 4.79%	0.7%	
10		<u> </u>	1.15%	0.6%	
10	-		1.06%	0.5%	
10		-	0.99%	0.5%	Complicated multisegmented structure. Detailed review needed.
10	=		1.90%	0.5%	
10'	_		5.86%	0.5%	Per Report, the seismic deficiencies would not pose collapse.

Outline of Path Forward for JCC Using HAZUS Methodology to Update Seismic Ratings/Rankings

Outline of Path Forward for JCC

- Create a database of building information drawing largely from the information gathered and generated for the 2003-2005 seismic evaluations, including:
 - Key building/structure information (size, age, structural system, etc.),
 - Identification of critical seismic deficiencies, and
 - Other parameters that influence structural strength and response.
- Determine the Site-Specific Seismic Hazard:
 - Spectral Response Accelerations,
 - Distance to Governing Fault, and
 - Magnitude of Governing Fault.
- Using the Collapse Probability (CPA) Tool recently developed for the GSA:
 - Perform calibration test runs using building information from the JCC database,
 - Review the results for appropriateness and make refinements to the CPA Tool as may be warranted.

Outline of Path Forward for JCC

- Following from the above, use the CPA Tool to establish a
 preliminary Seismic Risk Rating (SRR) for each building/structure in
 the JCC database, and then group the structures into categories possibly Yellow, Red, and Black based upon their SRR scores
 which relate to recommended time frames for follow-up action.
- Submit a draft of the findings to the JCC for review, including a graphic which superimposes the JCC's buildings with their SRR on a map of California showing the major fault lines for reference; meet to discuss the findings.
- Finalize the submittal products and present them in a close-out meeting with the JCC.



Meeting Date: 1/15/2016

Discussion Item 5

Summary:

Update on revisions to Prioritization Methodology/Implementation Guideline.

Supporting Documentation:

• Slide

Discussion Item 5 Update: Prioritization Methodology

- Implementation Guideline
 - FM Policy
 - Guidelines/Protocols
 - CFR Procedure



Meeting Date: 1/15/2016

Information Only Item 1

Summary:

Informational report on FY 15-16 Q2 expenditures from CFTF.

Supporting Documentation:

• Expenditures document

Court Facilities Trust Fund Quarterly Report of FY 2015-16 Year-to-Date Revenues and Expenditures

	Projected as of 7/1/2015	Actual as of 12/31/2015
Excess Cash Carryover from prior year	12,291,251	12,291,251

	Estimated		% Revenue
Revenue Sources	Revenue	Revenue	Received
County Facilities Payment	96,147,818	55,568,791	57.80%
Rental Revenue	7,553,950	1,746,097	23.12%
General Fund Transfer	8,053,000	8,053,000	100.00%
Night Court Fees	2,213,000	601,093	27.16%
Surplus Money Investment Fund	45,000	40,135	89.19%
Miscellaneous Revenue	4,000	49,495	1237.38%
Total Revenue	114,016,768	66,058,612	57.94%
Total Resources Available	126,308,019	78,349,863	62.03%

Expenditure Categories	Budget Allocation	Expenditures ¹	Budget Balance	% Expended
Judicial Council Managed Expenditures				
Routine Maintenance	43,284,469	12,868,625	30,415,844	29.73%
Non-Reimbursement	37,574,331	11,315,889	26,258,442	30.12%
Reimbursement	5,710,138	1,552,736	4,157,402	27.19%
Utilities	20,605,482	8,694,499	11,910,983	42.20%
Non-Reimbursement	17,315,620	7,460,834	9,854,786	43.09%
Reimbursement	3,289,862	1,233,665	2,056,197	37.50%
Rent	13,857,360	7,286,893	6,570,467	52.59%
Non-Reimbursement	13,857,360	7,286,893	6,570,467	52.59%
Insurance	1,000,000	301,101	698,899	30.11%
Non-Reimbursement	1,000,000	301,101	698,899	30.11%
Total Judicial Council Managed	78,747,311	29,151,119	49,596,192	37.02%
Total Non-Reimbursement	69,747,311	26,364,718	43,382,593	37.80%
Total Reimbursement	9,000,000	2,786,401	6,213,599	30.96%
Court Delegated Expenditures				
Routine Maintenance	4,009,491	1,974,745	2,034,746	49.25%
Total Court Delegated	4,009,491	1,974,745	2,034,746	49.25%
County Managed Expenditures				
Routine Maintenance	7,572,253	3,094,925	4,477,328	40.87%
Utilities	33,112,830	9,095,275	24,017,555	27.47%
Rent	2,383,076	1,496,014	887,062	62.78%
Insurance	938,820	187,399	751,421	19.96%
Total County Managed	44,006,979	13,873,614	30,133,365	31.53%
Total Expenditures	126,763,781	44,999,478	81,764,303	35.50%
Less Reimbursements	-9,000,000	-2,786,401	-6,213,599	30.96%
Total Expenditures Less Reimbursements	117,763,781	42,213,077	75,550,704	35.85%

^{1.} Reflects expenditures posted to financial system as of December 31, 2015. Due to lag in receipt and processing of invoices the expenditure values will not reflect all costs for services provided through the reporting period.



Information Only Item 2

Summary:

Informational report on FY 15-16 budget reconciliation and spending plan, as well as completed and canceled facility modifications during the reporting period.

Meeting Date: 1/15/2016

Supporting Documentation:

• Budget reconciliation document

Meeting Date: January 15, 2016

Facility Modifications Completed and Canceled

During the January reporting period 161 facility modifications funded over multiple fiscal years were completed. Collectively, the actual costs were under budget of the original estimated amounts by approximately 16%. For this fiscal year there were 18 funded projects that were canceled. There were 136 FY 15-16 projects closed out with an aggregate savings of \$294,308.

REPORTING PERIOD STATUS	Quantity	Estimated Cost of FM Program Budget Share	Actual Cost of FM Program Budget Share	% of Estimated Cost
Completed	161	\$2,900,435	\$2,429,417	84%
Funded FMs Canceled	18	\$118,015	N/A	N/A
Non-Funded FMs Canceled	13	N/A	N/A	N/A

CURRENT YEAR STATUS	Quantity	Cost Adjustment to Current Year FM Program Budget
Completed	136	\$294,308
Canceled	1	\$111,795
TOTAL COS	T ADJUSTMEN	T \$406,103

FY 2015-2016 FM Budget YTD Reconciliation

The first meeting of the year in July 2015 included initial encumbrances, as well as for the approved FMs over \$50,000 and cost increases greater than \$50,000. The remaining available funds for facility modifications before the January 15th meeting is \$9,451,000.

FY 2015-2016 (\$1,000s)									
Description	Budget Amount	Reconciled Expenditure	Funds Available						
Statewide FM Planning Allocation	\$4,000	\$4,000	\$0						
Priority 1 FM Allocation	\$10,000	\$10,000	\$0						
FMs Less Than \$50K Allocation	\$8,000	\$8,000	\$0						
Planned FMs Allocation	\$2,900	\$2,900	\$0						
Priority 2-6 FMs Allocation	\$40,100	\$30,649	\$9,451						
TOTALS:	\$65,000	\$55,549	\$9,451						

Meeting Date: January 15, 2016

FY 2015-2016 FM Budget Spending Plan

Based on the recommended project funding for this meeting we anticipate an expenditure of \$3.1 million at this meeting, including energy efficiency projects. The FMs that were approved by the committee but remained unfunded due to lack of county shared funding commitments have since been funded as P1 projects.

FY 2015-2016 Spending Plan (\$	1,000s)
Month/Item	Spending
JUL 2015 (approved 7/17)	\$31,330
AUG 2015 (approved 8/31)	\$4,624
OCT 2015 (approved 10/23)	\$11,669
DEC 2015 (approved 12/7)	\$5,026
JAN 2016	\$2,990
FEB 2016	\$2,000
APR 2016	\$2,261
MAY 2016	\$2,000
Energy Efficiency – JAN 2016	\$140
Energy Efficiency – APRIL 2016	\$1,860
Approved Projects Pending Funds	\$1,100
TOTAL	\$65,000



Meeting Date: 1/15/2016

Information Only Item 3

Summary:

Memorandum from Judge So for all JCC committees on the timelines associated with the submittal of legislative proposals for possible Judicial Council sponsorship in 2017, together with the timeline for this year.

Supporting Documentation:

Memo



JUDICIAL COUNCIL OF CALIFORNIA

770 L Street, Suite 1240 • Sacramento, California 95814-3368 Telephone 916-323-3121 • Fax 916-323-4347 • TDD 415-865-4272

MEMORANDUM

Date

January 5, 2016

To

Advisory Committee Chairs and Staff

From

Hon. Kenneth K. So, Chair Policy Coordination and Liaison Committee

Subject

Deadlines for Judicial Council-Sponsored Legislation

Action Requested

Please review

Deadline

N/A

Contact

Laura Speed, Principal Manager 916-323-3121 phone laura.speed@jud.ca.gov

As Chair of the Judicial Council's Policy Coordination and Liaison Committee, I am writing to advise you of the timelines and process for developing potential proposals for Judicial Council-sponsored legislation. Each year, the council sponsors bills that seek to improve the administration of justice in California and assist, where needed, in accomplishing branchwide goals and objectives. Judicial Council advisory committees are ideally positioned to identify and develop proposals for statutory change given committee members' extensive expertise in the committee's subject area.

In order to meet the deadlines for developing, refining, circulating, and revising proposals for possible Judicial Council sponsorship in 2017, your committee should be developing proposals in January - March of this year. The timeline for the development of sponsored legislation is attached for your reference.

Judicial Council directive 23 seeks to identify legislative requirements that impose unnecessary reporting or other mandates on the courts and the Judicial Council and make appropriate efforts to repeal such mandates. When considering possible sponsorship proposals, please keep this directive in mind and assist Governmental Affairs in identifying items that should be repealed.

January 5, 2016 Page 2

Please contact your advisory committee staff, or Laura Speed in Governmental Affairs at 916-323-3121, if you have any questions. Thank you.

Calendar for Judicial Council—Sponsored Legislation

	Advisory Committee Staff Due Date
Proposal development Advisory committee, in consultation with Governmental Affairs staff, develops proposals for Judicial Council–sponsored legislation.	January–March 2016
Proposals to Governmental Affairs Staff Advisory committee staff forwards draft Invitations to Comment to Governmental Affairs staff for review before submission to the Policy Coordination and Liaison Committee (PCLC).	March 11, 2016
Governmental Affairs staff, in consultation with advisory committee staff, finalizes Invitations for Comment and submits them to PCLC.	March 28, 2016
PCLC meeting to review Invitations to Comment PCLC determines if proposals may be circulated for public comment.	April 7, 2016
Posting to the Website Governmental Affairs staff sends approved ITC to Advisory Committee staff (AC) and AC staff sends approved ITC's to Camilla Kieliger for posting to the website for public comment.	April 8, 2016
Comment period Advisory committee staff, in consultation with GA staff, circulates draft Judicial Council–sponsored legislation proposals to interested and affected parties.	April 15–June 14, 2016
Staff consultation Advisory committee staff consults with GA staff regarding responses to comments and further development of proposals for Judicial Council—sponsored legislation.	June–August 2016
Final proposals for Judicial Council-sponsorship sent to PCLC	October 13, 2016
PCLC meeting to review proposals for possible Judicial Council-sponsorship	October 27, 2016 In person meeting
Judicial Council meeting Judicial Council takes action on proposals for Judicial Council–sponsored legislation for upcoming legislative year.	December 16, 2016